

CONTRACT REPORT CR-NAVFAC-EXWC-SH-22269 AUGUST 2022

# FUEL TRANSFER SYSTEM INSPECTION REPORT

FUEL TRANSFER INFRASTRUCTURE ASSESSMENT

Red Hill Bulk Fuel Storage Facility, Hawaii (RHL)

(b) (6)

Austin Brockenbrough and Associates, LLC

This page is intentionally left blank.

REPORT DOCUMENTATION PAGE  1. REPORT DATE  08/31/2022  Contract Report  START DATE March 21, 2022  4. TITLE AND SUBTITLE FUEL Transfer System Inspection Report  So. CONTRACT NUMBER N39430-20-D-2242  So. GRANT NUMBER N39430-20-D-2242  So. FROORM ELEMENT NUMBER N39430-20-D-2242  So. TASK NUMBER N3943022F4333  T719610  Austin Brockenbrough and Associates, LLC 7. FERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Austin Brockenbrough & Associates, LLC 1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC ORGANIZATION NAME(S) ADDRESS (ES) NAVFAC EXWC ORGANIZATION NAME(S) ADDRESS (ES) NAVFAC EXWC ORGANIZATION NAME(S) ADDRESS (ES) NAVFAC EXWC SHI 2026  13. SUPPLEMENTARY NOTES  14. ABSTRACT AUGUST (Controlled by ADDRESS (ES) NAVFAC EXWC SHI 2026 ORGANIZATION NAME(S) ADDRESS (ES) NAVE ADDRESS (ES)							
08/31/2022 Contract Report  4. TITLE AND SUBTITLE FUEI Transfer System Inspection Report  56. CONTRACT NUMBER N39430-20-D-2242  56. PROJECT NUMBER N39430-20-D-2242  56. PROJECT NUMBER SE. TASK NUMBER N3943022F4333  57. PROJECT NUMBER N3943022F4333  58. TASK NUMBER N3943022F4333  59. AUTHOR(S)  AUSTIN Brockenbrough and Associates, LLC  7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) NAUSTIN Brockenbrough & Associates, LLC  1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  8. PENDANGRING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC  1000 23rd Avenue NAVFAC EXWC  1000 23rd Avenue NAVFAC EXWC  1000 23rd Avenue NAVFAC EXWC  11. SPONSORMONITOR'S NAVFAC EXWC  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N39/430200224/2, Delivery Order N39/43022F4333 to Proper Nave Accompany of the Nave Acc			REPORT DOCUMENT	TATION PAG	E)		
4. TITLE AND SUBTITLE FUEL TRANSFER System Inspection Report  5a. CONTRACT NUMBER N39430-20-D-2242  6b. GRANT NUMBER N39430-20-D-2242  6c. FROGRAM ELEMENT NUMBER N3943022F4333  6c. TASK NUMBER N3943022F4333  1719610  6c. AUTHOR(S)  Austin Brockenbrough and Associates, LLC 7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Austin Brockenbrough & Associates, LLC 1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  9. SPONSORING/MONTORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC NO0023rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  14. ABSTRACT August 2022  15. SUPPLEMENTARY NOTES  16. SUPPLEMENTARY NOTES  16. SUPPLEMENTARY NOTES  17. LIMITATION OF ABSTRACT ALB BIR FLOW Strond Endowed by MANYFAC EXWC under Contract No. N304032002242, Delivery Order N3040322F4333 to perform an inspection of the fact branches of the result of the Red Hill Bulk Full Strong Endolf (HISP-S) and Inspection is the inspection is the inspection in the inspection of the Part of the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform in a the Red Hill Bulk Full Strong Endolf (HISP-S) and Files Perform	1. REPORT DATE 2. REPORT TYPE			3. D.	3. DATES COVERED		
Fuel Transfer System Inspection Report  56. CONTRACT NUMBER N39430-20-D-2242  56. RASK NUMBER 22-022  56. ASK NUMBER 37. S. PROGRAM ELEMENT NUMBER 37. WORK UNIT NUMBER 38. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) 40. AUSTIN Brockenbrough & Associates, LLC 40. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) 40. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) 40. SPONSORIMONITORING AGENCY NAME(S) ADDRESS(ES) 40. SPONSORIMONITORING AGENCY NAME(S) ADDRESS(ES) 40	08/31/2022 Contract Report						
S6. CONTRACT NUMBER N39430-20-D-2242 S6. PROGRAM ELEMENT NUMBER S6. PROGRAM ELEMENT NUMBER S6. PROGRAM ELEMENT NUMBER S6. PROGRAM ELEMENT NUMBER S6. WORK UNIT NUMBER S6. WORK UNIT NUMBER T719610 S. AUTHOR(S) AUSTIN Brockenbrough and Associates, LLC T. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) AUSTIN Brockenbrough & Associates, LLC S11 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225 S. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC S100 23rd Avenue NAVFAC EXWC S100 23rd Avenue NAVFAC EXWC SIGNAMFAC EXWC SIGNAMFAC EXWC SIGNAMFAC EXWC Under Contract No. N394302002242, Delivery Order N364302274333 to perform an inspection of the the transfer system, supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs supporting infrastructure, and apportenances, including valves and any other company and the Ref Insert Springs support suppor	4. TITLE AND SUBTITLE			31	127		17771
N39430-20-D-2242  6d. PROJECT NUMBER  22-022  N3943022F4333  1719610  Austin Brockenbrough and Associates, LLC  7. PERFORMING ORGANIZATION NAME(s) AND ADDRESS(ES) Austin Brockenbrough & Associates, LLC  1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  9. SPONSORING/MONITORING AGENCY NAME(s) AND ADDRESS(ES) NAVFAC EXWC  1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N39430202242, Delivery Order N3943022F433 to Perform an image-ind of the fluid transfer system, supporting infrastructure, and apputernances, including valves and any other corrosion proise equipment at the Red Hill Bulk Fam (BIFT). Included in this inspection is the fluid diameter in the Red Hill Bulk Fam (BIFT). Included in this inspection is the fluid diameter in the Red Hill Bulk Fam (BIFT). Also included is the supporting and and effect of including valves and any other corrosion proise equipment at the Red Hill Bulk Fam (BIFT). Also included is the supporting and effect of including valves and any other corrosion proise equipment at the Red Hill Bulk Fam (BIFT). Also included is the supporting and effect of including valves and any other corrosion proise equipment at the Red Hill Bulk Fam (BIFT). Also included is the supporting and effect of including valves and any other corrosion proise equipment at the Red Hill Bulk Fam (BIFT). Also included is the supporting and effect of including valves and any other corrosion proise equipment at the Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  17. LIMITATION OF ABSTRACT  18. NUMBER OF PAGES  10.84  198. NAME OF RESPONSIBLE PERSON  199. PHONE NUMBER (Include area code)	BUTTER CONTRACTOR OF THE CONTRACTOR SOCIETY FOR CONTRACTOR	System Ir	FOR THE PROPERTY OF THE PROPER	rt			
56. PROJECT NUMBER 22-022  56. AUTHOR(S)  AUSTIN Brockenbrough and Associates, LLC 7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Austin Brockenbrough & Associates, LLC 1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  9. SPONSORINGIMONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N394302002242, Delivery Order N394302274333 to Perform an inspection of the fuel transfer system, supporting infrastructure, and apputenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFS) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the 19-9 diameter 7-19-5, and the 25-9 diameter 7-19 peripliers from harbor-side entrance to the underground pumphouse, including up to the Surger Tanks, to the 19-9 diameter 7-19-5. Author 25-9 diameter 7-19-19 peripliers from harbor-side entrance to the underground pumphouse including up to the Surger Tanks, to the 19-9 diameter 7-19-19-19-19-19-19-19-19-19-19-19-19-19-	PER TOTAL BUILDING TO A CONTROL OF A		5b. GRANT NUMBER		5c. PROGRA	M ELEM	ENT NUMBER
8. AUTHOR(S)  Austin Brockenbrough and Associates, LLC 7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Austin Brockenbrough & Associates, LLC 1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and apputenances, including valves and any other corrosion prone equipment at the Red Hill Bulk rule Storage Facility (PHEPS') at Joint Base Pearl Harbor Hickam (JBPHAF), included in this inspection is the glumber of the fuel transfer system, supporting in frastructure, and apputenances, including valves and any other corrosion prone equipment at the Red Hill Bulk rule Storage Facility (PHEPS') at Joint Base Pearl Harbor Hickam (JBPHAF), included in this inspection is the glumber of the fuel transfer system in the protein of the fuel transfer system in the protein of the fuel transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  U	N39430-20-D	)-2242					
Austin Brockenbrough and Associates, LLC  7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Austin Brockenbrough & Associates, LLC 1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N394302002242, Delivery Order N3943022F4333 to perform an inspection of the fuel stransfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk rule Storage Facility (PHEFSF) at Joint Base Pearl Hatroer Hickam (JBPHH), included in this inspection is the facility of the contract No. N394302002242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk rule Storage Facility (PHEFSF) at Joint Base Pearl Hatroer Hickam (JBPHH), included in this inspection is the supporting of the fuel transfer system in the pearl of the contract No. N394302002242, Delivery Order N3943022F4333 to pearl of the fuel transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  b. ABSTRACT  C. THIS PAGE  SAR  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084	5d. PROJECT NUMBER		5e. TASK NUMBER		5f. WORK UN	NIT NUME	BER
Austin Brockenbrough and Associates, LLC  7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Austin Brockenbrough & Associates, LLC 1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Ausin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N394302002242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting a fuel of the feel fill Bulk Fuel Share facility (Rishers Fysherm, supporting 4 and 6 feel fill Bulk Fuel Share fuel of the Red Hill Bulk Tank Farm (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including to the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As including the Surge Lanks, to the Red Hill Bulk Tank Fuel (BHTF). As i	22-022		N3943022F43	33	17196	10	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) AUSTIN Brockenbrough & Associates, LLC 1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225 9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043 12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red III Blu K Fuel Straight Fam (BHT). Included in this inspection is the 1911 diameter JP-5, and the 32 manual properties from harbor-side entrance to the underground pumphouse, including up to the Surger Lanks, to the Red Hill Buk Fuel Straight Fuel Oil Rectaim pipelines that rurs from RHTF to Trank S-311 located outside 1912.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  D. ABSTRACT  D. ABSTRACT  D. ABSTRACT  C. THIS PAGE  U  15b. PHONE NUMBER (Include area code)	6. AUTHOR(S)	,	THE PERSON NAMED IN THE PE		CONTRACTOR CONTRACTOR	Service of the servic	
Austin Brockenbrough & Associates, LLC 1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225  9. sponsoring/Monitroring agency name(s) and address(es) 10. sponsoring/Monitroring agency name(s) and address(es) NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Ausin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N394302002242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including values and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the Surger Fanks, to the Red Hill Bulk K Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3 supporting 15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  ACRONYM(8)  119. PHONE NUMBER (Include area code)	Austin Brock	kenbrougl	n and Associa	ites, LLC	)		
AUSTRACT  14. ABSTRACT  14. ABSTRACT  Ausin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N394302002242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Field Storage Facility (BHFF). Also included is the supporting 4 and 6 Field Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  15. D. ABSTRACT  LU  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  SAR  18. NUMBER OF PAGES  10. PHONE NUMBER (Include area code)	7. PERFORMING ORGANIZA	ATION NAME(S) AND	ADDRESS(ES)				
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N394302002242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFS) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the Hill Bulk Famk Farm (BHTF). Also included is the supporting 4 and 6 requirement of the red family of the Surge Tanks, to the Red Hill Bulk Famk Farm (BHTF). Also michaed is the supporting 4 and 6 requirement of the red family of the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also michaed is the supporting 4 and 6 requirement of the red family of the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also michaed is the supporting 4 and 6 requirement of the red family of the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also michaed is the supporting 4 and 6 requirement of the red family of the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also michaed is the supporting 4 and 6 requirement of the red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  17. LIMITATION OF ABSTRACT U	Austin Brockenbrou	gh & Associates	s, LLC		and the second	REPORT	NUMBER
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)  NAVFAC EXWC  100. 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT  Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility (HBHSFS) at Jointon His Inspection in this inspection in the fuel diameter LPG pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Lanks, to the Red Hill Buk Tank Farm (BHTF). Also included is the supporting 4— and 6— Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  16. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT U  17. LIMITATION OF ABSTRACT U  18. NUMBER OF PAGES 1084			200				
NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility (RBFSF) at Joint Base Pearl Harbor Hickam (JBFH). Including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility (RBFSF) at Joint Base Pearl Harbor Hickam (JBFH). Including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility (RBFSF) at Joint Base Pearl Harbor Hickam (JBFH). Including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility and the Fuel Oil Reclaim pipelines that runs from RHTF to Tank St. to the Red Hill Bluk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank St. 311 located outside 15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  b. ABSTRACT  C. THIS PAGE  C. THIS PAGE  SAR  19. PHONE NUMBER (Include area code)	Richmond, Virginia	23225					
NAVFAC EXWC 1000 23rd Avenue Port Hueneme, CA 93043  12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility (RBFSF) at Joint Base Pearl Harbor Hickan (JBFH). Including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility (RBFSF) at Joint Base Pearl Harbor Hickan (JBFH). Including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility (RBFSF) at Joint Base Pearl Harbor Hickan (JBFH). Including valves and any other corrosion prone equipment at the Red Hill Bluk Fuel Storage Facility damater F-76 pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bluk K Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  b. ABSTRACT  C. THIS PAGE  C. THIS PAGE  SAR  19. PHONE NUMBER (Include area code)	9 SPONSOPING/MONITOP	ING AGENCY NAME(S	AND ADDRESS(ES)	10.9	PONSOR/MON	UTOP'S	11 SPONSOP/MONITOR'S
12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the supporting of diameter JRS, to the Red Hill Bulk Tank Farm (BHTF). Also included is the supporting 4 and 8 fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 1. Subspect TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  10. 84  198. PHONE NUMBER (Include area code)		INO ACENCT NAME(O	AND ADDITECTOR				
12. DISTRIBUTION/AVAILABILITY STATEMENT  August 2022  13. SUPPLEMENTARY NOTES  14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the fuel transfer system from harbor-side entrance to the underground pumphouse, including up to the Surge Lanks, to the Red Hill Bulk X Tank Farm (BHTF). Also included is the supporting 4 and 6 fuel fuel fuel fuel fuel fuel fuel fuel	1000 23rd Avenue			NIA	NAVEAC EXIMO OF NAVEAC EXIMO OF		OD NAVEAO EVINO OLI 20000
14. ABSTRACT Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the 19 diameter J-5, and the 22 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse in the 19 diameter J-5, and the 23 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse to the subground pumphouse in the 19 diameter J-5, and the 19 diameter J-5, and the 19 diameter J-5, and the 20 diameter J-6 pipelines from harbor-side entrance to the underground pumphouse in the 19 diameter J-5, and the 19 diameter J-5, and the 19 diameter J-5, and the 19 diameter J-6 pipelines from harbor-side entrance to the underground pumphouse in the 19 diameter J-5, and the 19 diameter J-5, and the 19 diameter J-6 pipelines from harbor-side entrance to the underground pumphouse in the 19 diameter J-5, and the 19 diameter J-5, and the 19 diameter J-6 pipelines from harbor-side entrance to the underground pumphouse in the 19 diameter J-5, and the 19 diameter J-5, and the 19 diameter J-6 pipelines from harbor in the 19 diameter J-6 pi	Port Hueneme, CA 93043 NAVFAC EXWC-SH-22269						
13. SUPPLEMENTARY NOTES  14. ABSTRACT  Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk rule Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the property of the National Control of the International Control of In	12. DISTRIBUTION/AVAILA	BILITY STATEMENT					
14. ABSTRACT  Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the High and the High and the Hill Bulk Was and any other corrosion prone equipment at the Red Hill Burk Storage Including up to the Surge Tanks, to the Red Hill Burk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084  19b. PHONE NUMBER (Include area code)					A	August	2022
14. ABSTRACT  Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the High and the High and the Hill Bulk Was and any other corrosion prone equipment at the Red Hill Burk Storage Including up to the Surge Tanks, to the Red Hill Burk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084  19b. PHONE NUMBER (Include area code)							
14. ABSTRACT  Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the High and the High Andrews and any other corrosion prone equipment at the Red  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF ABSTRACT  U  18. NUMBER OF ABSTRACT  H 18. NUMBER OF PAGES  19. ABAM ANDREW OF ABSTRA							
Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the JP-5, and the 32 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084  19b. PHONE NUMBER (Include area code)	13. SUPPLEMENTARY NOT	ES					
Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the JP-5, and the 32 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084  19b. PHONE NUMBER (Include area code)							
Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the JP-5, and the 32 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084  19b. PHONE NUMBER (Include area code)							
Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the JP-5, and the 32 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084  19b. PHONE NUMBER (Include area code)							
Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the JP-5, and the 32 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084  19b. PHONE NUMBER (Include area code)	77 184-814						
perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the JP-5, and the 32 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bulk Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  b. ABSTRACT  U  17. LIMITATION OF ABSTRACT  U  18. NUMBER OF PAGES  1084  19b. PHONE NUMBER (Include area code)		riates LLC (Brockenbrou	igh) was retained by NAVFAC EXV	NC under Contract No	N3943020D2	242 Deliv	en/ Order N3943022F4333 to
JP-5, and the 32 diameter F-76 pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bu k Tank Farm (BHTF). Also included is the supporting 4 and 6 Fuel Oil Reclaim pipelines that runs from RHTF to Tank S-311 located outside 3.  15. SUBJECT TERMS  Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT  U  D. ABSTRACT  U  D. ABSTRACT  U  D. ABSTRACT  U  D. ABSTRACT  U  D. PHONE NUMBER (Include area code)	perform an inspection of the fu	el transfer system, suppo	orting infrastructure, and appurtena	nces, including valve	s and any other		prone equipment at the Red
15. SUBJECT TERMS Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT U  b. ABSTRACT U  C. THIS PAGE U  SAR  19b. PHONE NUMBER (Include area code)	JP-5, and the 32- diameter	r F-76 pipelines from har	bor-side entrance to the undergrou	nd pumphouse, inclu	ding up to the Si		s, to the Red Hill Bu k Tank
Fuel Transfer System Inspection Report Red Hill Bulk Storage Facility Hawaii  16. SECURITY CLASSIFICATION OF:  a. REPORT U  b. ABSTRACT U  17. LIMITATION OF ABSTRACT SAR  1084  19a. NAME OF RESPONSIBLE PERSON  19b. PHONE NUMBER (Include area code)	Farm (BHTF). Also included is	s the supporting 4-	Fuel Oil Reclaim pipeline	s that runs from RHT	to Tank S-311	located o	outside 3.
16. SECURITY CLASSIFICATION OF:  a. REPORT U  b. ABSTRACT U  17. LIMITATION OF ABSTRACT SAR  1084  19a. NAME OF RESPONSIBLE PERSON  19b. PHONE NUMBER (Include area code)	15. SUBJECT TERMS						
a. REPORT U  b. ABSTRACT U  c. THIS PAGE U  SAR  1084  19a. NAME OF RESPONSIBLE PERSON  19b. PHONE NUMBER (Include area code)	Fuel Transfer Syste	m Inspection Re	eport Red Hill Bulk Sto	rage Facility H	ławaii		
a. REPORT U  b. ABSTRACT U  c. THIS PAGE U  SAR  1084  19a. NAME OF RESPONSIBLE PERSON  19b. PHONE NUMBER (Include area code)	92						
a. REPORT U  b. ABSTRACT U  c. THIS PAGE U  SAR  1084  19a. NAME OF RESPONSIBLE PERSON  19b. PHONE NUMBER (Include area code)							
a. REPORT U  b. ABSTRACT U  c. THIS PAGE U  SAR  1084  19a. NAME OF RESPONSIBLE PERSON  19b. PHONE NUMBER (Include area code)	46 SECURITY OF ASSISTANTION OF						
U U SAR 1084  19a. NAME OF RESPONSIBLE PERSON  19b. PHONE NUMBER (Include area code)			(1000 - 1100 / 10	N OF ABSIKA	C I	Principal Community of the Community of	
19a. NAME OF RESPONSIBLE PERSON  19b. PHONE NUMBER (Include area code)	CONTRACTOR PRODUCTIONS	02 25	ACTIVITIES OF BUILDINGS AND	SAR			1084
(b) (6)	\$1000 ·	LE PERSON	(A.C.F.)	1	19b. PHO	NE NUM	BER (Include area code)
	(b) (6)				(b) (6)		

This page is intentionally left blank.



# FUEL TRANSFER SYSTEM INSPECTION REPORT

FUEL TRANSFER INFRASTRUCTURE ASSESSMENT Red Hill Bulk Fuel Storage Facility, Hawaii (RHL)

> Delivery Order No. N3943022F4333 A/E Contract No. N39430-20-D-2242

## Submitted to:

Naval Facilities Engineering Command Engineering and Expeditionary Warfare Center 1000 23rd Avenue, Port Hueneme, CA 93043-4370

August 30, 2022

## Submitted by:



1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225 Phone: 804.592.3900 www.brockenbrough.com Job No. 22-022





ACF	RONY	MS	3
A.	EXE	CUTIVE SUMMARY	5
B.	INT	RODUCTION	9
	1.	Infrastructure Assessment Objectives	
	2.	Project Scope	
	3.	Use of this Report	10
	4.	Project Team	11
C.	FAC	CILITY DESCRIPTION	13
	1.	Project Location	13
	2.	System Overview	
	3.	F-24 Pipelines	
	4.	JP-5 Pipelines	
	5.	F-76 Pipelines	
	6.	FOR Pipelines	
D.	INS	PECTION METHODOLOGY	
	1.	References	
	2.	External Visual and Hands-On API 570 Inspection	
	3.	Long-Range Ultrasonic Testing (LRUT)	
	4.	Weld Examination and Inspection – Phase Array Ultrasonic Testing (PAUT)	
	5.	Ultrasonic Thickness Measurements (UTMs)	
	6.	Pipe Support Observation	
	7.	Validation of 2016 and 2019 Piping Repair Recommendations	
E.		NDITION ASSESSMENT	
	1.	F-24 System Assessment	
	2.	JP-5 System Assessment	
	3.	F-76 System Assessment	
_	4.	FOR System Assessment	
F.		DINGS AND RECOMMENDATIONS	
	1.	LRUT Results	
	2.	PAUT Weld Examination Results	
	3. 4.	Hands-on and Visual Examination ResultsValidation of 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	
4 D.F		X 'A' – FLOW SCHEMATIC	
		X 'B' - SYSTEM DRAWINGS	
		X 'C' - API 570 INSPECTION REPORT	
		X 'D' - TRIP REPORT	
		X 'E' - CALCULATIONS	
APP	ENDI	X 'F' – PIPE SUPPORT ASSESSMENT	85
APP	ENDI	X 'G' – SORTED TABLES – FINDINGS AND RECOMMENDATIONS (BY URGENCY)	162



Table 1 - Project Team	11
Table 2 - F-24 Pipeline Information	14
Table 3 - JP-5 Pipeline Information	15
Table 4 - F-76 Pipeline Information	16
Table 5 - FOR Pipeline Information	17
Table 6 - Inspection Techniques	21
Table 7 - F-24 Findings and Recommendations	35
Table 8 - F-24/JP-5 Pipe Support Findings and Recommendations	40
Table 9 - JP-5 Findings and Recommendations	42
Table 10 - F-76 Findings and Recommendations	51
Table 11 - F-76 Pipe Support Findings and Recommendations	60
Table 12 - FOR Findings and Recommendations	61
Table 13 - FOR Pipe Support Findings and Recommendations	66
Table 14 - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipeli Report	
Table 15 - FOR Pipe Support Findings and Recommendations	86
Table 16 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations	95
Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations	113
Table 18 - Underground Pumphouse Pipe Support Findings and Recommendations	157
Table 19 - Surge Tank Pipe Support Findings and Recommendations	161
Table 7 (Sorted) - F-24 Findings and Recommendations	163
Table 8 (Sorted) - F-24/JP-5 Pipe Support Findings and Recommendations	170
Table 9 (Sorted) - JP-5 Findings and Recommendations	173
Table 10 (Sorted) - F-76 Findings and Recommendations	183
Table 11 (Sorted) - F-76 Pipe Support Findings and Recommendations	192
Table 12 (Sorted) - FOR Findings and Recommendations	193
Table 13 (Sorted) - FOR Pipe Support Findings and Recommendations	198
Table 14 (Sorted) - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red H	
Pipelines Report	
Table 15 (Sorted) - FOR Pipe Support Findings and Recommendations	
Table 16 (Sorted) - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations	
Table 17 (Sorted) - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations	
Table 18 (Sorted) - Underground Pumphouse Pipe Support Findings and Recommendations	
Table 19 (Sorted) - Surge Tank Pipe Support Findings and Recommendations	288



## **ACRONYMS**

API American Petroleum Institute

ASME American Society of Mechanical Engineers

AST Aboveground Storage Tank

ASTM American Society for Testing and Materials

BH Barrels
Bulk Head

CFR Code of Federal Regulations
CML Condition Monitoring Location
COR Contracting Officer's Representative
DBB Double Block and Bleed [Twin-Seal Valve]

DoD Department of Defense

ECDA External Corrosion Direct Assessment

FFS Fitness For Service
FLC Fleet Logistics Center
FOR Fuel Oil Reclaim
FW Flash Welded

GFI Government Furnished Information

HPV High Point Vent ILI In-Line Inspection

IMP Integrity Management Plan

Joint Base Pearl Harbor-Hickam

LF-ERW Low Frequency Electric Resistance Welded

LLC Limited Liability Corporation

LPD Low Point Drain

LRUT Long-Range Ultrasonic Testing

MAOP Maximum Allowable Operating Pressure
MAWP Maximum Allowable Working Pressure

MOP Maximum Operating Pressure

MOV Motor Operated Valve

NAVFAC Naval Facilities Engineering Systems Command

NAVFAC Expeditionary Warfare Center

**NAVSUP Naval Supply Systems Command** NDAA National Defense Authorization Act NDE Non-Destructive Examination **NFPA** National Fire Protection Agency **NIWC Naval Information Warfare Center PAUT** Phased Array Ultrasonic Testing POL Petroleum, Oil, and Lubricants Pounds per Square Gauge **RHBFSF** Red Hill Bulk Fuels Storage Facility

RHTF Red Hill Tank Farm SOW Scope of Work

SPCC Spill Prevention Control and Countermeasures

Acronyms page 3



UGPH Underground Pumphouse UFC Unified Facilities Criteria

UT Ultrasonic Testing
UTF Upper Tank Farm

UTM Ultrasonic Thickness Measurement

Acronyms \_\_\_\_ page 4

## A. EXECUTIVE SUMMARY

Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the (b) (3) (A)

pipelines from harbor-side entrance to the underground pumphouse, including up to the Surge Tanks, to the Red Hill Bulk Tank Farm (RHTF). Also included is the supporting (b) (3) (A)

pipelines that runs from the RHTF to Tank 311 located outside of 3.

As required by this Delivery Order, Brockenbrough along with our subconsultants, InterSpec, LLC and E&I Hawaii, executed a pipeline inspection site visit to JBPHH. The inspection activities occurred during March 21, 2022, through May 23, 2022. This inspection was performed following the principles of API 570 and included external corrosion direct assessment (ECDA) of the pipelines, visual inspection of the pumps and other fuel system components, phased array ultrasonic testing (PAUT) of pipeline girth welds, and long-range ultrasonic testing (LRUT) of pipelines within concrete bulkheads. The following report was generated from the results of our field investigations, discussion with personnel, calculations, and analysis and represents the findings, assessments, recommendations, and conclusions developed during this project.

The current condition assessment is primarily based upon the inspection efforts made during our field investigation, and relevant supporting material provided in the government furnished information. We have assigned five easily understood levels of condition:

- Poor The piping system is showing signs of significant integrity issues such as severe corrosion where significant pipe wall loss, greater than 50-percent, is present.
- Fair The piping system is showing signs of moderate to severe integrity issues such as corrosion where pipe wall loss, greater than 40-percent but less than 50-percent, is present.
- Satisfactory The piping system is showing signs of moderate integrity issues such as moderate corrosion where pipe wall loss, greater than 10-percent but less than 40-percent, is present.
- Good The piping system shows signs of light to moderate corrosion where pipe wall loss, less than 10-percent, is present.
- Excellent The piping system shows no signs of integrity issues or active corrosion.

The API 570 inspection and other advanced inspection methods performed on the fuel transfer systems at RHBFSF resulted in several findings and repair recommendations which have been prioritized into three categories:

 Mandatory/Urgent Repairs - Repairs identified as urgent are those that represent an immediate/major risk to personnel safety and/or the environment and have failed a fitness for

Executive Summary page 5



- service evaluation. These are repairs that are critical to the hydraulic and structural integrity of the piping system and should be completed as soon as possible prior to defueling the RHTF.
- Long-Term Repairs Repairs identified as long-term are those that do not pose an immediate risk to personnel safety and/or the environment. These repairs are not critical to the hydraulic and structural integrity of the piping system.
- Other Items of Note Repairs or upgrades that could be addressed to upgrade the system piping to meet current military criteria or improve system operations but may not be warranted based on cost-benefit considerations and timeline of defueling the RHBFSF.

The decision has been made to close and defuel the Red Hill Bulk Fuel Storage Facility's fuel systems within the next five years. Therefore, the urgent recommendations included in this report are focused on system repairs needed to safely defuel the RHTF over the next 5 years. The only systems within the scope of this report that will remain in service after the fuel system closure of the RHBFSF is the UGPH. All the urgent and long-term deficiencies identified within the UGPH are recommended. These long-term deficiencies should be programmed for execution after defueling operations are complete.

In general, the piping systems at the RHBFSF are in fair to satisfactory condition and were found to be serviceable to support defueling operations. However, there were several identified mandatory/urgent deficiencies that should be corrected prior to performing defueling operations. Many of these urgent deficiencies are due to weeping fittings, severe external corrosion, and pitting, loose and/or missing fasteners on valves and other components, additional protective measures, and severe corrosion or damage on pipe supports and anchors. A complete list of repairs and deficiencies can be found in Section F of this report and are broken down between product and geographic locations.

The following is a summary of the major repairs recommended prior to defueling operations begin.

- Replacement of 22 steel pipe supports supporting the F-24 and JP-5 pipelines throughout the Harbor Tunnel.
- Replacement of 10 steel pipe supports supporting the FOR pipelines throughout 3/Lower Access Tunnel.
- Repair of the two concrete pipe anchor bulkheads. (Deficiency Item Nos. 44A and
- Replacement of approximately 150 linear of aboveground 6-per FOR pipe from Tanks 311 isolation valve to aboveground/underground pipeline transition outside of (Deficiency Item No. FOR.059)
- Perform Borescope examination of underground FOR Pipeline at 3. Note: This is not a repair but a requirement for further nondestructive examination of this pipe segment. This is currently under contract to be performed in the near future. (Deficiency Item No. FOR.055)
- Replacement of Tank 9 sample piping. (Deficiency Item No. FOR.031)
- Perform further NDE assessment of bell joint weld between 572 and 573 due to geometric anomaly/dent on the 18- JP-5 pipeline. (Deficiency JP5.077)

Based on the LRUT investigation and results performed during this inspection, there were five (5) locations that have indications present that require follow-on verification to determine the extent and size of the indications. These locations should be inspected prior to performing defueling operations and they include:

- CML# B8 (Between 135 and 136) An indication (corrosion spot) was observed approximately 7 past the concrete bulkhead, towards the tank gallery, underneath the pipe wrap. Location of indication is on the pipe wrap be removed, and the pipeline be inspected at this location.
- CML# B17 (Between 239 and 240) An area of inactive pitting (approximately 0.050 deep) with some large area scaling was identified. An additional two areas of possible corrosion of similar magnitude of pitting are suspected under the pipe wrap at this location. These areas are located on the (b) (3) (A) pipeline. It is recommended that the pipe wrap be removed, and the pipeline be further inspected at these locations.
- CML# B21 (Between 291 and 292) One confirmed indication was detected at approximately -402 to -411 from setup on the (b) (3) (A) pipeline. There was also an indication identified at the pipeline to concrete saddle support 195 on the (b) (3) (A) pipeline that will require additional investigation. This will require the pipe to be lifted off the concrete support or the pipe support removed and replaced to allow further inspection. It is recommended that follow-up inspection occur at both these locations.
- CML# B26 (Between 570 and 571) One indication was observed approximately -460 from setup on the (b) (3) (A) pipeline. Indication is believed to be under the pipe wrap. It is recommended that the pipe wrap be removed at this location and further inspection of the pipe in this area be performed to confirm the extent of this indication.
- CML# B26 (Between 570 and 571) Two indications were noted approximately -976 and -963 from setup on the (b) (3) (A) pipeline. The indication is believed to be under pipe wrap. It is recommended that the pipe wrap be removed at this location and further inspection of the pipe be performed to confirm the extent of these indications.

The following is a summary of deficiencies for all four product pipelines within the RHBFSF.

	Quantity of Mandatory/Urgent Repairs	Quantity of Long Term Repairs	Quantity of Other Items of Note
F-24 Pipelines	19	31	16
JP-5 Pipelines	21	64	42
F-76 Pipeline	47	79	25
FOR Pipelines	22	43	1
Total	109	217	84

NOTE: Quantities include previous deficiencies identified in the 2016 and 2019 "Inspection and Repair of Red Hill Pipelines Report".

Executive Summary page 7

The following is a summary of deficiencies for all pipe supports within the RHBFSF.

	Quantity of Mandatory/Urgent Repairs	Quantity of Long Term Repairs	Quantity of Other Items of Note
FOR Pipe Supports	12	199	34
Frame Pipe Supports (JP-5/F-24)	22	670	56
Concrete Sleepers (F-76)	2	61	553
UGPH Pipe Supports	-	26	96
Surge Tank Pipe Supports	-	9	9
Total	36	965	748

## Disclaimer

Report is based on information known as of the date of the report and subject to revision should new information become available.

## **Photograph Release Statement**

All photographs contained in this report unless otherwise noted were taken by Austin Brockenbrough & Associates, LLC or its subcontractors. Austin Brockenbrough & Associates, LLC hereby grants permission to the US Government and its contractors to publish/republish these photographs.

Executive Summary page 8

# **B. INTRODUCTION**

Austin Brockenbrough & Associates, LLC (Brockenbrough) was retained by NAVFAC EXWC under Contract No. N3943020D2242, Delivery Order N3943022F4333 to perform an inspection of the fuel transfer system, supporting infrastructure, and appurtenances, including valves and any other corrosion prone equipment at the Red Hill Bulk Fuel Storage Facility (RHBFSF) at Joint Base Pearl Harbor Hickam (JBPHH). Included in this inspection is the (b) (3) (A) the (b) (3) (A) and the (b) (3) (A) and the (b) (3) (A) pipelines from the entrance to the underground pumphouse, including up to the (A) Surge Tanks, to the RHBFSF. Also included is the supporting (b) (3) (A) pipelines that runs from the RHBFSF Tanks to Tank 311 located outside of 3.

As required by this Delivery Order, Brockenbrough along with our subconsultants, InterSpec, LLC and E&I Hawaii, executed a pipeline inspection site visit to JBPHH. Our inspection activities occurred during March 21, 2022, through May 23, 2022. This inspection was performed following the principles of API 570 and included External Corrosion Direct Assessment (ECDA) of the pipelines, visual inspection of the pumps and other fuel system components, phased array ultrasonic testing (PAUT) of pipeline girth welds, and long-range ultrasonic testing (LRUT) of pipelines within concrete bulkheads. The following report was generated from the results of our field investigations, discussion with personnel, and various calculations and analysis and represents the findings, assessments, recommendations, and conclusions developed during this project.

#### 1. Infrastructure Assessment Objectives

The objective of this assessment is to conduct an inspection of the fuel transfer system, supporting infrastructure, and related POL appurtenances at the RHBFSF, report findings and provide recommendations, and provide an assessment of the overall condition of the POL piping systems.

The decision has been made to close and defuel the Red Hill Bulk Fuel Storage Facility's fuel systems within the next five years. Therefore, the urgent recommendations included in this report are focused on system repairs needed to safely defuel the RHTF over the next 5 years. The only systems, within the scope of this report, that will remain in service after the fuel system closure of the RHBFSF are the surge tanks and UGPH. All the urgent and long-term deficiencies identified within the UGPH are recommended. These long-term deficiencies should be programmed for execution after defueling operations are complete.

## 2. Project Scope

For the purposes of this assessment, the scope boundary and area of interest includes the JP-5, F-24, and F-76 pipelines from the Surge Tanks (Tanks 0221, 0222, 0223, and 0224), inside the Underground Pumphouse (UGPH), in the Harbor Tunnel, in the Lower Access Tunnel, and in the Red Hill Tank Gallery. The scope also includes the Fuel Oil Reclaim (FOR) pipelines from Tank 311,

Introduction page 9

outside of 3, in the lower access tunnel, and in the Red Hill Tank Gallery. Our project scope of work includes the following pipeline inspection techniques and methodologies:

- Gathering of historical system data and review of Government Furnished Information (GFI).
- Performing a visual and hands-on pipeline inspection following the principles of API 570.
- Performing guided wave ultrasonic testing of piping portions passing through concrete bulkheads.
- Performing phased array ultrasonic testing (PAUT) of pipeline girth welds.
- Collecting ultrasonic thickness measurements on the pipelines to determine nominal pipeline wall thicknesses.

The systems included in this assessment are as follows:

- JP-5 The JP-5 aviation kerosene grade fuel system includes the associated pipeline systems and support equipment.
- F-24 The F-24 aviation kerosene grade fuel system includes the associated pipeline systems and support equipment.
- F-76 The F-76 diesel grade fuel system includes the associated pipeline systems and support equipment.
- FOR The FOR system contains untreated off-spec or contaminated product from the three
  main bulk fuel products (such as tank water bottoms) and includes the associated pipeline
  systems and support equipment that contain FOR.

The fuel systems are further broken down by sub-systems, or areas, as follows:

- UGPH The UGPH which contains the primary distribution pumps, the Surge Tanks, and associated piping.
- Harbor Tunnel The tunnel between the UGPH and RHTF containing the three primary bulk fuel pipelines.
- RHTF The RHTF contains the 20 primary bulk fuel storage tanks and associated piping.
- 3 Tunnel FOR piping from Tank 311 to RHTF.

#### 3. Use of this Report

This report identifies deficiencies within the RHBFSF and provides the urgency of when they should be performed to support defueling operations over the next five years. The engineering evaluation was performed by Brockenbrough and is supported by the supplemental API 570 Inspection Report performed by InterSpec, LLC and E&I Hawaii. The engineering evaluation includes all items identified within the API 570 report and any additional findings identified during our assessment. The full list of engineering evaluation findings and recommendations to support defueling can be found in Section F of this report. The API 570 report can be found in Appendix C. Note that the

Introduction \_\_\_\_ page 10

urgency assigned to these findings within the engineering evaluation may be different than what is indicated within the API 570 report, as the engineering evaluation is tailored for the upcoming defuel timetable. When there is a discrepancy within this report, all findings and recommendations within Section F, including the urgency of the recommendations, shall govern. The API 570 report is to be used as a reference document to allow the reader access to additional information, photographs, and backup data. The Brockenbrough engineering team and their associated qualification are listed in Table 1 below.

## 4. Project Team

Table 1 below highlights the project team, roles, and contact information.

	Table 1 - Project Tea	m.
NAME	PROJECT ROLE	CONTACT INFORMATION
NAVFAC EXWC		(b) (6)
(b) (6)	Contracting Officer	(6) (6)
	Contract Specialist	
	Project Manager	
	Design Manager	
BROCKENBROUGH PERSONNEL - F	PRIME	(IN COV
(b) (6) Program Manager	Project Manager, API 570 Inspector, SSHO	(b) (6)
(b) (6) Director - Fuels Infrastructure	Project Engineer, API 570 Inspector, SSHO	
(b) (6) Principal	Field Team Supervisor, SSHO	
(b) (6) , PE Sr. Project Manager	Mechanical Engineer, SSHO	
(b) (6) , PE	Structural Engineer	
(b) (6)	CAD Technician	
INTERSPEC, LLC PERSONNEL (SUBC	CONSULTANT - API 570 INSPE	CTION)
(b) (6)	PM, API 570 Inspector	(b) (6)
	API 570 Inspector, SSHO	
	Field Technician	

Introduction page 11



Table 1 - Project Team			
NAME	PROJECT ROLE	CONTACT INFORMATION	
E&I HAWAII PERSONNEL (SUB	CONSULTANT - PAUT NDE TECHN	IICIAN)	
(b) (6)	NDE Technician/Specialist	Phone: (b) (6)	
(b) (6)	NDE Technician/Specialist	Phone: (b) (6)	

Introduction \_\_\_\_ page 12

## C. FACILITY DESCRIPTION

## 1. Project Location

This pipeline assessment and inspection was performed at RHBFSF at JBPHH, Hawaii.

#### 2. System Overview

Constructed around 1943, the RHBFSF consists of 20 underground storage tanks, an underground pumphouse, and a 3-mile tunnel containing product piping. The Red Hill storage tanks are bulk tanks that receive, store, and issue DLA-E capitalized JP-5, F-24, and F-76 to support NAVSUP Fleet Logistics Center (FLC) mission. The 20 tanks, which were mined inside Red Hill, are steel lined, concrete encased, and have an approximate storage capacity of 297,000 Tanks 1-4 are in approximately 238 and 100 in Tanks 5-20 are 250 are 100 in Fuel receipt into the Red Hill tanks is accomplished via transferring fuel from ships, pipeline receipt from the commercial refinery, or from the Upper Tank Farm (UTF) through aboveground pipelines within the Harbor Tunnel and Lower Access Tunnel uphill approximately three miles. Pumping operations uphill are accomplished by pulping fuel transfer pumps ranging from (b) (3) horsepower. The system also includes (b) underground Surge Tanks, with a capacity of (b) (3) (A) each, that act as an atmospheric buffer during fuel receipt operations. The pumphouse is configured such that the fuel transfer pumps can work in series or parallel as needed to match fuel receipt flowrates coming from ships and can provide enough head to successfully fill the farthest and highest tank. Fuel is issued, via gravity, from the Red Hill Storage Tanks to US Navy vessels, oilers, and barges at several piers and docks and to Hickam Field. The three main transfer pipelines that carry fuel to and from the Red Hill Tanks include a (b) (3) (A) pipeline. These pipelines are routed aboveground through the Harbor Tunnel and RHTF and are Service Class 3 per API 570.

There are two FOR systems at this facility: an upper and lower system. The system at RHTF, the upper system, is currently used to collect sump water from the Red Hill Tunnel Tank Gallery and water bottoms from the Red Hill Storage Tanks. FOR product is stored in one 1,000 AST, Tank 311, located adjacent to the 3 entrance. The FOR pipelines within the RHTF consist of a 4-pipeline header within a floor trench that is connected to each of the Red Hill Storage Tanks. Once the pipeline leaves the RHTF it transitions out of the trench adjacent to Sump Station 23 and increases in size to a 6-pipeline all the way through the lower access tunnel up to the flange on Tank 311. The FOR system at Pearl Harbor, the lower system, has two 14,000 aboveground storage tanks (ASTs), one 25,000 gal AST, and various associated piping for processing FOR. The reclaimed fuel can be issued to the truck fillstand or into the F-76 header. For the purposes of this assessment and inspection, we focused on the upper FOR system. The assessment and inspection of the lower FOR system at JBPHH is not in the scope of this contract.

Refer to Appendix A and B for detailed drawings showing the fuel system layout and schematics.

Facility Description page 13



The following table summarizes the general pipeline information associated with the F-24 pipelines from the surge tanks, within the UGPH, through the tunnel system, and within the RHTF.

	Table 2 - F-24 Pipeline Information
Pipeline Identification:	(b) F-24 Pipeline
Current Service:	F-24 Aviation Turbine Fuel
Prior Services:	Unknown
Installation Date:	1942-1946
Location:	RHTF, Harbor Tunnel, UGPH
Pipeline Length:	(b) (3) (A)
Pipe Material:	Carbon Steel, Similar Composition to API 5L and ASTM A53 (based on Pipe Pedigree Report) <sup>1</sup>
Flanges:	Class 300 in UGPH, Harbor Tunnel, and RHTF; Class 150 Flanges in RHTF; Types: Weld neck
Fittings:	Mitered joints; Fabricated Tees and Branch Connections; Factory Fabricated Tees, Elbows, and Components
Gasket Type:	Unknown
Fabrication Method(s):	<ul> <li>(1) The seamed piping has both flash welded (FW) and low frequency electric resistance welded (LF-ERW) longitudinal seam welds.<sup>1</sup></li> <li>(2) Girth welds: majority of piping is bell-bell-chill ring joints (possibly with backing rings). Remaining girth welds are standard butt welds.</li> </ul>
Design Code:	ASME B31.3 (assumed)
Supporting Method:	Varies: (1) Supported on steel pipe supports with sacrificial pad welded to pipe at contact point with support approximately every 25 ft. (2) Cast directly into 26 concrete anchors/ bulkheads from UGPH up to RHTF. (3) Concrete Sleepers with Slides
Coating System	Varies: (1) Lead-Based Paint throughout system (original paint) (2) >50% of line has Pipe-Wrap (3) 1-Part System over Lead Primer
Nominal Pipe Diameters:	(b) (3) (A)
Nominal Wall Thicknesses:	Primarily 0.25 in.
Maximum Allowable Operating Pressure (MAOP):	(b) (3) (A)

# 4. JP-5 Pipelines

The following table summarizes the general pipeline information associated with the JP-5 Pipelines from the surge tanks, within the UGPH, through the tunnel system, and within the RHTF.

Table 3 - JP-5 Pipeline Information				
Pipeline Identification:	JP-5 Pipeline			
Current Service:	JP-5 Aviation Turbine Fuel			
Prior Services:	Unknown			
Installation Date:	1942-1946			
Location:	RHTF, Harbor Tunnel, UGPH			
Pipeline Length:	(b) (3) (A)			
Pipe Material:	Carbon Steel, Similar Composition to API 5L and ASTM A53 (based on Pipe Pedigree Report) <sup>1</sup>			
Flanges:	Class 300 in UGPH, Harbor Tunnel, and RHTF; Class 150 Flanges in RHTF; Types: Weldneck, slip-on			
Fittings:	Mitered joints; Fabricated Tees and Branch Connections; Factory Fabricated Tees, Elbows, and Components			
Gasket Type:	Unknown			
Fabrication Method(s):	(1) The seamed piping has both flash welded (FW) and low frequency electric resistance welded (LF-ERW) longitudinal seam welds. <sup>1</sup> (2) Girth welds: majority of piping is bell-bell-chill ring joints (possibly with backing rings). Remaining girth welds are standard butt welds.			
Design Code:	ASME B31.3 (assumed)			
Supporting Method:	Varies: (1) Supported on steel pipe supports with sacrificial pad welded to pipe at contact point with support approximately every 25 ft. (2) Cast directly into 26 concrete anchors/ bulkheads from UGPH up to RHTF. (3) Concrete Sleepers with Slides			
Coating System:	Varies: (1) Lead-Based Paint throughout system (original paint) (2) >50% of line has Pipe-Wrap (3) 1-Part System over Lead Primer			
Nominal Pipe Diameters:	(b) (3) (A)			
Nominal Wall Thicknesses:	Primarily 0.25 in.			
Maximum Allowable Operating Pressure (MAOP):	(b) (3)			



# 5. F-76 Pipelines

The following table summarizes the general pipeline information associated with the F-76 Pipelines from the surge tanks, within the UGPH, through the tunnel system, and within the RHTF.

	Table 4 - F-76 Pipeline Information
Pipeline Identification:	(b) F-76 Pipeline
Current Service:	F-76 Marine Grade Diesel
Prior Services:	Heavy Fuel Oil (Unknown Time Period)
Installation Date:	1942-1946
Location:	RHTF, Harbor Tunnel, UGPH - Aboveground
Pipeline Length:	(b) (3) (A)
Pipe Material:	Carbon Steel, Unknown Specification (Assume ASTM A53)1
Flanges:	Class 300 in UGPH, Harbor Tunnel, and RHTF; Class 150 Flanges in RHTF; Types: Weld neck, slip-on
Fittings:	Mitered joints; Fabricated Tees and Branch Connections; Factory Fabricated Tees, Elbows, and Components
Gasket Type:	Unknown
Fabrication Method(s):	<ul> <li>(1) The seamed piping has both flash welded (FW) and low frequency electric resistance welded (LF-ERW) longitudinal seam welds.<sup>1</sup></li> <li>(2) Girth welds: majority of piping is bell-bell-chill ring joints (possibly with backing rings). Remaining girth welds are standard butt welds.</li> </ul>
Design Code:	ASME B31.3 (assumed)
Supporting Method:	Varies: (1) Supported on concrete sleeper supports approximately every 25 ft. (2) Cast directly into concrete anchors/ bulkheads from UGPH up to RHTF. (3) Supported on steel pipe supports with sacrificial pad welded to pipe at contact point with support approximately every 25 ft.
Coating System:	Varies: (1) Lead-Based Paint throughout system (original paint) (2) >50% of line has Pipe-Wrap (3) 1-Part System over Lead Primer
Nominal Outer Diameters:	32 in. 20in. tank piping cross laterals 18 in. reduction for (4) Sectional DBB Isolation Valves
Nominal Wall Thicknesses:	Primarily 0.375 in.
Maximum Allowable Operating Pressure (MAOP):	(b) (3)

## 6. FOR Pipelines

The following table summarizes the general pipeline information associated with the FOR Pipelines from Tank S-311, through the tunnel system, and within the RHTF.

Table 5 - FOR Pipeline Information		
Pipeline Identification:	6" FOR Pipeline	
Current Service:	Fuel Oil Reclaim (FOR)	
Prior Services:	Unknown	
Installation Date:	Unknown	
Location:	RHTF, Lower Access Tunnel, 3 to Tank S-311	
Pipeline Length:	6,600 ft (approximately)	
Pipe Material:	Carbon Steel, Unknown Specification (Assume ASTM A53)	
Flanges:	Class 150 Flanges Types: Weld neck, slip-on	
Fittings:	Mitered joints; LR elbows, STD tees and branch connections; Grooved Mechanical Fittings	
Gasket Type:	Unknown	
Fabrication Method(s):	Buttwelded pipe and Grooved Mechanical Fittings	
Design Code:	ASME B31.3 (assumed)	
Supporting Method:	Varies: (1) Fabricated Steel Supports (2) Stanchion Type Supports (3) Supported at approximately every 10-15 ft.	
Coating System:	Unknown.	
Nominal Outer Diameters:	6 in. Lower Access Tunnel to Tank S-311 4 in. (pipe trench within Red Hill Bulk Fuel Storage Facility)	
Nominal Wall Thicknesses:	Primarily 0.275 in.	
Maximum Allowable Operating Pressure (MAOP):	Unknown.	

## Tables 2-5 Footnotes:

- 1. In 2019, Enterprise Engineering Inc. (EEI) under contract to APTIM, completed a Pipe Pedigree Report on the pipelines within the RHBFSF. The results of the testing resolves that both the are of an acceptable industry standard, equivalent to ASTM A53, Grade B piping. The chemistry, grade, and tensile strengths are of a high quality for the time of production. The FW piping seams were also metallurgically examined and tested to ensure that the weld quality factor was equal to one (1). In addition, extensive examinations were made in the tank gallery on the suspected LF-ERW piping utilizing ultrasonic phased array examinations of 100% of the LF-ERW piping. The results conclude that there is no LF-ERW piping within the Red Hill Facility which may be affected by seam weld cracks or other type of selective seam weld corrosion.
- 2. The F-24, JP-5, and F-76 piping systems are rated for an MAOP of 275 psig provided:

Facility Description \_\_\_\_ page 17



- All repairs and further investigations called for in 2010 EEI Surge Analysis report are completed.
- All repairs and further investigations called for in 2019 APTIM/EEI Inspection and Repair of Red Hill Pipelines are completed.
- Dresser Coupling investigations are completed, and they are found to be rated for 275 MAOP.
- Piping is braced off the tank at every location.
- Installed materials that will be subjected to full line pressure are rated for 275
- All urgent repairs and further investigations called for in this report are completed.
- 3. Per the DoD Defueling Plan of the Red Hill Bulk Fuels Storage Facility an evaluation to confirm all ratings of piping and hoses between the Red Hill and Pier Facilities is currently under contract.

Facility Description page 18



## D. INSPECTION METHODOLOGY

The pipeline inspections of the RHBFSF were performed by representatives from Brockenbrough, InterSpec, LLC, and E&I Hawaii. Pipeline inspection activities occurred over a 9-week period between March 21 through May 23, 2022. The pipeline inspection followed the principles of API 570. The following is a summary of inspection techniques that were implemented to perform the assessment of the piping systems within the RHBFSF. Refer to Appendix C – API 570 Inspection Report for more information.

#### 1. References

The following references were used in the collection of data, inspection, and assessment of the piping systems at RHBFSF:

•	API 570	Piping Inspection Code
•	API 574	Inspection Practices for Piping System Components
•	API 577	Welding Inspection and Metallurgy
•	ASME B31.3	Process Piping
•	ASME B31G	Manual for Determining Remaining Strength of Corroded Pipelines
•	40 CFR 112	Oil Pollution Prevention
•	NFPA 30	Flammable and Combustible Liquids Code
•	UFC 3-460-01	Design: Petroleum Fuel Facilities
•	UFC 3-460-03	O&M: Maintenance of Petroleum Systems

Additional references and criteria can be found in the API 570 Inspection Report in Appendix C.

## 2. External Visual and Hands-On API 570 Inspection

The purpose of the external visual and hands-on API 570 Inspection is to find and locate conditions or areas of concern that compromise the integrity of the piping. Areas of concern included but are not limited to metal-to-metal contact, corrosion, deteriorated coating systems, weeping joints or fittings, and damaged or deteriorated pipeline supporting mechanisms. The external visual and hands-on inspection was performed on the following pipeline segments and wetted system components under this project scope of work:

- (b) (3) JP-5 Pipelines from the Surge Tanks to the RHTF including the (b) (3) tank lateral piping.
- (b) (3) F-24 Pipelines from the Surge Tanks to the RHTF including the (b) (3) tank lateral piping.
- (b) (3) F-76 Pipelines from the Surge Tanks to the RHTF including the (b) (3) (A) latera piping.



- FOR pipelines from Tank 311 to the RHTF including the small ancillary piping within the trenches, etc.
- All fuel transfer pumps, valves, and other wetted components installed within the four product systems.
- All associated POL pipeline supports within the RHBFSF.

## 3. Long-Range Ultrasonic Testing (LRUT)

LRUT uses guided wave technology and excites low-frequency ultrasonic waves that travel the of a piping system to detect wall thickness variations. It is an advanced non-destructive inspection technique. Our inspection team performed LRUT at locations where visual/hands-on inspection activities are not possible, such as where piping passes through concrete bulkheads or pipe anchors, etc. InterSpec, LLC performed LRUT at a total of 20 locations throughout the Red Hill Complex. Our team primarily focused on the concrete bulkhead penetrations associated with the JP-5, F-24, and F-76 pipelines.

## 4. Weld Examination and Inspection – Phase Array Ultrasonic Testing (PAUT)

To check welds for service-induced cracking/fatigue, PAUT was completed on 86 girth welds throughout the POL pipeline systems. PAUT is an advanced non-destructive inspection technique that uses a set of ultrasonic testing (UT) probes made up of small elements which are pulsed individually with computer-calculated timing or phasing. PAUT was performed by technicians from E&I Hawaii. The following is a breakdown of the pipeline girth welds that were examined by PAUT.

- Three within the Surge Tank Piping Gallery (one for each product: JP-5, F-24, and F-76)
- Nine within the UGPH (three per product: JP-5, F-24, and F-76)
- 56 within the Harbor Tunnel (19 per product: JP-5, F-24, and F-76)
- 18 within the tank gallery (six per product: JP-5, F-24, and F-76)

NOTE: PAUT was not performed on the FOR piping systems because the piping system is an ancillary piping system, is predominately constructed of grooved mechanical fittings, is not under constant pressure, and is not subject to higher system pressure as the main fuel piping associated with the F-24, JP-5, and F-76 pipelines.

## 5. Ultrasonic Thickness Measurements (UTMs)

Ultrasonic thickness measurements (UTMs) were taken at numerous locations throughout the piping systems. The primary purpose of collecting UTMs is to establish and identify the nominal pipe thickness of the piping. UTMs were also taken at areas on the piping systems that were subjected to severe corrosion and where pipe thickness/wall loss was present. These measurements were collected and will be used to further evaluate pipeline integrity and fitness-for-service, e.g. corrosion rates, remaining life calculations, minimum wall thickness, etc.



For each of the above referenced fuel lines, a visual condition observation of the pipe supports was performed. Supports were evaluated on several criteria, including general support type; support material deterioration; pipe support connection to ground, wall, or ceiling; and adequate pipe protection through the use of isolation pads and sleeves. Each support on each fuel line was numbered and catalogued, with support descriptions and deficiencies noted, described, and photographed.

## 7. Validation of 2016 and 2019 Piping Repair Recommendations

In 2016 and 2019, an "Inspection and Repair of Red Hill Pipelines Report" was completed by Enterprise Engineering, Inc. Our scope of work included validation and determination of which repairs have been completed and which repairs are still valid from this report. A table summary of the deficiencies, recommendations, and status is included in Section F, Table 14. Note, the deficiencies identified from the smart pigging/ILI operations could not be validated due to difficulty in determining the location of the anomalies with respect to the pipeline pig runs lengths/distances and start/ending points.

The following table provides a summary of the above-mentioned inspection methodologies:

Table 6 - Inspection Techniques						
Pipe Segment	System	External Visual	Hands- On API 570	PAUT	LRUT	GFI Review and Historical Document Review
UGPH	(b) (3) (A)	X	X	X	X	X
		X	X	X	X	X
		X	X	X	Х	X
		X	X	Χ	X	X
Harbor Tunnel		X	Х	Χ	X	X
		X	X	Х	X	X
3		X	X	5	170	Х
Lower Access Tunnel		X	Х	歷	229	X
		X	Х	X	Х	X
200		X	Х	Х	X	Х
RHTF		X	Х	X	X	X
		X	X	益	20	Х

Inspection Methodology page 21

# E. CONDITION ASSESSMENT

The current condition assessment is primarily based upon the inspection efforts made during our field investigation from March 21 through May 23, 2022, and relevant supporting material provided in the government furnished information. We have assigned five easily understood levels of condition:

- Poor The piping system is showing signs of significant integrity issues such as severe corrosion where significant pipe wall loss, greater than 50-percent, is present.
- Fair The piping system is showing signs of moderate to severe integrity issues such as corrosion where pipe wall loss, greater than 40-percent but less than 50-percent, is present.
- Satisfactory The piping system is showing signs of moderate integrity issues such as moderate corrosion where pipe wall loss, greater than 10-percent but less than 40-percent, is present.
- Good The piping system shows signs of light to moderate corrosion where pipe wall loss, less than 10-percent, is present.
- Excellent The piping system shows no signs of integrity issues or active corrosion.

All pipe support deficiencies were noted during the condition observation, performed during the field investigation from March 21 through April 2, 2022, and are available in detail in Appendix F - Pipe Support Assessment. On many supports, there were multiple areas of deterioration, varying in severity. Only one condition assessment level was assigned to each pipe support, however, corresponding to the most severe deterioration observed on the support. The condition levels for pipe support assessment are similar to the pipe condition assessment levels above:

- Poor One or more of the support components shows severe or complete deterioration and is
  either barely useable or not providing the intended load transfer and must be replaced within
  five years.
- Fair One or more of the support components shows deterioration but should be able to remain in service for at least five years or longer with proper maintenance.
- Satisfactory One or more of the support components shows minor deterioration but should be able to remain in service for the design lifespan with proper maintenance.
- Good Few of the support components shows any deterioration. The support should be able to remain in service for the design lifespan with proper maintenance.
- Excellent Support components are new and do not show any sign of deterioration. The support should be able to remain in service for the design lifespan with proper maintenance.

For a more detailed condition assessment of each individual valve and other system components, refer to 2022 "Lifecycle Sustainment Plan Report".

## 1. F-24 System Assessment

The F-24 fueling system at the RHBFSF provides receipt, storage, and transfer of F-24 aviation fuel to support operations at JBPHH. (b) (3) (A)

Fuel is then issued or transferred by gravity from the RHTF to other facilities on JBPHH.

- a. UGPH The facility was generally found to be in fair to good condition considering it has been operated continuously since 1943. The F-24 pipelines and system components within the UGPH can be fully serviceable to support the upcoming defuel operations with a few system upgrades and/or repairs.
  - 1) Piping The F-24 pipelines within the UGPH were found to be in good condition. The coating systems are relatively intact with only a few areas of coating failure observed throughout the facility. There was no notable corrosion on the piping systems within the UGPH. However, there were several flanges and threaded fittings throughout the facility with evidence of past and/or active weeping that require further maintenance. Many of these locations were at low point drains, high point vents, and pipeline instrumentation connections throughout the facility. Additionally, it was observed that the dresser couplings on the pump suction and discharge piping had loose nuts on the retaining rods and require further maintenance. It was also noted that the dresser coupling lugs on the pump suction side were installed backwards.
  - 2) Fuel Transfer Pumps and and The fueling pumps are the original pumps that were installed back in 1943. The pumps are in fair condition but are showing signs of age and general wear. There is some coating failure on the pump casings, but no noticeable corrosion was present. At this advanced age, the fuel pumps have required maintenance of the pump bearings and have experienced shaft alignment issues.
  - 3) <u>Valves and Other Components</u> The valve types found in the UGPH include DBB valves, ball valves, gate valves, butterfly valves, pressure relief valves, and hydraulically operated control valves. The valves were found to be in good condition except for the gate valves and pressure relief valves. The gate valves are original equipment and are weeping and frequently require maintenance and service. The (b) (3) (A) relief valves (Cla-Val) have noticeable fuel weeps and require maintenance and repair.
  - 4) <u>Pipe Supports</u> The pipe supports in the UGPH include concrete sleepers and painted steel frame supports in several configurations to accommodate the tight piping spacing. In general, the supports in the UGPH are all in satisfactory, good, or excellent condition. No pipe support maintenance is required in the UGPH to facilitate safe defueling operations, though routine maintenance will be needed for the piping systems that are to remain in service after defueling operations are complete.

- b. **Harbor Tunnel** The Harbor Tunnel F-24 piping system features primarily a (b) (3) carbon steel bi-directional transfer line. This line is routed approximately 8 above the finished floor and is supported by regular spaced steel pipe supports. At various locations, the piping is anchored into concrete bulkheads. There are three DBB isolation valve stations located throughout the Harbor Tunnel.
  - 1) Piping The F-24 piping system within the Harbor Tunnel was found to be in generally satisfactory to good condition. The pipeline coating system within the Harbor Tunnel was found to be in generally poor to fair condition. There are many instances of coating failure and resultant light to moderate corrosion noted throughout. But no areas of severe corrosion or significant pitting was noted that would affect future operations. There were also many instances of pipe wrap system failure, exposing piping to accelerated corrosion at contact points.
  - 2) <u>Valves and Other Components</u> The isolation valves within the Harbor Tunnel are in satisfactory condition with only minor coating failure and loose or missing fasteners noted. There were minor fuel weeps observed throughout the Harbor Tunnel. These areas included threaded piping connections associated with the LPDs and HPVs.
  - 3) Pipe Supports The F-24 pipe supports in the Harbor Tunnel are primarily painted steel built-up frames made from plates and angles and bolted to both the floor and the tunnel wall. Both the F-24 and JP-5 pipes are supported on the same frame supports. Most of these frame supports are in satisfactory or fair condition and will not require repair before defueling, but some supports are in poor condition and will need to be replaced prior to defueling operations. Severe deterioration was noted, primarily at the column baseplates and wall anchorage locations. Concrete bulkhead anchors are also located periodically throughout the Harbor Tunnel, some of which show concrete deterioration, and which will also require repair prior to defueling.
- c. RHTF The F-24 system within the RHTF includes the (b) (3) (A) pipeline and the system tank issue and receipt cross laterals, which are (b) (3) in (b) (3) (A) storage tanks, with the capacity to cross connect into (b) (3) (A) if needed.
  - 1) Piping The piping system within the RHTF was found to be in generally satisfactory condition. Many instances of coating failure and resultant corrosion were noted, but most were not severe enough to affect operations in the near future. There were several locations where minor fuel weeps were evident, mainly observed at threaded pipe connections throughout the RHTF.
  - 2) <u>Pipe Supports</u> The pipe supports in the RHTF are primarily painted frame supports with two columns to the ground, or one column and a wall anchorage. In general, these

supports are in satisfactory to good condition, and will not require repair before defueling operations. Some supports showed local corrosion or member deformation, however, and will need to be repaired or replaced prior to defueling operations.

Several urgent deficiencies associated with the F-24 piping systems were noted throughout the facility and should be addressed prior to beginning any defueling operations. Refer to Tables 7 and 8 for a complete list of deficiencies identified.

## 2. JP-5 System Assessment

The JP-5 fueling system at the RHBFSF provio	les receipt, storage, and transfer of JP-5 aviation fuel to
support operations at JBPHH. (b) (3) (A)	
	Fuel is then issued or transferred by gravity from the
RHTF to other facilities on JBPHH.	

- a. UGPH The facility was generally found to be in fair to good condition considering it has been operated continuously since 1943. The JP-5 pipelines and system components within the UGPH can be fully serviceable to support the upcoming defuel operations with a few system upgrades and/or repairs.
  - 1) Piping The JP-5 pipelines within the UGPH were found to be in good condition. The coating systems are relatively intact with only a few areas of coating failure observed throughout the facility. There was no notable corrosion on the piping systems within the UGPH. However, there were several flanges and threaded fittings throughout the facility with evidence of past and/or active weeping that require further maintenance. Many of these locations were at low point drains, high point vents, and pipeline instrumentation connections throughout the facility. Additionally, it was observed that the dresser couplings on the pump suction and discharge piping had loose nuts on the retaining rods and requires further maintenance. It was also noted that the dresser coupling lugs on the pump suction side were installed backwards.
  - 2) Fuel Transfer Pumps and and The The fueling pumps are the original pumps that were installed back in 1943. The pumps are in fair condition but are showing signs of age and general wear. There is some coating failure on the pump casings, but no noticeable corrosion was present. There were some minor hairline cracks observed on the concrete pump bases, but these do not appear to be of any concern. At this advanced age, the fuel pumps have required maintenance of the pump bearings and have experienced shaft alignment issues.
  - 3) <u>Valves and Other Components</u> The valve types found in the UGPH include DBB valves, ball valves, gate valves, butterfly valves, pressure relief valves, and hydraulically operated control valves. The valves were found to be in good condition except for the gate valves

- and pressure relief valves. The gate valves are original equipment and are weeping and require frequent maintenance and service. The (b) (3) (A) relief valves (Cla-Vals) have noticeable fuel weeps and require maintenance and repair.
- 4) <u>Pipe Supports</u> The pipe supports for all lines in the UGPH include concrete sleepers and painted steel frame supports in several configurations to accommodate the tight pipe spacing. In general, the supports in the UGPH are all in satisfactory, good, or excellent condition. No pipe support maintenance is required in the UGPH to facilitate safe defueling operations, though routine maintenance will be needed for the piping systems that are to remain in service after defueling operations are complete.
- b. **Harbor Tunnel** The Harbor Tunnel JP-5 piping system features primarily an (b) (3) (A) transfer line. This line is routed approximately 6 above the finished floor and is supported by regular spaced steel pipe supports. At various locations, the piping is anchored into concrete bulkheads. There are three DBB isolation valve stations located throughout the Harbor Tunnel.
  - 1) Piping The piping system within the Harbor Tunnel was found to be in generally satisfactory to good condition. The pipeline coating system within the Harbor Tunnel was found to be in generally poor to fair condition. There were many instances of coating failure and resultant light to moderate corrosion noted throughout. The exception to this is seven areas of severe external corrosion and pitting were identified with pipe wall loss ranging from 38 percent to 60 percent. ASME B31G level 1 FFS evaluation was performed at these locations. Our analysis did not identify any locations in which the resultant remaining wall thickness of the pipe failed FFS evaluation. However, long term consideration should be given to replacing these sections of pipe. There were also many instances of pipe wrap system failure, exposing piping to accelerated corrosion at contact points.
  - 2) Valves and Other Components The isolation valves within the Harbor Tunnel are in satisfactory condition with only minor coating failure noted and issues with oil weeping from valve gear boxes. There were minor fuel weeps observed throughout the Harbor Tunnel. These areas included threaded piping connections associated with the LPDs and HPVs.
  - 3) <u>Pipe Supports</u> The JP-5 pipes in the Harbor Tunnel are supported on the same frames as the F-24 line; primarily painted steel built-up frames made from plates and angles and bolted to both the floor and the tunnel wall. As discussed in the F-24 pipe support description, most of these frame supports are in satisfactory or fair condition and will not require repair before defueling, but some supports were in poor condition and will need to be replaced prior to defueling operations. Severe deterioration was noted, primarily at the column baseplates and wall anchorage locations. Concrete bulkhead anchors were also

located periodically throughout the Harbor Tunnel, some of which exhibit concrete deterioration and will also require repair prior to defueling.

- c. RHTF The JP-5 system within the RHTF includes the (b) (3) (A) pipeline and the system tank issue and receipt cross laterals, which are (b) (3) in (b) (3) (A)
  - 1) Piping The piping system within the RHTF was found to be in generally satisfactory condition. Many instances of coating failure and resultant corrosion were noted, but most were not severe enough to affect operations in the near future. There were several locations where minor fuel weeps were evident, mainly observed at threaded pipe connections throughout the RHTF.
  - 2) Pipe Supports The JP-5 pipe supports in the RHTF are the same primarily painted frame supports with two columns to the ground, or one column and a wall anchorage as support both the F-24 and F-76 lines. In general, these supports are in satisfactory to good condition, and will not require repair before defueling operations. Some supports showed local corrosion or member deformation, however, and will need to be repaired or replaced prior to defueling operations.

Several urgent deficiencies associated with the JP-5 piping systems were noted throughout the facility and should be addressed prior to beginning any defueling operations. Refer to Table 9 for a complete list of deficiencies identified.

Note: The JP-5 pipeline was undergoing repairs during our inspection to correct the damage that occurred during the May 6<sup>th</sup>, 2021 pipeline event.

## 3. F-76 System Assessment

The F-76 fueling system at the RHBFSF provides receipt, storage, and transfer of F-76 diesel fuel to support operations at JBPHH. (b) (3) (A)

Fuel is then issued or transferred by gravity from the RHTF to other facilities on JBPHH.

- a. UGPH The facility was generally found to be in fair to good condition considering it has been operated continuously since 1943. The F-76 pipelines and system components within the UGPH can be fully serviceable to support the upcoming defuel operations with a few system upgrades and/or repairs.
  - 1) Piping The F-76 pipelines within the UGPH were found to be in good condition. The coating systems are relatively intact with only a few areas of coating failure observed throughout the facility. There was no notable corrosion on the piping systems within the

UGPH. However, there were several flanges and threaded fittings throughout the facility with evidence of past and/or active weeping that require further maintenance. Many of these locations were at low point drains, high point vents, and pipeline instrumentation connections throughout the facility. Additionally, it was observed that the dresser couplings on the pump suction and discharge piping had loose nuts on the retaining rods and require further maintenance. It was also noted that the dresser coupling lugs on the pump suction side were installed backwards.

- 2) Fuel Transfer Pumps and and and The fueling pumps are the original pumps that were installed back in 1943. Pump appeared to be out of service undergoing maintenance during our inspection. The pumps are in fair condition but are showing signs of age and general wear. There is some coating failure on the pump casings, but no noticeable corrosion was present. At this advanced age, the fuel pumps have required maintenance of the pump bearings and have experienced shaft alignment issues.
- 3) <u>Valves and Other Components</u> The valve types found in the UGPH include DBB valves, ball valves, gate valves, butterfly valves, pressure relief valves, and hydraulically operated control valves. The valves were found to be in good condition except for the gate valves and pressure relief valves. The gate valves are original equipment and are weeping and require frequent maintenance and service. The 4- pressure relief valves (Cla-Vals) have noticeable fuel weeps and require maintenance and repair.
- 4) <u>Pipe Supports</u> The pipe supports for all lines in the UGPH include concrete sleepers and painted steel frame supports in several configurations to accommodate the tight piping spacing. In general, the supports in the UGPH are all in satisfactory, good, or excellent condition. No pipe support maintenance is required in the UGPH to facilitate safe defueling operations, though routine maintenance will be needed for the piping systems that are to remain in service after defueling operations are complete.
- b. Harbor Tunnel The Harbor Tunne (b) (3) (A)

  transfer line. This line is routed approximately 3 above the finished floor and is supported by regular spaced concrete pipe supports. At various locations, the piping is anchored into concrete bulkheads. There are three DBB isolation valve stations located throughout the Harbor Tunnel.
  - 1) Piping The piping system within the Harbor Tunnel was found to be in generally satisfactory to good condition. The pipeline coating system within the Harbor Tunnel was found to be in generally poor to fair condition. There were many instances of coating failure and resultant light to moderate corrosion noted throughout. But most were not severe enough to affect operations in the near future. The exception to this is five areas of severe external corrosion and pitting were identified with pipe wall loss ranging from 29 percent to 46 percent. ASME B31G level 1 FFS evaluation was performed at these

locations. Our analysis identified that these locations were acceptable for continued operations. There were also many instances of pipe wrap system failure, exposing piping to accelerated corrosion at contact points.

- 2) Valves and Other Components The isolation valves within the Harbor Tunnel are in satisfactory condition with only minor coating failure noted and issues with oil weeping from valve gear boxes. There were minor fuel weeps observed throughout the Harbor Tunnel. These areas included threaded piping connections associated with the LPDs and HPVs.
- 3) <u>Pipe Supports</u> The F-76 pipe supports in the Harbor Tunnel are concrete sleepers with embedded steel saddles. In general, these supports are in satisfactory to good condition, with minor concrete chipping and efflorescence where the concrete has been exposed to water. With few exceptions, which are noted in the following tables, these supports do not need repair before defueling operations begin.
- c. RHTF The F-76 system within the RHTF includes the (b) (3) (A) and the system tank issue and receipt cross laterals, which are (b) (3) (A)
  - 1) Piping The piping system within the RHTF was found to be in generally satisfactory condition. Many instances of coating failure and resultant corrosion were noted, but most were not severe enough to affect operations in the near future. There were several locations where minor fuel weeps were evident, mainly observed at threaded pipe connections throughout the RHTF.
  - 2) <u>Pipe Supports</u> The F-76 pipe shares the same painted steel frame supports as the F-24 and JP-5 pipes in the RHTF. In general, these supports are in satisfactory to good condition, and will not require repair before defueling operations. Some supports showed local corrosion or member deformation, however, and will need to be repaired or replaced prior to defueling operations.

Several urgent deficiencies associated with the F-76 piping systems were noted throughout the facility and should be addressed prior to beginning any defueling operations. Refer to Tables 10 and 11 for a complete list of deficiencies identified.

## 4. FOR System Assessment

The FOR collection and transfer system at the RHBFSF provides capture, transfer, and storage of FOR type waste from various operational systems at JBPHH. FOR is collected within the piping tunnel system through various sumps and drains and is then transferred to the FOR storage facility,

Tank 311, located outside at 3. The FOR product is stored at this location until it can be issued to a truck for ultimate removal and disposal.

- a. 3 FOR product piping at 3 consists of 6- welded pipe. The piping is routed from the 3 entrance to Tank 311.
  - 1) Piping In general, the FOR product piping system at 3 was found to be in poor condition. The coating was in poor to fair condition and has failed, with resultant corrosion noted at several locations throughout. The corrosion was such that replacement of sections of the FOR product line are recommended as soon as possible. Refer to the following deficiency table in the "Findings and Recommendation" section of this report for locations and severity of corrosion. A borescope internal inspection of the underground piping segment at the entrance to 3 has been recommended to confirm the condition where piping is not accessible.
  - 2) <u>Pipe Supports</u> At \_\_\_\_\_\_ 3, the FOR pipe supports are primarily painted steel saddles or stanchions bolted to concrete pads. They are generally in satisfactory to good condition and do not require repair before defueling operations.
- b. Lower Access Tunnel FOR product piping in the Lower Access Tunnel consists of 6-grooved mechanical connected pipe. The piping is routed from Sump 23 at the RHTF to 3 entrance.
  - 1) Piping FOR piping within the Lower Access Tunnel was found to be in generally satisfactory condition, with some instances of coating failure and resultant minor to moderate corrosion noted. A few joints were observed to be weeping and require further maintenance. There was a segment of 4- piping within the pipe trench adjacent to Sump 23 where the pipeline was showing significant wall loss and had been previously repaired with three temporary pipe clamps. Note, the entire FOR pipeline within the Lower Access Tunnel from Sump 23 to 3 entrance is being recoated as part of the "FLC POL Pipeline Repairs" project (E-Project Work Order No. 1615884). The temporary pipe clamps are also being removed and replaced with a pipe pup under this project as well.
  - 2) Pipe Supports There are primarily three types of FOR pipe supports in the Lower Access Tunnel. The first type is a wall mounted support consisting of a double cradle made of built-up bar stock painted and attached to the wall at two locations. The upper cradle supports the FOR pipe and the lower cradle is empty. The second type is a frame support consisting of painted frames made from built-up steel angle with a column attached to the floor and two arms attached to the wall. These frames support the FOR line on one arm and other piping on a second arm. The third type of frame is a galvanized Unistrut or angle frame with two columns to the ground and the FOR pipe strapped or u-bolted to a Unistrut or angle cross member. All three types of support are generally in satisfactory condition.

Several of the wall mounted supports show severe corrosion and loss of anchorage and must be replaced before defueling operations begin. Many of the frames are missing isolation pads or otherwise have metal-to-metal contact, which must be replaced if the line is to remain in service.

- c. RHTF FOR product piping within the RHTF consists primarily of a header pipe and laterals to each tank, mostly located in a shallow floor trench throughout the facility. FOR product is transferred from the storage tanks through the 4- carbon steel piping to the aboveground storage facility outside of 3.
  - 1) <u>Piping</u> FOR piping within the RHTF was found to be in generally satisfactory to good condition, with some instances of minor coating failure and other deficiencies.
  - 2) Pipe Supports In the RHTF, the FOR pipe is located in a trench in the floor and is supported by I-beam lengths, generally on their sides. These supports are frequently corroded or shimmed with wood pieces, but do not need to be replaced for defueling operations.

Several urgent deficiencies associated with the FOR piping systems were noted throughout the facility and should be addressed prior to beginning any defueling operations. Refer to Tables 12 and 13 for a complete list of deficiencies identified.



The API 570 inspection and other advanced inspection methods performed on the fuel transfer systems at RHBFSF resulted in several findings and repair recommendations which have been prioritized into three categories:

- Mandatory/Urgent Repairs Repairs identified as urgent are those that represent an immediate/major risk to personnel safety and/or the environment and have failed a fitness for service evaluation. These are repairs are critical to the hydraulic and structural integrity of the piping system and should be completed as soon as possible prior to defueling the RHTF.
- Long-Term Repairs Repairs identified as long-term are those that do not pose an immediate risk to personnel safety and/or the environment. These repairs are not critical to the hydraulic and structural integrity of the piping system.
- Other Items of Note Repairs or upgrades that could be addressed to upgrade the system piping to meet current military criteria or improve system operations but may not be warranted based on cost-benefit considerations and timeline of defueling the RHBFSF over the next five years.

For additional information and photographs of the deficiencies refer Appendix C – API 570 Inspection Report. For pipe support deficiencies classifications, only Urgent repairs have been included in the following tables. For a list of all pipe support deficiencies, including long term repairs and other items of note, see Appendix F – Pipe Support Assessment. The pipe supports for the F-24 and JP-5 pipelines throughout the system share common pipe support frames and are included in Table 8 – F-24/JP-5 Pipe Support Findings and Recommendations. For approximate locations of the deficiencies refer to Appendix B – System Drawings. The list of deficiencies which have been sorted by urgency are included in Appendix G – Sorted Tables – Findings and Recommendations for quick reference.

## 1. LRUT Results

The primary purpose in performing LRUT was to investigate locations where access for inspection of the pipeline was not physically possible via traditional hands on and visual methods, e.g. concrete bulkhead and at concrete supports. The LRUT data that was collected were field analyzed for accuracy, signal amplitude, and range. Much of the data that was captured and analyzed indicated that the piping was in satisfactory condition with no indications within the detectible limits of the LRUT equipment. There were five (5) locations that have indications present that require follow-on verification to determine the extent and size of the indications. These locations include:

• CML# B8 (Between 135 and 136) – An indication (corrosion spot) was observed approximately 7 past the concrete bulkhead, towards the tank gallery, underneath the pipe wrap. Location of indication is on the (b) (3) (A) It is recommended that the pipe wrap be removed, and the pipeline be inspected at this location.





- CML# B17 (Between 239 and 240) An area of inactive pitting (approximately 0.050 deep) with some large area scaling was identified. An additional two areas of possible corrosion of similar magnitude of pitting are suspected under the pipe wrap at this location. These areas are located on the (b) (3) (A) It is recommended that the pipe wrap be removed, and the pipeline be further inspected at these locations.
- CML# B21 (Between 291 and 292) One confirmed indication was detected at approximately -402 to -411 from setup on the (b) (3) (A) There was also an indication identified at the pipeline to concrete saddle support 195 on the (b) (3) (A) that will require additional investigation. This will require the pipe to be lifted off the concrete support or the pipe support removed and replaced to allow further inspection. It is recommended that follow-up inspection occur at both these locations.
- CML# B26 (Between 570 and 571) One indication was observed approximately -460 from setup on the (b) (3) (A) Indication is believed to be under the pipe wrap. It is recommended that the pipe wrap be removed at this location and further inspection of the pipe in this area be performed to confirm the extent of this indication.
- CML# B26 (Between 570 and 571) Two indications were noted approximately 976 and -963 from setup on the (b) (3) (A) The indication is believed to be under pipe wrap. It is recommended that the pipe wrap be removed at this location and further inspection of the pipe be performed to confirm the extent of these indications.

Refer to Appendix C – API 570 Inspection Report for additional information on the locations, techniques applied, and results related to the LRUT inspection.

## 2. PAUT Weld Examination Results

The primary purpose of the PAUT weld examination was to detect any service induced defects such as cracking or erosion/corrosion that may be present in the girth welds. The selection of the 86 welds is intended to be representative sample of the piping and were performed at areas that could see higher stresses due to pipe movement, anchorage/restraint, and cyclic stresses. The locations of PAUT on the selected welds was based on pipe movement and anticipated and/or potential exposure of shear and bending stress due to operating conditions. The PAUT data indicated that there are no service induced defects on any of the welds that were tested. For the exact locations PAUT was performed, techniques applied, and results refer to Appendix C – API 570 Inspection Report.



## 3. Hands-on and Visual Examination Results

The primary purpose of the hands-on visual examination was to detect areas of corrosion and pipeline integrity issues. The findings and recommendations are presented in the following tables separated by product.

## 4. Validation of 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report

Refer to Table 14 for these deficiencies and status and recommendations.

		0.1			Table 7 - F-24 Findings and Recommendations		No.
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F24.001		PM-19 PM-20 PM-21 PM-22	RHTF	(b) (3) (A)	Dresser Couplings are installed in tank piping laterals.	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
F24.002			RHTF		Tank sample piping downstream of the isolation valves are open to the atmosphere. If the isolation valves were to be bumped or inadvertently forced open, this could lead to an accidental fuel spill.	Urgent	Provide threaded caps on tank sample piping downstream of isolation valves.  NOTE: This deficiency has been corrected for the tanks that have been previously cleaned, inspected, and repaired.
F24.003	A1		RHTF		Brass/bronze valve (low melting point) attached to the blind flange of the (10) (3) (A) Rating of valve is unknown.	Urgent	Replace valve with a Class 150 ball valve.  Long-term consideration should be given into replacing threaded pipe and fittings with welded pipe.
F24.004	A4		RHTF		(b) (3) (A)	Urgent	Provide threaded plug on ball valve drain.
F24.005	A5		RHTF		Coating failure and corrosion on (b) (3) (A) at support.	Long	Remove surface corrosion and recoat affected area. Consider replacing support with a saddle that is welded to the structural support and providing a Teflon pad between pipe and saddle.
F24.006	A6		RHTF	- 0	has a thick coating system preventing inspection of the pipe exterior. A dent was observed at the 7 o'clock position near 38 which could not be analyzed due to coating system.	Long	Remove thick coating system, inspect exterior of pipe, and recoat.
F24.007	A9		RHTF		is not adequately supported, approximately between 46 and 47, with a saddle missing at 46.	Long	Install saddle support at 46 to properly support the pipeline.
F24.008	A10		RHTF	Ž	pipeline has a metal shim between pipe and saddle support.	Long	Remove support and shim, realign support saddle/base to properly support the pipe, and provide Teflon pad between saddle support and pipeline.
F24.009	A8	LAT-47	RHTF		pipeline is not adequately supported. Saddle is not engaged, wood shim is used, and saddle is not secured to I-beam support.	Long	Replace pipe support at this location with a suitable saddle of sufficient height to properly support the pipe and secure support to the I-beam structure. Provide Teflon pad between saddle support and pipeline.
F24.010	A11		RHTF		pipeline is unsupported between supports, approximately 58	Long	Shim the pipe or pipe supports to uniformly support the pipe.
F24.011	A11		RHTF		(b) (3) (A) is unsupported between supports. Support is partial engagement on one side of the pipeline.	Long	Shim the pipe or pipe supports to uniformly support the pipe.

	Assessed to C. A.D.	r	r ·	r	Table 7 - F-24 Findings and Recommendations	r	
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F24.012	A12		RHTF	(b) (3) (A)	Threaded 2 carbon steel low point drain valve is located on Valve classification is unknown.	Urgent	Replace valve with a Class 150 ball valve.  Long term consideration should be given to replacing the threaded valve and piping with welded pipe and flanged ball valve.
F24.013	A13		RHTF		Non-standard flanges and non-standard weld tie-ins at the cross- tunnel pipeline tees.	Long	Consider upgrading to ASME B16.5 rated flanges and fittings with buttwelded arrangements at cross-tunnel pipeline connections.
F24.014	A14		RHTF		Two loose joint harness fasteners were noted on the Dresser coupling on the Discourage pipeline.	Urgent	Tighten fasteners per manufacturers or designer of record specifications.
F24.015	A15		RHTF		Metal-to-metal contact between the (b) (3) pipeline and Unistrut support has caused coating failure and surface corrosion.	Long	Modify Unistrut support to eliminate metal-to-metal contact and spot repair coating system at the affected area.
F24.016	A16		RHTF		welded and flanged branch connection on top of the pipeline. Six of the flange fasteners are not fully engaged.	Urgent	Replace hardware to ensure fasteners are fully engaged (nuts are fully engaged with threaded bolts).
F24.017	B48 Table H		Harbor Tunnel		The pipeline is covered by a protective wrap throughout the Harbor Tunnel. Protective wrap is failing in numerous locations and prohibits external inspection of the piping condition.	Long	Remove protective pipe wrap and perform visual inspection of these sections of pipe for external corrosion.
F24.018	B10 Table H	HT-1 HT-9 HT-16 HT-17 HT-23 HT-24 HT-37 HT-40	Harbor Tunnel		Several areas of coating failure with minor to moderate corrosion was observed on the (b) (3) (A) See Table H in API 570 report for exact locations.	Long	Clean, prep and recoat affected areas.
F24.019	В1		Harbor Tunnel		Moderate coating failure and moderate corrosion on pipe, flanges, fasteners, and components on the (a) (b) (b) (b) (c) (d) (d) (d) (d) (d) (d) (d) (d) (d) (d	Long	Seal the tunnel or provide ceiling trays to prevent further deposits on the pipeline. Clean, prep, and recoat affected area.
F24.020	B7		Harbor Tunnel		There are two high point vents on the pipeline between the UGPH concrete bulkhead and 690 (within the vicinity of Valve 0151) that are constructed of threaded valves, nipples, and piping. Staining and weeping were noted around the threaded fittings. Valve classifications are unknown.	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps. Replace valves with Class 150 carbon steel ball valves.  Long term consideration should be given to replacing the high point vent piping and valves with welded pipe with flanged connections.
F24.021	B7 B8		Harbor Tunnel		There are two low point drains on the between the UGPH concrete bulkhead and 690 that are constructed of threaded valves, nipples, and piping. Notable corrosion was observed on the LPD just before the bulkhead to the UGPH. Valve classifications are unknown.	Urgent	Replace low point drains with Class 150 carbon steel ball valves, replace corroded piping, and recoat affected areas.  Long term consideration should be given to replacing the low point drain piping and valves with welded pipe with flanged connections.
F24.022	B20		Harbor Tunnel		A non-standard repair at the bulkhead between 651 and 652 was noted. The repair includes a full encirclement welded split sleeve (clamshell) on 652 side and a partial patch plate style repair on 651 side of the bulkhead with square corners.	Other	This repair is scheduled for completion.

					Table 7 - F-24 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F24.023	В9		Harbor Tunnel	(b) (3) (A)	The (a) (b) (b) was manufactured with four studs on the top and four studs on the bottom of the valve flanges where clearance to install a hexagonal bolt behind the flange is not possible. The threaded studs are not fully engaged at these locations. Engagement between 0.250 and 0.550 inches was observed with the valve flange.	Urgent	Replace fasteners that are not fully engaged per manufacturers recommendations.
F24.024	B15 Table F	HT-4 HT-18	Harbor Tunnel		Several dents were present on the (1) (3) (A) within the harbor tunnel. See Table F in API 570 report for exact locations.	Long	The assessment indicates dents are within acceptable limits per API 579 Section 12 Level 1 assessment. Monitor dent locations at next API 570 inspection.
F24.025	B18		Harbor Tunnel		Several HPVs and LPDs throughout the harbor tunnel. These are composed of threaded valves, piping, and components. Minor staining was noted on some of these fittings. Also, the valve classifications in several locations are unknown. Locations include:  1 threaded plug on top of pipe 650 and 651)  1 threaded plugon top of pipe 597 and 598)  Two 2 high point vents 595 and 596)  1 5 high point vent 277 and 278)  high point vent 276 and 278)  high point vent 267 and 268) (weeping)  high point vent 189 and 190)  1.5 threaded plug on bottom of pipe 144 and 146)  1.5 low point drain 106 and 107)  high point vent 106 and 107)	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps at the high point vent between 267 and 268.  Replace all associated valves with Class 150 ball valves.  Long term consideration should be given to replacing threaded connections with welded and flanged connections.
F24.026	B50		Harbor Tunnel		There are several plates that are tack welded to the pipeline. These plates do not appear to serve a purpose.	Long	Remove tack welded plates/attachments, grind down, and perform additional NDE at these areas.
F24.027			UGPH		The gate valves within the piping systems inside the underground pumphouse are weeping and require continuous maintenance	Long	Remove the gate valves and install ball valves. It is recommended to program this valve replacement after defueling of RHTF is complete.
F24.028	C9		UGPH		The ball valve on the strainer drains associated with the pump discharge control valves are not plugged.	Long	Provide threaded plugs to prevent accidental discharge of fuel product.
F24.029	C14		UPGH		The small isolation ball valves on the pump discharge control valve tubing are missing operating handles. This will prevent isolation in the event of an emergency such as a tubing break or damage to isolate the fuel leak.	Long	Provide operating handles on ball valves and consider a car-seal to lock valves in desired position.
F24.030	C15		UPGH		Minor bearing oil staining was noted on pump casings.	Long	Perform routine cleaning and removal of bearing oil staining from pump casings.
F24.031	C18		UPGH		Conduit plug is being used to plug tee fitting on pressure gauge assemblies.	Urgent	Install appropriate threaded pipe plugs on tee fittings.
F24.032	C26		UGPH		Moderate weeping/staining on front bearing shaft and casing of pump.	Long	Perform routine cleaning and removal of oil staining from pump casings.

					Table 7 - F-24 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F24.033	C31		UGPH	(b) (3) (A)	One loose joint harness fastener was noted on the Dresser coupling on the discharge side of Pump 209.	Long	Tighten fasteners per manufacturers or designer of record specifications.
F24.034	C32		UGPH		Two loose joint harness fasteners were noted on the Dresser coupling on the discharge side of Pump 210.	Long	Tighten fasteners per manufacturers or designer of record specifications.
F24.035	C33		UGPH		Dresser coupling lugs on pump suction side are installed backwards.	Long	Repair dresser coupling lugs to be installed correctly.
F24.036	<b>C37</b>		UGPH		Fuel staining and weeping was noted on the pipe tie-ins associated with the temperature sensors, pressure sensors, high point vents, and low point drains. Weeping is present at threaded connections associated with these fittings. The following locations should addressed:  PIT-301 and adjacent Temperature Sensor  Valve GI58B  Valve GI38B  Valve GI38B  Valve GI48B  Valve GI48B  Valve GI48C  Valve GI48D	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps.  Long term consideration should be given to replacing threaded connections with welded connections where possible.
F24.037	C38		UGPH		Several threaded fittings were noted throughout the UGPH piping below the grating on the main header piping. Some of the branch connections welds are not per industry standard (did not use Weldolet or other approved branch connections).	Long	Replace threaded fitting and pipe with welded connection and replace branch connections with industry approved connections.
F24.038	C40		UGPH		Several transducers are attached to the piping and the conduits do not have seal off fittings. Additionally, the conduits are ridged which could break under pipe movement.	Long	Provide appropriate seal fittings and flexible conduit connections at transducers.
F24.039	C41		UGPH		It was noted that several of the pressure transducers are past due for calibration. (Calibration due date of 10/23/18)	Urgent	Perform calibration of all temperature and pressure devices in the UGPH.
F24.040	C42		UGPH		There is staining and some minor drips noted on the Cameron ball valves throughout the UGPH. Drips appear to be coming from the stem injection port.	Long	Clean valve body, service stem nut/upper stem seal to prevent future weeps/drips.
F24.041	C46		UGPH		There is a 3/4 high point vent located on the 16 F-24 pipeline downstream of MOV 216E3. The 3/4 piping terminates just before the UGPH sump and is lacking a threaded pipe plug.	Urgent	Provide threaded pipe plug to prevent accidental discharge of product from high point vent. Consideration should be given to modify the high point vent piping, so it terminates near the high point vent.
F24.042	C47		UGPH		There is a 3/4 threaded valve mounted on the side of the There is no pipe cap or plug at the end of the valve. Note: It is not clear as to the purpose of this connection Valve classification is unknown.	Urgent	Provide plug or cap to prevent accidental discharge of product. Replace valve with Class 150 ball valve.  Long term consideration should be given to removing this connection if it serves no purpose.

					Table 7 - F-24 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F24.043	C48 C54		UGPH	(b) (3) (A)	There was noticeable fuel drips and weeps coming from pressure relieving devices on the valve above the grating. (Cla Val relief devices)	Urgent	Service pressure relieving devices to prevent future weeps. If valves are not serviceable, consideration should be given to replacement of these valves. Perform routine pressure testing/calibration of pressure relieving devices.
F24.044	C49		UGPH		Mechanical dent was found on the to/from the surge tank. Dent depth is 0.505 inches with perpendicular orientation and length of 5 inches located 58 inches from the miter weld before the surge tank-to-UGPH bulkhead penetration. This results in a dent depth of 3 2%. Assessment indicates this dent is acceptable based on latest edition of API RP 1183; Assessment and Management of Pipeline Dents. Plain dents regardless of shape with depths up to 10 % of the pipe diameter, without coincident features such as metal loss, welds, or cracks have been shown in testing to have the same failure pressure as plain line pipe (Section 1). Dent is also acceptable per API 579 Section 12 Level 1 assessment (acceptable if it is ≤ 7% of the pipe diameter).	Long	Monitor at next API 570 Inspection.
F24.045	C51		UGPH	Ti i	Valve flange for the 12 gate valves is missing a fastener.	Urgent	Install new fastener on valve flange.
F24.046	C52		UGPH		It was also noted that there are no pressure relief devices installed on the header piping.	Long	Provide pressure relief devices to prevent an over pressurization of the header piping.
F24.047	C53		UGPH		All the gate valves on the suction and discharge side of the pumps are equipped with motorized valve actuators. It was observed that the motorized valve actuators are mounted on a stich welded adapter plate. Several of the stitch welds have hairline cracks present and could cause the adapter plate to shear off during actuator operation.	Long	Remove coating and perform further weld inspection.
F24.048	C56		UGPH		The pressure relief system has an Emerson Figure 533 flow control valve with hydramotor actuator. The hydramotor actuator still has the factory plastic caps installed in the unused conduit inlet ports.	Long	Remove plastic caps and provide threaded steel conduit plugs.
F24.049	D1		UGPH		Several locations where the Teflon pad is missing between pipe and pipe support, creating metal-to-metal contact.	Long	Provide Teflon isolation pads to eliminate metal-to-metal contact between support and pipe.
F24.050	D3		UGPH		The 1 ball valve associated with the sample/water drain line that ties into the 4 low suction line was observed as open and not secured. This could create a potential for a fuel spill. Valve was closed during our inspection.	Long	Consider a self-closing/spring loaded ball valve to prevent the valve from being inadvertently left open which could cause an accidental fuel spill.
F24.051	LRUT Results CML# B17		Harbor Tunnel		An area of inactive pitting (approximately 0.050 inches deep) with some large area scaling was identified. An additional two areas of possible corrosion of similar magnitude of pitting are suspect under the pipe wrap at this location.	Urgent	Remove the pipe wrap and inspect these areas on the pipeline.

					Table 8 - F-24/JP-5 Pipe Support Findings and Recommendat	ions	
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
685	B14 Table E2		Harbor Tunnel	(b) (3) (A)	Severely corroded base plate and bottom of column, loss of steel in column, delamination of base plate, no grout pad, F-24 connected to wall severely corroded.	Urgent	Replace support.
596	B14 Table E2		Harbor Tunnel	W 10	Severe corrosion and loss of support at baseplate and lower column connection.	Urgent	Replace support, support on minimum 6" raised concrete pier.
592			Harbor Tunnel		Extreme corrosion with no or very little material at any number of locations, active dripping.	Urgent	Replace support, support on minimum 6" raised concrete pier.
510	Table E2	HT-33	Harbor Tunnel		Corrosion to loss of support, wall anchors not visible.	Urgent	Replace support.
493		HT-32	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, complete deterioration through bottom front flange of both columns, extreme deterioration of anchor bolts over back flange of both columns.	Urgent	Replace support.
492	Table E2	HT-32	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, severe corrosion over entire support complete less of support at bottom of both columns and both flanges, delamination (severe) at baseplate, angles to wall severely deteriorated. API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
475	Table E2		Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, wall anchor not visible, flanges at angle column not attached to baseplate, severe delamination at baseplate.  API 570: Support wear plate to support not engaged (JP-5) (floating pipe).	Urgent	Replace support.
473			Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme corrosion at baseplate and column flanges, appears unattached and detached when sounded.	Urgent	Replace support.
472	Table E2		Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme delamination at baseplate, columns not attached due to extreme deterioration, JP-5 bracket to the wall deteriorated and detached.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
469			Harbor Tunnel		Severe corrosion w/ significant loss of material at any number of locations, column flange deformed	Urgent	Replace support.
468	8	8	Harbor Tunnel		Severe corrosion w/ significant loss of material at any number of locations, column flange deformed	Urgent	Replace support.
467			Harbor Tunnel		Severe corrosion w/ significant loss of material at any number of locations, column flange deformed	Urgent	Replace support.
466			Harbor Tunnel		Severe corrosion w/ significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.

					Table 8 - F-24/JP-5 Pipe Support Findings and Recommendat	tions	
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
411	111111111111111111111111111111111111111	-	Harbor Tunnel	(b) (3) (A)	Severe corrosion w/ loss of material at any number of locations, grout pad broken, loss of bearing.	Urgent	Replace support.
399			Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, JP-5 at wall.	Urgent	Replace support.
310	Table E2	HT-26 HT-28	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, column flanges completely deteriorated at slab, baseplate is dust, JP-5 attachments to wall completed corroded not attached at (1) side.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
306			Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme corrosion at bottom of column and significant loss of column flange section at baseplate interface.	Urgent	Replace support.
305	B32 Table E2	HT-26	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, column moderately corroded, JP-5 anchor to wall complete section loss.  API 570: Corrosion on pipe support at the tunnel wall attachment.	Urgent	Replace support.
304		HT-26	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, moderate column corrosion, complete loss of section at JP-5 and F-24 anchor to wall on 1 side	Urgent	Replace support.
288			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, impacted and deformed column flanges.	Urgent	Replace support.
48	A7 A10 Table E1 Table E2	LAT-41 LAT-42	RHTF		Severe corrosion and loss of support at train-side column (photo), minor corrosion at center column baseplate, grout pad edges destroyed at center column baseplate (photo), severe corrosion and loss of material at beam near wall (photo) API 570: Metal to metal contact. No Teflon shims/insulation strip. Rail-ties wedged between pipe and saddle (F-24). Corrosion on base of pipe support and I-beam.	Urgent	Replace support. This repair is scheduled for completion.
47	A7 Table E1 Table E2	LAT-38 LAT-40	RHTF		Severe corrosion and loss of support at bottom of column, minor flange deformation at free end, corrosion at JP-5 saddle, corrosion and loss of angle at lower angle support, no saddle at F-24.  API 570: Metal to metal contact. No Teflon shims/insulation strip.  Missing steel saddle (floating pipe) (F-24). Corrosion on base of pipe support and I-beam.	Urgent	Replace support. This repair is scheduled for completion.

	V.	10			Table 9 - JP-5 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
JP5.001		PM-19 PM-20 PM-21 PM-22	RHTF	(b) (3) (A)	Dresser Couplings are installed in tank piping laterals.	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
JP5.002	A20		RHTF		The 2 high point vent piping on the (0) (3) (A) is threaded and extends down below the pipe. Pipe extends into personnel movement space below and is at risk for possible damage from impact.	Long	Replumb high point vent piping such that it does not extend into personnel movement space and is constructed of welded pipe and flanged components.  Note: This repair is currently programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
JP5.003			RHTF		Tank sample piping downstream of the isolation valve are open to the atmosphere. If the isolation valves were to be bumped or inadvertently forced open, this could lead to an accidental fuel spill.	Urgent	Provide threaded caps on tank sample piping downstream of isolation valves.  NOTE: This deficiency has been corrected for the tanks that have been previously cleaned, inspected, and repaired.
JP5.004	A2		RHTF		Minor staining, indicative of a minor fuel weep, on the upstream body threaded plug associated with 12 DBB tank isolation valve.	Long	Tighten threaded plug and monitor as needed until it is repaired.  Remove plug from the valve body and retape and reinstall to prevent future weeps. NOTE: Removal of plug cannot be performed without taking the tank out of service.
JP5.005	А3		RHTF		HPV on Tank 16 jet fuel piping downstream of the 12 tank isolation valve is missing a threaded plug. Some fuel was noted inside the valve body.	Urgent	Provide threaded plug on high point vent.
JP5.006	A4		RHTF		The DBB valves are equipped with a drain valve in lieu of a plug. The end of the valves is not secured with a pipe plug.  Tank 7 – 20 & 12 DBB  Tank 8 – 12 DBB  Tank 9 – 20 DBB  Tank 10 – 20 DBB	Urgent	Provide threaded plug on ball valve drain.
JP5.007	A13		RHTF		Non-standard flanges and non-standard weld tie-ins at the cross- tunnel pipeline tees.	Long	Consider upgrading to ASME B16.5 rated flanges and fittings with buttwelded arrangements at cross-tunnel pipeline connections.
JP5.008	A19		RHTF		Coating failure and corrosion between pipe and pipe support on the (3) (A)	Long	Remove pipe support, clean, and recoat affected area, and reinstall pipe support. Secure saddle support to support beam and provide Teflon pad between support and pipe to eliminate metal-to-metal contact. NOTE: This may require replacement of the affected pipe supports.
JP5.009	A19		RHTF		Coating failure and corrosion between pipe and pipe support on the (0) (3) (A)	Long	Remove pipe support, clean, and recoat affected area, and reinstall pipe support. Secure saddle support to support beam and provide Teflon pad between support and pipe to eliminate metal-to-metal contact. NOTE: This may require replacement of the affected pipe supports.

					Table 9 - JP-5 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
JP5.010	A19		RHTF	(b) (3) (A)	Coating failure and corrosion between pipe and pipe support on the (b) (3) (A)	Long	Remove pipe support, clean, and recoat affected area, and reinstall pipe support. Secure saddle support to support beam and provide Teflon pad between support and pipe to eliminate metal-to-metal contact. NOTE: This may require replacement of the affected pipe supports.  Note: This segment of piping (8ft pup) is currently being replaced as part of the FY21 Emergent Pipeline Repair Project.
JP5.011	A19		RHTF		Coating failure and (b) (3) (A)	Long	Remove pipe support, clean, and recoat affected area, and reinstall pipe support. Secure saddle support to support beam and provide Teflon pad between support and pipe to eliminate metal-to-metal contact. NOTE: This may require replacement of the affected pipe supports.
JP5.012	A18	LAT-50	RHTF		Coating failure and corrosion due to mineral deposits on the No significant pitting was observed.	Long	Clean and recoat affected area of the pipeline.
JP5.013	A17		RHTF		High point vent with threaded fittings and a brass (low melting point) valve on top of the (10) (3) (A) Valve classification is also unknown.	Urgent	Replace high point vent valve with Class 150 ball valve.  Long term consideration should be given to replacing high point vent assembly with welded pipe and valve with flanged connections.  Note: This repair is currently programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
JP5.014	LRUT Results CML# B26		Harbor Tunnel		One indication was observed approximately -460 inches from setup on the (b) (3) (A)	Urgent	Remove pipe wrap and inspect the pipeline at these locations.
JP5.015	B47		Harbor Tunnel		Out-of-round (flat spot) noted on the (b) (3) (A) at the bell-weld between the 12 o'clock and 3 o'clock position.	Other	No action needed to perform defuel operations. Evaluate at the next API 570 inspection.
JP5.016	B44		Harbor Tunnel		The (b) (3) (A) is unsupported and unreinforced. Branch line does not appear to be in use and blinded with a skillet and flange.	Long	Remove unused branch connection.
JP5.017	B40		Harbor Tunnel		Pitting corrosion on (b). (3) (A) at the 2 o'clock position. Corrosion areas is 2 by 2 with a pit depth measurement of 0.113 inches. Remaining metal thickness of 0.120 to 0.125 inches. Metal thickness of unaffected area is 0.233 to 0 238 inches. Approximate wall loss of 48.5%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
JP5.018	B33		Harbor Tunnel		Inactive pitting on the (b) (3) (A) at the 10 o'clock position. Corrosion area is 8 by 8 with pit depth measurements of 0.050 to 0.135 inches. Remaining metal thickness of 0.091 to 0.099 inches. Metal thickness of unaffected area is 0.226 to 0 234 inches. Approximate wall loss of 59.7%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.

					Table 9 - JP-5 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
JP5.019	B34		Harbor Tunnel	(b) (3) (A)	Inactive pitting on the (b) (3) (A) at the 5 o'clock position. Corrosion area is 6 by 6 with pit depth measurements of 0.050 to 0.089 inches. Remaining metal thickness of 0.152 to 0.156 inches. Metal thickness of unaffected areas is 0.234 to 0.241 inches. Approximate wall loss of 38%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
JP5.020	B31		Harbor Tunnel		Pitting corrosion was observed at the 6 o'clock position on the Corrosion areas is 10 by 10 with pit depth measurements of 0.055 to 0.102 inches. Remaining metal thickness of 0.116 to 0.136 inches. Metal thickness of unaffected areas is 0 218 to 0.238 inches. Approximate wall loss of 46.8%	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
JP5.021	B26		Harbor Tunnel		Heavy pitting was observed on the piping at the 9.0'clock position on the 18 JP-5 pipeline. Corrosion area is 9 by 9 with pit depth measurements of 0.050 to 0.140 inches. Metal thickness of unaffected area is 0.239 to 0 244 inches. Approximate wall loss of 58.6%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
JP5.022	B49		Harbor Tunnel		Heavy pitting was observed on the piping at the 2-6 o'clock positions on the 18 JP-5 pipeline at the interface where the piping penetrates the concrete bulkhead. Pit depth measurements of 0.0625 to 0.105 inches. Metal thickness of the unaffected area is 0.240 to 0.243 inches. Remaining metal thickness of 0.135 to 0.138 inches. Approximate wall loss of 43 8% wall loss.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup. Note, this will require removal of the pipeline within the concrete bulkhead.
JP5.023	B48 Table H		Harbor Tunnel		The pipeline is covered by a protective wrap throughout the Harbor Tunnel. Protective wrap is failing in numerous locations and prohibits external inspection of the piping condition.	Long	Remove protective pipe wrap and perform visual inspection of these sections of pipe for external corrosion.
JP5.024	B10 Table H	HT-1 HT-16 HT-17 HT-23 HT-24 HT-41 HT-48 HT-50 HT-51	Harbor Tunnel		Several areas of coating failure with minor to moderate corrosion was observed on the 18 JP-5 pipeline. See Table H in API 570 report for exact locations.	Long	Clean, prep and recoat affected areas.
JP5.025	B1	HT-52	Harbor Tunnel	3	Moderate coating failure and moderate corrosion on pipe, flanges, fasteners, and components on the 18 JP-5 pipeline due to mineral deposits and water infiltrating through tunnel ceiling.	Long	Seal the tunnel or provide ceiling trays to prevent further deposits on the pipeline. Clean, prep, and recoat affected area.

				77	Table 9 - JP-5 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
JP5.026	B5 B6		Harbor Tunnel	(b) (3) (A)	between the UGPH concrete bulkhead and 690 that are constructed of threaded valves, nipples, and piping. There is evidence of fuel staining and weeping noted around the threaded fittings. Moderate corrosion was observed on low point drain piping adjacent to 690. Notable corrosion was observed on LPD pipe adjacent to isolation valve #0156. Valve classification is unknown.	Urgent	Remove, retape, and reassemble threaded connections. Replace low point drains with Class 150 carbon steel ball valves. Recoat affected areas to prevent further corrosion. Replace corroded piping with new.  Long term consideration should be given to replacing the low point drain piping and valves with welded pipe with flanged connections.
JP5.027	B12		Harbor Tunnel		Non-standard flange construction at 12 branch connection on the (b) (3) (A) Blind flange was constructed with 12-weldneck flange with a flat plate welded to flange for blind.	Long	Replace non-standard blind with a 12 blind flange per ASME B16.5.
JP5.028	B13		Harbor Tunnel		Moderate oil staining noted on the 12 DBB valve gear box.	Long	Clean up gear box and ensure covers are secured to prevent future oil leaks. Verify sufficient lubricant is still present and if needed service actuator gear box.
JP5.029	B27		Harbor Tunnel		Tack weld fit up tab is located on the (b) (3) (A) at the 12 o'clock position.	Long	Remove temporary attachment on the pipeline and perform NDE.
JP5.030	B29		Harbor Tunnel	<del>-</del>	Several active and inactive pitting locations and general corrosion was noted on the (5) (3) (A) at the 12 o'clock position. Location is approximately 21-inches from 475. Pit depth measurement of 0.095 inches. Remaining wall thickness of 0.130" to 0.147" is estimated at this location. Metal thickness of unaffected areas is 0.225 inches. Approximate wall loss of 42.2%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
JP5.031	B15 Table F	HT-4 HT-18	Harbor Tunnel		Several dents were present on the (b) (3) (A) within the harbor tunnel. See Table F in API 570 report for exact locations.	Long	The assessment indicates dents are within acceptable limits per API 579 Section 12 Level 1 assessment. Monitor dent locations at next API 570 inspection.
JP5.032	B18		Harbor Tunnel		Several HPVs and LPDs throughout the harbor tunnel. These are composed of threaded valves, piping, and components. Minor staining was noted on some of these fittings. Also, the valve classifications in several locations are unknown.  1 high point vent 650 and 651)  Two 2 high point vent 650 and 651)  1 which point vent 650 and 651)  1 threaded plug on top of pipe 311 and 312)  1 threaded plug on top of pipe 311 and 312)  1 threaded plug on top 6 pipe 300 and 301)  1 threaded plug on top 298 and 299) (weeping)  2 high point vent 277 and 278)  1 which point vent 276 and 277)  Two 1 state threaded plugs on top 315 and 3216)  Two 1 high point vent 206 and 207)  high point vent 205 and 206)	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps at the two high point vents between \$595 and \$596 and the threaded plug between \$298 and \$299. Replace all associated valves with Class 150 ball valves.  Long term consideration should be given to replacing threaded connections with welded and flanged connections.

					Table 9 - JP-5 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
JP5.033	B50		Harbor Tunnel	(b) (3) (A)	There are several plates that are tack welded to the pipeline. These plates do not appear to serve a purpose.	Long	Remove tack welded plates/attachments, grind down, and perform additional NDE at these areas.
JP5.034			UGPH		The gate valves within the piping systems inside the underground pumphouse are weeping and require continuous maintenance.	Long	Remove the gate valves and install ball valves. It is recommended to program this valve replacement after defueling of RHTF is complete.
JP5.035	C9		UGPH		The ball valve on the strainer drains associated with the pump discharge control valves are not plugged.	Urgent	Provide threaded plugs to prevent accidental discharge of fuel product.
JP5.036	C14		UPGH		The small isolation ball valves on the pump discharge control valve tubing are missing operating handles. This will prevent isolation in the event of an emergency such as a tubing break or damage to isolate the fuel leak.	Urgent	Provide operating handles on ball valves and consider a car-seal to lock valves in desired position.
JP5.037	C15		UPGH		Minor bearing oil staining was noted on pump casings.	Other	Perform routine cleaning and removal of bearing oil staining from pump casings.
JP5.038	C18		UPGH		Conduit plug is being used to plug tee fitting on pressure gauge assemblies.	Urgent	Install appropriate threaded pipe plugs on tee fittings.
JP5.039	C26		UGPH		Moderate weeping/staining on front bearing shaft and casing of pump.	Long	Perform routine cleaning and removal of oil staining from pump casings.
JP5.040	C28		UGPH		Inactive corrosion and bolt diameter reduction was noted on the follower bolts associated with the suction side dresser coupling.	Long	Replace dresser coupling follower bolts. Monitor for damage until repair is complete.
JP5.041	C29		UGPH		Housing on flow switch mounted on discharge side of pump is not secured and loose. Current configuration does not meet hazardous area rating.	Long	Secure housing and properly seal all conduit connections.
JP5.042	C30		UGPH		1/2 piping and pressure gauge assembly was observed to be weeping on the discharge side of 208.	Long	Disassemble piping and gauge, retape threaded connections, and reassemble to prevent future weeps.
JP5.043	C33		UGPH		Dresser coupling lugs on pump suction side are installed backwards.	Long	Repair dresser coupling lugs to be installed correctly.
JP5.044	<b>G</b> 7		UGPH		Fuel staining and weeping was noted on the pipe tie-ins associated with the temperature sensors, pressure sensors, high point vents, and low point drains. Weeping is present at threaded connections associated with these fittings.	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps.  Long term consideration should be given to replacing threaded connections with welded connections where possible.
JP5.045	C38		UGPH		Several threaded fittings were noted throughout the UGPH piping below the grating on the main header piping. Some of the branch connections welds are not per industry standard (did not use Weldolet or other approved branch connections).  - PIT-284 and adjacent Temperature Sensor  - Valve GI15D  - Valve GI35E  - Valve GI25B  - Valve GI25C	Long	Replace threaded fitting and pipe with welded connection and replace branch connections with industry approved connections.

					Table 9 - JP-5 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
JP5.046	C40		UGPH		Several transducers are attached to the piping and the conduits do not have seal off fittings. Additionally, the conduits are ridged which could break under pipe movement.	Urgent	Provide appropriate seal fittings and flexible conduit connections at transducers.
JP5.047	C41		UGPH		It was noted that several of the pressure transducers are past due for calibration. (Calibration due date of 10/23/18)	Urgent	Perform calibration of all temperature and pressure devices.
JP5.048	C42		UGPH		There is staining and some minor drips noted on the Cameron ball valves throughout the UGPH. Drips appear to be coming from the stem injection port.	Urgent	Clean valve body, service stem nut/upper stem seal to prevent future weeps/drips.
JP5.049	C48 C54		UGPH		There was noticeable fuel drips and weeps coming from pressure relieving devices on the valve above the grating. (Cla Val relief devices)	Urgent	Service pressure relieving devices to prevent future weeps. If valves are not serviceable, consideration should be given to replacement of these valves.
JP5.050	C52		UGPH		The JP-5 header manifold has a 3/4 gate valve (Valve GP98J) at the end of the header. The 3/4 valve is allowing product to weep by and drip into a catchment basin. It was also noted that there are no pressure relief devices installed on the header piping.	Long	Provide pressure relief devices to prevent an over pressurization of the header piping.
JP5.051	C53		UGPH		All the gate valves on the suction and discharge side of the pumps are equipped with motorized valve actuators. It was observed that the motorized valve actuators are mounted on a stich welded adapter plate. Several of the stitch welds have hairline cracks present and could cause the adapter plate to shear off during actuator operation.	Long	Remove coating and perform further weld inspection.
JP5.052	C55		UPGH	7):	4 gate valve is weeping at bonnet.	Urgent	Service valve to prevent future weeps. If valve cannot be serviced, consider for replacement.
JP5.053	C56		UGPH	-	The pressure relief system has an Emerson Figure 533 flow control valve with hydramotor actuator. The hydramotor actuator still has the factory plastic caps installed in the unused conduit inlet ports.	Long	Remove plastic caps and provide threaded steel conduit plugs.
JP5.054	D1		UGPH		Several locations where the Teflon pad is missing between pipe and pipe support, creating metal-to-metal contact.	Long	Provide Teflon isolation pads to eliminate metal-to-metal contact between support and pipe.
JP5.055	D4 D5 D6		UGPH		Some minor staining was noted on the bottom of the flanges for the (19) (3) (A) near Surge Tank 1 and Surge Tank 2. No active weeping was noted. Liquid does not appear to be fuel as there was no presence of odor.	Long	Clean flange and monitor for future weeps. Repair as needed.
JP5.056	D7		UGPH	-	The 1 ball valve that is mounted on the 4 low suction line at Surge Tank 2 is missing a plug.	Urgent	Install a plug to prevent accidental fuel release.
JP5.057	F1		RHTF		Dresser coupling joints and associated joint harness at Tanks 18, 19, and 20 are damaged due to the May 6 <sup>th</sup> event.	Other	The lateral piping associated with Tanks 18, 19, and 20 are currently under repair as part of the FY21 Emergent Pipeline Repair Project.
JP5.058	F4		RHTF		Facility piping at the tank piping laterals tees have nonstandard rated flanged fittings and non-standard weld tie-ins. Noted at Tank 11/12, 13/14, 15/16.	Long	Replace fittings with ASME B16.5 fittings and flanges at these locations.

					Table 9 - JP-5 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
JP5.059	F5		RHTF	(b) (3) (A)	Heavy corrosion with pitting was located at the rolled 45-degree elbows. Corrosion is due to active drips from the tunnel ceiling mineral deposits. Nominal thickness was likely 0 375". The general metal thickness at this area is now 0.300" with a pit depth of 0.100" resulting in a remaining thickness of 0.200".	Other	This segment of piping is currently under repair as part of the FY21 Emergent Pipeline Repair Project. No further action is recommended.
JP5.060	F6	LAT-12 LAT-14	RHTF		A section of (b) (3) (A) is not adequately supported at \$11 resulting in an unsupported pipe span of 44 between \$10 and 12. The maximum suggested pipe support spacing for NPS 18 pipe is 28	Long	Install saddle supports between the pipe and I-beam at 11.  Note: This repair is currently programmed as a predictive repair as part of the FY21 Emergent Pipeline Repair Project.
JP5.061	F7		RHTF		A section of NPS 18 piping is not adequately supported at resulting in an unsupported pipe span of 30 between 12 and concrete penetration at Door C. The maximum suggested pipe support spacing for 18 between 29 JP-5 pipeline is 28	Long	Install saddle supports between the pipe and I-beam at 13.  Note: This repair is currently programmed as a predictive repair as part of the FY21 Emergent Pipeline Repair Project.
JP5.062	F9	20	RHTF		There is moderate coating failure and associated corrosion on the MOV-0163 DBB valve and associated hardware. Corrosion on fasteners, flanges, valve body, and relief pipe nipples was noted.	Long	Replace the coating on the DBB valve and associated hardware.
JP5.063	F10		RHTF		The MOV-0163 DBB body cavity relief nipple is in contact with the galvanized conduit. Potential for further corrosion due to dissimilar metal contact is present.	Long	Reroute conduit or DBB relief piping to eliminate metal-to-metal contact/interference.
JP5.064	F11		RHTF		There is heavy corrosion on the MOV-0163 DBB flanges promoting crevice corrosion on the fasteners.	Long	Replace fasteners.
JP5.065	F12		RHTF		There is heavy corrosion on the conduit and fittings associated with MOV-0163.	Long	Replace corroded conduit and associated fittings on MOV-0163.
JP5.066	F13		RHTF	II)	There is a threaded nipple (high point vent) near Tanks 11 and 12 installed with a 3/4 ball valve. Note: There is staining/wetting on the lower threaded fitting. Location is between 38 and 39.	Urgent	Product staining was noted at threaded connections. Urgent repair should be to disassemble threaded joints, clean, retape, and reassemble to prevent future weeps.  Long term consideration should be given to replacing high point vent assembly with welded pipe and valve with flanged connections.  Note: This is programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
JP5.067	F14 Table F		RHTF		A dent has been identified with a depth of 0.950 and needs to be repaired prior to returning the JP5 pipeline above valve MOV-0163 back to service. An additional 10 dents were located from MOV-0163 to Tank 20. Refer to Table F in the API 570 report in Appendix C for exact dent locations of the other 10 dents.	Other	This segment of piping has been repaired by pup replacement as part of the FY21 Emergent Pipeline Repair Project. Recommendation for the other ten dents is to monitor at the next API 570 inspection.

	No.	10			Table 9 - JP-5 Findings and Recommendations		
item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
JP5.068	F15		RHTF	(b) (3) (A)	Facility piping girth (circumferential) welds include several non- typical bell and spigot style fillet welds. Some welds are direct bell- bell buttweld attachments. These welds appear to be part of the original construction. There has been ongoing replacement effort of these welds with several identified and replaced since the 2015 API 570 inspection. There are currently ten (10) welds with a bell and spigot/ bell-bell weld configuration in the segment inspected.	Long	Replace these joints to bring the piping into current standards. Note: Bell joints are being replaced between 22 and 23 and 60 as part of the FY21 Emergent Pipeline Repair Project.
JP5.069	F16		RHTF		A weld undercut was identified on the (10), (3) pipeline (located approximately 100 inches past 40) at the 4 o'clock position. The measured depth was 1/32 This is acceptable for normal and Category M fluid service.	Long	Recoat affected area where the coating was removed for weld measurement.
JP5.070	F20		RHTF		There is an 18 dresser coupling joint and associated joint harness at 25 just past the concrete penetration. Visual inspection did not reveal any deficiencies at this location. A slight tilt was noted and documented. Approximately a 0 9-degree tilt over a 36" span was recorded.	Long	Monitor at next API 570 inspection.  Note: This is programmed for removal as part of the FY21 Emergent Pipeline Repair Project.
JP5.071	F21	PM-23	RHTF		The 18 dresser coupling joint harness has four lugs that are welded backwards on the upstream side of the coupling.	Urgent	Correct positioning of the lugs in accordance with manufacturer's recommendation.  Note: This is programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
JP5.072	F22	PM-25	RHTF		There was corrosion identified under insulation at the Tank 10 dresser coupling. Location is at the 8 o'clock to 10 o'clock position.	Long	Clean, prep, and recoat affected areas. Reinstall insulation after coating work is complete. Add inspection to the next API 570 inspection for all dresser couplings.
JP5.073	F23		RHTF		Internal portions of the piping at Tanks 18 and 20 were visual inspected to get a condition assessment. The piping is in satisfactory condition with minor pitting. Minor pitting was noted at the bottom of the pipe (likely due to standing water). Pitting depth of 0.030" to 0.050" was noted.	Long	Exercise the tank valves periodically to move product and prevent standing water at low points of the piping system.
JP5.074	F24		RHTF		Minor pipe pitting was identified on Tank 18 laterally below a bubbled coating. Piping is 16 schedule 40. Pitting depth of 0.030" to 0.070" was noted.	Long	Clean, prep, and recoat affected area.
JP5.075	F26	PM-10	RHTF		There is no hold down u-bolts or slide-guide to prevent lateral pipe movement at the end of the header pipe run (at 1).	Long	Add guided slide support with hold down lugs at 1.  Note: This repair is currently programmed as a predictive repair as part of the FY21 Emergent Pipeline Repair Project.
JP5.076	F27		RHTF		There is coating damage at the pipe repair sleeve located approximately 2.5 from 16.	Long	Clean, prep, and recoat affected areas.

	Table 9 - JP-5 Findings and Recommendations										
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs				
JP5.077	B52		Harbor Tunnel	(b) (3) (A)	A dent was observed at the bell joint. Due to location of anomaly's proximity to a weld this will not pass API 579 Section 12 Level 1 assessment. Measured depth of anomoly was 0.320 inches.	Urgent	Perform follow-on NDE examination of the weld at this location to validate if weld is acceptable for continued service.				

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.001		PM-19 PM-20 PM-21 PM-22	RHTF	(b) (3) (A)	Dresser Couplings are installed in tank piping laterals.	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
F76.002	A22		RHTF		Dresser coupling on the (a) (b) (b) is missing the deflection ring. A small gap was noted between the washer and harness lug.	Urgent	Install appropriate deflection rings and tighten fasteners per manufacturers or designer of record specifications.
F76.003			RHTF		Tank sample piping downstream of the isolation valve are open to the atmosphere. If the isolation valves were to be bumped or inadvertently forced open, this could lead to an accidental fuel spill.	Urgent	Provide threaded caps on tank sample piping downstream of isolation valves.  NOTE: This deficiency has been corrected for the tanks that have been previously cleaned, inspected, and repaired.
F76.004	A13		RHTF		Non-standard flanges and non-standard weld tie-ins at the cross- tunnel pipeline tees.	Long	Consider upgrading to ASME B16.5 rated flanges and fittings with buttwelded arrangements at cross-tunnel pipeline connections.
F76.005	A21		RHTF		The high point vent on the (b) (3) (A) is constructed with a non-standard threaded bronze/brass (low melting point) valve. Valve is located between riser tee to lateral piping and blind flange at the end of the pipe run. Valve classification is unknown.	Urgent	Replace high point vent valve with a Class 150 flanged carbon steel ball valve and welded pipe.
F76.006	A23		RHTF	_	Area of inactive corrosion observed on (b) (3) (A) between supports, approximately 108 inches from 40. Pit depth = 0.196"-0.200" and UTT of 0.430" on unaffected areas resulting in remaining thickness of 0.219" to 0.250". Approximate wall loss of 46.5%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
F76.007	A33	PM-23 PM-24	RHTF		Dresser coupling on the (b) (3) (A) was observed with backwards lugs. There are no deflection rings or adapters on the hamess lugs.	Urgent	Correct positioning of the lugs and provide deflection rings and adapters on the harness lugs. Tighten hardware on rods per manufacturer or designer of record specifications.
F76.008	A24		RHTF		pipeline is not fully supported at pipe support.	Long	Modify pipe support to adequately support pipe. Install Teflon pad between saddle support and pipeline to eliminate metal-to-metal contact.
F76.009	A24		RHTF		(b) (3) pipeline is not fully supported at pipe support.	Long	Modify pipe support to adequately support pipe. Install Teflon pad between saddle support and pipeline to eliminate metal-to-metal contact.
F76.010	A25		RHTF		Second pipe support from Tank 9 is not supporting the (b) (3)  Approximately 39 of unsupported pipe from the lateral tee to the tank.	Long	Modify pipe support to adequately support pipe.
F76.011	A26		RHTF		Several fasteners on flanges between lateral tee and (b) (3) pipeline have moderate corrosion.	Urgent	Replace corroded fasteners and remove corrosion from spectacle blind. Recoat affected area.
F76.012	A27		RHTF		Two fasteners are not fully engaged on the blind flange associated with the branch piping on bloom pipeline.	Urgent	Tighten fasteners or replace fasteners with longer bolts to ensure nuts are fully engaged.

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.013	A29		RHTF	(b) (3) (A)	Branch connection on (b) (3) (A) has a 1 threaded fitting and valve. Fuel staining was evident on pipeline but no active weeping noted.	Long	Clean the staining from the flange joint, branch pipe, and header pipe.  Monitor the location for future weeps. Replace threaded fittings and valves with welded pipe and Class 150 flanged ball valve.
F76.014	A28		RHTF		Coating failure and corrosion due to mineral deposits on (3)  No significant pitting or thickness loss noted(A)	Long	Clean and recoat affected area of the pipeline.
F76.015	A30		RHTF		Staining noted on (0) (3) (A) between tanks. No active weeping was noted. Oily substance does not appear to be F-76 fuel.	Long	Thoroughly clean tie-in connections and flanges to remove oily substance. Monitor location for potential weeps and drips.
F76.016	A31		RHTF		Wood support extending from (b) (3) (A) to tunnel ceiling. Use and function of the support is unknown and not associated with pipeline support or restraint. The wood beams do not appear to be bearing any load on the pipe based on gaps between wood and top of steel saddle as well as gaps at bolting hardware.	Long	Further investigation of the use and purpose of the wood support. Perform alternative design to remove support from pipeline and for the intended function.
F76.017	A32		RHTF		Dresser coupling on the (10) (3) (A) was observed with rod restraint that did not appear to be fully engaged/tightened. There are no deflection rings or adapters on the harness lugs. The lugs are installed backwards. Dresser coupling is located on main pipeline within the RHTF.	Urgent	Correct positioning of the lugs and provide deflection rings and adapters on the harness lugs. Tighten hardware on rods per manufacturer or designer of record specifications.
F76.018	B48 Table H		Harbor Tunnel		The pipeline is covered by a protective wrap throughout the Harbor Tunnel. Protective wrap is failing in numerous locations and prohibits external inspection of the piping condition.	Long	Remove protective pipe wrap and perform visual inspection of these sections of pipe for external corrosion.
F76.019	B10 Table H	HT-1 HT-7 HT-16 HT-17 HT-34 HT-35 HT-42 HT-43 HT-43 HT-47 HT-48 HT-49	Harbor Tunnel		Several areas of coating failure with minor to moderate corrosion was observed on the (5) (3) (A) See Table H in API 570 report for exact locations.	Long	Clean, prep, and recoat affected areas.
F76.020	B1		Harbor Tunnel		Moderate coating failure and with moderate corrosion on pipe flanges, fasteners, and components on the (5) (3) (A) due to mineral deposits and water infiltrating through tunnel ceiling.	Long	Seal the tunnel or provide ceiling trays to prevent further deposits on the pipeline. Clean, prep, and recoat affected area.

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.021	В2		Harbor Tunnel	(b) (3) (A)	The two high point vents on the (5) (6) (A) adjacent to valve 0151 and the UGPH bulkhead are constructed of threaded valves, nipples, and piping. There is evidence of fuel staining and weeping noted around the threaded fittings. Valve classification is unknown.	Urgent	Remove, retape, and reassemble threaded connections. Replace high point vent valves with Class 150 carbon steel ball valves.  Long term consideration should be given to replacing the high point vent piping and valves with welded pipe with flanged connections.
F76.022	B3 B4 B5		Harbor Tunnel		There are three low point drains on the between the UGPH concrete bulkhead and 690 that are constructed of threaded valves, nipples, and piping. There is evidence of fuel staining and weeping noted around the threaded fittings. Valve classification is unknown.	Urgent	Remove, retape, and reassemble threaded connections. Replace low point drains with Class 150 carbon steel ball valves.  Long term consideration should be given to replacing the low point drain piping and valves with welded pipe with flanged connections.
F76.023	B11		Harbor Tunnel		Four arc strikes/weld lines between the 7 o'clock and 10 o'clock positions were identified on the (b) (3) (A) Each arc strike is approximately 3 inches long and are located adjacent to the pipeline miter circumferential weld. Gouge depths range from 0.03125 to 0.09375 inches.	Long	Remove coating and conduct close visual inspection along with liquid penetrant testing or magnetic particle testing of the arc strikes and weld lines.
F76.024	B19		Harbor Tunnel		DBB isolation valve on the (b) (3) (A) is missing a nut and bolt on the top plate.	Urgent	Install new nut and bolt on the top plate of the valve.
F76.025	B51		Harbor Tunnel		There appears to be a pipe alignment tab weld that was not ground flush.	Long	Grind weld attachment flush and conduct further NDE.
F76.026	B30		Harbor Tunnel		Inactive pitting and general corrosion were observed on the was observed between 314 and 315 at the 10 o'clock position. Corrosion area is approximately 24 inches by 16 inches with the deepest pit corrosion area covering 9 inches by 9 inches with pit depths range from 0.080 to 0.140 inches. Remaining wall thickness of 0.218 to 0.221 inches is estimated at this location. Metal thickness of unaffected area is 0 358 to 0.361 inches. Approximate wall loss of 39.1%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired a this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
F76.027	B28		Harbor Tunnel		Concrete saddle support (number 337) has several 1/8 rods between the pipe and concrete saddle.	Long	Remove 1/8 rods between pipe and concrete saddle, inspect interface, and provide Teflon pad between pipe and support.
F76.028	B21		Harbor Tunnel		"Clock Spring" repair sleeve on the (b) (3) (A)	Long	Review previous documentation to determine reason for repairs.  Consideration should be given into removing the clock spring repairs and replacing the section of piping with new. Note: Replacement of the clock springs was previously mentioned as a long-term repair in EEI's 2016 "Inspection and Repair of Redhill Pipelines Report" but does not appear to be performed as part of the 2019 fuel system repairs.
F76.029	B21		Harbor Tunnel		"Clock Spring" repair sleeve on the (b) (3) (A)	Long	Review previous documentation to determine reason for repairs.  Consideration should be given into removing the clock spring repairs and replacing the section of piping with new. Note: Replacement of the clock springs was previously mentioned as a long-term repair in EEI's 2016 "Inspection and Repair of Redhill Pipelines Report" but does not appear to be performed as part of the 2019 fuel system repairs.

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.030	B38		Harbor Tunnel	(-) (-)	Concrete pipe support, PSC-501, is not engaged with pipe and the pipe is floating. Loose concrete aggregate was noted between support and pipe.	Long	Remove the loose concrete aggregate between the pipe and the support and shim with Teflon pad.
F76.031	B22		Harbor Tunnel		The concrete saddle type support is cracked.	Long	Repair concrete saddle support.
F76.032	B23		Harbor Tunnel		threaded HPV is located on the (0).(3) (A)  The ball valve does not have a lock and the reducing bushing is not fully engaged in the threaded connection. Valve classification is unknown.	Urgent	Lock 2 ball valve out. Remove the reducing bushing and install a 2- pipe plug. Replace valve with a Class 150 carbon steel ball valve.  Long term consideration should be given to replacing the threaded piping and valve with welded pipe and flanged connections.
F76.033	B24		Harbor Tunnel		Coating failure and corrosion on the welded 8 branch on the	Long	Clean, prep, and recoat affected area.
F76.034	B37		Harbor Tunnel		Wood shim installed between (b) (3) (A) and concrete saddle support number 193.	Long	Remove wood shim and provide steel plate shim and Teflon pad.
F76.035	B35		Harbor Tunnel		Inactive pitting on (b) (3) (A) at the 6 o'clock position. Corrosion area is 3 by 2 with a pit depth measurement of 0.114 inches. Remaining metal thickness of 0.269 to 0.273 inches. Metal thickness of unaffected areas is 0.383 to 0.387 inches. Approximate wall loss of 29.8%	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
F76.036	B36		Harbor Tunnel		Inactive pitting on the (6) (6) (A) at the 6 o'clock position. Corrosion area is 15 by 24 with pit depth measurements of 0.050 to 0.114 inches. Remaining metal thickness of 0.186 to 0.193 inches. Metal thickness of unaffected areas is 0.386 to 0.393 inches. Approximate wall loss of 29.5%	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
F76.037	B41		Harbor Tunnel		Pitting on the (a) (b) (b) (c) at the 11 o'clock position. Corrosion area is 18 by 24 with pit depth measurements of 0.050 to 0.120 inches. Remaining metal thickness of 0.178 to 0.201 inches. Metal thickness of unaffected areas is 0.298 to 0.321 inches. Approximate wall loss of 40.3%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
F76.038	B43		Harbor Tunnel		Longitudinal weld on the (b) (3) (A) has a 5 long area of weld porosity.	Urgent	Conduct additional NDE to evaluate the extent of the porosity in this weld.
F76.039	B42		Harbor Tunnel		One bolt is missing a nut on the flange (b) (3) (A)	Urgent	Replace fastener that has a missing nut.
F76.040	B45		Harbor Tunnel		The flanged 6 branch connection on the 32 F-76 pipeline lacks proper thread engagement on a fastener and is missing a nut on another bolt. The blind flange installed does not appear to be ASME B16.5 rated.	Urgent	Install new fasteners to ensure proper thread engagement, install new nut, and install new ASME B16.5 blind.

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.041	B15 Table F	HT-4 HT-18 HT-21 HT-24	Harbor Tunnel	(b) (3) (A)	Several dents were present on the (b) (3) (A) within the harbor tunnel. See Table F in API 570 report for exact locations.	Long	The assessment indicates dents are within acceptable limits per API 579 Section 12 Level 1 assessment. Monitor dent locations at next API 570 inspection.
F76.042	B18		Harbor Tunnel		Several HPVs and LPDs throughout the harbor tunnel. These are composed of threaded valves, piping, and components. Minor staining was noted on some of these fittings. Also, the valve classifications in several locations are unknown.  1 threaded plug on top 595 and 596)  1 threaded plug on bottom 595 and 596)  2 high point vent 544 and 545)  2 high point vent 277 and 278)  2 high point vent 276 and 277)  high point vent 205 and 206) (weeping)	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps at the 2 high point vent located between 205 and 206. Replace all associated valves with Class 150 ball valves.  Long term consideration should be given to replacing threaded connections with welded and flanged connections.
F76.043	B50		Harbor Tunnel		There are several plates that are tack welded to the pipeline. These plates do not appear to serve a purpose.	Long	Remove tack welded plates/attachments, grind down, and perform additional NDE at these areas.
F76.044			UGPH		The gate valves within the piping systems inside the underground pumphouse are weeping and require continuous maintenance.	Long	Remove the gate valves and install ball valves. It is recommended to program this valve replacement after defueling of RHTF is complete.
F76.045	C1 C2 C7		UGPH		Two loose joint harness fasteners were noted on the Dresser coupling on the discharge side of pumps 201. Four loose joint harness fasteners were noted on the Dresser coupling on the suction side of pumps 201. Some minor coating cracks were noted on the discharge dresser coupling around the middle ring-to-follower joint area indicating potential movement.	Urgent	Tighten fasteners per manufacturers or designer of record specifications.
F76.046	C3		UGPH		Pump shaft guard post not secured to concrete pad.	Long	Secure shaft guard post.
F76.047	C4		UGPH		Several open conduits and sensor enclosures were noted on as this pump appears to be undergoing maintenance and/or repair.	Long	Secure all conduits and sensor enclosures prior to returning pump to service.
F76.048	C5		UGPH		Several loose fasteners noted on the upper half casing of 201 as this pump appears to be undergoing maintenance and/or repair.	Long	Secure all fasteners to the casing prior to returning the pump back to service.
F76.049	C8		UGPH		Hairline crack was noted in pump pad associated with Pump 201. Hairline crack does not appear to be of significant concern.	Other	Monitor hairline cracks in pump pad/foundations.
F76.050	C6		UGPH		Skillet is installed on the discharge pump nozzle on 201 and 205. The assembled joints have only one gasket installed.	Other	Consider installing another gasket to protect flange faces from contact surface damage.
F76.051	C9		UGPH		The ball valve on the strainer drains associated with the pump discharge control valves are not plugged.	Urgent	Provide threaded plugs to prevent accidental discharge of fuel product.
F76.052	C10		UPGH		A small fuel weep was observed on the suction side pressure gauge assembly at the threaded connection associated with Pump 201.	Urgent	Remove gauge, retape threaded connection, and reassemble to prevent future weeps.
F76.053	C11		UGPH		Hairline crack was noted in pump pad associated with Pump 202. Hairline crack does not appear to be of significant concern.	Other	Monitor hairline cracks in pump pad/foundations.

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.054	C12		UGPH		Coating failure on pump casing associated with Pump 202	Long	Clean, prep, and recoat affected areas.
F76.055	C13		UGPH		1/2 ball valve (Valve GP26H) is missing a plug.	Urgent	Provide threaded plug to prevent accidental discharge of fuel product.
F76.056	C14		UPGH		The small isolation ball valves on the pump discharge control valve tubing are missing operating handles. This will prevent isolation in the event of an emergency such as a tubing break or damage to isolate the fuel leak.	Urgent	Provide operating handles on ball valves and consider a car-seal to lock valves in desired position.
F76.057	C15		UPGH		Minor bearing oil staining was noted on pump casings.	Long	Perform routine cleaning and removal of bearing oil staining from pump casings.
F76.058	C16		UGPH		The control valve tubing on the pump discharge control valve is in contact with the grating/I-beam.	Long	Modify control valve tubing or grating to prevent metal-to-metal contact.
F76.059	C17		UGPH		Heavy discoloration and staining observed on the pump discharge control valve. Similar discoloration was noted on 203, 204, 205.	Urgent	Clean, disassemble, and replace valve cover gasketing to prevent future weeps and drips.
F76.060	C18		UPGH		Conduit plug is being used to plug tee fitting on pressure gauge assemblies.	Urgent	Install appropriate threaded pipe plugs on tee fittings.
F76.061	C19		UPGH		A small fuel weep was observed on the suction side pressure eauge assembly at the threaded connection associated with Pump 203.	Urgent	Remove gauge, retape threaded connection and reassemble to prevent future weeps.
F76.062	C20		UGPH		One loose joint harness fastener was noted on the Dresser coupling on the discharge side of pumps 203.	Urgent	Tighten fasteners per manufacturers or designer of record specifications.
F76.063	C21		UGPH		Two loose joint harness fasteners were noted on the Dresser coupling on the discharge side of pump. 204.	Urgent	Tighten fasteners per manufacturers or designer of record specifications.
F76.064	C22		UGPH		The fasteners on the pump discharge control valve are not fully engaged.	Urgent	Tighten fasteners or replace fasteners with longer bolts to ensure nuts are fully engaged.
F76.065	C23		UGPH		Two loose joint harness fasteners were noted on the Dresser coupling on the discharge side of pumper 205.	Urgent	Tighten fasteners per manufacturers or designer of record specifications.
F76.066	C24		UGPH		The isolation ball valve on the pump discharge control valve tubing was in the closed position at the time of inspection. The control valve function may be limited when the piloting is isolated and not subject to system pressures.	Urgent	Verify correct position of isolation valve on the control tubing and consider providing a lock or car-seal to prevent accidental misalignment of the valve position.
F76.067	C25 C27		UGPH		The suction side Dresser coupling is missing a nut on the restraining rod. Also, there was one loose joint harness fastener present.	Urgent	Provide nut and tighten fasteners per manufacturers or design of record specifications.
F76.068	C33		UGPH	41.3 TO	Dresser coupling lugs on pump suction side are installed backwards.	Long	Repair dresser coupling lugs to be installed correctly.
F76.069	C34		UGPH		There are several open conduits, junction boxes, and unsealed electrical fittings throughout the UGPH that will not meet hazardous area ratings.	Urgent	Seal all electrical fittings per NFPA requirements to meet hazardous area classifications.

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.070	C35		UGPH	Various	There are several locations throughout the UGPH where abandoned/open conduit penetrates the UGPH floor, potentially negating the secondary containment.	Long	Cap, seal, or remove all abandoned conduits within the UGPH.
F76.071	C36		UGPH	Various	There are several bronze/brass valves installed on the small ancillary piping systems within the UGPH. A few examples are Gate Valve GI58I, GI58G, and GI58H. Valve classification is unknown.	Urgent	Replace low melting point valves with Class 150 carbon steel ball valves.
F76.072	<b>C37</b>		UGPH	Various	Fuel staining and weeping was noted on the pipe tie-ins associated with the temperature sensors, pressure sensors, high point vents, and low point drains. Weeping is present at threaded connections associated with these fittings.  - PIT-0285 and adjacent Temperature Sensor  - Valve GI36C  - Valve GI36G  - Valve GI36E	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps.  Long term consideration should be given to replacing threaded connections with welded connections where possible.
F76.073	C38		UGPH	Various	Several threaded fittings were noted throughout the UGPH piping below the grating on the main header piping. Some of the branch connections welds are not per industry standard (did not use Weldolet or other approved branch connections).	Long	Replace threaded fitting and pipe with welded connection and replace branch connections with industry approved connections.
F76.074	C39		UGPH		Lack of thread engagement was observed on 12 fasteners on the bypass loop flanges associated with the	Urgent	Install proper flange bolts and hardware to insure proper thread engagement at all flanged connections.
F76.075	C40		UGPH	Various	Several transducers are attached to the piping and the conduits do not have seal off fittings. Additionally, the conduits are ridged which could break under pipe movement.	Urgent	Provide appropriate seal fittings and flexible conduit connections at transducers.
F76.076	C41		UGPH	Various	It was noted that several of the pressure transducers are past due for calibration. (Calibration due date of 10/23/18)	Urgent	Perform calibration of all temperature and pressure devices.
F76.077	C42		UGPH		There is staining and some minor drips noted on the Cameron ball valves throughout the UGPH. Drips appear to be coming from the stem injection port.	Urgent	Clean valve body, service stem nut/upper stem seal to prevent future weeps/drips.
F76.078	C43		UGPH		Localized coating failure and corrosion observed on pipeline at Valve 232E4. Small pitting was observed with pit depths ranging from 0.05 to 0.07 inches.	Long	Clean, prep, and recoat affected areas.
F76.079	C44		UGPH		Gate valve GR68B is missing wheel nut on valve stem.	Urgent	Install new wheel nut.
F76.080	C45		UGPH	Ü	The DBB valve on the F-76 pipeline has six fasteners/studs that are not fully engaged.	Urgent	Remove existing hardware and reinstall studs to ensure proper thread engagement with valve body flange.
F76.081	C48 C54		UGPH	Various	There was noticeable fuel drips and weeps coming from pressure relieving devices on the valve above the grating. (Cla Val relief devices)	Urgent	Service pressure relieving devices to prevent future weeps. If valves are not serviceable, consideration should be given to replacement of these valves.

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.082	C50		UGPH		The flange connection on the bulkhead penetration does not appear to be an ASME rated flange.	Long	Replace flanged connection with ASME B165 rated flange.
F76.083	C52		UGPH		It was also noted that there are no pressure relief devices installed on the header piping.	Long	Provide pressure relief devices to prevent an over pressurization of the header piping.
F76.084	C53		UGPH		All the gate valves on the suction and discharge side of the pumps are equipped with motorized valve actuators. It was observed that the motorized valve actuators are mounted on a stich welded adapter plate. Several of the stitch welds have hairline cracks present and could cause the adapter plate to shear off during actuator operation.	Urgent	Remove coating and perform further weld inspection.
F76.085	C56		UGPH		The pressure relief system has an Emerson Figure 533 flow control valve with hydramotor actuator. The hydramotor actuator still has the factory plastic caps installed in the unused conduit inlet ports.	Long	Remove plastic caps and provide threaded steel conduit plugs.
F76.086	D1	1	UGPH		Several locations where the Teflon pad is missing between pipe and pipe support, creating metal-to-metal contact.	Long	Provide Teflon isolation pads to eliminate metal-to-metal contact between support and pipe.
F76.087	D8		UGPH		Lack of thread engagement on nuts and bolts associated with the 4 low suction pipe flange for Surge Tank 3 at the pipe branch tie-in connection.	Urgent	Tighten fasteners or install new flange bolting hardware to ensure proper thread engagement is achieved at the flanged joint.
F76.088	D9 D15		UGPH		The valves that are mounted on the 4 low suction line at Surge Tanks 3 and 4 are missing plugs. A brass/bronze valve was noted at Surge Tank 3 location. Valve classification is unknown.	Urgent	Install a plug to prevent accidental fuel release. Replace bronze/brass valve with Class 150 carbon steel ball valve.
F76.089	D10		UGPH		Some minor staining was noted on the bottom of the 32  Dresser coupling on Surge Tank 4. No active weeping was observed. Liquid does not appear to be fuel.	Long	Clean flange and monitor for future weeps.
F76.090	D11		UGPH		The thermal relief flange at Surge Tank 4 appears to be equipped with a 1/16 gaskets instead of 1/8 gaskets.	Long	Disassemble the connection and provide dimensionally correct gaskets.
F76.091	D12 D13		UGPH		Some minor staining was noted on the bottom of the flanges for the pipeline just before support F76-8 and F76-9. No active weeping was observed. Liquid does not appear to be fuel.	Long	Clean flanges and monitor for future weeps.
F76.092	D14		UGPH		Some minor staining was noted on the bottom of the 4 low suction DBB valve flange at Surge Tank 4.	Urgent	Clean flanges and monitor for future weeps.
F76.093	LRUT Results CML# B8		Harbor Tunnel	2.00	LRUT Results - An indication (corrosion spot) was observed approximately 7 inches past the concrete bulkhead, towards the tank gallery, underneath the pipe wrap.	Urgent	Remove pipe wrap and inspect the pipeline at this location.

					Table 10 - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
F76.094	LRUT Results CML# B21		Harbor Tunnel		LRUT Results - One confirmed indication was detected at approximately -402 to -411 inches from setup on the pipeline. There was also an indication identified at the pipeline to concrete saddle support, PSC-195 on the pipeline that will require additional investigation.	Urgent	Perform further investigation of the indications at both locations. Note: This will require the pipe to be lifted off the concrete support or the pipe support removed and replaced to allow further inspection.
F76.095	LRUT Results CML# B26		Harbor Tunnel		Two indications noted approximately -976 inches and -963 inches from setup on the pipeline.	Urgent	Remove pipe wrap and inspect the pipeline at these locations.

	10				Table 11 - F-76 Pipe Support Findings and Recommendatio	ns	
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
PSC.44A			Harbor Tunnel		Concrete has been chipped out and removed on tank side around flange for the F-24 and JP-5 lines; concrete around F-24 line has broken out (but not fallen) on opposite side.	Urgent	Remove and replace concrete at anchor bulkhead.
PSC.71A			Harbor Tunnel		Concrete at F-24 line has been broken out on tanks side, no flange visible.	Urgent	Remove and replace concrete at anchor bulkhead.

					Table 12 - FOR Findings and Recommendations		
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
FOR.001	E1		RHTF		Threaded pipe nipple was noted on the Tank 20 FOR sample pipeline.	Long	Replace threaded connection with a welded connection.
FOR.002	E2		RHTF		Metal-to-metal contact was observed between the FOR pipeline and pipe support within the pipe trench, just downstream of the tank sampling manifold.	Long	Provide Teflon pad to prevent metal-to-metal contact.
FOR.003	E3		RHTF		Moderate corrosion was noted on the 2 blind flange and fasteners on the abandoned branch to the sampling lines at Tank 19.	Long	Clean, prep, and recoat branch connection, blind flange, and replace fasteners.
FOR.004	E7		RHTF		ball valve located on the blind flange on Tank 18's FOR pipeline is not plugged off. This valve is susceptible to being accidentally opened if something were to impact the ball valve handle causing it to open.	Urgent	Provide plug or cap on ball valve to prevent accidental fuel release.
FOR.005	E5		RHTF		Pipe support on the FOR line within the trench has become displaced and is no longer supporting the piping.	Long	Reposition the pipe support and Teflon pad to properly support the piping.
FOR.006	E6		RHTF		Pipe support on the FOR line within the trench has become displaced and is no longer supporting the piping.	Long	Reposition the pipe support and Teflon pad to properly support the piping.
FOR.007	E4		RHTF		General coating failure and corrosion on I-beam type pipe supports for the FOR pipeline within the trench. Moderate corrosion was observed on supports between Tanks 16 through 20.	Long	Clean, prep, and recoat pipe supports.
FOR.008	E8		RHTF		Spray foam material in contact with FOR pipeline.	Long	Remove spray foam as required to prevent contact with FOR piping.
FOR.009	E9		RHTF		FOR pipeline flange is covered with concrete within the sump.	Long	Remove concrete from pipe flange and fasteners. Clean, prep, and recoat affected flange and fasteners.
FOR.010	E10		RHTF		Moderate sump floor-to-wall deterioration observed in the concrete FOR sump.	Long	Consider installing a SS tank or lining the concrete pit and testing it annually.
FOR.011	E11		RHTF		The pressure gauge on the FOR line on the discharge side of the sump <u>pump</u> is out of calibration and the glass gauge is cracked.	Urgent	Replace damaged pressure gauge.
FOR.012	E12		RHTF		The 2 FOR pipeline between the tee and gate valve at Door C is covered with a stained plastic wrap and c-clamps. This is indicating a weep at the threaded joint.	Urgent	Remove wrap and repair piping connections to prevent future weeps and drips.
FOR.013	E13		RHTF		The wall mounted pipe support associated with the 2 FOR pipeline has a wood shim between the pipe and the support and the pipe is not secured.	Long	Repair/modify pipe support so the pipeline is secured, and the use of a wood shim is eliminated.
FOR.014	E14		RHTF		pipeline is constructed out of threaded pipe and joints from Sump 7 to Tank 15/16.	Long	Replace pipe segment with welded pipe
FOR.015	E15		RHTF		The section of pipeline from 17 to 20 is threaded and not supported adequately. The pipeline spans that are unsupported measure	Long	Provide additional pipe supports at 9-ft on center per industry standard.
FOR.016	E16		RHTF		Metal-to-metal contact was observed on the FOR pipeline within the electrical room between the pipe and pipe support.	Long	Provide Teflon pad or polymeric half rounds to eliminate metal-to-metal contact between the pipe and the support.

					Table 12 - FOR Findings and Recommendations		
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
FOR.017	E17		RHTF		There are four brass/bronze (low melting point) valves where the piping ties into the FOR-trench piping.	Long	Replace valves with Class 150 carbon steel ball valves.
FOR.018	E18		RHTF		Three pipe support on the FOR pipeline within the trench has become displaced and is no longer supporting the piping.	Long	Reposition the pipe support and Teflon pad to properly support the piping.
FOR.019	E19		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
FOR.020	E20		RHTF		Threaded pipe nipple was noted on the Tank 16 FOR sample pipeline.	Long	Replace threaded connection with a welded connections and Class 150 carbon steel ball valve with flanged ends.
FOR.021	E21		RHTF		Tank isolation valve on the pipeline has one fastener that is not fully engaged.	Urgent	Replace bolt on flange with a longer bolt to ensure nut has adequate thread engagement.
FOR.022	E22		RHTF		Pipe support on the FOR line within the trench has become displaced and is no longer supporting the piping. Support is also shimmed by a piece of wood.	Long	Provide a new pipe support that fully supports the piping.
FOR.023	E23		RHTF		The FOR-gate valve flange has three fasteners that are not fully engaged.	Urgent	Replace bolts on flange with a longer bolt to ensure nuts have adequate thread engagement.
FOR.024	E24		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or <u>nozzle</u>	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
FOR.025	E25		RHTF		The tank isolation valve on the pipeline has product staining on the valve body. This is indicative of a prolonged slow weep possibly from valve plugs in the body.	Urgent	Clean valve body and monitor for drips and weeps. Service the DBB valve as required.
FOR.026			RHTF		The FOR connection from the product lines is constructed out of a combination of hard pipe and hoses.	Urgent	Replace connections and hoses with hard pipe.
FOR.027	E27		RHTF		The tank sampling system at Tank 13 has three 1 flanged joints with cracked gaskets.	Urgent	Remove damaged gaskets and install new gaskets ensure proper torque sequence and specifications are met.
FOR.028	E28		RHTF		The pipeline within the pipe trench is being supported with a piece of wood.	Long	Provide new metal pipe support with Teflon pads to eliminate metal-to-metal contact.
FOR.029	E29		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
FOR.030	E30		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
FOR.031	E32		RHTF		The tank sampling piping associated with Tanks is showing signs of minor to moderate corrosion at areas where the piping has not been upgraded. Tank 9 sample piping is severely corroded and requires replacement.	Urgent	Repair by replacement the small-bore tank sample piping up to the sampling stations associated with Tank 9.  Long term - Clean, prep, and recoat other sampling lines associated with the charactanks.
FOR.032	E31		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
FOR.033	E33		RHTF		Metal-to-metal contact is present at three locations between the pipeline and pipe supports.	Long	Provide coated U-bolts and Teflon pads between the pipeline and supports at all three locations.

page 62 Findings and Recommendations

					Table 12 - FOR Findings and Recommendations		
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
FOR.034	E34		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle. The tank isolation valves are located approximately 30 ft from tank shell/nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
FOR.035	E35		RHTF		The R pipeline is covered with plastic within the AFFF Sump #4.	Long	Remove plastic covering and inspect the pipeline for corrosion or damage.
FOR.036	E38		RHTF		The tank sampling line associated with the 135 ft sample piping has product staining on valve and joints. Does not appear to be an active weep. Weep appears to be the result of residual fuel taken during sampling operations.	Urgent	Clean valve body and monitor for drips and weeps.
FOR.037	E39		RHTF	g .	The pipeline is not supported for a span of app <u>roximately</u> 31 ft.	Long	Provide additional pipe supports at no greater than $14$ -ft on center per industry standard.
FOR.038	E36		RHTF		The pipeline is not supported for a span of approximately 28 ft.	Long	Provide additional pipe support at 14-ft on center per industry standard.
FOR.039	E37		RHTF	· ·	Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
FOR.040	E40		RHTF		Metal-to-metal contact between the pipeline and pipe support within the FOR trench.	Long	Provide Teflon pad to eliminate metal-to-metal contact between the pipe and the support.
FOR.041	E41		RHTF		Metal-to-metal contact between the pipeline and pipe support within the FOR trench.	Long	Provide Teflon pad to eliminate metal-to-metal contact between the pipe and the support.
FOR.042	E42		RHTF		Metal-to-metal contact between the pipeline and pipe support within the FOR trench.	Long	Provide Teflon pad to eliminate metal-to-metal contact between the pipe and the support.
FOR.043	E48		RHTF		Unsecured flange and pipe nozzle at 6 ball valve. The flange is missing several fasteners and the pipe is not capped.	Urgent	Provide fasteners to secure flange connection to 6 ball valve and provide cap to secure pipe end.
FOR.044	E44 E45 E46		RHTF		Three temporary pipe clamps or adjacent to S-23. Pipe clamp lengths are 6 16 8 Also, UTT indicates pipe wall loss in this area over 55% metal loss is present.	Other	This piping repair is being performed as part of the "FLC POL Pipeline Repairs" project (E-Project Work Order No. 1615884). The temporary pipe clamps are being removed and pipeline segment is being replaced with a pipe pup.
FOR.045	E43		RHTF		A loose fastener was observed on a pipe trench adjacent to S-23.	Urgent	Tighten fastener on pipe flange.
FOR.046	E47		RHTF		The on the sump pump discharge piping within Sump S-23 is missing a body cavity relief handle and does not have a plug.	Urgent	Provide handle and threaded plug on cavity relief valve.
FOR.047	E49		RHTF		Metal-to-metal contact between pipeline and pipe support.	Long	Provide coated U-bolt and isolation Teflon pad between pipe and support to eliminate metal-to-metal contact.
FOR.048	E50		3		pipeline is constructed with grouped mechanical fittings. Product staining was noted at FOR 100, -31, -32, -30, and -29	Long	The grooved mechanical fittings do not meet current military criteria. Replace the piping system with welded pipe. Urgent maintenance is required at grooved fittings where fuel weeps are evident.
FOR.049	E51		3		Pipe support 238 supporting the 6 FOR Pipeline is damaged and the frame is bent.	Long	Replace damaged pipe support.

page 63

ŀ	=	
	5	
į	ĭ	
	۲	
	5	
Č	5	
ì	ξ	
١	ب	
Ċ	۲	
	2	
	Ę	
	S	
į	ū	
	215	
	21215	
	21216	
	ER STOLE	
	SPER STOLE	
	INSPER STATE	
	TAINSPER STOLE	
	INAMORER STOLE	
TO A A LOCATION OF THE PARTY OF	EL INAINSPER STSIE	
THE PARTY OF THE P	DEL IRANSPER STOLE	

					Table 12 - FOR Findings and Recommendations		
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
FOR.050	E52		3		Metal-to-metal contact between support.	Long	Provide coated U-bolt and isolation Teflon pad between pipe and support to eliminate metal-to-metal contact.
FOR.051	E52		3		Metal-to-metal contact between pipeline and pipe support.	Long	Provide coated U-bolt and isolation Teflon pad between pipe and support to eliminate metal-to-metal contact.
FOR.052	E53 Table H	HT-2 HT-3	3	Various	Coating failure and heavy corrosion or ch pipeline. See Table H in API 570 report for exact locations.	Long	Clean, prep, and recoat pipeline in affected area.
FOR.053	E54		3		Low Point Drain – No cap on cam-lock fitting. Two fasteners are not fully engaged on the 2 low point drain flange.	Urgent	Provide cam-lock cap on fitting and provide longer bolts to ensure nuts are fully engaged.
FOR.054	E55		3		Low Point Drain – No cap on cam-lock fitting. Two fasteners are not fully engaged on the 2 low point drain flange.	Urgent	Provide cam-lock cap on fitting and provide longer bolts to ensure nuts are fully engaged.
FOR.055			3		Condition of underground segment of the FOR pipeline is unknown. Per the 2021 CP Report, this section of buried pipe had ineffective magnesium anodes.	Urgent	Perform borescope examination of the underground pipeline segment to assess internal condition of the pipeline. This is currently under contract and will be performed in the near future.
FOR.056	E56		3		1 ½ low point drain valve is missing a plug.	Urgent	Provide plug on valve. NOTE: Facility Personnel corrected this finding during our inspection.
FOR.057	E57		3		1 ½ low point drain valve is missing a plug under the 3 staircase.	Urgent	Provide plug on valve. NOTE: Facility Personnel corrected this finding during our inspection.
FOR.058	E58		3		Moderate coating failure and minor corrosion was noted on the 8- FOR penetration sleeve just below the 3 staircase. Some minor corrosion was noted on 6 FOR pipeline at this location as well. Water infiltration at pipe sleeve was observed.	Long	Clean, prep, and recoat affected areas on the pipeline and penetration sleeve. Provide fuel resistant caulking around sleeve penetration to prevent water infiltration through concrete wall.
FOR.059	E60		TK S-311 – 3 3 Entrance		Severe corrosion and pitting at several locations between and S-311. Wall Loss observed between 60%-79%. Severe corrosion also observed at pipe support cradle interfaces.	Urgent	Replace approximately 150 linear of positive on the aboveround portion of the FOR line outside of 3. Limits are from pipe outside 3 to the DBB isolation valve outside of the secondary containment area of Tank S-311.
FOR.060	E59		3		Moderate coating failure and corrosion was observed on the FORriser pipe just outside 3 door.	Long	Clean, prep, and recoat affected areas on the flanges.
FOR.061	E61		3 to TKS-311	F	Excessive vegetation was observed around the from Tank S-311 to the underground pipeline transition at a entrance.	Long	Perform routine trimming/cutting of vegetation away from pipeline.
FOR.062	E62		TK S-311		Wooden pipe crossover staircase is in contact with the 6 FOR pipeline.	Long	Modify wooden stairway to eliminate contact with pipeline.
FOR.063	E63		TK S-311		The body cavity relief valve on the 8 DBB located on the FOR-receipt pipeline is discharging to isolated segment of piping downstream and should be discharging to the atmospheric, tank side of the valve.	Urgent	Replumb the body cavity relief to relieve towards Tank S-311.
FOR.064	E64		TK S-311		The 8 DBB valve, located outside of the secondary containment, has a loose fastener.	Urgent	Tighten loose fastener on valve flange.

page 64 Findings and Recommendations

	Recommended Repairs	Urgent Replumb the body cavity relief to relieve towards Tank S-311.	Provide insulating flange kits on flanges.
	Urgency	Urgent	Long
Table 12 - FOR Findings and Recommendations	Description	The body cavity relief valve on the scale body cavity relief valve on the FOR-issue pipeline is discharging to isolated segment of piping downstream and should be discharging to the atmospheric, tank side of the valve.	valve outside of the secondary containment and thermal relief valve flanges are not equipped with proper insulating flange kits.
	Location		
	Geographic Area	TK S-311	TK S-311
0	SGH Report Cross Reference		
	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	293	E65 and E66
	Item No.	FOR.065	FOR.066

page 65 Findings and Recommendations

		ā			Table 13 - FOR Pipe Support Findings and Recommendations	us	
Item No.	Appendix C - API 570 Report – Cross Reference Defidency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
PSF.13			8		Actively dripping, medium-high corrosion, metal to metal contact, corroded at pipe support interface	Urgent	Replace support.
PSF.14		88	3		Highly corroded and deformed, no contact w/ pipe	Urgent	Replace support.
PSF.15		6 6	3		Corroded, in contact w/ pipe	Urgent	Replace support.
PSF.16			3		Corroded, intact, metal to metal contact, only top anchor to wall present, lower part of bracket not in contact w/ wall	Urgent	Replace support.
PSF.42	Table E2		3		Not supporting pipe, no anchorage to wall at top, metal to metal contact	Urgent	Replace support.
PSF.60, PSF.61	Table E2		8	<i>37</i> - 10	No guide, support broken so pipe is at end of arm	Urgent	Replace Support.
PSF.87, PSF.89			8		No contact w/ pipe	Urgent	Replace Support or modify to properly support pipe.
PSF.169			3		No sleeve on U-bolt, U-bolt corroded to delamination, significant corrosion at base plate and anchors	Urgent	Replace Support.
PSF 234	Table E2		3		Front support flange bent from apparent impact, U-bolt displaced on pipe, not U-shaped.	Urgent	Replace Support.
PSF 238	E51 Table E2		3		Support completely deformed, removed from base plate	Urgent	Replace Support.

page 66

١.	
b	•
Ξ	7
L	•
۵	
ī	7
7	•
٠	
5	
S	
Г	١.
	•
-	
t	
'n	
ż	
٠	
v	•
>	
Š	•
Ξ	
2	•
2	
2	
2	
	1
	1000
CVCTEN	200
D CVCTEN	1000
FD CVCTEN	1000
	THE STATE OF
	21212
NCEED CVCTEN	STEP STEP
	MACHEN CLOSE
	ALL OF THE PARTY
	THE PARTY OF THE P
	ALL COLONES
	THE PARTY OF THE P
TRANSFER	ATTO IN THE PROPERTY.
	THE LINE OF THE PARTY OF THE PA

			Table	Table 14 - Validation of Deficienci	Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	ed Hill Pipe	ilines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	16-TG-1	RHTF		Patch Plate	Remove, provide, and install 4 fleed pup piece to eliminate the patch plate.	Other	Repair has been completed. No further action required.
	16-TG-2	RHTF		Threaded Small Bore Valve	Remove 2" threaded bronze gate valve. Provide 2" carbon steel Class 150 ball valve.	Urgent	Same deficiency observed. Concur with 2016 recommendation.
44	16-TG-3	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same deficiency observed. Concur with 2016 recommendation.
46	16-TG-4	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same deficiency observed. Concur with 2016 recommendation.
47	16-TG-5	RHTF		Corroding Pipe Support	Remove, provide, and install the bottom 1 ft column of pipe supports 47 and 48. Provide temporary support before repairs.	Urgent	Same deficiency observed. Concur with 2016 recommendation.
	16-TG-6	RHTF		Lifting Lug	Out off lifting lug and perform magnetic particle testing. Recoat after testing.	Other	Lifting lug has been removed and is presumed NDE was also conducted.  Visual inspection did not indicate area of concern during inspection.  Recommend no further action.
	16-TG-7	RHTF	4	Pitting at Lifting Lug Weld	Remove coating and perform magnetic particle testing.	Other	Lifting lug has been removed and is presumed NDE was also conducted.  Visual inspection did not indicate area of concern during inspection.  Recommend no further action.
	16-TG-9	RHTF		Arc Strike	Remove coating and perform magnetic particle testing. Recoat after testing.	Other	Same finding was observed. It is presumed that NDE was conducted. Visual inspection did not indicate area of concern during inspection. Recommend no further action.
	16-TG-11	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Other	Same finding was observed. Visual inspection did not indicate area of concern during inspection. Recommend no further action.
F24.009 73	16-TG-12	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
74	16-TG-13	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	16-TG-15	RHTF		2" Diameter Patch Plate	Remove, provide, and instal tee. The repair will require piping rework to fit a new tee. Engineering will be required for the repair design.	Other	Same finding observed. Visual inspection did not indicate area of concern during this inspection.
through 84	16-TG-16	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. 83 and 84 were also observed to be floating during this inspection. Concur with 2016 recommendation.
	16-TG-17	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Other	Same finding was observed. Visual inspection did not indicate area of concern during inspection. Recommend no further action.
F24.012	16-TG-19	RHTF		Threaded Small Bore Valve	Remove 2" threaded bronze gate valve. Provide 2" carbon steel Class 150 ball valve.	Urgent	Same finding was observed. Concur with 2016 recommendation.

page 67 Findings and Recommendations

			Table	14 - Validation of Deficienc	Table 14 - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	ed Hill Pipe	elines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
F24.016	16-TG-20	RHTF		Failing Gasket	Remove the failing gasket on the 3" blind flange. Provide and install new gasket.	Urgent	Did not observe failing gasket during this inspection. However, observed lack of engagement on fasteners at this flange during inspection. This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	16-TG-21	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect. Coating has not been removed yet by coating removal contractor.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	16-TG-23	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect. Coating was not adequately removed by coating removal contractor.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
F24.022	16-UGPH-1	Harbor Tunnel		Non-Standard Repair at Bulkhead	Remove, provide, and install 10 ft 16" pup piece to eliminate the non-standard repair in the bulkhead. This will involve cutting out the concrete surrounding the pipe in the bulkhead. The pipe is currently anchored to the bulkhead using welded on collars that are cast in place in the concrete. The piping will need to be reanchored as part of the repair.	Other	This repair is currently programmed as part of the FY2.1 Emergent Pipeline Repair Project.
F24.018	16-UGPH-2	Harbor Tunnel	N/A	Coating Repair	Recoat 400 ft of failing coating on the between the UGPH and	Long	Same finding observed. Concur with 2016 recommendation. Note that the corrosion in this area is approximately 500 linear
F24.020 F24.021	16-UGPH-3	Harbor Tunnel	N/A	Threaded Small Bore Pipe/Valve	Remove four threaded low point drain (LPD) assemblies and one threaded high point vent (HPV) assembly. Provide welded/flanged LPD and HPV assemblies with schedule 80 carbon steel pipe and Class 150 ball valves. LPDs and HPVs are located near the UGPH wall.	Urgent	Same finding observed. Concur with 2016 recommendation. In addition, refer to F24.020 and F24.021 for more information.
	16-LRUT-1	Harbor Tunnel		Coating Removal/Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	Assumed to be completed based on coating at this location appearing relatively new. Current inspection did not identify this as an area of concern. No further action needed.
	16-LRUT-2	Harbor Tunnel		Coating Removal/Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	Assumed to be completed based on coating at this location appearing relatively new. Current inspection did not identify this as an area of concern. No further action required.
2	18-TG-1	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding observed. Concur with 2016 recommendation.
	18-TG-2	RHTF		Gouge/Dent	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	This repair has been completed. No further action required.
	18-TG-3	RHTF		Socket Weld	Remove, provide, and install 4 ft 18" pup piece to eliminate the socket weld.	Other	There is a 4 pup installed between 3 and 4 and no socket weld. Repair is completed. No further action needed.
9	18-TG-5	RHTF		Missing Guide at Pipe Support	Provide guide for pipe support.	Long	Same finding observed. Guide is missing at the 7 o'clock position. Concur with 2016 recommendation.

- 1
-
00
0
E I
8
2
0
F
5
D
S
=
2
ш
2
2
~,
THE I
SF
Ž.
Z
E
7
Æ
F
200

			Table	14 - Validation of Deficienci	Table 14 - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	d Hill Pipe	lines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	18-TG-6	RHTF		Dent	Remove, provide, and install 4 ft piece to eliminate the dent.	Other	Per 2019 Inspection and Repair of Red Hill Pipelines – Pipe Pedigree Report, no longer recommended for repair.
	18-TG-11	RHTF		Dent/Crease	Remove, provide, and install 4 ft eliminate the dent.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
11	18-TG-12	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	18-TG-14	RHTF		Socket Weld	Remove, provide, and install 4 full ce to eliminate the socket welds.	Other	This repair has been completed. No further action required.
	18-TG-15	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Other	Lifting lugs not identified during inspection. Most likely removed during previous repairs. No further action is recommended.
12	18-TG-16	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	18-TG-18	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Long	Same finding was observed. Concur with 2016 recommendation.
16	18-TG-21	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	18-TG-22	RHTF		Corrosion on Sleeve	Install drip shield above pipe.	Long	Moderate coating failure is now present. Concur with 2016 recommendation. In addition, remove corrosion and recoat piping.
	18-TG-23	RHTF		Weld Overlay Repair	Remove weld overlay, remove coating, and perform magnetic particle testing. Recoat after testing.	Other	This was not identified during this inspection. No further action is recommended.
	18-TG-25	RHTF	1	Corrosion	Remove the corroded area of piping between the flange sets 20° downstream and 67" upstream of Pipe Support 20. Provide spool piece. Spool piece includes two rolled 45° elbows, elevation difference of 29", lateral difference of 31", and flange face to face distance of 87".	Other	This repair was being performed during our inspection. No further action required.
	18-TG-27	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	18-TG-28	RHTF		Socket Weld	Remove, provide, and install 5 ft 18" pup piece to eliminate the socket welds.	Other	Same finding was observed. Concur with 2016 recommendation. NOTE: This segment of pipe was marked for repair during our inspection.
	18-TG-29	RHTF		Dresser Coupling	TBD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	18-TG-30	RHTF	×	Dent	Remove coating and perform magnetic particle testing. Recoat after testing.	Other	Per 2019 Inspection and Repair of Red Hill Pipelines – Pipe Pedigree Report, no longer recommended for repair.

69 aged

Report and flegsale of Geographic Areas Red in Elecation Projects and install of the Recommendation Reported (2016) (Urgency Recommendation Resonance (2016) (Urgency Report Item No. 18-176-31 RHTF Corresion Projects and install of the Resonance (2016) (Urgency Report Item No. 18-176-32 RHTF Corresion Projects and install of the Resonance (2016) (Urgency Report Item No. 18-176-33 RHTF Corresion Projects and install of the Resonance (2016) (Urgency Report Item No. 18-176-34 RHTF Corresion Resonance (2016) (Urgency Report Item No. 18-176-35 RHTF Corresion Resonance (2016) (Urgency Report Item No. 18-176-35 RHTF Corresion Resonance (2016) (Urgency Resonance (2016)				Table	14 - Validation of Deficienci	Table 14 - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	ed Hill Pip	Blines Report
Red Hill         Geographic         Location         Description         Remove, provide, and install 4 ft         Urgency           18-1G-31         RHTF         Corrosion         Corrosion         Remove, provide, and install 4 ft         Other           18-1G-32         RHTF         Socket Weld         Remove, provide, and install 4 ft         to Other           18-1G-32         RHTF         6         Dent         Remove, provide, and install 4 ft         to Other           18-1G-33         RHTF         6         Dent         Remove, provide, and install 4 ft         to Other           18-1G-35         RHTF         6         Dent         Remove, it to dent pipe and perform magnetic particle         Other           18-1G-37         RHTF         Socket Weld         Remove, provide, and install 4 ft         to Other           18-1G-41         RHTF         Socket Weld         Remove, provide, and install 4 ft         cet to Other           18-1G-42         RHTF         Socket Weld         Remove, provide, and install 6 ft         to Other           18-1G-44         RHTF         Socket Weld         Remove, provide, and install 6 ft         to Other           18-1G-44         RHTF         Socket Weld         Remove, provide, and install 6 ft         to Other           18-1G-44 </th <th>Report</th> <th>EEI Inspection and Repair of</th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>	Report	EEI Inspection and Repair of						
18-16-31   RHTF	Cross Reference Item No.	Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
18-TG-32   RHTF   Socket Weld   Remove proclete, and install 4 ft   To Other Remove coating and perform magnetic particle   Other Cash Other Remove provide, and install 4 ft   To Other Remove provide, and install 5 ft   To Other Remove provide, and install 5 ft   To Other Remove provide, and install 6 ft   To Other Provide 6 ft   To Other Pro		18-TG-31	RHTF		Corrosion	Remove, provide, and install 4 ft. Pup piece shall extend 2 ft upstream and 2 ft. downstream of Pipe Support 30.	Other	This repair has been completed. No further action required.
18-TG-34 RHTF		18-TG-32	RHTF		Socket Weld	all 4 ft	Other	This was repaired with a 2 pipe pup. No further action required.
18-TG-34 RHTF Threaded Small Bore ranker Provide 3/4" welded/flanged schedule 80 Urgent arbon steel pipe and 3/4" flanged carbon steel Carbon steel pipe and stable to the repair carbon steel pipe and fittings with welded carbon carbon steel ball valve. RHTF Corrosion Remove, provide, and install 6 flameted carbon steel pipe and fittings with welded carbon carbon steel pipe and fittings with welded carbon carbon steel pipe and fittings with welded carbon steel pipe and fittings.  18-TG-41 RHTF Corrosion Remove, provide, and install 6 flameted carbon corrosion Remove, provide, and install 18 flameted carbon corrosion Remove, provide, and install 18 flameted carbon corrosion Replace to grant pipe support Recoat bottom of pipe at tong flameted carbon corrosion Replace pipe support Recoat bottom of pipe at tong flameted carbon corrosion Replace pipe support Recoat bottom of pipe at tong flameted carbon corrosion Replace pipe support Recoat bottom of pipe at tong flameted carbon corrosion Replace pipe support Recoat bottom of pipe at tong flameted carbon corrosion Replace pipe support Recoat bottom of pipe at tong flameted upstream and downstream of the corrosion of t		18-TG-33	RHTF	9	Dent	Remove coating and perform magnetic particle testing. Recoat after testing.	Other	Per 2019 Inspection and Repair of Red Hill Pipelines – Pipe Pedigree Report, no longer recommended for repair.
18-TG-35 RHTF Socket Weld Remove, provide, and install 4 ft to Other eliminate the socket welds.  18-TG-37 RHTF Socket Weld Remove, provide, and install 4 ft ece to Other eliminate the socket welds.  18-TG-40 RHTF Socket Weld Remove, provide, and install 6 ft and bore Long threaded pipe and fittings with welded carbon steel ball valve. Replace 7 ft of small bore carbon steel ball valve. Replace 7 ft of small bore threaded pipe and fittings with welded carbon steel ball valve. Replace 7 ft of small bore carbon steel ball valve. Replace 7 ft of small bore carbon steel ball valve. Replace 7 ft of small bore carbon steel ball valve. Replace 7 ft of small bore carbon steel ball valve. Replace 7 ft of small bore liminate the socket weld.  18-TG-42 RHTF Socket Weld Remove, provide, and install 8 ft are. The repair design.  18-TG-45 RHTF Corrosion Remove, provide, and install 8 ft 18" pupplece to Long Pipe Support 67 during Tank Gallery recoat.  Remove, provide, and install 6 ft 18" pupplece to Long Remove, provide, and install 6 ft 18" pupplece to Long Remove, provide, and install 6 ft 18" pupplece to Long Remove, provide, and install 6 ft 18" pupplece to Pupplece shall extend upstream and downstream Other of the corrosion of the corrosion are socket welds.	JP5.066	18-TG-34	RHTF		Threaded Small Bore Pipe/Valve	Remove 1 ft of and valve. Provide 3/4" welded/flanged schedule 80 carbon steel	Urgent	A shorter pipe nipple is now installed with % bull valve but still contains threaded fittings. Product staining was noted at threaded connections. Urgent repair should be to disassemble threaded joints, clean, retape, and reassemble to prevent future weeps.
18-TG-35 RHTF Socket Weld eliminate the socket welds.  18-TG-40 RHTF Socket Weld eliminate the socket welds.  18-TG-41 RHTF Socket Weld eliminate the socket welds.  18-TG-42 RHTF Socket Weld eliminate the socket welds.  18-TG-44 RHTF Socket Weld eliminate the socket welds.  18-TG-45 RHTF Socket Weld eliminate the socket welds.  18-TG-46 RHTF Socket Weld eliminate the socket welds.  18-TG-47 RHTF Socket Weld eliminate the socket welds.  18-TG-48 RHTF Socket Weld eliminate the socket welds.  18-TG-49 RHTF Socket Weld eliminate the socket welds.  18-TG-49 RHTF Socket Weld eliminate the socket welds.  18-TG-40 RHTF Socket Weld eliminate the socket welds.  Remove, provide, and install 4 socket weld.  Remove, provide, and install 6 the repair design.  Remove, provide, and install 6 the repair design.  Remove, provide, and install 6 the repair design.  Remove, provide, and install 6 the Tool of the repair design.  Remove, provide, and install 6 the Tool of the repair design.  Remove, provide, and install 6 the Tool of the repair design.  Remove, provide, and install 6 the Tool of the repair design.  Remove, provide, and install 6 the Tool of the repair design.  Remove, provide, and install 6 the Tool of the repair design.  Remove, provide, and install 6 the Tool of the corrosion peliminate the socket welds.  Remove, provide, and install 6 the Tool of the corrosion peliminate the socket welds.  Remove, provide, and install 6 the Tool of the corrosion of the repair design.  Remove, provide, and install 6 the Tool of the corrosion of the						Class 130 ball valve.		Note: This is programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
18-TG-40 RHTF RPJace 1 1/2" plastic ball valve with Class 150 carbon steel ball valve. Replace 7 ft of small bore threaded pipe and fittings.  18-TG-41 RHTF Socket Weld Socke		18-TG-35	RHTF		Socket Weld	11 4 ft	Other	Repair has been completed. No further action is required.
Replace 1 1/2" plastic ball valve with Class 150  Carbon steel ball valve. Replace 7 ft of small bore carbon steel ball valve. Replace 7 ft of small bore threaded pipe and fittings.  18-TG-41  RHTF  Socket Weld  18-TG-42  RHTF  Socket Weld  18-TG-45  RHTF  Socket Weld  Socket W		18-TG-37	RHTF		Socket Weld	II 4 ft	Other	Repair has been completed. No further action is required.
18-TG-41 RHTF Socket Weld eliminate the socket welds.  18-TG-42 RHTF Socket Weld eliminate the socket welds.  18-TG-44 RHTF Corrosion Replace pipe support Recoat bottom of pipe at Pipe Support Socket Weld Replace pipe support Recoat bottom of pipe at Pipe Support Recoat bottom of pipe at Pipe Support Socket Weld Remove, provide, and install 6 ft 18" pup piece to 18-TG-48 RHTF Socket Weld Remove, provide, and install 6 ft 18" pup piece to 18-TG-48 RHTF Remove, provide, and install 6 ft 18" pup piece to 18-TG-48 RHTF Remove, provide, and install 6 ft 18" pup piece to 18-TG-48 RHTF Remove, provide, and install 6 ft 18" pup piece to 18-TG-48 RHTF Remove, provide, and install 4 ft Remove, provide area.	JP5.002	18-TG-40	RHTF		Non-Standard Components	Replace 1 1/2" plastic ball valve with Class 150 carbon steel ball valve. Replace 7 ft of small bore threaded pipe and fittings with welded carbon steel pipe and fittings.	Long	Valve has been replaced but threaded piping still exists. Concur with replacing threaded pipe with welded and reroute out of the way of walking path, golf car or rail path.  Note: This repair is currently programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
18-TG-42 RHTF Socket Weld eliminate the socket weld.  18-TG-44 RHTF Corrosion Engineering will require piping rework to fit a new tee.  18-TG-45 RHTF Corrosion Remove, provide, and install 18" tee. The repair Long Engineering will be required for the repair design.  Replace pipe Support Recoat bottom of pipe at Pipe Support Recoat bottom of pipe at Pipe Support Recoat bottom of pipe at Long Remove, provide, and install 6 ft 18" pup piece to Long eliminate the socket welds.  Remove, provide, and install 4 ft Remove, provide, and install 4 ft Remove, provide, and install 4 ft Remove provide and install 4 ft Remove provide area.		18-TG-41	RHTF		Socket Weld		Long	Same finding was observed. At the time of our inspection coating was removed at this location presumably for repair. Concur with 2016 recommendation.
18-TG-44 RHTF Corrosion will require piping rework to fit a new tee.  18-TG-45 RHTF Corrosion Engineering will be required for the repair design.  Replace pipe support. Recoat bottom of pipe at Pipe Support Recoat bottom of pipe at Pipe Support Socket Weld Remove, provide, and install 6f 18" pup piece to liminate the socket weld.  Remove, provide, and install 4f All Remove, provide, and		18-TG-42	RHTF		Socket Weld	all 4 f	Other	Repair has been completed. No further action is required.
18-TG-45 RHTF Corrosion Replace pipe support. Recoat bottom of pipe at Pipe Support G7 during Tank Gallery recoat.  18-TG-46 RHTF Socket Weld Remove, provide, and install 6 ft 18" pup piece to eliminate the socket welds.  Remove, provide, and install 4 ft Remove.		18-TG-44	RHTF		Corrosion	Remove, provide, and install 18" tee. The repair will require piping rework to fit a new tee. Engineering will be required for the repair design.	Long	Same finding observed. Concur with 2016 recommendations. Coating was removed during inspection presumably for repairs.
RHTF Socket Weld eliminate the socket welds.  Remove, provide, and install 6 ft 18" pup piece to eliminate the socket welds.  Remove, provide, and install 4 ft Pup piece shall extend upstream and downstream of the corroded area.	29	18-TG-45	RHTF		Corrosion	Replace pipe support. Recoat bottom of pipe at Pipe Support 67 during Tank Gallery recoat.	Long	Same finding observed. Concur with 2016 recommendations.
RHTF Corrosion Pup piece shall extend upstream and downstream of the corroded area.		18-TG-46	RHTF		Socket Weld	Remove, provide, and install 6 ft 18" pup piece to eliminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendations. Coating was removed at the time of our inspection presumably for repair.
		18-TG-48	RHTF		Corrosion	Remove, provide, and install 4 full Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action is required.

ľ		
S	2	
200	5	
٥	Ļ	
ŝ	ž	
2	2	
	Š	
F	=	
ì	3	
٩	Ę	
	ž	
	Ē	
t	4	
′	7	
į	5	
1	5	
i	4	
4	2	
T V V V	ş	
i	2	
	-	
ì	i	
	Ď	

			Table	Table 14 - Validation of Deficienci	Deficiencies from the 2016 and 2019 Inspection and Renair of Red Hill Pipelines Benort	20d Hill Pin	alinac Rannrt
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	18-TG-49	RHTF		Welded Saddle Pipe Support	Remove, provide, and install 4 files to elso eliminate the saddle pipe support. Provide new pipe support.	Long	Same finding observed. Concur with 2016 recommendations.
	18-TG-50	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	18-TG-51	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	18-TG-52	RHTF		Corrosion	Remove, provide, and install 4 full Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action is required.
	18-TG-53 and 18-TG-54	RHTF		Corrosion	Remove, provide, and install 6 fthe Pup piece shall extend 6 ft upstream and 2 ft downstream of Pipe Support 75. *Note: 18-TG-53 and 18-TG-54 have been combined into one repair recommendation.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	18-TG-56	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Long	Same finding observed. Concur with 2016 recommendations.
	18-TG-58	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding observed. Concur with 2016 recommendations.
JP5.013	18-TG-59	RHTF		Threaded Small Bore Pipe/Valve	Remove 1" threaded pipe and gate valve. Provide 1" welded/flanged schedule 80 carbon steel pipe and 1" flanged carbon steel Gass 150 ball valve.	Urgent	Same finding observed. Concur with 2016 recommendations.  Note: This is programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
	18-TG-60	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding observed. Concur with 2016 recommendations.
	18-UGPH-1	Harbor Tunnel		Threaded Pipe	Remove threaded 4" blind flange. Provide 4" weld neck flange.	Long	Did not observe 4 threaded blind flange There is a 1-linch threaded fittings with a ball valve between 650 and 651. Replace ball valve with welded/flanged fittings and pipe.
	18-UGPH-2	Harbor		Dent/Gouge	Remove, provide, and install 4 ft eliminate the dent.	Other	This repair is currently programmed as part of the FY2.1 Emergent Pipeline Repair Project.
	18-UGPH-5	Harbor Tunnel		Dent	Term Remove, provide, and install 4 ft to eliminate the dent.	Other	Repair has been completed. No further action required.
	18-UGPH-6	Harbor Tunnel		Dent	Remove, provide, and install 4 ft eto eliminate the dent.	Other	Repair has been completed. No further action required.
	18-UGPH-7	Harbor Tunnel		Dent/Gouge	Remove, provide, and install 4 ft ce to eliminate the dent.	Other	This repair is currently programmed as part of the FY2.1 Emergent Pipeline Repair Project.
	18-UGPH-9	Harbor Tunnel		Dent	Remove, provide, and install 4 ft eliminate the dent.	Other	Per 2019 Inspection and Repair of Red Hill Pipelines – Pipe Pedigree Report, no longer recommended for repair.

=	
2	
ď	
RE	
-	
≥	
9	
2	
SP	
S	
2	
5	
ш	
7	
S	
SYSTE	
R SYSI	
FER SYST	
SFER SYST	
INSFER SYST	
RANSFER SYST	
TRANSFER SYST	
TRANSFER	
<b>UEL TRANSFER SYST</b>	

Table 14 - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	Description Recommendation Reported (2016) Urgency Recommendation (August 2022)	Remove four threaded low point drain (LPD) assemblies and one threaded high point vent (HPV) assembly. Provide welded/flanged LPD and HPV assemblies with schedule 80 carbon steel pipe and assembles with schedule 80 carbon steel pipe and assembles with schedule 80 carbon steel pipe and assemble with schedule 80 carbon	Coating Repair Between the UGPH and 2.	Dent Remove, provide, and install 4 ft. to Long Same finding observed. Concur with 2016 recommendation.	Coating Repair Recoat 5 ft of Long Same finding observed. Concur with 2016 recommendation.	Dent Remove, provide, and install 4 ft. Other Pipeline Repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.	Coating Repair Recoat 5 ft of Long Same finding observed. Concur with 2016 recommendation.	Dent/Gouge Remove, provide, and install 4 ft. Other Pipeline Repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.	Coating Removal / Remove 4 ft of coating and inspect. Other Pipeline Repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.	Non-Standard Flange Remove non-standard flange. Provide and install Long Same finding observed. Concur with 2016 recommendation.	Socket Weld Remove, provide, and install 4 ft. Long repair has not identified. Confirmation on repair is needed. If recommendation.	Peteriorated gasket was not observed during this inspection. Eight lugs on the upstream side of the dresser coupling. Provide and install new gasket? Stress analysis?  Deteriorated gasket was not observed during this inspection. Eight lugs on the upstream side of the dresser coupling are installed backwards and are not per manufacturer's detail. Rotate lugs for correct installation.	Remove, provide, and install 4 ft.  Corrosion Pup piece shall extend upstream and downstream Other This repair has been completed. No further action required.	Recoat bottom of pipe at Pipe Support 28 during  Corrosion  Tank Gallery recoat. Section of pipe support may Long Same finding observed. Concur with 2016 recommendation.	Non-Standard Flanges Provide, and install 4 flame.  Long Same finding observed. Concur with 2016 recommendation. the flange set.
14 - Validat	Des	Threaded S Pipe/Valve	Coating Re	Dent	Coating Re	Dent	Coating Re	Dent/Goug	Coating Re Unknown F	Non-Stand	Socket Wel	Dresser Co	Corrosion	Corrosion	Non-Stand
Table	Location	N/A	N/A												
	Geographic Area	Harbor Tunnel	Harbor	RHTF	Harbor	Harbor	Harbor	Harbor	Harbor	RHTF	RHTF	RHTF	RHTF	RHTF	RHTF
	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	18-UGPH-10	18-UGPH-11	18-LRUT-1	18-LRUT-2	18-LRUT-3	18-LRUT-4	18-LRUT-5	18-LRUT-6	32-TG-1	32-TG-3	32-TG-4	32-TG-5	32-TG-6	32-TG-7
	Report Cross Reference Item No.	JP5.026	JP5.024		JP5.024		JP5.024								

page 72 Findings and Recommendations

ь	•
	•
_	Ñ
>	•
٠	
u	4
ä	
-	
MODECTION	5
c	١.
÷	5
۰	-
L	)
ü	ū
	c
ü	5
5	ć
5	-
Ξ	7
5	3
5	
ď	٠
г	=
ď	,
CVCTEAA	2
v	7
n	
ī	1
ŭ	٠
ī	7
š	4
<	5
5	C
۵	2
TDANCEED	z
ū	٠
۲	4
-	3
ų	Ĺ

			Table	14 - Validation of Deficience	Table 14 - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	ed Hill Pip	elines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-TG-8	RHTF		Patch plate	Remove, provide, and install 4 ft Pup piece shall extend upstream downstream of the diameter patch plate.	Long	Same finding observed. Visual inspection did not indicate area of concern during this inspection. Concur with 2016 recommendation.
	32-TG-9	RHTF		Socket Weld	Remove, provide, and install 4 ft to eliminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-10	RHTF		Patch plate	Remove, provide, and install 4 ft.  Puppiece shall extend upstream downstream of the diameter patch plate.	Long	Same finding observed. Visual inspection did not indicate are of concern during this inspection. Concur with 2016 recommendation.
	32-TG-11	RHTF		Socket Weld	Remove, provide, and install 4 full to eliminate the socket weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-13	RHTF		Coating Removal / Unknown Repair Scope	Remove 5 ft of coating and inspect.	Long	Area has been recoated. Inactive pitting observed between 0.050 and 0.100 inches deep. Continue coating maintenance to deter further corrosion.
46	32-TG-14	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-15	RHTF		Coating Removal / Unknown Repair Scope	Remove 5 ft of coating and inspect.	Long	Area has been recoated. Inactive pitting observed between 0.050 and 0.100 inches deep. Continue coating maintenance to deter further corrosion.
	32-TG-16	RHTF		Corrosion	Remove, provide, and install 4 ft Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action required.
	32-TG-17	RHTF		Socket Weld	Remove, provide, and install 4 ft eliminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-19	RHTF		Corrosion	Remove, provide, and install 4 ft. Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action required.
	32-TG-20	RHTF		Non-Standard Flange	Remove, provide, and install 4 full Pup piece shall extend upstream downstream of the flange set.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-21	RHTF		Socket Weld	Remove, provide, and install 4 ft to eliminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-24a 32-TG- 24b 32-TG-24c	RHTF	+	Corrosion Dent/Gouge Corrosion	Remove, provide, and install 4 full Pup piece shall extend upstream and downstream of the corroded/dent area. *Note: 32-TG-24a, 32-TG-24b, and 32-TG-24c have been combined into one repair recommendation.	Long	Same finding observed. Concur with 2016 recommendation. Coating has been applied to arrest corrosion.
	32-TG-25	RHTF		Corrosion	Remove, provide, and install 4 ft. Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action required.

	3	3	
		:	
١		)	
١	3	Ļ	
١	ŧ	4	
Ę	2		
	>	•	
ì		₹	
3	١	2	
ŀ	٠		
Ç		þ	
ļ	į	4	
	4	Ļ	
١	4	)	
•	S	5	
	1	•	
	S	ī	
i		7	
į		•	
į	i	١	
2	>		
Ļ	•	7	
	s		
ĺ	i	ì	
Ļ		Z	
Ļ	,	)	
i	2	2	
•	q	r	
ľ	ì	2	
ŀ		ij	
į		i	
۰	•	5	
i	ī		

			Table	14 - Validation of Deficienci	Table 14 - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	ed Hill Pip	elines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-TG-27	RHTF		Socket Weld	Remove, provide, and install 4 fleriminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-28	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	No issues noted during inspection. Coating system appears to be relatively new in this area. No further action is required.
	32-TG-2932- TG-30 32-TG- 3132-TG-32 32-TG-33	RHTF		Corrosion, Non-Standard Repair, Coating Removal	Remove, provide, and install 30 ft.  Pup piece shall extend approximately 4 ft upstream of Pipe Support 70 and approximately 4 ft downstream of Pipe Support 69. *Note: 32-TG-29 through 32-TG-34 have been combined into one repair recommendation.	Long	Same finding observed. Concur with 2016 recommendation. Coating has been applied to arrest corrosion.
	32-TG-35	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	No issues noted during inspection. Coating system appears to be relatively new in this area. No further action is required.
	32-TG-36	RHTF		Socket Weld	Remove, provide, and install 4 fi	Long	Same finding observed. Concur with 2016 recommendation.
F76.016	32-TG-37	RHTF		Tunnel Support	Investigate if supports are load bearing on the piping?	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-38	RHTF		Socket Weld	Remove, provide, and install 4 ft eliminate the socket weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-39	RHTF		Socket Weld	Remove, provide, and install 4 ft to eliminate the socket weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-40	RHTF		Deadleg	Remove, provide, and install 4 ft to eliminate the deadleg.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-41	RHTF	1	Dresser Coupling	TBD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
F76.006	32-TG-42	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Long	Area of inactive corrosion was observed. Pit depth of 0.196 – 0.200 inches was found. FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4.
	32-TG-43	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-44	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Other	Inspection did not identify areas of concern at this location. Coating was relatively new indicating recent repair. There was a repair sleeve and some inactive pitting (0.05 – 0.180 inches) at this location. No further action is required.

			Table	Table 14 - Walidation of Dofficione	of Doficionaise from the 2016 and 2010 Increasing and Bonaic of Bod Lill Bigolines Bonat	od Hill Bing	10000
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-TG-45	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Other	Inspection did not identify areas of concern at this location. Coating was relatively new indicating recent repair. Inactive corrosion/pits identified halfway between 69 and 70 with max pit of 0.120 inches. No further action is required.
	32-TG-46	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Other	Inspection did not identify areas of concern at this location. Coating was relatively new indicating recent repair. Inactive corrosion/pits identified nea 70 with max pit of 0.150 inches. No further action is required.
	32-A2A3-1	Harbor Tunnel		Threaded Small Bore Pipe/Valve	Remove 2" threaded high point vent (HPV) assembly. Provide welded/flanged HPV assembly with schedule 80 carbon steel pipe and Class 150 ball valve.	Long	Same finding observed. Some product staining was noted but active weeping was not observed. Concur with 2016 recommendation. Recommend high point vent be monitored in until repair can be performed.
	32-A2A3-2	Harbor Tunnel		Dent/Gouge	Remove, provide, and install 4 ft eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-3	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 5 ft of coating and inspect.	Long	Minor pitting was observed at this location ranging from 0 50-0.080 inches. Repair coating to arrest further corrosion.
F76.019	32-A2A3-4	Harbor Tunnel		Coating Repair	Recoat 3 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-5	Harbor Tunnel		Corrosion	4' Pup Repair. Greater than 50% corrosion on Weld.	Other	Repair has been completed. No further action required.
F76.019	32-A2A3-6	Harbor Tunnel		Coating Repair	Recoat 3 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-7	Harbor Tunnel		Coating Repair	Recoat 4ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-8	Harbor Tunnel		Coating Repair	Recoat 3 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-9	Harbor Tunnel		Coating Repair	Recoat 1 ft of failing coating at the weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-10	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 8 ft of coating and inspect.	Long	Pitting was observed at this location approximate pit depth of 0.120 inches. Repair coating at this location to arrest corrosion.
	32-A2A3-11	Harbor Tunnel	() () () () () () () () () () () () () (	Coating Repair	Recoat 4 ft of failing coating.	Other	Repair has been completed. No further action required.
F76.019	32-A2A3-12	Harbor Tunnel		Coating Repair	Recoat 16 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-13	Harbor Tunnel		Coating Repair	Remove 24 ft of wrap coating and recoat.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-14	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 3 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.

page 75 Findings and Recommendations

			Table	Table 14 - Validation of Deficienci	of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Beport	Red Hill Pip	alines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location		Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-A2A3-15	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 12 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-16	Harbor Tunnel		Coating Repair	Recoat 10 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-17	Harbor Tunnel		Coating Repair	Recoat 4 ft of failing coating.	Pong	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-18	Harbor		Coating Repair	Recoat 15 ft of failing coating.	Pong	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-19	Harbor		Dent/Gouge	Remove, provide, and install 4 ft eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-20	Harbor Tunnel		Dent	Remove, provide, and install 4 ft ece to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-21	Harbor Tunnel		Dent	Remove, provide, and install 4 ft to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-22	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating at weld.	Pong	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-23	Harbor Tunnel		Dent	Remove, provide, and install 4 ft eliminate the dent.	Other	Repair has been completed. No further action required.
F76.019	32-A2A3-24	Harbor Tunnel		Coating Repair	Recoat 10 ft of failing coating.	Pong	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-25	Harbor Tunnel		Coating Repair	Recoat 3 ft of failing coating.	Pong	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-26	Harbor	9	Dent	Remove, provide, and install 4 ft	Other	Repair has been completed. No further action required.
	32-A2A3-27	Harbor Tunnel		Dent	Remove, provide, and install 4 ft. to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-28	Harbor Tunnel		Coating Repair	Recoat 3 ft of failing coating.	Pong	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-29	Harbor Tunnel		Coating Repair	Recoat 6 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-30	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating.	Pong	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-31	Harbor Tunnel		Coating Repair	Recoat 4 ft of failing coating.	Pong	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-32	Harbor Tunnel		Corrosion	Remove, provide, and install 4 ft	Other	Repair has been completed. No further action required.
F76.028	32-A2A3-33	Harbor Tunnel		Clockspring	Remove, provide, and instal to eliminate the Clockspring repair.	Long	Same finding observed. Concur with 2016 recommendation.

page 76 Findings and Recommendations

			Tahlo	14 - Validation of Deficienci	Table 14 - Validation of Deficiencies from the 2015 and 2019 Inspection and Renair of Red Hill Disalines Renort	and Hill Pine	Trong Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
F76.019	32-A2A3-34	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-35	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-36	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-37	Harbor Tunnel		Coating Repair	Recoat 12 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-38	Harbor Tunnel		Coating Repair	Recoat 6 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-39	Harbor Tunnel		Coating Repair	Recoat 8 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-40	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.018	32-A2A3-41	Harbor Tunnel	0	Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-42	Harbor Tunnel		Coating Repair	Recoat 20 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-43	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Gean, inspect, and recoat approximately 75 ft of piping between Pipe Support 595 and the bulkhead.	Long	Same finding observed. Concur with 2016 recommendation.
F76.029	32-A2A3-44	Harbor Tunnel		Clockspring	Remove, provide, and instal to eliminate the Clockspring repair.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-45	Harbor Tunnel		Coating Repair	Recoat 10 ft of failing coating.	Long	Same finding observed. Inspertion observed minimum corrosion and pitting at this area (pit depths commendation.
	32-A2A3-46	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 15 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-47	Harbor Tunnel		Coating Repair	Recoat 6 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-A2A3-48	Harbor Tunnel		Coating Repair	Recoat 20 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
F76.018	32-A2A3-49	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 30 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	32-UGPH-2	Harbor Tunnel		Dent	Remove, provide, and install 4 ft ce to eliminate the dent.	Long	Same finding observed. Concur with 2016 recommendation.

page 77 Findings and Recommendations

١.	
b	•
Ξ	7
L	•
۵	
ī	7
7	•
٠	
5	
S	
Г	١.
	•
-	
t	
'n	•
ż	
٠	
v	١.
>	
Š	•
Ξ	
2	1
2	
2	
2	
	1
	1000
CVCTEN	200
D CVCTEN	1000
FD CVCTEN	1000
	THE STATE OF
	21212
NCEED CVCTEN	STEP STEP
	MACHEN CLOSE
	ALL OF THE PARTY
	THE PARTY OF THE P
	ALL COLONES
	THE PARTY OF THE P
TRANSFER	ATTO IN THE PROPERTY.
	THE LINE OF THE PARTY OF THE PA

			Table	14 - Validation of Deficienci	Table 14 - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	ed Hill Pipe	lines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-ИGРН-6	Harbor Tunnel	N/A	Threaded Small Bore Pipe/Valve	Remove three threaded low point drain (LPD) assemblies and one threaded high point vent (HPV) assembly. Provide welded/flanged LPD and HPV assemblies with schedule 80 carbon steel pipe and Class 150 ball valves. LPDs and HPVs are located near the UGPH wall.	Long	Same finding observed. Concur with 2016 recommendation.
F76.019	32-UGPH-7	Harbor	N/A	Coating Repair	Recoat 400 ft of failing coating on the between the UGPH and 2.	Long	Same finding observed. Concur with 2016 recommendation.
	32-LRUT-1 32-LRUT-2	Harbor Tunnel		Corrosion at Bulkhead	Remove, provide, and install 10 flemove, provide, and install 10 fleminate the corroded areas in the bulkhead. This will involve cutting out the concrete surrounding the pipe in the bulkhead. The pipe is currently anchored to the bulkhead using welded on collars that are cast in place in the concrete. The piping will need to be reanchored as part of the repair.	Urgent	Not able to verify without performing LRUT at this location. It is unknown whether this has been repaired. If repair has not been performed, concur with 2016 recommendation.
	32-LRUT-3	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 8 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	TK2-TG-1	RHTF	N/A	Dresser Coupling	ТВО	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK4-TG-1	RHTF	N/A	Dresser Coupling	ТВО	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK6-TG-1	RHTF	N/A	Dresser Coupling	TBD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK6-TG-1	RHTF	N/A	Dresser Coupling	TBD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".

			Table	14 - Validation of Deficienci	Table 14 - Validation of Deficiencies from the 2016 and 2019 Incoertion and Renair of Red Hill Binelines Renort	d Hill Pine	lines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	TK8-TG-1	RHTF	N/A	Dresser Coupling	TBD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK10-TG-1	RHTF	N/A	Dresser Coupling	TBD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK10-TG-2	RHTF	N/A	Non-Standard Flange	TBD	Long	Replace flange with an ASME B16.5 rated flange and fitting.
	TK10-TG-3	RHTF	N/A	Corrosion	Remove jacketing at Dresser Coupling and inspect.	Other	Insulation was removed at Tank 10 during July 2021 inspection and the area was inspected and documented. Add inspection to the API 570 inspection program until dresser couplings are replaced or RHBFSF is defuel and decommissioned.
	TK12-TG-1	RHTF	N/A	Non-Standard Flange	TBD	Long	Replace flange with an ASME B16.5 rated flange and fitting.
	TK13-TG-1	RHTF	N/A	Non-Standard Flange	180		Replace flange with an ASME B16.5 rated flange and fitting.
	TK14-TG-1	RHTF	N/A	Dresser Coupling	TBD		Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK16-TG-1	RHTF	N/A	Dresser Coupling	TBD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK16-TG-2	RHTF	N/A	Non-Standard Flange	TBD	Long	Replace flange with an ASME B16.5 rated flange and fitting.
T19A	TK19-TG-1	RHTF	N/A	Pipe Support	Repair pipe support corroding steel and spalling concrete.	Long	Same conditioned identified in July 2021 inspection. Concur with 2016 recommendation.
T20B	TK20-TG-1	RHTF	N/A	Pipe Support	Replace pipe support corroding steel.	Long	Same conditioned identified in July 2021 inspection. Concur with 2016 recommendation.











## **APPENDIX 'B' - SYSTEM DRAWINGS**






















































































































#### APPENDIX 'C' - API 570 INSPECTION REPORT

Office: 757-622-6299

Toll Free: 800-546-7853

Fax: 757-622-9103



# **API-570 Inspection Report Facility POL Piping Red Hill Fuel Complex Piping**

(Tank Gallery, Harbor Tunnel, UGPH, Surge Tank and FOR Piping)
Joint Base Pearl Harbor Hickam; HI



Prepared for

### Austin Brockenbrough & Associates, LLC

1011 Boulder Springs Drive, Suite 200 Richmond, Virginia 23225

March 22 - May 24, 2022

API Standard 570 recommends this document containing valuable historical information be retained for the life of the piping.

Signature(s):

#### **General Conditions**

The information referenced in this engineering report is based solely upon the area(s) agreed upon and contracted for inspection on the date of the inspection and under those present, known, same, and current conditions. This report was prepared using retrievable data from those areas that were properly cleaned, prepared, and made accessible during the inspection. Areas not contracted for inspection, not cleaned, and not made accessible are not included in this report.

The methods, standards, and regulations used by InterSpec, LLC during the inspection and preparation of this engineering report comply with the most current and widely accepted standards and regulations in the industry, in which these standards and regulations make no representation, warranty, or guarantee. The professional opinions and recommendations stated in this report, including predictability of life, maximum of time for re-inspection, suitability for product storage, are conclusive approximations and are intended to serve mainly as guidelines and safe fill for obtaining the utmost in spill prevention and environmental protection. The listed recommendations may not necessarily be mandatory actions but corrective actions InterSpec, LLC suggests would better preserve the owners'/operators' facility components and may contribute to safer and more convenient operations. Failure to comply with these could result in, but may not be limited to, reduction of service life, piping mishap, legal consequences, and/or fines for owners/operators. It is best advised the recommended repairs, corrective actions, and procedures be fully and accurately complied with in order to meet the required and applicable federal, state, and local regulations and to have the necessary repairs and upgrades performed prior to making any change in service, product, and/or current conditions. Some recommendations and requirements are necessary to bring the component(s) into compliance with federal, state, and local regulations. InterSpec, LLC recommends re-inspection after any corrective action, repair, or change in usage when the change is to a more severe service. Any change in facility conditions that are applicable to this inspection report such as, but not limited to, a change in service or usage could result in outdating this report. The predictability of any component in this report is a result of following the procedures in the applicable industry standard. InterSpec, LLC accepts absolutely no responsibility or liability for any mishap or failure, including any subsequent clean-up costs or legal ramifications, resulting from owners'/operators' failure to perform the required repairs, inspections, and re-inspections as they apply.

## **Executive Summary**

This report contains an engineering analysis of the data collected during the inspection of the Red Hill fuel complex piping for Joint Base Pearl Harbor Hickam, Pearl Harbor located in Hawaii. The inspection is limited to sections specified in the SOW and included the primary piping, header piping, and associated valves and equipment for the piping, and associated valves and equipment for the pipelines. Piping associated with Surge Tanks and the FOR lines from the Tank Gallery to Tank 311 was also inspected. The UGPH piping, pumps, and pressure reliving devices/piping were also closely inspected, and the findings were documented.

The inspection was conducted on a mix of primarily carbon steel piping, spanning an approximately 3.5-mile stretch. The project completed was a hands-on API-570 visual inspection, visual weld inspection, ultrasonic thickness (UT) testing, Phased Array Ultrasonic Testing (PAUT) of welds, and ultrasonic guided wave inspection of concrete penetrations, pipe and saddle contact points. Results of the UT, PAUT and assessment is included in Annex A and Annex B. The inspection has identified five (5) locations that have indication requiring a follow-on verification to determine the extent and size of indication

The evaluation of the inspected POL piping shows the remaining life of the majority of the facility piping, if continued in the same product service, to be in accordance with API-570. There are, however, several segments of piping that are or approaching the minimum operating thickness or life with some that have moderate external corrosion and pitting. The location with localized pitting/corrosion that do not meet API Std. 570, API RP 574 and ASME B31.3 calculations are summarized in Table A2. A section of the FOR line outside of 3 is also not structurally sound due to pitting corrosion and requires replacement before continued use of the system.

The inspection, finding and data at this facility: is subgroup in six categories:

- A. Tank Gallery Piping
- B. Harbor Tunnel Piping
- C. UGPH Piping
- D. Surge Tank Piping
- E. FOR Piping
- F. JP-5 Piping from Tank 20 to (July 2021 Observations)

The Maximum Allowable Operating Pressure (MAOP) was calculated for the remaining aboveground piping using the minimum measured thicknesses and was determined to be greater than (b) (3) (A) herefore, the piping is structurally certified to meet the requirements of API Standard 570 (unless listed in Table A2). Other areas of compliance are contingent on accomplishing the requirements noted in Table D. Areas with localized pitting/corrosion identified during the inspection that do not meet the inspection standard and industry guidance are specifically identified in Table D along with the recommended repair (See summary in Table A2).

Design and the inspection data is summarized in Table A1 below based on TML data collected throughout that segment of piping):

TABLE A1 - Summary Design and Inspection Data											
MAOP* = 275	Pipe Size (Assumed)	Nominal Wall Thickness	Minimum Required Wall Thickness	Previous Measured Wall Thickness	Minimum Measured Wall Thickness	Corrosion Rates	Calculated Remaining Life (years)	Maximum Allowable Working Pressure at Next UT Inspection			
Tank Gallery Piping F-76 line by Tank 5 (Lateral) (TML G15)	(b) (3) (A)	0.375	0.171	0.375	0.318	0.00072		498			
Tank Gallery Piping JP-5 line by Tank 4 (Lateral) (TML G14)	(b) (3) (A)	0.375	0.110	0.375	0.320	0.00070	302	786			
Tank Gallery Piping F-24 line b/w & (TML G52)	(b) (3) (A)	0.250	0.137	0.250	0.240	0.00013	811	478			
Tank Gallery Piping JP-5 line b/w (TML G4)	(b) (3) (A)	0.250	0.154	0.250	0.231	0.00024	320	407			
Tank Gallery Piping F-76 line b/w & (TML G26)	(b) (3) (A)	0.375	0.274	0.375	0.342	0.00042	163	338			
Harbor Tunnel Piping (b) (3) F-24 (TML H124)	(b) (3) (A)	0.250	0.137	0.250	0.193	0.00072	78	372			
Harbor Tunnel Piping (b) (3) JP-5 (TML H164)	(b) (3) (A)	0.250	0.154	0.250	0.192	0.00073	52	329			
Harbor Tunnel Piping (b) (3) F-76 (TML H180)	(b) (3) (A)	0.375	0.274	0.375	0.344	0.00039	179	340			
UGPH Piping (TML P2)	(b) (3) (A)	0.250	0.154	0.250	0.224	0.00033	213	393			
UGPH Piping F-76 header manifold (TML P146)	(b) (3) (A)	0.375	0.206	0.375	0.341	0.00043	314	449			
UGPH Piping (TML P57)	(b) (3) (A)	0.375	0.137	0.375	0.360	0.00019	1174	716			
Surge Tank Piping NPS 16 (TML S1)	(b) (3) (A)	0.250	0.137	0.250	0.241	0.00011	912	480			
Surge Tank Piping NPS 18 (TML S10)	(b) (3) (A)	0.250	0.137	0.250	0.231	0.00024	390	458			
Surge Tank Piping NPS 32 (TML S22)	(b) (3) (A)	0.375	0.274	0.375	0.336	0.00049	126	331			
FOR Piping NPS 4 (TML F41)	(b) (3)	0.237	0.090	0.237	0.211	0.00033	368	1479			
FOR Piping NPS 6 (TML F54)	(b) (3)	0.280	0.110	0.280	0.219	0.00077	141	1019			
FOR Piping NPS 6 (TML X2) Exterior pipe outside of 3 (Due to Pitting)	(b) (3)	0.280	0.110	0.280	0.090	0.00241	-8	0			

Notes:

Table is based on thickness data collected at CMLs. Localized areas of pitting and corrosion are detailed in Table D (Piping Deficiency. Exterior section of the FOR pitting and corrosion is extensive and is added to the table.

<sup>\*</sup> When the design pressure or MAOP was not available, the pump dead head pressure or TRV set points are used in the working pressure calculation. The calculation was computed for the lowest CML in the NPS group. The maximum anticipated working pressure is used in the calculation (275 NOTE: TRV at UGPH is set to 260 based on the tag. MAOP of 275 (based on pedigree, specimen tests and study performed by APTIM/EEI)

<sup>\*\*</sup> The pipe appears to be a rolled and welded plate. STD schedule (0.375") is used for calculation purpose.

<sup>\*\*\*</sup> Use nominal when there is no documented TML data from previous inspection record

TABLE A2 - Localized Pitting and Corrosion Summary (Area Not Per API STD. 570/API RP 574)										
Piping Line/System  (b) (3) (A)		Minimum Measured Thickness (in.)	Pitting Depth (in.)	Remaining metal Thickness (in.)	See Item #					
(b) (3) (JP-5 line)		0.239 - 0.244	0.239 - 0.244	0.099	B26					
(b) (3) (JP-5 line)		0.225 - 0.242	0.060 - 0.095	0.130	B29					
(b) (3) (JP-5 line)		0.218 - 0.238	0.218 - 0.238	0.116	B31					
(b) (3) (JP-5 line)		0.226 - 0.234	0.050 - 0.135	0.099	B33					
(b) (3) (JP-5 line)		0.233 - 0238	0.113	0.120	B40					
(b) (3) (JP-5 line)		0.240 - 0.243	0.063 - 0.105	0.135	B49					
(b) (3) (F-76 line)		0.358 - 0.361	0.080 - 0.140	0.218	B30					
(b) (3) (F-76 line)		0.383 - 0.387	0.140	0.269	B35					
(b) (3) (F-76 line)		0.383 - 0.387	0.140	0.269	B36					
(b) (3) (F-76 line)		0.298 - 0.321	0.050 - 0.120	0.178	B41					
(b) (3) (F-76 line)		0.219 - 0.250	0.196 - 0.200	0.219	A23					
NPS 6 (FOR)		0.235 - 0.260	0.050 - 0.190	0.090	E60					

#### Note:

- Remaining metal thickness values were calculated in accordance with Equation (3a) from Paragraph 304.1.2, "Straight Pipe under Internal Pressure," of ASME B31.3, "Process Piping" Code.
- The piping line segment fails to meet the required minimum thickness calculated per ASME B31.3. Additional suitability for continued service assessment approach discussed in API STD 570 and AP RP 574 may be utilized when appropriate.
- Required minimum thickness per ASME B31.3 for and (seamed pipe under operating pressure of 275 PSIG)



#### 1.0 Introduction

- 1.1 Purpose
- 1.2 API-570 Pipeline Inspection Procedures

#### 2.0 References and Acronyms

- 2.1 American Petroleum Institute
- 2.2 American Society of Mechanical Engineers Codes
- 2.3 National Fire Protection Association
- 2.4 American Society of Nondestructive Testing
- 2.5 Code of Federal Regulations
- 2.6 Military and Host Nation References or Standards

#### 3.0 Description

- 3.1 Job Description
- 3.2 Piping Description
- 3.3 Part Description
- 3.4 Inspection Description
- 3.5 Piping Design Parameters
- 3.6 Equipment Description

#### 4.0 Inspection

- 4.1 Results
- 4.2 Maintenance Recommendations
- 4.3 Compliance Requirements

#### 5.0 Serviceability and Schedule

- 5.1 The next formal visual inspection schedule
- 5.2 Next ultrasonic thickness evaluation schedule
- 5.3 Owner/user inspection schedule

#### Annexes A - Phased Array Ultrasonic Testing and Guided Wave Results

- 1. Phased Array Ultrasonic Testing (PAUT)
- 2. Guided Wave (

#### **Annexes B – API-570 Inspection Attachments**

- 1. Appendix A (API 570 Calculations)
- 2. Appendix B (Thickness Data/CMLs)
- 3. Appendix C (Drawings)
- 4. Appendix D (API 570 Checklist and Site Assessment Findings/Discussion Form)
- 5. Appendix E (Photographs)
- 6. Appendix F (JP-5 repair Highlights; Tank 20 Tank 10)

#### **Tables**

- A1. Summary Design and Inspection Data
- A2. Localized Pitting and Corrosion Summary
- B. API Classification and Recommended Interval
- C. Deficiency Color Code
- D. Piping Deficiencies
- D-1. HPV and LPD Locations in the Harbor Tunnel (From 690 to
- E1. Pipe Support Inspection Summary (NPS 18 JP-5 Piping from Tank 20 to MOV 0163)
- E2. Pipe Support Inspection Summary (All other sections)
- F. Mechanical Dent (MD) Inspection Summary
- G. Validation of Repairs/Inspection findings (Based on EEI/APTIM previous reports)
- H. Coating Failure Summary
- I. PAUT Evaluation Summary Table
- J. Straight Beam Pipe Ultrasonic Thickness Testing Data at PAUT CMLs
- K. LRUT Evaluation Summary Table
- L. Straight Beam Pipe Ultrasonic Thickness Testing Data at LRUT CMLs
- M1. API STD 570 Thickness Data & TML
- M2. API STD 570 Thickness Data & TML (Exterior Section of FOR Piping)
- M3. API STD 570 Pitting Data & TML (Exterior Section of FOR Piping)

#### 1.0 Introduction


#### 1.1 Purpose

1.1.1 This report presents an analysis of data collected during an inspection conducted between March 22 through May 24, 2022 of the tunnel aboveground piping systems designated for inspection at the Red Hill fuel complex in Hawaii. The inspection was performed by a certified API-570 inspector from InterSpec, LLC. All data was collected in accordance with the guidelines set forth in API Standard 570, the appropriate ASME Codes, 40 CFR 112, and other supporting documents.

The project included mobilization of equipment and personnel to support the activities outlined in the SOW. The following inspections and tasks were completed:

- i. Guided wave ( or long-range ultrasonic testing (LRUT) of the selected concrete bulkhead penetrations and concrete support contact points. A representative sample of bulkhead penetrations and concrete support contact points were examined at the Tank Gallery, Harbor Tunnel, and Surge Tank. A total of 32 LRUT data acquisition setups were completed (note some locations yielded poor data due to pipe geometry or low amplitude signals).
- ii. Conducted manual and semi-automated Phased Array Ultrasonic Testing (PAUT) examinations of 86 welds. A representative sample of welds was examined at the Tank Gallery, Harbor Tunnel, Surge Tank, and Underground Pump House (UGPH).
- A hands-on API-570 visual inspection of the primary piping, header piping, and 111. associated valves and equipment for the (b) (3) (A) the (b) (3) (A) and the (b) (3) (A) pipelines. Piping associated with Surge Tanks and the FOR lines from the Tank Gallery to Tank 311 were inspected. The UGPH piping, pumps, and pressure reliving devices/piping were also closely inspected and findings documented. The inspection consisted of close visual examination of the piping to include coating inspection, pit measurements/sizing, corrosion evaluation, dent measurements/sizing, support inspection, soil-to-air/concrete-to-air interface inspections, crevice inspection at saddle and supports, along with other piping system integrity consideration. The section of JP-5 Piping from Tank 20 to was not evaluated during this trip (An API-570 inspection along with various NDE was completed on this section of piping in July 2021). The inspection observations from the 2021 report is incorporated in this current inspection report to consolidating the inspections. An appendix is also provided highlighting the status of this segment of piping and work completed at the time of demobilization.
- iv. Sections of piping inspected were also evaluated with ultrasonic thickness at selected locations to evaluate for internal and external corrosion and to establish Condition Monitoring Locations (CMLs) in accordance with API-570 and per the project scope. Dry Film thickness (DFT) readings were also conducted throughout the facility piping.
- v. Project also included removal of lead-based paint at 86 locations to support the PAUT weld examinations. All activity related to coating removal, collection, and disposal was managed by trained personnel per industry standard and Facility/OSHA regulations
- vi. All PAUT weld examination locations required surface preparation (weld spatter filling) to ensure adequate coupling to aid the transmission of ultrasonic energy.
- vii. At the completion of the project, all areas where coating was removed was coated with a Kem Kromik Universal Metal Primer.

#### 1.2 API-570 Pipeline Inspection Procedures



InterSpec initially conducted a visual inspection of the site and planned an integrity inspection that best fulfilled the needs of the customer. For example, the customer's piping might all be the same class, or there may be portions that are more critical. In each situation, the testing procedures will be the same, but re-inspection requirements will be different.

- 1.2.2 **General**: Visual, ultrasonic, magnetic particle, and dye penetrant examinations are used in InterSpec's evaluation.
  - a. Careful visual inspection to identify deficiencies in the material condition of the piping and insulation where it exists.
  - b. For underground or encased piping, conduct an above grade surveillance; looking for discoloration of the soil, softening of paving asphalt, or noticeable odor.
  - c. Deterioration may be in the form of electrochemical, chemical, mechanical, or a combination of these and may be accelerated by temperature, stress, fatigue, impingement, high velocity, or irregularity of flow rates. When any of these conditions are present, they will be evaluated by the appropriate NDE method.

**Corrosion** is the prime cause of deterioration in a piping system. InterSpec evaluates the following conditions when they exist:

- a. Caustics, inorganic acids, organic acids, and low pH water are all leading causes of corrosion within piping systems.
- b. Hydrogen sulfides attack metals and can cause hydrogen blistering and hydrogen embrittlement.
- c. Atmospheric corrosion Corrosion where humidity is above 60% allowing water to absorb oxygen at a high rate and increase rates of corrosion.
- d. Corrosion under insulation (CUI) Sources of moisture include rain, condensation, snow etc. (CUI is common).
- e. Check for caustic embrittlement Commonly found on systems carrying caustic products; check fitting connections, flanges, next to weld seams, and areas of high stress.

#### **Mechanical Forces**

- a. Check for cracks, bulges, and distortions.
- b. Check for fatigue failures.
- c. Check where thermal expansion is causing fatigue from heating and rapid cooling.
- d. Check fabrication defects.

#### **On-Stream Inspections**

- a. Determine pipe sections that may be approaching minimum life and have to be replaced at a scheduled shutdown.
- b. Inspect pipe supports and pipe anchors.
- c. Inspect for external corrosion piping, supports, slide shoes, and spring hangers.

#### **Visual Inspection**

- a. Check for leaks, safety, and fire hazards.
- b. Inspect flanged joints, packing glands, valve bonnets, and expansion joints.
- c. Check misalignment: pipe support out of plumb, shifting of base-plates, or foundation breaking supports, hangers, and braces.
- d. Check deterioration of protective coatings for evidence of corrosion, distortion, movement of concrete footings, failure or loose foundation bolts, restricted operation of pipe rollers, or slide plates.
- e. Check branch connections that are against pipe supports as a result of thermal movement.
- f. Check for damage due to hydraulic shock; check DUMMY LEGS (a weld support welded to an elbow, usually a piece of pipe or structural beam).
- g. Inspect for cracks where vibration or swaying has been observed (problems at small connections with heavy valves and small lines that are tied down to a larger line).
- h. Check external corrosion from sweating lines, moisture getting through insulation, or protective coatings.
- i. Check for accumulations of corrosion liquids (from spills and old leaks).
- j. Check for hot spots.

#### **Condition Monitoring Location (CML)**

- a. Ultrasonic thickness measurements.
- b. Tees, deadlegs, elbows, and reducers.
- c. Monitor each piping system by taking CMLs, where areas are subject to higher corrosion rates, areas are subject to localized corrosion, locate minimum thickness at CML, outside and inside radius of elbows taken (use lowest reading in calculations) establish minimum for areas of CUI.

#### MT/PT Inspection

a. Evaluate welds, cuts, and gouges.

#### **Hammer Testing**

a. Do not use on lines under pressure, stress-relieved lines in caustic service, or where stress corrosion cracking can occur.

#### Determine Retirement Thickness; Calculate Thickness According To:

a. ASME B31.3 using Barlow Equation if thickness is less than D/6 and SE is not greater than 0.385. t = PD/2SE, where

t = pressure design thickness,

= internal design pressure,

 $\overline{D}$  = outside of pipe,

S = allowable unit stress, and

E = longitudinal joint efficiency.

For valves and flanges use t = 1.5PD/2SE + corrosion allowance.

#### **Sketches**

a. Develop layout or isometric drawings providing a means of recording the size of piping, piping location, process flow, thickness measurements, and areas of serious corrosion.

#### **Inspection for Specific Types of Corrosion and Cracking (as applicable)**

- a. Injection points 12" or 3 pipe diameters downstream.
- b. Deadlegs –high points in hot piping.
- c. CUI integrity of insulation, sources of moisture, localized corrosion, chloride stress corrosion, or cracking of SS piping areas susceptible to CUI, areas exposed to mist over spray, steam vents, process spills, piping in intermittent service, vibrating piping, steam traced, and systems with deteriorated wrappings.
- d. Erosion occurs in areas of turbulent flow, downstream of control valves, downstream of pump discharges, and downstream of orifices.
- e. Environmental cracking causes are upset conditions, CUI, unanticipated condensation, and exposure to wet hydrogen sulfide or carbonates (usually on SS piping).
- f. Fatigue cracking from excess cyclic stresses caused by pressure, mechanical, or thermal changes. Low-cycle fatigue from heat up and cool down, and high-cycle from excessive piping vibration (preferred method of detection is PT or MT).
- g. Creep cracking depends on time, temperature, and stress; check high stress areas, mechanical changes from temperature most often in systems operating above 900 degrees.

#### **Classify Piping for Next Inspection Requirement**

- a. Class 1 next UT/VT in 5 years.
- b. Class 2 next VT in 5 years.
- c. Class 2/3 next UT in 10 years.
- d. 75% of Class 1, 50% of Class 2, and 25% of Class 3 piping that have areas of damaged insulation need to be inspected.

#### **Evaluation**

- a. Calculate the remaining life of piping system.
- b. Calculate long-term corrosion rate.
- c. Calculate short-term corrosion rate (if previous data is available and submitted).
- d. Evaluate locally thinned areas.
- e. Conduct piping stress analysis (as applicable).

#### Prepare an Inspection and Engineering Report

- a. Listing all references.
- b. Listing name and certification number of the API-570 inspector.
- c. Showing location of all thickness measurements.
- d. Showing all engineering calculations.
- e. Including a narrative of the aforementioned inspection, examination, and testing items.
- f. Including a statement of fitness for service.
- g. Including a corrosion rate and remaining life statement.
- h. Including a listing of recommended repairs and/or alterations.
- i. Including a statement of compliance with the API Standard 570.

#### 2.0 References and Acronyms

#### 2.1 American Petroleum Institute:

- 2.1.1 API Standard 570, Piping Inspection Code: Inspection, Repair, Alteration, and Rerating of In-Service Piping Systems
- 2.1.2 API RP 574, Inspection of Piping System Components
- 2.1.3 API RP 576, Inspection of Pressure-relieving Devices
- 2.1.4 API RP 577, Welding Inspection and Metallurgy
- 2.1.5 API RP 578, Material Verification Program for New and Existing Piping Systems
- 2.1.6 API Standard 579-1/ASME FFS-1, Fitness-For –Service
- 2.1.7 API RP 580, Risk-based Inspection
- 2.1.8 API RP 1110, Pressure Testing of Liquid Petroleum Pipelines

#### 2.2 American Society of Mechanical Engineers Codes:

- 2.2.1 Code for Pressure Piping, Chemical Plant and Petroleum Refinery Piping, ASME B31.3.
- 2.2.2 Standard for Pipe Flanges and Flanged Fittings; ASME B16.5
- 2.2.3 ASME Boiler and Pressure Vessel Code; Section V, Non-Destructive Examination
- 2.2.4 ASME Boiler and Pressure Vessel Code; Section IX, Welding and Brazing Qualifications

#### 2.3 National Fire Protection Association:

- 2.3.1 NFPA-30, Flammable and Combustible Liquids Code
- 2.3.2 NFPA-70, National Electrical Code
- 2.3.3 NFPA 704, Standard System for the Identification of the Hazards of Materials for Emergency Response

#### 2.4 American Society of Nondestructive Testing:

2.4.1 ASNT-SNT-TC-1A

#### 2.5 Code of Federal Regulations:

- 2.5.1 CFR, Title 29, Part 1910, Process Safety Management
- 2.5.2 CFR, Title 40, Volume 21, Chapter I, Subchapter D, Part 112, Oil Pollution Prevention

#### 2.6 Military and Host Nation References or Standards:

- 2.6.1 UFC 3-460-01, Petroleum Fuel Facilities
- 2.6.2 UFC 3-460-03 O&M Maintenance of Petroleum Systems
- 2.6.3 UFGS 33 52 43.13 Aviation Fuel Piping
- 2.6.4 UFGS-01 35 29, Safety and Occupational Health Requirements
- 2.6.5 UFGS-01 35 30, Safety, Health, and Emergency Response (HTRW/UST)

#### Acronyms and Abbreviations

#### ACRONYM DEFINITION

ACVG Alternating Current Voltage Gradient

AG Aboveground

API American Petroleum Institute

ASME American Society of Mechanical Engineers

AST Aboveground Storage Tank
CIS Close Interval Survey

CFR Code of Federal Regulations
CML Condition Monitoring Locations

CP Cathodic Protection
CR Corrosion Rates
CS Carbon Steel

DBB Double Block and Bleed Isolation Valve

DC Direct Current

DCVG Direct Current Voltage Gradient
ULSD-2 Ultra-Low Sulfur Diesel #2
EPA Environmental Protection Agency

F Fahrenheit FS Filter Separator

GAL Gallon

GPM Gallons per Minute HPV High Point Vent

ICCP Impressed Current Cathodic Protection

ILI In-Line Inspection LPD Low Point Drain

LRUT Long Range Ultrasonic Testing

LT Long Term

MAWP Maximum Allowable Working Pressure MAOP Maximum Allowable Operating Pressure

MOGAS Motor Gasoline

MSS Manufacturers' Standardization Society of the Valve and Fittings Industry

NFPA National Fire Protection Association

NWGLDE National Work Group on Leak Detection Evaluations

PAUT Phased Array Ultrasonic Testing

PH Pumphouse

POL Petroleum, Oil, and Lubricants

PRT Product Recovery Tank

S Pipe Support

Pounds Per Square Gauge

PSV Pressure Safety Valve

SCFM Standard Cubic per Minute

SPCC Spill Prevention Control and Countermeasures

SS Stainless Steel

TRV Thermal Relief Valves

UG Underground

USDOT United States Department of Transportation

UST Underground Storage Tank

UT Ultrasonic Testing

UV Ultraviolet

VOC Volatile Organic Compounds

VP Valve Pit

## 3.0 Description

## 3.1 Job Description:

Contracted by: Austin Brockenbrough & Associates, LLC

Job Number: 22-0114

### 3.2 Pipe/Location Description:

Owner/Operator: US Navy

Location: Joint Base Pearl Harbor Hickam; HI (Red Hill)

Pipe Identification: Header Piping

Service JP-5, F-24, F-76 and Fuel Contact Water

3.3 Part Description:

Construction Code: ASME B31.3 (Assumed)

Manufacturer: Unknown

Year Installed: Varies (Primarily 1940s with upgrades/modifications)
Material: Carbon steel (\*ASTM A53; Grade B specification)

ASTM A53 Grade B (TS = 60,000 PSI; YS = 35,000 PSI) \*Based on the 2017 Pipe Pedigree Testing performed by EEI

3.4 Inspection Description:

Inspection Type: API-570, Guided Wave and Phased Array Ultrasonic Testing Equipment Used: Ultrasonic Thickness Unit, PAUT & Guided Wave Unit

Inspector(s): Benyam Berhane

3.5 Piping Design Parameters:

Max Pressure:

Last Pressure Test Date: NA Max Temp: 200°F

Construction: Welded/Threaded/Flanged/Clamped (Victaulic) Joints

#### 3.6 Equipment Description:

#### **Ultrasonic Thickness Meter**

Manufacturer: General Electric Model: DMS-GO+

Calibration Methods Used: Zeroing Procedure, Copper Coating Calibration Procedure, and

Two Point Calibration Procedure

#### **Ultrasonic Flaw Detector**

Manufacturer: General Electric

Model: USM-GO

Wedge: GE Benchmark 70 degree/5 Mhz/0.500 (S/N # 024F2P)

Calibration Methods Used: Distance amplitude correction, sensitivity levels and flaw depth

Verified on standard test block containing side dried holes

**PAUT** 

Manufacturer: Olympus Model: OmniScan X3

Probe/Wedge: 5L32-A11 5MHz linear array probe using 32 active elements (45°

to 70° focused)

5L16-A10 5MHz linear array probe using 16 active elements (43°

to 70° focused)

Calibration Methods Used: NAVSHIPS calibration standard (S/N: 03-8269) with 3/64" side

drilled holes

**LRUT** 

Manufacturer: Southwest Research Institute (SwRI®)

Model: MsS Data Acquisition and Reporting Software for Pipeline

Inspection

Calibration Methods Used: Determined by geometrical feature. Unit maintenance/calibration

performed by manufacture (SwRI®)

## 4.0 Inspection

#### 4.1 Results:

### 4.1.1 Site Description

POL piping inspected at the Red Hill fuel complex consists of a mix of primarily , carbon steel piping, spanning an approximately 3.5-mile stretch. The fuel piping system at the tank gallery and harbor tunnel is a dual directional tank receipt and issue piping for Tanks 1 through 20. At the time of the inspection, several of the tanks were permanently out of service or removed for inspection/maintenance activity.

The F-24 (b) (3) and JP-5 (b) (3) piping is constructed from carbon steel with mostly schedule 10 (0.250-in thick) and some standard thickness piping at the tank gallery laterals and sections of replaced spool pieces in the harbor tunnel are used. The F-76 line (b) (3) is also carbon steel with majority STD (0.375-in thick) pipe. The fuel piping is primarily electric fusion welded (EFW) longitudinal seamed of unknown weld joint efficiency or quality factor and some that appear to be electric resistance welded (ERW) seams. The FOR is welded 4- schedule 40 at the tank gallery and clamped (Victaulic) 6- schedule 40 starting at the FOR-Sump (S-23) with an isolated section of 6- welded pipe in the tunnel. FOR piping from the saccess door to Tank 311 is welded pipe. The piping in the UGPH and Surge Tank tunnel is similar in design and construction to the harbor tunnel piping.

The piping and associated equipment facilitate the receipt, transfer, and distribution of the fuel within the POL facility. Product is received from an underground pumphouse and pumped to various tanks using the same piping headers.

The inspection is limited to sections specified in the SOW and included the primary piping, header piping, and associated valves and equipment for the F-24, the b (3) (A) jet propellant grade 5 (JP-5), and the (b) (3) (A) diesel fuel marine (F-76) pipelines. Piping associated with Surge Tanks and the FOR lines from the Tank Gallery to Tank 311 was also inspected. The UGPH piping, pumps, and pressure reliving devices/piping were also closely inspected and findings documented.

A list of deficiencies identified are outlined in Table D.

## 4.1.2 Inspection Code

The inspection was conducted in accordance with API-570. Unless otherwise stated, API-570 refers to the Fourth Edition, dated February 2016, "Piping Inspection Code: Inspection, Repair, Alteration, and Rerating of In-Service Piping Systems."

#### 4.1.3 Integrity Testing

Ultrasonic wall thickness measurements of the piping were taken in accordance with API-570 and per the project scope. The ultrasonic testing was conducted at each pipe support location as well as sampling for internal corrosion at change in product direction locations per the guidelines of API-570. Condition monitoring locations (CMLs) were selected by taking into account corrosion or erosion that might occur in piping transporting refined products. API-570 recognizes that, theoretically, a piping "circuit" subject to perfectly uniform corrosion could be adequately monitored with a single CML. Since corrosion is seldom uniform, each piping circuit in this report had multiple CMLs (if not restricted by access).

CMLs were often selected to be at a circumferential weld joining a straight section of pipe with an elbow. The selected CML was typically on the downstream side of the elbow. Thus, if erosion were to occur its effects would be detected by a reduction in the wall thickness along the outer arc of the elbow when

compared to the inner arc. The erosion would also be detected on the adjacent downstream pipe section where turbulence would preferentially thin the portion of the pipe wall.

The wall thickness was measured at the 12:00, 3:00, 6:00, and 9:00 o'clock positions at each CML unless an obstruction prevented recording the thickness. A circular area approximately 0.25" in centered 1" off the toe of the circumferential weld or coupling was ultrasonically scanned. The minimum thickness value detected was recorded. The clock positions are determined by looking downstream and in the direction of product flow. To assist in documenting the thickness values and reduce the potential for error during future thickness examinations, the location of each CML for each piping section was noted. The ultrasonic wall thickness measurements are contained in Appendix B, Piping Thickness Measurements.

### 4.1.4 Findings

An external visual inspection of the piping systems at this facility was performed to determine the condition of the piping, associated hardware, and coating systems. In addition to any coatings, the following were visually inspected:

- Valves were inspected to determine evidence of leakage, deterioration, and proper support.
- Flanged connections were inspected to ensure proper engagement between bolts and nuts, evidence of leakage, proper class rating, and sufficient weld deposition for slip-on flanges, and distortion. Additional flanged joints were inspected for evidence of leakage, stains, or drips.
- Piping supports were inspected for evidence of distortion, pipe-to-support contact, corrosion, general spacing, and deterioration.
- Other ancillary equipment associated with the piping system were also inspected for overall integrity.

All the POL piping at the facility is constructed of coated carbon steel piping. An external inspection was performed on the valves, supports, gauges, and other ancillary equipment to assess the integrity of the system. Pumps and pressure reliving devices were not inspected. Deficiencies for this facility is listed in Table D.

#### 4.1.5 Piping Construction

Documentation was not available as to whether these piping systems were designed in accordance with a national code or standard. As a basis of this report, it was assumed they were designed and installed in accordance with a previous edition of ASME B31.3, "Process Piping" Code. The intent of this inspection was not to determine compliance of the piping to ASME B31.3; rather it was to determine the current condition of the piping system and to evaluate its integrity for continued operation under normal operating conditions. However, where it was necessary to refer to a design code, B31.3 was selected.

Industrial piping can be fabricated by either rolling plate material to form a cylinder or by extruding it from a single billet of steel. In the case of the former, welding will seal the longitudinal seam created by rolling the plate. The ASTM piping specification will determine the actual welding process used. When piping is extruded, however, it has no longitudinal seam. Although the exact piping specification and nominal wall thickness used to erect the piping is unknown, the piping most likely conforms to ASTM Specification A53, "Pipe, Steel, Black and Hot-Dipped, Zinc-Coated, Welded, and Seamless." This specification addresses seamless piping and two types of seam-welded piping. See Note below.

reviewed. The (b) (3) pipe reported 43.5 – 48.2 yield and 65.7 – 71.6 tensile on the August 2018 test. The samples on the May 2000 test report produced 49.7 – 53 yield and 70.6 – 76.8 tensile. These results produced exceed ASTM A53 Grade B material with 35 yield and 60 tensile per current edition of ASME B31.3 Table A-1. The computations in this report will use ASTM A53 Grade B based on Pipe Pedigree Report.

The piping in this facility has mostly electric fusion welded (EFW) longitudinal seams of unknown weld joint efficiency or quality factor and some that appear to be electric resistance welded (ERW) seams. Table 302.3.4 of ASME B31.3 provides longitudinal weld joint quality factors. Based on this table, ERW pipes are listed as 0.85 weld joint quality factors, and single butt-welded pipes are listed as 0.80. The computations in this report will use the lower of the two longitudinal weld joint quality factors.

Wall thickness values were calculated in accordance with Equation (3a) from Paragraph 304.1.2, "Straight Pipe under Internal Pressure," of ASME B31.3, "Process Piping" Code. This formula calculates the internal pressure design thickness for straight pipe and elbows. The minimum required wall thickness of piping may be greater due to additional pipe wall stresses introduced by support spacing, concentrated loads, or other structural factors. In low pressure and temperature applications, the required thickness is calculated in accordance with Equation (3a) from Paragraph 304.1.2. This calculation may be very low, indicating that the pipe would have insufficient structural strength to support its weight. For this reason, an absolute minimum thickness (AMT) value is calculated by *InterSpec, LLC* to set the lower limits to prevent sagging, buckling, and collapse at supports. The owner may elect a more stringent lower limit. AMT value is also known as Minimum Alert Thickness (MAT). AMT or MAT are usually not intended to mean that pipe components must be retired when one CML reaches the default limit but rather to flag locations were additional engineering evaluation should be completed to assure overall piping integrity.

## 4.1.6 Piping Classification

The piping in this report is not considered process piping as defined in API-570; however, applying the prescribed classification will mitigate leaks, fire, hazards to personnel, and system failures. API 570 classifies piping systems into four different classes (1, 2, 3, and 4); see table B. Such a classification system allows extra inspection effort to be focused on piping systems that may have the highest potential consequence if failure or loss of containment occurs. In general, the lower classified systems require more extensive inspection at shorter intervals in order to affirm their integrity for continued safe operation. InterSpec, however, recommends the use of Class (1) since API classification is based on the consequence, not likelihood, of failure. Class (1) is proposed because any piping failure would significantly affect operation of the facility as well as have a greater potential of safety risk to environment and personnel.

	Table B - API classification and recommended interval					
Class	ass Thickness Measurement (UT) Visual Inspection (V					
1	Lesser of 5 Years or half the remaining Life	Lesser of 5 Years or half the remaining Life				
2	Lesser of 10 Years or half the remaining Life   Lesser of 5 Years or half the remaining I					
3	Lesser of 10 Years or half the remaining Life	0 Years or half the remaining Life   Lesser of 10 Years or half the remaining Life				
4*	Optional	Optional				

<sup>\*</sup> Piping service that is essentially nonflammable and nontoxic.

Table C – Deficiency Color Code						
Mandatory Repairs must be done as soon as practical or before in service		Repairs must be done as soon as practical or before piping is placed back in service				
	Short-Term	May fail within 2 to 3 years if corrective actions are not implemented or the component replaced				
	Long-term Repairs	No near-term adverse effect				

Note: the time line in this deficiency color code is not intended to predict when a component or equipment will fail. It is rather a tool to prioritize action or repair items to maintain a level of integrity, prevent equipment failure, and prolong the working life of the systems inspected.

#### Note:

The findings listed in Table D are grouped by location at this facility and categorized A through E with JP-5 observation consolidated in paragraph F:

- A. Tank Gallery Piping
- B. Harbor Tunnel Piping
- C. UGPH Piping
- D. Surge Tank Piping
- E. FOR Piping
- F. (b) (3) JP-5 Piping from Tank 20 to (b) (3) (A) (July 2021 Observations)

# Table D Piping Deficiency

## A. Tank Gallery Piping

A1) **Finding:** Brass/bronze (low melting point) valve attached to the end blind flange of the (b) (3) (F24) line near Tank 15/16 (b) (3) (A) ).

Reference: M, Short-Term

Recommendation: Remove the brass/bronze valve and install carbon steel Class 150 ball valve

with flanged ends.



A2) **Finding:** Minor staining on the upstream throat plug of the DBB skin valve for Tank 16. Monitor as needed; note: plug cannot be removed without draining the tank.

Reference: A/I/J, Mandatory

Recommendation: Monitor the plug on the DBB valve until repaired. Remove plug from the

valve (when the tank is empty) and reinstall after applying pipe thread sealant.



A3) **Finding:** There is an HPV valve on Tank 16 before the skin valve that is missing a plug. Some fuel was noted inside the valve body.

Reference: A/I/J, Mandatory

Recommendation: Secure the end of the valve with a threaded pipe plug after applying

appropriate thread sealant (Valve opening should be secured when not in use).





ith a drain valve in-leu of a plug. The end of the valve A4) Finding: The DBB valves are equipp is not secured with a pipe plug. This was noted on Tank 16 (b) (3) DBB), Tank 15 (b) (3) DBB), Tank 10 ((b) (3) DBB), Tank 9 (b) (3) DBB), Tank 8 (b) (3) DBB), Tank 7 (b) DBB), Tank 6 (b) (3) DBB), Tank 4 (b) (3) (A) DBB), Tank 3 (b) (3) (A)
DBB), and Tank 2 (b) (3) DBB). Note: The drain valve will see the same pressure as the pipeline when DBB is in the open position.

Reference: A/J, Short-Term

Recommendation: Secure the end of the valve with a threaded pipe plug after applying

appropriate thread sealant (Valve opening should be secured when not in use).



A5) Finding: Coating failure and corrosion on tank (b) (3) (F-24) pipe at (b) (3) Reference: I, Short-Term

**Recommendation:** Replace the corroded steel saddle support. Consider a saddle that is secured (welded to the support structure) and a Teflon pad between pipe and saddle. Apply protective coating.



**Ке**fегелсе: І, **Long-Term** around the 7 o'clock position. Size could not be verified. That appears to be a dent underneath the thick coating is limited. There is one location near encapsulated asbestos coating from . Inspection of the pipe in this area to about A6) Finding: The (5) (F-24) line a arrs to have some type of thick asbestos or bitumen

Recommendation: Remove the thick asbestos or bitumen coating and evaluate dent geometry.

E – Pipe Support Inspection Summary). See Table (F-24) line. Note the bracing between pipe support is also corroded off at A \tag{Finding: Moderate corrosion on the base of plate and vertical member of

Reference: C/I, Short-Term

Recommendation: Replace the base plate and affected section of the vertical member of the


pipe support and diagonal bracing.






Reference: C/I, Short-Term engaged, wood shim used, saddle not secured to the I-beam. (F-24) line. Note: saddle is not A8) Finding: Pipe not adequately supported at (2) on (2)

the pipe support to the I-Beam structure. Consider installing a Teflon pad between pipe and Recommendation: Install pipe support saddle of sufficient height to support the pipe. Secure





A12) **Finding:** Threaded 2-24) between (b) (3) (A) carbon stee PD valve mounted on the underside of the

Reference: A/I/J, Long-Term

Recommendation: Remove the threaded valve and install a welded Schedule 80 pipe with

carbon steel Class 150 ball valve with flanged ends.





A13) **Finding:** Facility piping at the tank tees has nonstandard (None ASME B16.5) rated flanged fittings and non-standard weld tie-ins. Noted throughout the facility (tees between tanks). Tank 13/14 shown but typical at each Tee at this facility. ASME B31.3 Paragraph 304.7.2 allows "Unlisted Components" provided engineering analysis is conducted and meets one or more of the means stated in subparts. (a) through (d).

Reference: I/J, Long-Term

Recommendation: Consider upgrading to an ASME B16.5 rated flange and fittings with butt-

welded arrangement.





A14) **Finding:** The dresser coupling joint have esses on the (b) (3) at Tank 6 lateral has two rods that are loose. Notable movement/gap on the bottom harness lug and deflection rings. A gap of 0.250" to 0.300" measured on both top and bottom joint harnesses.

Reference: A/I/J, Mandatory

**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed. (Note: This dresser coupling is provided with double nut and does not

(b) (3) (A)

(b) (3) (A)


(b) (3) (A)

A15) **Finding:** There are coating failure and contact/bimetallic corrosion on the between 6. Pipe corrosion is due to contact with Unistrut.

Reference: I/J, Long-Term

Recommendation: Provide sufficient spacing between pipe and Unistrut. Repair the coating

on the pipe.



nged branch connection on top of (b) (3) (F-24) line A16) Finding: There is a 3welded an between (b) (3) (A) with six bolts that are not fully engaged.

Reference: I/J, Long-Term

**Recommendation:** Replace the fasteners that are not fully engaged. Provide a bolt of sufficient length.






A17) **Finding:** There is a threaded fitting with brass (low melting) valve on top of the (b) (3) pipe at (b) (3). Note: these types of valves are not intended to be used on fuel systems. Some staining noted at the packing nut.

Reference: A/I/J/M, Mandatory

Recommendation: Remove the threaded brass valve and install a welded Schedule 80 pipe









A18) Finding: Coating failure and some corrosion due to material drips from tunnel ceiling on the (JP-5) pipe at (b) (3) (no significant pitting noted).

Reference: I/J, Long-Term

Recommendation: Seal the tunnel ceiling to prevent material drips on the pipe or provide ceiling trays. Clean the pipe and repair the coating.





gap noted between the washer and harness lug. chiesing the deflection ring on the A22) Finding: Dresser coupling to Tank 1 line. Small

Reference: A/I/J, <mark>Mandatory</mark>

document review is needed. (Note: This dresser coupling is provided with double nut and does not sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out Recommendation: All restraining nuts should be snug (not torqued down but at least fully in






."022.0 ot "912.0 = 0.196" – 0.200" and UTT of 0.430" on unaffected area resulting in remaining thickness of ). Pit depth (5) (6) (9) Read inactive corrosion area between (6) (7)

Reference: A/I, Mandatory

additional suitability for continued service assessment approach discussed in API STD 570 and long (b) (3) spool or perform Recommendation: Replace the section of piping with 60-


AP RP 574 may be utilized when appropriate.





Reference: C/I, Long-Term

**Recommendation:** Shim pipe support so as to provide positive contact between pipe and saddle support. Consider Teflon shim between pipe and saddle.



A25) **Finding:** The second pipe support from Tank 9 for the pipe (floating pipe). It is 39- of unsupported pipe from tank to the tee.

Reference: C/I, Short-Term

**Recommendation:** Adjust the elevation of the pipe support plate to provide sufficient load bearing contact between pipe and support plate.



ange from the (b) (3) (F-76) header to lateral tees A26) Finding: Several of the fasteners o between Tank 9 and 10 have moderate corrosion.

Reference: A/I/J, Short-Term

Recommendation: Replace the fasteners at this flanged joint. Remove corrosion from the



A27) Finding: The branch piping on (6) (3) (F-76) header has a welded and flanged branch fitting at about the 2 o'clock position. Two fasteners were not fully engaged. This is located between (b) (3) and (b) (3) (approximately (b) (3) from (b) (3)).

Reference: I/J, Long-Term


Recommendation: Replace the fasteners that are not fully engaged. Provide a bolt of sufficient

length (b) (3) (A)

A28) **Finding:** Coating failure and some community sion due to material drips from tunnel ceiling on the (F-76) pipe at (b) (3) (no significant pitting or thickness loss noted).

Reference: I/J, Long-Term

**Recommendation:** Seal the tunnel ceiling to prevent material drips on the pipe or provide ceiling trays. Clean the pipe and repair the coating.



A29) **Finding:** There is a branch connection on the threaded fitting and valve. Some fuel staining was noted around the flange and pipe, but no active weeping was noted. The existing 1-threaded fittings and ball valve appear to be relatively new.

Reference: A/I/J, Mandatory

**Recommendation:** Disassemble the threaded fitting and reassemble after applying pipe thread sealant. Clean the staining from the flange joint, branch pipe and header pipe. Monitor the flanged joint and the threaded fittings. Alternatively; consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping must be drained to perform the work safely.



A30) Finding: Some staining noted on the (5) (3) (F-76) flange tie-in between Tank 3 and 4 (no active weeping noted). Note: the staining did not appear to be F-76 (based on odor and gas meter testing) and had the viscosity of oil. InterSpec suspects this oily substance is caused by one of the two following reasons: oil used to lubricate the bolts or areas rich in polyamide or amine content in the epoxy coating that caused yellowing/blushing and/or an oily exudate. Chemical reactions that form the exudate creates a chain of reactions that can lead to a sticky, oily, or waxy film appearing on the surface of the cured epoxy coating. Amine blush testing or lab testing is suggested to fully determine the fluid type. Review of prior history at this flange and work completed will aid in determining the exact source. Industry standard including gasket manufacturers do not recommend tightening or torquing a flanged fitting while it is in service.

Reference: A/I, Long-Term

**Recommendation:** Clean the staining from the flange joint, branch pipe and header pipe. Monitor the flanged joint. Alternatively, a hydrostatic test can be conducted to check the joint

tightness of the flange.



A31) **Finding:** There is a 4 x 6— wood support extending from the (b) (3) (F-76) to tunnel ceiling. Use and function unknown (Near (b) (3)). The wood beams do not appear to be bearing any load on the pipe (based on the gaps between wood and top of the steel saddle as well as gaps at the bolt notches).

Reference: C/I, Long-Term

Recommendation: Investigate the function of the wood support and remove from the pipe.

Provide alternate design for the intended function.






A32) **Finding:** One joint harness with gap ted on the (F76) dresser coupling at (b) (3). There are no deflection rings and adapters on the harness lugs. Note: Eight out of the sixteen lugs are installed backwards (those on the bulkhead side).

Reference: A/I/J, Mandatory

**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed. Rotate lugs or consider removing the dresser coupling and associated harness if engineering assessment indicates it is not needed.



A33) **Finding:** The dresser coupling at (b) (3) (A) on the (b) (3) (F76) has lugs installed backwards. There are no deflection rings and adapters on the harness lugs.

Reference: A/I/J, Short-Term

**Recommendation:** Rotate lugs or consider removing the dresser coupling and associated harness if engineering assessment indicates it is not needed. All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed.



A34) Finding: The section of (b) (3) JP-5 Piping from (b) (3) to (b) (3) (A) was not evaluated during this trip (An API-570 inspection along with various NDE was completed on this section of piping in July 2021). It was observed that several repairs were in progress on this segment of piping at the time of the 2022 inspection. Sections of pipe were isolated, cut, or blanked off.

Reference: No Code

**Recommendation:** Follow the requirements of API Std 570 required repairs and NDE. (NO PHOTO)

- B. <u>Harbor Tunnel Piping</u> (Note: All clock posit; when listed, are looking towards the UGPH)
  - B1) **Finding:** Moderate coating failure and corrosion on pipe, flange, and fasteners noted on all three lines (segment from (b) (3) to the UGPH bulk head). Corrosion due to drips from tunnel ceiling; there is currently a yellow tarp hanging above the pipes in this area. Notable corrosion was on the (b) (3) (JP-5) line.

Reference: I/J, Long-Term

**Recommendation:** Seal the tunnel ceiling to prevent material drips on the pipe or provide

ceiling trays. Clean the pipe and repair the coating.






B2) Finding: HPV are threaded valves, nipples, and ball float trap. Staining and weeping were noted around the threaded fitting on the (b) (3) (F-76) past isolation valve (b) (3). Similar staining and weeping were noted on the plugged HPV valve just before the bulkhead to UGPH on line.

Reference: A/I/J, Mandatory

**Recommendation:** Disassemble the threaded fitting and reassemble after applying pipe thread sealant on plugged/threaded HPV and the threaded ball float trap. Clean the staining from the fittings and pipe. Monitor the threaded fittings. Alternatively; consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping must be drained to perform the work safely (from valve (b) (3) (A) and bypass line to (b) (3)



B3) **Finding:** Staining noted around the three d LPD on the (b) (3) (F-76) just before the bulkhead to UGPH. A total of three threaded LPDs noted between (b) (3) and the UGPH bulkhead. **Reference:** A/J, Mandatory

**Recommendation:** Disassemble the threaded fitting and reassemble after applying pipe thread sealant /threaded LPDs (QTY 3). Alternatively; consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping must be drained to perform the work safely.





B4) **Finding:** Some staining and wetting were noted on the threaded LPD assembly on (F-76) LPD just past (b) (3) 0 (note the drip pan).

Reference: A/I/J, Mandatory

**Recommendation:** Disassemble the threaded fitting and reassemble after applying pipe thread sealant. Alternatively; consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping must be drained to perform the work safely.





B5) **Finding:** The (b) (3) (JP-5) line just past 690 and before UGPH bulkhead has a threaded LPD. There is notable corrosion on the pipe nipple (red arrow).

Reference: A/I/J, Mandatory

**Recommendation:** Disassemble the threaded fitting and replace with extra heavy pipe fittings. Alternatively; consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping (from (b) (3) (A) ) must be drained to perform the work safely.



B6) **Finding:** Another LPD with notable e nipple corrosion on the (b) (3) (JP-5) line before isolation valve #0156. See red arrow.

Reference: A/I/J, Mandatory

**Recommendation:** Disassemble the threaded fitting and replace with extra heavy pipe fittings. Alternatively; consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping (from (b) (3) (A)) must be drained to



B7) Finding: The (b) (3) (F-24) line has two threaded LPDs and one HPV (between (b) (3) and the (b) (3) (A) ). The first LPD and the HPV did not have staining or corrosion on fittings.

Reference: A/I/J, Short-Term

**Recommendation:** Consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping (from (b) (3) (A) and (b) (3)) must be drained

to perform the work safely.




B8) **Finding:** The second LPD on the (b) (3) (F-24) between (b) (3) and the has a notable corrosion on the pipe nipple (red arrow).

Reference: A/I/J, Mandatory

**Recommendation:** Disassemble the threaded fitting and replace with extra heavy pipe fittings. Alternatively; consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping (from (b) (3) (A) and (b) (3)) must be drained to


perform the work safely.



B9) Finding: Twin Seal DBB flange hold are drilled and tapped, when there is no possibility of fitting a hexagonal nut behind the flange when manufactured. The F-24 line between (b) (3) and the (b) (3) (A) has four studs on the top and four studs on the bottom with minimal thread engagement to the DBB flange (tank side flange). Threaded engagement of only 0.250 to 0.550 inches was measured. There is also one stud on the other side of the (b) (3) (A) that is not fully engaged with less than 0.500 inches measured. Red arrow shows measured engagement depth of studs (white dots/lines marked with white paint on the flange).

Reference: I/J, Short-Term

**Recommendation:** Replace the fasteners that are not fully engaged. Provide a bolt of sufficient length. See manufacturer's instruction for the required bolt or stud size for drilled and tapped flange holes.



B10) **Finding:** Several areas of coating failure (minor to moderate noted on all three lines in the harbor tunnel). Location and extent of coating damage is provided in Table H (Coating Failure Summary).

Reference: I/J, Short-Term to Long-Term (noted in the harbor tunnel)


Recommendation: Clean the pipe and repair the coating.



B11) Finding: Four arc strikes/weld lines ween the 7 to 10 o'clock position; each approximately 3 long, noted near miter weld on (F-76) line just before (D) (3) Inc. The purpose and cause of these weld features are, but arc gouge depth of 1/32" to 3/32" was measured. Note: these appear to be original construction fit-up anomalies.

Reference: 1/J, Long-Term

**Recommendation:** Remove coating and conduct close visual inspection along with liquid penetrant testing (PT) or magnetic particle testing (MT) of the arc strikes/weld lines.





B12) **Finding:** Nonstandard flange configure on (blind flange) noted on the (b) (3) (JP-5) line near (b) (3) . A 12- welding neck-flange with flat plate welded is used. Note: ASME B16.5 NPS 12 class 150 blind flange has a minimum flange thickness of 1.190". The center plate in the current configuration has thickness of 0.933".

Reference: I/J, Long-Term

Recommendation: Replace with ASME B16.5 rated blind flange.






B13) **Finding:** Some moderate oil staining noted on (b) (3) (A) ) gear box near (b) (3) wye.

Reference: A/I/J, Long-Term

**Recommendation:** Clean staining from the valve actuator gear box and EIM actuator. Verify sufficient lubricant is still preset. Service the valve actuator gear box and EIM actuator.



B14) **Finding:** Coating failure and corrosion noted on the steel pipe supports at various locations. Noted on the base plate, on angle iron, and tunnel wall attachment points.

(b) (3) (A) (b) (3) (A)


Reference: C/I, Short-Term

Recommendation: Replace the base plate and affected section of the vertical member of the


pipe support along with horizontal support-to-wall attachment angle iron.







Reference: A/J, Long-Term



B16) **Finding:** Majority of the piping support in the box (3) (A) has tack-welded steel wear plates between pipe and pipe support. Few locations with metal-to-metal contact and some corrosion were noted on the (5) (3) (F-24) and (5) (3) (JP-5) lines. The (5) (3) (F-76) line was mostly supported on concrete saddles with some welded steel anchor saddles. (b) (3) (A) and (b) shown. (See Table E for a full list of pipe support inspection summary)

Reference: C/J, Short-Term

**Recommendation:** Repair coating on the pipe and support. Provide a Teflon shim at location of metal-to-metal contact points



B17) **Finding:** The anchor type saddle sup t next to (b) (3) was previously cut (likely for pipe repairs or modification). The existing weld attachment is now only tack welds at two locations in the front of the saddle support (weaker anchor).

Reference: C, Long-Term

**Recommendation:** Engineering assessment may be required to determine if this saddle support is sufficiently anchored.



[Inspection finding continued on the next page]

B18) **Finding:** Several threaded fittings no on all three piping from (b) (3) (A). Majority of the fittings are equipped with valves and are used as LPDs and HPVs. Minor staining was noted on some threaded fittings, but no active weeping or leaks were noted during the inspection (note: system was not in operation or pressurized during the inspection). Table D-1 is provide to list the threaded fittings identified in the harbor tunnel from

**Reference:** A/I/J, Mandatory (Mandatory for the five locations identified with staining on Table D-1 below). The remaining threaded fitting without stating are considered as Long-term repairs.

**Recommendation:** Disassemble the threaded fitting and reassemble after applying pipe thread sealant for the five locations identified with staining in Table D-1. Alternatively; consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping must be drained to perform the work safely.




(See Table below for location of threaded fittings identified in the (b) (3) (A)

Table I	D-1 HPV and	LPD Location n the Harbor Tunnel (Fro	m (b) (3) (A)
Relative	Pipe	Description	Condition
o) (3) (A)			
		Threaded 1" HPV valve w/plug	Dry/no active corrosion
		Threaded 1" plug (Top)	Dry/no active corrosion
		Threaded 1" plug (Top)	Dry/no active corrosion
		Threaded 1" plug (Top)	Dry/no active corrosion
		Threaded 1" plug (Bottom)	Dry/minor corrosion
		Threaded 2" fitting w/ valve (Top)	Dry/minor corrosion
		Threaded 2" fitting w/ valve (Top)	Small stain at fittings
		Threaded 2" fitting w/ valve (Top)	Dry/minor corrosion
		Threaded 2" fitting w/ valve (Top)	Dry/minor corrosion
		Threaded 1.5" fitting w/ valve (Top)	Dry/minor corrosion
		Threaded 2" fitting w/ valve (Top)	Dry/minor corrosion
		Threaded 2" fitting w/ valve (Top)	Small stain at fittings
		Threaded 1/2" plug (Top)	Dry/no active corrosion
		Threaded 1/2" plug (Top)	Dry/no active corrosion
		Threaded 1" plug (Top)	Small stain at fittings
		Threaded 2" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 2" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 2" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 2" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 2" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 2" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 1.5" fitting w/ valve (Top)	Small stain at fittings
		Threaded 1.5" plug (Top)	Dry/no active corrosion
		Threaded 1.5" plug (Top)	Dry/no active corrosion
		Threaded fitting w/ valve (Top) on branch	Dry/no active corrosion
		Threaded 1" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 2" fitting w/ valve (Top)	Large stain at fittings
		Threaded 2" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 2.5" fitting w/ valve (Top)	Dry/no active corrosion
		Threaded 1.5" plug (Bottom)	Dry/no active corrosion
		Threaded 1.5" fitting w/ valve (Bottom)	Dry/no active corrosion
		Threaded 1.5" fitting w/ valve (Bottom)  Threaded 1.5" fitting w/ valve (Top)	Dry/no active corrosion
		Timeaded 1.5 Titting w/ valve (10p)	Dry/no active corrosion

B19) **Finding:** Isolation DBB (b) (3) (A) on the (b) (3) (F-76) line by 2 wye past (b) (3) is missing a nut and bolt on the DBB top plate.


Code Reference: A/I/J, Long-Term Recommendation: Install a nut and bolt.



B20) **Finding:** The (b) (3) (F-24) line has onstandard repair at bulkhead between (b) (3) (A) The repair includes a full encirclement welded split sleeve (clamshell) on (b) (3) (A) and a partial (patch plate style) repair on (b) (3) side of the bulkhead with square corner (API STD. 570 lists all repair patches shall have a min. of 1". Additionally, the patch repair cannot exceed ½ the pipe diameter (a full encirclement sleeve is required if the corroded area exceeds ½ the pipe diameter). Some coating failure and corrosion noted at the penetration.

Reference: I/J, Short-Term


**Recommendation:** Review repair details. Remove coating and conduct NDE (PT/MT) on the



B21) **Finding:** Two locations with composite repair sleeves "Clock Spring" noted on the (b) (3) (F-76) pipe at (b) (3) (A) each approximately 70-inches long. Review per ASME PCC-2 Article 401 recommended.

Reference: I/J, Long-Term


**Recommendation:** Review previous document to determine the reason for the repairs. Consider removing the composite repair sleeves and replace the section of piping as need.



B22) **Finding**: The concrete saddle (Saddle # 530) is cracked on the edge with large splint noted on (F-76) line at about the 7 o'clock position.

Reference: C, Short-Term


**Recommendation:** Repair the concrete saddle support. Consider installing a Teflon pad between the saddle and pipe.



B23) **Finding:** The (b) (3) (F-76) pipe a threaded (b) (3) HPV welded on top of a full encirclement welded split sleeve repair between (b) (3) (A) The ball valve does not have a lock, and the reducing bushings are not engaged completely in the valve. (Lock valve out)

Reference: A/I/J, Long-Term

**Recommendation:** Install a lock or wire seal to prevent accidental actuation of valve handle. Remove the reducing busing and install a 2- pipe plug. Consider a welded Schedule 80



B24) **Finding:** Coating failure and some corrosion on a welded branch on the (F-76) line. Corrosion around weld noted.

Reference: I/J, Short-Term

**Recommendation:** Repair the coating to arrest the corrosion on the branch connection and pipe.




B25) **Finding:** Pipe support with anchor bolts not embedded in the concrete noted on Table E – Pipe Support Inspection Summary)


Reference: C/I, Short-Term

Recommendation: Secure the anchor bolts to the base plate of the pipe support.






**Recommendation:** Replace the section of piping with 48-pipe spool. Additional suitability for continued service assessment approach discussed in API STD 570 and AP RP 574 may be



B27) Finding: There is a tack-weld fit up ("Welding Dog") tab on the (b) (3) (JP-5) line between (b) (3) (A) . Approximately 63" from (b) (3) . This was probably installed as a welding ground attachment point during recent hot work and never was removed. Not a standard practice. Temporary attachments are supposed to be removed and area tested with appropriate NDE.

Reference: A/J, Long-Term



CUI

[47]


ER-JBPHH.HI-RED HILL FACILITY-PIPING-MAY/2022 B28) Finding: Concrete saddle support (# 337) between (b) (3) (A) has several 1/8" rods between the pipe and the concrete saddle. Reason is unknown. Reference: C/I, Long-Term Recommendation: Remove the 1/8" rods between the concrete support saddle and pipe. Conduct visual inspection of the interface. Consider a Teflon shim between saddle and pipe.

B29) Finding: Several active and inactive pitting and general corrosion on section of the (JP-5) pipe, approximately 21-inches from were noted. The pitting/corrosion area is at the 12 o'clock position. Pitting depth of 0.060" to 0.095" was measured with UTT adjacent to the pits was 0.225" - 0.242" inches. Resulting in remaining metal thickness of 0.130" to 0.147".

Reference: A/I, Mandatory

**Recommendation:** Replace the section of piping with 60- long (b) (3) spool. Additional suitability for continued service assessment approach discussed in API STD 570 and AP RP 574 may be utilized when appropriate.





B32) **Finding:** Corrosion on pipe support a e tunnel wall attachment at (b) (3)

Reference: C/I/J, Short-Term


**Recommendation:** Replace the corroded pipe support members.





B33) Finding: Inactive pitting on (b) (3) (JP-5) line between (b) (3) (A) 10 o'clock. Corrosion Area is 8" x 8", Pit Depth is 0.050" - 0.135", Metal thickness on unaffected area is 0.226" - 0.234" resulting in a remaining metal thickness of 0.091" to 0.099". Reference: A/I, Mandatory


**Recommendation:** Replace the section of piping with pipe spool. Additional suitability for continued service assessment approach discussed in API STD 570 and AP RP 574 may be



B34) **Finding**: Inactive pitting on (b) (3) (JP-5) line between (b) (3) (A) at 5 o'clock. Corrosion Area is 6" x 6", Pit Depth is 0.050" - 0.089", Metal thickness on unaffected area is 0.241" - 0.234" resulting in a remaining metal thickness of 0.152" to 0.156". Reference: I, Short-Term

**Recommendation:** Consider replacing the section of piping with pipe spool. Continue coating maintenance and periodically survey area until the next API 570 inspection.





B38) **Finding:** (F-76) pipe has a correte pipe saddle # 501 (Between (b) (3) (A) ) not engaged with pipe (floating pipe). There is loose concrete aggregate between pipe and saddle. Borescope inspection in the cavity did not indicate corrosion/erosion at this area.

Reference: C/I, Short-Term

**Recommendation:** Remove the loose concrete aggregate between pipe and saddle and shim


with Teflon pad. Repair the saddle as needed.





B39) Finding: The (b) (3) (F-24) pipe has a plate tack welded to the bottom of the wear plate on . This was probably installed as a welding ground attachment point during recent hot work and never was removed. Not a standard practice. Temporary attachments are supposed to be removed and area tested with appropriate NDE. The grounding plate may also interfere with pipe movement (wear plates are designed to allow laterally movement across the pipe supports).

Reference: C/I, Short-Term





B40) **Finding: Pitting** Corrosion on the street of the str

Reference: A/I, Mandatory

**Recommendation:** Replace the section of piping with pipe spool. Additional suitability for continued service assessment approach discussed in API STD 570 and AP RP 574 may be utilized when appropriate.

(b) (3) (A)





B46) **Finding:** The concrete saddle (Saddl 36) is cracked on the edge with large splint noted on (F-76) line at about the 7 o'clock position.

Reference: C/I/J, Short-Term


Recommendation: Repair or replace the concrete saddle support.





B47) **Finding:** Out-of-round/flat spot noted on the (b) (3) (JP-5) between (b) (3) (A) bell-weld (12 o'clock to 3 o'clock position).

Reference: No Code



B48) **Finding:** Coating at the harbor tunnel consisted of bitumen with asbestos wrap; sections with wax tape wrap and coating with lead and another hazardous chemical.

Reference: No Code

**Recommendation:** Consider using Table H (Coating Failure and Corrosion Table) to prioritize areas to remove and repair coating. Some of the location highlighted in Table H (particularly ones with wrap) should be further evaluated after hazardous coating/wrap is removed.



(A)

B49) **Finding:** Air-to-concrete interface cossion and under-wrap corrosion near weld on (JP-5) pipe between (b) (3) (A) (bulkhead penetration). Corrosion is between 2 to 6 o'clock. Pit Depth is 0.0625" to 0.105", Metal thickness on unaffected area is 0.240" - 0.243" resulting in a remaining metal thickness of 0.135" to 0.138". The interface corrosion appears to be due to drips from ceiling and failed coating system. The interface corrosion does not seem to extend in to the concrete (small section of concrete chipped to check).

Reference: A/I, Mandatory

Recommendation: Replace the section of piping with (b) (3) (A) spool. Additional suitability for continued service assessment approach discussed in API STD 570 and AP RP 574 may be utilized when appropriate. Note replacement requires demolition and rebuild of the bulkhead. Alternatively, a (b) (3) (A) pipe can be installed using the existing (b)



B50) **Finding:** There are several locations that have a plate tack welded directly to the pipe. The function and use are unknown. One location on the (b) (3) line between (b) (3) (A) has a failed tack weld.

Reference: I, Long-Term


**Recommendation:** Consider removing these tack welded plates, grind down the tack welds and conduct NDE (PT).



B51) **Finding:** There is what appears to b pipe alignment tab weld that was not grounded flush near a circumferential weld by (5) (3). This appears to be original to the facility. Some corrosion was <u>noted</u> at the alignment tab weld.

Reference: I, Long-Term

Recommendation: Grind alignment tab weld flush and conduct NDE (PT).



B52) **Finding:** There is a mechanical dent on a bell joint located between depth of approximately 0.320 inches was identified at the 3 o'clock position. This is a dent with coincident feature (a dent geometrically overlapping a weld).

Reference: A/I, Mandatory

Recommendation: Conduct a follow-on NDE assessment of the bell weld.

(No Photo)

## C. UGPH Piping

C1) **Finding:** Two loose joint harnesses were noted on the discharge side of Pump (b) (3). Gaps measured between harness lug and nut were 0.082" and 0.734". Note: additional design and/or MFG document review is needed to determine how much is too much gap on the joint harnesses, but initial understanding is that gaps should not exceed the pipe-to-pipe gap specified within the coupling. Additionally, joint harness gaps should likely not exceed the deflection ring when provided (note all dresser couplings in the UGPH are not provided with deflection rings and adapters on the harness lugs).

Reference: A/I/J, Mandatory

**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed.



C2) **Finding:** Four loose joint harnesses were noted on the suction side of pump lower left = 0.200", lower right = 0.173", top right = 0.010", top left = 0.210" (See Notes above)

Reference: A/I/J, Mandatory

**Recommendation:** See Dresser Coupling restraining nut recommendation from above. (NO PHOTO)

C3) **Finding:** Pump shaft guard post not secured to the concrete pad on pump (b) (3) (pump appears to be <u>undergoing repair</u>).

Reference: I, Long-Term

**Recommendation:** Secure the pump shaft guard post prior to returning pump to service.



C4) **Finding:** Several open conduits and s or enclosures noted on pump (b) (3) (pump appears to be undergoing repair).

Reference: B, Long-Term

**Recommendation:** Secure all conduits and sensor enclosures prior to returning pump to service.



C5) **Finding:** Several loose fasteners noted on the upper half casing of Pump (b) (3) (pump appears to be undergoing repair).

Reference: A/I, Long-Term

Recommendation: Secure all fasteners to the casing prior to returning pump to service.



C6) **Finding:** Pump (b) (3) had a skillet installed on the discharge side of the pump nozzle. The assembled joint only had one gasket installed. Similar condition noted on (b) (3).

Reference: I, Long-Term

**Recommendation:** Consider using two gaskets when installing spectacle blind or skillet to protect the flange face and contact surface from damage; particularly for flanges with serrated finishes (ASME B16.5 and ASME PCC-1-2019). Inspect flange face when reassembling the flange.



C7) **Finding:** Some minor coating cracks — e noted on the discharge dresser coupling around the middle ring-to-follower joint area of Pump — discharge line (indicating potential movement). This movement is most likely due to loosened joint harnesses and not limitation of the dresser coupling (These couplings have demonstrated satisfactory performance when MFG specification and guidance are followed).

Reference: A/I, Short-Term

**Recommendation:** Inspect the dresser coupling and harness bolts after the spectacle blinds are removed. PM program that verifies dresser coupling mechanical integrity (verifying joint harness retention rod and follower bolt tightness). Alternatively, the dresser coupling can be dissembled and overhauled.



C8) **Finding:** Minor hairline crack noted on Pump (b) (3) pump pad. Note the hairline crack does not appear to be significant to warrant integrity concern and foundation pad is not exposed to precipitation were rebar corrosion is a concern.

Reference: I, Long-Term


Recommendation: Apply maintenance coating and monitor overtime.

(NO PHOTO)

C9) **Finding:** Strainer drain ball valve on the inlet side of the control valve is not plugged. Consider installing a plug on the strainer drain valve and remove only during maintenance (Typical for all control valves on the discharge side of pumps at UGPH).

Reference: A/I, Short-Term

Recommendation: Consider installing threaded pipe plug with appropriate thread sealant on



C10) Finding: Weeping at suction side pre e gauge associated with Pump (b) (3)

Reference: A/I/J, Mandatory

Recommendation: Remove pressure gauge and associated fittings; reinstall after applying pipe



C11) **Finding:** Hairline crack noted on Pump (b) (3) pump pad. Note the hairline crack does not appear to be significant to warrant integrity concern and foundation pad is not exposed to precipitation were rebar corrosion is a concern.

Reference: I, Long-Term

Recommendation: Apply maintenance coating and monitor overtime.



C12) Finding: Coating failure on pump casing on Pump (5) (3)

Reference: I/J, Long-Term

Recommendation: Prepare surface and apply maintenance coating.



C13) Finding: The ½- valve (b) (3) (A) mounted on the suction side of the pressure gauge pipe on pump (b) (3) is missing plug and valve is non-lockable type.

Reference: A/I/J, Short-Term

Recommendation: Install ½-discharge if valve is bumped.

C14) Finding: Several of the ball valves on the control valve are missing valve handles. Exact reason is unknown but suspected to prevent operation of the valves (Note: operating during emergency such as a tubing break or damage will be difficult with missing valve handles. (Typical for majority of control valves on the discharge side of pumps at UGPH).

Reference: I/J, Long-Term
Recommendation: Replace the valve handles and consider a car-seal for valve line up purpose

in-leu of valve handle removal.




C15) Finding: Minor bearing oil staining on pump casing (Typical for some pumps at UGPH). Pump (5) (3) shown.

Reference: I/J, Long-Term

Recommendation: Clean the oil staining and service the pumps as needed.





CUI

C19) **Finding:** Weeping at suction side pressure gauge associated with Pump (b) (3).

Reference: A/I/J, Mandatory

**Recommendation:** Remove pressure gauge and associated fittings; reinstall after applying pipe

thread sealant. Monitor fitting when pump is under pressure.



C20) **Finding:** One slightly loose joint harness was noted on the discharge side of Pump (b) (3). Gaps measured between harness lug and nut were 0.030". Note: additional design and/or MFG document review is needed to determine how much is too much gap on the joint harnesses, but initial understanding is that gaps should not exceed the pipe-to-pipe gap specified within the coupling. Additionally, joint harness gaps should likely not exceed the of the deflection ring when provided (note all dresser couplings in the UGPH are not provided with deflection rings and adapters on the harness lugs).

Reference: A/I/J, Short-Term

**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed.

(NO PHOTO)

C21) **Finding:** Two loose joint harnesses were noted on the discharge side of pump measured between harness lug and nut were 0.180" and 0.845" Note: additional design and/or MFG document review is needed to determine how much is too much gap on the joint harnesses, but initial understanding is that gaps should not exceed the pipe-to-pipe gap specified within the coupling. Additionally, joint harness gaps should likely not exceed the deflection ring when provided (note all dresser couplings in the UGPH are not provided with deflection rings and adapters on the harness lugs).

Reference: A/I/J, Mandatory

**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed.






C22) **Finding:** The outlet side flange bolts he control valve on Pump (b) (3) are not fully engaged.

Reference: I/J, Long-Term

**Recommendation:** Replace the fasteners that are not fully engaged. Provide a bolt of sufficient



C23) **Finding:** Two slightly loose joint harnesses were noted on the discharge side of Pump (b) (3). Gaps measured between harness lug and nut were approx. 0.030". Note: additional design and/or MFG document review is needed to determine how much is too much gap on the joint harnesses, but initial understanding is that gaps should not exceed the pipe-to-pipe gap specified within the coupling. Additionally, joint harness gaps should likely not exceed the deflection ring when provided (note all dresser couplings in the UGPH are not provided with deflection rings and adapters on the harness lugs).

Reference: A/I/J, Short-Term

**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed.






C24) Finding: The ball valve before the	ner on the inlet side of the control valve was in the
closed position at the time of the ins	spection on (b) (3). The control valve may not function as
intended when the system cannot dete	ect differential pressure.


Reference: I/J, Mandatory

**Recommendation:** Ensure all ancillary equipment is in the correct position prior to operation. Consider a car-seal for valve line up on critical equipment.



C25) Finding: Missing nut observed on the suction side of the joint harnesses of pump before continued operations: All restraining nuts should be installed and snug (not necessarily torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. (See next item about loose joint harness on the same dresser coupling)

Reference: A/I/J, Mandatory



C26) **Finding:** Moderate weeping/staining on front bearing shaft and casing on Pump (b) (3) (A) shown below.

Reference: A/I/J, Short-Term

Recommendation: Clean staining from pump casing and service as needed per

manufacturer's instruction.



C27) **Finding:** One loose joint harness on suction side of the joint harnesses of Pump (this is the same dresser coupling with the missing nut). Gaps measured between harness lug and nut were: Upper left = 0.250". lower left side = 0.275" (Facing pump) Note: additional design and/or MFG document review is needed to determine how much is too much gap on the joint harnesses, but initial understanding is that gaps should not exceed the pipe-to-pipe gap specified within the coupling. Additionally, joint harness gaps should likely not exceed the height of the deflection ring when provided (note all dresser couplings in the UGPH are not provided with deflection rings and adapters on the harness lugs).

Reference: A/I/J, Mandatory

**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG

document review is needed.





C28) **Finding:** Some inactive corrosion and bolt diameter reduction (due to the corrosion) noted on the suction side dresser coupling follower bolts on Pump (b) (3).

Reference: A/I, Long-Term

**Recommendation:** Consider replacing the dresser coupling follower bolts. Monitor until bolt

is replaced.



C29) **Finding:** The hazardous area rated flow switch (MFG by SOR Inc) mounted on the discharge side of Pump (10) (3) has a housing cover that is not secured. Will not meet hazardous area rating (NFPA class I, division II, Group D). Additionally, all housings must be properly "sealed" at the conduit connection and housing cover to maintain the NEMA classification.

**Reference: B, Short-Term** 

**Recommendation:** Ensure all electronic equipment is sealed per manufacturer and NFPA requirements.



C30) **Finding:** The ½- discharge side pressure gauge threaded fittings have several areas of wetting/weeping around the threaded fitting on Pump (5) (3). Wet absorbent pads noted beneath the fittings.

Reference: I, Mandatory

**Recommendation:** Dissemble the pressure gauge and associated fittings and reassemble the fittings with a suitable thread sealant.



C31) **Finding:** One slightly loose joint harness was noted on the discharge side of pump (6) (3). Gaps measured between harness lug and nut were approx. 0.030" (enough for the rod and bolt to move laterally).

Reference: A/I/J, Short-Term


**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed.

(NO PHOTO)

C32) **Finding:** Two slightly loose joint har es were noted on the discharge side of Pump (b) (3). Gaps measured between harness lug and nut were approx. 0.030" (enough for the rod and bolt to move laterally).


Reference: A/I/J, Short-Term

**Recommendation:** All restraining nuts should be snug (not torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Additional design and/or MFG document review is needed.



C33) **Finding:** Dresser lugs on Pump (b) (3) suction side are installed backwards (this was also noted on the other dresser couplings at UGPH). Joint harnesses are not equipped with double nuts **Reference:** A/I/J, Short-Term

**Recommendation:** Rotate lugs or consider removing the dresser coupling and associated harness if engineering assessment indicates it is not needed. The restraining nuts should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations.



C34) Finding: There are several open con s, exposed wires, and unsealed electrical equipment housing throughout the UGPH including what appears to be abandoned conduits on the floor. Will not meet hazardous area rating (NFPA class I, division II, Group D).

Reference: B, Short-Term

**Recommendation:** Ensure all electronic equipment and conduits are sealed per

manufacturer's and NFPA requirements.



C35) Finding: The open conduit on the UGPH floor will limit the secondary containment capability of the UGPH (no secondary containment).

Reference: B/I, Mandatory

Recommendation: Ensure all electronic equipment and conduits are sealed per manufacturer and NFPA requirements. Ensure all unused conduits are capped to prevent migration of vapors to other areas. Additionally, all unused conduit that penetrated the floor should be capped to prevent fuel escaping from the secondary containment in an event of a spill.







Reference: M, Short-Term

**Recommendation:** Remove the threaded brass valve and install a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends.



C37) **Finding:** Several staining, weeping fittings noted in the UGPH piping below the grating (on main header piping to/from the RH and main header to/from the lower yard tunnel). This was noted on tie-ins for temperature sensors, pressure sensors, HPVs, and other small-bore auxiliary fittings.

Reference: A/I/J, Mandatory

Recommendation: Disassemble and reassemble fittings with appropriate thread sealant.

Consider a welded Schedule 80 pipe with flanged instrumentation sensors.



C38) **Finding:** Several threaded fittings noted in the UGPH piping below the grating (on main header piping to/from the RH and main header to/from the lower yard tunnel). Note: some of the branch tie-in welds are not per industry standard (did not use Weldolet and other branch connecting fittings that provide integral reinforcement and reduce stress at joint). This includes HPVs, LPDs, and pressure sensors tie-in fittings.

Reference: A/I/J, Short-Term

**Recommendation:** Install weldolet and other branch connecting fittings that provide integral reinforcement and reduce stress at joint end of the pipe. Consider a welded Schedule 80 pipe



Y 12) on the bypass loop across the (b) (3) (F-76) C39) Finding: Lack of thread engagement line to/from the RH. This is on the pup piece that replaced the flow meter.

Reference: I/J, Long-Term


**Recommendation:** Replace the fasteners that are not fully engaged. Provide a bolt of



C40) Finding: Several transducers are attached to the pipe, and the conduit did not have seal-off fitting. There is no tag or marking on these transducers that provide the hazardous location rating or the enclosure NEMA rating. Additionally, the transducer is connected using ridged conduit which can potentially break during pipe or conduit movement.

Reference: A/B/I, Short-Term


Recommendation: Provide and install transducers and sensors that are in a NEMA rated enclosures or have an FM and ATEX certification for hazardous locations. Consider flexible conduit fitting when attaching transducers and sensors to system that may move during operation. Consider a welded Schedule 80 pipe with carbon steel ends for equipment tie-




C41) Finding: Several of the pressure transducers have past due calibration dates. (Due Date of 10/23/18)

Reference: I/H/J, Short-Term

**Recommendation:** Provide periodic calibration for all sensors and transducer.






C45) Finding: There is (b) (3) DBB valv the F76 line (Valve (b) (3) ) with six studs that are not fully engaged. The stud is supposed to be engaged on the upper position of the DBB flange anywhere from 1.75 to 1.88 inches. Threaded engagement of only 0.25 to 0.75 inches where measured. Green arrow shows the available thread depth, the red arrow shows measured engagement depth of studs. (black dots marked with black Sharpie on the flange).

Reference: I/J, Short-Term

**Recommendation:** Replace the fasteners that are not fully engaged. Provide a bolt of sufficient length. See manufacturers instruction for the required bolt or stud size for drilled and tapped

flange holes.




C46) **Finding**: There is a  $\frac{3}{4}$ - HPV on the (b) (3) (F-24) line after (b) (3) (A) line is routed towards the UGPH sump nut and terminates just before the sump. The end of this line is open without a pipe plug. This is located just below the UGPH sump access staircase.

Reference: A/I, Mandatory

Recommendation: Furnish and install a 3/4plug.







C48) Finding: Fuel soaked absorbent pads on the valves, piping, and UGPH floor (typical at several PRD branch connections). Fuel is from the PRD above the grating.

Reference: I, Mandatory



C49) **Finding:** Mechanical dent on (F-24) tie-in line (to/from surge tank). Dent depth is 0.505" with perpendicular orientation and length of 5" located 58" from the miter weld before the surge tank-to-UGPH bulkhead penetration. This results in a dent depth of 3.2%. Note: assessment indicates this dent is acceptable based on latest edition of API RP 1183; Assessment and Management of Pipeline Dents. Plain dents regardless of shape with depths up to 10% of the pipe diameter, without coincident features such as metal loss, welds, or cracks have been shown in testing to have the same failure pressure as plain line pipe (Section 1). Dent is also acceptable per API 579 section 12 Level 1 assessment (acceptable if it is < 7% of the pipe diameter). (See Table F – Mechanical Dent (MD) Inspection Summary).

Reference: I, Long-Term

Recommendation: Monitor at next API 570 inspection.

C50) **Finding**: (b) (3) pipe flange to/fro urge tank before the surge tank-to-UGPH bulkhead penetration does not appear to be ASME standard flange. ASME B31.3 Paragraph 304.7.2 allows "Unlisted Components" provided engineering analysis is conducted and meets one or more of the means stated in subparts. (a) through (d).

Reference: I/J, Long-Term

**Recommendation:** Consider upgrading to an ASME B16.5 rated flange and fittings with butt-

welded arrangement.




C51) **Finding:** Missing one nut and bolt on the (b) (3) (A) e that branches off the (1) (3) F-24 line from the lower yard tunnel ((b) (3) (A) ) (No close-up photo, but valve/flange before green arrow. Photo facing Surge tank bulk wall)

Reference: I/J, Long-Term

**Recommendation:** Replace the fasteners that are not fully engaged. Provide a bolt of

sufficient length.



C52) Finding: The JP-5 header manifold attached to the piping to/from the lower yard tunnel is gate valve ((b) (3) (A) ) at the end of header. The 3/4equipped with a 3/4allowing product to weep by. NOTE: no pressure relief device (PRD) provided to the header (trapped fuel). The F-24 and F-76 headers also do not have PRDs.

Reference: A/I/J/G, Mandatory

**Recommendation**: Replace the weeping valve. Consider adding a pressure relief system on the manifold. Considered a welded Schedule 80 pipe with carbon steel Class 150 ball valve

with flanged ends.



C53) **Finding:** All the gate valves on the let and outlet side of pump are equipped with valve actuators mounted on stitch-welded adapter plate (four stitch-welds approximately 1" to 1.5" long used). Several of the welds have hairline cracks (potential for adapter plate to shear off during actuator operation). Some had one affected weld, and some had up to three of the four welds showing sign of hairline cracks. (Note: weld inspection is limited due to coating. Coating removal and NDE required to gain full assessment). This was present on (b) (3) (A)

Reference: I, Short-Term

**Recommendation:** Repair the cracked welds or furnish and install new valve actuator mating post.



C54) **Finding:** Several of the PRDs were—eeping. Weeping noted on the CRL Pressure Relief Control body (manufactured by CLA VAL). Weeping noted on diaphragm between top cover and lower body. Some drips also noted on the strainer fittings, threaded stainless nipples, and tubing. No car-seal on PRDs and CRL. No pressure calibration sticker.

Reference: A/I/J/G, Mandatory

**Recommendation:** Service the PRD and associated components. Calibrate PRDs annually and provide car-seals to prevent unauthorized pressure adjustment of the PRD.



C55) **Finding:** The (b) (3) gate valve used on the JP-5 line to/from (b) (3) (A) is weeping at gate valve bonnet (b) (3) (A).

Reference: A/I, Mandatory

Recommendation: Service the valve or replace as needed.
(b) (3) (A)

C56) **Finding:** The PRV system for each piping in the UGPH has an Emerson Figure 533 flow control valve with Hydramotor actuator (QTY 6). The Hydramotor actuators still have the factory plastic caps on the unused conduit inlet ports. This will not meet hazardous area rating (NFPA class I, division II, Group D).

Reference: B, Long-Term

Recommendation: Remove plastic caps and install steel conduit plugs; tighten existing steel

conduit plugs (typical all).



## D. Surge Tank Piping

D1) Finding: Several locations without Teflon or isolation material were noted throughout the surge tank piping system.

Reference: C/J, Short-Term

Recommendation: Install Teflon shims/insulation strips between the pipe and saddle or half

round Teflon strips between the pipe and plate type supports.






D2) Finding: Deteriorated grout noted at the bottom of the pipe support at (b) (3) (A) (just past the (b) (3) (A)

Reference: C/I/J, Short-Term

Recommendation: Repair grouting at the base of the pipe support.



D3) **Finding:** The (b) (3) sample/water drain line that ties to the (b) (3) (A) (F-24) has a valve that is not secured in the closed position; potential for accidental spill (note: inspection team closed the valve during the inspection).

Reference: A/J, Short-Term

Recommendation: Consider a self-closing valve or a LOTO program.





from

Reference: A/I/J, Mandatory

Recommendation: Clean the staining and monitor. Repair as needed.



D5) Finding: Some staining noted on the bottom of the flange for the (b) (3) (A) just before pipe support (b) (3) (no active weeping noted). Note: the staining did not appear to be JP-5 (based on odor and gas meter testing) and had the viscosity of oil. InterSpec suspects this oily substance is caused by one of the two following reasons: oil used to lubricate the bolts or areas rich in polyamide or amine content in the epoxy coating that caused yellowing/blushing and/or an oily exudate. Chemical reactions that form the exudate creates a chain of reactions that can lead to a sticky, oily, or waxy film appearing on the surface of the cured epoxy coating. Amine blush testing or lab testing is suggested to fully determine the fluid type.

Reference: A/I, Long-Term

Recommendation: Clean the staining from the flange joint, branch pipe and header pipe. Monitor the flanged joint. Alternatively, a hydrostatic test can be conducted to check the joint

tightness of the flange.





D6) Finding: Some staining noted on the om of the flange for the (b) (3) (A); just before pipe support (b) (3) (no active weeping noted). Note: See comment in Item 5 above about non-fuel related oily material.

Reference: A/I, Long-Term

**Recommendation:** Clean the staining from the flange joint, branch pipe and header pipe. Monitor the flanged joint. Alternatively, a hydrostatic test can be conducted to check the joint tightness of the flange.



D7) Finding: There is a missing cap on a 1- ball valve that is mounted to the 4- low suction line at (b) (3) (A)

Reference: A/I/J, Short-Term

**Recommendation:** Secure the end of the valve with a threaded pipe cap after applying appropriate thread sealant (Valve opening should be secured when not in use). Consider a self-closing valve or a LOTO program.



D8) Finding: Lack of thread engagement noted on the (b) (3) low suction pipe flange from (b) (3)

Reference: I/J, Long-Term

**Recommendation:** Replace the fasteners that are not fully engaged. Provide a bolt of sufficient length



D9) **Finding:** There is a missing plug on a ch ball valve that is mounted to the Note: brass valve used.

Reference: A/I/J/M, Short-Term

**Recommendation:** Secure the end of the valve with a threaded pipe cap after applying appropriate thread sealant (Valve opening should be secured when not in use). Consider a self-closing valve or a LOTO program. Remove the brass/bronze valve and install carbon steel Class 150 ball valve.





D10) **Finding:** Some minor staining noted on the bottom of the (b) (3) (A) (no active weeping noted). Note: See comment in Item D5 above about non-fuel related oily material related to epoxy coating curing.

Reference: A/I, Long-Term

**Recommendation:** Clean the staining from the flange joint, branch pipe and header pipe. Monitor the flanged joint. Alternatively, a hydrostatic test can be conducted to check the joint

tightness of the flange.






D11) **Finding:** The TRV system flange at (b) (3) (A) is equipped with 1/16-gaskets instead of 1/8-gaskets.

Reference: A/I/G, Long-Term

Recommendation: Consider using 1/8- gaskets during the next tank inspection cycle or



D12) **Finding:** Some minor staining noted on the bottom of the flange for the (b) (3) (A) from Surge Tank 4; just before pipe support (b) (3) (some staining noted on the floor but no active weeping noted). Note: See comment in Item D5 above about non-fuel related oily material.

Reference: A/I/J, A/I, Long-Term

**Recommendation:** Clean the staining from the flange joint, branch pipe and header pipe. Monitor the flanged joint. Alternatively, a hydrostatic test can be conducted to check the joint

tightness of the flange.



D13) Finding: Some staining noted on the bottom of the flange for the (some staining noted on the floor but no active weeping noted). Note: See comment in Item D5 above about non-fuel related oily material.

Reference: A/I, Long-Term

**Recommendation:** Clean the staining from the flange joint, branch pipe and header pipe. Monitor the flanged joint. Alternatively, a hydrostatic test can be conducted to check the joint

tightness of the flange.





D14) **Finding:** Some staining noted on the tom of the NPS 4 low suction DBB skin valve flange from Surge Tank 4. Similar discoloration noted on the 1-sample line flange (likely due to drips from the 4-sample flange). Operators or others appeared to have applied Kolor Kut fuel gauging paste to detect weather the staining is fuel. Since Kolor Kut fuel gauging paste reacts to hydrocarbons; this method cannot distinguish between fuel versus other oils. Note: See comment in Item 5 above about non-fuel related oily material.

Reference: A/I, Long-Term

**Recommendation:** Clean the staining from the flange joint, branch pipe and header pipe. Monitor the flanged joint. Alternatively, a hydrostatic test can be conducted to check the joint tightness of the flance.



D15) **Finding:** There is a missing plug on a 1- sample ball valve that is mounted to the 4-low suction line at Surge Tank 4. Install a plug; consider a self-closing valve or a LOTO program.

Reference: A/I/J, Short-Term

**Recommendation:** Secure the end of the valve with a threaded pipe plug after applying appropriate thread sealant (Valve opening should be secured when not in use). Consider a self-

closing valve or a LOTO program.





## E. FOR Piping

E1) **Finding:** Threaded sampling pipe nipple on Tank 20 FOR Line after tank skin valve. The threaded pipe nipple is for the Bottom "BTM" sampling.

Reference: A/I/J, Long-Term

**Recommendation:** Consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve

with flanged ends.



E2) **Finding:** Missing Teflon pad (metal-to metal contact) between pipe and support on Tank 20 FOR line in the trench past tank sampling line branch.

Reference: C/J, Long-Term

**Recommendation:** Install Teflon pad between pipe and pipe support.



E3) **Finding:** Moderate corrosion on blind flange and fasteners on Tank 19 (abandoned branch to the sampling lines).

Reference: A/I/J, Short-Term

Recommendation: Replace corroded fasteners. Repair coating on pipe and flange assembly.





E4) **Finding:** Coating failure and corros on the I-beam type pipe supports within the trench (typical throughout the pipe run but noted to be moderate between Tank 20 and Tank 16).

Reference: C/I, Short-Term

Recommendation: Repair coating or replace the corroded pipe support.



E5) Finding: Displaced pipe support on piping within trench between

Reference: C/I, Short-Term

Recommendation: Adjust the pipe or pipe support to center the pipe across the center of the

support. Reinstall the Teflon pad.



E6) Finding: Displaced Teflon pad pipe support within trench at

Reference: C/J, Short-Term

Recommendation: Repair the pipe support.

(NO PHOTO)

E7) **Finding:** There is a flange installed on Tank 18 FOR line, but there is an ball valve that is not plugged off. There is a potential for the ball valve to be bumped and cause spill. This valve appears to be installed temporarily during the tank cleaning/inspection outage.

Reference: A/I/J, Mandatory

**Recommendation:** Secure the end of the valve with a threaded pipe plug after applying appropriate thread sealant (Valve opening should be secured when not in use). Consider a self-

closing valve or a LOTO program.



E8) **Finding:** Spray foam material used to 1 edge of AFFF Sump # 1. Foam material is in contact with pipe (Spray foam intent and function unknown).

Reference: I/J, Long-Term

**Recommendation:** Remove the spray from the bottom of the pipe.



E9) **Finding:** The top of flange just before the FOR concrete pit; Sump 7 (near Door C) is covered with concrete to include side of the flange, face of flange, and fasteners.

Reference: I/J, Long-Term

Recommendation: Clean the concrete splatter from the flanged joint.




E10) **Finding:** FOR concrete pit; Sump 7 (near Door C), is not lined. Fuel contact water is dropped in this sump before it is picked up with sump pump to downstream segment of the FOR line. There is moderate sump floor-to-wall deterioration with periodic bubble formation from bottom the sump.

Reference: A/I/J, Short-Term

**Recommendation:** Consider installing a stainless-steel tank or lining the concrete pit and testing annually. The sump can be tested by filling the sump with water to within 1" to 2" of the top rim and holding for a minimum of 2 hours. The sump will be considered satisfactory if

there is no measurable change in the water level





E11) **Finding:** The pressure gauge on the R line (from Sump 7 pump) is out of calibration, and the glass is cracked.

Reference: H, Short-Term

Recommendation: Replace the pressure gauge. Provide gauge calibration annually.



E12) **Finding:** Section of the wall mounted pipe by door C has a stained plastic wrap with C-clamp between the TEE and gate valve (indicating a leaking threaded joint).

Reference: A/I, Mandatory

**Recommendation:** Remove the plastic and investigate the reason for the plastic wrap at the Tee. Disassemble the threaded fitting and reassemble with appropriate thread sealant applied to

each joint. Consider a welded piping configuration.





E13) **Finding:** Section of the wall mounted pipe by door C has a wood shim between pipe and support. Note: pipe is not secured to the support.

Reference: C/I, Short-Term

**Recommendation:** Provide a steel pipe support that is secured to the I-beam. Provide Teflon I-

rod or Teflon pad between support saddle and pipe.



E14) **Finding:** Section for the FOR pipe ff Sump 7 is threaded piping until it ties in to the Tank 15/16 FOR line.

Reference: I/J, Long-Term

Recommendation: Consider a welded piping configuration.





E15) **Finding:** Section of NPS 1.5 threaded FOR piping between (b) (3) (A) has three segments of unsupported piping measuring 23 ft, 22 ft and 20 ft respectively. Note: industry standard is nine-span for 1.5-spaper.

Reference: C/I, Short-Term

Recommendation: Provide additional pipe support.



E16) **Finding:** Section of FOR piping from Sump 7 routes through the electrical room. Section of this pipe is not equipped with Teflon pads (metal-to-metal contact).

Reference: C/J, Short-Term

**Recommendation:** Install Teflon shims/insulation strips between the pipe and saddle or half-round Teflon strips between the pipe and I-Beam structure.



E17) **Finding:** The segment of the FOR and has four brass/bronze (low melting point) valves where the line ties in to Tank 15/16 FOR trench piping. This includes the temporary line that is attached to the F76 header pipe.

Reference: M, Short-Term

**Recommendation:** Remove the brass/bronze valve and install carbon steel Class 150 ball valve

with flanged ends. Consider a welded piping configuration.





E18) **Finding:** There are three pipe supports in the trench that are displaced near the FOR-line tie-in at Tank 15/16 (past the flange from the above photo).

Reference: C/I, Short-Term

**Recommendation:** Repair pipe supports; position the Teflon pads between pipe and support.





E19) **Finding:** Tank 16 sample lines are not equipped with skin valves positioned as close as practical to the tank shell (and or nozzle).

Reference: A/I, Short-Term

**Recommendation:** Install isolation valves at the tank skin valve at the next clean/inspect/repair project. Monitor sample lines, associated fittings, and threaded nipples periodically until skin valves are installed.



E20) **Finding:** Threaded sampling pipe ni on (b) (3) (A) tank skin valve. The threaded pipe nipple is for the Bottom "BTM" sampling.

Reference: I, Long-Term

**Recommendation:** Remove the threaded valve and install a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends



E21) **Finding:** (b) (3) (A) has one fastener that is not fully engaged.

Reference: I/J, Long-Term

Recommendation: Replace the fasteners that are not fully engaged. Provide a bolt of

sufficient length.





E22) **Finding:** The FOR piping within the trench by Tank 15 has a 2 x 4 wood shim (the support is slanted and not adequately supported).

Reference: C/I, Short-Term

**Recommendation:** Remove wood shim and provide a steel support of sufficient height. Install Teflon shim between pipe and support.



E23) **Finding:** There are three fasteners of ate valve past the skin valve that are not fully engaged at Tank 15.

Reference: I/J, Long-Term

**Recommendation:** Replace the fasteners that are not fully engaged. Provide a bolt of sufficient length.



E24) **Finding:** Tank 15 sample lines are not equipped with skin valves positioned as close as practical to the tank shell (and or nozzle).

Reference: A/I, Short-Term

**Recommendation:** Install isolation valves at the tank skin valve at the next clean/inspect/repair project. Monitor sample lines, associated fittings, and threaded nipples periodically until skin valves are installed.



E25) **Finding:** Product staining noted on (b) (3) (A) skin valve.

Reference: A/I/J, Mandatory

**Recommendation:** Monitor the plug on the valve until repaired. Service the valve

(when the tank is empty).





E26) Finding: (b) (3) (A) wa lated for ongoing repair activity by a contractor.

Reference: No Code

**Recommendation:** No Recommendation (Information only)

(NO PHOTO)

E27) **Finding:** The tank sampling system at Tank 13 was upgraded with new piping to include installing flanged joints in the past. Three flanged joints have cracked gaskets indicating potential improper torque sequence, over torqueing, or use of lubricants that chemically attacked gaskets to soften the binders and reduce the crush strength of the gasket.

Reference: A/I/J, Mandatory

**Recommendation:** Isolate flange and replace gasket (QTY 3)





E28) **Finding:** The FOR piping within the trench at Tank 13 does not have correct pipe supports. Wood pipe supports noted.

Reference: C/I, Short-Term

**Recommendation:** Install Teflon shims/insulation strip or half-round Teflon strips between the

pipe support.





Reference: A/I, Short-Term
Recommendation: Install isolation valves at the tank skin valve at the next clean/inspect/ repair project. Monitor sample lines, associated fittings, and threaded nipples periodically until skin

valves are installed.



E30) **Finding:** Tank 9 sample lines are not equipped with skin valves positioned as close as practical to the tank shell (and or nozzle).

Reference: A/I, Short-Term

**Recommendation:** Install isolation valves at the tank skin valve at the next clean/inspect/ repair project. Monitor sample lines, associated fittings, and threaded nipples periodically until skin valves are installed.



E31) **Finding:** Tank 8 sample lines are not equipped with skin valves positioned as close as practical to the tank shell (and or nozzle).

Reference: A/I, Short-Term

**Recommendation:** Install isolation valves at the tank skin valve at the next clean/inspect/ repair project. Monitor sample lines, associated fittings, and threaded nipples periodically until skin valves are installed.



E32) Finding: Some coating failure and can sion noted on the tank sampling lines throughout the facility; mostly on the threaded style sampling system that has not yet been upgraded to welded and flanged system. Tank 9 sampling system had the most aggressive corrosion on piping and supports. There are no skin valves close to the tank for Tank 9 sampling system. NOTE: additional evaluation to include coating/corrosion removal is required to fully access the affected sample pipe. A spill kit and pipe repair clamp should be readily available during

corrosion removal.

Reference: A/I, Wlandatory

Recommendation: Remove coating and corrosion on the sampling line from tank 9 to evaluate extent of pitting/corrosion. It is recommended to have pipe repair clamps and other temporary line repair materials prior to removal of the corrosion area. Coating failure and corrosion in all other areas can be repaired with maintenance coating.



E33) Finding: Missing coated U-bolts and isolation Teflon on Tank 5 FOR piping. (QTY 3) Reference: C\J, Long-Term

Recommendation: Consider coated U-bolts and install Teflon shims/insulation strips between



E34) **Finding:** Tank 4 sample lines are not ipped with skin valves positioned as close as practical to the tank shell (and or nozzle). This tank has approximately 30- of pipe between the tank and the first available isolation valve located at the sample manifold.

Reference: A/I, Short-Term

**Recommendation:** Install isolation valves at the tank skin valve at the next clean/inspect/ repair project. Monitor sample lines, associated fittings, and threaded nipples periodically until skin



E35) **Finding:** Section of FOR piping through the AFFF Sump Pit # 4 (Just past b) (3) is covered with plastic (reason unknown but assumed to protect FOR pipe during repair at the sump pit area).

Reference: I, Long-Term

Recommendation: Remove the plastic wrap.





E36) **Finding:** There is a segment of unsupported (b) (3) (A) piping spanning (b) (3) at Tank 3 (Note industry standard is fourteen span for 1.5-pipe).

Reference: C/I, Short-Term

Recommendation: Install additional pipe supports.



E37) **Finding:** Tank 3 sample lines are not to the tank shell (and or nozzle).

Reference: A/I, Short-Term

**Recommendation:** Install isolation valves at the tank skin valve at the next clean/inspect/ repair project. Monitor sample lines, associated fittings, and threaded nipples periodically until skin valves are installed



E38) **Finding:** Some staining noted on Tank 3 sampling system (just below the "135 sample line valve). The staining was noted on the downstream side of the valve (bottom, see red arrow). Note the valve was in the closed position. It is possible it may be active weeping when sample line is open but only sign of weeping noted during the inspection.

Reference: A/I/J, Mandatory

**Recommendation:** Clean the staining. Disassemble the threaded fitting and reassemble with appropriate thread sealant applied to each joint. Consider a welded piping configuration.





(Note: industry standard is fourteenline header is also bearing on the FOR line.

Reference: C/I, Short-Term

**Recommendation:** Provide additional pipe support.

E40) **Finding:** Missing Teflon pad (metal-metal contact) between pipe and support on FOR line between (b) (3) (A)

Reference: C/J, Short-Term

Recommendation: Provide and install a Teflon pad between pipe and support.



E41) Finding: Missing Teflon pad (metal-to metal contact) between pipe and support on FOR line

between (b) (3) (A)

Reference: C/J, Short-Term

**Recommendation:** Provide and install a Teflon pad between pipe and support.

(NO PHOTO)

E42) Finding: Missing Teflon pad (metal-to metal contact) between pipe and support on FOR line

between (b) (3) (A)

Reference: C/J, Short-Term

**Recommendation:** Provide and install a Teflon pad between pipe and support.

(NO PHOTO)

E43) **Finding:** The sump/pump bypass valve flange is missing a nut.

Reference: A/I/J, Mandatory

Recommendation: Replace the fasteners that are not fully engaged. Provide a bolt of sufficient

length.



(b) (3) pipe with repair clamps at the FOR-Sump (S-E44) **Finding:** There are three locations on downstream of the isolation valve (shown with green arrow). The presence of these types of clamps indicate there were areas of compromised pipe sections at this location. A 6", 16" and 8" long full circumferential, single-section stainless steel repair clamp manufactured by Romac Industries is used with a 54section of the pipe. See next related inspection item.

Reference: A/I/J, Mandatory

Recommendation: Replace section of the pipe.



E45) Finding: Several low ultrasonic thickness (UT) data were recorded near the locations where repair clamps are used. A section of FOR pipe was closely checked with a UT gauge, and several locations with thickness ranging from 0.106" to 0.190" were identified indicating over 55% of metal loss was present. The nominal thickness of (b) (3) pipe is 0.237". See next related inspection item.


Reference: A/I/J, Mandatory

Recommendation: Replace section of the pipe.

with low UT data and repair clamps is considered a E46) Finding: The section of piping ident dead-leg with stagnant area that normally has little or no significant flow. This section requires a low point drain (LPD) or periodic flushing to prevent microbial-influenced corrosion (MIC).

Reference: A/I/J, Mandatory


Recommendation: Install a system with LPD.



E47) Finding: The (6) (3) (A) on the sump pump discharge line before the strainer is missing a body cavity relief valve handle. The valve is also not plugged when not used.

Reference: A/J, Short-Term

Recommendation: Secure the end of the valve with a threaded pipe plug after applying appropriate thread sealant (Valve opening should be secured when not in use). Replace the valve handle and consider a car-seal for valve line up purpose in-leu of valve handle removal.



E48) Finding: The (b) (3) valve above the FOR isolation valve has a loose flange with several missing fasteners and a Camlock without a cap (potential spill point).

Reference: A/I/J, Mandatory

Recommendation: Secure the camlock opening by installing a lockable cap. Install new

fasteners that are not fully engaged.





CUI

E49) Finding: Missing coated U-bolts and isolation Teflon on FOR isolation valves supports.

Reference: C/J, Long-Term

Recommendation: Consider coated U-bolts and install Teflon shims/insulation strips between

the pipe and support.



E50) Finding: Segment of tunnel piping from the constructed with mechanical coupling (Style 77 Victaulic joint). Some discoloration corrosion cell and staining were noted at the following joints located at (b) (3) (A)

were labeled to aide in identifying and locating findings reported. The letter "F" is tacked to the pipe supports (numbers to distinguish the FOR pipe supports.

Reference: A/I/J, Mandatory

Recommendation: Replace Style 77 Victaulic joint with flanged and welded joint.

(b) (3) (A)

E51) **Finding**: (b) (3) (A) is damaged likely to impact with displaced pipe support and U-bolt.

Reference: C/I, Short-Term

Recommendation: Replace the damaged pipe support and install Teflon-coated U-bolts with

Teflon shim between pipe and support.






E52) **Finding:** Several locations with lose U-bolts, displaced Teflon pads, missing Teflon pads or loose hangers were noted. Some of the locations are summarized below with a full list to be provided in the report.

Reference: C/I, Short-Term

**Recommendation:** Install Teflon shims/insulation strips between the pipe and saddle or half-round Teflon strips between the pipe and I-Beam structure at all pipe support locations.



E53) Finding: Areas of total coating failu—nd heavy corrosion were identified on sections of the FOR line. Some of the locations are summarized in the table (note: some coating repair activity was noted during the inspection on some specific locations). See Table H for a full list of coating

failure and corrosion locations.

Reference: I/J, Short-Term



E54) Finding: There is a 2- TPD and ¾- TPV near (b) (3) (A) The LPD is missing a camlock cap, and there are two bolts that are not fully engaged on the 2- TPD flange.

Reference: I/J, Long-Term

Recommendation: Replace the fasteners that are not fully engaged. Provide a bolt of

sufficient length. Install a lockable Camlock cap.



E55) **Finding:** There is a 2- LPD and 74 ch HPV (b) (3) (A) The LPD is missing a camlock cap, and there are two bolts that are not fully engaged on the 2- LPD flange.

Reference: I/J, Short-Term

Recommendation: Replace the fasteners that are not fully engaged. Provide a bolt of sufficient



E56) **Finding:** An LPD with missing plug and a ball valve that is not locked-out was noted on the FOR line near (b) (3) (note: facility personnel corrected this finding).

Reference: No Code


**Recommendation:** No recommendation (facility personnel corrected this finding).



E57) **Finding:** An LPD with missing plug and a ball valve that is not locked-out was noted on the FOR line beneath (b) (3) staircase (note: facility personnel corrected this finding).

Reference: A/I/J, Short-Term

**Recommendation:** Secure the end of the valve with a threaded pipe plug after applying appropriate thread sealant (Valve opening should be secured when not in use). Replace the valve handles and consider a car-seal for valve line up purpose in-leu of valve handle removal.



E58) **Finding:** There is moderate coating the lure and some corrosion noted on the penetration sleeve just below the corrosion was noted at the NPS 6 pipe by the Link-Seal.

**Reference: I/J, Short-Term** 

Recommendation: Seal the concrete above the pipe penetration to stop water infiltration.

Remove the Link-seal, clean the pipe/sleeve and repair the coating.



E59) **Finding:** There are moderate coating failure and corrosion on the FOR riser flange just outside of (b) (3) door. Note: there is a threaded (b) (3) fitting with a pressure gauge mounted on the flange.

Reference: A/I, Short-Term

**Recommendation:** Replace the flange and fasteners. Install a welded and flange fitting in-lieu

of the threaded assembly currently installed.





The thickness data indicates approximately 0.020" to 0.035" internal corrosion on the segment of pipe with several external pitting ranging from 0.010" to 0.190". This section of FOR pipe is NPS 6 Schedule 40 with original thickness of 0.280". Pitting near depth ranging between 0.100" to 0.140" and local metal thickness of 0.252" Remaining metal thickness: (0.252" - 0.140" = 0.112"). This is equivalent of approx. 60% loss from original thickness or 56% localized loss. Segment of the piping near with the local metal thickness of 0.248" resulting in remaining metal thickness of (0.248" - 0.190") 0.058". This is equivalent of approx. 79% loss from original thickness or 77% localized loss. There are areas that are not accessible without pipe jacking with moderate corrosion and a suspected weeping/wetting noted at (b) (3) (A) Fuel odor detected at this location. This segment of piping from (b) (3) (A) Fuel odor detected at this is not fit for continued service and requires replacement. Length of pipe from the (b) (3) (A)

Reference: A/I, Mandatory

**Recommendation:** Isolate and secure this segment of the FOR piping from continued use. Replace the FOR piping from (b) (3) (A) valve (to DBB valve outside the



E61) Finding: Excessive vegetation around pipe (section of FOR pipe to (b) (3) (A)

Reference: I, Short-Term

Recommendation: Clear vegetation.





CUI

E62) Finding: The wooden staircase is partially resting on the pipe at one side of the landing.

Reference: I, Short-Term

Recommendation: Install a steel staircase across the pipe.






E63) **Finding:** The body cavity relief valve of the (b) (3) (A) valve (outside of the secondary containment of (b) (3) (A) is discharging to the isolated side (should discharge towards the tank side).

Reference: A/I/G, Short-Term

**Recommendation:** Move the differential thermal relief (DTR) bleed system to the other side (tank side) of the DBB valve. A crossover pipe with 1—TRV may also be installed per DoD



E64) **Finding:** The (b) (3) (A) (outside of the secondary containment of (b) (3) (A) has one loose fastener. Note: (b) (3) (A) has cathodic protection and fasteners with insulating flange kit (IFK) is required.

Reference: A/I/J, Short-Term

**Recommendation:** Tighten the loose fastener or replace. IFKs are required for the proper performance of cathodic protection system. Install a complete isolation flange kit





E65) **Finding:** The (b) (3) (A) valve (out of the secondary containment of (b) (3) (A) does not have a complete insulating flange kit (IFK). The gasket used does not appear to be insulating type and has one missing insulating washer. Additional test required to determine if IFK is functioning properly. NOTE: (b) (3) (A) and the segment of buried FOR piping outside of are protected by two sperate galvanic cathodic protection system.

Reference: I/J, Long-Term

**Recommendation:** IFKs are required for the proper performance of cathodic protection system. Note: it may be practical to install ICCP on (b) (3) (A) and remove the IFK to extend CP to the section of buried piping at (c) (review of the 2021 CP Report indicated the section of buried


piping had ineffective magnesium anode).



E66) **Finding:** The TRV bypass lines (QTY 2) at Tank do not have a complete insulating flange kit (IFK). Only has insulating washer on the lower flange. The gasket used also does not appear to be insulating type.

Reference: I/J, Long-Term

**Recommendation:** IFKs are required for the proper performance of cathodic protection system.



E67) **Finding:** The body cavity relief valve the (b) (3) (A) valve (outside of the secondary containment of Tank 311) is discharging to the isolated/capped side (should discharge towards the tank side). There is a potential to develop excessive pressure in the isolated/capped side of the pipe spool; shown with a red arrow below.

Reference: A/I/G, Short-Term

**Recommendation:** Move the differential thermal relief (DTR) bleed system to the other side (tank side) of the (b) (3) (A) A crossover pipe with 1- TRV may also be installed per DoD Standard Design AW 078-24-27.



F. (b) (3) (A)

(July 2021 Observations)

NOTE: Pertinent portions of the 2021 report is incorporated in this paragraph. Majority of the deficiency observation are repaired or in the process of being repaired at the time of the 2022 visit. The intent of this paragraph is to consolidate the reported observations and eliminate any data gap.

F1) **Finding:** Dresser coupling joints and associated joint harness at Tanks (a) (a) (b) (a) (b) (b) (c) (d) (d) are damaged due to the event of May 2021. Note: The dresser coupling middle rings at these tanks are only of 0.250" thick. Typical application per manufacturer is to use the same thickness as the pipe material. Pipe is NPS 12 with 0.375" thickness.

Reference: I, Mandatory

**Recommendation:** Replace the joint harness prior to returning pipe to service.






F2) **Finding:** There is mechanical damage with notable deformation at the pipe-support I-beam at Tanks 18, 19, and 20. There is damage to the adjacent ancillary equipment associated with the piping system at these locations (conduits, lights, and fire alarm sensors).

Reference: B/C/I, Short-Term

Recommendation: Replace the damaged I-beams and adjacent damaged conduits.






F3) **Finding:** There is an unknown style pipe stanchion support welded directly to an elbow on the drain line by Door C. It's unknown if the stanchion is seal-welded at the bottom.

Reference: B/C/I, Short-Term

**Recommendation:** Consider replacing with a conventional adjustable pipe support.







F8) **Finding:** There is spalling and broken uting noted between the pipe support I-beam structure base plate and floor at (b) (3) (A)

Reference: I/C/J, Short-Term






F9) **Finding:** There is moderate coating failure and associated corrosion on the valve body and associated hardware. Corrosion on fasteners, flanges, valve body, differential thermal relief (DTR) and pipe nipple noted. Location (b) (3) (A)

Reference: A/I/J, Short-Term

Recommendation: Replace the differential thermal relief (DTR) system including pipe nipple

and fittings. Repair the coating on the DBB valve and hardware.





F10) Finding: The body cavity relief nipple is in contact with the galvanized conduit. Potential for further corrosion due to dissimilar metal contact is present. Location (A)

Reference: A/I/J, Short-Term

Recommendation: Rework the conduit or the DBB relief pipe to eliminate the contact



the (b) (3) (A) F11) Finding: There is heavy corrosion valve body flanges promoting crevice corrosion on the fasteners.

Reference: A/I/J, Short-Term

Recommendation: Replace the flange fasteners. Consider Teflon coated studs and nuts.





F12) Finding: There is heavy corrosion on the conduits and fittings associated with (5) (3) (A) MOV may fail to operate properly if the corrosion on the conduit damages the internal wiring. Location (b) (3) (A)

Reference: B, Short-Term

Recommendation: Replace the corroded conduit and conduit fittings.





F13) **Finding:** There is a threaded nipple near tanks 11 and 12 installed with a <sup>3</sup>/<sub>4</sub>" ball valve. Note: There is staining/wetting on the lower threaded fitting. Location (b) (3) (A)

Reference: I, Mandatory

**Recommendation:** Disassemble the threaded fitting and reassemble after applying pipe thread sealant on plugged/threaded HPV and the threaded ball float trap. Clean the staining from the fittings and pipe. Monitor the threaded fittings. Consider a welded Schedule 80 pipe with carbon steel Class 150 ball valve with flanged ends. Note: Section of this piping must be drained to

perform the work safely.





F14) **Finding:** There are eleven mechanic dents identified in this segment of piping inspected. Dents range from minor to moderate (0.030" to 0.950" depth). There is one dent (A-MD-2) identified at that a depth of 0.950" with coincident features (corrosion with multiple gouges). Dents identified are listed in Table F.

Reference: I, Mandatory

Recommendation: Repair the dent located at (b) (3) (A)

Monitor the other ten dents at

the next API-570 inspection.





F15) **Finding:** Facility piping girth (circumferential) welds include several non-typical bell and spigot style fillet welds. Some welds are direct bell-bell buttweld attachments. These welds appear to be part of the original construction. There has been ongoing replacement effort of these welds with several identified and replaced since the 2015 API 570 inspection. There are currently ten (10) welds with a bell and spigot/ bell-bell weld configuration in the segment inspected.

Reference: No Code

**Recommendation:** Replace these joints to bring the piping system to current standards. Engineering evaluation may be required to qualify continued long-term use of these welds.



F16) **Finding:** A weld undercut was idented on the 18" (located approx. 100-inches past b) (3) at the 4 o'clock position. Undercut appears to be due to poor weld start/termination tie in technique. Note: Weld direction also charged at this location contributing to the porosity. The measured depth was 1/32". This is acceptable for normal and Category M fluid service.

Reference: No Code

**Recommendation:** Apply top coat on the area where the coating was removed for weld measurement.





F17) **Finding:** The piping supports at this facility are partial saddle support with contact at approximately 5 and 7 o'clock position. There is direct metal-to-metal contact with no Teflon shims/insulation strips. There are also several locations where pipe supports are missing with the pipe resting directly on I-Beams. There is pipe coating failure at support contact locations. See: Table E1.

Reference: C/J, Short-Term

**Recommendation:** Install Teflon shims/insulation strips between the pipe and saddle or half-round Teflon strips between the pipe and I-Beam structure at all pipe support locations. Repair

the pipe coating at the pipe supports.





F18) **Finding:** There are moderate coating—lure and heavy corrosion at the pipe support I-beams The majority of the corrosion was noted at the base of the I-beams. Spalling concrete/broken grouting fill were also noted. These were identified on the second pipe support after Tank 19 (left hand side facing the tank), on the first pipe support after (b) (3) (A)

Reference: C/J, Short-Term

**Recommendation:** Replace the section of I-beams with heavy corrosion. Prepare and recoat

the surface. Repair the spalling concrete footing.





F19) **Finding:** There is a loose I-beam base plate anchor bolt at (b) (3)

Reference: C, Short-Term

**Recommendation:** Replace or secure the I-Beam base plate anchor bolt.





F20) **Finding:** There is an 18- dresser coupling joint and associated joint harness between S 25 just past the concrete penetration. Visual inspection did not reveal any deficiencies at this location. A slight tilt was noted and documented. Approximately a 0.9 ° tilt over a 36" span was recorded.

Reference: No Code


**Recommendation:** Monitor at the next API 570 inspection.



F21) **Finding:** The (b) (3) dresser coupli—oint harness has four lugs that are welded backwards on the upstream side of the coupling. This is not per mfg. details.

**Reference: I, Short-Term** 


Recommendation: Rotate lugs or consider removing the dresser coupling and associated



F22) **Finding:** There is corrosion under insulation (CUI) at the (b) (3) (A) dresser coupling. Located approximately 8 to 10 o'clock position. The remaining insulation was removed at (b) (3) (A) and the area was inspected/documented.

Reference: I, Long-Term

Recommendation: Prepare the area and repair the coating. Add a CUI inspection to the API



F23) **Finding:** Internal portions of the piping at Tanks (b) (3) (A) were visual inspected to get a condition assessment. The piping is in satisfactory condition with minor pitting. Minor pitting was noted at the bottom of the pipe (likely due to standing water). Pitting depth of 0.030" to 0.050" was noted.

Reference: I, Long-Term

Recommendation: Exercise the tank valves periodically to move product and prevent standing

water at low points of the piping system.





F24) **Finding:** Minor pipe pitting was ide ed on (b) (3) (A) lateral pipe below a bubbled coating (between pipe support (b) (3) (A) Piping is (b) (3) (A) Pitting depth of 0.030" to 0.070" was noted.

Reference: I, Long-Term



F25) **Finding:** There is some damage to the ceiling trays at the ceiling trays were added to redirect water drips away from the pipe.

Reference: I, Long-Term







F26) **Finding:** There is no hold down u-bolts or slide-guide to prevent lateral pipe movement at the end of the header pipe run (at (b) (3)


Reference: I, Long-Term

**Recommendation:** Consider a guided support with hold down lugs at the type pipe support (particularly when adjoining tanks are disconnected from pipe header).



F27) **Finding:** There is coating damage at pipe repair sleeve located approximately 2.5

Reference: I, Long-Term
Recommendation: Recoat the piping. Consider drip trays to redirect drips away from the pipe.



#### **Reference Section**

Reference highlights sections of state, federal, manufacturer, and industry standard codes and regulations. Letters are affixed at the beginning of a reference code for ease of reference from the deficiency list. These letters are also color coded in the deficiency report based on the condition of the unit inspected and the timeline for failure (see deficiency section color codes). In accordance with API standards, the owner/operator has ultimate responsibility for complying with the provisions outlined in API publications. The requirements referenced from ASME are based upon sound engineering principles, research, records of tests, and field experience, and an appreciation of the problems of manufacture, installation, and use derived from consultation with and information obtained from manufacturers, users, inspection authorities, and others having specialized experience.

#### A Leaks

# **Tightness of Piping**

NFPA 30-27.3.2 — "Piping systems shall be maintained liquid tight. A piping system that has leaks that constitute a hazard shall be emptied of liquid or repaired in a manner acceptable to the authority having jurisdiction, or it shall be emptied of liquid, vapor freed, and no longer be used."

NFPA 30-21.8.6 – "Storage tanks and their appurtenances, including, piping, normal vents, emergency vents, overfill prevention devices, and related devices, shall be inspected and maintained to ensure that they function as intended in accordance with written procedures."

<u>API 570 Section 5.5.5</u> – "An external visual inspection is performed to determine the condition of the outside of the piping, insulation system, painting, and coating systems, and associated hardware; and to check for signs of misalignment, vibration, and leakage."

#### API 574 Section 10.1.2

"Leaks can be safety or fire hazards. They can cause premature shutdown of equipment and often result in economic loss." Tightening flange bolts in a pressurized line is only recommended when special steps are taken to avoid the following potential problems: bolt interaction, bolt overloading, and flange deflection."

### **B** Electrical Wiring

NFPA 30-7.3.2 – "All electrical utilization equipment and wiring shall be of a type specified by and installed in accordance with NFPA 70, National Electrical Code."

NFPA 30-6.5.4 (Static Electricity and Grounding) "All equipment such as tanks, machinery, and piping shall be designed and operated to prevent electrostatic ignitions. All metallic equipment where an ignitable mixture could be present shall be bonded or grounded. The bond or ground or both shall be physically applied or shall be inherently present by the nature of the installation. Any electrically isolated section of metallic piping or equipment shall be bonded or grounded to prevent hazardous accumulation of static electricity. All nonmetallic equipment and piping where an ignitable mixture could be present shall be given special consideration."

# **C** Pipe Supports

NFPA 30-27.6.1 – "Piping systems shall be substantially supported and protected against physical damage and excessive stresses arising from settlement, vibration, expansion, or contraction. The installation of nonmetallic piping shall be in accordance with the manufacturer's instructions." (Also, see API 570-7.5).

NFPA 30-27.6.3 – "Piping that passes through or pierces a dike wall or the wall of a structure shall be designed to prevent excessive stresses and leakage due to settlement or fire exposure."

<u>API 570 Section 7.8</u> – "Piping shall be supported and guided so that (a) its weight is carried safely, (b) it has sufficient flexibility for thermal expansion or contraction, and (c) it does not vibrate excessively."

### API 574 Section 7.4.15

"Localized corrosion at pipe support contact points is the result of crevice corrosion due to deposits that contain corrosive species, water, and oxygen typical of an externally corrosive environment."

#### **D** Combustible Materials

NFPA 30-22.12.5 – "Structures such as stairways, walkways, instrumentation shelters, and supports for piping and equipment that are located in a remote impoundment area, diked area, or spillway draining to a remote impoundment area shall be constructed of noncombustible materials."

# **E** Underground Piping

NFPA 30-27.6.5.1 – "Underground piping shall be installed on at least 6 compacted bedding material."

NFPA 30-27.6.5.2 – "In areas subject to vehicle traffic, the pipe trench shall be deep enough to permit a cover of at least 18 (450 mm) of well-compacted backfill material and pavement."

NFPA 30-27.6.5.3 – "In paved areas where a minimum 2 (50 mm) of asphalt is used, backfill between the pipe and the asphalt shall be permitted to be reduced to 8 (200 mm) minimum."

NFPA 30-27.6.5.4 – "In paved areas where a minimum 4 (100 mm) of reinforced concrete is used, backfill between the pipe and the asphalt shall be permitted to be reduced to 4 (100 mm) minimum."

NFPA 30-27.6.5.5 – "In areas not subject to vehicle traffic, the pipe trench shall be deep enough to permit a cover of at least 6 (150 mm) of well-compacted backfill material."

NFPA 30-27.6.5.6 – "A greater burial depth shall be provided when required by the manufacturer's instructions or where frost conditions are present."

NFPA 30-27.6.5.7 – "Piping within the same trench shall be separated horizontally by at least two pipe diameters. Separation need not exceed 9 (230 mm)."

# F Pipe and Valve Marking

<u>ANSI / ASME A13.</u> – ANSI/ASME recommends pipe marking labels must effectively communicate the contents of the pipes and give additional detail if special hazards.

## **G** Pressure/Safety Relief Valves

### API 570 Section 6.7.1

"Pressure relieving devices (PRDs) shall be tested and repaired by a repair organization experienced in relief valve maintenance. PRDs should be inspected, tested, and maintained in accordance with API 576."

### API 570 Section 6.7.3.1

"Pressure-relieving devices shall be tested and inspected at intervals that are frequent enough to verify that the valves perform reliably in the particular service conditions."

### API RP 576, Section 6.3.e

"Seals installed to protect the spring setting and ring pin setting have not been broken."

## **H** Pressure Gauge and Flow Meters

Out of calibration, damaged, or broken gauges, flow meters, and other indication devices will fail to indicate when abnormal conditions are present in piping system.

### I Structural Integrity/Coating of Piping or System

### API 574 Section 5.4 (Flanged Joint)

"Flanged joints should be assembled by trained and qualified personnel (see Appendix A of ASME PCC-1). Consideration should be given to establishing a finished joint examination process. See 6.2 on flanged joint leakage."

#### API 574 Section 10.1.16

"Defects in protective coatings and in the waterproof coating of insulation will permit moisture to come into contact with the piping. Corrosion may be found under clamps on suspended lines. Piping mounted on rollers or welded support shoes is subject to moisture accumulation with resultant corrosion."

#### API 574 Section 7.4.14

"To prevent freeze damage, precautions need to be taken to drain, purge, or heat trace systems where moisture could collect and unexpectedly freeze during severe or sudden subfreezing temperature excursions."

#### API 570 Section 5.1.2

"Flange fasteners should be examined visually for corrosion and thread engagement. Fasteners should be fully engaged. Any fastener failing to do so is considered acceptably engaged if the lack of complete engagement is not more than one thread."

### API 574 Section 7.3.3

"A number of factors can affect the rate and nature of pipe wall corrosion. They include, but are not limited to piping external conditions, including: coating/painting, insulation, and soil conditions, as applicable."

### API 574 Section 7.4.6 (Soil-to-air Interface – SAI)

"If significant corrosion is noted, thickness measurements and excavation may be required to assess whether the corrosion is localized to the SAI or can be more pervasive to the buried system. Thickness readings at SAIs can expose the metal and accelerate corrosion if coatings and wrappings are not properly restored."

### API 574 Section 7.4.4 (dead legs)

"The corrosion rate in dead-legs can vary significantly from adjacent active piping. Consideration should be given to removing dead-legs that serve no further process purpose."

### *NOTE:*

1. Majority of code compliance, when not listed, are in this category based on API 570, ASME B31.3, and other pertaining industry standards.

Systems that have an "I" deficiency code may not necessarily all have a direct code reference or code requirement but are identified as a deficiency to assure the overall integrity of the component if deemed to be out of manufacturer's intended performance, use, or based on good engineering practice.

### J Government/Military Standards

Items in this group fall under government and host nation standards or regulations

### UFC 3-460-01 paragraph 9-8 (a) (welded flanges)

"For steel piping systems, use weld neck forged flanges with raised faces having a modified spiral serrated gasket surface finish, except for piping 2—(50 mm) and less located in contained pumphouses... Slip-on flanges are not permitted in new systems. Use of slip on flanges may be considered in connections between new and existing systems/components only when dimensional factors prevent the effective use of weld neck flanges."

### UFC 3-460-01 paragraph 9-8 (e) (welded connections)

"Use welded connections for joining steel pipe. Use flange connections for joining pipe to equipment. Use threaded connections only where unavoidable such as on differential pressure gages, pressure snubbers, and fuel sample points."

### UFC 3-460-01 paragraph 9-8 (f) (fasteners)

"Use carbon steel bolts, studs, and nuts with carbon steel flanges. Use stainless steel bolts, studs, and nuts with stainless steel flanges. Stainless steel bolts may be used on carbon steel flanges in corrosive environments."

### UFC 3-460-01 paragraph 9-8 (1) (insulating flange kits)

"Provide insulating flange kits at locations required for the proper performance of cathodic protection systems on underground piping."

### UFC 3-460-01 paragraph 9-8 (h) (branch connections)

"Make branch connections with butt welded tees except where the branch is at least two pipe sizes smaller than the run, in which case the branch connection can be made with a forged or seamless branch outlet fitting."

### UFC 3-460-01 paragraph 9-10 (a) (Pipe Coating)

"Protect the exterior surfaces of all aboveground carbon steel piping systems by coating in accordance with applicable service requirement. Exterior surface of pipe shall be prepared by abrasive blasting and cleaned prior to coating application."

### UFC 3-460-01 paragraph 9-3.1 (Pipe Marking/Identification)

"Identify piping in accordance with Chapter 2 of this UFC. In addition, mark fuel lines at head of fueling pier near valves, and mark valve "open" and "close" positions."

### UFC 3-460-01 paragraph 9-2.1(h) (Valve Thermal Relief)

"All installed double block and bleed valves and other valves within the piping system should be provided with thermal relief devices."

### UFC 3-460-01 paragraph 9-3.3 (Pipe Supports)

"Rest piping on supports, both insulated and uninsulated, on a steel shoe welded to the bottom of the pipe. Leave the shoe free to move on the support (See additional details in Facility Pallet)."

### UFC 3-460-01 paragraph 9-3.5 (TRVs)

"Provide any section of pipe that has the potential to be isolated by a shut-off valve or other means with a thermal relief valve to relieve the isolated piping section. Provide a thermal relief of the internal cavity of valves where pressure is trapped when the valve is in the closed position (double block and bleed plug valves for example)."

### UFC 3-460-03 paragraph 6-6.3.1 (TRVs)

"Inspect exterior of thermal and pressure relief valves for corrosion. Repaint as required. Information plates attached to thermal and pressure relief valves *must not be painted over*."

"Thermal and pressure relief valves must be validated for proper calibration by isolating the valve and using the test connection provided on the piping in conjunction with a hand pump and portable reservoir. The operating pressure must be checked against the set pressure listed on the stamped information plate attached to the valve."

### UFC 3-460-01 paragraph 9-4.76 (Double-wall piping)

"Provide double-wall piping for Ground Vehicle Fueling Facilities. For other applications, do not use double-wall piping unless required by state or local regulations, and approved by Service Headquarters."

### AW 78-24-27 Drawing D.10 Detail 4. (TRV rated for GPM)

This detail shows TRVs rated for liquid service (rated in GPM) versus rated for gas service (SCFH).

### UFC 3-460-01 paragraph 6-10 (Aboveground Piping and Equipment Coatings)

"A three coat system (primer, intermediate, and top coat) is the primary protective coating system for aboveground piping. All surface corrosion or damage coating must be removed per coating manufacturer's requirements. In addition, abrade immediate area surrounding repair to feathered edge to allow proper adhesion of repair coating layers. Do not paint stainless steel, aluminum or galvanized surfaces."

### UFC 3-460-01 paragraph 9-9 (Exterior pipe Coating)

Protect the exterior surfaces of all aboveground carbon steel piping systems by coating in accordance with applicable service requirement.

### **K** Cathodic Protection

Deficiencies related to cathodic protection based on the visual evaluation of the aboveground section of the piping are listed in this group. Detailed CP assessment, data, and findings will be submitted by others.

### NACE SP0169-2013 Section 4.3.1 (Isolation Kits)

"Isolation devices such as flange assemblies, prefabricated joints, unions, couplings, or, where permissible, sections of nonconductive piping should be installed within piping systems in which electrical isolation of portions of the system is required to facilitate the application of external corrosion control. Locations considered:

- 4.3.1.6 The junction of dissimilar metals;
- 4.3.1.8 The junction of a coated pipe and an uncoated pipe;
- 4.3.1.9 Locations at which electrical grounding is used, such as motorized valves and instrumentation."

### L Safety System

Deficiencies related to safety systems and devices unrelated to piping systems are referenced in this section based on the visual evaluation of the aboveground section of the piping or components associated with piping.

### Unguarded Platform OSHA §1910.25

"Open-sided floors or platforms 4 or more above adjacent floor or ground level must be guarded by a standard railing (or equivalent) on all open sides, except where there is an entrance to a ramp, stairway, or fixed ladder.

1910.25(b)(1) requires that employers ensure handrails, stair rail systems, and guardrail systems are provided in accordance with final 1910.28. This provision is intended to protect workers from falling off stairways.

### 1910.28(b)(1)(i)

Except as provided elsewhere in this section, the employer must ensure that each employee on a walking-working surface with an unprotected side or edge that is 4 (1.2 m) or more above a lower level is protected from falling.

### 1910.28(b)(3)(iv)

Each employee is protected from falling into a ladderway floor hole or ladderway platform hole by a guardrail system and toeboards erected on all exposed sides, except at the entrance to the hole, where a self-closing gate or an offset must be used."

### M Low Melting Point Material

<u>NFPA 30-27.2.4</u> – "Low Melting Point Materials. Materials that melt at a low temperature, including but not limited to aluminum, copper, or brass; materials that soften on fire exposure, such as plastics; or nonductile materials, such as cast iron."

NFPA 30-27.4.4 – "...(1) They are resistant to damage by fire, (2) They are located so that any leakage resulting from failure will not expose persons, important buildings, tanks, or structures."

NFPA 30-27.4.4 – "...(1) They are connected above the normal operating liquid level of the tank (See also 27.4.4.5 (2) conditions)."

Pipe Sumport Sa Sa A B B B Sa			
	Incade to trans	radie et – ripe Support inspection Summary (	
€	Type of Support	Finding	Recommendation
	Saddle Type – Partial (1)	Saddle is displaced from support beam with 1.5" Unistrut support placed underneath.	Remove Unistrut and reposition saddle.
	Saddle Type – Partial	Not in contact with saddle with minor gaps.	Refer to Note (2)
	Bulk head penetration	Sleeve in contact with the bottom of the pipe. Abrasion marks on pipe at 3 o'clock and 5 o'clock	Realign pipe to prevent contact (crevice corrosion) at bulkhead penetration
	Missing Saddle Support	Pipe is resting on I-beam with no saddle or Teflon shims/insulation strip.	Refer to Note (2)
	Saddle Type – Partial	There is a mechanical dent on pipe at pipe support location	See Mechanical Dent Table.
	Missing Saddle Support	Pipe is resting on I-beam with Teflon shims/insulation strip and wood	Remove wood shim. Refer to Note (2)
	Broken Saddle Support	Metal to metal contact. No Teflon shims/insulation strip. Pulled anchor stud at concrete footing. Broken grouting.	Install support with insulation or half-round Teflon strip. Re-secure anchor stud and re-grout
	Saddle Type – Partial	Missing one nut at concrete footing. Broken grouting.	Replace missing nut and re-grout.
$oxed{\mathbb{Z}}  ar{\mathbb{Z}}  \ ar{\mathbb{Z}}\  \ ar{\mathbb{Z}}\  \ ar{\mathbb{Z}}\ $	Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Z   Š   B   S   Z	Bulk head penetration	Sleeve in contact with the bottom of the pipe. Abrasion marks on pipe at 3 to 4 o'clock and 5 to 8 o'clock positions. Note there is a lapwelded sleeve at this penetration.	Realign pipe to prevent contact (crevice corrosion) at bulkhead penetration
	Missing Saddle Support	Shimmed with Teflon pads.	None
	Saddle Type - Partial	The pipe is partially in contact with the pipe support.	Add shims to support to gain contact.
	Bulk head penetration	Not in contact with pipe	None
S	Saddle Type – Partial	Not in contact with saddle.	Add shims to support to gain contact.
$\geq$	Saddle Type – Partial	The pipe is partially in contact with the pipe support.	Add shims to support to gain contact.
TAT	Missing Saddle Support	There is no saddle support and the pipe is not resting on the I-beam.	Add shims to support to gain contact.
SI	Sleeved penetration	Minor coating failure with fireproofing seal pushed out	Repair coating & reseal sleeve opening
SE	Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
W	Missing Saddle Support	There is no saddle support and the pipe is not resting on the 1-beam.	Add shims to support to gain contact.
Σ Σ	Saddle Type – Partial	Not in contact with saddle.	Add shims to support to gain contact.
χ c	Saddle Type – Fartial	Metal to metal contact. No 1 effon shims/insulation strip.	Kerer to Note (2)
ĭ σ	Saddle Type – Partial	Metal to metal contact. No Teffon shims/insulation strip.	Refer to Note (2)
S	Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
W	Welded Saddle	NA	NA
Sa	Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Se	Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
SE	Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
SE	Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)


$\overline{\mathcal{A}}$	
$\widetilde{}$	
•••	
<u>Q</u>	

Concrete penetration	Concrete anchor point with pipe incased in the 60" of concrete.	Continue NDE program (LRUT) at next API 570 inspection
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Bulk head penetration	Direct concrete penetration without sleeve (12" long).	Continue NDE program (LRUT) at next API 570 inspection
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)
Saddle Type – Partial	Metal to metal contact. No Teflon shims/insulation strip.	Refer to Note (2)

### Note:

- E1-1) Partial saddle support with contact at approximately 5 and 7 o'clock positions
- E1-2) Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
- E1-3) Penetration through concrete walls/bulkheads are included in this table
- Laterals to tanks also have several metal-to-metal style saddle supports or are directly resting on I-beam without Teflon shims/insulation (See Table E2) E1-4) Table only includes header piping from [D] (3) [A]

Photos of Typical Saddle Supports from Table E1



This page is intentionally left blank.

	Tabl	Table E2 – Pipe Support Inspection Summary (All other sections)	ections)
Pipe Sunport* S)#	Type of Support	Finding	Recommendation
(b) (3) (A)		FOR PIPING	
	Saddle Type – Partial (1)	I-Beam type support is displaced	Reposition support and add Teflon shim
	Saddle Type – Partial <sup>(1)</sup>	I-Beam type support is displaced and Teflon pad has slid out	Reposition support and add Teflon shim
	Saddle Type – Partial (1)	Thee 3 pipe supports that are displaced or not in contact with pipe (at tank 16)	Reposition support and add Teflon shim
	Saddle Type – Partial (1)	Wood used to shim pipe support (at tank 15)	Remove wood add larger pipe support
	N/A	Wood pipe support used (tank 13). Note area was under construction	Install support. Refer to Note (2)
	N/A	27'-11" of unsupported pipe from tank 3 to the next support	Install support. Refer to Note (2)
	N/A	31'-0" of unsupported pipe from tank 4 to the next support	Install support. Refer to Note (2)
	Saddle Type – Partial <sup>(1)</sup>	Missing Teflon spacer/pad between pipe and support	Refer to Note (2)
	Saddle Type – Partial <sup>(1)</sup>	Missing Teflon spacer/pad between pipe and support	Refer to Note <sup>(2)</sup>
	Saddle Type – Partial <sup>(1)</sup>	Missing Teflon spacer/pad between pipe and support	Refer to Note (2)
	Angle iron with U-bolt (4)	Missing Teflon spacer/pad between pipe and support	Refer to Note (2)
	Angle iron with U-bolt	Damaged pipe support (impacted by a moving vehicle)	Replace support
	Angle iron with U-bolt	Loose U-bolt	Tighten the U-bolts
	Angle iron with U-bolt	Loose U-bolt	Tighten the U-bolts
	Angle iron with U-bolt	Displaced bottom Teflon pad	Refer to Note (2)
	Strap type pipe support	Missing pipe clamp bolt (no isolation Teflon pad)	Install clamp bolt. Refer to Note (2)
	Strap type pipe support	Dislodge pipe clamp bolt (no isolation Teflon pad)	Secure Strap. Refer to Note (2)
	Strap type pipe support	Dislodge pipe clamp bolt (no isolation Teflon pad)	Secure Strap. Refer to Note (2)
	Strap type pipe support	Missing pipe clamp bolt (no isolation Teflon pad)	Install Strap. Refer to Note (2)
	Strap type pipe support	Dislodge pipe clamp bolt (no isolation Teflon pad)	Secure Strap. Refer to Note (2)
	Strap type pipe support	Dislodge pipe clamp bolt (no isolation Teflon pad)	Secure Strap. Refer to Note (2)
	Strap type pipe support	Dislodge pipe clamp bolt (no isolation Teflon pad)	Secure Strap. Refer to Note (2)
	Strap type pipe support	Missing pipe strap at the support (no isolation Teflon pad)	Secure Strap. Refer to Note (2)
	Strap type pipe support	Support anchor dislodge from tunnel wall	Secure pipe support. Refer to Note (2)
	Unistrut type pipe clamp	Missing pipe clamp (no isolation Teflon pad)	Secure pipe clamp. Refer to Note (2)
	Angle iron with U-bolt	Heavy corrosion at saddle-to-pipe crevice (no isolation Teflon pad)	Repair support. Refer to Note (2)
		Tank Gallery (5)	
	Adjustable plate type	Small deflection on pipe support after dresser coupling (Tank 16)	Adjust support (raise the plate).
	Adjustable plate type	Pipe is not bearing on support (floating pipe) (F-76)	Adjust support (raise the plate).
	Adjustable plate type	Small deflection on pipe support after dresser coupling (Tank 7)	Adjust support (raise the plate).
	Adjustable plate type	No Teflon between pipe and support (Tank 5)	Refer to Note (2)
	Adjustable plate type	Loose nut on adjustable plate/some deflection on plate (NPS 20)	Secure the nut on the Plate
	Adjustable plate type		Adjust support (raise the plate).
	Adjustable plate type	Pipe is not bearing on support (floating pipe) NPS 12	Adjust support (raise the plate).

6.4
$\alpha$
$\overline{a}$
64
_
$\sim$
_
⋖,
_
$\rightarrow$
—
-4
( )
=
$\mathbf{z}$
$\overline{}$
_
_
Ь
_
CILITY-PIPING-
_
-
$\blacksquare$
()
ч.
$\checkmark$
. ~
_
_
7
$\overline{}$
$\mathbf{T}$
TT1
-
$\simeq$
HI-RED HILL
<u> </u>
_
_
_
т.
т.
_
1
m
ER-JBPHF
ı,
-5
~
177
_

Pipe Sunport* S)#	Type of Support	Finding	Recommendation
	Steel Saddle	Pipe is not fully bearing on support (partial support) F-24	Shim. Refer to Note (2)
	Utility support	Unistrut in contact with pipe at	Repair pipe add shim
	Utility support	Unistrut in contact with pipe at causing coating failure/corrosion	Repair pipe add shim
	Steel Saddle	Pipe is not fully bearing on support (partial support) F-24	Shim. Refer to Note (2)
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel Saddle	Moderate corrosion on the steel saddle (F-24)	Replace steel saddle
	Steel Saddle	Moderate corrosion on the steel saddle (JP-5)	Replace steel saddle
	Steel Saddle	Moderate corrosion on the steel saddle (JP-5)	Replace steel saddle
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel Saddle	Pipe is not bearing on support, missing saddle (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel Saddle	Wood shim b/w saddle and pipe support member/dislodge (F-24)	Repair
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-24)	Shim. Refer to Note (2)
	Steel support member	There is moderate coating failure and some corrosion on the horizontal	Repair coating
	0.4-1	pipe support 1-beam	n
	Steel Support member	Contact type abrasion and corrosion at pipe support/pipe (JF-5)	Repair coating. Refer to Note
	Steel Saddle	Moderate corrosion on the steel saddle (JP-5)	Replace steel saddle
	Steel Saddle	Pipe is not bearing on support (floating pipe) (F-76)	Shim. Refer to Note (2)
	Steel Saddle	Moderate corrosion on the steel saddle (JP-5)	Replace steel saddle
	Steel Saddle	Unistrut in contact with pipe at	Repair pipe add shim
	Steel support member	Contact type abrasion and corrosion at pipe support/pipe (JP-5)	Repair coating. Refer to Note (2)
	Steel Saddle	Coating failure and corrosion at saddle support (JP-5)	Repair coating. Refer to Note (2)
	Steel Saddle	The pipe is partially in contact with the pipe support (JP-5)	Shim and monitor at next inspection
	Steel Saddle	The pipe is partially in contact with the pipe support (JP-5)	Shim and monitor at next inspection
	Steel Saddle	Moderate corrosion on the steel saddle (F-24)	Replace steel saddle
	Steel Saddle	Moderate corrosion on the steel saddle (F-76)	Replace steel saddle
	Steel saddle	Moderate corrosion on the steel saddle (F-24)	Replace steel saddle
	Steel saddle	Missing steel saddle (floating pipe) (F-24)	Install saddle. Refer to Note (2)
	Steel saddle	Missing steel saddle (floating pipe) (F-24)	Install saddle. Refer to Note (2)
	Steel saddle	Missing steel saddle (floating pipe) (F-24)	Install saddle. Refer to Note (2)
	Steel saddle	Rail-ties wedged between pipe and saddle (F-24)	Remove rail-ties. Refer to Note (2)
	Steel support member	Corrosion on base of pipe support and I-beam	Repair
	Steel support member	Corrosion on base of pipe support and I-beam	Repair
	Saddle type	Pipe is not bearing on support (floating pipe) (F-76)	Shim. Refer to Note (2)
	Saddle type	Pipe is not bearing on support (floating pipe) (F-76)	Shim. Refer to Note (2)

ipe port* S)#	Type of Support	Finding	Recommendation
	Saddle type	Pipe is not bearing on support (floating pipe) (F-76)	Shim. Refer to Note (2)
	3	Harbor Tunnel	60
	Steel Saddle type	No wear plate or Teflon pad between pipe and pipe support (F-24)	Refer to Note (2)
	Steel Saddle type	No wear plate or 1 effon pad between pipe and pipe support (F-24)	Keier to Note (**)
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Steel support member	No wear plate or Teflon pad between pipe and pipe support (F-24)	Refer to Note (2)
	Steel support member	No wear plate or Teflon pad between pipe and pipe support (JP-5)	Refer to Note (2)
	Steel support member	No wear plate or Teflon pad between pipe and pipe support (F-76)	Refer to Note (2)
	Steel Saddle (anchor)	Anchor type welded saddle was cut of the pipe (likely for previous repairs/mods). The existing weld attachment is only tack welded at two location (weaker)	Engineering assessment may be required
	Concrete Saddle	Concrete saddle # 530 is cracked on the edge.	Repair as needed/ monitor
	Concrete Saddle	Corrosion on steel plate on saddle # 548 (there is steel plate between pipe and concrete saddle)	Repair as needed/ monitor
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Concrete Saddle	Concrete pipe saddle # 501 is not engaged with pipe (floating pipe).	Remove aggregate, shim and monitor at
		There is loose concrete aggregate between pipe and saddle	next inspection
	Concrete Saddle	Wood shim at saddle #502 (between steel wear plate and saddle	Remove wood and install Tetlon shim
	Steel support member	Moderate corrosion on horizontal support attachment to wall (QTY 4)	Replace
	Concrete Saddle	Concrete pipe saddle # 481 is not engaged with pipe (floating pipe)	Shim and monitor at next inspection
	Steel support member	Support wear plate to support not engaged (JP-5) (floating pipe)	Shim and monitor at next inspection
	Steel support member	Minor to moderate corrosion on the base plate due to standing water	Repair corroded base plates
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Steel support member	Anchor bolt on the base of plate are not secured down to the floor	Secure anchor bolts
	Steel support member	Anchor bolt on the base of plate are not secured down to the floor	Secure anchor bolts
	Steel support member	No wear plate or Teflon pad between pipe and pipe support (JP-5)	Refer to Note (2)
	Steel support member	No wear plate or Teflon pad between pipe and pipe support (JP-5)	Refer to Note (2)
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Steel support member	Anchor bolt on the base of plate are not secured down to the floor	Defer to next inspection (has grouting)
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Steel support member	Support wear plate to support not engaged (JP-5) (floating pipe)	Shim and monitor at next inspection
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Steel support member	No wear plate or Teflon provided after repairs (JP-5) (floating pipe)	Shim and monitor at next inspection
	Concrete Saddle	Concrete saddle support (# 337) has several 1/8" rods between the pipe and the concrete saddle. Reason is unknown	Monitor at next inspection
	Steel support member	No wear plate or Teflon provided after repairs (F-24) (floating pipe)	Shim and monitor at next inspection

Pipe Sunport*	Type of Support	Finding	Recommendation
S)#			
(3)(A)	Steel support member	No wear plate or Teflon provided after repairs (JP-5)	Refer to Note (2)
	Concrete Saddle	Concrete pipe saddle # 256 is not engaged with pipe (floating pipe)	Shim and monitor at next inspection
	Concrete Saddle	Wood shim at saddle #231 (unknown reason, but no corrosion noted)	Remove wood and install Teflon shim
	Steel support member	No wear plate or Teflon provided after repairs (F-24) (floating pipe)	Shim and monitor at next inspection
	Steel support member	Corrosion on base of pipe support (attachment to tunnel floor)	Repair
	Concrete Saddle	Concrete pipe saddle # 312 is not engaged with pipe (floating pipe)	Shim and monitor at next inspection
	Steel support member	No wear plate or Teflon provided after repairs (JP-5) (floating pipe)	Shim and monitor at next inspection
	Steel support member	Moderate corrosion on horizontal support attachment to wall (QTY 4)	Replace
	Steel support member	Moderate corrosion on horizontal support attachment to wall (QTY 1)	Replace
	Steel support member	No wear plate or Teflon provided after repairs (F-24)	Shim and monitor at next inspection
	Concrete Saddle	Wood shim at saddle #193 (between Teflon wear plate and saddle	Remove wood and install Teflon shim
	Steel support member	No wear plate or Teflon provided after repairs (F-24)	Shim and monitor at next inspection
	Steel support member	No wear plate or Teflon provided after repairs (JP-5) (floating pipe)	Shim and monitor at next inspection
	Steel support member	No wear plate or Teflon provided after repairs (JP-5)	Shim and monitor at next inspection
	Concrete Saddle	Concrete pipe saddle # 178 is not engaged with pipe (floating pipe)	Shim and monitor at next inspection
	Steel support member	The original tack welded wear plate between pipe and support is short.  The bell-bell weld is resting on directly on pipe support member	Refer to Note (2)
	Concrete Saddle	Concrete pipe saddle # 110 is not engaged with pipe (floating pipe)	Shim and monitor at next inspection
	Steel support member	Small wood shim between wear plate and Steel support member (JP-5)	Remove wood and install Teflon shim
	Steel support member	No wear plate or Teffon at the intermediate next to 143 (F-24)	Refer to Note (2)
3 3	Steel support member	Intermediate between F-76 and F-24 line is welded directly to pipe	Monitor at next inspection
	Steel support member	No wear plate or Teflon at 140 (F-24)	Refer to Note (2)
	Steel support member	Moderate coating failure on support and underside of pipe	Repair coating
	Steel support member	Pipe is not in contact with support (F-24) (floating pipe)	Shim and monitor at next inspection
	Concrete Saddle	Deteriorated saddle with rebar exposed (saddle # 36)	Repair concrete saddle
	Concrete Saddle	Pipe is not in contact with saddle # 24 (floating pipe)	Shim and monitor at next inspection
	Steel support member	Anchor bolt on the base of plate are not secured down to the floor	Secure anchor bolts
		Surge Tank	
	Steel saddle type	No wear plate or Teflon provided after repairs (F 24)	Refer to Note (2)


### Note:

were labeled to aide in identifying and locating findings reported. from the facility designated pipe supports. The two pipe supports at each tank (laterals) are labeled LPS-xA and LPS-xB where x refers to the tank number in the tank gallery. numbers to distinguish the FOR and ending at the (3) isolation valves ( The letter "F" is tacked to the pipe supports starting at tank

- E2-1) Partial saddle support with contact at approximately 5 and 7 o'clock positions
- E2-2) Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.

- E2-3) Penetration through concrete walls/bulkheads are included in this table.
- are strap type support (8) (A) is galvanized angle iron with U-bolt supports. From (D) (8) (A) are strap type sudoor are Unistrut type pipe clamp with no Teflon pad or isolation material. All exterior pipe support past are steel angle iron with U-bolt. E2-4) The FOR pipe from
- Majority of the pipe support in the tank gallery is steel saddle type with partial contact at the bottom with no Teflon shim or insulation E2.5)

Photos of Typical Saddle Supports from Table E2





Photos of Typical Saddle Supports from Table E2 (Cont.)

			Taklo F Machanical Dant (MD) Inspection Cun	in our		
			Table r = Mechanical Dent (MD) Inspection Summary	IIIIaiy		
				į	Dent Size	
ID#	NPS	Relative Location	Dent Description (orientation)	Clock** Position	Approx. Depth	Recommendation
(b) (3) (A)					(in.)	
				∞	0.150	Monitor at next inspection
			Single uniform dent (\\) with center gouge of approx. 1/64" Coating damaged at dent location.	7	0.950	Install a pipe spool to eliminate the dent
			Single uniform Dent (1)	12	0.188	Monitor at next inspection
			Single uniform Dent (1) at tee	8	0.120	Monitor at next inspection
			Single uniform Dent (L)	9	0.140	Monitor at next inspection
			Single uniform Dent (L)	5	0.030	Monitor at next inspection
			Single uniform Dent (L)	7	0.250	Monitor at next inspection
			Single uniform Dent (L)	9	0.219	Monitor at next inspection
			Single uniform Dent (L)	5	0.156	Monitor at next inspection
			Single uniform Dent (L)	5	0.125	Monitor at next inspection
			Single uniform Dent (L)	5	0.156	Monitor at next inspection
			Single uniform dent (L); 116" from (3) (A)	1	0.162	Monitor at next inspection
				12	0.090	Monitor at next inspection
			Single uniform dent (//); 83" from	12	0.225	Monitor at next inspection
				1	0.320	Monitor at next inspection
			Single uniform dent (L)	2	0.270	Monitor at next inspection
			Single uniform dent (L)	9	0.150	Monitor at next inspection
			Single uniform dent (L)	2	0.080	Monitor at next inspection
			Single uniform dent (L); More out of round than dent	r	0.386	Monitor at next inspection
			Single uniform dent (L); Not visible	r	N/A	Monitor at next inspection
				2	0.130	Monitor at next inspection
			Single uniform dent (L); 102" from (3)	3	0.200	Monitor at next inspection
			Single uniform dent (1); Possibly dent - Remove wrap/coating to evaluate; 40" from 38		ŗ	Monitor at next inspection
			Single uniform dent (1): Possibly dent - Remove wrap/coating to evaluate; 68" from to be a single to be a singl	ı	ij	Monitor at next inspection
			Single uniform dent (L); 58" from joint: About 5" long	1-3	0.505	Monitor at next inspection
			Single uniform dent (1); Between (3) (4)  8" Long	10	0.368	Monitor at next inspection
			Single uniform dent (L); Between (b) (3) (A)	10	ŗ	Monitor at next inspection
			Single uniform dent (L); Between (b) (3) (A)	11	•	Monitor at next inspection
			Single uniform dent (L); 67" from (b) (3) (A)	10	0.100	Monitor at next inspection
			Single uniform dent (L); 117" fro	9	0.031	Monitor at next inspection
			Single uniform dent (1); 51" from	2:30	0.050	Monitor at next inspection
			Single uniform dent (L); 79" from	1:30	0.130	Т
3)			Single uniform dent (L); 117" fro	5:30	0.224	Monitor at next inspection 113

) (3) (A)		(a)				0
	Single uniform dent (L); 61" from	(3)	9	0.208	Monitor at next inspection	_
	Single uniform dent (L)	(4)	a e	0.146	Monitor at next inspection	
	Single uniform dent (L)		3	0.224	Monitor at next inspection	
	Single uniform dent (\\) on Bell	4	3	0.320	Conduct a follow-on NDE assessment	
	Single uniform dent (L); 72" from	549	a	0.078	Monitor at next inspection	
	Single uniform dent (L); 72" from	549	10	0.063	Monitor at next inspection	36
	Single uniform dent (L); 77" from	549	•	0.143	Monitor at next inspection	-
	Single uniform dent (L)		3:30	0.206	Monitor at next inspection	
	Single uniform dent (L); 45" from	1130; 7" Long	11:30	0.400	Monitor at next inspection	
	Single uniform dent (L)		3	0.207	Monitor at next inspection	
	Single uniform dent (L); 31" from	496	9	0.286	Monitor at next inspection	
	Single uniform dent (L)		1	0.125	Monitor at next inspection	
	Single uniform dent (L)			0.166	Monitor at next inspection	_
	Single uniform dent (L)		4	0.047	Monitor at next inspection	
	Single uniform dent (L)		4	0.138	Monitor at next inspection	
	Single uniform dent (L); 113" from	471 or 113" before 1450	7:30	0.200	Monitor at next inspection	
	Single uniform dent (L)	93	4	0.156	Monitor at next inspection	
	Single uniform dent (L)		1	0.245	Monitor at next inspection	
	Single uniform dent (L)		31	0.295	Monitor at next inspection	-
	Single uniform dent (L)		100	0.094	Monitor at next inspection	
	Single uniform dent (L)		=	0.156	Monitor at next inspection	
	Single uniform dent (L)		8	0.250	Monitor at next inspection	
	Single uniform dent (L)		=	0.109	Monitor at next inspection	
	Single uniform dent (L)		-	0.125	Monitor at next inspection	
	Single uniform dent (L)		3	0.188	Monitor at next inspection	
	Single uniform dent (L)		3	0.047	Monitor at next inspection	
	Single uniform dent (L)		3	0.109	Monitor at next inspection	
	Single uniform dent (L)		3	0.125	Monitor at next inspection	
	Single uniform dent (L)		3	0.151	Monitor at next inspection	
	Single uniform dent (L)		3	0.293	Monitor at next inspection	
	Single uniform dent (L)		4	0.141	Monitor at next inspection	_
	Single uniform dent (L) (b) (3)		4	0.188	Monitor at next inspection	100
	Single uniform dent (L); Nea(A)		2	0.146	Monitor at next inspection	
	Single uniform dent (L); Nea		3:30	0.156	Monitor at next inspection	1.0
	Single uniform dent (L); Nea		3	0.186	Monitor at next inspection	_
	Single uniform dent (L)		4	0.191	Monitor at next inspection	
	Single uniform dent (L)		3:30	0.104	Monitor at next inspection	_
	Single uniform dent (L); Near/At		4	0.156	Monitor at next inspection	
	Single uniform dent (L); Near/At		3:30	0.109	Monitor at next inspection	
	Single uniform dent (L)		3	0.125	Monitor at next inspection	
	Single uniform dent (L)		3:30	0.125	Monitor at next inspection	
	Single uniform dent (L)		_	0.161	Monitor at next inspection	
	Single uniform dent (L); 39" from	(5)	8:30	0.442	Monitor at next inspection	
	Single uniform dent (L)		3	0.200	Monitor at next inspection	

[138]

Single uniform dent (L); 43" from (b) (3) (A)	7	0.436	Monitor at next inspection
Single uniform dent (L); 31" from	3	0.321	Monitor at next inspection
Single uniform dent (L); 31" from	4	0.188	Monitor at next inspection
Single uniform dent (1); 31" from	10	0.100	Monitor at next inspection
Single uniform dent (1); 31" from	10	0.310	Monitor at next inspection
Single uniform dent (L); 31" from	2:30	0.191	Monitor at next inspection
Single uniform dent (L)	1:20	0.220	Monitor at next inspection
Single uniform dent (L) (b) (3)	1:20	0.210	Monitor at next inspection
Single uniform dent (1); 56" from (A)	1	0.230	Monitor at next inspection
Single uniform dent (1); 27" from	11	0.140	Monitor at next inspection
Single uniform dent (L); 154" fro	3	0.140	Monitor at next inspection
Single uniform dent (L)	3	0.080	Monitor at next inspection
Single uniform dent (L); 134" fro	9	0.242	Monitor at next inspection
Single uniform dent (L); 199" fro	S	0.182	Monitor at next inspection
	6	0.160	Monitor at next inspection
Single uniform dent (L); 181" fro	6	0.140	Monitor at next inspection
Single uniform dent (1); 121" fro	3	0.080	Monitor at next inspection
Single uniform dent (1); Vertical Crease; 40" from	•	0.231	Monitor at next inspection
Single uniform dent (1); 20" from (5) (3)	2	0.380	Monitor at next inspection
Single uniform dent (1); 142" fro (A)	2	0.170	Monitor at next inspection
Single uniform dent (L)	•	N/A	Monitor at next inspection
Single uniform dent (L)	12-3	0.297	Monitor at next inspection
Behind Wrap; *Unknown without Removal	-		Monitor at next inspection
Behind Wrap; *Unknown without Removal	10		Monitor at next inspection
Single uniform dent (L)	12	0.170	Monitor at next inspection
Single uniform dent (1); 102" from	4	0.311	Monitor at next inspection
Single uniform dent (L); 46" from	3	0.171	Monitor at next inspection
		0.160	Monitor at next inspection
Single uniform dent (L); 111" from	10	0.170	Monitor at next inspection
Single uniform dent (1)	2	0.110	Monitor at next inspection
	1-2	090.0	Monitor at next inspection
	1-2	0.050	Monitor at next inspection
	1-2	0.180	Monitor at next inspection
dent (1); 36" from	4	0.460	Monitor at next inspection
dent (1); 34" from	•	0.156	Monitor at next inspection
dent (L); 34" from		0.125	Monitor at next inspection
Single uniform dent ( $\bot$ ); 131" from gth = 2", Width = 1"	10	0.125	Monitor at next inspection
Single uniform dent ( $\bot$ ); Length = $4$ ", Width = 2.5"; Length along		0.219	Monitor at next inspection
		0.0	
dent (L); 81" from	. ;	0.250	Monitor at next inspection
	12	0.1875	Monitor at next inspection
	9	0.375	Monitor at next inspection
_	•	0.330	Monitor at next inspection
Single uniform $(9)$ $(8)$	ı	0.110	Monitor at next inspection

[139]

	(b) (3) (A)	EN-JBFIIII	ייייי ליייי	EN-JDFIIII,III-NED IIIEE FACIEII I-FIFING-MA1/2022
(b) (3) (A)	Single uniform dent (L);	1	0.098	Monitor at next inspection
Sir	Single uniform dent (L);	6	0.050	Monitor at next inspection
Sir	Single uniform dent (L);	6	0.050	Monitor at next inspection
Sir	Single uniform dent (L);	6	0.050	Monitor at next inspection
Sir	Single uniform dent (L);	6	0.050	Monitor at next inspection
Sir	Single uniform dent (L);	6	0.050	Monitor at next inspection
Sir	Single uniform dent (L);	2	0.016	Monitor at next inspection
Sir	Single uniform dent (L);	-	0.135	Monitor at next inspection
Sir	Single uniform dent (L)	1	0.250	Monitor at next inspection
Sir	Single uniform dent (L);	-	0.250	Monitor at next inspection
Sir	Single uniform dent $(\perp)$ ;	11	0.225	Monitor at next inspection
Sir	Single uniform dent (L)	12	0.188	Monitor at next inspection
Sir	Single uniform dent (L)	1	0.110	Monitor at next inspection
Sir	Single uniform dent (L)	1	0.110	Monitor at next inspection
Sir	Single uniform dent (L) (b) (3) (A)	3	0.125	Monitor at next inspection
Sir	Single uniform dent (L); Near	3	0.100	Monitor at next inspection
Sir	Single uniform dent (L)	7	0.200	Monitor at next inspection
Sir	Single uniform dent (L); 27" fr	10	0.110	Monitor at next inspection
Sir	Single uniform dent $(\perp)$ ; 10" fi	6	0.297	Monitor at next inspection
Sir	Single uniform dent (L); 73" fi	2	0.214	Monitor at next inspection
Sir	Single uniform dent (L)	1	0.080	Monitor at next inspection
Sir	Single uniform dent (L)	2	0.284	Monitor at next inspection
Sir	Single uniform dent (L)	9	0.140	Monitor at next inspection
Sir	Single uniform dent (L)	9	0.600	Monitor at next inspection
Sir	Single uniform dent (L)	10	0.210	Monitor at next inspection
Sir	Single uniform dent (L)	12	0.125	Monitor at next inspection
Sir	Single uniform dent (L) (b) (3) (A)	2	0.050	Monitor at next inspection
Sir	Single uniform dent (L); 62" fr	11	0.120	Monitor at next inspection
Sir	Single uniform dent (L); 12" L	2	0.392	Monitor at next inspection
Sir	Single uniform dent (L); At	1	0.230	Monitor at next inspection
Sir	Single uniform dent (1); fr	10	0.280	Monitor at next inspection
Sir	Single uniform dent (L); 154"	2:30	0.328	Monitor at next inspection
Sir	Single uniform dent (L); 158"	2:30	0.271	Monitor at next inspection
Sir	Single uniform dent (L); 1" Lo	2-3	0.031	Monitor at next inspection
Sir	Single uniform dent (L); 2.25"	2-3	0.031	Monitor at next inspection
Sir	Single uniform dent (L); Near saddle	5	0.265	Monitor at next inspection
Sir	Single uniform dent (L)	2	0.063	Monitor at next inspection

### Note:

- MD = Mechanical Dent

- MD/G = Mechanical Dent with Gouge # = Girth Weld number marked on pipe (from 2016 IL.I run) \* Dents identified in July 2021 \*\* All clock positions are given facing UGPH59 (flow path towards UGPH59)

- $\mathcal{L} = perpendicular$  to pipe run
  - || = parallel to pipe run || = at an angle to pipe run

## Dent assessment criteria applied

### a) API 579-1/ASME FFS-1

- cyclic service based on facility operation parameters (the piping operates in a relatively constant pressure/temperature relative to process piping used in refinery). The acceptability criterion is based on Level 1 assessment procedure for non-cyclic service is applied. Piping was evaluated assuming non-(≤ 7%). limiting the maximum dent depth in the pipe to a percentage of the pipe outside
  - The cyclic service screening procedure in Part 14 is also satisfied by provision of 14.4.2.2 Method A: when a successful experience over a sufficient time frame (greater than or equal to the intended design life of a given component) is obtained with comparable equipment subject to a similar loading time history, then fatigue analysis is not required as part of the FFS Assessment. ri

In this case considering satisfactory service history with the flaw in place since the beginning (or at least


since the latest year lead based paint was used (Circa 1971)).

# b) API RP 1183 (Assessment and Management of Pipeline Dents)

- The Fitness-for-Service Assessment detailed in paragraph 5.2.5 relies on comprehensive assessment of the data set available. The testing data has shown that plain dents (regardless of shape) with depths up to (without coincident metal loss, weld, or crack features) have the same failure pressure as plain line pipe (i.e. does not limit the pressure). 10 % of the pipe
- The maximum depth and maximum allowable dent depth and % dent are tabulated bellow based on both assessment criteria used in a) and b). ં

API 579-1/ASME FFS-1 API RP 1183	API RP 1183	Max	Max measured
		measured	equivalent %
Max dent allowed	Max dent		value
(2%)	allowed (10%)		
1.12	1.6	0.386	2.4 %
1.26	1.8	0.505 in	2.8 %
2.24	3.2 in	0.600 in	1.9 %

A-MD-2\* is not included in this table since the pipe spool containing the dent was removed during the 2022 trip.



CC



Tab	Table G – Valid	ation of	Validation of Repairs/Inspection Finding	2s (Based on 2015 & 2016	bection Findings (Based on 2015 & 2016 revision of EEI/APTIM reports)
Item #	EEI/APTIM Item #	Pipe Support #	Previous API 570 Finding Reported (2015/2016)	Recommendation Reported (2015/2016)	Follow-on Activity/ Recommendation (July 2021/June 2022)
*	TK10-TG-3	1	Corrosion under dresser     coupling insulation	Remove jacketing at dresser coupling and inspect	• Insulation was removed at Tank 10 and area inspected/documented. Add CUI inspection to the API 570 inspection program
*	TK12-TG-1	1	• Non-standard flange in vertical tee.	None Listed	<ul> <li>Consider upgrading to an ASME B16.5 rated flange and fittings. Typical at various locations.</li> <li>Note: ASME B31.3 Paragraph 304.7.2 allows "Unlisted Components" provided engineering analysis is conducted and meets one or more of the means stated in subparts. (a) through (d).</li> </ul>
3*	TK13-TG-1	-	<ul> <li>Non-standard flange in vertical tee.</li> </ul>	None Listed	• See Item # 2 Recommendation
*	TK14-TG-1	1	<ul> <li>Dresser coupling under insulation. Additional engineering investigation required</li> </ul>	None Listed. Additional engineering investigation requested.	Add CUI inspection to the API 570 inspection program until dresser couplings are replaced.
*	TK16-TG-1	1	<ul> <li>Dresser coupling under insulation. Additional engineering investigation required.</li> </ul>	None Listed. Additional engineering investigation requested.	<ul> <li>Add CUI inspection to the API 570 inspection program until dresser couplings are replaced.</li> </ul>
*9	TK16-TG-2	-	<ul> <li>Non-standard flange in vertical tee.</li> </ul>		• See Item # 2 Recommendation
*	TK19-TG-1		<ul> <li>Pipe support corroding steel and spalling concrete</li> </ul>	Repair pipe support corroding steel and spalling concrete.	<ul> <li>Same condition identified during this inspection cycle. This was identified on the second pipe support after Tank 19 (left hand side facing the tank). There is a yellow marking on I-beam listing this as "Item g."</li> <li>Replace pipe support I-beam structure and repair concrete footing.</li> </ul>
<b>*</b> ∞	TK20-TG-1	1	<ul> <li>Corroding steel on pipe support</li> </ul>	Replace pipe support corroding steel	<ul> <li>Same condition identified during this inspection cycle. Corrosion was identified on the first pipe support after Tank 20 (right hand side facing the tank). There is a yellow marking on I-beam listing this as "Item b" and "Item d."</li> <li>Replace pipe support I-beam structure</li> </ul>

7	
202	
Y/2	
AA.	
<u>1</u> -5	
ž	
PIP	
ΙŢ	
CE	
FA	
Ţ	
昰	
ED	
4	
H,	
H	
BP	
R-J	
田	

	S 3	S 3	쏭	ıt ,			9			igs ik.
Same finding observed     Concur with Reported Recommendation	• There is a 4 pup installed between S. & 4 approx. 55" from S. 3. No dent. No further action. Completed 4/13/2016	• There is a 4 pup installed between 8 & 4 (no socket weld here) No further action	<ul> <li>Same finding observed (guide at 7 o'clock missing)</li> <li>Concur with Reported Recommendation</li> </ul>	approx. depth of 0.1875 (with coating) (See MD-3). Unclear if this the same dent identified previously in the 2015 inspection; no clock position given. Remove coating to verify dent depth. No impact on fitness for service based on depth of 0.1875	• Same finding noted at the bottom of the lower tee for Tank 17 & 18 (6 o'clock) with approx. depth of 0.375 (with coating). See MD-5 Concur with Reported Recommendation	Same finding observed     Concur with Reported Recommendation	• There is a 4 pup installed between 5 12 & 13 No further action. Completed 4/11/2016	• This was not identified during this inspection (likely replaced with the pup piece). Several spools in this section of pipe run.  No further action	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	• Same finding observed. There are two lugs or tabs welded directly to the pipe at 7 o'clock position. Lug is 4" wide, ½" thick. Located just before door C.
Provide shims to close gap between the pipe and pipe support.	Remove, provide, and install 4 pup piece to eliminate the dent.	Remove, provide, and install 4 pup piece to eliminate the socket weld.	Provide guide for pipe support.	Remove, provide, and install 4 pup piece to eliminate the dent.	Remove, provide, and install 4 pup piece to eliminate the dent.	Provide shims to close gap between the pipe and pipe support.	Remove, provide, and install 4 pup piece to eliminate the socket welds.	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Provide shims to close gap between the pipe and pipe support.	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.
• Floating Pipe Support Pipe is only in contact on one side of saddle pipe support	• Gouge/Dent Approximate dent depth measurement: 0.265".	Socket Weld	Missing Guide at Pipe Support     Pipe support only has one guide	• Dent Approximate dent depth measurement: 0.350".	• Dent/Crease Approximate dent depth measurement: 0.300". Dent located at bottom of a tee	Floating Pipe Support	<ul> <li>Socket Weld</li> <li>Two socket welds located</li> <li>apart.</li> </ul>	• Lifting Lug	<ul> <li>Floating Pipe Support</li> </ul>	• Lifting Lug
at 2	3 / 4	3 / 4	at 6	5/6	10 / 11	at 11	12 / 13	12 / 13	at 12	13 / 14
18-TG-1	18-TG-2	18-TG-3	18-TG-5	18-TG-6	18-TG-11	18-TG-12	18-TG-14	18-TG-15	18-TG-16	18-TG-18
*6	10*	11*	12*	13*	14*	15*	16*	17*	18*	19*

20*	18-TG-21	at 16	Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Concur with Reported Recommendation     Same finding observed Concur with Reported Recommendation
21*	18-TG-22	16 / 17	Corrosion on Sleeve     Minor corrosion on top of     encirclement sleeve. Water     actively dripping on it	Install drip shield above pipe.	<ul> <li>Moderate coating failure is now present.</li> <li>Sleeve was likely added in the past to correct corrosion areas in the past due to drips.</li> <li>Concur with Reported recommendation.</li> <li>Remove corrosion spot and recoat piping.</li> </ul>
22*	18-TG-23	16 / 17	• Weld Overlay Repair  Excessive weld overlay on pipe. Two locations each one is 2" x 2". Located from repair sleeve	Remove weld overlay, remove coating, and perform magnetic particle testing. Recoat after testing.	• This was not identified during this inspection  No further action
23*	18-TG-25	20 / 21	• Corrosion Heavy corrosion between flange sets. Two rolled 45s. Heavy corrosion and exfoliation. Corrosion extends across girth weld. Pitting measured approximately 0.125"; however, it is difficult to get accurate pit depths	Remove the corroded area of piping between the flange sets 20" downstream and 67" upstream of Pipe Support 20. Provide spool piece. Spool piece includes two rolled 45° elbows, elevation difference of 29", lateral difference of 31", and flange face to face distance of 87".	• Same finding observed. Corrosion is due to active drips from tunnel ceiling mineral deposit. Nominal thickness was likely 0.375". The general metal thickness at this area is now 0.300" with a pit depth of 0.100" resulting in remaining thickness of 0.200". The remaining life at this location calculates to 15 years (approximate).
24*	18-TG-27	20 / 21	Coating Removal     Corrosion under bubble     coating. Not able to assess     without coating removal	Remove 2 of coating and inspect.	• This finding is same Item # 24 See Item # 24
25*	18-TG-28	22 / 23	• Socket Weld Two socket welds located 38" apart	Remove, provide, and install 5  pup piece to eliminate the socket welds.	<ul> <li>Same finding was observed (location is marked as "item n" with yellow ink</li> <li>Concur with Reported Recommendation</li> </ul>
26*	18-TG-29	25 / 26	<ul> <li>Dresser Coupling</li> <li>Additional engineering investigation required.</li> </ul>	TBD	<ul> <li>Same observation. Note: the four lugs on the upstream side of the dresser coupling welded to the pipe are backwards and are not per mfg. detail.</li> <li>Rotate lugs or consider removing the dresser coupling if engineering assessment indicated it is not needed</li> </ul>
27*	18-TG-30	28 / 29	<ul><li>Dent</li><li>Approximate dent depth</li></ul>	Remove coating and perform magnetic particle testing.	• Same finding noted. Located 81" from S 29 (7 o'clock) with approx. depth of

			measurement: 0.230"	Recoat after testing.	0.250" (with coating). See MD-7
28*	18-TG-31	at 30	• Corrosion • Corrosion at Pipe Support 30. Pitting depths measured at approximately 0.100" at top of pipe	Remove, provide, and install 4  pun piece. Pup piece shall extend 2 upstream and 2 downstream of Pipe Support 30.	<ul> <li>There is a 4 pup installed at this location</li> <li>No further action. Completed 4/9/2016</li> </ul>
29*	18-TG-32	30 / 31	Socket Weld	Remove, provide, and install 4 pup piece to eliminate the socket weld.	<ul> <li>There is a 2 pup installed at this location</li> <li>No further action. Completed 4/8/2016</li> </ul>
30*	18-TG-33	35 / 36	• Dent • Approximate dent depth measurement: 0.188"	Remove coating and perform magnetic particle testing. Recoat after testing.	• Same finding noted at the bottom of the lower tee for Tank 98" from S 35 (6 o'clock) with approx. depth of 0.219 (with coating). See MD-8 • Concur with Reported Recommendation
31*	18-TG-34	38 / 39	<ul> <li>Threaded Small Bore Pipe/Valve</li> <li>The 3/4" threaded piping is below the minimum structural wall thickness.</li> </ul>	Remove 1 of 3/4" threaded pipe and 3/4" gate valve. Provide 3/4" welded/flanged schedule 80 carbon steel pipe and 3/4" flanged carbon steel Class 150 ball valve.	• A shorter pipe nipple is now installed with 34" ball valve but still contains threaded fitting. Note: there is staining/wetting on the lower threaded fitting.
32*	18-TG-35	40 / 41	<ul> <li>Socket Weld         Two socket welds located 20"     </li> </ul>	Remove, provide, and install 4 pup piece to eliminate the socket welds.	• There is a 4 pup installed at this location  No further action. Completed 4/4/2016
33*	18-TG-37	50 / 51	• Socket Weld Two socket welds located 28" apart	Remove, provide, and install 4 pup piece to eliminate the socket welds.	<ul> <li>There is a 4 pup installed at this location</li> <li>No further action. Completed 3/31/2016</li> </ul>
34	18-TG-40	57 / 58	Non-Standard Components	Replace 1 ½" plastic ball valve with Class 150 carbon steel ball valve. Replace 7 of small bore threaded pipe and fittings with welded carbon steel pipe and fittings.	<ul> <li>The Plastic ball valve was replaced but threaded piping still exists.</li> <li>Concur with replacing with welded carbon steel pipe.</li> <li>Consider routing the piping away from walking path, golf cart or rail path.</li> </ul>
35	18-TG-41	09 / 69	• Socket Weld	Remove, provide, and install 6 pup piece to eliminate the socket welds.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> <li>Coating is removed by others at this location (presumably for repairs)</li> </ul>
36	18-TG-42	<i>L9</i> / 99	Socket Weld	Remove, provide, and install 4 pup piece to eliminate the socket welds.	<ul> <li>There is a 4 pup installed between S</li> <li>66 &amp; 67</li> <li>No further action. Completed 3/24/2016</li> </ul>
37	18-TG-44	<i>L9</i> / 99	• Corrosion	Remove, provide, and install tee. The repair will require piping rework to fit a new tee.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> <li>Coating is removed by others at this</li> </ul>

<ul> <li>1" HPV b/w valve # 0159 &amp; UGPH wall</li> <li>1" LPD b/w valve # 0159 &amp; UGPH wall</li> <li>1" LPD past valve # 0159</li> <li>1" HPV past valve # 0159</li> <li>1" LPD past valve # 0159</li> <li>1" LPD past valve # 0159</li> <li>(additional information in Table D)</li> </ul>	<ul> <li>There is a 4 pup installed between S</li> <li>25 &amp; 26</li> <li>No further action. Completed</li> <li>10/26/2016</li> </ul>	Same finding observed     Concur with Reported Recommendation	<ul> <li>Same finding observed</li> <li>Note 47 of floating pipe combined with the other unsupported pipe</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Same finding observed at both 47 and 48</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Lifting lug is removed</li> <li>It is presumed NDE was also conducted</li> <li>No further action. Completed</li> </ul>	<ul> <li>Lifting lug is removed</li> <li>It is presumed NDE was also conducted</li> <li>Visual inspection did not indicate area of concern during this inspection.</li> <li>No further action. Completed</li> </ul>	<ul> <li>Same finding observed</li> <li>It is presumed NDE was conducted</li> <li>Visual inspection did not indicate area of concern during this inspection.</li> <li>No further action.</li> </ul>	<ul> <li>Same finding observed</li> <li>Visual inspection did not indicate area of concern during this inspection.</li> <li>No further action.</li> </ul>	Same finding observed
assembly. Provide welded / flanged LPD and HPV assemblies with schedule 80 carbon steel pipe and Class 150 ball valves. LPDs and HPVs are located near the UGPH wall.	Remove, provide, and install 4 16" pup piece to eliminate the patch plate.	Remove 2" threaded bronze gate valve. Provide 2" carbon steel Class 150 ball valve.	Provide shims to close gap between the pipe and pipe support.	Provide shims to close gap between the pipe and pipe support.	Remove, provide, and install the bottom 1 column of pipe supports 47 and 48. Provide temporary support before repairs.	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Remove coating and perform magnetic particle testing. Recoat after testing.	Remove coating and perform magnetic particle testing. Recoat after testing.	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Provide shims to close gap
	• Patch Plate	Threaded Small Bore Valve	<ul> <li>Floating Pipe Support</li> </ul>	<ul> <li>Floating Pipe Support</li> </ul>	Corroding Pipe Support	• Lifting Lug	<ul> <li>Pitting at Lifting Lug Weld</li> </ul>	• Arc Strike	• Lifting Lug	Floating Pipe Support
	25 / 26	26 / 27	At 44	At 46 / 47	47 / 48	26 / 57	26 / 57	62 / 63	73 / 74	At 73
	16-TG-1	16-TG-2	16-TG-3	16-TG-4	16-TG-5	16-TG-6	16-TG-7	16-TG-9	16-TG-11	16-TG-12
	46	47	48	49	50	51	52	53	54	55

_	
<b>A</b>	
_	
-	
r	
_	
O	
_	
-	
=	
Ξ	
Ħ	
Ħ	
H	
Ħ	
HILL	
O HILL	
D HILL	
D HILL	
ED HILL	
ED HILL	
SED HILL	
RED HILL	
RED HILL	
-RED HILL	
I-RED HILL	
II-RED HILL	
HI-RED HILL	
HI-RED HILL	
HI-RED HILL	
I, HI-RED HILL	
H, HI-RED HILL	
H, HI-RED HILL	
IH, HI-RED HILL	
HH, HI-RED HILL	
HH, HI-RED HILL	
Ħ	
Ħ	
Ħ	
Ħ	
Ħ	
Ħ	
Ħ	
Ħ	
Ħ	
R-JBPHH, HI-RED HILL	
Ħ	
Ħ	
ER-JBPHH, HI-RED HILL	
Ħ	
Ħ	

			between the pipe and pipe support.	• Note 57' - 11" of floating pipe combined with the other unsupported pipe. with only 72 and 76 making contact in this section.
				<ul> <li>Concur with Reported Recommendation</li> </ul>
 16-TG-13	At 74	Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	• See Item 55 (16-TG-12)
16-TG-15	77 / 78	• 2" Diameter Patch Plate	Remove, provide, and install 16" tee. The repair will require piping rework to fit a new tee. Engineering will be required for the repair design.	<ul> <li>Same finding observed</li> <li>Visual inspection did not indicate area of concern during this inspection.</li> <li>The patch plate is acceptable per API 570 and ASME PCC-2 (Article 212)</li> <li>No further action.</li> </ul>
16-TG-16	79, 80, 81, 82	Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	<ul> <li>Same finding observed</li> <li>83 and 84 were also observed to be floating during this inspection cycle.</li> <li>Concur with Reported Recommendation</li> </ul>
16-TG-17	84 / 88	• Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	<ul> <li>Same finding observed</li> <li>Visual inspection did not indicate area of concern during this inspection.</li> <li>No further action.</li> </ul>
61-DL-91	101 / 102	Threaded Small Bore Valve	Remove 2" threaded <del>bronze gate</del> valve. Provide 2" arbon steel Class 150 ball valve	<ul> <li>Same finding observed</li> <li>The existing valve is actually carbon steel</li> <li>Concur with Reported Recommendation</li> </ul>
16-TG-20	102 / 103	• Failing Gasket	Remove the failing gasket on the 3" blind flange. Provide and install new gasket.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> <li>Did not observe during this inspection</li> <li>Lack of thread engagement on fasteners was noted on this flange</li> </ul>
16-TG-21	51/52	Coating Removal/Unknown Repair Scope	Remove 4 ft of coating and inspect. Coating has not been removed yet by coating removal contractor.	• Completed
16-TG-23	At 69	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	Remove 4 ft of coating and inspect. Coating was not adequately removed by coating removal contractor.	• Completed
TK2-TG-1	N/A	<ul> <li>Dresser coupling under insulation</li> </ul>	None Listed	Close visual inspection was completed at all insulated dresser (no tell-tell sign of     Add inspection to the API 570 inspection program until dresser couplings
				i

			, [		
					are replaced.
9	TK4-TG-1	N/A	Dresser coupling under insulation	None Listed	• See Item # 64
99	TK6-TG-1	N/A	Dresser coupling under insulation	None Listed	• See Item # 64
29	TK6-TG-1	N/A	Dresser coupling under insulation	None Listed	• See Item # 64
89	TK8-TG-1	N/A	Dresser coupling under insulation	None Listed	• See Item # 64
69	TK10-TG-1	N/A	Dresser coupling under insulation	TBD	• See Item # 64
70	TK10-TG-2	N/A	• Non-standard flange in vertical tee.	None Listed	• Consider upgrading to an ASME B16.5 rated flange and fittings. Typical at various locations.  Note: ASME B31.3 Paragraph 304.7.2 allows "Unlisted Components" provided engineering analysis is conducted and meets one or more of the means stated in subparts. (a) through (d).
71	TK10-TG-3	N/A	Corrosion (Dresser coupling under insulation)	Remove jacketing at dresser coupling and inspect	<ul> <li>Insulation jacket was removed at Tank 10 and area inspected/documented during 2021 inspection cycle</li> <li>See Item # 64</li> </ul>
72	16-LRUT-1	674/675	Coating Removal/Unknown Repair Scope (2016 LRUT scan reported indication)	Remove 2 of coating and inspect.	<ul> <li>Assumed completed (coating apereas to be relatively new).</li> <li>Current inspection did not identify areas of concern at this location</li> <li>No further action.</li> </ul>
73	16-LRUT-2	675/676	Coating Removal/Unknown Repair Scope (2016 LRUT scan reported indication)	Remove 2 of coating and inspect.	<ul> <li>Assumed completed (coating apereas to be relatively new).</li> <li>Current inspection did not identify areas of concern at this location</li> <li>No further action.</li> </ul>
74	32-TG-42	40/41	• Coating Removal/Unknown Repair Scope	Remove 4 of coating and inspect.	<ul> <li>Area of in inactive corrosion area between 40 and 41 (108" from 40). Pit depth = 0.196" - 0.200" and UTT of 0.430" on unaffected area resulting in remaining thickness of 0.219" to 0.250".</li> <li>Repair (See table D).</li> </ul>
75	32-TG-43	41/42	Coating Removal/Unknown Repair Scope	Remove 4 of coating and inspect.	<ul> <li>See item 74 above</li> <li>No further action.</li> </ul>
92	32-TG-44	41/42	Coating Removal/Unknown Repair Scope	Remove 4 of coating and inspect.	<ul> <li>Assumed completed (coating apereas to be relatively new).</li> </ul>

	<del> </del>	<u> </u>	<del> </del>	1			1			
<ul> <li>Current inspection did not identify areas of concern at this location. There is encirclement Repair Sleeve and some inactive pits (0.050 – 0.180").</li> <li>No further action.</li> </ul>	<ul> <li>Assumed completed (coating apereas to be relatively new).</li> <li>Current inspection did not identify areas of concern at this location. Inactive pits halfway b/w with max pit of 0.120".</li> <li>No further action.</li> </ul>	<ul> <li>Assumed completed (coating apereas to be relatively new).</li> <li>Current inspection did not identify areas of concern at this location. Inactive pits near 70 with max pit of 0.150".</li> <li>No further action</li> </ul>	<ul> <li>Same finding observed</li> <li>Note: some staining was noted but no active weeping</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed</li> <li>(2/19/2018)</li> </ul>	<ul> <li>Same finding observed</li> <li>Area inspected with through coating UTT probe and has UTT of 0.389" - 0400" on topside of pipe and 0.389" - 0400" on bottom side of pipe with active pits 0.050 - 0.080" and</li> <li>Repair coating to arrest corrosion.</li> </ul>	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed</li> <li>(2/12/2018)</li> </ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>
	Remove 4 of coating and inspect.	Remove 4 of coating and inspect.	Remove 2" threaded high point vent (HPV) assembly. Provide welded/flanged HPV assembly with schedule 80 carbon steel pipe and Class 150 ball valve.	Remove, provide, and install 4ft 32" pup piece to eliminate the dent.	Remove 5 of coating and inspect.	Recoat 3 of failing coating	4' Pup Repair. Greater than 50% corrosion on Weld	Recoat 5 of failing coating.	Recoat 4 of failing coating.	Recoat 3 of failing coating.
	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	<ul> <li>Threaded Small Bore Pipe/Valve</li> </ul>	• Dent/Gouge	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	<ul> <li>Coating Repair</li> </ul>	• Corrosion	<ul> <li>Coating Repair</li> </ul>	<ul> <li>Coating Repair</li> </ul>	Coating Repair
	02/69	02/69		232-233	238/239	At 246	254/255	At 260	At 264	271/272
	32-TG-45	32-TG-46	32-A2A3-1	32-A2A3-2	32-A2A3-3	32-A2A3-4	32-A2A3-5	32-A2A3-6	32-A2A3-7	32-A2A3-8
	77	78	79	08	81	82	83	84	85	98

		I										<u> </u>			
<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Same finding observed</li> <li>Area inspected and has UTT of 0.298" – 0.321" and a max pit of 0.120"</li> <li>Repair coating to arrest corrosion.</li> </ul>	<ul> <li>There is coating repair b/w 288 and BH.(near BH)</li> <li>No further action. Completed</li> </ul>	Same finding observed     Concur with Reported Recommendation	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Same finding observed</li> <li>Pipe is wrapped in this area</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Same finding observed</li> <li>Pipe is wrapped in this area</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Same finding observed</li> <li>Pipe is wrapped in this area</li> <li>Concur with Reported Recommendation</li> </ul>	<ul><li>Same finding observed</li><li>Pipe is wrapped in this area</li><li>Concur with Reported Recommendation</li></ul>	<ul> <li>Same finding observed</li> <li>Pipe is wrapped in this area</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed (1/28/2018)</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed (2/3/2018)</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed (3/13/2018)</li> </ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed (2/6/2018)</li> </ul>	Same finding observed
Recoat 1 of failing coating at the weld.	Remove 8 of coating and inspect.	Recoat 4 of failing coating.	Recoat 16 of failing coating	Remove 24 of wrap coating and recoat.	Remove 8 of coating and inspect.	Remove 12 of coating and inspect.	Recoat 10 of failing coating.	Recoat 4 of failing coating.	Recoat 15 of failing coating.	Remove, provide, and install 4ft 32" pup piece to eliminate the dent.	Remove, provide, and install 4ft 32" pup piece to eliminate the dent.	Remove, provide, and install 4ft 32" pup piece to eliminate the dent.	Recoat 2 of failing coating at weld.	Remove, provide, and install 4ft 32" pup piece to eliminate the dent.	Recoat 10 of failing coating.
Coating Repair	• Coating Removal/Unknown Repair Scope (Area of previous repair)	Coating Repair	<ul> <li>Coating Repair</li> </ul>	<ul> <li>Coating Repair</li> </ul>	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	<ul> <li>Coating Repair</li> </ul>	<ul> <li>Coating Repair</li> </ul>	<ul> <li>Coating Repair</li> </ul>	• Dent/Gouge	• Dent/Gouge	• Dent	<ul> <li>Coating Repair</li> </ul>	• Dent	<ul> <li>Coating Repair</li> </ul>
At 276	At 277	288/BH	294/295	298/299	307/308	312/313	326/327	327/328	333/334	341/342	353/354	353/354	At 355	364/365	382/383
32-A2A3-9	32-A2A3-10	32-A2A3-11	32-A2A3-12	32-A2A3-13	32-A2A3-14	32-A2A3-15	32-A2A3-16	32-A2A3-17	32-A2A3-18	32-A2A3-19	32-A2A3-20	32-A2A3-21	32-A2A3-22	32-A2A3-23	32-A2A3-24
87	88	68	06	91	92	93	94	95	96	97	86	66	100	101	102

					G. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
103	32-A2A3-25	391/392	Coating Repair	Recoat 3 of failing coating.	<ul> <li>Concur with Reported Recommendation</li> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
104	32-A2A3-26	405/406	• Dent	Remove, provide, and install 4ft 32" pup piece to eliminate the dent.	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed</li> <li>(2/26/2018)</li> </ul>
105	32-A2A3-27	406/407	• Dent	Remove, provide, and install 4ft 32" pup piece to eliminate the dent.	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed</li> <li>(2/28/2018)</li> </ul>
106	32-A2A3-28	408/409	Coating Repair	Recoat 3 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
107	32-A2A3-29	414/415	Coating Repair	Recoat 6 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
108	32-A2A3-30	438/439	Coating Repair	Recoat 2 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
109	32-A2A3-31	469/470	Coating Repair	Recoat 4 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
110	32-A2A3-32	470/471	Corrosion at saddle support	Remove, provide, and install 4ft 32" pup piece to eliminate the corroded area.	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed (3/2/2018)</li> </ul>
111	32-A2A3-33	473/474	ClockSpring (installed several years ago as a temporary repair)	Remove, provide, and install 32" pup piece to eliminate the Clock spring repair.	Same finding observed     Concur with Reported Recommendation
112	32-A2A3-34	501/502	Coating Repair	Recoat 3 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
113	32-A2A3-35	At 527	Coating Repair	Recoat 2 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
114	32-A2A3-36	527/528	Coating Repair	Recoat 2 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
115	32-A2A3-37	543/544	Coating Repair	Recoat 12 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
116	32-A2A3-38	549/550	Coating Repair	Recoat 6 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
117	32-A2A3-39	09\$/6\$\$	Coating Repair	Recoat 8 of failing coating.	<ul> <li>Same finding observed</li> <li>Pipe is wrapped in this area</li> <li>Concur with Reported Recommendation</li> </ul>
118	32-A2A3-40	576/577	Coating Repair	Recoat 2 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
119	32-A2A3-41	279/580	• Coating Removal/Unknown Repair Scope	Remove 2 of coating and inspect.	<ul> <li>Same finding observed</li> <li>Pipe is wrapped in this area</li> <li>Concur with Reported Recommendation</li> </ul>
120	32-A2A3-42	591/BH	• Coating Repair	Recoat 20 of failing coating.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>

	i		•				1		i			
<ul> <li>Same finding observed</li> <li>Minimal corrosion noted at this location with UTT of 0.381"</li> <li>Repair coating to arrest the corrosion</li> </ul>	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Same finding observed</li> <li>Minimal corrosion observed at this location with UTT of 0.389" and pitting of 0.030 – 0.060"</li> <li>Repair coating to arrest the corrosion</li> </ul>	<ul> <li>Same finding observed</li> <li>Minimal corrosion observed at this location with pitting of 1/16"</li> <li>Repair coating to arrest the corrosion</li> </ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	<ul> <li>Same finding observed</li> <li>Minimal corrosion observed at this location with UTT of 0.385"</li> <li>Repair coating to arrest the corrosion</li> </ul>	<ul> <li>Did not observe threaded NPS 4 pipe</li> <li>There is a 1" threaded fitting with a ball valve between 650/651.</li> <li>Replace the NPS 1 ball valve with NPS 80 pipe and welded/flanged fitting</li> </ul>	<ul> <li>Dent located at 3 o'clock</li> <li>Dent is acceptable per API RP 1183</li> <li>No further action.</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed</li> <li>(11/15/2017)</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed (1/2/2018)</li> </ul>	<ul><li>Dent is acceptable per API RP 1183</li><li>No further action.</li></ul>	<ul> <li>Dent is acceptable per API RP 1183</li> <li>No further action.</li> </ul>
Clean, inspect, and recoat approximately 75 of piping between Pipe Support 595 and the bulkhead.	Remove, provide, and install 32" pup pieces to eliminate the Clockspring repair.	Recoat 10 of failing coating.	Remove 15 of coating and inspect.	Remove 6 of failing coating.	Recoat 20 of failing coating.	Remove 30 of coating and inspect.	Remove threaded 4" blind flange. Provide 4" weld neck flange.	Remove, provide, and install 4ft pup piece to eliminate the dent.	Remove, provide, and install 4ft pup piece to eliminate the dent.	Remove, provide, and install 4ft pup piece to eliminate the dent.	Remove, provide, and install 4ft pup piece to eliminate the dent.	Remove, provide, and install 4ft pup piece to eliminate the
<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	Clockspring (installed several years ago as a temporary repair)	<ul> <li>Coating Repair</li> </ul>	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	<ul> <li>Coating Repair</li> </ul>	<ul> <li>Coating Repair</li> </ul>	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	• Threaded Pipe (NPS 4 blind flange)	• Dent/Gouge (0.130") 0.120" dent and 0.010" gouge	• Dent with crease (0.368")	• Dent with crease and sharp geometry (0.275")	<ul><li>Dent/Gouge (0.180")</li><li>0.160" dent and 0.020" gouge</li></ul>	• Dent (0.291")
BH/595	595/596	296/597	865//268	612/613	639/640	640/641	650/651	652/653	661/662	664/665	899/L99	681/682
32-A2A3-43	32-A2A3-44	32-A2A3-45	32-A2A3-46	32-A2A3-47	32-A2A3-48	32-A2A3-49	18-UGPH-1	18-UGPH-2	18-UGPH-5	18-UGPH-6	18-UGPH-7	18-UGPH-9
121	122	123	124	125	126	127	128	129	130	131	132	133

7
202
X
IA
4
5
PII
-P
TY
II
AC
H
HILI
RED
Ė
H
BP
ER-J

		_					二
angle iron welded on the top of the NPS 32 pipe to support the NPS 18 pipe. Concur with Reported Recommendation	Consider upgrading to an ASME B16.5 rated flange and fittings. Typical at various locations.  Note: ASME B31.3 Paragraph 304.7.2 allows "Unlisted Components" provided engineering analysis is conducted and meets one or more of the means stated in subparts. (a) through (d).	Did not identify during this inspection	<ul> <li>Deteriorated gasket was not observed during this inspection</li> <li>Note: the 8 lugs on the upstream side of the dresser coupling welded to the pipe are backwards and are not per mfg. detail.</li> <li>Rotate lugs or consider removing the dresser coupling if engineering assessment indicated it is not needed</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed</li> <li>(12/12/2016)</li> </ul>	<ul> <li>Pipe is coated around support</li> <li>Consider recoating the pipe support during the next maintenance coating activity</li> </ul>	Consider upgrading to an ASME B16.5 rated flange and fittings. Typical at various locations.  Note: ASME B31.3 Paragraph 304.7.2 allows "Unlisted Components" provided engineering analysis is conducted and meets one or more of the means stated in subparts. (a) through (d).	<ul> <li>Same finding observed</li> <li>Visual inspection did not indicate area of concern during this inspection.</li> </ul>
	Remove non-standard flanges and install standard weld neck flanges	Remove, provide, and install 4ft 32" pup piece.	Remove deteriorating gasket on the Dresser coupling. Provide and install new gasket? Stress analysis?	Remove, provide, and install 4ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Recoat bottom of pipe at Pipe Support 28 during Tank Gallery recoat. Section of pipe support may need to be removed to recoat.	Remove, provide and install 4 32" pup piece. Pup piece shall extend upstream and downstream of the flange set.	Remove, provide and install 4 32" pup piece. Pup piece shall extend upstream and
	Non-Standard Flanges	<ul> <li>Socket Weld (two socket welds located 22" apart)</li> </ul>	• Dresser Coupling	• Corrosion (Failed FFS with pits = 0.220")	<ul> <li>Corrosion (bottom of pipe and support)</li> </ul>	• Non-Standard Flanges	• Patch Plate ( patch plate)
	20/21	22/23	25/26	26/27	28	29/30	30/31
	32-TG-1	32-TG-3	32-TG-4	32-TG-5	32-TG-6	32-TG-7	32-TG-8
	141	142	143	144	145	146	147

<ul> <li>The patch plate is acceptable per API 570 and ASME PCC-2 (Article 212)</li> <li>No further action.</li> </ul>	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Same finding observed</li> <li>Visual inspection did not indicate area of concern during this inspection.</li> <li>The patch plate is acceptable per API 570 and ASME PCC-2 (Article 212)</li> <li>No further action.</li> </ul>	<ul> <li>Same finding observed between 38/39 and 39/40 (QTY 2)</li> <li>Concur with Reported Recommendation</li> </ul>	<ul> <li>Ok with inactive pits 0.050 to 0.100</li> <li>Area is recoated</li> <li>Continue coating maintenance to deter corrosion.</li> </ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	<ul> <li>Ok with inactive pits 0.050 to 0.100</li> <li>Area is recoated</li> <li>Continue coating maintenance to deter corrosion.</li> </ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed</li> <li>(9/16/2016)</li> </ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	<ul> <li>There is a pup piece at this location</li> <li>No further action. Completed</li> <li>(9/16/2016)</li> </ul>	Consider upgrading to an ASME B16.5 rated flange and fittings. Typical at various locations.  Note: ASME B31.3 Paragraph 304.7.2
downstream of the patch plate.	Remove, provide, and install 4 32" pup piece to eliminate the socket welds.	Remove, provide and install 4 32" pup piece. Pup piece shall extend upstream and downstream of the 10" patch plate.	Remove, provide, and install 4 32" pup piece to eliminate the socket weld.	Remove 5 of coating and inspect.	Provide shims to close gap between the pipe and pipe support.	Remove 5 of coating and inspect.	Remove, provide, and install 4ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Remove, provide, and install 4 32" pup piece to eliminate the socket weld.	Remove, provide, and install 4ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Remove, provide and install 4 32" pup piece. Pup piece shall extend upstream and downstream of the flange set.
	Socket Weld	• Patch Plate (10 patch plate)	Socket Weld	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	<ul> <li>Floating Pipe Support</li> </ul>	<ul> <li>Coating Removal/Unknown</li> <li>Repair Scope</li> </ul>	• Corrosion with pit of 0.186"	Socket Weld	• Corrosion with estimated pit of 0.200"	Non-Standard Flange
	31/32	31/32	38/40	44/45	At 46	48/49	49/50	50/51	At 52	57/58
	32-TG-9	32-TG-10	32-TG-11	32-TG-13	32-TG-14	32-TG-15	32-TG-16	32-TG-17	32-TG-19	32-TG-20
	148	149	150	151	152	153	154	155	156	157

[158]


-		<del>i</del>	i .		1			
allows "Unlisted Components" provided engineering analysis is conducted and meets one or more of the means stated in subparts. (a) through (d).	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>	<ul> <li>Same finding observed but corrosion is arrested with coating.</li> <li>Dent is within acceptable limits of API RP 1183</li> <li>Pit does pass ASME calculation (measured depth was 0.080")</li> <li>Continue coating maintenance to deter corrosion.</li> </ul>	<ul> <li>There is a pup piece at this location with Teflon shims between pipe and support</li> <li>No further action. Completed (9/14/2016)</li> </ul>	Same finding observed     Concur with Reported Recommendation	<ul> <li>Area is ok with no reportable deficiency</li> <li>Coating appears relatively new</li> <li>No further action</li> </ul>	• Coating appears relatively new • Pitting is within acceptable limits • Insert type repairs noted at two locations before and after 70. The insert plates do not have rounded corner per requirements of API STD 570 and ASME PCC-2. Review reason for the repair and NDE performed after the repair, perform additional NDE (PAUT or RT) or replace the section of pipe with non-standard repair at	<ul><li>Area is ok with no reportable deficiency</li><li>Coating appears relatively new</li><li>No further action</li></ul>	<ul><li>Same finding observed</li><li>Concur with Reported Recommendation</li></ul>
	Remove, provide, and install 4 32" pup piece to eliminate the socket weld.	Remove, provide, and install 4 32" pup piece. Pup piece shall extend upstream and downstream of the corroded/dent area. *Note: 32-TG-24a, 32-TG-24b, 32-TG-24c have been combined into one repair recommendation.	Remove, provide, and install 4ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Remove, provide, and install 4 32" pup piece to eliminate the socket weld.	Remove 2 of coating and inspect.	Remove, provide, and install 30 32" pup piece. Pup piece shall extend approximately 4ft upstream of Pipe Support 70 and approximately 4 downstream of Pipe Support 69. *Note: 32-TG-29 through 32-TG-34 have been combined into one repair recommendation.	Remove 2 of coating and inspect.	Remove, provide, and install 4 32" pup piece to eliminate the socket weld.
	• Socket Weld (14" apart)	• Corrosion Dent/Gouge Corrosion (Corrosion at top of pipe/bottom of pipe at PS66.  Dent/gouge 2 from 66 corrosion pit = 0.065" and dent = 0.320")	• Corrosion (heavy corrosion at the bottom of 67 with reported pits of 0.125")	• Socket Weld ( apart)	• Coating Removal/Unknown Repair Scope	• Corrosion, Non-Standard Repair, Coating Removal (Several finding in a 2f span including multiple location of pitting with 0.100" measured, coating removal for assessment and nonstandard pipe repair)	<ul> <li>Coating Removal/Unknown Repair Scope</li> </ul>	• Socket Weld
	09/69	At 66 65/66 At 66	At 67	69/89	69/89	68/69 69/70 69/71 69/70 At 70 70/71	71/72	8L/LL
	32-TG-21	32-TG-24a 32-TG-24b 32-TG-24c	32-TG-25	32-TG-27	32-TG-28	32-TG-29 32-TG-30 32-TG-31 32-TG-32 32-TG-33 32-TG-33	32-TG-35	32-TG-36
	158	159	160	161	162	163	164	165

166	32-TG-37	77/78	• Tunnel Support (tunnel support on pipe? two knee braces on pipe via a 4 x 6 wood beams)	Investigate if supports are load bearing on the piping?	• Same finding observed with a saddle type end piece across the NPS 32 pipe. The wood beams do not appear to be bearing any load on the pipe (based on the gaps between wood and top saddle as well as gaps at the bolt notches)
167	32-TG-38	80/81	Socket Weld	Remove, provide, and install 4ft 32" pup piece to eliminate the socket weld.	Same finding observed     Concur with Reported Recommendation
168	32-TG-39	81/82	• Socket Weld	Remove, provide, and install 4ft 32" pup piece to eliminate the socket weld.	<ul> <li>Same finding observed</li> <li>Concur with Reported Recommendation</li> </ul>
169	32-TG-40	86/L6	• Deadleg ( branch connection as a deadleg does not appear to have usefully purpose)	Remove, provide, and install 4ft 32" pup piece to eliminate the deadleg.	Same finding observed     Concur with Reported Recommendation
170	32-TG-41	100/101	100/101 • Dresser Coupling	TBD	<ul> <li>Same observation</li> <li>Note: the 8 lugs on the upstream side of the dresser coupling welded to the pipe are backwards and are not per mfg. detail.</li> <li>One joint harness with gap noted. There are no deflection rings and adapters on the harness lugs (See table D)</li> <li>Rotate lugs or consider removing the dresser coupling if engineering</li> <li>assessment indicated it is not needed</li> </ul>

# Note:


(\* for uniformity and completeness; the July 2021 API-570 validation of Repairs/Inspection is incorporated in this 2022 inspection completed by InterSpec, LLC. Segment of piping inspected in 2021 is currently undergoing repairs)

- Only areas covered in InterSpec's SOW were followed up and documented in the table above. 7: -
  - Additional findings observed during this inspection are listed in Table D.
- Sample pictures of corresponding deficiencies are included in the following page (not all repair or validation photos provided in this section)
  - Several repairs were completed after the 2015 API 570 inspection. Repairs were completed in 2016 2019



No Photo (repaired)		20		24
No Photo (floating pipe)	No Photo (lugs/tabs)	19	(b) (c) (d)	2.3
The second of th	No Photo (floating pipe)	18	No Photo (not identified)	2.2
The state of the s	No Photo (repaired)	17	(b) (3) (A)	

28	No Photo (repaired)	32			
		31			
	The state of the s	30			
(b) (d)		29 (repaired)	No Photo (repaired)	33	





ER-JBPHH, HI-RED HILL FACILITY-PIPING-MAY/2022



NPS   System   18   System   19   System   18   System   19   System   10   System	H – Coating failure and corrosion (cont.)	Description	roximately 5' of concrete splatter at 12 o'clock on pipe	ted area of coating failure wall side with no significant corrosion (no significant pits noted)		Approximately 20' of coating failure with no signification corrosion (no significant pits noted)	ted area of coating failure on wall side with no significant corrosion (no significant pits noted)	Some corrosion on the base of the pipe support	Approximately 5' of plaster drips on pipe at 12 o'clock	Area of coating failure, approximately 5' long	3' of coating failure and corrosion, no significant pits at 8-11 o'clock	Approximately 20' of coating failure with no significant corrosion (no significant pits noted)	Approximately 6' of coating failure with no significant corrosion (no significant pits noted)	Approximately 4' of coating failure with no corrosion at 9 o'clock (no significant pits noted)	Approximately 20' of coating failure with no significant corrosion (no significant pits noted)	Approximately 10' of coating failure with no significant corrosion (no significant pits noted)	ted area of coating with minor corrosion at 7-10 o'clock (no significant pits noted)	Approximately 3' of coating failure with minor corrosion near saddle (no significant pits noted)	and active pits at 12 o'clock, 21" from , 0.095", 0.080", 0.060" and 0.070" (UTT = $6" - 0.101$ ")	Active and inactive pits 0.050" – 0.070"	Approximately 5' of coating failure with no significant corrosion (no significant pits noted)	Approximately 7' of pipe is wrapped near at this location	ted area of coating failure and corrosion between 7-11 o'clock with minor pitting.	One active pit 0.050" at 7 o'clock, 24" from	Active and inactive pits 0.050" – 0.080"	ted area of corrosion on base plate to steel frame	Approximately 5' of coating failure with some surface rust (no significant pits noted); Approximately 2' long	Approximately 2' of small area of coating failure with no corrosion (no significant pits noted)	Approximately 2' of small area of coating failure with no corrosion (no significant pits noted)	Approximately 10' of coating failure with no significant corrosion (no significant pits noted)	Approximately 6' of coating failure with no signification corrosion near 415 (no significant pits noted)	5	Approximately 2' of coating failure with minor corrosion near at 5-10 o'clock (no significant pits noted)	Approximately 3' of pipe is wrapped from the coating failure and corrosion location near	Approximately 3' of coating failure with no corrosion (no significant pits noted)	Approximately 5' of coating failure with no significant corrosion (no significant pits noted)	ignificar	rosion	Approximately 3' of coating failure with no corrosion near (no significant pits noted)
	Ta	System																																					F-76
10010101010101010101010101010101010101		Item NPS	Н	+	+		72 16	73 16	74 16	75 16			78 32	79 32			_			85 18	86 18		88 18	89 16	90 16			+	94 16	95 16	96 32		-	+		+		+	104 32

Relative Location	tion	System F-76 F-76 F-76 F-76 F-76 F-24	Approximately 3' of coating failure with no significant corrosion near Approximately 3' of coating failure with no significant corrosion near Approximately 2' of coating failure with no significant corrosion near Approximately 10' of coating failure with no significant corrosion (no significant pits noted) Approximately 10' of coating failure with no significant corrosion (no significant pits noted)
		F-24 F-24 F-24	ignifica
		F-24 F-76 JP-5 F-24 F-76	Approximately 2' of coating failure with no corrosion near (no significant pits noted)  Approximately 10' of coating failure with no corrosion (no significant pits noted)  Approximately 10' of coating failure with no corrosion (no significant pits noted)  Approximately 8' of coating failure with no corrosion (no significant pits noted)  Approximately 24" of this pipe are wrapped at 2 locations in this section
		F-76 F-76 F-76 F-76 F-76	Approximately 24" of this pipe are wrapped at 2 locations in this section Approximately 24" of this pipe is wrapped at this location Approximately 60" of this pipe is wrapped at this location Approximately 24" of this pipe is wrapped at 4 locations in this section Approximately 24" of this pipe is wrapped at 3 locations in this section
		F-76 F-76 F-76 F-76	Approximately 24" of this pipe is wrapped at 3 locations in this section  Approximately 24" of this pipe is wrapped at 2 locations in this section  Large section of pipe has been wrapped, no corrosion or pitting noted  Large section of pipe has been wrapped, no corrosion or pitting noted, but there is coating failure at areas exposed  Smalls section of pipe is wrapped at this location with some areas of coating failure and surface rust was noted in this section (no significant pite noted)
		л5 л5 л5 л5 л5 л5 л5	Approximately 24" of this pipe is wrapped at this location Approximately 24" of this pipe is wrapped at this location Approximately 60" of this pipe is wrapped at this location Approximately 24" of this pipe is wrapped at this location Approximately 24" of this pipe is wrapped at 4 locations in this section Approximately 24" of this pipe is wrapped at 3 locations in this section
		JP-5 JP-5 JP-5 JP-5 JP-5 F-24 F-24 F-24 F-24	Approximately 24" of this pipe is wrapped at 3 locations in this section  Approximately 24" of this pipe is wrapped at 2 locations in this section  Large section of pipe is wrapped at this location, no corrosion or pitting noted  Large section of pipe is wrapped, with some corrosion at areas exposed in this section  Small section of pipe is wrapped at this location, no corrosion or significant pitting noted  Approximately 2' of this pipe are wrapped at 2 small locations in this section  Approximately 24" of this pipe is wrapped at this location  Approximately 24" of this pipe is wrapped at this location

				Table H – Coating failure and corrosion (cont.)
Item #	NPS	Relative Location	System	Description
145	16		F-24	Approximately 24" of this pipe is wrapped at this location
146	16		F-24	Approximately 24" of this pipe is wrapped at 4 locations in this section
147	16		F-24	Approximately 24" of this pipe is wrapped at 3 locations in this section
148	16		F-24	Approximately 24" of this pipe is wrapped at 3 locations in this section
149	16		F-24	Large section of pipe is wrapped at this location, no corrosion or significant pitting noted
150	16		F-24	Large section of pipe is wrapped, with small coating failure near
151	16		F-24	Small section of pipe is wrapped at this location, some coating failure and minor surface corrosion noted in this
				section (no significant pits noted)
152	32		F-76	Most of the pipe is wrapped, there are coating failures in sections of the pipe but no signification corrosion
153	32		F-/6	Moderate coating failure, notable corrosion, no significant pits at saddle #23/
154	32		F-76	Approximately 24" of this pipe are wrapped at 3-4 locations in this section; there is some damage to the wrap and minor corrosion
155	32		F-76	Approximately 5' of coating failure and corrosion (no pits or significant pits noted)
156	32		F-76	Pipe is spot wrapped at this location and is mostly set
157	32		F-76	Approximately 24" of coating failure with no corrosion (no significant pits noted)
158	32		F-76	Approximately 60" of coating failure with some corrosion on BTM (no significant pits noted)
159	32		F-76	Approximately 24" of coating failure near saddle at 6 o'clock
160	32		F-76	Approximately 24" of coating failure with some corrosion and no significant pits noted
161	32		F-76	Inactive pits 0.080" – 0.140" at 10 o'clock
162	32		F-76	Some isolated paint blisters in this section with new coat
163	32		F-76	Isolated area of coating failure and corrosion with pitting 0.060" at saddle #216
164	32		F-76	Approximately 40' of wrap and coat failure in this section with active and inactive corrosion; pits were noted 0.080" – 0.100"
165	18		JP-5	Pipe is wrapped with some sections only intermittently wrapped. There is minor to moderate coating failure but no notable corrosion.
166	18		JP-5	Approximately 24" of this pipe are wrapped at 3-4 locations in this section; there is some damage to the wrap and minor corrosion
167	18		JP-5	2-4 spot wraps in this section and mostly satisfactory
168	18		JP-5	Approximately 24" of coating failure with no corrosion (no significant pits noted)
169	18		JP-5	Approximately 36" of coating failure with no corrosion (no significant pits noted)
170	18		JP-5	Approximately 140" of pipe is coated and wrapped at this location
171	18		JP-5	Isolated area of coating failure and corrosion 0.050" at 9 o'clock, 70" from
172	18		JP-5	Approximately halfway from 311-312 to is wrapped
173	18		JP-5	Isolated external area of coating failure and corrosion at 6 o'clock and pitting 0.055" – 0.102" (UTT = 0.218" – 0.238")
174	18		JP-5	Supports for this pipe has a corroded base
175	16		F-24	Most of the pipe is wrapped, there are coating failures in sections of the pipe but no signification corrosion
176	16		F-24	Approximately 24" of this pipe are wrapped at 3-4 locations in this section; there is some damage to the wrap and minor corrosion
177	16		F-24	About 1 or 2 spots of this pipe are wrapped at this location
178	16		F-24	Approximately 36" of coating failure with no corrosion (no significant pits noted)

H - Coating failure and corrosion (cont.)	Description	Approximately halfway from is wrapped	Supports for this pipe has a corroded base	Some active coating failure and corrosion (unknown how much). Remove approximately 5' of wrapping between these pipe supports. Will need a new coating wrapping for VT/570.	d area of coating failure and corrosion at pipe saddle #210 (no significant pits noted)	Pipe is wrapped at this location. This section has wrap that is failing with some corrosion spot.	Pipe is wrapped at this location. This section is mostly okay with minimal bubbles and corrosion spot.	Approximately 20' of coating failure and corrosion (no significant pits noted)	Pipe is wrapped at this location. This section is mostly okay with isolated area of wrap failure and some coating failure with corrosion.	Isolated area of coating failure and corrosion with pitting 0.050" noted at 6 o'clock 57" from (UTT = 0.401" - 0.406")	Pit 0.114" at 6 o'clock 82" from $IITI = 0.383" - 0.387"$	Pit $0.050$ "- $0.200$ " at 6 o'clock $22$ " from (UTT = $0.386$ " – $0.393$ ")	Pipe is wrapped up to the middle of this section. There is some coating failure but no significant corrosion in this section.	Approximately 6' of coating failure and corrosion under the wrap. Will need to remove wrap and coat for VT/570.	Pipe is wrapped at this location. The wrap is failing with corrosion noted.	This pipe support to wall attachment is completely corroded (qty 4)	This pipe support has one wall attachment and is corroded	Pipe is wrapped at this location. This section is mostly okay with minimal bubbles and corrosion spot.	Approximately 24" of coating failure and corrosion near	Pipe is wrapped at this location. This section is mostly okay with isolated area of wrap failure and some minor coating failure with corrosion	station with corresponding to the sound of the sound control of co		Pit 0.050"-0.089" at 5 o'clock 121" from UTT = 0.241" - 0.275")	d area with minimal coating failure and no significant corrosion	Pipe is wrapped at this location. The wrap has minimal corrosion noted.	This pipe support to wall attachment is completely corroded (qty 4)	This pipe support has one wall attachment and is corroded	Pit $0.050$ "- $0.070$ "(UTT = $0.250$ " - $0.252$ ") 15" from	The first 6' is wrap with some as wax tape in this section. The wrap is mostly set and intermittent. Some coating failure is noted but no notable corrosion.	Approximately 8' of coating failure and minor corrosion at 6 o'clock	Pipe is mostly (70-100%) wrapped at this location	Wrap is damaged with some corrosion and spot coating repair done in the past but not 100% completed. Remove 10' of wrap and coat	Pup at this pipe support has areas of coating failure and some corrosion. Area was cleaned off in the past (see rust scale under pipe). Spot coat repair is not satisfactory.
Table		Appr	Supp	Some ac	Isolated	Pipe	Pipe	Appr	Pipe failu	Isola 0.40]	Pit 0	Pit 0	Pipe this s	Approxii VT/570.	Pipe	This	This	Pipe	Appr	Pipe	Isolated	Pit 0.	Pit 0	Isolated	Pipe	This	This	Pit 0	The first failure is	Appr	Pipe	Wrap	Pup a
	System	F-24	F-24	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	JP-5	JP-5	JP-5	JP-5	JP-5	JP-5	JP-5	JP-5	IP.5	JP-5	JP-5	F-24	F-24	F-24	F-24	F-24	F-76	F-76	F-76	F-76	F-76
	Relative Location																									-							
	NPS	16	16	32	32	32	32	32	32	32	32	32	18	18	18	18	18	18	18	18	18	18	18	16	16	16	16	16	32	32	32	32	32
	Item #	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	108	199	200	201	202	203	204	205	206	207	208	209	210

				Table H – Coating failure and corrosion (cont.)
Item #	NPS	Relative Location	System	Description
241	18		JP-5	There are small drips and stains with coating failure at 17 o'clock between near
242	18		JP-5	Approximately 24" of coating failure and minor corrosion in no wrap section
243	18		JP-5	oot wrapped at this location
244	16		F-24	There is pipe penetration at the 288 side which has approximately 36" of wax tape. There is some minor failure of the wax tape and small corrosion area. Approximately 30-40 pits were noted. Recommend to remove tape and paint.
245	16		F-24	Pipe is wrapped at this location and is mostly satisfactory with some wrap failure. Coating failure and minor corrosion noted but not significant.
246	16		F-24	Approximately 6' of wrap damage at this location. Have previously done spot coat touch up, but not 100%.
247	16		F-24	
248	16		F-24	
249	16		F-24	Pipe is wrapped at this location with some minor coating failure and no significant corrosion. Note: Coat repair was only done in the front 1-6 o'clock. There is heavy coating failure and moderate corrosion between 6-12 o'clock.
250	16		F-24	Pipe is wrapped at this location. Approximately 10' section at sections but no significant coating failure or corrosion was noted.
251	16		F-24	Approximately 12" of coating failure and minor corrosion (no significant pits noted)
252	16		F-24	Pipe is mostly wrapped at this location. Approximately 10' section of coating noted near and intermittent wrap (<12' of wrap sections) between the ending of the ending failure or corrosion was noted.
253	16		F-24	Pipe is wrapped at this location. Wrap is fairly good with minimal damage and good adhesion to pipe.
254	16		F-24	Approximately 60" of coating failure and minor corrosion in no wrap section (no significant pits noted)
255	16		F-24	Approximately 12" of wrap is damaged and has coating failure with minor corrosion (no significant pits noted)
256	16		F-24	Approximately 36" of coating failure and minor corrosion in no wrap section near at previous coat repair
257	16		F-24	Approximately 24" of coating failure and minor corrosion in no wrap section. This is an old coat repair spot.
258	16		F-24	Approximately 24" of coating failure and minor corrosion in no wrap section (no significant pits noted)
259	16		F-24	Small Drips and stain with coating failure at 12 o'clock near
260	16		F-24	Pipe is wrapped at this location. Approximately 72" of wrap failure with coating failure and minor corrosion.
261	16		F-24	Pipe is wrapped at this location. Approximately 72" of wrap failure with coating failure and minor corrosion.
262	32		F-76	Pipe is wrapped at this location intermittently. There are 1 or 2 small sections of wraps with minimal peel.
263	32	,	F-76	Approximately 56" of coating failure and minor corrosion near BH (no significant pits noted)
265	32		F-76	Approximately 48" of coating failure and corrosion. This was flagged for clean and repair coat in 2010. Pit 0.050"-0.080" noted.
266	32		F-76	Approximately 36" of coating failure and minor corrosion (no significant pits noted)
267	32		F-76	Approximately 24" of coating failure and minor corrosion near at 8-11 o'clock
768	32	,	F-/6	Approximately 48" of coating failure with no significant corrosion (no significant pits noted)

# ER-JBPHH,HI-RED HILL FACILITY-PIPING-MAY/2022

Table H – Coating failure and corrosion (cont.)	Description	Approximately 60" of coating failure and moderate corrosion (no significant pits noted) at 5-10 o'clock	Approximately 24" of coating failure and corrosion (no significant pits noted) at 7-10 o'clock	Approximately 12" of coating failure and corrosion (no significant pits noted) at 6 o'clock	Pipe is spot wrapped at this location	Approximately 60" of coating failure and corrosion (no significant pits noted) at 11-6 o'clock	Approximately 24" of coating failure and minor corrosion (no significant pits noted) at 6-12 o'clock	Approximately 36" of coating failure and minor corrosion (no significant pits noted) at 6-8 o'clock	Approximately 36" of coating failure and minor corrosion (no significant pits noted) at 6-10 o'clock	Pipe is wrapped at this location	Pipe is coated only with one wrap at this location	Approximately 24" of coating failure and corrosion (no significant pits noted) at 360 o'clock	Pipe is spot wrapped at this location	Isolated area of coating failure and minor corrosion (no significant pits noted) at 6 o'clock	Approximately 36" of coating failure and minor corrosion (no significant pits noted) at 6-12 o'clock	Pipe is wrapped at this location	Pipe is wrapped at this location. There is wrap failure and coating failure with minor corrosion	Pipe is coated only with one wrap at this location	Isolated area of minor coating failure and corrosion at door wall pen, approximately 6" from the wall	Approximately 60" of coating failure and corrosion (no significant pits noted) at 360 o'clock	Pipe is spot wrapped at this location	Pipe is wrapped at this location	Isolated minor area of coating failure and corrosion (no significant pits noted)	Approximately 32" of coating failure and minor corrosion (no significant pits noted) at 90-60 o'clock	Isolated areas of coating failure with minor corrosion (no significant pits noted) at 3 locations 6-10 o'clock	Approximately 12" of coating failure with minor corrosion (no significant pits noted) at 60-90 o'clock at guided wave	Approximately 12" of coating failure (no corrosion or significant pits noted) at 6-8 o'clock	Approximately 36" of coating failure with minor corrosion (no significant pits noted) at 6-9 o'clock	Approximately 24" of coating failure with minor corrosion (no significant pits noted) at 7-9 o'clock	Approximately 36" wrap failed at this location with coating failure and minor corrosion at 6-9 o'clock near	Approximately 36" of wrap failed at this location with coating failure and corrosion at 6-12 o'clock	Approximately 12" of coating failure (no corrosion or significant pits noted) at 6-3 o'clock near	Approximately 24" of coating failure with minor corrosion (no significant pits noted) at 6-9 o'clock near	Approximately 24" of wrap failed at this location with coating failure and corrosion at 6 o'clock near saddle	Approximately 36" of wrap failed at this location with coating failure and minor corrosion at 6-9 o'clock	Approximately 36" of wrap failed at this location with coating failure and corrosion 0.369"-0.384" at 6-9 o'clock	Approximately 36" of wrap failed at this location with coating failure and unknown severity of corrosion at 6 o'clock near saddle
T	System	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	JP-5	JP-5	JP-5	JP-5	JP-5	JP-5	JP-5	F-24	F-24	F-24	F-24	F-24	F-24	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76	F-76
	Relative Location																																				
	NPS	32	32	32	32	32	32	32	32	32	18	18	18	18	18	18	18	16	16	16	16	16	16	32	32	32	32	32	32	32	32	32	32	32	32	32	32
	Item #	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340

Item	SdN	Relative	Svetem	Table H – Coating failure and corrosion (cont.)
#	CIN	Location	massic	Describing
341	18		JP-5	Pipe is spot wrapped at this location
342	18		JP-5	Approximately 24" of coating failure (no corrosion or significant pits noted) at 6-8 o'clock
343	18		JP-5	Approximately 18" of wrap failed at this location with coating failure and corrosion at 6 o'clock with 0.050"-0.080" pits noted
344	18		JP-5	Approximately 12" of coating failure (no corrosion or significant pits noted) at 6 o'clock near
345	18		JP-5	Approximately 24" of coating failure (no significant corrosion or pits noted) at 6-9 o'clock
346	16		F-24	Approximately 12" of coating failure (no corrosion or significant pits noted)
347	16		F-24	Approximately 36" of coating failure with minor corrosion (no significant pits noted) near
348	16		F-24	Approximately 24" of wrap failed at this location with coating failure and minor corrosion at 6-10 o'clock
349	16		F-24	Approximately 24" of wrap failed at this location with coating failure and minor corrosion at 6-8 o'clock
350	16		F-24	There is coating failure and corrosion noted at BH concrete penetration. Note some concrete spalling also noted at the BH penetration
351	32		F-76	Isolated area of moderate coating failure and minor corrosion 0.020"-0.080" at 6-10 o'clock
352	18		IP-5	Approximately 24" of coating failure with minor corrosion (no significant pits noted) each at 2 locations
353	18		JP-5	Approximately 36" of coating failure with no significant corrosion (no significant pits noted)
354	18		JP-5	Approximately 24" of wrap failed at this location with corrosion near Recommend to remove wrap.
355	16		F-24	Isolated area of moderate coating failure (no corrosion of pits noted)
356	16		F-24	Isolated area of moderate wrap failure with coating failure and corrosion
357	16		F-24	Approximately 30" of coating failure with minor corrosion (no significant pits noted) each at 2 locations
358	16	-1	F-24	Approximately 36" of coating failure with no significant corrosion (no significant pits noted) near
359	16		F-24	Approximately 36" of coating failure with no significant corrosion (no significant pits noted) past
360	32		F-76	Pipe is spot wrapped at a couple of spots in this location. No significant wrap failure noted.
361	32		F-76	Isolated area of wrap failure near BH with some minor corrosion 0.050"-0.080" at 12-6 o'clock
362	32		F-76	Isolated area of coating failure with no significant corrosion at saddle #36, 8-11 o'clock due to water drip
363	32		F-76	Isolated area of coating failure with no significant corrosion at 7-11 o'clock
364	32	1	F-76	Pipe is spot wrapped 60-70% in this location
365	32		F-76	Approximately 24" of coating failure (no corrosion or significant pits noted) at 6-10 o'clock
366	32		F-76	Approximately 36" of coating failure with minor corrosion (no significant pits noted) at 6-11 o'clock due to wrap failure
367	32		F-76	Approximately 24" of wrap failure with coating failure and minor corrosion (no significant pits noted) at 6-10 o'clock
368	32		F-76	Approximately 24" of wrap failure with coating failure (no corrosion or significant pits noted) at 6-9 o'clock
369	18		JP-5	Approximately 24" coating failure and no significant corrosion (no significant pits noted) at about the halfway point
370	18		JP-5	Pipe is spot wrapped 60-70% in this location
371	18		JP-5	Approximately 36" of coating failure with minor corrosion (no significant pits noted) at 6-10 o'clock due to wrap failure
372	18		JP-5	Approximately 36" of coating failure (no corrosion pits noted) at 6-10 o'clock
373	18		JP-5	Isolated area of coating failure (no corrosion or significant pits noted) at 12-6 o'clock

Itom		Dolotivo		Table H – Coating failure and corrosion (cont.)
# #	NPS	Location	System	Description
374	18		JP-5	Approximately 24" coating failure (no corrosion or significant pits noted) at 12-6 o'clock
375	16		F-24	Approximately 24" of coating failure with no significant corrosion (no significant pits noted) near
376	16		F-24	Approximately 24" of coating failure with no significant corrosion (no significant pits noted) at about the halfway point
377	16		F-24	Pipe is spot wrapped 40-50% in this location
378	16		F-24	Approximately 48" of coating failure with minor corrosion (no significant pits noted)
379	16		F-24	Approximately 36" coating failure (no corrosion or significant pits noted)
380	16		F-24	Approximately 24" coating failure with minor corrosion (no significant pits noted) at 6-9 o'clock
381	16		F-24	Approximately 14" coating failure with minor corrosion (no significant pits noted) at 6-12 o'clock
382	32		F-76	Approximately 36" of wrap failure with coating failure and minor corrosion (no significant pits noted) at 6-10 o'clock
383	32		F-76	Isolated area of wrap failure with coating failure and minor corrosion and inactive pitting 0.060"-0.080" at 6-8 o'clock
384	32		F-76	Isolated area of wrap failure at 6 o'clock after saddle #15 and corrosion severity unknown
385	32		F-76	Isolated area of coating failure with minor corrosion at 6-10 o'clock
386	32		F-76	Pipe is spot wrapped 50-70% in this location
387	18		JP-5	Approximately 24" of wrap failure with coating failure and minor corrosion (no significant pits noted)
388	18		JP-5	Approximately 24" of wrap failure with coating failure and (no corrosion or significant pits noted) at 8-12 o'clock
389	18		JP-5	Isolated area of coating failure (no corrosion or significant pits noted)
390	18		JP-5	Isolated area of coating failure (no corrosion or significant pits noted) at 6 o'clock
391	18		JP-5	Isolated area of a wrap failure
392	18		JP-5	Pipe is spot wrapped 50-60% in this location
393	16		F-24	Pipe is spot wrapped 30-40% in this location
394	16		F-24	Approximately 24" of wrap failure with coating failure (no corrosion or significant pits noted) at 6-12 o'clock
395	16		F-24	Approximately 24" of wrap failure with coating failure (no corrosion or significant pits noted) at 6-10 o'clock
396	16		F-24	Isolated area of a wrap failure
397	16		F-24	Isolated area of wrap failure with coating failure and minor corrosion (no significant pits noted)
398	16		F-24	Isolated area of corrosion on pipe sleeve weld 2" HPV and LPV before flange
399	32		F-76	Approximately 6' of coating failure (no corrosion or significant pits noted)
400	18		JP-5	BH Pipe Penetration has pitting 0.026"-0.046" at 1-4 o'clock (UTT = 0.231" – 0.240")
401	18		JP-5	Isolated area of coating failure (no corrosion or significant pits noted)
				The coating on the UGPH piping is mostly in satisfactory condition with minor isolated coating failure noted
	,		F-76	on segments of piping below the grating. One location of moderate coating failure and pitting (0.050-0.070)
402	NA		JP-5	noted on line just before ball valve #232E4. Some coating failure and inactive pitting was noted on the
			F-24	Ilange, dresser coupling and appurtenances. Some discoloration due to staining also noted on segments of UGPH piping.
			F-76	The coating at the tank gallery is in satisfactory condition with very minor isolated coating failure. Most of the
403	NA		JP-5	coating failures were localized due to contact type abrasion damage or location were ceiling material is drinning on the pine. Increasions with material drins from the ceiling did not have any significant coating failure.
			F-24	Specific locations of coa <u>ting f</u> ailures and corrosion areas on the pipe and support are listed in Table D and E.

				Table H – Coating failure and corrosion (cont.)
Item #	SdN	Relative Location	System	Description
404	NA		F-76 JP-5 F-24	The coating at the surge tank is in satisfactory condition with very minor isolated coating failure. There were no areas of corrosion noted due to coating failure at the surge tank. Majority of the coating damage is due to impact (nick and scratches) from resent tank cleaning and inspection staging. There are several equipment staged in surge tank area. There is one location on tank that was prepared for coating touch up (section taped off with blue masking tape) but not completed.

\*All clock positions are given facing U \*\* BH = Bulkhead

### 4.2. Maintenance Recommendations

Refer to Table D to identify areas of correction required to assure longevity of piping systems. Some general deficiencies and preventive maintenances are highlighted below:

- **4.2.1** Periodically inspect and maintain all above ground piping and appurtenances per requirements outlined in UFC 3-460-03.
- **4.2.2** There are minor to moderate coating failures noted on carbon steel pipes, flanges, appurtenances, and hardware. Repair coating per UFC 3-460-03.
- **4.2.3** Repair the pipe supports; consider installing thermoplastic spacers, shims, or half round (I-Rod) type supports to help reduce metal/metal contact and prevent crevice corrosion.
- **4.2.4** Report all segments of piping where excessive vibration and swaying are noted during operation for a follow-up inspection per API STD 570.

### 4.3. Compliance Requirements

Refer to Table D to identify areas of correction required to assure longevity of piping systems.

**4.3.1** All deficiencies with a mandatory color code should be repaired as soon as practical or before the piping is returned back to normal operating service.

### 5.0 Serviceability and Schedule

The piping systems covered by this report are certified for continued normal service contingent on the completion of the mandatory items identified in Table D. See requirements noted in Section 4.3. This certification is based on the data recorded, the engineering analysis and recommendations presented in the body of this report, and no change to the piping products or service. This certification is in accordance with API-570. This is a baseline assessment of the facility piping, and inspection and testing should be ongoing. This report classifies the piping systems as Class 1 in accordance with API-570.

- 5.1.1 The next <u>formal visual inspection</u> should be conducted by an API-570 inspector by May, 2027 (every five years for Class 1 piping).
- 5.1.2 The next <u>ultrasonic thickness evaluation</u> should be conducted by an API-570 inspector by May, 2027 (every five years for Class 1 piping).
- 5.1.3 The following <u>owner/user inspection</u> schedule is added to aid in the integrity of the facility pipeline and may be accomplished by facility personnel or outside contractor.
  - 5.1.3.1 Visual inspection by maintenance personnel. (Daily)
  - 5.1.3.2 Visual inspection with log/checklist by maintenance personnel. (Monthly)
  - 5.1.3.3 Inspect exterior coatings by maintenance personnel. (Semi-Annually)
  - 5.1.3.4 Thermal Relief Valve (TRV) inspection and testing by maintenance personnel (Annually).
  - 5.1.3.5 Low Point Drains (LPDs) exercising by maintenance personnel (including dead legs when present).

# Annex A Phased Array Ultrasonic and Guided Wave Results

- 1. Phased Array Ultrasonic Testing Results
- 2. Guided Wave Results



### Results of the Ultrasonic Phased Array Ultrasonic Testing Conducted

### **A.1.1** Executive Summary

Phased Array Ultrasonic Testing (PAUT) of selected welds were conducted under this project. The PAUT condition monitoring locations (CMLs) were selected based on pipe movement and anticipated/potential exposure of shear and bend stress due to operating conditions. The purpose of this PAUT weld examination was to detect any service induced defects such as cracking or erosion/corrosion that may be present in selected welds and heat affected zones. Welds selected are intended to be a representative sample of facility piping and selected based on areas that could see higher than normal stress due to pipe movement, cyclic stresses, or boundary restraints (sections between anchor points). The primary focus of the PAUT weld examination was the circumferential welds, but select abutting longitudinal welds were also examined for completeness when possible. The original welding flaws were considered non-relevant (unless gross weld flaw was detected) for this inspection since there is satisfactory service history. A combination of manual and semi-automated PAUT was performed and results documented. The PAUT data indicated there was no service induced defects on all tested welds. Eight-six locations (86) were completed throughout the facility.

The PAUT condition monitoring locations are documented in the tables in Annex 1 and shown in Appendix C (Drawings).

Project included removal of lead-based paint at 86 locations to support the PAUT weld examinations. PAUT weld examination locations also required surface preparation (weld spatter filling) to ensure adequate coupling to aid the transmission of ultrasonic energy. Locations where the coating was removed for the PAUT testing were restored with a Kem Kromik Universal Metal Primer.

### A.1.2 Introduction and Background:

This annex presents the work carried out and an analysis of data collected during the PAUT inspection conducted from April 19, 2022 through May 12, 2022 at Joint Base Pearl Harbor Hickam; Hawaii, under contract for Austin Brockenbrough & Associates LLC. The inspection was performed by a certified PAUT Level III technician. The testing was conducted by a teaming partner from Engineering & Inspection Hawaii, Inc (E&I Inc) under the supervision of a certified weld inspector from InterSpec, LLC.

### A.1.3 Test Procedure:

PAUT techniques are used for identification of discontinuities in welds and heat affected zones (HAZs). The sound beam enters the area of the weld at an angle. If the sound reflects from a discontinuity, a portion of the sound beam returns to the receiver where it is displayed on the ultrasonic instrument. PAUT is conducted using manual, semi-auto or fully automated scanning using probes consisting of various piezoelectric elements that are pulsed individually to create the phased aspect of the signal generation.

Daily calibration using a test block containing side dried holes are performed prior to and at the completion of an examination at the end of the day.

Approximately sixaccordance with the written procedure. Both longitudinal and transverse scans were completed at each
weld unless limited by the geometrical features of the pipe weld. A full circumferential scan was
completed unless access was limited at the weld by adjacent pipes, ventilation ducting, conduits, etc.

PAUT was conducted per ASME Section V, Article 4, Ultrasonic Examination Methods for Welds, 2015 edition. Results of the PAUT is included in this Annex.

6
9
<b>Fable</b>
2
lar
Ξ
Ξ
=
5
Ξ
.=
aluation S
Ξ
2
E
5
V
4
ž
able
550

CML					Weld	Coating	CML	HAZ	PAUT		
ID	Area	Line	Location	NPS	Type	Removed	Label	Cleaned	Done	Restored	Result*
ST3	Surge Tank	F-76			W	X	X	X	X	X	Satisfactory
ST2	Surge Tank	F-24			W	X	X	X	X	X	Satisfactory
STI	Surge Tank	F-76			W	X	X	X	X	X	Satisfactory
2B	UGPH	JP-5			W	X	X	X	X	X	Satisfactory
3B	UGPH	F-24			W	X	X	X	X	X	Satisfactory
4B	UGPH	F-76			W	X	X	X	X	X	Satisfactory
5B	UGPH	JP-5			W	X	X	X	X	X	Satisfactory
1A	UGPH	F-76			W**	X	X	X	X	X	Satisfactory
2A	UGPH	JP-5			M	X	X	X	X	X	Satisfactory
3A	UGPH	F-24			W	X	X	X	X	X	Satisfactory
5A	UGPH	JP-5			W	X	X	X	X	X	Satisfactory
P4	UGPH	F-24			M	X	X	X	X	X	Satisfactory
DI	Tank Gallery	F-76			M	X	X	NA	X	X	Satisfactory
D2	Tank Gallery	F-76			W	X	X	NA	X	X	Satisfactory
D3	Tank Gallery	F-76			W	X	X	NA	X	X	Satisfactory
D5	Tank Gallery	F-76			W	X	X	NA	X	X	Satisfactory
C1	Tank Gallery	JP-5			W	X	X	NA	X	X	Satisfactory
C2	Tank Gallery	JP-5			W	X	X	NA	X	X	Satisfactory
C3	Tank Gallery	JP-5			W	X	X	NA	X	X	Satisfactory
C4	Tank Gallery	F-76			W	X	X	X	X	X	Satisfactory
B1	Tank Gallery	JP-5			W	X	X	NA	X	X	Satisfactory
B2	Tank Gallery	JP-5			W	X	X	NA	X	X	Satisfactory
B3	Tank Gallery	JP-5			W	X	X	NA	X	X	Satisfactory
B4	Tank Gallery	F-76			W	X	X	NA	X	X	Satisfactory
B5	Tank Gallery	F-76			W	X	X	NA	X	X	Satisfactory
A1	Tank Gallery	F-24			W	X	X	NA	X	X	Satisfactory
A3	Tank Gallery	F-24			W	X	X	NA	X	X	Satisfactory
A4	Tank Gallery	F-24			W	X	X	NA	X	X	Satisfactory
A5	Tank Gallery	F-24			W	X	X	NA	X	X	Satisfactory

ER-JBPHH, HI-RED HILL FACILITY-PIPING-MAY/2022

Table I - PAUT Evaluation Summary Table (Cont.)

			Table I - FAUT EN	valuatio	III Sulli	Evaluation Summary radic (Cont.)	אנ (כי	JIII.)			
CML					Weld	Coating	CML	HAZ	PAUT		
ID	Area	Line	Location	NPS	Type	Removed	Label	Cleaned	Done	Restored	Result*
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			MW	X	X	X	X	X	Satisfactory
		JP-5			MW	X	X	X	X	X	Satisfactory
		F-76			MW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	×	X	X	X	Satisfactory
		F-24			BBW	X	×	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory

Table I - PAUT Evaluation Summary Table (Cont.)

			T TOYY TAIGHT	L'anuan Summai Fasic (Sont)			(2)	(222	•		
CML					Weld	Coating	CML	HAZ	PAUT		
ID	Area	Line	Location	NPS	Type	Removed	Label	Cleaned	Done	Restored	Result*
		JP-5		(b) (3) (A)	BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			W	X	X	X	X	X	Satisfactory
		F-24			MW	X	X	X	X	X	Satisfactory
		JP-5			MW	X	X	X	X	X	Satisfactory
		F-76			MW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76	_		BBW	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			W	X	X	X	X	X	Satisfactory
		F-24			BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			W	X	X	X	X	X	Satisfactory
		F-24	_		BBW	X	X	X	X	X	Satisfactory
		JP-5			BBW	X	X	X	X	X	Satisfactory
		F-76			W	X	X	X	X	X	Satisfactory
		F-24			MW	X	X	X	X	X	Satisfactory
		JP-5			MW	X	X	X	X	X	Satisfactory
		F-76			MW	X	X	X	X	X	Satisfactory

welding flaws were considered non-relevant for this inspection since there is satisfactory service history. However, any gross original weld flaw The purpose of this PAUT weld examination was to detect any service induced defects such as cracking or erosion/corrosion. The original would be flagged when identified.

<sup>\*\*</sup> Partial weld Girth and seam weld



Inspection Date: April 19th through May 12th, 2022

### Red Hill, PAUT of Piping Butt Welds

No service induced defects detected at time of inspection.

### SCOPE

Engineering & Inspections Hawaii, conducted manual and semi-automated Phased Array Ultrasonic Testing (PAUT) examinations for Interspec at the Red Hill facility in Aiea, HI on April 19<sup>th</sup> through May 12<sup>th</sup>, 2022. The purpose of this examination was to detect any service induced defects such cracking or erosion/corrosion that may be present in selected welds and heat affected zones. Original welding flaws were considered non-relevant for this inspection. Examples of typical original welding flaws found during this inspection are included in Appendix A at the end of this report.

If you have any questions regarding this matter or require any additional information, please do not hesitate to contact J(b) (6)



API-QUTE API-570 AWS CWI

Engineering & Inspections Hawaii, Inc

P. O. Box 700217 • Kapolei, HI 96709-0217 • Tel: (808) 682-1667 • Fax: (808) 682-1834 • E-Mail: E I Hawaii@aol.com



### **TECHNIQUE**

Welds with a wall thickness of 0.375 or greater were scanned with a 5MHz linear array probe using 32 active elements to produce a sectorial scan utilizing shear waves from 45° to 70° focused at 1.5x the pipe thickness.

Welds with a wall thickness of 0.250 or less were scanned with a 5MHz linear array probe using 16 active elements to produce a sectorial scan utilizing shear waves from 43° to 70° focused at 1.5x the pipe thickness.

The client had coating removed and scanning surfaces manually filed smooth to remove weld spatter and ensure adequate coupling to aid the transmission of ultrasonic energy.

All welds in the Surge Tank and Galley areas were accessible and encoded. All welds in the Pump House and Harbor Tunnel areas had limitations which did not allow for encoding and were manually scanned instead.

### **CALIBRATION**

### Wedge delay calibration

Steel NAVSHIPS calibration standard (S/N: 03-8269) with 3/64" side drilled holes.

### Sensitivity and TCG calibration

Steel NAVSHIPS calibration standard (S/N: 03-8269) with 3/64" side drilled holes.

### **INSPECTION RESULTS**

**Specification:** ASME Section V **Procedure:** NDT-005.6, Rev. A

**Acceptance:** Client Information Only. Report all service induced defects.

No service induced defect indications detected No service induced defect indications detected No service induced defect indications detected
No service induced defect indications detected No service induced defect indications detected
No service induced defect indications detected
No service induced defect indications detected



HT1	No service induced defect indications detected
HT2	No service induced defect indications detected
HT3	No service induced defect indications detected
HT4	No service induced defect indications detected
HT5	No service induced defect indications detected
HT6	No service induced defect indications detected
1110	
HT7	No service induced defect indications detected
HT8	No service induced defect indications detected
HT9	No service induced defect indications detected
HT10	No service induced defect indications detected
HT11	No service induced defect indications detected
HT12	No service induced defect indications detected
11112	
HT13	No service induced defect indications detected
HT14	No service induced defect indications detected
HT15	No service induced defect indications detected
LITT	No complete in decoral districtions districted
HT16	No service induced defect indications detected
HT17	No service induced defect indications detected
HT18	No service induced defect indications detected
HT19	No service induced defect indications detected
HT20	No service induced defect indications detected
HT21	No service induced defect indications detected
HT22	No service induced defect indications detected
HT23	No service induced defect indications detected
HT24	No service induced defect indications detected
HT25	No service induced defect indications detected
HT26	No service induced defect indications detected
HT27	No service induced defect indications detected
HT28	No service induced defect indications detected
HT29	No service induced defect indications detected
HT30	No service induced defect indications detected
LITEO 1	No service induced defect indications detected
HT31	
HT32	No service induced defect indications detected  No service induced defect indications detected
HT33	No service induced defect indications detected
HT34	No service induced defect indications detected
HT35	No service induced defect indications detected
HT36	No service induced defect indications detected
HT37	No service induced defect indications detected
HT38	No service induced defect indications detected
HT39	No service induced defect indications detected



HT40	No service induced defect indications detected
HT41	No service induced defect indications detected
HT42	No service induced defect indications detected
HT43	No service induced defect indications detected
HT44	No service induced defect indications detected
HT45	No service induced defect indications detected
HT46	No service induced defect indications detected
HT47	No service induced defect indications detected
HT48	No service induced defect indications detected
HT49	No service induced defect indications detected
HT50	No service induced defect indications detected
HT51	No service induced defect indications detected
HT52	No service induced defect indications detected
HT53	No service induced defect indications detected
HT54	No service induced defect indications detected
HT55	No service induced defect indications detected
HT56	No service induced defect indications detected
HT57	No service induced defect indications detected
A1	No service induced defect indications detected
A3	No service induced defect indications detected
A4	No service induced defect indications detected
A5	No service induced defect indications detected
B1	No service induced defect indications detected
B2	No service induced defect indications detected
B3	No service induced defect indications detected
B4	No service induced defect indications detected
B5	No service induced defect indications detected
C1	No service induced defect indications detected
C2	No service induced defect indications detected
C3	No service induced defect indications detected
C4	No service induced defect indications detected
	V
D1	No service induced defect indications detected
D2	No service induced defect indications detected
D3	No service induced defect indications detected
D5	No service induced defect indications detected

<sup>\*</sup>Original welding flaws were considered non-relevant to this inspection. Examples of typical original welding flaws found during this inspection are included in Appendix A at the end of this report.



## Engineering Inspections Hawaii

91-515 Nukuawa St. Kapolei, HI 96707 (808) 682-1667

**Project** 

Client Interspec Contact

Project Red hill piping Red Hill, Aeia, HI Location

Project No. 22-131 Inspector Name

220419-PAUT-RH ASNT UT level III Inspection No. Inspector Licence Total pages 3


Description PAUT examination of piping butt welds wall thickness approx 0.375 +

### **Instrument Specifications**

Data File Name 220507-RH-D1-090.odat Instrument OmniScan X3

Instrument Serial QC-0075896 Software Version OmniPC 5.6.0 Inspection Version 5.6.0.2057


Model OMNIX3-PA32128PR





### Part & Weld

Material	Steel, Mild	Fill Height	0.000 in
Geometry	Pipe	Fill Angle	0.0°
Thickness	0.375 in	Hot-Pass Height	0.296 in
Outside Diameter	12.750 in	Hot-Pass Angle	30.0°
Weld Type	V Offset	Land Height	0.079 in
Symmetry Type	Symmetric	Land Offset	0.079 in
		Root Height	0.000 in
		Root Angle	0.0°
		Haz Width	0.236 in
		Cap Height	0.079 in
		Cap Width	0.259 in



### **Inspection Summary**

No service induced flaw indications detected.







### Scan Area

Scan Start 0.00 in

Scan End 65.00 in

Scan Resolution 0.04 in

Max. Speed 5 in/s

Scan Encoder

Encoder Type Quadrature

Encoder Resolution 304.80 step/in.

Polarity **Normal** 

Input 1

### **Inspection and Environment Context Notes**

[Click/Tap to edit]

# Engineering & Inspections Hawaii 91-515 Nukuawa St. Kapolei, HI 96707

## PA-1

## **Probe Characteristics**

Probe Model 5L32-A11 Scan Offset 0.000 in Serial \_1 Index Offset -0.500 in Probe Skew 90.0° Frequency 5.0 MHz

Probe Aperture 32

Wedge Model SA11-N55S 5L3

36.1° Fill Angle

Cotup	C CD 4						
Setup	Group: GR-1						
Туре	PA	Averaging Factor	1	Gain	27.8 dB		
Beam Delay	22.79 µs	Compression	4	Mode	PE (Pulse-Echo)		
Start True Depth	0.250 in	Effect. Digit. Frequency	100 MHz	Video Filter	Off		
Wave Type	Shear	Net Digit. Frequency	25 MHz	Range True Depth	0.832 in		
Rectification	Absolute	Velocity	0.1276 in/µs	Acq. Rate	120.0 Hz		
Filter	BP 5.25 MHz	Pulse Width	100.0 ns	Voltage	40.00 V		
Gates	Start	Width	Treshold	Synchro	Peak Selection		
Α	0.000:-	0.504 :	45.0/	Dules	I Calana		
A	0.200 in	0.591 in	15 %	Pulse	Highest		
2. AND SOCIAL AND COLORS - 100 - 100 AND COLORS - 100	0.200 In  Position True Depth		100 EC	Puise Position True Depth	Date or		
2. AND SOCIAL AND COLORS - 100 - 100 AND COLORS - 100			100 EC		DOTE: NA		
TCG Point Number	Position True Depth	Gain	TCG Point Number	Position True Depth	Gain		
TCG Point Number 1 Calculator	Position True Depth	Gain	TCG Point Number	Position True Depth	Gain		
TCG Point Number	Position True Depth 0.000 in	Gain 0.0 dB	TCG Point Number 2	Position True Depth 0.749 in	Gain 2.7 dB		
TCG Point Number  1  Calculator  Law Configuration	Position True Depth 0.000 in Sectorial	Gain 0.0 dB Element Step	TCG Point Number	Position True Depth 0.749 in  Angle Resolution	Gain 2.7 dB 1.0 °		



# Engineering Inspections Hawaii

91-515 Nukuawa St. Kapolei, HI 96707 (808) 682-1667

**Project** 

Client Interspec Contact

Project Red hill piping Location Red Hill, Aeia, HI

Project No. 22-131 Inspector Name

Inspection No. 220419-PAUT-RH Inspector Licence ASNT UT level III Total pages 3

Description PAUT examination of piping butt welds wall thickness approx 0.250"

## **Instrument Specifications**

Instrument OmniScan X3 Data File Name 220422-RH-HT9.odat

Instrument Serial QC-0075896
Software Version OmniPC 5.6.0
Inspection Version 5.6.0.2057


Model OMNIX3-PA32128PR





#### Part & Weld

Material	Steel, Mild	Fill Height	0.000 in
Geometry	Pipe	Fill Angle	0.0°
Thickness	0.250 in	Hot-Pass Height	0.171 in
Outside Diameter	18.000 in	Hot-Pass Angle	30.0°
Weld Type	V Offset	Land Height	0.079 in
Symmetry Type	Symmetric	Land Offset	0.079 in
		Root Height	0.000 in
		Root Angle	0.0°
		Haz Width	0.236 in
		Cap Height	0.079 in
		Cap Width	0.187 in



#### **Inspection Summary**

No service induced flaw indications detected.





# Engineering & Inspections Hawaii 91-515 Nukuawa St. Kapolei, HI 96707

Scan Area

Scan Start 0.00 in

Scan End 62.20 in

Scan Resolution 0.04 in

# **Inspection and Environment Context Notes**

[Click/Tap to edit]



# **Engineering & Inspections Hawaii** 91-515 Nukuawa St. Kapolei, HI 96707

## PA-1

#### **Probe Characteristics**

Probe Model 5L16-A10 Scan Offset 0.000 in

Serial \_1 Index Offset -0.375 in

Frequency 5.0 MHz Probe Skew 90.0 °

Probe Aperture 16


Wedge Model SA10-N55S 5L1

Fill Angle 36.1 °

Setup	Group: GR-1				
Туре	PA	Averaging Factor	1	Gain	24.5 dB
Beam Delay	8.88 µs	Compression	3	Mode	PE (Pulse-Echo)
Start True Depth	0.100 in	Effect. Digit. Frequency	100 MHz	Video Filter	Off
Wave Type	Shear	Net Digit. Frequency	33 MHz	Range True Depth	0.700 in
Rectification	Absolute	Velocity	0.1276 in/μs	Acq. Rate	120.0 Hz
Filter	BP 5.25 MHz	Pulse Width	100.0 ns	Voltage	40.00 V
Gates	Start	Width	Treshold	Synchro	Peak Selection
Α	0.120 in	0.400 in	15 %	Pulse	Highest
TCG Point Number	Position True Depth	Gain	TCG Point Number	Position True Depth	Gain
1	0.000 in	0.0 dB			
Calculator					
Law Configuration	Sectorial	Element Step	27	Angle Resolution	1.0 °
Element Qty Used	16	Start Angle	43.0 °	Focus	0.250 in
First Element	1	Stop Angle	70.0 °	Focusing Type	True Depth
Beam Skew	0°	Last Element	16		




ST1 (Encoded)



No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.

(m) 0.000 in




# ST3 (Encoded)



No service induced defect indications were detected in this scan.



# 2B (Manual)



No service induced defect indications were detected in this scan.




3B (Manual) 60 0 67.0 26.2 dB ND (-U(m·r) 0.000 in 0.000

No service induced defect indications were detected in this scan.




4B (Manual)




No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan. \*Back side of pipe not accessible (long seam section included to make up for missed section of circ weld).






No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.



HT1 (Manual) OmniPC - 220512-RH-HT01-090.odat OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help Multiple Print Screen 6 0 68.0 I-U(m·r) 0.000 in 0.000 in

No service induced defect indications were detected in this scan.




HT2 (Manual) Multiple Multiple Print Screen 6 0 65.0 21.7 dB 6-U(m·r) 0.000 in 0.000 in

No service induced defect indications were detected in this scan.




HT3 (Manual)



No service induced defect indications were detected in this scan.



# HT4 (Manual)




No service induced defect indications were detected in this scan.



HT5 (Manual) OmniPC - 220512-RH-HT05-090.odat OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help Multiple 60 0 45.0° 21.7 dB I-U(m-r) 0.000 in 0.000 in


No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.




HT8 (Manual) OmniPC - 220422-RH-HT8.odat OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help  $\oplus$ 60 0 43.0 24.5 dB

No service induced defect indications were detected in this scan.



# HT9 (Manual)




No service induced defect indications were detected in this scan.



HT10 (Manual) OmniPC - 220422-RH-HT10.odat OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help Multiple 0 Print Screen 60 0 60.0 23.5 dB 33.813 in I-U(m·r) 0.000 in 0.000

No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.



HT12 (Manual)



No service induced defect indications were detected in this scan.




HT13 (Manual) OmniPC - 220425-RH-HT13.oda OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help Multiple 6 0 40.0 24.6 dB 24.570 in 0.264 in -0.238 in 0.345 in ViA^ -0.738 in I·U(m·r) 0.000 in

No service induced defect indications were detected in this scan.




HT14 (Manual)



No service induced defect indications were detected in this scan.



HT15 (Manual)




No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.



HT18 (Manual) OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help  $\oplus$ Multipl 60 0 66.0 24.8 dB 2.769 in I•U(m·r) 0.000 in

No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.



HT20 (Manual) OmniPC - 220425-RH-HT20.odat OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help  $\oplus$ Multiple 6 0 45.0 24.8 dB 2.769 in (•U(m·r) 0.000 in (m) 0.000 in

No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.




HT22 (Manual)



No service induced defect indications were detected in this scan.




HT23 (Manual)



No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.




HT25 (Manual)



No service induced defect indications were detected in this scan.




HT26 (Manual)




No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.




HT29 (Manual)



No service induced defect indications were detected in this scan.




HT30 (Manual)



No service induced defect indications were detected in this scan.




HT31 (Manual)



No service induced defect indications were detected in this scan.



HT32 (Manual)




No service induced defect indications were detected in this scan.



HT33 (Manual) OmniPC - 220427-RH-HT33.oda OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help  $\oplus$ 60 0 40.0 25.4 dB 4.223 in 0.207 in 5A^ 0.383 in I•U(m·r) 0.000 in

No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.




HT35 (Manual) OmniPC - 220427-RH-HT35.oda OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help  $\oplus$ 6 0 40.0 25.4 dB 4.223 in Custom (•U(m·r) 0.000 in

No service induced defect indications were detected in this scan.




## HT36 (Manual)



No service induced defect indications were detected in this scan.




HT37 (Manual)



No service induced defect indications were detected in this scan.




HT38 (Manual)



No service induced defect indications were detected in this scan.




## HT39 (Manual)



No service induced defect indications were detected in this scan.



HT40 (Manual)



No service induced defect indications were detected in this scan.




HT41 (Manual) OmniPC - 220427-RH-HT41.odat OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measurements Display Preferences Help 6 0 45.0 27.6 dB 12.413 in 0.247 in PA^ -0.181 in 5A^ 0.358 in

No service induced defect indications were detected in this scan.

0.000 in (m) 0.000 in






No service induced defect indications were detected in this scan.




HT43 (Manual)



No service induced defect indications were detected in this scan.




HT44 (Manual)



No service induced defect indications were detected in this scan.




HT45 (Manual)



No service induced defect indications were detected in this scan.




## HT46 (Manual)



No service induced defect indications were detected in this scan.




HT47 (Manual)



No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.



HT49 (Manual)



No service induced defect indications were detected in this scan.




HT50 (Manual) OmniPC UT Settings Gates Scan Probe & Parts Focal Law Measure  $\oplus$ 60 0 40.0 22.8 dB I•U(m·r) 0.000 in

No service induced defect indications were detected in this scan.




HT51 (Manual)



No service induced defect indications were detected in this scan.




HT52 (Manual)



No service induced defect indications were detected in this scan.




HT53 (Manual)



No service induced defect indications were detected in this scan.




HT54 (Manual)



No service induced defect indications were detected in this scan.




HT55 (Manual)



No service induced defect indications were detected in this scan.






No service induced defect indications were detected in this scan.




HT57 (Manual)



No service induced defect indications were detected in this scan.




## A1 (Encoded)



No service induced defect indications were detected in this scan.




## A3 (Encoded)



No service induced defect indications were detected in this scan.




## A4 (Encoded)



No service induced defect indications were detected in this scan.




## A5 (Encoded)




No service induced defect indications were detected in this scan.



B1 (Encoded)



No service induced defect indications were detected in this scan. \*4.6" of missed data due to coating section unable to be removed on backside of pipe.




B2 (Encoded) Multiple Print Screen 0,000 in I-U(m r) 0.000 in

No service induced defect indications were detected in this scan.

0.000 in



B3 (Encoded)



No service induced defect indications were detected in this scan.




B4 (Encoded) 69.0 I+U(m·r) 0.000 in I(m) 0.000 in

No service induced defect indications were detected in this scan.



B5 (Encoded)




No service induced defect indications were detected in this scan.



C1 (Encoded) OmniPC - 220506-RH-C1-090.odat 68.0 0.000 in I+U(m·r) 0.000 in (m) 0.000 in


No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.





No service induced defect indications were detected in this scan.




C4 (Encoded) HD S TCG OmniPC 5.6 Print Screen 6 68.0 (m) 0.000 in

No service induced defect indications were detected in this scan. \*Upper side of pipe not accessible (long seam section included to make up for missed section of circ weld).



D1 (Encoded)



No service induced defect indications were detected in this scan.




D2 (Encoded) 6 69.0 27.8 dB I+U(m·r) 0.000 in I(m) 0.000 in

No service induced defect indications were detected in this scan.



D3 (Encoded)



No service induced defect indications were detected in this scan.



D5 (Encoded) OmniPC - 220507-RH-D5-090.odat 0 69.0 I+U(m·r) 0.000 in (m) 0.000 in

No service induced defect indications were detected in this scan.



## Appendix A

The purpose of this examination was to detect any service induced defects such cracking or erosion/corrosion that may be present in selected welds and heat affected zones. Original welding flaws were considered non-relevant for this inspection.

The following screen shots are examples of original welding flaws typically seen during this inspection. These are included to illustrate the original welding flaws that were typically detected but is not an exhaustive representation of all flaws found.


AdBA

I·U(m-r)

18.2 dB

0.149 in

S(m-r)CSC 1.038 in



## Comment

Pump house, location 4B, Original welding flaw, Lack of side wall fusion

Depth: 0.242", Length: 1.038", Through wall height: 0.100", Distance from weld centerline: +0.110"

I·U(m-r)

0.317 in

S(m-r)CSC **0.000** in




## **Indication Type: Porosity** Ref. Sectorial Group 9.5 % A% DA^ 0.133 in 0.250 in S(m-r) 0.210 in U(m-r) 0.237 in I(m-r) VIA^ 0.014 in PA^ 0.514 in Comment AdBA 1.5 dB

Pump house, Location 3A, Original welding flaw, Cluster porosity

Depth: 0.133", Length: 0.250", Through wall height: 0.210", Distance from weld centerline: +0.134" -0.106"







## PAUT coating removal and restoration photos



## PAUT coating removal and restoration photos (Cont.)



## PAUT coating removal and restoration photos (Cont.)



Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

464 S Independence Blvd, C-104, Virginia Beach, VA www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853

## Table J - Straight Beam Pipe Ultrasonic Thickness Testing Data at PAUT CMLs

CML ID#	d	ipe Ultrasonic Thickness   Surge Tanks	Pipe Ultrasonic Thickness Data at PAUT Locations (Inches) Surge Tanks	hes)
ST1	0.342			0.360
ST2	0.361	10	1	0.362
ST3	0.377	1	ī	0.358
		Underground Pump House	use	
1A	0.390	1	1	0.365
2A	0.380	T.		0.355
3A	0.360	1	ű	0.380
5A	0.390	1	T.	0.365
6A	0.367	10	1	0.400
2B	0.378	1	ï	0.400
3B	0.250	10	1	0.375
4B	268.0	1	ĩ	0.362
SB	765.0	Е	ĭ	0.376
		Harbor Tunnel		
HT1	0.390	r	ī	0.390
HT2	0.280	30		0.240
HT3	0.252	1	ï	0.240
HT4	0.400	1	-	0.400
HT5	0.240	1	i i	0.235
HT6	0.230	r	ī	0.248
HT7	0.388	31		0.410
HT8	0.240	ı	ī	0.250
HT9	0.247	30		0.247
HT10	0.395	1	ī	0.407
HT11	0.238	г	1	0.245
HT12	0.239	1	(m)	0.247
HT13	0.406	п	-	0.396
HT14	0.258	30	3	0.230

Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853

# Table J - Straight Beam Pipe Ultrasonic Thickness Testing Data at PAUT CMLs (Cont.)

les)	0.238	0.399	0.244	0.252	0.396	0.267	0.254	0.385	0.249	0.248	0.363	0.236	0.234	0.382	0.230	0.237	0.388	0.245	0.245	0.394	0.249	0.242	0.399	0.241	0.239	0.401	0.228	0.250	0.397
a at PAUT Locations (Inch		(=)		-	-	-	10	(5)	( <b>-</b> )	_	î	-		12		ī		-	=						(=		-	-	30
Pipe Ultrasonic Thickness Data at PAUT Locations (Inches)	=	1	30	1		3	U		ı	-	1		3	E	3	ı	30	1	=		L	3	1	3	1	ı	1	ı	310
Pipe	0.236	0.383	0.246	0.249	0.400	0.249	0.262	0.386	0.252	0.242	0.387	0.257	0.233	0.370	0.226	0.245	0.390	0.234	0.243	0.395	0.235	0.233	0.390	0.248	0.235	0.406	0.232	0.230	0.417
CML ID#	HT15	HT16	HT17	HT18	HT19	HT20	HT21	HT22	HT23	HT24	HT25	HT26	HT27	HT28	HT29	HT30	HT31	HT32	HT33	HT34	HT35	HT36	HT37	HT38	HT39	HT40	HT41	HT42	HT43

Office: 757-622-6299

Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Fax: 757-622-9103 Toll Free: 800-546-7853

# Table J - Straight Beam Pipe Ultrasonic Thickness Testing Data at PAUT CMLs (Cont.)

ches)	0.244	0.246	0.406	0.230	0.239	0.408	0.225	0.232	0.368	0.244	0.242	0.411	0.258	0.230		0.350	0.450 (TEE)	0.450 (TEE)	0.371	0.375	0.472 (TEE)	0.505 (TEE)	0.550 (TEE)	0.380	0.370	0.360 (TEE)	0.470 (TEE)	0.375	0.380
a at PAUT Locations (In	(m)		•						*		ï			Ĭ		r		*	•	*		•		-	×		(50)		•
Pipe Ultrasonic Thickness Data at PAUT Locations (Inches)	=	-	8	-	8	1	P	-	-				я	Е	Tank Gallery	r	8	-	-		=	3	-	8	1	=	п	-	т
Pipe	0.236	0.230	0.358	0.248	0.238	0.406	0.240	0.237	0.377	0.236	0.252	0.398	0.253	0.245		0.348	0.350	0.350	0.363	0.370	0.340	0.342	0.345	0.380	0.370	0.349	0.350	0.385	0.350
CML ID#	HT44	HT45	HT46	HT47	HT48	HT49	HT50	HT51	HT52	HT53	HT54	HTSS	HT56	HT57		A1	A3	A4	A5	B1	B2	B3	B4	B5	CI	C2	C3	C4	DI

Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853

# Table J - Straight Beam Pipe Ultrasonic Thickness Testing Data at PAUT CMLs (Cont.)

(es)	0.538 (TEE)	0.500 (TEE)	0.347
a at PAUT Locations (Inches	(200)		1
Pipe Ultrasonic Thickness Data at PAUT Locations	=	-	-
Pipe	0.348	0.344	0.347
CML ID#	D2	D3	DS

[295]

This page is intentionally left blank.



## **Results of the Guided Wave Testing Conducted**

## **A.2.1** Executive Summary

Guided wave ( or long-range ultrasonic testing (LRUT) of the selected concrete bulkhead penetrations and concrete support contact points at the Red Hill fuel complex was completed on April 12, 2022 to evaluate the system's integrity, collect data, and establish a database for future inspections and evaluations. The piping penetrations through the interfaces were inspected unless obstructed by the geometrical features of the pipe or appurtenance attachments. The locations of data acquisition and summary are listed in LRUT Evaluation Summary Table (Table K).

The general pipe configuration; including the bell-shaped pipe ends, pipe weld configuration, pipe weld size, multiple welds at close proximity to each other and other geometrical features on the pipe line (branch connections, anchor plates, other attachments) presented a challenging data acquisition and analysis.

Majority of the data captured and analyzed indicated the piping was satisfactory with no indication within the detectible limits of the LRUT equipment. There were however five (5) locations that have indication requiring a follow-on verification to determine the extent and size of indication. The CMLs for these LRUT scans are listed in Table A.2.1. Other areas of corrosion and pitting captured on the LRUT data were field verified during the test or during the API 570 close visual inspection.

There are one or more signals produced within the bulkhead that are marked as anchor/supports because highest magnitude is at the 6 o'clock position and similar pattern was seen on other tests at this facility. Additionally, there are some bulkheads with expose anchor plates or ring that matched approximately the same "burial depth" within the concrete bulkhead. Other inspections InterSpec performed using borescope and other inspection techniques did also confirm the presence of anchor plates within the bulkhead. Review of construction drawing, other available drawings or previous bulkhead repair projects is recommended to confirm the signals are actually due to anchor plates/rings welded to the pipe.

The data acquisition and analyses were done using a Magnetostrictive sensor (MsS) system. The MsS system is a device that electromagnetically generates and receives low-frequency ultrasonic guided waves. It is used for rapidly surveying a long of pipeline from a single test location. The MsS technology was selected because it is very useful for inspecting and monitoring areas that are difficult to access, such as those at high elevations, behind walls, buried, or under insulation, or from a remote accessible location.

The project included removing layers of deteriorated coating as needed, performing the LRUT, and restoring the coating with a Kem Kromik Universal Metal Primer. The primary focus of this inspection was determining the condition of the bulkhead/concrete penetration piping.

The LRUT condition monitoring locations (CMLs) are documented in the tables in this Annex and shown in Appendix C (Drawings).

	Table A.2.1 (Location requiring a follow-up verification)		
CML#	Description/Name	#	Pipe
B8	There is a failed asbestos wrap with some corrosion noted past the bulkhead (tank gallery side) in the positive direction (creating signal at Q1 (7" past the bulkhead; but remove wrap to verify and inspect indication produced).	(b) (3)	(b) (3) (F76)
B17	One location of defect later identified as inactive pitting (approx. 0.050") with some large area of scaling but minimal metal loss. Two areas of possible similar magnitude of pitting on some frequency seen under pipe wrap. Wrap removal required to get exact size of pitting depth (marked as M1 and M2).	(b) (3)	(b) (3) (F24)
B21	Multiple welds in close proximity to each other are producing directionality and multiple reflection signals but one confirmed indication detected at -402" to -411" on this pipe. There is also one indication identified underneath a concrete saddle support (Saddle # 195) that requires prove-up (visual, thickness and pit inspection) after pipe is lifted off the saddle support. Indication at saddle area was noted on all frequencies ranges.	(b) (3)	(b) (3) (F76)
B26	This data has several multiple reflections and directionality due to weld geometry. There is one indication (Q1 at -460") that needs to be checked using other NDT methods. Perform field verification of signal to include local visual inspection at indication location and thickness test (Note: pipe warp may need to be removed if present).	(b) (3)	(b) (3) (JP5)
B27	This data has several multiple reflections and directionality due to weld geometry. There are two indications (Q1 at -976" and Q2 at -963") that need to be checked using other NDT methods. Perform field verification of signal to include local visual inspection at indication location and thickness test (Note: pipe warp may need to be removed if present).	(b) (3)	(b) (3) (F76)

## A.2.2 Introduction and Background:

This annex presents the work carried out and an analysis of data collected during the inspection conducted in April 2022 at Joint Base Pearl Harbor Hickam; Hawaii, under contract for Austin Brockenbrough & Associates LLC. The inspection was performed by certified MsS LRUT inspectors. The inspection was conducted by *InterSpec*, *LLC* 

## A2.3 Test Procedure:

LRUT pipe inspection is accomplished using the Magnetostrictive Sensor (MsS) System. The system is composed of the MsSR3030 instrument, MsS probes, and a laptop computer. MsS probes consist of deformed ferromagnetic strips and ribbon cables of appropriate size for the piping to be inspected. After selecting suitable test areas (typically small-bore piping and locations with cross sectional reduction), the pipe is cleaned with a moist rag to remove surface contaminants. The ferromagnetic strips are then applied using a wax-based shear couplant and held in place with tape. The assembled sensor ferromagnetic strip is then conditioned two to three times with an acoustic signal at a relatively constant speed of about 1 ft./sec. The appropriate 40 pin dual coil adapters are installed over the ferromagnetic strip. A 32, 45, 64, 90, and 128 kHz probes were used for this facility. Following all sensor installations, the data was recorded on the MSSR3030 system with a relative amplitude of 25% and 5000 kHz sampling in Pulse Echo Ultrasonic Mode. A repetition rate of 8 Hz and sampling average of five to ten cycles were selected for data acquisition.

Following the data acquisition, the plot is field analyzed for accuracy, signal amplitude, and range. Any immediate anomalies in the test are identified for further evaluation. Subsequent data analysis is performed using the MsS data analysis and reporting software.

COI

Table K - LRUT Evaluation Summary Table

CML.#	SdN	Product DATA	DATA	Inspection Area Zone	Sensor Location PS	Comments
-			Yes	Bulkhead	(p)	Piping tested satisfactory with no corrosion indication noted at the bulkhead penetration
GW B2	)	FOR	Bad	Trench at Door 5		Weak Signal
GW B2A		FOR	Bad	Trench at Door 5		Weak Signal
GW B3		28			20 100 100 100 100 100 100 100 100 100 1	Blank
GW B4		F76	Yes	Bulkhead	(p) (3)	Piping tested satisfactory with no corrosion indication noted at the bulkhead penetration.
GW B5		JP5	Yes	Bulkhead	(q)	Piping tested satisfactory with no corrosion indication noted at the bulkhead penetration.
GW B6		F24	Yes	Bulkhead	(b) (3)	Piping tested satisfactory with no corrosion indication noted at the bulkhead penetration. BUT: Note Q1 likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen in the adjacent pipe (GW–B7) within the bulkhead. There does appear to be an anchor plate welded inside the bulkhead located approximately 7" inside the bulkhead (Harbor tunnel side of bulkhead). The signal (M1) identified as the possible anchor ring is constant around the pipe and shows up in different clock position around the pipe. Review construction drawing is recommended to determine what M1 is.
		2				Piping tested satisfactory with a few unidentified indications noted in the bulkhead (Q2 @ +56", Q3 @ 74") and one location before the neutration (Q1 @ 17). Note Q2 is likely next of the analysis manner because highest magnitude is at the
						6 o'clock position and similar pattern seen in the adjacent pipe in other bulkhead. There is asbestos wrap in the positive
GW B7		JPS	Yes	Bulkhead	(p) (g)	direction (likely the creating signal Q1 but remove to verify). The anchor plates welded inside the bulkhead are located
						approximately 5" inside the bulkhead (Harbor tunnel side of bulkhead). The signal (M2) identified as the possible anchor
						ring is constant around the pipe and shows up in different clock position around the pipe. Review construction drawing is
						recommended to determine what M1 is. Small Indication at +74.75" ((0) (3) ) or 20" inside the bulkhead.
						Piping tested satisfactory with a few unidentified indications noted in the bulkhead (M1 @ +46.3", M2 @ 58.6", M3 @
						70.7" and M4 $(a, 84.8")$ and one location past the penetration (Q1 $(a, 107.3)$ ). Note M1 is likely part of the anchor/support
	ı					because highest magnitude is at the 6 o'clock position and similar pattern seen in other tests at this facility. This data also shows sionals generated by annex 12" inside the hulkhead and annears to be welds attaching to possibly rebar inside the
GW B8		F76	Yes	Bulkhead	(S) (G)	bulkhead. There is a failed asbestos wrap with some corrosion noted past the bulkhead (tank gallery side) in the positive
						direction (creating signal at Q1 (7" past the bulkhead; but remove wrap to verify). The anchor plates welded inside the
						bulkhead are located approximately 6" inside the bulkhead (Harbor tunnel side of bulkhead). Review construction drawing
						is recommended to determine what M1-M4 are. Follow-up with wrap removal recommended.
GW B9		F24	Yes	Bulkhead	(b) (3)	Multiple welds in close proximity to each other is producing directionality and multiple reflection signals but no indication was noted at the area of interest within the bulkhead. The metal ring weld around the pipe is noted as M1 and M2. There is coating failure and surface corrosion at the [D] (3) [Pumphouse side) penetration but no reportable indication on LRUT.
GW B10	)	JPS	Yes	Bulkhead	(b) (d)	JP-5 line (D) through pipe sleeve. The pipe sleeve is approx. 58" long. There is a metal ring on the pipe at the tank side that is tack welded (+24") and (+82"). Both rings welded on the pipe are visible at the bulk head penetrations. There one welded pipe nipple on -85"
GW B11	_	F76	Yes	Bulkhead	(b) (d)	There are large plates seal welded (Anchor) to both sides of bulkhead and multiple welds in close proximity to the sensor creating directionality and multiple reflection signals.
GW B12		F76	yes	Saddle	(b) (3)	Ok. No indication is found within the inspection range.
GW B13	_	F24	Yes	Bulkhead	(b) (4),	Ok. No indication is found within the inspection range.

2
20
$\mathbf{x}$
7
$\vec{\leq}$
7
9
$\leq$
4
$\mathbf{F}$
Ľ.
$\subseteq$
$\exists$
$\mathcal{L}$
Υ.
$\Gamma$
3
≓
=
궄
$\overline{z}$
<u> </u>
I
Į.
茔
<u>.</u>
<u>m</u>
₹
Ξ

,			;			
GW B14		JP5	Yes	Bulkhead	(c) (d)	OK. No indication is found within the inspection range.
GW B15		F76	Yes	Bulkhead	(b)(3)	Ok. No indication is found within the inspection range.
GW B16		F76	Yes	Saddle		No indication is found within the inspection range other than the corrosion area located 447" to 467" from sensor is visible on lower frequencies (see report body for UTT and pit sizes)
GW B17		F24	Yes	Pipe	(b) (3)	One location of defect later identified as inactive pitting (approx. 0.050") with some large area of scaling but minimal metal loss. Two area of possible similar magnitude of pitting on some frequency seen under pipe wrap. Wrap removal required to get exact size of pitting depth (marked as M1 and M2).
GW B18		JP5	Yes	Pipe	(b) (3)	Ok. No indication is found within the inspection range.
GW B19		F24	Yes	Pipe	(b) (3)	No indication is found within the inspection range other than the corrosion area located near pipe support 290 (-480" from sensor) is visible on multiple frequencies (see report body for UTT and pit sizes).
GW B20		JP5	Yes	Bulkhead & Pipe	(b) (3)	No indication is found within the inspection range other than the corrosion area located near (b) (3) (A) (at - 258" and -195" from sensor) is visible on multiple frequencies (see report body for UTT and pit sizes)
GW B21		F76	Yes	Bulkhead & Saddle	(p) (3)	Multiple welds in close proximity to each other is producing directionality and multiple reflection signals but one confirmed indication detected at 402" to 411" on this pipe. There is also one indication identified underneath a concrete saddle support (Saddle # 195) that requires prove up (visual, thickness and pit inspection) after pipe is lifted off the saddle support. Indication at saddle area was noted on all frequencies ranges.
						Piping tested satisfactory with a few unidentified indications noted in the bulkhead (M1 @ $+93.47$ " and M2 @ $+107.5$ "). Note M1 is likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen
GW B22		F24	Yes	Bulkhead	(b) (3)	in other tests at this facility. This data also shows the signals separated by approx. 14" inside the bulkhead and appears to be welds attaching to possibly rebars or other anchor plates inside the bulkhead. The anchor plates welded inside the bulkhead are located approximately 6.5" inside the bulkhead (Tank gallery side of bulkhead). Review construction drawing is recommended to determine what M1 – M2 are. The section of piping can remain in-service.
GW B23		JPS	Yes	Bulkhead & Saddle	(p) (g)	drawing is recommended to determine what $M1 - M2$ are. The section of piping can remain in-service. Piping tested satisfactory with a few unidentified indications noted in the bulkhead ( $M1$ @ $+90$ " and $M2$ @ $+104$ "). Note $M1$ is likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen in other tests at this facility. This data also shows the signals separated by approx. 14" inside the bulkhead and appears to be welds attaching to possibly rebars or other anchor plates inside the bulkhead. The anchor plates welded inside the bulkhead are located approximately 6" inside the bulkhead (Tank gallery side of bulkhead). Review construction drawing is recommended to determine what $M1 - M2$ are. The section of piping can remain in-service.
GW B24		F76	Yes	Bulkhead & Saddle	(b) (3)	Piping tested satisfactory with a few unidentified indications noted in the bulkhead (M1 @ +107", M2 @ 122", M3 @ 137"). Note M1 is likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen in other tests at this facility. This data also shows the signals separated by approx. 15" inside the bulkhead and appears to be welds attaching to possibly rebars or other anchor plates inside the bulkhead. The anchor plates welded inside the bulkhead are located approximately 4.5" inside the bulkhead (Tank gallery side of bulkhead). Review construction drawing is recommended to determine what M1 – M3 are. The section of piping can remain in-service.
GW B25		F24	Yes	Pipe	(b) (3)	Ok. No indication is found within the inspection range.
GW B26	)	JP5	Yes	Pipe	(p) (g)	This data has several multiple reflections and directionality due to weld geometry. There is one indication (Q1 at -460") need to be checked using other NDT methods. Perform field verification of signal to include local visual inspection at indication location and thickness test (Note: pipe warp may need to be removed if present).
GW B27		F76	Yes	Pipe	(p) (3)	This data has several multiple reflections and directionality due to weld geometry. There are two indications (Q1 at -976" and Q2 at -963") need to be checked using other NDT methods. Perform field verification of signal to include local visual inspection at indication location and thickness test(Note: pipe warp may need to be removed if present).

## ER-JBPHH,HI-RED HILL FACILITY-PIPING-MAY/2022

GW B28	9	FOR	No	Pipe	Below ADIT 3 Door	3 Door Weak Signal
GW B29	9	FOR	Yes	Pipe	Outside ADIT 3	Outside ADIT 3 Limited and has high S/N in the inspection range. Do other NDE (Borescope and CP survey)
GW B30		F24	Yes	Bulkhead below Door	Surge Tank to UGPH	Surge Tank to UGPH Ok. No indication is found within the inspection range.
GW B31	<u> </u>	JP5	Yes	Bulkhead below Door	Surge Tank to UGPH	Surge Tank to UGPH Ok. No indication is found within the inspection range.
GW B32	)	JP5	Yes	Ceiling Penetration Surge Tank		Ceiling Ok. No indication is found within the inspection range.

## Note:

- SAI = Soil-to-air interface
   CAI = Concrete-to-air interface
   See in CML locations in Appendix C (Drawings)



464 S Independence Blvd, C-104 Virginia Beach, VA 23452 (757) 622-6299 www.interspecllc.net

GW-B1

## MsS Guided Wave Testing Report

Site: RH PPG Date: 23-Mar-2022

Pipe ID/Location: GW-B1 GWT System: MsSR3030R 53100
Pipe Size: (b) (3) (A) , 0.392-inch-wall Analysis S/W: MsSPipe-V3.00
Inspector: (b) (6) Wave Mode: Torsional Mode

Analyzer: (b) (6) Velocity: (b) (3) (A)

Client: AB&A Refl. % Ref.: 1) W6, 13.0%; 2) W6, 15.0%

Procedure: GWA 1.01 Attenuation: 1) 0.004 dB/inch Inspection Range: -874.9 to 363.9 inch 2) 0.004 dB/inch

Threshold Level: 1) 2.0%(-995.6 ~ 995.8) 2) 2.0%(-991.8 ~ 992.1)

Test Pipe: Aboveground; Painted; 7.860000e+01 F F-76 (Diesel)-carrying pipe; 0.390, 0.392, 0.393,

0.394-inch wall; Supported with Carbon Steel

Note: ~F-76 (b) (3) line between (b) (3) (A) . Inspection zone is 60: bulkhead penetration.

Bulkhead is 40.25" from sensor. The positive weld is a Bell-Bell Weld (BBW) with Dresser


Coupling located past the BBW at approximately 147"

Summary: ~Piping tested satisfactory with no corrosion indication noted at the bulkhead


penetration. There are multiple reflections generated due to several welds within few feet of each other. The section of piping can remain in-service. There does appear to be a anchor plate welded inside the bulkhead located approximately 12" inside the bulkhead.


Sym.	Dist.(inch)	% Refl.	Comment
Y1	-874 92	3.1	Multiple Reflection;  MsS-X =874 92; W2-W5-W4 (875.4, 0.11)
W1	-849.76	4.8	Weld;
W2	-828.19	10.4	Weld;
W3	-586.32	5.8	Weld;
Y2	-410 35	35	Multiple Reflection;  MsS-X =410 35; W4-W5-W4 (408.6, 0 05)
W4	-361.35	5.1	Weld;
W5	-314.13	20.6	Weld;
Y3	-161 23	2.4	Multiple Reflection;  MsS-X =161 23; W6-PS1 (159.8, 1 66)
W6	-107.00	15.0	Weld;
X1	-53.66	45	Directionality;  MsS-X =53 66; PS1 (52.8, 3.78)
X2	-53.66	45	Directionality;  MsS-X =53 66; PS1 (52.8, 3.78)
MsS1	0.00	520.60	Initial Pulse;
(b)	52.84	13.8	Pipe Support; Pipe anchor (welded plate) inside bu khead
Х3	108.83	45	Directionality;  MsS-X =108.83; W6 (107.0, 4.10)
S1	161.67	1.9	Spacer; End of Pipe (inside Dresser Coupling)











GW-B1; Concrete penetration (bulkhead inspection); (Area = Between (b) (3) (A)

## Inter Spec LLC

Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net



GW-B4

Date: 23-Mar-2022

Refl. % Ref.: 1) W3, 6.3%; 2) W3, 22.2%

2) 0.015 dB/inch

GWT System: MsSR3030R 53100

Analysis S/W: MsSPipe-V3.00 Wave Mode: Torsional Mode

Velocity: (b) (3) (A

Attenuation: 1) 0.003 dB/inch

### MsS Guided Wave Testing Report

Site: RH PPG Pipe ID/Location: GW-B4

Pipe Size: (b) (3) (A)

e: (b) (3) (A) , 0.392-inch-wall

Inspector: (b) (6)
Analyzer: (b) (6)

Client: AB&A

Procedure: GWA 1.01

Inspection Range: -489.7 to 488.5 inch Threshold Level: 1) 0.6%(-498.7 ~ 498.8)

2) 2.0%(-496.9 ~ 497.1)

Test Pipe: Aboveground; Painted; 80 F JP-5-carrying pipe; 0.235, 0.232, 0.235, 0.245-inch wall;

Supported with Carbon Steel

Note: ~F-76 (b) (3) ) line between (b) (3) (A) (the steel pipe). Inspection zone is 48:

bulkhead penetration. Bulkhead is 89" form sensor. The positive weld is a Bell-Bell Weld (BBW). Negative weld is regular butt weld located at -72" and -288 and 295". Welded

branch at 208".

Summary: ~Piping tested satisfactory with no corrosion indication noted at the bulkhead


penetration. There are multiple reflections generated due to several welds within few feet of each other. The section of piping can remain in-service. There does appear to be an anchor plate welded inside the bulkhead located approximately 17" inside the bulkhead

(b) (3) side). The signal (M1) identified as the possible anchor ring is constant around the pipe and shows up in different clock position around the pipe. Review of the


2017 bulkhead repair/construction is recommended to determine what M1 is.


Sym.	Dist.(inch)	% Refl.	Comment
F1	-368.55	1.1	Flange;
Y1	-357 04	5.4	Multiple Reflection;  MsS-X =357 04; W1-??-W3 (357 9, 2.23)
Y2	-352 36	36	Multiple Reflection; [MsS-X]=352 36; ??-W4 (353.0, 9.12)
X1	-344 53	43	Directionality; [MsS-X =344.53; W4 (343.7, 4.99)
Y3	-324.44	23	Multiple Reflection;  MsS-X =324.44; W2-PS4 (326.5, 1 04)
W1	-295.00	19.6	Weld;
W2	-288.30	33.5	Weld;
TC1	-279.35	0.7	T-Connection; Branch pipe connection
PS1	-187.36	1.3	Pipe Support; Welded pipe saddle support
PS2	-175.87	2.2	Pipe Support; Welded pipe saddle support
Y4	-107.75	45	Multiple Reflection;  MsS-X =107.75; M1 (106.4, 2.67)
Y5	-85.27	0.7	Multiple Reflection;  MsS-X =85.27; MsS1-W3-MsS1 (83.8, 2.43)
W3	-72.24	22.2	Weld;
MsS1	0.00		Initial Pulse;
(b)	26.99	1.3	Pipe Support; Welded pipe saddle support
Y6	30.28	0.7	Multiple Reflection;  MsS-X =30.28; PS3-MsS1 (31 3, 1.27)
(b)	38.19	3.9	Pipe Support; Welded pipe saddle support
X2	73.69	42	Directionality;  MsS-X =73 69; W3 (72 2, 5.00)
M1	106.42	877.	Marker, Poss ble anchor ring welded on the pipe
Х3	289.88	59	Directionality;  MsS-X =289.88; W2 (288.3, 7.55)
Y7	296.58	3.1	Multiple Reflection;  MsS-X =296 58; ??-W2 (297.7, 13.17)
W4	343.71	22.2	Weld; Bell-Bell Weld (BBW)
Y8	349.44	12	Multiple Reflection;  MsS-X =349.44; W4-MsS1 (349.2, 2 06)
Y9	354.12	0.7	Multiple Reflection;  MsS-X =354.12; W4-MsS1-MsS1 (354 9, 2.46)
Y10	393.74	3.1	Multiple Reflection;  MsS-X =393.74; M1-W2 (394.7, 3.18)
Y11	416.61	39	Multiple Reflection; [MsS-X]=416 61; W4-W3 (416 0, 3.94)











## Inter Spec LLC

 $\overline{\mathbb{S}}$ 

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Fax: 757-622-9103 Office: 757-622-6299

Toll Free: 800-546-7853

GW-B4; Concrete penetration at Oil Tight Door (bulkhead inspection); (Area = Between (b) (3) (A)



GW-B5

Date: 23-Mar-2022

Refl. % Ref.: 1) W2, 25.4%; 2) W2, 47.6%

2) 0.031 dB/inch

GWT System: MsSR3030R 53100

Analysis S/W: MsSPipe-V3.00 Wave Mode: Torsional Mode

Velocity: (b) (3) (A)

Attenuation: 1) 0.037 dB/inch

### MsS Guided Wave Testing Report

Site: RH PPG

Pipe ID/Location: GW-B5

Pipe Size: (b) (3) (A) Inspector: (b) (6)

(3) (A) , 0.250-inch-wall

Analyzer:

Client: AB&A

Procedure: GWA 1.01

Inspection Range: -193.4 to 200.6 inch

Threshold Level: 1) 3.0%(-160.0 ~ 160.1)

2) 3.0%(-110.1 ~ 110.0)

Test Pipe: Aboveground; Painted; 80 F JP-5-carrying pipe; 0.235, 0.235, 0.235, 0.245-inch wall;

Supported with Carbon Steel

Note: ~JP-5 (b) (3) ) line between (b) (3) (A) . Inspection zone is the 48" bulkhead

penetration. Bulkhead is 60" from sensor. This LRUT data is looking up to the tank gallery with the positive weld at approx. 172" as a standard weld and the negative weld is Bell-Bell Weld (BBW) weld located at -26" and a tack welded plate between pipe and

(b) (3) (A) at -127".


Summary: ~Piping tested satisfactory with no corrosion indication noted at the bulkhead

penetration. There are multiple reflections generated due to several welds within few feet of each other. The section of piping can remain in-service. There does appear to be an anchor plate welded inside the bulkhead located approximately 14" inside the bulkhead (Harbor tunnel side of bulkhead). The signal (M1) identified as the possible anchor ring is constant around the pipe and shows up in different clock position around the pipe. Review of the 2017 bulkhead repair/construction is recommended to determine what


M1 is.


Sym.	Dist.(inch)	% Refl.	Comment
F1	-193.36	23.0	Flange;
W1	-187.71	47.3	Weld;
Y1	-145 68	18.1	Multiple Reflection;  MsS-X =145 68; W2-M1-W2 (145.2, 3.47)
Y2	-120 01	11.6	Multiple Reflection;  MsS-X =120 01; W2-M1 (119.9, 5 82)
W2	-25.26	47.6	Weld; BBW
MsS1	0.00		Initial Pulse;
M1	94.66	<u> </u>	Marker; Poss ble anchor welded on the pipe inside bulkhead
Y3	121.10	43	Multiple Reflection;  MsS-X =121.10; M1-W2 (119.9, 5 82)
W3	173.18	49.9	Weld;













### Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Fax: 757-622-9103

Office: 757-622-6299

Toll Free: 800-546-7853

GW-B5; Concrete penetration at Oil Tight Door (bulkhead inspection); (Area = Between (b) (8) (A)



GW-B6

Date: 24-Mar-2022

Refl. % Ref.: 1) W1, 15.0%; 2) W1, 15.0%

2) 0.004 dB/inch

GWT System: MsSR3030R 53100

Analysis S/W: MsSPipe-V3.00 Wave Mode: Torsional Mode

Attenuation: 1) 0.030 dB/inch

Velocity: 1

### MsS Guided Wave Testing Report

Site: RH PPG
Pipe ID/Location: GW-B6

Pipe Size: (b) (3) (A)

Inspector: (b) (6)

Analyzer: (b) (6)

Client: AB&A

Procedure: GWA 1.01

Inspection Range: -113.4 to 37.9 inch

Threshold Level: 1) 2.0%(-594.1 ~ 594.2)

2) 2.0%(-594.3 ~ 594.5)

Test Pipe: Aboveground; Painted; 8.010000e+01 F JP-5-carrying pipe; 0.239, 0.236, 0.242, 0.240-inch

wall; Supported with Carbon Steel

0.250-inch-wall

Note: ~F24 (b) (3) ) line between (b) (3) (A) at anchor bulkhead. Inspection is the 60"

bulkhead penetration. Penetration is 30" from sensor. The negative weld is a Bell-Bell

Weld (BBW) at -113".


Summary: ~Piping tested satisfactory with no corrosion indication noted at the bulkhead

penetration. Note Q1 is likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen in the adjacent pipe (GW-B7) within the bulkhead There are multiple reflections generated due to several welds within few feet of each other. The section of piping can remain in-service. There does appear to be an anchor plate welded inside the bulkhead located approximately 7" inside the bulkhead (Harbor tunnel side of bulkhead). The signal (M1) identified as the possible anchor ring is constant around the pipe and shows up in different clock position around the


pipe. Review construction drawing is recommended to determine what M1 is.


Sym.	Dist.(inch)	% Refl.	Comment
W1	-113.39	15.0	Weld; BBW
MsS1	0.00		Initial Pulse;
M1	37.86	5 <u>10-90</u> 5	Marker; Poss ble anchor welded on the pipe inside bulkhead
Q1	55.29	0.7	Indication; 26.4-%;
Y1	113.45	0.8	Multiple Reflection;  MsS-X =113.45; W1 (113.4, 1 60)











GW-B6; Concrete penetration at bulkhead; (Area = Between (b) (3) (A)

# Inter Spec LLC Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

www.interspecllc.net



GW-B7

### **MsS Guided Wave Testing Report**

Site: RH PPG Date: 24-Mar-2022

Pipe ID/Location: GW-B7
Pipe Size: (b) (3) (A) , 0.250-inch-wall
Inspector: (b) (6)

GWT System: MsSR3030R 53100
Analysis S/W: MsSPipe-V3.00
Wave Mode: Torsional Mode

Analyzer: (b) (6) Velocity: 1(b) (3) (A)

Client: AB&A Refl. % Ref.: 1) W1, 15.0%; 2) M2, 15.0%

Procedure: GWA 1.01 Attenuation: 1) 0.101 dB/inch Inspection Range: -205.9 to 401.7 inch 2) 0.066 dB/inch

Threshold Level: 1) 1.4%(-111.1 ~ 111.2); 2.0%(-137.6 ~ -111.1;111.2 ~ 137.5); 5.0%(-207.0 ~ -137.6;137.5 ~ 206.9)

2) 2.1%(-140.0 ~ 140.1); 5.0%(-203.0 ~ -140.0;140.1 ~ 203.0)

Test Pipe: Aboveground; Painted; 8.010000e+01 F JP-5-carrying pipe; 0.239, 0.236, 0.242, 0.240-inch

wall; Supported with Carbon Steel

Note: ~JP5 (b) (3) line between P(b) (3) (A) at anchor penetration. Inspection zone is 60"

penetration. Penetration is 35" from sensor, weld is a Bell-Bell Weld (BBW) at -109". Two small dents were identified on positive side past wall at 195" and 209". One dent is

field identified in the negative side -11"


Summary: ~Piping tested satisfactory with a few unidentified indications noted in the bulkhead

(Q2 @ +56", Q3 @ 74") and one location before the penetration (Q1 @ 17). Note Q2 is likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen in the adjacent pipe (GW-B6) within the bulkhead. There is asbestos wrap in the positive direction (likely the creating signal Q1 but remove to verify). The section of piping can remain in-service. The anchor plates welded inside the bulkhead are located approximately 5" inside the bulkhead (Harbor tunnel side of bulkhead). The signal (M2) identified as the possible anchor ring is constant around the pipe and shows up in different clock position around the pipe. Review construction drawing is recommended to determine what M1 is. Small Indication at +74.75" (PS 135)


side) or 20" inside the bulkhead.

Sym.	Dist.(inch)	% Refl.	Comment
(b)	-183.73	6.3	Pipe Support; Tack Weld
W1	-109.00	15.0	Weld; BBW
M1	-11.68	<u> </u>	Marker; Dent C @ -11"
MsS1	0.00		Initial Pulse;
Q1	17.09	5.0	Indication; 98.7–%;
M2	40.35		Marker; Poss ble anchor welded on the pipe inside bulkhead
Q2	56.46	1.8	Indication; 50.2–%;
Q3	74.75	2.2	Indication; 57.9-%;
X1	111.67	2.1	Directionality;  MsS-X =111.67; W1 (110.8, 5.19)
M3	196.69		Marker; Dent B @ -195"
M4	206.56	F <u>35384</u>	Marker; Dent A @ -209"
Y1	401.75	94.9	Multiple Reflection;  MsS-X =401.75; ??-??-?? (401.4, 63.89)









Distance (inch)

## Inter Spec LLC


Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299

Fax: 757-622-9103

Toll Free: 800-546-7853





GW-B8

Date: 24-Mar-2022

### MsS Guided Wave Testing Report

Site: RH PPG
Pipe ID/Location: GW-B8 GW

O/Location: GW-B8
Pipe Size (b) (3) (A) , 0.396-inch-wall
Inspector: (b) (6)

GWT System: MsSR3030R 53100
Analysis S/W: MsSPipe-V3.00
Wave Mode: Torsional Mode

Analyzer: (b) (6) Velocity: (b) (3) (A)

Client: AB&A Refl. % Ref.: 1) W3, 7.4%; 2) W3, 26.1%

Procedure: GWA 1.01 Attenuation: 1) 0.039 dB/inch

Inspection Range: -501.0 to 401.5 inch 2) 0.027 dB/inch

Threshold Level: 1)  $2.0\%(-262.5 \sim 262.5)$ ;  $4.0\%(-414.3 \sim -262.5;262.5 \sim 414.4)$ 2)  $2.5\%(-302.7 \sim 302.8)$ ;  $4.0\%(-371.5 \sim -302.7;302.8 \sim 371.4)$ 

Test Pipe: Aboveground; Painted; 8.020000e+01 F F76-carrying pipe; 0.394, 0.369, 0.385, 0.396-inch

wall; Supported with Carbon Steel

Note: ~F76 ((b) (3) ) line between (b) (3) (A) (b) (3) (A) ) at anchor

penetration. Inspection zone is 60" wall penetration. Penetration is 40" from sensor.

the negative weld is a BBW at -103". Positive butt weld at 137".


Summary: ~Piping tested satisfactory with a few unidentified indications noted in the bulkhead

(M1 @ +46.3", M2 @ 58.6", M3 @ 70.7" and M4 @ 84.8) and one location past the penetration (Q1 @ 107.3). Note M1 is likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen in other tests at this facility. This data also shows signals separated by approx. 12" inside the bulkhead and appears to be welds attaching to possibly rebar inside the bulkhead. There is a failed asbestos wrap with some corrosion noted past the bulkhead (tank gallery side) in the positive direction (creating signal at Q1 (7" past the bulkhead but remove to verify). The anchor plates welded inside the bulkhead are located approximately 6" inside the bulkhead (Harbor tunnel side of bulkhead). Review construction drawing is recommended to determine what M1 – M4 are. The section of piping can remain in–service but


follow-up with wrap removal recommended.


Sym.	Dist.(inch)	% Refl.	Comment
W1	-505.56	27.6	Weld;
(b)	-400.71	5.4	Pipe Support; Welded Saddle
W2	-345.74	13.2	Weld;
Y1	-257 09	3.4	Multiple Reflection;  MsS-X =257 09; W3-M1-W3 (250.0, 1.18)
Y2	-154.15	29	Multiple Reflection;  MsS-X =154.15; W3-M1 (148.0, 3 60)
Y3	-116.70	33	Multiple Reflection;  MsS-X =116.70; Y3-MsS1 (116.0, 0.33)
W3	-103.00	26.1	Weld; BBW
MsS1	0.00	-	Initial Pulse;
M1	46.30	9 <del>70.00</del> 3	Marker; Marker; Possible anchor welded on the pipe inside bulkhead
M2	58.55		Marker; M1 to M2 (approx. 12")
МЗ	70.67	[ <u>7588</u> ]	Marker; M2 to M3 (approx. 12")
M4	84.78		Marker; M3 to M4 (approx. 12")
Q1	107.27	6.4	Indication; Corrosion Area at 6 o'clock
W4	139.75	0.8	Weld;
Y4	348.10	4.1	Multiple Reflection;  MsS-X =348.10; W2 (342.6, 2 23)











GW-B8; Concrete penetration at bulkhead; (Area = Between (b) (3) (A)

# Inter Spec LLC Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853



GW-B9 (SP8) 6OC

### **Guided Wave Inspection Report**

Site: RH PPG

Pipe ID/Location: GW-B9 (SP8) 6OC

Pipe Size:

Inspector: Analyzer:

Client: AB&A (US Navy)

, 0.373-inch-wall

Procedure: GWA 4.01 Wave Mode: Torsional Mode Inspection Range: -297.6 to 282.7 inch

Analysis S/W: V4.1

Date: 25-Mar-2022

GWT System: MsSR3030R 8C00

Test Pipe: Aboveground; Painted; 80°F F24-carrying pipe; 0.376, 0.380, 0.376, 0.376-inch wall; Supported

with Steel

Note:


Summary: Multiple welds in close proximity to each other is producing directionality and multiple reflection signals but no indication was noted at the area of interest within the bulkhead. The metal ring


weld around the pipe is noted as M1 and M2.

Sym.	Dist.(inch)	% Refl.	Comment
X1	-265.14	3.3	Directionality;  MsS-X =265.14; W6 (265.21, 2.27)
(b)	-257.82	18.5	Pipe Support;
Y1	-245.77	13.6	Multiple Reflection;  MsS-X =245.77; Y5-W5 (246.03, 2.53)
W1	-185.64	9.3	Weld;
Y2	-159.00	6.1	Multiple Reflection;  MsS-X =159.00; W2-W5-W2 (159.00, 0.40)
Y3	-146.01	15.4	Multiple Reflection;  MsS-X =146.01; W2-TC2 (146.50, 2.27)
Y4	-136.80	7.5	Multiple Reflection;  MsS-X =136.80; W2-W5 (135.77, 2.03)
Y5	-132.79	10.7	Multiple Reflection;  MsS-X =132.79; W2-W5 (135.08, 1.86)
Y6	-123.78	12.9	Multiple Reflection;  MsS-X =123.78; TC2 (123.81, 2.41)
Y7	-119.53	2.8	Multiple Reflection;  MsS-X =119.53; W3-W5 (121.85, 1.95)
X2	-114.57	2.6	Directionality;  MsS-X =114.57; W5 (112.24, 2.88)
X3	-110.79	6.0	Directionality;  MsS-X =110.79; W5 (113.24, 4.80)
X4	-100.64	3.5	Directionality;  MsS-X =100.64; W4 (99.26, 2.81)
TC1	-87.18	1.8	T-Connection;
W2	-23.11	19.7	Weld;
W3	-10.00	15.4	Weld;
MsS1	0.00	<u> </u>	Initial Pulse;
X5	10.53	3.0	Directionality;  MsS-X =10.53; W3 (9.61, 2.81)
Mk1	23.51	-	Marker; Metal ring tack welded (anchor?)
Mk2	77.41		Marker, Metal ring tack welded (anchor?)
W4	99.45	15.4	Weld;
W5	113.24	25.7	Weld;
TC2	123.39	12.5	T-Connection;
Y8	146.89	6.1	Multiple Reflection;  MsS-X =146.89; TC2-W2 (146.50, 2.27)
X6	235.32	23.4	Directionality;
W6	264.36	161.2	Weld;




GW-B9 (SP8) 6OC



















# Inter Spec LLC Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Fax: 757-622-9103 Toll Free: 800-546-7853

Office: 757-622-6299

GW-B9; Concrete penetration at bulkhead; (Area = Between (b) (3) (A)

Site: RH PPG Date: 25-Mar-2022
Pipe ID/Location: GW-B10 GWT System: MsSR3030R 8C00

Pipe Size: (b) (3) (A) , 0.375-inch-wall Analysis S/W: V4.1 Procedure: GWA 4.01 Wave Mode: Torsional Mode
Client: AB&A (US Navy) Inspection Range: -352.2 to 333.5 inch

Test Pipe: Aboveground; Painted; 80°F JP-5-carrying pipe; 0.362, 0.370, 0.336, 0.361-inch wall; Supported

with Steel

Note:

Summary: Multiple welds in close proximity to each other is producing directionality and multiple reflection


signals but no indication was noted at the area of interest within the bulkhead. The metal ring


weld around the pipe is noted as M1 and M2.


Sym.	Dist.(inch)	% Refl.	Comment
Y1	-178.84	5.7	Multiple Reflection;  MsS-X =178.84; W3-Y8 (178.61, 0.80)
Y2	-174.31	6.9	Multiple Reflection;  MsS-X =174.31; W2-W5 (173.84, 3.34)
W1	-160.13	11.6	Weld;
(b)	-145.46	4.0	Pipe Support;
X1	-141.79	4.2	Directionality;  MsS-X =141.79; W5 (140.13, 3.65)
X2	-127.24	2.8	Directionality;  MsS-X =127.24; W4 (125.58, 2.71)
TC1	-84.66	8.0	T-Connection; Q18 (85.74, 0.35);
Y3	-48.62	1.9	Multiple Reflection;  MsS-X =48.62; W2-W3-W2 (48.75, 0.89)
W2	-34.08	24.4	Weld;
W3	-19.40	15.0	Weld;
MsS1	0.00		Initial Pulse;
MsS2	0.00	2500	Initial Pulse; Metal ring tack welded (anchor?)
X3	19.97	1.4	Directionality;  MsS-X =19.97; W3 (19.40, 1.69)
Mk1	23.86	-	Marker; Metal ring tack welded (anchor?)
Y4	26.98	2.3	Multiple Reflection;  MsS-X =26.98; W2 (33.79, 1.83)
X4	34.64	2.2	Directionality;  MsS-X =34.64; W2 (34.08, 2.74)
Mk2	82.30	(21V2)	Marker; Metal ring tack welded (anchor?)
Y5	85.74	3.1	Multiple Reflection;
X5	88.68	2.2	Directionality;
X6	91.37	1.3	Directionality;
W4	125.77	20.2	Weld;
W5	140.20	26.2	Weld;
Y6	144.90	4.3	Multiple Reflection;  MsS-X =144.90; W4-W3 (144.77, 1.75)
Y7	154.93	3.0	Multiple Reflection;  MsS-X =154.93; W5-W4-W5 (154.63, 1.38)
Y8	159.35	8.7	Multiple Reflection;  MsS-X =159.35; W4-W2 (159.29, 2.48)
Y9	174.14	7.9	Multiple Reflection;  MsS-X =174.14; W5-W2 (173.84, 3.34)
Y10	285.77	10.0	Multiple Reflection;  MsS-X =285.77; W4-W1 (285.62, 1.14)
Y11	299.20	11.6	Multiple Reflection;  MsS-X =299.20; W5-W1 (300.05, 1.48)


GW-B10














Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853

GW-B10; Concrete penetration at bulkhead; (Area = Between (b) (3) (A)

Site: RH PPG Date: 25-Mar-2022
Pipe ID/Location: GW-B11 GWT System: MsSR3030R 8C00

Pipe Size: (b) (3) (A) , 0.375-inch-wall Analysis S/W: V4.1
Inspector: (b) (6) Procedure: GWA 4.01
Wave Mode: Torsional Mode
Client: Guided Wave Analysis LLC Inspection Range: -103.2 to 118.4 inch

Test Pipe: Aboveground; Painted; 80°F F76-carrying pipe; 0.376, 0.378, 0.376, 0.371-inch wall; Supported

with Steel

Note: Note no indication in the negative pipe support as notedd on teh last GW


Summary: There are large plates seal welded (Anchor) to both sides of bulkhead and multiple welds in close


proximity to the sensor creating directionality and multiple reflection signals. No indication is


found within the inspection range.


<u> </u>			
Sym.	Dist.(inch)	% Refl.	Comment
W1	-247.58	6703.1	Weld;
Y1	-103.24	8.8	Multiple Reflection;
X1	-66.93	7.1	Directionality;
Y2	-43.21	9.5	Multiple Reflection;
W2	-24.78	15.0	Weld;
X2	-19.77	8.5	Directionality;  MsS-X =19.77; Mk1 (17.75, 9.90)
MsS1	0.00	2000	Initial Pulse;
Mk1	17.75		Marker; Large plate seal welded (Anchor)
Y3	30.22	8.3	Multiple Reflection;  MsS-X =30.22; W2 (24.50, 3.03)
X3	42.20	9.6	Directionality;  MsS-X =42.20; Y2 (43.21, 4.10)
X4	60.73	5.1	Directionality;
Mk2	77.90		Marker; Large plate seal welded (Anchor)
W3	220.83	667.1	Weld:


GW-B11











www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853

GW-B11; Concrete penetration at bulkhead; (Area = Between (b) (3) (A)

 Site: RH PPG
 Date: 17-Oct-2018

 Pipe ID/Location: GW-B12
 GWT System: MsSR3030R 8C00


Test Pipe: Aboveground; Painted; 80°F F76-carrying pipe; 0.435, 0.439, 0.440, 0.424-inch wall; Supported


with Steel


Note:


Summary: No indication is found within the inspection range.


Sym.	Dist.(inch)	% Refl.	Comment
W1	-1027.71	12.0	Weld;
Y1	-957.49	11.7	Multiple Reflection;  MsS-X =957.49; W2-GF3 (958.10, 1.14)
W2	-782.14	43.5	Weld;
X1	-718.31	5.7	Directionality;  MsS-X =718.31; ?? (717.74, 4.11)
W3	-543.05	15.1	Weld;
Y2	-487.36	7.5	Multiple Reflection;  MsS-X =487.36; GF1-GF3 (481.00, 1.59)
Y3	-478.01	12.6	Multiple Reflection;  MsS-X =478.01; ?? (476.69, 8.59)
Y4	-315.39	16.3	Multiple Reflection;  MsS-X =315.39; X2-GF1-X2 (317.02, 1.49)
X2	-311.51	21.8	Directionality;  MsS-X =311.51; GF1-W4-GF1 (311.51, 1.02)
GF1	-306.00	31.3	Geometric Feature; Bell
W4	-302.66	19.9	Weld; W5-Q6 (321.38, 0.49);
Y5	-240.96	3.7	Multiple Reflection;  MsS-X =240.96; W5-W6 (237.28, 2.27)
X3	-177.91	1.0	Directionality;  MsS-X =177.91; GF3 (175.93, 1.93)
X4	-172.74	3.1	Directionality;  MsS-X =172.74; W6 (171.17, 5.45)
X5	-164.82	2.1	Directionality;  MsS-X =164.82; GF2 (168.36, 2.36)
W5	-65.57	14.0	Weld;
MsS1	0.00	-	Initial Pulse;
X6	67.29	5.3	Directionality;  MsS-X =67.29; W5 (66.11, 5.62)
GF2	168.36	8.7	Geometric Feature;
W6	171.55	11.5	Weld;
GF3	174.62	13.1	Geometric Feature;
Y6	238.63	3.2	Multiple Reflection;  MsS-X =238.63; W6-W5 (238.16, 2.37)
Y7	243.64	2.5	Multiple Reflection;  MsS-X =243.64; W6-W5 (238.16, 2.24)
X7	306.22	12.1	Directionality;  MsS-X =306.22; W4 (302.66, 11.22)
X8	544.09	6.9	Directionality;  MsS-X =544.09; W3 (543.84, 5.62)
X9	547.90	6.3	Directionality;  MsS-X =547.90; W3 (546.59, 5.01)
X10	782.70	15.1	Directionality;  MsS-X =782.70; W2 (782.14, 18.54)
X11	1020.75	5.9	Directionality;  MsS-X =1020.75; W1 (1021.70, 5.91)











Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853

GW-B12; General pipe and saddle inspection; (Area = Between (b) (3) (A)

Site: RH PPG Date: 17-Oct-2018

Pine ID/Location: GW-R13 GWT System: MsSR3030R 8C

Pipe ID/Location: GW-B13 GWT System: MsSR3030R 8C00 Pipe Size: (b) (3) (A) 0.250-inch-wall Analysis S/W: V4.1

Inspector: (b) (6)
Analyzer: (b) (6)
Client: Guided Wave Analysis LLC
Procedure: GWA 4.01
Wave Mode: Torsional Mode
Inspection Range: -296.4 to 354.7 inch

Test Pipe: Aboveground; Painted; 80°F F24-carrying pipe; 0.249, 0.249, 0.246, 0.249-inch wall; Supported


with Steel


Note:


Summary: No indication is found within the inspection range.


Sym.	Dist.(inch) % Refl.		Comment
F1	-291.38	31.4	Flange;
W1	-285.37	45.1	Weld;
(b)	-250.16	5.6	Pipe Support;
TC1	-210.32	1.5	T-Connection;
X1	-180.09	1.7	Directionality;
Y1	-160.04	4.0	Multiple Reflection;
W2	-124.37	15.0	Weld;
X2	-33.16	0.5	Directionality;  MsS-X =33.16; Mk1 (31.47, 0.58)
MsS1	0.00		Initial Pulse;
GF1	23.20	0.4	Geometric Feature; Wall attenuation
Mk1	32.86	222	Marker;
X3	125.45	2.4	Directionality; W2 (125.03, 0.91);
Y2	157.27	3.1	Multiple Reflection;
<b>Y3</b>	191.03	3.7	Multiple Reflection;
Y4	312.99	0.7	Multiple Reflection;  MsS-X =312.99; Y3-W2 (313.45, 0.08)
W3	359.29	18.1	Weld;


GW-B13











GW-B13; Concrete penetration at bulkhead; (Area = Between (0) (3) (A)

Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299

Fax: 757-622-9103

Toll Free: 800-546-7853

This page is intentionally left blank.



**GW-B14** 

# **Guided Wave Inspection Report**

Site: RH PPG Date: 28-Mar-2022

Pipe ID/Location: GW-B14 GWT System: MsSR3030R 53100

Pipe Size: (b) (3) (A) , 0.250-inch-wall Analysis S/W: V4.1 Procedure: GWA 4.01
Analyzer: (b) (6) Wave Mode: Torsional Mode
Client: AB&A (US Navy) Inspection Range: -253.8 to 400.8 inch

Test Pipe: Aboveground; Painted; 80°F JP 5-carrying pipe; 0.237, 0.242, 0.241, 0.243-inch wall; Supported

with Steel

Note:

Summary: No indication is found within the inspection range.


Sym.	Dist.(inch) % Refl.		Comment
F1	-260.82	12.9	Flange;
W1	-248.42	12.1	Weld;
TC1	-147.32	3.5	T-Connection;
W2	-102.35	15.0	Weld;
X1	-46.10	0.5	Directionality;  MsS-X =46.04; Mk1 (44.57, 0.72)
MsS1	0.31		Initial Pulse;
Mk1	44.87		Marker;
Y1	60.58	1.9	Multiple Reflection;
X2	104.03	2.8	Directionality;  MsS-X =103.53; W2 (102.85, 3.18)
Y2	147.63	4.5	Multiple Reflection;  MsS-X =147.13; TC1 (147.82, 1.41)
X3	191.85	2.8	Directionality;
X4	249.98	5.2	Directionality;  MsS-X =249.48; W1 (248.92, 4.86)
Y3	294.80	8.3	Multiple Reflection;
<b>X</b> 5	338.90	10.7	Directionality;
W3	378.36	3.4	Weld;
TC2	443.41	17.1	T-Connection;






**GW-B14** 





























# Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853

GW-B14; Concrete penetration at bulkhead; (Area = Between (b) (3) (A)

This page is intentionally left blank.

# **Guided Wave Inspection Report**

Site: RH PPG Date: 28-Mar-2022

Pipe Size: (b) (3) (A) , 0.405-inch-wall Analysis S/W: V4.1
Inspector: (b) (6) Procedure: GWA 4.01
Analyzer: (b) (6) Wave Mode: Torsional Mode
Client: AB&A (US Navy) Inspection Range: -245.4 to 471.4 inch


Test Pipe: Aboveground; Painted; 81°F F76-carrying pipe; 0.405, 0.395, 0.396, 0.401-inch wall; Supported


with Steel


Note:


Summary: No indication is found within the inspection range.

Sym.	Dist.(inch)	% Refl.	Comment
F1	-213.35	70.1	Flange;
W1	-209.56	4.5	Weld; Flange Weld
TC1	-204.80	22.8	T-Connection; Q22 (209.93, 0.94);
TC2	-171.94	6.3	T-Connection; 4"
TC3	-164.25	6.2	T-Connection; 6"
W2	-124.95	20.0	Weld;
MsS1	0.00		Initial Pulse;
Mk1	38.71		Marker; Metal ring (anchor) 8" inside concrete
Y1	50.61	5.1	Multiple Reflection;
W3	125.43	3.4	Weld;
Y2	164.05	4.2	Multiple Reflection;  MsS-X =164.05; TC2 (169.10, 0.11)









Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Toll Free: 800-546-7853

Office: 757-622-6299 Fax: 757-622-9103

GW-B15; Concrete penetration at bulkhead; (Area = Between (b) (3) (A)

This page is intentionally left blank.

# **Guided Wave Inspection Report**

Site: RH PPG Date: 28-Mar-2022

Pipe ID/Location: GW-B16 GWT System: MsSR3030R 53100

Pipe Size: (b) (3) (A) , 0.405-inch-wall Analysis S/W: V4.1
Inspector: (b) (6) Procedure: GWA 4.01
Wave Mode: Torsional Mode
Inspection Range: -603.5 to 601.9 inch

Test Pipe: Aboveground; Painted; 74°F F76-carrying pipe; 0.398, 0.401, 0.395, 0.399-inch wall; Supported


with Steel


Note:


Summary: No indication is found within the inspection range other than the corrosion area located 447" to


467" from sensor is visible on lower frequencies (see report body for UTT and pit sizes).


Sym.	Dist.(inch) % Refl.		Comment
W1	-599.14	10.7	Weld;
Y1	-587.71	3.7	Multiple Reflection;  MsS-X =587.71; X1-W4 (589.77, 5.95)
X1	-476.74	17.4	Directionality;  MsS-X =476.74; W2-W4 (474.87, 4.80)
D1	-452.77	17.5	Defect; 32-% wall loss;
W2	-362.80	33.2	Weld;
GF1	-358.42	15.6	Geometric Feature; W3-Q4-W3 (362.43, 1.30);
X2	-348.67	1.1	Directionality;  MsS-X =348.67; W5 (346.61, 0.95)
X3	-257.01	4.5	Directionality;
Y2	-240.83	2.6	Multiple Reflection;  MsS-X =240.83; W3-W4 (238.06, 2.36)
<b>Y</b> 3	-237.82	3.4	Multiple Reflection;  MsS-X =237.82; W3-W4 (238.06, 2.36)
W3	-125.74	15.0	Weld;
X4	-119.88	2.7	Directionality;  MsS-X =119.88; Y4 (118.80, 9.45)
X5	-114.83	8.3	Directionality;  MsS-X =114.83; W4 (113.97, 19.18)
X6	-112.11	8.1	Directionality;  MsS-X =112.11; W4 (113.97, 19.18)
GF2	-66.98	1.0	Geometric Feature; Pipe Wrap
GF3	-56.77	2.8	Geometric Feature;
MsS1	0.00	-	Initial Pulse;
GF4	110.94	57.7	Geometric Feature;
W4	113.97	39.6	Weld;
Y4	118.13	29.8	Multiple Reflection;  MsS-X =118.13; W4-GF4-W4 (117.39, 7.93)
Y5	120.86	32.1	Multiple Reflection;
X7	124.70	18.8	Directionality;  MsS-X =124.70; W3 (124.75, 4.93)
X8	127.18	18.9	Directionality;  MsS-X =127.18; W3 (125.33, 6.78)
Y6	238.87	3.1	Multiple Reflection;  MsS-X =238.87; W4-W3 (238.06, 2.36)
W5	347.36	3.0	Weld; W4-W3-W4 (352.30, 1.41);
X9	365.09	8.3	Directionality;  MsS-X =365.09; W2 (365.28, 9.19)
Y7	476.55	16.6	Multiple Reflection;  MsS-X =476.55; W4-W2 (476.33, 9.92)
W6	589.00	10.7	Weld; W4-W2-W4 (589.85, 3.67);











Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103

Toll Free: 800-546-7853

GW-B16; General pipe and saddle inspection; (Area = Between (b) (3) (A)

This page is intentionally left blank.



**GW-B17** 

### **Guided Wave Inspection Report**

Site: RH PPG Date: 28-Mar-2022
Pipe ID/Location: GW-B17 GWT System: MsSR3030R 53

O/Location: GW-B17 GWT System: MsSR3030R 53100
Pipe Size: (b) (3) (A) , 0.250-inch-wall Analysis S/W: V4.1

Inspector: (b) (6)
Analyzer: (b) (6)
Client: AB&A (US Navy)

Procedure: GWA 4.01
Wave Mode: Torsional Mode
Inspection Range: -995.3 to 648.2 inch

Test Pipe: Aboveground; Painted; 73°F F24-carrying pipe; 0.244, 0.238, 0.242, 0.244-inch wall; Supported

with Steel

Note:


Summary: One location of defect later identified as inactive pitting (approx. 0.050") with some large area of scaling but minimal metal loss. Two area of possible similar magnitude of pitting on some

frequency seen under pipe wrap. Wrap removal required to get exact size of pitting depth (marked as

M1 and M2).


Sym.	Dist.(inch) % Refl.		Comment
X1	-590.03	2.2	Directionality;  MsS-X =590.03; Y9 (588.08, 2.50)
Mk1	-536.40		Marker; W1-W4 (536.51, 2.08);
Mk2	-486.78		Marker,
W1	-483.90	14.0	Weld;
TC1	-476.77	20.1	T-Connection; Q12-W4 (463.73, 0.79);
X2	-407.52	23.1	Directionality;
Y1	-392.77	14.8	Multiple Reflection;  MsS-X =392.77; Y8 (385.33, 2.40)
Y2	-363.15	10.4	Multiple Reflection;  MsS-X =363.15; Y7 (365.40, 1.96)
Y3	-350.77	13.4	Multiple Reflection; Q18 (349.96, 2.33);
Y4	-332.90	13.3	Multiple Reflection;  MsS-X =332.90; W2-W4 (335.25, 3.95)
D1	-299.15	7.4	Defect; 30-% wall loss; Q19 (298.46, 0.53);
W2	-281.40	22.9	Weld;
W3	-246.03	20.3	Weld;
X3	-54.40	6.6	Directionality;  MsS-X =54.40; W4 (52.27, 4.26)
MsS1	0.00		Initial Pulse;
W4	53.85	15.0	Weld;
Y5	299.96	5.2	Multiple Reflection;  MsS-X =299.96; D1 (299.15, 2.09)
Y6	352.35	27.5	Multiple Reflection;  MsS-X =352.35; W4-D1 (353.63, 1.72)
Y7	365.40	6.4	Multiple Reflection;  MsS-X =365.40; W4-D1 (351.89, 0.23)
Y8	385.33	8.5	Multiple Reflection;
W5	535.83	9.3	Weld; W1-Q11 (536.51, 2.08);
<b>Y</b> 9	588.96	9.2	Multiple Reflection;  MsS-X =588.96; W4-Mk1 (587.98, 1.55)






Distance (inch)









Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299

Fax: 757-622-9103 Toll Free: 800-546-7853

GW-B17; General pipe inspection; (Area = Between (6) (3) (A)

# **Guided Wave Inspection Report**

Site: RH PPG Date: 29-Mar-2022

Pipe ID/Location: GW-B18(SP8)6OC GWT System: MsSR3030R 53100 Pipe Size: (b) (3) (A) ..., 0.250-inch-wall Analysis S/W: V4.1

Pipe Size: (b) (3) (A) , 0.250-inch-wall Analysis S/W: V4.1
Inspector: (b) (6) Procedure: GWA 4.01
Analyzer: (b) (6) Wave Mode: Torsional Mode
Client: AB&A (US Navy) Inspection Range: -952.6 to 951.6 inch


Test Pipe: Aboveground; Painted; 73°F JP-8-carrying pipe; 0.236, 0.237, 0.241, 0.237-inch wall; Supported

with Steel


Note:


Summary: No indication is found within the inspection range.

Sym.	Dist.(inch)	% Refl.	Comment
W1	-874.77	10.0	Weld;
GF1	-477.31	10.6	Geometric Feature;
GF2	-422.93	2.4	Geometric Feature; Repair Sleeve
W2	-398.68	16.2	Weld;
X1	-386.52	7.5	Directionality;  MsS-X =386.52; PS2 (379.58, 0.81)
X2	-371.68	2.1	Directionality;  MsS-X =371.68; PS1 (365.83, 0.28)
Х3	-78.78	3.9	Directionality;  MsS-X =78.78; W3 (77.08, 4.39)
Y1	-16.61	1.1	Multiple Reflection;  MsS-X =16.61; ?? (25.90, 0.30)
MsS1	0.00		Initial Pulse;
W3	78.03	14.4	Weld;
(b)	362.08	4.5	Pipe Support;
(b)	379.52	4.3	Pipe Support;
X4	398.83	14.1	Directionality;  MsS-X =398.83; W2 (398.77, 5.78)
X5	411.65	11.8	Directionality;  MsS-X =411.65; GF2 (423.40, 1.77)
Y2	463.40	15.1	Multiple Reflection;  MsS-X =463.40; W3-W2 (476.23, 3.22)
Y3	476.83	31.3	Multiple Reflection;  MsS-X =476.83; W3-W2 (476.23, 3.22)
W4	556.83	17.3	Weld; W1-Q12 (565.14, 2.51);
Y4	565.58	21.0	Multiple Reflection;  MsS-X =565.58; W3-GF1 (564.89, 0.52)
X6	878.33	4.6	Directionality;  MsS-X =878.33; W1 (874.77, 4.39)
Y5	951.58	8.4	Multiple Reflection; Q1 (952.65, 3.18);



CW-B18(SP8)60C





# Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Fax: 757-622-9103 Toll Free: 800-546-7853

Office: 757-622-6299

GW-B18; General pipe inspection; (Area = Between (6) (3) (A)



**GW-B19** 

### **Guided Wave Inspection Report**

Site: RH PPG Date: 29-Mar-2022
Pipe ID/Location: GW-B19 GWT System: MsSR3030R 53100

Pipe Size: (b) (3) (A) , 0.250-inch-wall Analysis S/W: V4.1
Inspector: (b) (6) Procedure: GWA 4.01
Analyzer: (b) (6) Wave Mode: Torsional Mode

Analyzer: (b) (6) Wave Mode: Torsional Mode
Client: AB&A (US Navy) Inspection Range: -897.0 to 899.5 inch

Test Pipe: Aboveground; Painted; 73°F F24-carrying pipe; 0.470, 0.247, 0.250, 0.244-inch wall; Supported

with Steel

Note:


Summary: No indication is found within the inspection range other than the corrosion area located near pipe

support 290 (-480" from sensor) is visible on multiple frequencies (see report body for UTT and pit


sizes).

Sym.	Dist.(inch)	% Rofl	Comment
X1	-897.84	7.5	Directionality;  MsS-X =897.84; Y7 (897.89, 5.73)
W1	-852.43	14.0	Weld:
(b)	-798.84	5.5	Pipe Support; Q7–W6 (798.23, 1.25);
X2	-751.18	10.6	Directionality;  MsS-X =751.18; W7 (747.64, 6.31)
TC1	-725.59	19.3	T-Connection:
Х3	-650.18	6.6	Directionality;  MsS-X =650.18; Y5 (649.09, 5.63)
Y1	-625.68	7.7	Multiple Reflection;
W2	-610.34	80.0	Weld:
X4	-576.71	8.8	Directionality;  MsS-X =576.71; W4-W6-W4 (572.69, 0.16)
Y2	-525.46	23.3	Multiple Reflection;
D1	-477.71	31.9	Defect; 33–% wall loss; corrosion area by saddle (0.077" pits)
Y3	-423.71	9.7	Multiple Reflection;  MsS-X =423.71; W4-W6 (424.13, 5.97)
Y4	-376.21	21.7	Multiple Reflection;  MsS-X =376.21; W5-W6 (374.61, 4.35)
X5	-274.59	12.3	Directionality;  MsS-X =274.59; W6 (272.77, 11.56)
(b)	-207.68	0.9	Pipe Support,
GF1	-203.55	2.8	Geometric Feature; W4-W5-W4 (197.46, 0.45);
W3	-202.09	11.5	Weld; W4–W5–W4 (197.46, 0.45);
W4	-149.71	17.4	Weld:
W5	-101.96	15.0	Weld:
MsS1	0.00		Initial Pulse:
	98.16	1.0	Pipe Support; W5 (102.09, 3.77);
(b) X6	102.64	5.5	Directionality: IMsS-XI=102.64; W5 (101.84, 7.17)
X7	150.64	4.9	Directionality;  MsS-X =150.64; W4 (149.84, 6.39)
X8	202.27	7.6	Directionality;  MsS-X =202.27; W3 (202.09, 8.19)
W6	274.41	28.2	Weld:
GF2	279.41	12.0	Geometric Feature;
X9	376.04	17.2	Directionality;  MsS-X =376.04; Y4 (375.71, 7.41)
X10	426.16	6.8	Directionality; W6-W4 (423.14, 2.60);
X11	475.14	13.6	Directionality;  MsS-X =475.14; D1 (475.34, 9.32)
X12	525.77	4.2	Directionality;  MsS-X =525.77; Y2 (524.71, 4.83)
X13	576.77	4.0	Directionality;  MsS-X =576.77; X4 (576.71, 6.28)
X14	611.21	6.2	Directionality;  MsS-X =611.21; W2 (610.30, 6.70)
Y5	649.16	56.8	Multiple Reflection;  MsS-X =649.16; W6-Y4 (649.51, 3.47)
Y6	697.84	14.5	Multiple Reflection; MsS-XI=697.84; W6-Y3 (695.86, 0.83)
W7	748.04	56.2	Weld;
GF3	753.79	36.2	Geometric Feature;
X15	799.02	12.6	Directionality;  MsS-X =799.02; PS1 (798.84, 3.95)
X16	852.02	14.4	Directionality;  MsS-X =852.02; W1 (850.59, 7.17)
Y7	884.59	17.3	Multiple Reflection;  MsS-X =884.59; W6-W2 (882.73, 3.95)



















Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299

Fax: 757-622-9103

Toll Free: 800-546-7853

GW-B19; General pipe inspection; (Area = Between (6) (3) (A)



GW-B20

Date: 29-Mar-2022

GWT System: MsSR3030R 53100

Procedure: GWA 4.01 Wave Mode: Torsional Mode

Inspection Range: -998.1 to 978.3 inch

Analysis S/W: V4.1

## **Guided Wave Inspection Report**

Site: RH PPG Pipe ID/Location: GW-B20

Pipe Size: Inspector: Benyam Berhane

Analyzer: Benyam Berhane Client: AB&A (US Navy)

Test Pipe:


Note:

Summary: No indication is found within the inspection range other than the corrosion area located near pipe support 290 and 291 (at -258" and -195" from sensor) is visible on multiple frequencies (see report


body for UTT and pit sizes).

Sym.	Dist.(inch)	% Refl.	Comment
W1	-979.34	5.1	Weld; Q48 (978.27, 2.57);
Y1	-954.46	5.7	Multiple Reflection;  MsS-X =954.46; Y5-W4 (950.48, 0.78)
Y2	-950.46	6.5	Multiple Reflection;  MsS-X =950.46; Y9 (949.52, 4.34)
W2	-921.46	4.3	Weld;
Mk1	-890.96		Marker; Possible Anchor approx. 11" in wall but (Low S/N)
GF1	-877.71	1.9	Geometric Feature; Attenuation at wall
X1	-813.71	3.7	Directionality;  MsS-X =813.71; W5 (811.39, 3.64)
Y3	-790.55	2.3	Multiple Reflection;  MsS-X =790.55; GF2-W4 (789.36, 0.43)
Y4	-741.42	2.9	Multiple Reflection; GF3-Q7 (743.26, 0.23);
TC1	-686.59	2.3	T-Connection;
Y5	-614.18	10.5	Multiple Reflection;  MsS-X =614.18; W3-Y8 (612.86, 2.73)
Y6	-505.96	2.6	Multiple Reflection;  MsS-X =505.96; ?? (503.41, 0.72)
Y7	-476.43	9.7	Multiple Reflection;  MsS-X =476.43; Y8 (474.77, 7.12)
GF2	-453.21	2.7	Geometric Feature;
GF3	-402.92	3.6	Geometric Feature; Pipe repair sleeve (48" long) Start
X2	-338.09	5.5	Directionality;  MsS-X =338.09; W4 (336.77, 6.05)
D1	-253.34	0.8	Defect; 28.3-% wall loss; Pits
D2	-195.59	1.3	Defect; 39.4-% wall loss; Pits
W3	-138.96	15.0	Weld;
MsS1	0.00		Initial Pulse;
Х3	138.52	6.1	Directionality;  MsS-X =138.52; W3 (138.09, 6.05)
W4	338.54	15.0	Weld;
X4	404.14	1.6	Directionality;  MsS-X =404.14; GF3 (403.71, 1.29)
X5	451.89	1.5	Directionality;  MsS-X =451.89; GF2 (451.84, 1.09)
Y8	476.59	14.4	Multiple Reflection;  MsS-X =476.59; W4-W3 (474.86, 2.31)
X6	611.96	3.8	Directionality;  MsS-X =611.96; Y5 (614.49, 0.88)
W5	811.84	8.0	Weld;
Y9	949.52	7.2	Multiple Reflection;  MsS-X =949.52; W5-W3 (949.48, 1.39)

















Inter Spec LLC

Environmental Inspection Services
464 S Independence Blvd, C-104, Virginia Beach, VA 23452

Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

www.interspecllc.net



GW-B21

Date: 30-Mar-2022

GWT System: MsSR3030R 53100

Procedure: GWA 4.01

Wave Mode: Torsional Mode

Inspection Range: -1294.9 to 962.8 inch

Analysis S/W: V4.1

# **Guided Wave Inspection Report**

Site: RH PPG Pipe ID/Location: GW-B21

Pipe Size: (b) (3) (A) Inspector: (b) (6)

Analyzer: (b) (6)
Client: AB&A (US Navy)

Test Pipe: (b) (3) (A)

with Steel

Note:


Summary: Multiple welds in close proximity to each other is producing directionality and multiple reflection

signals but one confirmed indication detected at -402" to -411" on this pipe. There is also one indication identified underneath a concrete saddle support (Saddle # 195) that requires prove up (visual, thickness and pit inspection) after pipe is lifted off the saddle support. Indication at

saddle area was noted on all frequencies ranges. Item Q1


Sym.	Dist.(inch)	% Refl.	Comment
W2	-744.84	41.0	Weld:
Y2	-715.09	23.7	Multiple Reflection;  MsS-X =715.09; W5-W9 (714.48, 5.15)
TC1	-667.84	10.2	T-Connection;
X1	-625.46	17.9	Directionality;  MsS-X =625.46; GF4-W9-GF4 (628.19, 0.70)
X2	-618.71	10.8	Directionality;
X3	-576.96	7.9	Directionality;  MsS-X =576.96; W10 (575.14, 5.04)
Y3	-518.46	11.4	Multiple Reflection;  MsS-X =518.46; GF2-W3-GF2 (518.71, 1.34)
GF2	-513.71	18.0	Geometric Feature;
W3	-508.71	41.1	Weld;
W4	-485.34	11.3	Weld;
TC2	-480.59	18.4	T-Connection; Q12-W4 (463.73, 0.79);
D1	-402.46	5.7	Defect; 50.9-% wall loss; GF2-W3-GF2 (388.32, 0.15);
GF3	-382.09	6.8	Geometric Feature;
W5	-378.34	11.8	Weld;
X4	-337.96	8.6	Directionality;  MsS-X =337.96; W9 (336.02, 10.98)
W6	-240.96	3.8	Weld;
GF4	-143.84	19.2	Geometric Feature;
W7	-141.46	15.0	Weld;
X5	-97.84	6.0	Directionality;  MsS-X =97.84; W8 (96.66, 6.40)
MsS1	0.00	-	Initial Pulse;
Q1	34.66	2.2	Indication; 45.0-% wall loss; Indication at saddle area (noted on all frequency)
W8	96.66	47.5	Weld;
X6	144.79	4.7	Directionality;  MsS-X =144.79; W7 (141.34, 4.98)
Y4	242.29	3.5	Multiple Reflection;  MsS-X =242.29; W8-GF4 (240.50, 6.83)
GF5	333.79	54.3	Geometric Feature;
W9	336.02	48.5	Weld;
Y5	340.77	21.9	Multiple Reflection;
Y6	362.54	4.9	Multiple Reflection; W2–Q36–W2 (357.10, 0.13);
Y7	372.91	4.4	Multiple Reflection;  MsS-X =372.91; W5 (378.46, 2.28)
Y8	381.21	4.8	Multiple Reflection;  MsS-X =381.21; GF3 (382.59, 1.24)
Y9	479.39	13.3	Multiple Reflection; Q30 (478.71, 6.24);
W10	571.21	11.4	Weld; Q42-W2-Q42 (570.91, 14.00);






Distance (inch)
















larbor, HI (Project # 22-0114) ]		(Sch. STD, Nom. 0.375)	S Navy - Pearl Harbor, HI  8y: InterSpec, LLC.   Modified By:	Date: 3/30/2022   Rev No : N/A   Strunnel Piping   Public   Publ
Joint Base Pearl Harbor Hickam, Pearl Harbor, HI (Project # 22-0114)  [GW - B21]				Description: F-76
	(b) (3) (A)	73.5 F	Remarks/Legend: BBW - Bell - Bell Weld W - Weld PS - Pipe Support	Drawing Title: GW - B21



Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

www.interspecllc.net

[440]

### **Guided Wave Inspection Report**

Site: RH PPG Pipe ID/Location: GW-B22

Pipe Size: (b) (3) (A) Inspector(b) (6)

Analyzer AB&A (US Navy)

Date: 30-Mar-2022 GWT System: MsSR3030R 53100

Analysis S/W: V4.1 Procedure: GWA 4.01 Wave Mode: Torsional Mode


Inspection Range: -1201.0 to 1204.2 inch


Test Pipe:


Note:


Summary: Piping tested satisfactory with a few unidentified indications noted in the bulkhead (M1 @ +93.47" and M2 @ +107.5"). Note M1 is likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen in other tests at this facility. This data also shows the signals separated by approx. 14" inside the bulkhead and appears to be welds attaching to possibly rebars or other anchor plates inside the bulkhead. The anchor plates welded inside the bulkhead are located approximately 6.5" inside the bulkhead (Tank gallery side of bulkhead). Review construction drawing is recommended to determine what M1 - M2 are. The section of piping can remain in-service.


Sym.	Dist.(inch)	% Refl.	Comment
W1	-1203.59	38.9	Weld;
PS1	-1057.38	26.5	Pipe Support;
W2	-721.23	48.1	Weld;
Y1	-671.85	2.3	Multiple Reflection;  MsS-X =671.85; X1-Mk1 (670.42, 2.18)
Y2	-666.04	2.3	Multiple Reflection;  MsS-X =666.04; X1-Mk1 (670.42, 2.18)
X1	-576.95	11.5	Directionality;  MsS-X =576.95; W3-W5 (578.89, 4.29)
Y3	-532.34	2.2	Multiple Reflection;
X2	-337.47	5.5	Directionality;
Y4	-330.01	2.5	Multiple Reflection;  MsS-X =330.01; W3-Mk1 (334.39, 6.90)
W3	-241.65	38.9	Weld;
PS2	-113.29	2.6	Pipe Support;
<b>X3</b>	-94.93	2.1	Directionality;  MsS-X =94.93; Mk1 (93.09, 1.95)
MsS1	0.00	-	Initial Pulse;
Mk1	93.47	-	Marker;
Mk2	107.50	-	Marker; PS2 (112.96, 0.04);
Y5	116.22	1.3	Multiple Reflection;  MsS-X =116.22; PS2 (112.88, 0.65)
W4	243.60	23.7	Weld;
X4	250.68	3.3	Directionality;  MsS-X =250.68; W3 (245.60, 11.66)
W5	336.11	8.4	Weld;
X5	1204.16	11.0	Directionality;  MsS-X =1204.16; W1 (1203.47, 12.55)














	Joint Base Pearl Harbor Hickam, Pearl Harbor, HI (Project # 22-0114)	
	[GW - B22]	
(b) (3) (A)		
3/31/2022 73.3 F	UT: 0.250, 0.250, 0.247, 0.249 (Sch. 10, Nom. 0.250)	
Remarks/Legend: A - Dent/Gouge (0.273") at 413" (3 o'clock) B - Dent (0.050") at +181" (3 o'clock)	arbor,	
Drawing Title: GW - B22	Drawn By: InterSpec, LLC.   Modified By:   Description:   Description:   Rev No: N/A   S     F-24 Tunnel Piping   F-24 Tunnel Piping	Modified By: InterSpec, LLC.  N/A Scale: N/A



www.interspecllc.net

Office: 757-622-6299

Fax: 757-622-9103

Toll Free: 800-546-7853

[449]

This page is intentionally left blank.

## **Guided Wave Inspection Report**

Site: RH PPG Pipe ID/Location: GW-B23

> Pipe Size: Inspector: (b) (6) Analyzer:

> > Client: AB&A (US Navy)

Date: 30-Mar-2022 GWT System: MsSR3030R 53100

Analysis S/W: V4.1 Procedure: GWA 4.01 Wave Mode: Torsional Mode Inspection Range: -874.7 to 399.0 inch


Test Pipe: (b) (3) (A)


Note:


Summary: Piping tested satisfactory with a few unidentified indications noted in the bulkhead (M1 @ +90" and M2 @ +104"). Note M1 is likely part of the anchor/support because highest magnitude is at the 6 o'clock position and similar pattern seen in other tests at this facility. This data also shows the signals separated by approx. 14" inside the bulkhead and appears to be welds attaching to possibly rebars or other anchor plates inside the bulkhead. The anchor plates welded inside the bulkhead are located approximately 6" inside the bulkhead (Tank gallery side of bulkhead). Review construction drawing is recommended to determine what M1 - M2 are. The section of piping can remain in-service


Sym.	Dist.(inch)	% Refl.	Comment
X1	-875.97	6.9	Directionality; W1-Q4-W1 (861.86, 0.32);
W1	-784.12	27.7	Weld;
PS1	-707.34	20.1	Pipe Support;
PS2	-412.44	2.8	Pipe Support; Q7 (398.14, 0.64);
X2	-400.38	8.4	Directionality;  MsS-X =400.38; X4 (398.14, 1.31)
W2	-310.66	27.7	Weld;
PS3	-127.90	0.7	Pipe Support;
MsS1	0.00	200	Initial Pulse;
Mk1	90.32		Marker;
Mk2	104.01	, FEREN	Marker;
PS4	168.90	0.2	Pipe Support;
Х3	309.31	7.5	Directionality;  MsS-X =309.31; W2 (308.75, 6.60)
X4	399.02	5.2	Directionality;  MsS-X =399.02; PS2 (412.03, 0.34)
PS5	446.14	0.6	Pipe Support;


GW-B23











Modified By: InterSpec, LLC. UT: 0.249, 0.244, 0.247, 0.245 US Navy - Pearl Harbor, HI (Sch. 10, Nom. 0.250) Drawn By: InterSpec, LLC.
Date: 3/31/2022 | Rev No: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI (Project # 22-0114) Description: JP-5 Tunnel Piping [GW - B23]BBW - Bell - Bell Weld W - Weld PS - Pipe Support A - Dent/Gouge (0.156) at -107" (3 o'clock)
B - Dent/Gouge (0.109) at -114" (4 o'clock)
C - Dent/Gouge (0.1035) at -321" (3 o'clock)
D - Dent/Gouge (0.1910) at -353" (4 o'clock)
E - Dent/Gouge (0.069) at +334" (3 o'clock) 3/31/2022 GW - B23 Drawing Title:

Inter Spec LLC

Environmental Inspection Services
464 S Independence Blvd, C-104, Virginia Beach, VA 23452 www.interspecllc.net

Office: 757-622-6299

Fax: 757-622-9103

Toll Free: 800-546-7853

[457]

This page is intentionally left blank.



**GW-B24** 

## **Guided Wave Inspection Report**

Site: RH PPG

Pipe ID/Location: GW-B24 Pipe Size: (b) (3) (A)

Inspector: Analyzer:

Client: AB&A (US Navy)

Date: 31-Mar-2022

GWT System: MsSR3030R 53100

Analysis S/W: V4.1 Procedure: GWA 4.01 Wave Mode: Torsional Mode

Inspection Range: -721.1 to 766.7 inch

Test Pipe: (b) (3) (A)

Note:

Summary: Piping tested satisfactory with a few unidentified indications noted in the bulkhead (M1 @ +107", M2 @ 122", M3 @ 137"). Note M1 is likely part of the anchor/support because highest magnitude is at

the 6 o'clock position and similar pattern seen in other tests at this facility. This data also


shows the signals separated by approx. 15" inside the bulkhead and appears to be welds attaching to possibly rebars or other anchor plates inside the bulkhead. The anchor plates welded inside the bulkhead are located approximately 4.5" inside the bulkhead (Tank gallery side of bulkhead).

Review construction drawing is recommended to determine what M1 - M3 are. The section of piping

can remain in-service.


Sym.	Dist.(inch)	% Refl.	Comment
W1	-658.08	116.3	Weld;
GF1	-653.54	52.0	Geometric Feature; Bell
PS1	-544.09	5.2	Pipe Support; W2-Q19 (545.61, 0.57);
Y1	-422.30	1.5	Multiple Reflection; [MsS-X]=422.25; W3-W4-W3 (423.27, 0.38)
W2	-417.80	25.8	Weld;
Y2	-349.26	2.5	Multiple Reflection;  MsS-X =349.39; PS2-Mk1 (348.08, 1.45)
Y3	-303.37	5.1	Multiple Reflection; MsS-X =303.51; W3-Mk2 (303.32, 1.47)
Y4	-288.24	12.2	Multiple Reflection;  MsS-X =288.38; W3-Mk1 (286.94, 9.24)
Y5	-257.66	0.9	Multiple Reflection;  MsS-X =257.61; W3-W4 (254.91, 0.39)
PS2	-241.60	8.4	Pipe Support;
W3	-181.40	23.6	Weld; Q11 (176.67, 1.32);
GF2	-176.14	17.8	Geometric Feature; Bell
X1	-139.58	2.5	Directionality;  MsS-X =139.50; Mk3 (137.44, 0.48)
X2	-124.58	3.2	Directionality, MsS-X = 124.50; Mk2 (122.31, 1.11)
Y6	-112.85	2.6	Multiple Reflection;  MsS-X =112.78; Mk1-Mk1-Mk1 (111.74, 0.15)
X3	-110.58	3.8	Directionality;  MsS-X =110.51; Mk1 (106.98, 5.03)
X4	-62.43	4.9	Directionality;  MsS-X =62.35; W4 (60.99, 5.36)
MsS1	0.00	<u> </u>	Initial Pulse;
PS3	44.79	0.3	Pipe Support;
W4	60.99	25.8	Weld;
GF3	101.46	2.0	Geometric Feature;
Mk1	107.63	75.5	Marker, Anchor/support
Y7	114.82	3.1	Multiple Reflection;  MsS-X =114.90; Mk1-GF3-Mk1 (113.89, 0.13)
Mk2	122.26	22	Marker, Anchor/support
X5	127.80	2.2	Directionality;
Mk3	137.39	<u> </u>	Marker; Anchor/support
Y8	176.59	6.4	Multiple Reflection;  MsS-X =176.67; GF2 (176.06, 3.70)
X6	179.99	5.2	Directionality;  MsS-X =180.07; W3 (179.16, 6.88)
X7	181.36	10.1	Directionality;  MsS-X =181.22; W3 (180.46, 12.76)
X8	190.89	0.8	Directionality;  MsS-X =190.94; W3 (188.45, 0.69)
Y9	240.99	8.5	Multiple Reflection;  MsS-X =240.85; W4-W3 (240.80, 9.02)
Y10	287.51	13.3	Multiple Reflection;  MsS-X =287.37; Mk1-W3 (286.94, 9.24)
W5	300.75	5.9	Weld;
W6	355.04	2.4	Weld;
PS4	397.52	2.7	Pipe Support; Q16–Q10–Q16 (399.97, 0.28);
W7	494.59	3.5	Weld;






Distance (inch)

















 $\bigcup_{i \in I} C_i$ 

Inter Spec LLC

Environmental Inspection Services
464 S Independence Blvd, C-104, Virginia Beach, VA 23452

Office: 757-622-6299

Fax: 757-622-9103



This page is intentionally left blank.



**GW-B25** 

Date: 31-Mar-2022

GWT System: MsSR3030R 53100

Procedure: GWA 4.01

Wave Mode: Torsional Mode

Inspection Range: -1914.6 to 1530.4 inch

Analysis S/W: V4.1

## **Guided Wave Inspection Report**

Site: RH PPG Pipe ID/Location: GW-B25

Pipe Size: (b) (3) (A) Inspector (b) (6)

Analyzer

Client: AB&A (US Navy)

Test Pipe:


Note:

Summary: This data has several multiple reflections and directionality due to weld geometry. No indication

is found within the inspection range


Sym.	Dist.(inch)	% Refl.	Comment
W1	-1819.92	16.3	Weld; Q11-W2-Q11 (1822.71, 3.17);
X1	-1530.32	3.2	Directionality;  MsS-X =1530.32; W9 (1530.38, 2.50)
W2	-1344.79	9.9	Weld; Q22-W5-Q22 (1342.78, 2.28);
W3	-1340.09	10.2	Weld; Q22-W5-Q22 (1342.78, 2.28);
X2	-1051.78	2.8	Directionality;  MsS-X =1051.78; W8 (1051.33, 2.42)
W4	-863.19	14.1	Weld; Q21-W5-Q21 (862.54, 63.62);
X3	-574.00	3.8	Directionality;  MsS-X =574.00; W7 (573.42, 3.08)
Y1	-480.17	10.2	Multiple Reflection;  MsS-X =480.17; W5-W6 (477.64, 0.98)
PS1	-393.63	2.0	Pipe Support;
W5	-384.86	24.3	Weld;
PS2	-95.83	2.7	Pipe Support; W5 (96.54, 8.43);
MsS1	0.00	-	Initial Pulse;
W6	96.54	14.1	Weld;
X4	384.83	3.3	Directionality;  MsS-X =384.83; W5 (384.27, 2.61)
PS3	479.63	10.8	Pipe Support;
W7	572.94	12.4	Weld;
GF1	578.03	3.8	Geometric Feature;
GF2	585.02	4.1	Geometric Feature; Bell
Y2	957.04	8.9	Multiple Reflection;  MsS-X =957.04; W7-W5 (957.69, 1.33)
W8	1052.29	16.4	Weld; W7-W5-W6 (1054.63, 0.32);
GF3	1058.16	7.6	Geometric Feature; Bell
<b>X</b> 5	1341.91	2.5	Directionality;  MsS-X =1341.91; W3 (1342.23, 2.23)
Y3	1435.45	9.5	Multiple Reflection;  MsS-X =1435.45; W6-W3 (1436.23, 1.23)
W9	1533.03	17.6	Weld; W5-W2-W5 (1533.01, 48.70);
GF4	1542.86	10.5	Geometric Feature;






Distance (inch)
























CC



Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

[475]

www.interspecllc.net

This page is intentionally left blank.



GW-B26

## **Guided Wave Inspection Report**

Site: RH PPG Pipe ID/Location: GW-B26

Pipe Size: (b) (3) (A)

Inspector: (b) (6) Analyzer:

Client: AB&A (US Navy)

Date: 31-Mar-2022

GWT System: MsSR3030R 53100

Analysis S/W: V4.1 Procedure: GWA 4.01 Wave Mode: Torsional Mode

Inspection Range: -1453.8 to 1532.4 inch

Test Pipe: (b) (3) (A)

Note:


Summary: This data has several multiple reflections and directionality due to weld geometry. There is one indication (Q1 at -460") need to be checked using other NDT methods. Perform field verification of

signal to include local visual inspection at indication location and thickness test (Note: pipe


warp may need to be removed if present).

0	D:-4 (:L)	0/ D-fl	
Sym.	Dist.(inch)	0.210.00	Comment
Y1	-1438.48	7.8	Multiple Reflection;  MsS-X =1438.48; X5 (1437.90, 3.52)
W1	-1360.46	16.6	Weld;
X1	-1039.03	2.7	Directionality;  MsS-X =1039.03; W6 (1037.83, 3.08)
Y2	-959.62	4.6	Multiple Reflection;  MsS-X =959.62; Y5-PS2 (959.58, 1.13)
W2	-882.08	49.6	Weld;
Y3	-793.94	15.7	Multiple Reflection;
Y4	-766.76	12.3	Multiple Reflection;
Y5	-481.87	18.9	Multiple Reflection;  MsS-X =481.87; PS2 (479.57, 3.41)
Q1	-461.14	7.3	Indication;
GF1	-402.34	20.3	Geometric Feature; Bell
W3	-399.30	21.2	Weld;
X2	-80.95	3.7	Directionality;  MsS-X =80.95; W4 (80.07, 5.21)
MsS1	0.00		Initial Pulse;
W4	80.07	35.9	Weld;
GF2	83.86	3.6	Geometric Feature;
PS1	193.11	0.2	Pipe Support;
X3	401.74	5.8	Directionality;  MsS-X =401.74; W3 (400.35, 3.60)
PS2	481.28	25.4	Pipe Support;
W5	558.41	6.1	Weld;
GF3	561.83	7.8	Geometric Feature; W4-W3-W4 (559.44, 2.74); (Note Dent at Weld)
GF4	566.69	2.7	Geometric Feature; Bell (Note Dent at Weld)
X4	879.89	1.8	Directionality;  MsS-X =879.89; W2 (879.33, 2.26)
Y6	962.03	8.9	Multiple Reflection;  MsS-X =962.03; W4-W2 (962.14, 13.98)
PS3	999.45	5.4	Pipe Support;
W6	1037.82	7.4	Weld; W4-W2-W4 (1040.08, 0.16);
X5	1437.90	8.5	Directionality;  MsS-X =1437.90; W4-W1 (1437.93, 1.36)
Y7	1453.20	8.9	Multiple Reflection;  MsS-X =1453.20; W4-W1 (1439.32, 1.83)
W7	1516.80	7.7	Weld;
























Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

www.interspecllc.net

[483]




GW-B27

### **Guided Wave Inspection Report** Site: RH PPG Date: 01-Apr-2022 Pipe ID/Location: (b) (3) GWT System: MsSR3030R 53100 Analysis S/W: V4.1 Procedure: GWA 4.01 Inspector: Analyzer: Wave Mode: Torsional Mode Client: AB&A (US Navy) Inspection Range: -1226.6 to 1227.4 inch Test Pipe: Note: test Summary: This data has several multiple reflections and directionality due to weld geometry. There are two indications (Q1 at -976" and Q2 at -963") need to be checked using other NDT methods. Perform field verification of signal to include local visual inspection at indication location and thickness test

(Note: pipe warp may need to be removed if present).


Sym.	Dist.(inch)	% Dofl	Commont
W1	-1253.51	13.3	Continent Weld
X1	-1161.71	6.2	Directionality;  MsS-X =1161.71; W9 (1159.12, 6.41)
Ŷ1	-1013.01	9.9	Multiple Reflection;
Y2	-1006.25	2.6	Multiple Reflection;  MsS-X =1006.25; W3-W7 (1009.31, 0.18)
Q1	-976.91	1.8	Indication; 51.4–% wall loss; %refection is not accurate due to the two type (butt & the bell-bell) weld in this shot.
X2	-967.24	10.8	Directionality;  MsS-X =967.24; X17 (966.67, 10.76)
Q2	-962.63	2.4	Indication, 62.6–% wall loss; %refection is not accurate due to the two type (butt & the bell-bell) weld in this shot.
W2	-773.27	11.7	Weld;
GF1	-768.34	7.0	Geometric Feature;
GF2	-763.15	3.0	Geometric Feature: Bell
X3	-724.91	3.0	Directionality;  MsS-X =724.91; X15 (728.44, 2.16)
X4	-675.78	4.2	Directionality;  MsS-X =724.91, X13 (720.44, 2.10) Directionality;  MsS-X =675.78; W8 (679.13, 3.62)
W3	-527.71	6.6	Directionality, [ws5-x]-073.76, wo (073.13, 3.02)
GF3	-522.47	1.9	Geometric Feature;
X5	-480.04	6.6	Directionality:
GF4	-293.28	6.2	Geometric Feature: Bell
W4	-286.39	18.1	Geometric readure, Dell
Y3	-240.68	3.8	Multiple Reflection;  MsS-X =240.68; W5-GF6 (242.56, 1.52)
PS1	-195.29	7.3	Pipe Support;
W5	-46.84	14.0	ripe support, Weld'
MsS1	0.00	14.0	vveiu, Initial Pulse:
X6	47.78	7.5	Directionality;  MsS-X =47.78; W5 (46.71, 7.70)
PS2	91.66	0.1	Pipe Support;
GF5	189.97	2.9	Geometric Feature; Bell
W6	193.55	8.8	Weld:
GF6	196.97	14.1	Geometric Feature: Bell
X7	205.82	2.4	Directionality;  MsS-X =205.82; GF6-W6-GF6 (200.38, 0.17)
X8	240.11	3.3	Directionality, IMSS X =200.01, 91.0 YO 61.0 (200.00, 0.17)
Y4	244.00	2.6	Directionality;  MsS-X =240.11; Y3 (240.68, 2.91)  Multiple Reflection;  MsS-X =244.00; GF6-W5 (243.80, 2.03)  Directionality;  MsS-X =287.21; W4 (286.39, 5.93)
X9	287.21	5.4	Directionality: IMSS_XI=247.00, 01 0 473 (5.03, 2.03)
X10	289.17	12.6	Directionality, MsS-XI=289.17; W4 (286.33, 13.33)
PS3	392.92	0.8	Pipe Support;
X11	433.19	2.2	Directionality;  MsS-X =433.19; PS3-W5 (439.57, 0.14)
X12	479.22	5.9	Directionality: IMsS-XI=479.22: X5 (480.04.5.05)
W7	485.54	5.9	Weld's A -473.22, A3 (400.04, 5.03)
X13	528.66	5.1	Vield Directionality;  MsS-X =528.66; W3 (527.71, 5.04)
GF7	672.87	2.0	Geometric Feature:
W8	679.13	4.7	Weld:
PS4	696.05	0.9	Pipe Support:
X14	720.22	2.2	Directionality;  MsS-X =720.22; X3 (721.18, 2.04)
X15	724.58	3.1	Directionality: IMSS-X1=724.58: X3 (729.77.2.06)
X16	774.34	11.3	Directionality, MsS-X = 724.58; X3 (729.27, 2.06) Directionality, MsS-X = 774.34; W2 (773.27, 9.01)
X17	966.67	14.0	Directionality, MsS-X =966.67; W6-W2 (966.34, 2.92)
PS5	1014.08	8.9	Pipe Support: W7-W3 (1013.00, 0.36):
W9	1159.12	8.3	Weld:
X18	1207.55	7.6	Directionality;  MsS-X =1207.55; ?? (1207.99. 6.21)
X19	1254.33	9.6	Directionality; MsS-X =1254.33; W1 (1253.51, 10.25)
	.201.00	0.0	Directioning, price 74, 1201.00, 111 (1200.01, 10.20)






Distance (inch)














CCI

Inter Spec LLC


Environmental Inspection Services
464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Office: 757-622-6299

Fax: 757-622-9103

Toll Free: 800-546-7853



Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452 www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

[494]




GW-B29


### **Guided Wave Inspection Report** Site: RH PPG Date: 01-Apr-2022 Pipe ID/Location: (b) (3) GWT System: MsSR3030R 53100 Analysis S/W: V4.1 Procedure: GWA 4.01 Inspector: Analyzer: Wave Mode: Torsional Mode Client: AB&A (US Navy) Inspection Range: -35.9 to 131.0 inch Test Pipe: Note: Summary: No indication is found within the inspection range. The inspection range was limited for this location. It is recommend to supplement this inspection with other NDE (Borescope and CP Survey)

Sym.	Dist.(inch) % Refl.		Comment
F1	-22.96	21.0	Flange;
W1	-19.46	13.6	Weld;
W2	-8.09	15.0	Weld;
MsS1	0.00		Initial Pulse;
X1	8.91	4.3	Directionality;  MsS-X =8.91; W2 (8.09, 3.17)
X2	23.77	4.6	Directionality;  MsS-X =23.77; F1 (22.84, 5.15)
EW1	34.39	13.0	Elbow Weld;
EW2	42.64	4.8	Elbow Weld;
EW3	53.64	5.5	Elbow Weld;
Y1	57.39	8.3	Multiple Reflection;  MsS-X =57.39; EW1-F1 (57.23, 2.90)
Y2	91.34	3.9	Multiple Reflection;  MsS-X =91.34; EW1-F1-EW1 (91.85, 0.28)
Y3	98.84	3.1	Multiple Reflection;  MsS-X =98.84; EW1-F1-EW1 (91.85, 0.28)
W3	125.39	9.4	Weld;
EW4	130.96	10.2	Elbow Weld;




**GW-B29** 

























Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853


www.interspecllc.net


[502]


## Site: RH PPG Pipe ID/Location: (b) (3) Inspector: (b) (6) Analyzer: (b) (6) Analyzer: Client: AB&A (US Navy) Test Pipe: (b) (3) (A) Note: Summary: No indication is found within the inspection range.

Sym.	Dist.(inch)	% Refl.	Comment
F1	-73.89	30.3	Flange;
W1	-62.14	12.0	Weld;
MsS1	0.11	J <del>-100-</del> 2	Initial Pulse;
X1	74.82	3.3	Directionality;  MsS-X =74.76; F1 (73.95, 4.86)
X2	89.44	3.6	Directionality;  MsS-X =89.38; F1 (88.95, 3.07)
Y1	301.57	4.3	Multiple Reflection;
Y2	341.44	6.2	Multiple Reflection;
Y3	357.57	2.7	Multiple Reflection;  MsS-X =357.51; Y1-W1 (358.08, 0.24)
W2	387.94	52.1	Weld;
F2	399.82	80.0	Flange;









# Inter Spec LLC Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

www.interspecllc.net

[510]





**GW-B31** 


### Date: 01–Apr–2022 GWT System: MsSR3030R 53100 Analysis S/W: V4.1 Procedure: GWA 4.01 Wave Mode: Torsional Mode Inspection Range: -192 3 to 370.0 inch Wave Inspection Report Site: Pipe ID/Location: Pipe Size: Inspector: Analyzer: Test Pipe: Note:


Summary: No indication is found within the inspection range.


Comment	Flange;	Weld;	Initial Pulse;	Directionality;  MsS-X =119.91; F1 (118.96, 4.23)	Multiple Reflection;	Weld;	Weld;	Weld;
% Refl.	37.1	15.0	1	2.8	3.1	21.5	25.6	27.4
Dist.(inch) % Refl.	-116.05	-104.59	0.00	119.91	320.16	343.59	355.16	359.29
Sym.	F1	W1	MsS1	×	71	W2	W3	W4














Inter Spec LLC

Environmental Inspection Services
464 S Independence Blvd, C-104, Virginia Beach, VA 23452

Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

www.interspecllc.net

[519]

This page is intentionally left blank.




464 S Independence Blvd, C-104 Virginia Beach, VA 23452 (757) 622-6299 www.interspecllc.net


**GW-B32** 


# **Guided Wave Inspection Report**


Date: 02–Apr–2022
GWT System: MsSR3030R 53100
Analysis S/W: V4.1
Procedure: GWA 4.01
Wave Mode: Torsional Mode
Inspection Range: -236 5 to -0 3 inch Summary: No indication is found within the inspection range. Site: Test Pipe: Note: Pipe ID

Sym.	Dist.(inch)	% Refl.	Comment
H	-234.88	29.2	Flange;
W	-198.13	18.5	Weld;
WZ	-85.27	4.6	Weld;
W3	-79.68	9.6	Weld;
×	-79.68	9.6	Directionality;  MsS-X =79.77; EW1-EW2-EW1 (75.25, 0.43)
EW1	-66.36	23.7	Elbow Weld;
EW2	-57.21	9.7	Elbow Weld;
W4	-18.08	15.0	Weld;
MsS1	-0.27	ŀ	Initial Pulse;
X	19.32	2.4	Directionality;  MsS-X =19.14; W4 (18.14, 2.29)
X3	67.01	2.0	Directionality;  MsS-X =66.83; EW1 (66.10, 2.65)
X4	81.16	2.4	Directionality;  MsS-X =80.99; W3 (79.98, 2.31)
X5	198.78	3.9	Directionality;  MsS-X =198.60; W1 (197.60, 3.86)
9X	235.65	6.4	Directionality;  MsS-X =235.47; F1 (235.06, 7.88)









	Joint Base Pearl Harbor Hickam, Pearl Harbor, HI (Project # 22-0114)	(Project # 22-0114)
(b) (3) (A)		
emarks/Legend: V - Weld		Owner: US Navy - Pearl Harbor, HI
		Drawn By: InterSpec, LLC. Modified By: InterSpec, LLC.  Date: 4/2/2022   Rev No: N/A   Scale: N/A
raw Title: - B32	Description:  JP-5 Line Going Up to Tunnel Ceiling	



[527]

Inter Spec LLC

Environmental Inspection Services
464 S Independence Blvd, C-104, Virginia Beach, VA 23452

Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

www.interspecllc.net



This page is intentionally left blank.

Inter Spec LLC

Environmental Inspection Services

464 S Independence Blvd, C-104, Virginia Beach, VA 23452 www.interspecllc.net

Office: 757-622-6299 Fax: 757-622-9103 Toll Free: 800-546-7853

# Table L - Straight Beam Pipe Ultrasonic Thickness Testing Data at LRUT CMLs

Inter Spec LLC

Environmental Inspection Services 464 S Independence Blvd, C-104, Virginia Beach, VA 23452

www.interspecllc.net

Fax: 757-622-9103 Toll Free: 800-546-7853 Office: 757-622-6299

# Table L - Straight Beam Pipe Ultrasonic Thickness Testing Data at LRUT CMLs (Cont.)

CML ID#	Pip	e Ultrasonic Thickness Da	Pipe Ultrasonic Thickness Data at LRUT Locations (Inches)	nes)
GW B28		0.292	0.227	0.242
GW B29	0.278	0.271	0.275	0.274
GW B30	0.384	0.375	0.377	0.373
GW B31	0.348	0.336	0.379	0.380
GW B32	0.370	0.371	0.372	0.374

### Annex B Facility Piping Appendices

- 1. Appendix A (API 570 Calculations)
- 2. Appendix B (Thickness Data/CMLs)
- 3. Appendix C (Drawings)
- 4. Appendix D (API 570 Checklist and Site Assessment Findings/Discussion Form)
- 5. Appendix E (Photographs)

# Appendix A API-570 Calculations

- 1. Minimum Thickness Calculation
- 2. Remaining Life
- 3. Maximum Allowable Operating Pressure

#### **Definitions**

#### **API 570 - PIPE EVALUATION**

#### References:

#### **API 570**

- 7.1 Corrosion Rate Determination
- 7.2 MAOP Determination
- 7.3 Minimum Required Thickness (Reference API 574, Section 9)

#### **ASME B31.3**

- 304.1.2 Internal Pressure Calculations
- 304.1.3 External Pressure Calculations

#### **Definitions:**

- A = factor determined from Figure G in Subpart 3 of Section II, Part D and used to enter the applicable material chart in Subpart 3 of Section II, Part D.
- **B** = factor determined from applicable material chart in Subpart 3 of Section II, Part D for maximum design temperature.
- **C**<sub>a</sub> = remaining corrosion allowance of the pipe section under consideration, in inches.
- $C_r$  = corrosion rate of the pipe section under consideration, in inches per year.
  - **d** = inside diameter of the pipe section under consideration, in inches.
- **D** = outside diameter of the pipe section under consideration, in inches.
- E = Quality factor from Table A-1A
- L = total length of a pipe section between lines of support, in inches.
- = the design maximum allowable internal working pressure, including static head pressure, in psi.
- **P**<sub>a</sub> = maximum allowable external working pressure, in psi.
- $R_L$  = estimated remaining life of the pipe section under consideration, in years.
- $R_o$  = outside radius of the pipe section consideration, in inches.
- S = stress value for material from Table A-1, in psi.
- t = thickness of the pipe section under consideration, variable related to applicable calculation used therein, in inches.
- t act = minimum thickness measurement of the pipe section under consideration, as recorded at the time of inspection, in inches.
- $t_{eng}$  = an established engineering minimum thickness that considers structural support and localized corrosion, in inches.
- $t_{min}$  = minimum required thickness of pipe section, as calculated from the MOWP at the coinciding working temperature or  $t_{enq}$  thickness, whichever is greater, in inches.
- $t_{nom}$  = design nominal thickness of pipe section, in inches.
- $t_{prev}$  = original thickness of the pipe section under consideration, as recorded at first inspection or nominal thickness if no original thickness measurements were for  $t_{prev}$ , in years.
  - Y = time span between thickness readings or age of the pipe section if  $t_{nom}$  is used for tprev, in years.
- $Y_n$  = estimated time span to next inspection of the vessel part under consideration, in years.

# Pipe Wall Minimum Thickness, Remaining Life, and MAOP Calculations

#### A) Minimum Thickness Calculation

NPS	Schedule	$t_{nom}$	MAOP
20	20	0.375	275
,	<b>-</b>	<b>-</b>	3

	D	S	E
275	20.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.171$$
 $t_{eng} = 0.120$ 
 $t_{use} = 0.171$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.171	0.318	0.375	79

$$C_{a} = t_{act} - t_{use} = 0.147$$

$$C_{r} = t_{prev} - t_{act} / \Delta Y = 0.000722$$

$$R_{L} = C_{a} / C_{r} = 204$$
years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.318	5	0.000722

$$t_{req} = t_{act} - 2Y_n C_r = 0.311$$

S	E	$t_{req}$	D
20,000	0.8	0.311	20.000

$$= 2t_{req} SE/D = \underline{\qquad} 498 \underline{\qquad} psi$$

#### A) Minimum Thickness Calculation

NPS	Schedule	$t_{nom}$	MAOP
12	STD	0.375	275

	D	S	E
275	12.750	20,000	0.8

$$t_{eng} = D/2(SE+0.4P) = 0.109$$
 inches  $t_{eng} = 0.110$  inches  $t_{use} = 0.110$  inches  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### B) Remaining Life

t use	t act	t prev	$\Delta Y$
0.110	0.320	0.375	79

$$C_a = t_{act} - t_{use} = 0.210$$
 inches
$$C_r = t_{prev} - t_{act} / \Delta Y = 0.000696$$
 inches/year
$$R_L = C_a / C_r = 302$$
 years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$Y_n$	$C_r$
0.320	5	0.000696

$$t_{req} = t_{act} - 2Y_n C_r =$$
 0.313 inches

S	E	t req	D
20,000	0.8	0.313	12.750

$$= 2t_{req} SE/D = ___ 786 __psi$$



#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
16	10	0.250	275

	D	S	E
275	16.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.137$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.137$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.137	0.240	0.250	79

$$C_a = t_{act} - t_{use} = 0.103$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.000127$  year
 $R_L = C_a / C_r = 811$  years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.240	5	0.000127

$$t_{req} = t_{act} - 2Y_n C_r = 0.239$$

S	E	t <sub>req</sub>	D
20,000	0.8	0.239	16.000

$$= 2t_{req} SE/D = \underline{\qquad} 478 \underline{\qquad} psi$$

#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
18	10	0.250	275

	D	S	E
275	18.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.154$$
 $t_{use} = 0.110$ 
 $t_{use} = 0.154$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.154	0.231	0.250	79

$$C_a = t_{act} - t_{use} = 0.077$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.000241$ 
 $R_L = C_a / C_r = 320$  years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.231	5	0.000241

$$t_{req} = t_{act} - 2Y_n C_r = 0.229$$

S	E	$t_{req}$	D
20,000	0.8	0.229	18.000

$$= 2t_{req} SE/D = \underline{\qquad} 407 \underline{\qquad} psi$$

#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
32	STD	0.375	275

	D	S	E
275	32.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.274$$
 $t_{eng} = 0.150$ 
 $t_{use} = 0.274$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.274	0.342	0.375	79

$$C_{a} = t_{act} - t_{use} = 0.068$$

$$C_{r} = t_{prev} - t_{act} / \Delta Y = 0.000418$$

$$R_{L} = C_{a} / C_{r} = 163 \quad years$$

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.342	5	0.000418

$$t_{req} = t_{act} - 2Y_n C_r = 0.338$$

S	E	$t_{req}$	D
20,000	0.8	0.338	32.000

$$= 2t_{req} SE/D = 338 \quad psi$$

#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
16	10	0.250	275

	D	S	E
275	16.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.137$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.137$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.137	0.193	0.250	79

$$C_a = t_{act} - t_{use} = 0.056$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.000722$  year
 $R_L = C_a / C_r = 78$  years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.193	5	0.000722

$$t_{req} = t_{act} - 2Y_n C_r =$$
\_\_\_\_\_0.186

S	E	$t_{req}$	D
20,000	0.8	0.186	16.000

$$= 2t_{req} SE/D = 372 psi$$



#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
18	10	0.250	275

	D	S	E
275	18.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.154$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.154$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.154	0.192	0.250	79

$$C_a = t_{act} - t_{use} = 0.038$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.000734$ 
 $R_L = C_a / C_r = 52$  years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.192	5	0.000734

$$t_{req} = t_{act} - 2Y_n C_r = 0.185$$

S	E	$t_{req}$	D
20,000	0.8	0.185	18.000

$$= 2t_{req} SE/D = ___ 329 __ psi$$

#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
32	STD	0.375	275

	D	S	E
275	32.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.274$$
 $t_{eng} = 0.150$ 
 $t_{use} = 0.274$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.274	0.344	0.375	79

$$C_{a} = t_{act} - t_{use} = 0.070$$

$$C_{r} = t_{prev} - t_{act} / \Delta Y = 0.000392$$

$$R_{L} = C_{a} / C_{r} = 179$$
years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.344	5	0.000392

$$t_{req} = t_{act} - 2Y_n C_r = 0.340$$

S	E	$t_{req}$	D
20,000	0.8	0.340	32.000

$$= 2t_{req} SE/D = \underline{\qquad 340 \qquad psi}$$





#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
18	10	0.250	275

	D	S	E
275	18.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.154$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.154$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.154	0.224	0.250	79

$$C_{a} = t_{act} - t_{use} = 0.070$$

$$C_{r} = t_{prev} - t_{act} / \Delta Y = 0.000329$$

$$R_{L} = C_{a} / C_{r} = 213 \quad years$$

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.224	5	0.000329

$$t_{req} = t_{act} - 2Y_n C_r = 0.221$$

S	E	$t_{req}$	D
20,000	0.8	0.221	18.000

$$= 2t_{req} SE/D = ___ 393 __p si$$

#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
24	20	0.375	275

	D	S	E
275	24.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.206$$
 $t_{eng} = 0.130$ 
 $t_{use} = 0.206$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.206	0.341	0.375	79

$$C_a = t_{act} - t_{use} = 0.135$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.00043$ 
 $R_L = C_a / C_r = 314$ 
years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.341	5	0.00043

$$t_{req} = t_{act} - 2Y_n C_r = 0.337$$

S	E	$t_{req}$	D
20,000	0.8	0.337	24.000

$$= 2t_{req} SE/D = \underline{\qquad 449 \qquad psi}$$

#### A) Minimum Thickness Calculation

NPS	Schedule	t <sub>nom</sub>	MAOP
16	STD	0.375	275

	D	S	E
275	16.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.137$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.137$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.137	0.360	0.375	79

$$C_a = t_{act} - t_{use} = 0.223$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.00019$ 
 $R_L = C_a / C_r = 1174$  years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.360	5	0.00019

$$t_{req} = t_{act} - 2Y_n C_r = 0.358$$

S	E	$t_{req}$	D
20,000	0.8	0.358	16.000

$$= 2t_{req} SE/D = \underline{716} psi$$



#### A) Minimum Thickness Calculation

NPS	Schedule	t <sub>nom</sub>	MAOP
16	10	0.250	275

	D	S	E
275	16.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.137$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.137$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.137	0.241	0.250	79

$$C_a = t_{act} - t_{use} = 0.104$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.000114$ 
 $R_L = C_a / C_r = 912$  years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

#### Next Inspection $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.241	5	0.000114

$$t_{req} = t_{act} - 2Y_n C_r = 0.240$$

S	E	$t_{req}$	D
20,000	0.8	0.240	16.000

$$= 2t_{req} SE/D = \underline{\qquad} 480 \underline{\qquad} psi$$



#### A) Minimum Thickness Calculation

NPS	Schedule	t <sub>nom</sub>	MAOP
16	10	0.250	275

	D	S	E
275	16.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.137$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.137$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.137	0.241	0.250	79

$$C_{a} = t_{act} - t_{use} = 0.104$$

$$C_{r} = t_{prev} - t_{act} / \Delta Y = 0.000114$$

$$R_{L} = C_{a} / C_{r} = 912$$
years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$Y_n$	$C_r$
0.241	5	0.000114

$$t_{req} = t_{act} - 2Y_n C_r = 0.240$$

S	E	$t_{req}$	D
20,000	0.8	0.240	16.000

$$= 2t_{req} SE/D = \underline{\qquad} 480 \underline{\qquad} psi$$



#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
32	STD	0.375	275

	D	S	E
275	32.000	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.274$$
 $t_{eng} = 0.150$ 
 $t_{use} = 0.274$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.274	0.336	0.375	79

$$C_{a} = t_{act} - t_{use} = 0.062$$

$$C_{r} = t_{prev} - t_{act} / \Delta Y = 0.000494$$

$$R_{L} = C_{a} / C_{r} = 126$$
years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.336	5	0.000494

$$t_{req} = t_{act} - 2Y_n C_r = 0.331$$

S	E	$t_{req}$	D
20,000	0.8	0.331	32.000

$$= 2t_{req} SE/D = 331 psi$$

#### A) Minimum Thickness Calculation

NPS	Schedule	$t_{nom}$	MAOP
4	40	0.237	275
	D	C	Г

$$t_{eng} = PD/2(SE+0.4P) = 0.039$$
 $t_{eng} = 0.090$ 
 $t_{use} = 0.090$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.090	0.211	0.237	79

$$C_a = t_{act} - t_{use} = 0.121$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.000329$  year
 $R_L = C_a / C_r = 368$  years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.211	5	0.000329

S	E	$t_{req}$	D
20,000	0.8	0.208	4.5

$$= 2t_{req} SE/D = \underline{\qquad} 1479 \underline{\qquad} psi$$



# Pipe Wall Minimum Thickness, Remaining Life, and MA0P Calculations



#### A) Minimum Thickness Calculation

NPS	Schedule	$t_{nom}$	MAOP
6	40	0.280	275

	D	S	E
275	6.625	20,000	0.8

$$t_{eng} = PD/2(SE+0.4P) = 0.057$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.110$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.110	0.219	0.280	79

$$C_{a} = t_{act} - t_{use} = 0.109$$

$$C_{r} = t_{prev} - t_{act} / \Delta Y = 0.000772$$

$$R_{L} = C_{a} / C_{r} = 141$$
years

#### C) MAOP at Next UT Inspection

Pipe Class: 1

Next Inspection  $(Y_n)$ :

t act	$\boldsymbol{Y}_n$	$C_r$
0.219	5	0.000772

$$t_{req} = t_{act} - 2Y_n C_r = 0.211$$

S	E	$t_{req}$	D
20,000	0.8	0.211	6.625

$$= 2t_{req} SE/D = \underline{1019} psi$$

#### A) Minimum Thickness Calculation

NPS	Schedule	t nom	MAOP
6	40	0.280	275

$$t_{eng} = PD/2(SE+0.4P) = 0.057$$
 $t_{eng} = 0.110$ 
 $t_{use} = 0.110$ 

\*  $t_{use}$  is greater of  $t_{min}$  and  $t_{eng}$ 

#### **B)** Remaining Life

t use	t act	t prev	$\Delta Y$
0.110	0.090	0.280	79

$$C_a = t_{act} - t_{use} = -0.020$$
 $C_r = t_{prev} - t_{act} / \Delta Y = 0.002405$ 
 $R_L = C_a / C_r = -8$  years

#### C) MAOP at Next UT Inspection

Pipe Class: \_\_\_1

Next Inspection  $(Y_n)$ :

t act	$Y_n$	$C_r$
0.090	-4	0.002405

S	E	$t_{req}$	D
20,000	0.8	0.109	6.625

$$= 2t_{req} SE/D = \underline{\qquad} 526 \underline{\qquad} psi$$

# Appendix B Thickness Data/CMLs

Table M1 - API STD 570 Thickness Data & TML								
(b) (3) (A)	Pipe		1				inches)	
TML	Size	Pipe	Thickness Measurements (in inches) (Metal Thickness)					
ID	(in.)	Sch.	Nom.	00	90°	270°	180°	
G1	(b) (3) (a		0.375	0.353	0.348	0.348	0.352	
G2	-	,	0.375	0.343	0.353	0.350	0.357	
G3	-	·	0.375	0.260	0.259	0.255	0.258	
G4 G4	-		0.250	NA	0.231	0.266	0.236	
G5	-		0.375	NA	0.377	0.371	0.377	
G6	-		0.375	0.351	0.351	0.349	0.352	
G7	-		0.375	0.350	0.349	0.352	0.352	
G8	-		0.375	0.354	0.357	0.357	0.354	
G9	-		0.375	0.351	0.349	0.348	0.352	
G10	-		0.375	0.372	0.360	0.376	0.368	
G11	-		0.250	0.238	0.243	0.239	0.241	
G12	-		0.375	NA	0.383	0.355	0.379	
G13	-		0.375	0.352	0.357	0.358	0.354	
G14			0.375	0.351	0.320	0.344	0.346	
G15	-		0.375	0.318	0.348	0.344	0.355	
G16	_		0.375	0.330	0.354	0.357	0.359	
G17	-		0.375	0.383	0.369	0.379	0.367	
G18	-		0.250	0.252	0.252	0.240	0.244	
G19	-		0.375	NA	0.381	0.364	0.381	
G20	-		0.375	0.350	0.348	0.347	0.354	
G21	-		0.375	0.347	0.353	0.352	0.349	
G22	-		0.375	0.346	0.350	0.353	0.354	
G23	-		0.375	0.354	0.348	0.345	0.349	
G24	-		0.375	NA	0.368	0.363	0.367	
G25	-		0.250	NA	0.265	0.235	0.245	
G26	-		0.375	NA	0.343	0.347	0.342	
G27	-		0.375	0.349	0.349	0.357	0.349	
G28	_		0.375	0.346	0.344	0.344	0.335	
G29	-		0.375	0.348	0.356	0.341	0.350	
G30	_		0.375	0.352	0.350	0.352	0.344	
G31	_		0.250	NA	0.257	0.244	0.251	
G32			0.250	0.252	0.245	0.239	0.252	
G33	_		0.375	0.387	0.357	0.395	0.395	
G34	_		0.375	0.381	0.353	0.354	0.356	
G35	_		0.375	0.345	0.347	0.350	0.350	
G36	_		0.375	0.344	0.353	0.352	0.355	
G37	_		0.375	0.362	0.361	0.359	0.355	
G38	_		0.250	NA	NA	0.244	NA	
G39			0.250	NA	0.240	0.246	0.247	
G40			0.375	NA	0.387	0.371	0.400	
G41			0.375	0.342	0.347	0.350	0.358	
G42			0.375	0.356	0.361	0.357	0.363	
G43			0.375	0.350	0.349	0.344	0.340	
G44			0.375	0.351	0.350	0.345	0.350	
G45			_	NA	NA	NA	NA	
G46			0.250	NA	0.256	0.246	0.233	
G47			0.375	NA	0.371	0.371	0.369	

	(b) (3) (A)					
G48		0.375	0.351	0.353	0.349	0.343
G49		0.375	0.356	0.358	0.348	0.362
G50		0.375	0.353	0.349	0.352	0.352
G51		0.375	0.353	0.349	0.352	0.349
G52		0.250	NA	0.258	0.240	0.246
G53		0.250	0.253	0.256	0.237	0.241
G54		0.375	0.391	0.405	0.390	0.386
G55		0.375	0.356	0.354	0.344	0.357
G56		0.375	0.348	0.337	0.345	0.346

Table M1 - API STD 570 Thickness Data & TML (Cont.)								
	Pipe   Thickness Measurements (in inches							inches)
TML		Size	Pipe	(Coating Thickness)				
ID	Location/Description	(in.)	Sch.	Nom.	0°	90°	180°	270°
G1	(b) (3) (A)	(111.)	Jen.		0.021	0.029	0.024	0.028
G2			_	_	0.021	0.023	0.024	0.020
G3			_	_	0.031	0.033	0.028	0.030
G4				_	NA	0.022	0.023	0.023
G5			_	-	NA	0.010	0.022	0.023
G6			_	_	0.025	0.026	0.039	0.022
G7			_	_	0.023	0.025	0.038	0.034
G8			_	_	0.016	0.026	0.033	0.033
G9			_	_	0.016	0.019	0.022	0.020
G10			_	_	0.010	0.012	0.016	0.010
G11			_	_	0.021	0.022	0.011	0.020
G12			_	_	NA	0.022	0.025	0.020
G13			_	_	0.026	0.021	0.023	0.019
G14			_	_	0.024	0.044	0.024	0.029
G15			_	_	0.041	0.031	0.021	0.025
G16			_	_	0.044	0.031	0.033	0.028
G17			_	_	0.017	0.021	0.033	0.019
G18			_	_	0.009	0.007	0.027	0.021
G19			_	_	NA	0.028	0.030	0.023
G20			_	_	0.026	0.026	0.040	0.025
G21			_	_	0.020	0.024	0.038	0.029
G22			-	-	0.037	0.029	0.037	0.035
G23			-	-	0.030	0.036	0.033	0.032
G24			-	-	NA	0.022	0.027	0.028
G25			-	-	NA	0.038	0.027	0.021
G26			-	-	NA	0.024	0.039	0.061
G27			-	-	0.031	0.031	0.057	0.048
G28			-	-	0.028		0.036	0.033
G29			-	-	0.028	0.026	0.040	0.020
G30			-	-	0.026	0.032	0.035	0.031
G31			-	-	NA	0.027	0.038	0.030
G32			-	-	0.025	0.024	0.021	0.034
G33			-	-	0.031	0.035	0.017	0.017
G34			-	-	0.024	0.027	0.044	0.028
G35			-	-	0.035	0.029	0.028	0.034
G36			-	-	0.036	0.022	0.031	0.023
G37			-	-	0.023	0.024	0.026	0.030
G38			-	-	NA	NA	0.025	NA
G39			-	-	NA	0.039	0.031	0.029
G40			-	-	NA	0.016	0.017	0.026
G41			-	-	0.038	0.038	0.060	0.068
G42			-	-	0.026	0.027	0.027	0.027
G43			-	-	0.021	0.028	0.035	0.029
G44			-	-	0.031	0.026	0.034	0.023
G45			-	-	NA	NA	NA	NA
G46			-	-	NA	0.043	0.028	0.024
G47			-	-	NA	0.021	0.025	0.023

(b) (3) (A)						
G48	8	-	0.025	0.026	0.031	0.027
G49	-	3 <b>-</b> 3	0.023	0.028	0.040	0.031
G50	=	121	0.023	0.021	0.028	0.026
G51	-	-	0.028	0.028	0.040	0.032
G52	_	1=1	NA	0.062	0.019	0.025
G53	=		0.044	0.053	0.030	0.034
G54	-	-	0.024	0.033	0.021	0.024
G55	H	-	0.026	0.024	0.051	0.032
G56		-	0.031	0.042	0.040	0.027

	Table M1 - API STD 570 Thickness Data & TML (Cont.)									
		Pipe		-	iess Me			inches)		
TML		Size	Pipe			al Thick				
ID	Location/Description	(in.)	Sch.	Nom.	0°	90°	270°	180°		
H1	(b) (3) (A)	(111.)	10	0.250	0.246	0.244	0.250	0.253		
H2			10	0.250	0.232	0.228	0.241	0.228		
H3			STD	0.230	0.232	0.382	0.368	0.228		
H4			10	0.250	0.261	0.259	0.251	0.247		
H5			10	0.250	0.240	0.236	0.237	0.255		
H6			STD	0.375	0.369	0.406	0.404	0.386		
H7			10	0.250	0.257	0.257	0.255	0.255		
H8			10	0.250	0.239	0.248	0.239	0.237		
H9			STD	0.375	0.395	0.375	0.384	0.402		
H10			10	0.250	0.254	0.252	0.247	0.251		
H11			10	0.250	0.245	0.242	0.233	0.248		
H12			STD	0.375	0.386	0.375	0.379	0.387		
H13			10	0.250	0.223	0.250	0.252	0.252		
H14			10	0.250	0.247	0.248	0.243	0.241		
H15			STD	0.375	0.364	0.371	0.360	0.373		
H16			10	0.250	0.249	0.256	0.251	0.248		
H17			10	0.250	0.243	0.243	0.236	0.228		
H18			STD	0.375	0.401	0.368	0.398	0.410		
H19			10	0.250	0.256	0.258	0.252	0.258		
H20			10	0.250	0.237	0.240	0.242	0.239		
H21			STD	0.375	0.404	0.404	0.398	0.394		
H22			10	0.250	0.268	0.269	0.265	0.269		
H23			10	0.250	0.230	0.249	0.244	0.258		
H24			STD	0.375	0.403	0.413	0.406	0.395		
H25			10	0.250	0.254	0.226	0.254	0.257		
H26			10	0.250	0.227	0.241	0.258	0.249		
H27			STD	0.375	0.409	0.412	0.402	0.395		
H28			10		0.249			0.255		
H29			10	0.250	0.253	0.241	0.229	0.230		
H30			STD	0.375	0.392	0.394	0.392	0.379		
H31			10	0.250	0.245	0.248	0.244	0.247		
H32			10	0.250	0.230	0.237	0.247	0.247		
H33			STD	0.375	0.392	0.413	0.414	0.389		
H34			10	0.250	0.255	0.255	0.254	0.252		
H35			10 STD	0.250	0.239	0.243	0.246	NA 0.302		
H36 H37			STD 10	0.375	0.376	0.392	0.392	0.392		
H38			10	0.250	0.260	0.258	0.256	0.258		
H39			STD	0.230	0.246	0.246	0.240	0.239		
H40			10	0.373	0.380	0.373	0.390	0.388		
H41			10	0.250	0.249	0.237	0.244	0.238		
H42			STD	0.230	0.242	0.237	0.242	0.238		
H43			10	0.250	0.241	0.239	0.236	0.382		
H44			10	0.250	0.233	0.239	0.230	0.236		
H45			STD	0.230	0.404	0.237	0.409	0.413		
H46			10	0.250	0.254	0.240	0.409	0.413		
H47			10	0.250	0.225	0.240	0.239	0.242		
114/			10	0.430	0.223	0.213	0.437	0.242		

(b) (3) (A)					
H48	0.375	0.404	0.386	0.386	0.401
H49	0.250	0.254	0.251	0.250	0.251
H50	0.250	0.248	0.249	0.245	0.245
H51	0.375	0.411	0.407	0.391	0.385
H52	0.250	0.411	0.407	0.351	0.363
		500 Unit 1974 August		100000000000000000000000000000000000000	Market State Control
H53	0.250	0.239	0.242	0.245	0.243
H54	0.375	0.403	0.416	0.421	0.388
H55	0.250	0.254	0.256	0.255	0.259
H56	0.250	0.250	0.243	0.247	0.246
H57	0.375	0.388	0.404	0.405	0.406
H58	0.250	0.263	0.260	0.263	0.261
H59	0.250	0.254	0.224	0.218	0.237
H60	0.375	0.389	0.385	0.381	0.391
H61	0.250	0.246	0.248	0.246	0.248
H62	0.250	0.224	0.242	0.231	0.248
H63	0.375	0.404	0.405	0.396	0.401
H64	0.250	0.228	0.260	0.261	0.258
H65	0.250	0.234	0.230	0.265	0.246
H66	0.375	0.234	0.230	0.203	0.240
H67	0.250				
		0.237	0.243	0.238	0.240
H68	0.250	0.242	0.217	0.238	0.236
H69	0.375	0.415	0.419	0.411	0.413
H70	0.250	0.225	0.256	0.252	0.255
H71	0.250	0.243	0.231	0.243	0.241
H72	0.375	0.380	0.368	0.390	0.388
H73	0.250	0.247	0.249	0.244	0.251
H74	0.250	0.239	0.234	0.218	0.242
H75	0.375	0.405	0.393	0.376	0.409
H76	0.250	0.256	0.255	0.252	0.255
H77	0.250	0.254	0.231	0.253	0.250
H78	0.375	0.391	0.396	0.391	0.390
H79	0.250	0.252	0.250	0.245	0.252
H80	0.250	0.226	0.240	0.244	0.242
H81	0.375	0.398	0.406	0.408	0.387
H82	0.250	0.256	0.256	0.250	0.253
H83	0.250	0.235	0.229	0.245	0.240
H84	0.375	0.360	0.376	0.380	0.370
H85	0.250	0.254	0.254	0.250	0.250
H86	0.250	0.261	0.240	0.258	0.241
H87	0.375	0.408	0.397	0.380	0.409
H88	0.250	0.359	0.250	0.252	0.255
H89	0.250	0.238	0.250	0.252	0.253
H90	0.375	0.404	0.230	0.384	0.233
		_			
H91	0.250	0.250	0.243	0.243	0.237
H92	0.250	0.246	0.235	0.239	0.232
H93	0.375	0.388	0.381	0.384	0.384
H94	0.250	0.245	0.246	0.239	0.241
H95	0.250	0.239	0.225	0.239	0.239
H96	0.375	0.387	0.405	0.408	0.378
H97	0.250	0.248	0.250	0.246	0.252
H98	0.250	0.237	0.235	0.247	0.238
H99	0.375	0.399	0.385	0.352	0.397
	25				

(b) (3) (A)					
H100	0.250	0.253	0.253	0.250	0.252
H101	0.250	0.246	0.248	0.249	0.247
H102	0.375	0.393	0.357	0.391	0.387
H103	0.250	0.251	0.250	0.251	0.218
H104	0.250	0.242	0.206	0.246	0.235
H105	0.375	0.391	0.373	0.399	0.402
H106	0.250	0.260	0.261	0.227	0.255
H107	0.250	0.232	0.241	0.245	0.240
H108	0.375	0.388	0.387	0.384	0.382
H109	0.250	0.249	0.251	0.250	0.249
H110	0.250	0.233	0.203	0.210	0.237
H111	0.375	0.404	0.402	0.390	0.407
H112	0.250	0.236	0.248	0.239	NA
H113	0.250	0.241	0.244	0.239	0.244
H114	0.375	0.389	0.387	0.392	0.403
H115	0.250	0.250	0.251	0.243	0.250
H116	0.250	0.245	0.252	0.243	0.252
H117	0.375	0.388	0.392	0.394	0.401
H118	0.250	0.245	0.239	0.241	0.249
H119	0.250	0.235	0.236	0.235	0.222
H120	0.375	0.420	0.409	0.367	0.419
H121	0.250	0.262	0.265	0.253	0.259
H122	0.250	0.224	0.224	0.236	0.236
H123	0.375	0.384	0.368	0.384	0.390
H124	0.250	0.255	0.259	0.193	0.248
H125	0.250	0.234	0.221	0.231	0.237
H126	0.375	0.408	0.406	0.406	0.403
H127	0.250	0.254	0.257	0.256	0.257
H128	0.250	0.255	0.248	0.244	0.239
H129	0.375	0.378	0.384	0.385	0.373
H130	0.250	0.251	0.252	0.249	0.257
H131 H132	0.250	0.240	0.237	0.255	0.227
H132 H133	0.375	0.369	0.383	0.388	0.371
H134	0.250	0.247	0.242	0.233	0.244
H135	0.230	0.224	0.229	0.400	0.233
H136	0.250	0.346	0.346	0.400	0.400
H137	0.250	0.238	0.239	0.239	0.239
H138	0.230	0.238	0.239	0.239	0.239
H139	0.250	0.232	0.250	0.372	0.256
H140	0.250	0.232	0.236	0.234	0.229
H141	0.375	0.203	0.390	0.380	0.378
H142	0.250	0.246	0.248	0.244	0.249
H143	0.250	0.244	0.244	0.247	0.246
H144	0.375	0.395	0.375	0.386	0.407
H145	0.250	0.247	0.249	0.248	0.238
H146	0.250	0.233	0.229	0.256	0.240
H147	0.375	0.401	0.411	0.403	0.403
H148	0.250	0.239	0.236	0.244	0.244
H149	0.250	0.237	0.248	0.248	0.241
H150	0.375	0.411	0.420	0.414	0.403
H151	0.250	0.250	0.250	0.249	0.253

	ER-JDP	nn,ni-ke	D HILL FF	ACILII I -P	TPING-IVIA
(b) (3) (A)					
H152	0.250	0.239	0.242	0.244	0.247
H153	0.375	0.407	0.420	0.410	0.403
H154	0.250	0.216	0.241	0.242	0.244
H155	0.250	0.242	0.242	0.226	0.245
H156	0.375	0.399	0.401	0.403	0.387
H157	0.250	0.243	0.246	0.240	0.240
H158	0.250	0.225	0.241	0.238	0.242
H159	0.375	0.386	0.378	0.384	0.396
H160	0.250	0.253	0.247	0.250	0.245
H161	0.250	0.230	0.238	0.240	0.232
H162	0.375	0.393	0.395	0.403	0.384
H163	0.250	0.244	0.246	0.253	0.250
H164	0.250	0.269	0.251	0.192	0.248
H165	0.375	0.394	0.375	0.395	0.396
H166	0.250	0.248	0.251	0.248	0.246
H167	0.250	0.244	0.237	0.248	0.228
H168	0.375	0.388	0.390	0.381	0.390
H169	0.250	0.252	0.251	0.249	0.222
H170	0.250	0.251	0.250	0.245	0.245
H171	0.375	0.370	0.383	0.378	0.356
H172	0.250	0.249	0.242	0.241	0.247
H173	0.250	0.245	0.245	0.245	0.247
H174	0.375	0.386	0.382	0.369	0.359
H175	0.250	0.253	0.254	0.252	0.247
H176	0.250	0.238	0.236	0.235	0.229
H177	0.375	0.374	0.386	0.409	0.395
H178	0.375	0.373	0.360	0.321	0.351
H179	0.250	NA	0.248	0.246	0.243
H180	0.375	NA	0.344	0.387	0.412
H181	0.375	0.371	0.371	0.380	0.351
H182	0.250	0.241	0.240	0.242	0.239
H183	0.375	0.379	0.388	0.376	0.379

Table M1 - API STD 570 Thickness Data & TML (Cont.)									
		Pipe		-	ess Me			inches)	
TML		Size	Pipe	- I III CILI		ng Thic		menesy	
ID	Location/Description	(in.)	Sch.	Nom.					
H1	(b) (3) (A)	(111.)	- Jen.	-	0.023	0.024	0.033	<b>180°</b> 0.012	
H2			_	_	0.031	0.033	0.014	0.030	
H3			_	_	0.022	0.025	0.021	0.019	
H4			_	_	0.009	0.008	0.012	0.014	
H5			_	_	0.008	0.007	0.009	0.051	
H6			_	_	0.023	0.010	0.008	0.007	
H7			_	_	0.007	0.009	0.004	0.008	
H8			_	_	0.008	0.004	0.006	0.007	
H9			_	_	0.009	0.007	0.011	0.006	
H10			_	_	0.003	0.004	0.006	0.003	
H11			_	_	0.004	0.005	0.007	0.004	
H12			_	_	0.007	0.006	0.005	0.006	
H13			-	-	0.019	0.003	0.005	0.008	
H14			_	_	0.005	0.008	0.012	0.007	
H15			_	_	0.018	0.012	0.013	0.006	
H16			_	_	0.019	0.009	0.008	0.006	
H17			-	-	0.008	0.011	0.007	0.005	
H18			-	-	0.009	0.010	0.009	0.007	
H19			-	-	0.008	0.005	0.010	0.003	
H20			-	-	0.011	0.009	0.010	0.012	
H21			-	-	0.007	0.009	0.007	0.005	
H22			-	-	0.004	0.005	0.010	0.004	
H23			-	-	0.005	0.005	0.011	0.007	
H24			-	-	0.007	0.007	0.007	0.008	
H25			-	-	0.006	0.019	0.006	0.003	
H26			-	-	0.016	0.016	0.016	0.016	
H27			-	-	0.007	0.009	0.009	0.007	
H28			-	-		0.006		0.007	
H29			-	-	0.010	0.008	0.036	0.035	
H30			-	-	0.006	0.010	0.012	0.009	
H31			-	-	0.004	0.005	0.004	0.003	
H32			-	-	0.005	0.003	0.005	0.009	
H33			-	-	0.008	0.005	0.004	0.011	
H34			-	-	0.009	0.006	0.010	0.005	
H35			-	-	0.011	0.010	0.008	NA	
H36			-	-	0.006	0.008	0.009	0.009	
H37			-	-	0.006	0.007	0.008	0.008	
H38				-	0.005	0.007	0.012	0.020	
H39			-	-	0.009	0.009	0.016	0.011	
H40			-	-	0.015	0.017	0.011	0.010	
H41			-	-	0.010	0.009	0.011	0.014	
H42			-	-	0.010	0.006	0.032	0.008	
H43			-	_	0.008	0.012	0.013	0.009	
H44			-	-	0.017	0.014	0.010	0.009	
H45			-	-	0.019	0.018	0.012	0.013	
H46			-	-	0.007	0.018	0.007	0.020	
H47			-	-	0.012	0.017	0.011	0.012	

(b) (3) (A)	-			Š.			
H48		<u> </u>	-	0.004	0.007	0.006	0.012
H49		-	-	0.004	0.008	0.003	0.005
H50	3		121	0.007	0.005	0.006	0.008
H51	-	_	2-2	0.013	0.006	0.007	0.029
H52	3	_	_	0.004	0.006	0.006	0.008
H53	-	_	-	0.006	0.005	0.003	0.004
H54	3	Ξ.	-	0.007	0.003	0.010	0.008
H55	<u> </u>	<u>-</u>		0.007	0.009	0.010	0.003
H56		100		0.011	0.009	0.009	0.013
		-		0.012	0.009	0.009	0.000
H57 H58		-	200				0.011
	3	-	y=2	0.009	0.009	0.012	
H59		-	(=)	0.014	0.012	0.012	0.013
H60		Ē.	1552	0.012	0.012	0.016	0.013
H61		-	-	0.006	0.008	0.006	0.011
H62		-	-	0.007	0.009	0.008	0.004
H63	<u></u>	=	()	0.015	0.008	0.010	0.015
H64		-	-	0.017	0.005	0.005	0.005
H65		Π.,	15.72	0.019	0.008	0.010	0.006
H66	3	_	3	0.011	0.012	0.013	0.011
H67		8	1	0.007	0.005	0.006	0.005
H68		-	(=)	0.005	0.006	0.008	0.009
H69	-	2	121	0.007	0.006	0.004	0.004
H70		<u>.</u>	5 <del>-</del> 2	0.014	0.005	0.007	0.005
H71		<u>~</u>	848	0.005	0.008	0.008	0.010
H72		_	-	0.008	0.008	0.008	0.011
H73		-	-	0.006	0.003	0.007	0.003
H74	<u>6</u> 5		121	0.005	0.006	0.007	0.005
H75	-	_	0-1	0.009	0.009	0.006	0.004
H76		_	224	0.006	0.005	0.010	0.016
H77	_	_		0.004	0.003	0.008	0.005
H78	-	<u> </u>	-	0.008	0.007	0.006	0.009
H79	· ·	8 1	828	101111111111111111111111111111111111111	0.007		No. of the last of
H80	4	<u> </u>		0.003	0.008	0.009	0.007
H81	<u> </u>	-	1000				
H82	-	-	121	0.007	0.007	0.009	0.006
		=	<u>1772</u>	0.003	0.003	0.010	0.008
H83	5	-	2000	0.006	0.007	0.006	0.007
H84		Ω.	150	0.015	0.008	0.006	0.007
H85		-	(=)	0.004	0.005	0.005	0.007
H86		Ē	-	0.006	0.003	0.008	0.008
H87		-	(=)	0.006	0.006	0.013	0.006
H88		ŭ	12	0.023	0.006	0.004	0.005
H89		-	5 <del>-</del> 5	0.005	0.006	0.007	0.005
H90		<u>=</u>	( <b>=</b> )	0.008	0.007	0.018	0.006
H91		ā	1557	0.006	0.006	0.007	0.013
H92		-	-	0.005	0.007	0.006	0.005
H93			121	0.008	0.026	0.011	0.011
H94				0.025	0.013	0.013	0.013
H95		<u>=</u>	(1 <u></u> )	0.005	0.003	0.003	0.012
H96		Ī.	-	0.007	0.006	0.005	0.008
H97		-	3-3	0.004	0.005	0.006	0.006
H98		9	-	0.005	0.005	0.009	0.006
H99		-	3-3	0.011	0.008	0.011	0.012

(b) (3) (A)						
H100	H	-	0.006	0.007	0.005	0.011
H101	-	2=3	0.005	0.005	0.007	0.008
H102		123	0.016	0.013	0.006	0.015
H103	_	-	0.006	0.010	0.007	0.019
H104	_	-	0.004	0.018	0.007	0.009
H105	_	<u> </u>	0.009	0.007	0.010	0.004
H106	-	-	0.005	0.006	0.022	0.009
H107	2	-	0.008	0.005	0.007	0.007
H108	-	0-0	0.004	0.016	0.010	0.007
H109	_	2-3	0.006	0.005	0.005	0.005
H110	_	(-)	0.007	0.006	0.006	0.003
H111	-	(=)	0.006	0.009	0.004	0.003
H112			0.004	0.007	0.004	NA
H113	<u> </u>	-	0.004	0.017	0.003	0.006
H114	-	12	0.007	0.007	0.003	0.000
H115		+	0.016	0.017	0.007	0.009
		( <del>-</del>				
H116		200	0.005	0.004	0.008	0.010
H117		157	0.018	0.013	0.007	0.010
H118		(=)	0.004	0.008	0.008	0.005
H119	=	-	0.006	0.016	0.013	0.005
H120		(=)	0.008	0.003	0.013	0.004
H121		121	0.006	0.006	0.007	0.006
H122		. 550	0.004	0.006	0.011	0.012
H123		200	0.007	0.006	0.006	0.007
H124	-	550	0.005	0.008	0.030	0.009
H125		-	0.012	0.013	0.013	0.009
H126	<u>-</u>	-	0.007	0.010	0.013	0.011
H127		3-1	0.005	0.005	0.009	0.007
H128		120	0.006	0.007	0.006	0.004
H129		3 <del>-</del> 1	0.013	0.009	0.011	0.008
H130	-	3=3	0.009	0.008	0.014	0.004
H131	9	-	0.007	0.007	0.016	
H132	<u> </u>	1-1	0.009	0.006	0.007	0.007
H133	-	-	0.008	0.010	0.009	0.009
H134	-	9-2	0.010	0.008	0.012	0.014
H135	-	1-1	0.008	0.009	0.007	0.008
H136	=	150	0.014	0.014	0.011	0.007
H137	_	-	0.022	0.020	0.033	0.022
H138	8	-	0.015	0.009	0.017	0.013
H139	-	(=)	0.039	0.015	0.014	0.016
H140	-	121	0.026	0.010	0.018	0.028
H141	-	979	0.021	0.014	0.029	0.019
H142	-	(=)	0.006	0.004	0.010	0.006
H143	<u>-</u>	150	0.007	0.006	0.005	0.008
H144	-	(=)	0.007	0.006	0.008	0.006
H145	2	121	0.006	0.005	0.006	0.013
H146	-	(=)	0.009	0.006	0.027	0.007
H147	-	200	0.006	0.006	0.011	0.005
H148		9=2	0.009	0.020	0.008	0.014
H149	-	(=)	0.011	0.009	0.016	0.013
H150	-	-	0.014	0.006	0.007	0.006
H151	-	3-3	0.006	0.006	0.007	0.004
	Se ses	i.			And the state of t	100000000000000000000000000000000000000

	71 1 101 111			72.			
	(b) (3) (A)			0.005	0.00	0.00.	0.006
H152		<u> </u>	-	0.005	0.005	0.005	0.006
H153			3-1	0.008	0.006	0.015	0.006
H154		-	121	0.023	0.006	0.005	0.005
H155		_ =	-	0.006	0.009	0.011	0.015
H156		-	-	0.009	0.011	0.019	0.009
H157		-	(7)	0.006	0.005	0.009	0.007
H158		-	-	0.005	0.008	0.008	0.017
H159		8	-	0.009	0.007	0.005	0.007
H160		-	7-1	0.005	0.010	0.010	0.007
H161		-	-	0.005	0.005	0.006	0.008
H162		-	577	0.004	0.007	0.021	0.003
H163		=	(=)	0.015	0.012	0.017	0.015
H164		-	1072	0.020	0.017	0.046	0.016
H165			-	0.014	0.024	0.025	0.013
H166		2	121	0.004	0.005	0.007	0.005
H167		-	(=)	0.007	0.012	0.008	0.007
H168		-	742	0.020	0.020	0.015	0.020
H169		-	150	0.006	0.008	0.019	0.018
H170		-	(=)	0.007	0.008	0.005	0.006
H171		=	-	0.007	0.006	0.010	0.013
H172		-	(=)	0.003	0.006	0.008	0.006
H173		-	121	0.008	0.007	0.010	0.009
H174				0.008	0.014	0.008	0.021
H175		<u> =</u>	-	0.009	0.006	0.009	0.007
H176		-	(5)	0.004	0.004	0.008	0.014
H177		-	-	0.020	0.020	0.010	0.006
H178		-	120	20		62	121
H179		-	3-1	-/	-	10.	-
H180		-	-		_	-	7=1
H181		-	-	-	-	107	5 <del>-</del> 2
H182		-	3=1	-	-	-	(=)
H183		=	-	-	· •	-	-

	Table M1 - API STD 570 Thickness Data & TML (Cont.)							
(b	) (3) (A)			Thickn	ess Mea	asureme	ents (in	inches)
TML					(Meta	al Thick	mess)	
ID				Nom.	0°	90°	270°	180°
P1				0.375	0.374	0.382	0.391	0.385
P2			į.	0.250	0.237	0.233	0.234	0.224
P3				0.375	0.356	0.361	0.366	0.356
P4			_	0.375	0.366	0.354	0.375	0.363
P5				0.375	0.366	0.371	0.360	0.370
P6				0.375	0.362	0.361	0.389	0.374
P7				0.375	0.389	0.396	0.395	0.354
P8			_	0.375	0.411	0.408	0.387	NA
P9				0.250	0.255	0.255	0.252	0.251
P10			70-	0.375	0.346	0.362	0.355	0.356
P11				0.375	0.414	0.390	0.397	0.420
P12				0.375	0.399	0.396	0.369	0.380
P13				0.375	0.380	0.365	0.360	0.387
P14				0.375	0.391	0.390	0.368	0.375
P15				0.375	0.360	0.381	0.385	0.380
P16				0.375	0.384	0.377	0.385	0.374
P17				0.375	0.341	0.347	0.347	0.343
P18				0.375	0.373	0.372	0.318	0.360
P19				0.375	0.374	0.356	0.366	0.361
P20				0.375	0.354	0.376	0.360	0.359
P21			<u> </u>	0.375	0.334	0.370	0.332	0.330
P22				0.375	0.378	0.339	0.332	0.346
P23				0.375	0.367	0.343	0.310	0.346
P24				0.375	0.307	0.303	0.347	0.400
P25				0.375	0.411	0.413	0.373	NA
P26			——————————————————————————————————————	0.375	_			0.374
P26 P27			<u> </u>	0.375	0.376	0.357	0.347	0.374
P27				0.375	0.308	0.333		
			70	0.375			0.384	0.408
P29			-		0.384		0.339	0.360
P30 P31			- 1	0.375	0.381	0.372	0.333	0.357
A40 20 A A A A A A A A A A A A A A A A A A					0.400	7.000.000.000	0.416	0.396
P32 P33				0.375	0.379	0.368	0.362	0.381
P33				0.375	0.372		0.359	0.375
					0.328	0.359	0.383	
P35				0.375	0.386	0.391	0.389	0.395
P36				0.375	0.381	0.385	0.387	0.384
P37			N-	0.375	0.378	0.366	0.334	0.387
P38			- S	0.375	0.413	0.410	0.399	NA 0.410
P39				0.375	0.417	0.409	0.384	0.410
P40				0.375	0.355	0.337	0.373	0.346
P41				0.375	0.367	0.385	0.386	0.385
P42				0.375	0.356	0.368	0.362	0.320
P43				0.375	0.381	0.373	0.376	0.381
P44				0.375	0.379	0.365	0.375	0.369
P45				0.375	0.401	0.392	0.395	0.387
P46				0.375	0.358	0.371	0.379	0.352
P47				0.375	0.411	0.409	0.369	0.395

	(b) (3) (A)				
P48	0.375	0.411	0.421	0.427	0.437
P49	0.375	0.376	0.370	0.333	0.349
P50	0.375	0.379	0.372	0.373	0.371
P51	0.375	0.360	0.363	0.382	0.367
P52	0.375	0.396	0.391	0.391	0.390
P53	0.375	0.386	0.379	0.373	0.367
P54	0.375	0.384	0.380	0.363	0.378
P55	0.375	0.380	0.381	0.375	0.370
P56	0.375	0.379	0.381	0.387	0.397
P57	0.375	0.374	0.381	0.360	0.371
P58	0.375	0.361	0.372	0.357	0.357
P59	0.375	0.351	0.377	0.375	0.364
P60	0.375	0.379	0.356	0.320	0.363
P61	0.375	0.396	0.395	0.383	0.397
P62	0.375	0.367	0.355	0.364	0.380
P63	0.375	0.418	0.402	0.405	0.408
P64	0.375	0.377	0.368	0.359	0.357
P65	0.375	0.381	0.363	0.357	0.381
P66	0.375	0.400	0.400	0.394	0.371
P67	0.375	0.360	0.400	0.373	0.374
P68	0.375	0.354	0.373	0.368	0.354
P69	0.375	0.378	0.371	0.363	0.360
P70	0.375	0.370	0.371	0.364	0.359
P71	0.375	0.370	0.371	0.377	0.339
P71	0.375	0.381	0.396	0.400	0.389
P73	0.375				
		0.396	0.411	0.410	0.409
P74	0.375	0.402	0.374	0.362	0.409
P75	0.375	0.381	0.394	0.389	0.369
P76	0.375	0.392	0.378	0.354	0.377
P77	0.375	0.378	0.371	0.373	0.378
P78	0.375	0.394	0.374	0.371	0.369
P79	0.375				0.361
P80	0.375	0.409	0.393	0.375	0.407
P81	0.375	0.364	0.372	0.361	0.363
P82	0.375	0.371	0.362	0.348	0.362
P83	0.375	0.344	0.353	0.356	0.339
P84	0.375	0.376	0.364	0.352	0.348
P85	0.375	0.381	0.385	0.344	0.383
P86	0.375	0.395	0.383	0.361	0.318
P87	0.375	0.378	0.369	0.350	0.389
P88	0.375	0.341	0.335	0.345	0.354
P89	0.375	0.359	0.366	0.362	0.376
P90	0.375	0.378	0.363	0.354	0.373
P91	0.375	0.378	0.374	0.365	0.377
P92	0.375	0.357	0.358	0.349	0.356
P93	0.375	0.366	0.371	0.365	0.341
P94	0.375	0.382	0.366	0.343	0.348
P95	0.375	0.346	0.380	0.349	0.322
P96	0.375	0.371	0.381	0.377	0.388
P97	0.375	0.370	0.369	0.354	0.373
P98	0.375	0.345	0.390	0.347	0.359
P99	0.375	0.332	0.374	0.367	0.369
	Parameter and the second secon				

	(b) (3) (A)					
P100		0.375	0.386	0.402	0.385	0.403
P101		0.375	0.381	0.382	0.368	0.377
P102		0.375	0.390	0.382	0.362	0.389
P103		0.375	0.360	0.368	0.356	0.372
P104		0.375	0.381	0.389	0.365	0.358
P105		0.375	0.368	0.377	0.360	0.349
P106		0.375	0.354	0.355	0.371	0.399
P107		0.375	0.365	0.378	0.361	0.373
P108		0.375	0.393	0.375	0.356	0.379
P109		0.375	0.397	0.392	0.355	0.359
P110		0.375	0.364	0.372	0.367	0.380
P111		0.375	0.380	0.371	0.339	0.368
P112		0.375	0.371	0.380	0.377	0.376
P113		0.375	0.357	0.367	0.381	0.383
P114		0.375	0.364	0.358	0.363	0.376
P115		0.375	0.370	0.326	0.373	0.386
P116		0.375	0.397	0.371	0.341	0.372
P117		0.375	0.360	0.362	0.352	0.366
P118		0.375	0.373	0.366	0.336	0.366
P119		0.375	0.372	0.359	0.362	0.371
P120		0.375	0.255	0.250	0.243	0.248
P121		0.375	0.253	0.252	0.240	0.248
P122		0.375	0.346	0.353	0.351	0.353
P123		0.375	0.380	0.380	0.354	0.347
P124		0.375	0.376	0.357	0.397	0.391
P125		0.375	0.388	0.377	0.367	0.386
P126		0.375	0.380	0.380	0.345	0.356
P127		0.375	0.378	0.380	0.348	0.381
P128		0.375	NA	0.380	0.370	0.376
P129		0.375	0.360	0.379	0.350	0.350
P130		0.375	0.340	0.349	0.328	0.343
P131		0.375	0.389	0.381	0.366	0.371
P132		0.375	0.366	0.361	0.362	0.361
P133		0.375	0.377	0.378	0.344	0.338
P134		0.375	0.389	0.371	0.367	0.375
P135		0.375	0.360	0.366	0.365	0.358
P136		0.375	0.383	0.381	0.367	0.367
P137		0.375	0.372	0.357	0.349	0.363
P138		0.375	0.379	0.386	0.375	0.360
P139		0.375	0.360	0.354	0.314	0.328
P140		0.375	0.375	0.369	0.345	0.353
P141		0.375	0.371	0.352	0.344	0.344
P142		0.375	0.424	0.392	0.357	0.389
P143		0.375	0.377	0.377	0.397	0.361
P144		0.375	0.385	0.388	0.389	0.395
P145		0.375	0.378	0.375	0.362	0.360
P146		0.375	0.384	0.341	0.354	0.352
P147		0.375	0.386	0.381	0.384	0.361
		100,000,000,000			1	

Table M1 - API STD 570 Thickne	ess Data &	& TM	L (Co	nt.)	
(b) (3) (A)		iess Mea			inches)
TML			ng Thic		
ID	Nom.	0°	90°	270°	180°
P1	-	0.013	0.013	0.009	0.011
P2	-	0.017	0.011	0.012	0.011
P3	-	0.010	0.013	0.009	0.008
P4	-	0.023	0.018	0.011	0.016
P5	-	0.012	0.010	0.014	0.009
P6	-	0.010	0.009	0.010	0.008
P7	-	0.007	0.009	0.009	0.011
P8	-	0.011	0.011	0.008	NA
P9	-	0.012	0.010	0.007	0.011
P10	-	0.009	0.006	0.009	0.008
P11	-	0.012	0.007	0.012	0.008
P12	-	0.016	0.010	0.010	0.010
P13	-	0.008	0.007	0.011	0.013
P14	-	0.010	0.016	0.008	0.012
P15	-	0.011	0.007	0.011	0.008
P16	-	0.020	0.016	0.017	0.019
P17	-	0.010	0.010	0.006	0.010
P18	-	0.010	0.010	0.012	0.008
P19	-	0.012	0.010	0.010	0.008
P20	-	0.014	0.009	0.011	0.013
P21	-	0.014	0.011	0.008	0.011
P22	-	0.012	0.010	0.021	0.014
P23	-	0.009	0.008	0.009	0.006
P24	-	0.011	0.009	0.011	0.006
P25	-	0.012	0.011	0.009	NA
P26	-	0.010	0.007	0.013	0.008
P27	_	0.014	0.019	0.031	0.018
P28	-	0.017	0.012	0.012	0.008
P29	-	0.018	0.013	0.012	0.006
P30	-	0.009	0.011	0.011	0.006
P31	-	0.015	0.008	0.010	0.011
P32	-	0.015	0.008	0.006	0.007
P33	-	0.011	0.008	0.014	0.011
P34 P35	-	0.014	0.018	0.014	0.028
P36	-	0.012		0.009	0.018
P30 P37	_	0.008	0.007	0.010	0.010
P37 P38	-	0.013	0.008	0.009	0.013
P39	_	0.013	0.008	0.008	0.007
P40	-	0.009	0.007	0.008	0.007
P41	-	0.013	0.013	0.010	0.010
P42	_	0.015	0.010	0.003	0.010
P43	_	0.010	0.011	0.013	0.010
P44	-	0.010	0.012	0.006	0.011
P45	_	0.005	0.013	0.000	0.011
P46	-	0.020	0.013	0.009	0.011
P47	_	0.009	0.007	0.019	0.006
		0.007	0.007	0.000	0.000

(b) (3) (A)		2/2			
P48	-	0.011	0.006	0.007	0.007
P49	1=1	0.011	0.006	0.005	0.011
P50	-	0.010	0.007	0.009	0.009
P51	1 <del>-</del> 0	0.013	0.006	0.005	0.011
P52	9=6	0.022	0.016	0.016	0.016
P53	-	0.017	0.007	0.007	0.011
P54		0.010	0.006	0.008	0.007
P55	9 <del>-</del> 1	0.008	0.012	0.007	0.012
P56	;-:	0.009	0.008	0.009	0.006
P57	-	0.010	0.008	0.008	0.010
P58	; <del>-</del> :	0.010	0.010	0.009	0.008
P59	1-1	0.013	0.009	0.010	0.009
P60	-	0.013	0.012	0.014	0.014
P61	-	0.010	0.010	0.010	0.010
P62	-	0.011	0.006	0.007	0.008
P63	( <del>*</del> )	0.029	0.016	0.022	0.022
P64	-	0.013	0.011	0.014	0.009
P65		0.011	0.013	0.015	0.011
P66	1-1	0.013	0.010	0.008	0.012
P67	-	0.011	0.011	0.008	0.008
P68	3 <del>-</del> 2	0.012	0.009	0.011	0.010
P69		0.012	0.011	0.008	0.007
P70	i <del>-</del> :	0.022	0.007	0.007	0.009
P71	3=1	0.012	0.008	0.005	0.008
P72		0.013	0.011	0.007	0.010
P73	-	0.014	0.009	0.006	0.007
P74	85	0.011	0.006	0.010	0.008
P75	( <del>-</del> )	0.011	0.008	0.007	0.008
P76	120	0.014	0.010	0.010	0.008
P77	:=:	0.008	0.007	0.007	0.011
P78	-	0.013	0.006	0.005	0.006
P79	-		0.008		
P80	-	0.011	0.007	0.005	0.017
P81	-	0.008	0.006	0.007	0.007
P82		0.009	0.013	0.007	0.008
P83	( <del>L</del> )	0.007	0.006	0.006	0.008
P84		0.012	0.008	0.012	0.024
P85	-	0.010	0.009	0.011	0.011
P86	-	0.016	0.011	0.010	0.021
P87	<u></u>	0.012	0.008	0.007	0.006
P88	-	0.014	0.013	0.015	0.014
P89	( <del>-</del>	0.014	0.011	0.011	0.011
P90	141	0.010	0.007	0.010	0.008
P91	-	0.013	0.011	0.011	0.013
P92	-	0.014	0.010	0.011	0.011
P93	-	0.013	0.011	0.013	0.018
P94	<u></u>	0.009	0.009	0.011	0.010
P95	-	0.010	0.013	0.011	0.008
P96		0.009	0.007	0.010	0.011
P97	-	0.018	0.014	0.013	0.013
P98	-	0.011	0.009	0.016	0.009
P99		0.027	0.011	0.006	0.010

(b) (3) (A)	ER-JBP	пп,пі-ке	D HILL FF	CILII I -P	IPING-MA
	45000	0.022	0.000	0.012	0.000
P100	-	0.022	0.009	0.012	0.008
P101	3=1	0.012	0.006	0.009	0.007
P102		0.011	0.010	0.011	0.011
P103	1 <del>-</del> 1	0.015	0.008	0.020	0.007
P104		0.014	0.010	0.006	0.009
P105		0.007	0.008	0.011	0.008
P106		0.009	0.007	0.015	0.011
P107	-	0.008	0.008	0.008	0.012
P108	3-3	0.010	0.008	0.009	0.009
P109	7-1	0.008	0.008	0.010	0.013
P110	9-1	0.018	0.012	0.012	0.011
P111	(12)	0.008	0.008	0.006	0.049
P112	150	0.009	0.009	0.010	0.009
P113	<u> </u>	0.009	0.007	0.008	0.008
P114	121	0.012	0.007	0.012	0.008
P115	(=)	0.011	0.006	0.007	0.011
P116	543	0.005	0.012	0.010	0.012
P117	150	0.010	0.009	0.011	0.013
P118	(=)	0.007	0.006	0.008	0.007
P119	-	0.012	0.011	0.017	0.015
P120	0.00	0.007	0.008	0.007	0.009
P121	TES	0.014	0.008	0.014	0.008
P122	9=2	0.008	0.006	0.007	0.011
P123	7=1	0.010	0.007	0.007	0.007
P124	150	0.007	0.007	0.011	0.014
P125	1-0	0.008	0.007	0.012	0.008
P126	-	0.013	0.009	0.012	0.011
P127	-	0.009	0.008	0.006	0.005
P128	12	0.011	0.007	0.005	0.007
P129		NA	0.233	0.233	0.233
P130		0.011	0.010	0.010	0.010
P131	-	0.011	0.010	0.012	0.011
P132	-	0.016	0.017	0.02	0.018
P133		0.012	0.01	0.01	0.01
P134	: <del>-</del>	0.007	0.007	0.011	0.007
P135	343	0.01	0.015	0.011	0.027
P136		0.008	0.008	0.008	0.01
P137	-	0.009	0.011	0.012	0.009
P138	-	0.009	0.015	0.009	0.013
P139	1-1	0.008	0.007	0.01	0.011
P140		0.012	0.007	0.009	0.006
P141	1 <del>-</del> 1	0.011	0.008	0.015	0.016
P142	(2)	0.011	0.009	0.011	0.012
P143	-	0.007	0.012	0.014	0.009
P144	-	0.006	0.008	0.007	0.022
P145		0.006	0.006	0.01	0.014
P146	-	0.009	0.009	0.009	0.009
P147	120	0.01	0.017	0.007	0.009

	Table M1 - API STD 570 Thickness Data & TML (Cont.)						
	(b) (3) (A)	Thickn	ess Mea	asureme	ents (in	inches)	
TML			(Meta	al Thick	(ness		
ID		Nom.	0°	90°	270°	180°	
S1		0.250	0.246	0.243	0.241	0.242	
S2		0.250	0.245	0.245	0.241	0.246	
S3		0.250	0.248	0.247	0.245	0.248	
S4		0.250	0.244	0.245	0.241	0.243	
S5		0.250	0.244	0.241	0.239	0.244	
S6		0.250	0.243	0.245	0.247	0.244	
S7		0.250	0.247	0.249	0.248	0.249	
S8		0.375	0.373	0.373	0.375	0.374	
S9		0.375	0.375	0.373	0.373	0.375	
S10		0.250	0.244	0.245	0.231	0.243	
S11		0.375	0.399	0.387	0.383	0.400	
S12		0.375	0.394	0.385	0.374	0.400	
S13		0.375	0.375	0.375	0.364	0.375	
S14		0.375	0.389	0.390	0.374	0.364	
S15		0.375	0.375	0.373	0.365	0.369	
S16		0.375	0.401	0.398	0.375	0.399	
S17		0.375	0.371	0.368	0.348	0.375	
S18		0.375	0.390	0.401	0.375	0.398	
S19		0.375	0.375	0.373	0.353	0.369	
S20		0.375	0.379	0.390	0.398	0.387	
S21		0.375	0.375	0.365	0.369	0.370	
S22		0.375	0.365	0.369	0.336	0.361	

F1       0.237       0.241       0.229       0.238       0.22         F2       0.237       0.244       0.244       0.236       0.23         F3       0.237       0.226       0.239       0.224       0.23         F4       0.237       0.246       0.250       0.229       0.22         F5       0.237       0.242       0.234       0.236       0.23         F6       0.237       0.234       0.237       0.238       0.237       0.238       0.237       0.23       0.24       0.23       0.23       0.23       0.24       0.23       0.23       0.24       0.23       0.23       0.24       0.23       0.23       0.24       0.23       0.23       0.22       0.229       0.221       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.22       0.2		Table M1 - API STD 570 Thickness Data	& TM	L (Co	nt.)	
TML         Nom.         0°         90°         20°         20°         20°         20°         18           F1         0.237         0.241         0.223         0.223         0.224         0.238         0.22           F2         0.237         0.246         0.239         0.242         0.23           F4         0.237         0.224         0.234         0.236         0.23         0.22         0.23         0.22         0.23         0.22         0.23         0.22         0.23         0.22         0.23         0.22         0.23         0.22         0.23	(1	(3) (A) Thic	kness Me	asurem	ents (in	inches)
Nom.   0°   90°   270°   180     F1			(Met	tal Thic	kness)	
F1       0.237       0.241       0.229       0.238       0.22         F2       0.237       0.244       0.244       0.236       0.23         F3       0.237       0.246       0.239       0.242       0.25         F4       0.237       0.246       0.250       0.229       0.22         F5       0.237       0.242       0.234       0.236       0.23         F6       0.237       0.234       0.237       0.228       0.238       0.237       0.238       0.237       0.238       0.237       0.238       0.237       0.238       0.237       0.238       0.237       0.238       0.237       0.238       0.237       0.238       0.237       0.238       0.237       0.248       0.248       0.242       0.235       0.244       0.236       0.237       0.244       0.236       0.237       0.244       0.236       0.237       0.244       0.236       0.237       0.244       0.236       0.237       0.244       0.236       0.237       0.242       0.221       0.225       0.221       0.227       0.221       0.225       0.221       0.225       0.221       0.227       0.231       0.237       0.231       0.232       0.231		Non				180°
F2       0.237 0.244 0.244 0.236 0.23       0.237 0.226 0.239 0.242 0.25       0.237 0.246 0.239 0.242 0.25       0.237 0.246 0.250 0.229 0.22       0.25       0.237 0.246 0.250 0.229 0.22       0.237 0.246 0.234 0.234 0.234 0.236 0.23       0.237 0.224 0.234 0.234 0.236 0.23       0.237 0.234 0.237 0.238 0.237 0.23       0.237 0.234 0.237 0.233 0.23       0.237 0.234 0.237 0.233 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.248 0.242 0.23       0.237 0.224 0.224 0.23       0.237 0.236 0.23       0.237 0.224 0.224 0.224 0.22       0.237 0.224 0.224 0.224 0.22       0.237 0.231 0.23       0.237 0.224 0.224 0.224 0.22       0.237 0.231 0.230 0.240 0.23       0.237 0.231 0.230 0.240 0.23       0.237 0.231 0.230 0.240 0.23       0.237 0.231 0.230 0.240 0.23       0.237 0.231 0.230 0.240 0.23       0.237 0.231 0.230 0.230 0.23       0.237 0.231 0.230 0.231 0.230 0.23       0.237 0.231 0.230 0.231 0.230 0.23       0.237 0.231 0.231 0.230 0.231 0.23       0.237 0.231 0.231 0.230 0.233 0.23       0.237 0.231 0.231 0.230 0.233 0.23       0.237 0.231 0.231 0.235 0.228 0.23       0.237 0.236 0.237 0.231 0.237 0.239 0.23       0.237 0.236 0.237 0.231 0.235 0.237 0.23       0.237 0.236 0.237 0.233 0.235 0.237 0.23       0.237 0.231 0.235					0.238	0.228
F3         0.237         0.226         0.239         0.242         0.225           F4         0.237         0.246         0.250         0.229         0.22           F5         0.237         0.234         0.234         0.238         0.237         0.235         0.238         0.237         0.237           F6         0.237         0.234         0.237         0.238         0.237         0.238         0.237         0.238         0.237         0.238         0.237         0.234         0.237         0.238         0.237         0.234         0.237         0.234         0.237         0.234         0.237         0.234         0.237         0.234         0.237         0.234         0.237         0.234         0.237         0.248         0.242         0.235         0.237         0.244         0.236         0.237         0.242         0.237         0.248         0.242         0.237         0.221         0.225         0.237         0.224         0.237         0.221         0.225         0.221         0.225         0.221         0.225         0.221         0.225         0.221         0.225         0.231         0.237         0.231         0.237         0.231         0.237         0.231         0						0.232
F4       0.237       0.246       0.250       0.229       0.225         F5       0.237       0.224       0.234       0.236       0.23         F6       0.237       0.235       0.238       0.237       0.23       0.237       0.233       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.248       0.242       0.23       0.23       0.248       0.244       0.23       0.23       0.244       0.234       0.23       0.23       0.244       0.234       0.23       0.23       0.244       0.244       0.233       0.23       0.24       0.23       0.23       0.22       0.229       0.221       0.22       0.229       0.221       0.22       0.229       0.221       0.22       0.229       0.221       0.22       0.229       0.221       0.225       0.23       0.24       0.23       0.23       0.221       0.228       0.23       0.228       0.23       0.228       0.23       0.228       0.23       0.228       0.23       0.228       0.23       0.228       0.23       0.23       0.228       0.23       <						0.250
F6       0.237       0.235       0.238       0.237       0.235         F7       0.237       0.234       0.237       0.233       0.23         F8       0.237       0.248       0.248       0.242       0.25         F9       0.237       0.244       0.236       0.239       0.22         F10       0.237       0.244       0.232       0.221       0.22         F11       0.237       0.248       0.242       0.233       0.23         F12       0.237       0.246       0.244       0.239       0.24         F13       0.237       0.241       0.239       0.24         F14       0.237       0.221       0.225       0.223       0.23         F15       0.237       0.231       0.230       0.240       0.23         F16       0.237       0.231       0.230       0.240       0.23         F17       0.237       0.235       0.242       0.224       0.22         F18       0.237       0.237       0.231       0.237       0.23         F20       0.237       0.237       0.231       0.237       0.23       0.227       0.23         F21	F4	0.23	7 0.246		0.229	0.226
F7       0.237       0.234       0.237       0.238       0.223       0.248       0.248       0.242       0.23       0.248       0.248       0.242       0.23       0.244       0.236       0.239       0.24       0.237       0.244       0.236       0.239       0.22       0.220       0.220       0.223       0.23       0.237       0.248       0.242       0.233       0.23       0.21       0.22       0.229       0.221       0.22       0.229       0.221       0.22       0.229       0.221       0.22       0.229       0.221       0.22       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.22       0.223       0.23       0.23       0.230       0.240       0.23       0.237       0.231       0.230       0.240       0.237       0.231       0.237       0.231       0.237       0.231       0.237       0.233       0.241       0.237       0.233	F5	0.23	7 0.224	0.234	0.236	0.238
F8       0.237       0.248       0.248       0.242       0.22         F9       0.237       0.244       0.236       0.239       0.24         F10       0.237       0.248       0.242       0.233       0.23         F11       0.237       0.222       0.229       0.221       0.22         F12       0.237       0.246       0.244       0.239       0.24         F13       0.237       0.221       0.225       0.223       0.22         F14       0.237       0.221       0.225       0.223       0.22         F15       0.237       0.231       0.230       0.240       0.23         F16       0.237       0.231       0.230       0.240       0.22         F17       0.237       0.237       0.231       0.237       0.231       0.237       0.231         F18       0.237       0.237       0.231       0.237       0.231       0.237       0.231       0.237       0.224       0.22       0.22       0.22       0.22       0.22       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.22       0.23       0.23       0.23       0.23 </th <th>F6</th> <th>0.23</th> <th>7 0.235</th> <th>0.238</th> <th>0.237</th> <th>0.237</th>	F6	0.23	7 0.235	0.238	0.237	0.237
F9       0.237       0.244       0.236       0.239       0.24         F10       0.237       0.248       0.242       0.233       0.23         F11       0.237       0.222       0.229       0.221       0.22         F12       0.237       0.246       0.244       0.239       0.24         F13       0.237       0.221       0.225       0.223       0.22         F14       0.237       0.231       0.228       0.236       0.23         F15       0.237       0.231       0.230       0.240       0.23         F16       0.237       0.231       0.230       0.240       0.23         F17       0.237       0.235       0.242       0.224       0.22         F18       0.237       0.235       0.232       0.233       0.23         F19       0.237       0.236       0.233       0.241       0.23         F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.236       0.233       0.241       0.23         F22       0.237       0.236       0.239       0.23       0.23         F23       0.237	F7	0.23	7 0.234	0.237	0.233	0.236
F10       0.237       0.248       0.242       0.233       0.23         F11       0.237       0.222       0.229       0.221       0.22         F12       0.237       0.246       0.244       0.239       0.24         F13       0.237       0.221       0.225       0.223       0.22         F14       0.237       0.231       0.228       0.236       0.23         F15       0.237       0.231       0.230       0.240       0.23         F16       0.237       0.235       0.242       0.224       0.22         F17       0.237       0.235       0.242       0.224       0.22         F18       0.237       0.235       0.232       0.233       0.23         F19       0.237       0.235       0.232       0.233       0.23         F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.236       0.233       0.241       0.23         F22       0.237       0.236       0.239       0.23       0.23         F23       0.237       0.241       0.237       0.235       0.235       0.23         F24 <th>F8</th> <th>0.23</th> <th>7 0.248</th> <th>0.248</th> <th>0.242</th> <th>0.250</th>	F8	0.23	7 0.248	0.248	0.242	0.250
F11       0.237       0.222       0.229       0.221       0.22         F13       0.237       0.246       0.244       0.239       0.22         F14       0.237       0.221       0.225       0.223       0.22         F15       0.237       0.231       0.228       0.236       0.23         F16       0.237       0.231       0.230       0.240       0.23         F17       0.237       0.227       0.231       0.237       0.22         F18       0.237       0.227       0.231       0.237       0.23         F19       0.237       0.229       0.227       0.229       0.22         F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.236       0.233       0.241       0.23         F22       0.237       0.236       0.229       0.232       0.23         F23       0.237       0.236       0.229       0.232       0.23         F24       0.237       0.241       0.237       0.235       0.235       0.237         F25       0.237       0.241       0.237       0.235       0.235       0.23	F9	0.23	7 0.244	0.236	0.239	0.244
F12       0.237       0.246       0.244       0.239       0.24         F13       0.237       0.221       0.225       0.223       0.22         F14       0.237       0.231       0.228       0.236       0.23         F15       0.237       0.231       0.230       0.240       0.23         F16       0.237       0.235       0.242       0.224       0.22         F17       0.237       0.237       0.231       0.237       0.23       0.237       0.23       0.237       0.22       0.231       0.237       0.22       0.231       0.237       0.22       0.231       0.237       0.22       0.231       0.237       0.22       0.231       0.237       0.22       0.231       0.237       0.22       0.231       0.237       0.22       0.231       0.237       0.229       0.22       0.23       0.23       0.231       0.237       0.231       0.237       0.231       0.237       0.231       0.237       0.231       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       0.237       <	F10	0.23	7 0.248	0.242	0.233	0.237
F13       0.237       0.221       0.225       0.223       0.22         F14       0.237       0.231       0.228       0.236       0.23         F15       0.237       0.231       0.230       0.240       0.23         F16       0.237       0.235       0.242       0.224       0.22         F17       0.237       0.237       0.231       0.237       0.23         F18       0.237       0.235       0.232       0.233       0.23         F19       0.237       0.229       0.227       0.229       0.22         F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.241       0.235       0.228       0.23         F22       0.237       0.241       0.235       0.23       0.23         F23       0.237       0.241       0.237       0.23       0.23         F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.241       0.237       0.235       0.235       0.23         F26       0.237       0.231       0.235       0.235       0.235       0.23 <t< th=""><th>F11</th><th>0.23</th><th>7 0.222</th><th>0.229</th><th>0.221</th><th>0.225</th></t<>	F11	0.23	7 0.222	0.229	0.221	0.225
F14       0.237       0.231       0.228       0.236       0.23         F15       0.237       0.231       0.230       0.240       0.23         F16       0.237       0.235       0.242       0.224       0.22         F17       0.237       0.227       0.231       0.237       0.22         F18       0.237       0.225       0.232       0.233       0.23         F19       0.237       0.229       0.227       0.229       0.22         F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.241       0.235       0.228       0.23         F22       0.237       0.241       0.235       0.23       0.23         F23       0.237       0.241       0.235       0.23       0.23         F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.241       0.237       0.235       0.235       0.23         F26       0.237       0.241       0.237       0.231       0.235       0.235       0.23         F28       0.237       0.231       0.235       0.225       0.23<	F12	0.23	7 0.246	0.244	0.239	0.241
F15       0.237       0.231       0.230       0.240       0.23         F16       0.237       0.235       0.242       0.224       0.22         F17       0.237       0.237       0.231       0.237       0.23         F18       0.237       0.235       0.232       0.233       0.23         F19       0.237       0.229       0.227       0.229       0.22         F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.241       0.235       0.228       0.23         F22       0.237       0.236       0.229       0.232       0.23         F23       0.237       0.238       0.235       0.237       0.23         F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.241       0.237       0.235       0.235       0.23         F26       0.237       0.241       0.237       0.231       0.235       0.23         F28       0.237       0.231       0.235       0.229       0.23         F29       0.237       0.231       0.235       0.228       0.23	F13	0.23	7 0.221	0.225	0.223	0.221
F16       0.237       0.235       0.242       0.224       0.227         F17       0.237       0.227       0.231       0.237       0.23         F18       0.237       0.235       0.232       0.233       0.23         F19       0.237       0.229       0.227       0.229       0.22         F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.241       0.235       0.228       0.23         F22       0.237       0.236       0.229       0.232       0.23         F23       0.237       0.238       0.235       0.237       0.23         F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.241       0.237       0.239       0.23         F26       0.237       0.241       0.237       0.233       0.228       0.235         F28       0.237       0.231       0.235       0.229       0.23         F29       0.237       0.231       0.235       0.228       0.23         F30       0.237       0.230       0.233       0.228       0.23         F31<						0.233
F17       0.237       0.227       0.231       0.237       0.23       0.233       0.23       0.233       0.23       0.233       0.23       0.233       0.23       0.233       0.229       0.229       0.229       0.229       0.229       0.229       0.229       0.229       0.229       0.23       0.241       0.23       0.241       0.23       0.241       0.23       0.228       0.23       0.24       0.23       0.241       0.237       0.23       0.24       0.237       0.241       0.237       0.233       0.24       0.237       0.231       0.237       0.233       0.24       0.237       0.231       0.237       0.233       0.228       0.23       0.23       0.23       0.23       0.23       0.23       0.23       0.23 <td< th=""><th></th><th></th><th></th><th>_</th><th>0.240</th><th>0.239</th></td<>				_	0.240	0.239
F18       0.237       0.235       0.232       0.233       0.22         F20       0.237       0.229       0.227       0.229       0.22         F21       0.237       0.236       0.233       0.241       0.23         F22       0.237       0.241       0.235       0.228       0.23         F23       0.237       0.238       0.229       0.232       0.23         F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.241       0.237       0.235       0.235       0.24         F26       0.237       0.241       0.237       0.233       0.24       0.237       0.233       0.24         F27       0.237       0.231       0.237       0.235       0.22       0.23         F28       0.237       0.231       0.235       0.229       0.23         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.245       0.238       0.228       0.23         F32       0.237       0.245       0.238       0.228       0.23						0.221
F19       0.237       0.229       0.227       0.229       0.22         F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.241       0.235       0.228       0.23         F22       0.237       0.236       0.229       0.232       0.23         F23       0.237       0.238       0.235       0.237       0.23         F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.244       0.235       0.235       0.24         F26       0.237       0.241       0.237       0.233       0.248       0.235       0.23         F28       0.237       0.231       0.235       0.229       0.23         F29       0.237       0.231       0.235       0.225       0.228       0.33         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.245       0.238       0.228       0.23         F32				_		0.229
F20       0.237       0.236       0.233       0.241       0.23         F21       0.237       0.241       0.235       0.228       0.23         F22       0.237       0.236       0.229       0.232       0.23         F23       0.237       0.238       0.235       0.237       0.23       0.23         F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.244       0.235       0.235       0.24         F26       0.237       0.241       0.237       0.233       0.28       0.235       0.23         F27       0.237       0.231       0.235       0.228       0.23       0.23         F28       0.237       0.231       0.235       0.225       0.23       0.23         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.245       0.238       0.228       0.23         F32       0.237       0.245       0.238       0.228       0.23						0.235
F21       0.237       0.241       0.235       0.228       0.23         F22       0.237       0.236       0.229       0.232       0.23         F23       0.237       0.238       0.235       0.237       0.23       0.237       0.231       0.237       0.239       0.23         F24       0.237       0.241       0.237       0.239       0.23       0.24         F25       0.237       0.244       0.235       0.235       0.24         F26       0.237       0.241       0.237       0.233       N/A         F27       0.237       0.233       0.228       0.235       0.23         F28       0.237       0.231       0.235       0.229       0.23         F29       0.237       0.235       0.225       0.228       0.33         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.245       0.238       0.228       0.23         F32       0.237       0.245       0.238       0.228       0.23						0.225
F22         F23         F24         F25         F26         F27         F28         C237       0.241       0.237       0.235       0.237       0.244       0.237       0.235       0.235       0.24         F26       0.237       0.241       0.237       0.233       N/A         F27       0.237       0.231       0.235       0.228       0.235       0.23         F28       0.237       0.231       0.235       0.229       0.23         F30       0.237       0.235       0.225       0.228       0.23         F31       0.237       0.226       0.230       0.233       0.228       0.23         F32       0.237       0.245       0.238       0.228       0.23						0.237
F23       0.237       0.238       0.235       0.237       0.23         F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.244       0.235       0.235       0.24         F26       0.237       0.241       0.237       0.233       N/A         F27       0.237       0.233       0.228       0.235       0.23         F28       0.237       0.231       0.235       0.229       0.23         F29       0.237       0.235       0.225       0.228       0.33         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.226       0.230       0.233       0.228         F32       0.237       0.245       0.238       0.228       0.23			_			0.232
F24       0.237       0.241       0.237       0.239       0.23         F25       0.237       0.244       0.235       0.235       0.24         F26       0.237       0.241       0.237       0.233       N/A         F27       0.237       0.233       0.228       0.235       0.235       0.235       0.229       0.23         F28       0.237       0.231       0.235       0.229       0.23       0.23       0.228       0.33         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.226       0.230       0.233       0.228         F32       0.237       0.245       0.238       0.228       0.23						0.235
F25       0.237       0.244       0.235       0.245       0.24         F26       0.237       0.241       0.237       0.233       N/A         F27       0.237       0.233       0.228       0.235       0.235       0.235       0.229       0.23         F28       0.237       0.231       0.235       0.229       0.23         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.226       0.230       0.233       0.228         F32       0.237       0.245       0.238       0.228       0.23						0.233
F26       0.237       0.241       0.237       0.233       N/A         F27       0.237       0.233       0.228       0.235       0.23         F28       0.237       0.231       0.235       0.229       0.23         F29       0.237       0.235       0.225       0.228       0.33         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.226       0.230       0.233       0.22         F32       0.237       0.245       0.238       0.228       0.23				+		
F27         F28         F29         F30         F31         F32         F32         0.237       0.231       0.235       0.229       0.23         0.237       0.235       0.225       0.228       0.23         0.237       0.230       0.233       0.228       0.23         F31       0.237       0.226       0.230       0.233       0.228         F32       0.237       0.245       0.238       0.228       0.23						
F28       0.237       0.231       0.235       0.229       0.23         F29       0.237       0.235       0.225       0.228       0.33         F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.226       0.230       0.233       0.22         F32       0.237       0.245       0.238       0.228       0.23				+		
F29         F30         F31         F32             0.237       0.235       0.225       0.228       0.23         0.237       0.230       0.233       0.228       0.23         0.237       0.226       0.230       0.233       0.22         F32       0.237       0.245       0.238       0.228       0.23			_	+		
F30       0.237       0.230       0.233       0.228       0.23         F31       0.237       0.226       0.230       0.233       0.22         F32       0.237       0.245       0.238       0.228       0.23						
F31 F32 0.237 0.226 0.230 0.233 0.22 0.237 0.245 0.238 0.228 0.23						
F32 0.237 0.245 0.238 0.228 0.23						
				+	+	
	F33			0.235	0.225	0.233
						0.240
			_			0.233
				+		0.225
					+	0.224
						0.241
						0.227
			_	+		0.235
						0.219
						0.267
						0.258
				+		0.259
				_		0.255
				+		0.258
	F47					0.230

(b) (3) (A)	,				
F48	0.	280 0.261	0.261	0.248	0.240
F49	0.	280 0.228	0.236	0.256	0.254
F50	0.	280 0.265	0.239	0.251	0.261
F51	0.	280 0.259	0.239	0.233	0.253
F52	0.	280 0.261	0.260	0.250	0.257
F53	0.	280 0.255	0.253	0.248	0.247
F54	0.	280 0.239	0.257	0.219	0.251
F55	0.	280 0.258	0.234	0.248	0.257
F56	0.	280 0.253	0.251	0.250	0.255
F57	0.	280 0.268	0.246	0.261	0.266
F58	0.	280 0.266	0.270	0.233	0.267
F59	0.	280 0.255	0.257	0.247	0.249
F60	0.	280 0.256	0.258	0.246	0.262
F61	0.	280 0.229	0.237	0.261	0.253
F62	0.	280 NA	0.255	0.255	0.256
F63	0.	280 0.249	0.249	0.250	0.251
F64	0.	280 0.241	0.256	0.261	0.241
F65	0.	280 0.229	0.240	0.248	0.251
F66	0.	280 0.259	0.261	0.259	0.259

\*Note: (b) (3) (A) were labeled to aide in identifying and locating findings reported. The letter "F" is tacked to the pipe supports (PS) numbers to distinguish the FOR PS from the facility designated pipe supports.




Table M3 - API STD 570 Pitting Data & TML (Exterior FOR Piping)								ng)
		Pipe		N	<b>1easure</b>	ments (	in inche	es)
TML		Size	Pipe		(I	Pit Dept	h)	
ID	Location/Description	(in.)	Sch.	Nom.				
X1	(b) (3) (A)			0.280	0.091			
X2				0.280	0.190			
X3				0.280	0.100	0.140	0.110	0.110
X4				0.280	arge corr	osion are	ea at PS (	no acces
X5				0.280	arge corr	osion are	ea at PS (	no acces
X6				0.280	0.130			
X7				0.280	0.100			
X8				0.280	0.100			
X9				0.280	0.100	0.120		

## Appendix C Drawings

- 1. Tank Gallery, FOR, Harbor Tunnel Piping Layout (Drawing 1 through 29)
- 2. UGPH Piping Layout (Drawing 1 through 4)
- 3. Exterior FOR Piping Isometric Layout (Drawing 1 through 5)
- 4. Surge Tank Piping Layout (Drawing 1 through 9)


	Owner:  US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC. Modified By: InterSpec, LLC. Date: 05/24/2022   Rev No: N/A   Scale: N/A	77/1 77/7/1-7/0
		Description: Facility Piping (1 of 29)
(b) (3) (A)	Remarks/Legend:	Drawing Title: Overall Layout [1 of 1]

		Owner	earl Harbor Hickam, Pearl Ha	03/24/2022
		GW - Ultrasonic Guided Wave CMLs	PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support	TML - Thickness Measurement Location  Description: Facility Piping (3 of 29)
(b) (3) (A)		Remarks/Levend: n - Concrete Saddle Support	· · · · · · · · · · · · · · · · · · ·	Drawing Title: Tank 13-16 Layout [1 of 1]

	ER-JBPHH,HI-RED HILL FACILIT Y-PIPING-MAY/2022
	Owner:  US NAVY:  Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC.  Date: 05/24/2022   Rev No: N/A   Scale: N/A
	GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Laieral Pipe Support TML - Thickness Measurement Location TML - Thickness Measurement Location Facility Pining (4 of 20)
(b) (3) (A)	(b) (3) (A)  In - Concrete Saddle Support  DBB Valve  B of H  Ball Valve  B of H  PS - Pipe Sipport  Drawing Title:  Tank 11.12 Layout [1] of 1]

	ER-JDI IIII,III-RED IIIELTACIEIT I-TII ING-MAT/2022	
	Owner:  US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC. Date: 05/24/2022   Rev No: N/A   Scale: N/A	
	GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location Facility Piping (5 of 29)	/:
(b) (3) (A)	Remarks/Legend:   n - Concrete Saddle Support     (b) (3) (A)	[f:f:

	ER-JBPHH,HI-RED HILL FACILITY-PIPING-MAY/2022
	Owner: US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC: Modified By: InterSpec, LLC: Date: 05/24/2022 Rev No: N/A Scale: N/A
	GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location Facility Piping (6 of 29)
(b) (b) (d)	Remarks/Legend:    Remarks/Legend:



earl Harbor, HI InterSpec, LLC. Scale: N/A
or Hickam, Pe
NAVY:  nt Base Pearl Harb  " InterSpec, LLC. 05/24/2022   Rev No:
Own
s ng CMLs eld or Bell - Bell Style Butt Weld tion Description: Facility Piping (8 of 29)
GW - Ultrasonic Guided Wave CMLs AUT - Phased Array Ultrasonic Testing C W - Butt Weld BBW - Bell and Spigot Style Fillet Weld o PS-n - Lateral Pipe Support TML - Thickness Measurement Location
GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW- Belt and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location Facility Piping (8 of 29)
oling s
DBB Valve  Media - DBB Valve  Media - Ball Valve  Flange  Dresser Coupling  Pripe Reducer
ction 1 [1 of
(b) (3) (A)    Kemarks/Legend:   Layout Se

 K-JDI IIII,III-KED IIILL FACILII I-I II ING-WA1/2022
Owner:  US NAVY:  Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC.  Date: 05/24/2022 Rev No: N/A Scale: N/A
GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location TML - Thickness Measurement Location
Remarks/Legend:  Remark

	ER-JBI IIII,III-RED IIIEE FACIEIT I-1	n n vo n	11111/2	.022
		Owner: US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI	Drawn By:InterSpec, LLC.Modified By:InterSpec, LLC.Date:05/24/2022Rev No:N/AScale:N/A	
		GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld W - Butt Weld	BBW - Ben and Spigor Style Filter weld of Ben - Ben Style Butt weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location	Description: Facility Piping (10 of 29)
(b) (3) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c		Remarks/Legend: n - Concrete Saddle Support   Concrete Saddle	PS - Pipe Sipport	Drawing Title: Layout Section 3 [1 of 1]

 I II VO-IV	IA1/2	2022
US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI	Drawn By: InterSpec, LLC. Modified By: InterSpec, LLC. Date: 05/24/2022   Rev No: N/A   Scale: N/A	6)
GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Wald WRW- Rell and Spriord Style Fillet Weld or Rell - Rell Style Butt Weld	LPS-n - Lateral Pipe Support TML - Thickness Measurement Location	Description: Facility Piping (11 of 29)
₩ <sup>∞</sup> (	Harden Description Harden Dresser Coupling Harden Description Description Harden Description Descript	on 4 [1 of 1]

	ER-JDI IIII,III-RED IIIEE PACIEIT I-I II ING-WAT/2	.022
	Owner:  US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC.  Date: 05/24/2022   Rev No: N/A   Scale: N/A	
	GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location	Description: Facility Piping (12 of 29)
(b) (3) (A)	Remarks/Legend:	Drawing Title: Layout Section 5 [1 of 1]

	US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC. Modified By: InterSpec, LLC.  Date: 05/24/2022 Rev No: N/A Scale: N/A
	GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location Facility Piping (13 of 29)
(A) (E	Drawing Title:    Drawing Title:   Drayout Section 6 [1 of 1]

US NAVY: US navy: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI nBy: InterSpec, LLC.   Modified By: InterSpec, LLC.   Scale: N/A   Scale: N/A
arl Harbor,
Pearl Scale:
Hickam,   Modified By:
or <b>H</b>
I Harbo
VV:  Base Pearl H  InterSpec, LLC:  24/2022 Rev
Y: se Pe
Owner:  US NAVY:  Joint Base P  Drawn By: InterSp  Date: 05/24/2022
Owner:  Join  Drawn By:  Date:  0
MLs or Bell - Bell Style Butt Weld rription: Facility Piping (14 of 29)
3utt W
Style I
Bell (
ALs  Bell - prion:
us ng CMLs eld or Bell tion Description:
re CMIIIet W
i Wav 'asoni' ort
Suidect ay Ult igot S Supp Measuu
GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location Facility Piping (14 of 29)
"W - Ultrasonic UT - Phased Arn W - Butt Welda 3W - Bell and Sj S-n - Lateral Pip ML - Thickness
GW - AUT - W - W - W - PS-n - FML - FML -
pling
DBB Valve  \$ □ MI Valve  \$ □ MI Valve  Tlange  # □ P. Dresser Coupling  > - Pipe Reducer
DBB v Ball V Flange Pipe R
of I
wing Title:  Layout Section 7 [1 of 1]
ition
and:
(A)  (B)  (C)  (Drawing Title:  Layout S
(A) (S) (d) $(A)$
 (b) (d)

		US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC.   Modified By: InterSpec, LLC.  Date: 05/24/2022   Rev No: N/A   Scale: N/A
		PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location TML - Thickness Measurement Location Facility Piping (15 of 29)
	(A) (S) (d)-	DBB Valve


er US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI	
arbo	InterSpec, LLC.
五二	le:
Pea	× ×
am,	ied By
Hick	Modified By:
bor ]	
Harl	Rev No:
arl	InterSpec, LLC. 24/2022   Rev
Y:	urSpec 022
Owner: US NAVY: Joint Base 1	Drawn By: InterSpc Date: 05/24/2022
JS N	1 By:
owne [	Date: 0
Welc	ription: Facility Piping (16 of 29)
e Butt	3 (16
I Style	iping
- Bel	ity P
MLs	tion Description: Facil
S. ng C. eld or	tion Descri
GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld	PS-n Lateral Pipe Support TML - Thickness Measurement Location Desc
Wave sonic	ment
iided Ultra	LPS-n - Lateral Pipe Support TML - Thickness Measurem
iic Gu Array 8ld 1 Spig	Pipe S
3W - Ultrasonic UT - Phased Arı W - Butt Weld BW - Bell and S	ickne
V - UI V - Bu V - Be	n - La
GV PAU W WBBV	TM
t	
ıoddn	
n - Concrete Saddle Support DBB Valve H - Ball Valve	guile
te Sac alve	# • Dresser Coupling
1 - Concrete DBB Va Ball Val	pe Re
n - Concrete Sa DBB Valve	Q - N
	# 1
	wing Title:  Layout Section 9 [1 of 1]
	n 9
	ectio
zend:	ut S
(3) (A) (B) (3) (A)	Drawing Title: Layout
(A) (b) (d) (A) (b) (c) (d) (d) (d) (d) (d) (d) (d) (d) (d) (d	Drav
$(A) (E) (d)_{\equiv} (A) (E)$	(q)




 ER-JBPHH,HI-RED HILL FACILIT Y-PIPING-MAY/2022
Hickam, Pearl Harbor, HI  Modified By: InterSpec, LLC.  N/A   Scale: N/A
Owner:  US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC.   Modified By: InterSpec, LLC.  Date: 05/24/2022   Rev No: N/A   Scale: N/A
- Bell Style Butt Weld
GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bult and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location TML - Thickness Measurement Location Facility Piping (18 of 29
arks/Legend:  n - Concrete Saddle Support  DBB Valve  and Ball Valve  and Ball Valve  ## - Flange  ## - Flange  Layout Section 11 [1 of 1]
(b) (3) (A)    Remarks/Legend:   Drawing Title:   Layout Se


CW   Uncounc Gaster Wave CM1   CW   Uncounc Gaster Wave CM1	<u> </u>
OW Ultrasone Guided Wave CMLs  OW Ultrasone Guided Wave CMLs  Fig. 12 II Valve  Based Array Ultrasonic Facility Conference  Fig. Proceed Coupling  Fig. Proceed Coupling  Fig. Proced Coupling  Fig. Proced Coupling  TML Thickness Westerment Location  Facility Piping (19 of 29)	
COW - Ulmsome Gunded Wave CMLs  The Internal Party of Files Wide or Bell - Bell Style But Wed  By Progression [Lexing   Facility Physing (19 of 29)]  This Linear Meanment Lexing   Facility Physing (19 of 29)]	<b>3, H</b>
Ow Ultrasone Guided Wave CALLs  Ow Ultrasone Guided Wave CALLs  Ow Ultrasone Guided Wave CALLs  North The Compile String CALLs  FALT - Phased Army Ultrasonic Facility CALLs  FALT - Phased Army Ultrasonic Facility Page But Weld  FALT - Phased Army Ultrasonic Facility Page But Weld  FALT - Physics Relations  TALL - Physics Relations  TALL - Physics Relations  FALT - Phickness Alexanciant Lecation  FALT - Ph	arbo   N/A   N/A
CW - Ulmsome Conded Wave CAlls  CW - Ulmsom Conded Wave	rl H
Own Ultrasonic Guided Waye CWiles  Own PAUTH Phased Army Ultrasonic Fasting CMIs  A Ball Yalve  PAUTH Phased Army Ultrasonic Fasting CMIs  A Ball Yalve  Ball Yalv	Pean
OW Ultrasoure Guided Wave CMLs  OW PAUT - Phased Army Ultrasour Faing CMLs  A Ball Yalve  B W Ball Yalve  A Ball Yalve  B W B W B B Batt Weld  B W B B W B B Batt Weld  B W B W B B Batt Weld  B W B W B B Batt Weld  B W B W B W B B Batt Weld  B W B W B W B B Batt Weld  B W B W B W B W B B Batt Weld  B W B W B W B W B W B W B W B W B W B	<b>m</b> , and by a second se
Own CAV - Ultrasoure Guided Wave CMLs  Own PAUT - Phased Army Ultrasour Faring CMLs  A Ball Valve PAUT - Phased Army Ultrasour Fasing CMLs  Family Ball Valve PAUT - Phased Army Ultrasour Fasing CMLs  Family Ball Valve PAUT - Phased Army Ultrasour Configuration of Phase Page Result Configuration (19 of 29)  Section 12 [1 of 1]  Page Reducer Page Result Configuration (19 of 29)	licks Todific
OW - Ultrasoure Cunded Wave CMLs  OW - Ultrasoure Cunded Wave CMLs  A Ball Valve  A Ball Valve  A Ball Valve  Ball Valve  A Ball Valve  Ball Valve  A Ball Valve  A Ball Valve  Ball Valve  Ball Valve  A Ball Valve  Ball Val	H S
OW - Ulmsome Canded Wave CMLs  On AUT - Phased Array Ulmsome Testing CMLs  A Ball Valve  A Ball Valve  Ball Valve  A Ball Valve  Ball Valve  Ball Valve  A Ball Valve  Ball Va	No.
OW - Ultrasone Childel Wave CMLs  OW - Ultrasone Childel Wave CMLs  A Ball Valve  N Ball Valve  We had well  When Weld as Support  Libs - Latent Phys Support  TML - Thickness Measurement Location  Section 12 [1 of 1]  Pacific Physing (19 of 29)	
CWY - Unresone Guided Wave CMLs  CWY - Unresone Guided Wave CMLs  CWY - Unresone Guided Wave CMLs  CWY - Three Bull 'Ashe  What Well  What Bull 'Ashe  What Bul	Pea
CW - Umsome Guidel Wave CMLs  CW - Umsome Guidel Wave CMLs  CW - Umsome Guidel Wave CMLs  CW - Umsome Cuidel Wave CMLs  CW - Umsome CMLs  CM - U	VY Sase
CW - Umsome Guidel Wave CMLs  CW - Umsome Guidel Wave CMLs  CW - Umsome Guidel Wave CMLs  CW - Umsome Cuidel Wave CMLs  CW - Umsome CMLs  CM - U	1 NA   1   1   1   1   1   1   1   1   1
CW. Ultrasmac Gunded Wave CMLs  CW. Ultrasmac Gunded Wave CMLs  CAW. Ultrasmac Gunded Wave CMLs  CA	ne: Joint Joint J
OW - Ultrasome Guided Wave CAll.s  Ball Valve  Hall Valve  Flange  P. Pipe Reducer  TML - Thickness Measurement Location  Section 12 [1 of 1]	
OW - Ultrasome Guided Wave CAll.s  Ball Valve  Hall Valve  Flange  P. Pipe Reducer  TML - Thickness Measurement Location  Section 12 [1 of 1]	eld (529)
OW - Ultrasome Guided Wave CAll.s  Ball Valve  Hall Valve  Flange  P. Pipe Reducer  TML - Thickness Measurement Location  Section 12 [1 of 1]	utt W   19 0.
OW - Ultrasome Guided Wave CAll.s  Ball Valve  Hall Valve  Flange  P. Pipe Reducer  TML - Thickness Measurement Location  Section 12 [1 of 1]	/le B
OW - Ultrasome Guided Wave CAll.s  Ball Valve  Hall Valve  Flange  P. Pipe Reducer  TML - Thickness Measurement Location  Section 12 [1 of 1]	ell Sty
CW - Ultrasone Guided Wave CALLs  CM - Ultrasone Guided Wave CALLs  Pall Valve  Healt Valve  Healt Valve  Healt Valve  Healt Valve  Healt Section Taken Dresser Coupling  Live - Lateral Pipe Support  TML - Thickness Measurement Location  Section 12 [1 of 1]	II - Ba
CW - Ultrasone Guided Wave CALLs  CM - Ultrasone Guided Wave CALLs  Pall Valve  Healt Valve  Healt Valve  Healt Valve  Healt Valve  Healt Section Taken Dresser Coupling  Live - Lateral Pipe Support  TML - Thickness Measurement Location  Section 12 [1 of 1]	MLs or Bei
d.    A BB Valve Ball Valve Ball Valve Ball Valve Fange Ball Valve	LLs ting C
d.    A BB Valve Ball Valve Ball Valve Ball Valve Fange Ball Valve	e CCM
d.    A BB Valve Ball Valve Ball Valve Ball Valve Fange Ball Valve	Wav asoni ort
d.    A BB Valve Ball Valve Ball Valve Ball Valve Fange Ball Valve	uuded / Ultr
d.  Ball Valve  Ba	mic G Arrai 4 Spiù 1 Spiò 8 Pipe
d.  Ball Valve  Ba	traso assed at W. Traso at the M. Traso at the
d.  Ball Valve  Ba	V - U V - B V - B V - B
d.  BB Valve  B BB Valve  B BB Valve  B BB Valve  B BB PBB PBB PBB PBBB PBBBBBBBBBBBBBB	GV PAU V BBW TM
s. Section 12 [1 of	
Section 12 [1 of	
id: Section 12 [1 of	
id: Section 12 [1 of	ling
id: Section 12 [1 of	ulve ve Coup
Section 12 [1 of	B Version 11 Value
Section 12 [1 of	- DB - Ba - Dia
Section 12 [1 of	
ritle:	I of
ritie: Filte: Vout Section	12
Legend: Title: Vout Sec	tion
Title: Vout	S S
	I'itle:
Kemarks/Leger   Kemarks/Leger   Kemarks/Leger   Drawing Title:   Layout	marks. La
$(A) (E) (d) $ $(A) \frac{(E) (d)}{E}$ $(A) \frac{(E) (d)}{E}$	$(A) (S) (d)_{\overline{A}} (A) (\overline{A})$


ER-JBPHH,HI-RED HILL FACILITY-PIPING-MAY/2022
n, Pearl Harbor, HI  By: InterSpec, LLC.   Scale: N/A
or: US NAVY: US naVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI nBy: InterSpec, LLC.   Modified By: InterSpec, LLC.   Solic: N/A   Scale: N/A
Own    Draw   Date
GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location FALL - Thickness Measurement Location FALL - Thickness Measurement Facility Piping (20 of 29)
Remarks/Levend:   n - Concrete Saddle Support





	Owner: US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI	Drawn By: InterSpec, LLC. Modified By: InterSpec, LLC.  Date: 05/24/2022   Rev No: N/A   Scale: N/A	
	GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld	BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location	Facility Piping (24 of 29)
(b) (3) (A)	Remarks/Legend: n - Concrete Saddle Support (D) (3) (A)	PS - Pipe Sipport	Layout Section 17 [1 of 1]





H,
earl Harbor,
earl H
Hickam, P  Modified By:  N/A
or Hick
I Harbo
4VY:  Base Pearl H InterSpec, LLC. 24/2022   Rev
US N Joint Drawn By: Date: 05
Butt We
PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location TML - Thickness Measurement Expression Facility Piping (27 of 29)
ILs Bell - B. acility
PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BBW - Bell and Spigot Style Fillet Weld or Bell LPS-n - Lateral Pipe Support TML - Thickness Measurement Location Facil
sonic Te le Fillet t ment Lo
AUT - Phased Array Ultrasonic Testing C W - Butt Weld BBW - Bell and Signostyle Fillet Weld o LPS-n - Lateral Pipe Support TML - Thickness Measurement Location
UT - Phased Arr W - Butt Weld BW - Bell and Sj S-n - Lateral Pip ML - Thickness i
UT - Ph W - Bu BW - Be S-n - La ML - Th
PA B L L L L L L L L L L L L L L L L L L
pling
Berth - DBB Valve Berth - Ball Valve - Flange - Frange - Presser Coupling - Pipe Reducer
DBB Va H-Ball Val Flange 
1 of 1]
wing Title:  Layout Section 20 [1 of 1]
Section
Drawing Title:  Layout
$(A) (E) (d) \qquad (A) \qquad (A$

-
US NAVY:  Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  mBy: InterSpec, LLC.   Modified By: InterSpec, LLC.  105/24/2022   Rev No: N/A   Scale: N/A
arl Harbor, InterSpec, LLC.
H. H
Pearl Inter
Hickam, I
Hicka  Modifie
lacksquare
I Harbo
AVY:  Base Pearl H  InterSpec, LLC.  24/2022   Rev
Owner: US NAVY: Joint Base P Drawn By: InterSp Date: 05/24/2022
NA IN B
Owner: Join Drawn By: Date: 0
std (229)
M Itt We of
MLs  or Bell - Bell Style Butt Weld  ription: Facility Piping (28 of 29)
II Sty
ng CMLs eld or Bell tion Description: Facility
Ls ing C feld o
GW - Ultrasonic Guided Wave CMLs PAUT - Phased Array Ultrasonic Testing CMLs W - Butt Weld BW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld LPS-n - Lateral Pipe Support TML - Thickness Measurement Location Facility Piping (28 of 2)
Wave soon in the First of the F
iided Ultra
uic Gu Array Adray Pipe S Spig
GW - Ultrasonic Guided W PAUT - Phased Array Ultraso W - Butt Weld BW - Bell and Spigot Style LPS-n - Lateral Pipe Support TML - Thickness Measurem
7 - PB T - TB
GW PAUT WW WW WW LPSH TMI
pport
n - Concrete Saddle Support  DBB Valve  M - Ball Valve  M - Flange  Flange  Flange  Presser Coupling  Presser Coupling  Presser Plange
n - Concrete Saddle S  n - BBB Valve  n - Flange  r - Flange  Presser Coupling
rerete B Val 1 Valva 1 yee Sser C
Doncrete  - Concrete  - Ball Val  - Flange  - Dresser
Jol 1
narks/Legend:    Sample   Samp
noii
ip Sect
Cerems Firle:
Remarks/Legend:    Remarks/Legend:   Remarks/Legend:   PS - Pipe Sipport   Drawing Title:   Layout Secti
(A) (S) (d) (S) (d) (A) (A) (A) (A) (A) (A) (A) (A) (A) (A
(7)(8)(4)

(	DBB Valve	PAUT - Phased Array Ultrasonic Testing CMLs	US NAVY:
(8)	🖁 🖙 🕦 - Ball Valve	W - Butt Weld	Joint Base Pearl Harbor Hickam, Pearl Harbor, HI
(v () (i	- Flange	BBW - Bell and Spigot Style Fillet Weld or Bell - Bell Style Butt Weld	
d) d)	##- Dresser Coupling	LPS-n - Lateral Pipe Support	Drawn By: InterSpec, LLC. Modified By: InterSpec, LLC.
PS - Pipe Sipport	> - Pipe Reducer	TML - Thickness Measurement Location	Date: 05/24/2022   Rev No: N/A   Scale: N/A
Drawing Title:		Description:	
Layout Section 22	Layout Section 22 and Pumphouse [1 of 1]	Facility Piping (29 of 29)	

(A) (A)	
Remarks/Legend:	Owner: US Navy - Pearl Harbor, HI
Drawing Title: UGPH Layout [1 of 4]	Description: UT TML/PAUT CML

UT TML/PAUT CML-JBPH, HI-UGPH-MAY/2022

(b) (3) (A)	
	Owner:
	US Navy - Pearl Harbor, HI    Drawn By: InterSpec, LLC.   Medified By: InterSpec, LLC.   Date: 5/24/2022   Rev No: N/A   Scale: N/A
Drawing Title: UGPH Layout [3 of 4]	-

Remarks/Legend: P1-P119- UT TML 1A-5B - PAUT CML

Drawing Title: UGPH Layout [4 of 4]

A (n) - UT CMLs         Joint Base Pear! Harbor Hickam, Pearl Harbor, HI           X (n) - Pitting Corrosion data         Drawn By: InterSpec, LLC.         Modified By: InterSpec, LLC.           Date: 05/24/2022         Rev No: N/A         Scale: N/A           Drawing Title: FOR ISO Layout (1 of 5)         FOR ISO Layout F-PS17	Remarks/Legend:   GW - Ultrasonic Guided Wave CMLs	Owner: US NAVY:
Drawn By: InterSpec, LLC.   Date: 05/24/2022   Rev No:   FOR ISO Layout F-PS17	A (n) - UT CMLs	Joint Base Pearl Harbor Hickam, Pearl Harbor, HI
Date: 05/24/2022   Rev No :   Description:   FOR ISO Layout F-PS17	X (n) - Pitting Corrosion data	
Date: 05/24/2022   Rev No: N/A   Description:   FOR ISO Layout (1 of 5)		
O Layout (1 of 5)		
	Drawing Title:	Description:
	FOR ISO Layout (1 of 5)	FOR ISO Layout F-PS17


Remarks/Legend:	Owner:
GW - Ultrasonic Guided Wave CMLs A (n) - UT CMI s	US INAV Y: Loint Base Pearl Harbor Hickam. Pearl Harbor. HI
X(n) - Pitting Corrosion data	
	Drawn By: InterSpec, LLC. Modified By: InterSpec, LLC. Date: 05/24/2022   Rev No: N/A   Scale: N/A
Drawing Title:  FOR 1SO 1 avourt (2 of 5)	Description: FOR ISO I avoint E-DC17
	ON 130 Layout 1-1-31/


			tam, Pearl Ha	Date: 03/24/2022
				Description: FOR ISO Layout F-PS17
(b) (3) (A)			Remarks/Legend:  GW - Ultrasonic Guided Wave CMLs  A (n) - UT CMLs  X (n) - Pitting Corrosion data	Drawing Title: FOR ISO Layout (3 of 5)


$(\mathcal{C})$ (c) (d)		
Remarks/Legend:		Owner:
GW - Ultrasonic Guided Wave CMLs A (n) - UT CMLs		Joint Base Pearl Harbor Hickam, Pearl Harbor, HI
X (n) - Pitting Corrosion data		Dawn By: InterSpec. LLC. Modified By: InterSpec. LLC.
		Date: 05/24/2022 Rev No: N/A Scale: N/A
Drawing Tride: FOR ISO Layout (4 of 5)	Description: FOR ISO Layout F-PS17	


		Owner: US NAVY: Joint Base Pearl Harbor Hickam, Pearl Harbor, HI  Drawn By: InterSpec, LLC.   Modified By: InterSpec, LLC.  Date: 05/24/2022   Rev No: N/A   Scale: N/A	PS17
		Decembrica	Poscription: FOR ISO Layout F-PS17
(b) (3) (A)		Remarks/Legend:  GW - Ultrasonic Guided Wave CMLs  A (n) - UT CMLs  X (n) - Pitting Corrosion data	Por ISO Layout (5 of 5)























## Appendix D

# API 570 Checklist and Site Assessment Findings/Discussion Form

Comp	any	Name	US Navy - Red Hill Fuel Com	plex (upper tunne	el section)
Locati	on:		Pearl Harbor, HI		
Inspec	tor:			Date:	May 24, 2022
Syster	n:		Hill Fuel Complex Piping	Pipe Section ID:	Tank Gallery, Harbor Tunnel, UGPH, Surge Tank and FOR Piping
A.1.1	PII	PING	SUPPORTS		
	a.	X	Visually inspect for cracking, pit	ting, and corrosion	n.
	b.	X	Check clamp bolting is secure an	d minimum threa	d engagement.
	c.	Χ	Check for coating failures		
	d. X Check attachment welds for cracking and corrosion.			n.	
e. X Check that lines subject to thermal and cyclic n			Check that lines subject to therm	al and cyclic mov	ement are free from binding
f. X Check that piping has proper supporting for len			Check that piping has proper sup	porting for length	and weight of piping.
A.1.1.	1 (	Concr	ete Foundation Support		
	a. _	X	Inspect for broken concrete, spall faces.	ling and cracks. es	specially under bearing sur-
	b.	Χ	Inspect for erosion under foundat	tion of support/s.	
A.1.1.	2 V	Voode	en Supports		
	a. -	NA	Inspect for splintered, broken, flat pecially under bearing surfaces.	ttened, dry rotted	and cracked membranes, es-
A.1.1.	3 E	Iousel	keeping		
	a	Χ	Inspect the area for buildup of tra	ash, vegetation and	d obstructions. `
B.2 P	IPE	. Wal	I		
B.2.1	Ext	ternal	Visual Inspection		
	a.	X	Visually inspect wall surface for of-round and part deformation.	paint failures, pitt	ing, corrosion, denting, out-

b.	X	Check interstitial space of double wall, underground piping for product fumes.
c.		Visually inspect weld joints for cracking, pitting, corrosion and signs of leaking
_	Χ	_(product residue).
d	N/A	Perform dye penetrant or mag particle if leaks or cracks are suspected.
e.	Χ	Check for proper grounding

### **B.3 PIPE FITTINGS AND INSTRUMENTS**

### **B1.3.1** Branches, Fittings and Flanges.

a.	X	Inspect for fatigue cracks or signs of leakage on weld joints and reinforcing plates.
-	^	-
b.	Х	Inspect for deformation and dimpling around branches, caused by excessive pipe deflection.
c.	Х	Inspect for flange leaks and leaks around bolting.
d.	Χ	Check flange bolting are secure and have minimum thread engagement.
e.		Check that flange deflection shields are installed as required, have a proper fit
	N/A	and is secure.

### **B1.3.2** Relief Devices

a.	Χ	_ Inspect for flange leaks and leaks around bolting.				
b.	Χ	Check flange bolting are secure and have minimum thread engagement.				
c.	Χ	Record inlet and outlet sizes.	Inlet: 4"/1" Outlet: 4"/1" (UGPH/Surge tank)			
d.	Χ	Check that relief system outlet discharges to safe location (outside of building.)				
e	Χ	Record certification date	7/1/1997 and 03/19 (MFG Tag)			
f.	Χ	Record pressure setting	260/150(PSIG) (UGPH/Surge Tank)			
g.	Χ	Record type and identification number.	CLA VAL/Taylor T-8200-1 (UGPH/Surge Tank)			

### **B.1.1.3** Valves

- a. \_\_\_X \_\_ Inspect function of valves, including drain or return-to-tank line.
   b. \_\_X \_\_ Check for packing leaks.
- c. X Inspect for flange leaks and leaks around bolting.
- d. X Check flange bolting are secure and have minimum thread engagement.
- e. X Inspect for fatigue cracks, corrosion and pitting.
- f. X Check that valve handle has proper fit and is secure.
- g. Check that flange deflection shields are installed as required, have a proper fit and is secure.

### **B.13.4** Pumps, Compressors and Other Rotating Equipment

- a. X Inspect mounting bolts and support.
- b. \_\_\_ X \_\_ Inspect shaft seal for leakage and seal housing for hot spots.
- c. X Inspect shaft sealing liquid reservoir and tubing for liquid level and leaks.
- d. X Inspect condition of power lines and connections.
- e. N/A Inspect pump operation for vibration, belt squealing, uncommon noises.
- f. N/A Inspect casing for fatigue cracks, corrosion, pitting. and damage.
- g. X Inspect for flange leaks and leaks around bolting.
- h. X Check flange bolting are secure and have minimum thread engagement.
- i. X Check safe guards are in place and secure.
- j. Check that flange deflection shields are installed as required, have a proper fit and is secure.
- k. X Check equipment is properly grounded

### **B.4 INSULATION**

### **B.1.4.1 Visually Inspection**

- a. x Check for holes, missing portions, deterioration due to corrosion or abuse.
- o. X Check for sufficient sealing, especially around branches and appurtenances.
- c. X Check for wetness.

### **B.5 PRESSURE / TEMPERATURE INDICATORS**

### **B.1.5.1** Physical and Operating Conditions

- a. X Check that indicators are securely attached and operating properly.
- b. \_\_X \_\_ Check that indicators are in accessible locations and readable.
- c.  $\underline{\hspace{0.1cm}}$  Check that indicators have current calibration date.
- d.  $\underline{\hspace{0.1cm}}$  Check for any damage, or corrosion build up.

### **B.1.6 RECORD FOLLOWING DATA**

a.	Х	ID Number

- b. N/A Radiography Examination
- c. X MAWP
- d. \_ X MDMT
- e. X Nominal Wall Thicknesses
- f. X Nominal Lengths
- g. X Material
- h. X Manufacturer

Tank Gallery, Harbor Tunnel, UGPH,

Surge Tank and FOR Piping

N/A

275 psi

Varies (See UTT Data)

See Drawing

Carbon Steel


Unknown

	i.	Х	Year Built	1942 (Circa) with ongoing modification/upgrades	
	j	Х	Seamless/welded	Majority Seamed with some Seamless (Welded)	
	k	Х	_Design Code	Unknown (Assumed ASME B31.3)	
B.7 I	PIPI	NG L	AYOUT DRAWINGS		
B.1.7	.1 R	ecoro	l Following Data		
	a.	Х	Pipe lengths and plains (significant heig	hts).	
	b.	Χ	Type and placement of pipe supports.		
	c	Х	Foundation support member dimensions	s and orientation.	
	d	Х	_Inside Diameter		
	e	X	Piping part nominal thicknesses.		
	f	X	Branches, fittings and instrument - layouts, sizes and uses. Flow arrows and identification (Material, NPS, System ID, etc.)		
	g	Х	_ Flow arrows and identification (Materia	i, NPS, System ID, etc.)	
B.1.8	UT	THI	CKNESS READINGS		
	a.		Designate TML location on layout draw		
	_	Х	designated down stream of each flow tra	ansition and at each pipe support.)	
	b.		At each TML, record measurements at -		
	_	Х	_inches and greater, (1) point for nozzles	less than 2 inches.	
B.9 I	HYD	ROS	TATIC TESTING		
B.1.9	.1 R	ecord	l Following Data		
	a.	N/A	Actual pressures, temperatures, liquid le	evels and time duration of test	
	b.		Calibration dates of test instruments use	ed (i.e. pressure gages, temperature gag-	
	-	N/A	es, transducer etc.)		
	c.	N/A	Drawings indicating test sections.		
	d.	N/A	All Forms in API - 1110 filled out as red	quired.	
<b>B.10</b>	CA	ГНО	DIC PROTECTION FOR UNDERGRO	OUND PIPING	
B.1.1	0.1	Recoi	rd Following Data		
	a b.	NA NA	Soil Resistivity Soil Potential		
	о. с.	NA	Water table below ground level		
	~	. •• •	51011 5104114 10101		

## SITE ASSESSMENT FINDINGS AND DISCUSSION FORM

The following table highlights the overall site findings and assessment with regard to critical elements of the system and integrity management procedures and programs that contribute to or determine requirements for integrity management.

General piping system overview and relative	1940s (with subsequent upgrades)		
age:  Previous assessments and inspection history	<ul> <li>EEI/APTIM have completed previous assessment &amp; NDE and repairs (2010 appears to be the first year this is known to have been done)</li> <li>The section of JP-5 Piping from Tank 20 to was evaluated in July 2021 (AB&amp;A/InterSpec).</li> </ul>		
Piping leak history	There was a pipe related event in May of 2021. (RCA and analysis conducted by others)		
Use of underground piping in structural casings and double-wall secondary containment piping systems	N/A		
Cathodic system history and inspection findings	Survey conducted on the FOR piping (Dec. 2021) Report was provided and reviewed.		
Piping service class per API 570 Categories 1 (severe) to 3 (limited)	Class 1		
Conclusions regarding pressure testing criteria and adequacy of current pressure testing	Limited by expansion joints and non-standard flanges, fittings and welds (no known pressure testing was completed in this segment)		
Piggability	Not applicable to this report (Study conducted by others during 2016 IMP)		
Coating type and condition - Underground piping	N/A		
Coating type and condition - Aboveground piping	Appears to be Macropoxy 646 coating system on most of the newly coated piping. Majority of the existing coating type is unknown but appears to be epoxy based coating with lead-based primer. Large portion of the facility piping has satisfactory coating with isolated areas of moderate to major coating failure.		
Non-standard piping components and fittings	Several flanges, fittings and welds are not per current industry standards.		
Establish CMLs (condition monitoring locations)	See Thickness data for TMLs and NDE CMLs		
Determine long term corrosion rates and remaining system life per API 570	See Piping Calculations		
Adequacy of thermal relief system to prevent overpressure condition	There is differential thermal relief (DTR) system on DBBs and header piping in UGPH have pressure reliving device (PRD). See report body for areas identified without a PRD		
Adequacy of over pressure prevention system when a high-pressure system feeds a lower pressure class system	Exhibiting PRDs appear to adequate for overpressure protection. See report body for areas identified findings about PRDs		



Injection Points and Mix Points	None
Deadlegs	Dead legs identified are documented in the body of report. See body of report.
Corrosion Under Insulation (CUI)	Fireproofing insulation only on dresser coupling for tank 2, 4, 6, 8, 10, 12, 14 and 16. Insulation at Tank 12 was removed during the for close visual inspection of pipe and dresser coupling was completed during the July 2021 API 570. Some corrosion noted but CUI does not appear to be a corrosion mechanism for this facility.
Soil/Air Interfaces (SAI) - Concrete/Air (CAI) Interfaces	Visual inspection and some LRUT conducted at SAIs and CAIs. Section of the exterior FOR line by ADIT 3 was also inspected at the SAI. Some CAI corrosion noted and documented in the report. No reportable indication noted
Service Specific and Localized Corrosion Inspection	None observed and none expected for main product lines. Very minimal water bottom pitting noted on piping that were opened during this inspection. Thickness survey was also conducted at areas that have a potential to trap water (near valves, low areas in section of piping and at the lowest elevation of the pipe run). UTT did not reveal a concern for water bottom on fuel line. The FOR line did however have moderate to major corrosion due to product carried. See report body for locations identified.
Erosion and Corrosion/Erosion	None observed and none expected on product piping (refined product stored at this facility)
Environmental cracking	None observed and none expected
Corrosion beneath Linings	N/A
Fatigue Cracking	None observed and low likelihood
Creep Cracking	None observed and low likelihood
Brittle Fracture	None observed and none expected
Freeze Damage	None observed and none expected
Contact Point Corrosion	Some metal to metal contact points were observed but no large-scale corrosion cell observed at pipe supports. Recommendation is made for Teflon shims/insulation strip between pipe and saddle. See body of report and Table E for areas identified.



Internal Visual Inspection	Section of opened pipe at tanks 18 and 20 were visually inspected during the July 2021 inspection cycle. Other areas that were open for repairs were additionally inspected during this inspection cycle. No major internal pitting noted.
On-Stream Inspection	Periodic on-stream inspection is performed at this facility by facility personnel but no know on stream inspection documented or provided for review.
Thickness Measurement Inspection	Performed during this inspection and previous inspections
External Visual Inspection	This is been performed periodically.  Deficiencies identified are submitted in this report
External Inspection of Buried Equipment	N/A
CUI Inspection	Performed during the 2021 API 570 inspection cycle and this inspection at tank 2, 4, 6, 8, 10, 12, 14 and 16.
Vibrating Piping Inspection	Not expected but can only be performed during an on-stream inspection while pipe is in use and operating.
Supplemental Inspection	Periodic NDE is performed
Condition Measurement Locations (CMLs)	Performed during this inspection and previous inspections
Condition Monitoring Methods	Ultrasonic thickness testing and visual surveys, Guided wave (GW) inspection and Phased Array Ultrasonic Testing (PAUT) conducted at select locations
Pressure Testing of Piping Systems	There is no known pressure testing record
Material Verification and Traceability	Destructive testing and metallurgical lab testing were conducted on samples of piping in May 2000 and August 2018
Inspection of Valves, Gages and Pumps	Accessible section of valves and flanges were inspected (external only)
In-Service Inspection of Welds	Phased Array Ultrasonic Testing (PAUT) conducted at select locations
Inspection of Flanged Joints	Visual inspection



(This section applies for primarily buried underground piping. There is a small section of buried piping associated with the FOR line at ADIT 3. While piping at Red Hill fuel complex is primarily aboveground and available for inspection; some of this methods were applied for portions of piping that pass through bulkheads )

Above-grade Visual Surveillance	<ul> <li>Completed for section of FOR piping at ADIT 3</li> <li>(**) Visual surveillance was completed for all bulkhead penetration (surveyed for concrete discoloration, casing discoloration and for noticeable odor</li> </ul>
Close-Interval Potential Survey (CIP)	N/A
Pipe Coating Holiday Survey	N/A
Soil Resistivity	N/A
Cathodic Protection Monitoring	Survey conducted on the FOR piping (Dec. 2021) Report was provided and reviewed.
In-Line Inspection (ILI) – Intelligent Pigging	N/A
Video Cameras	• (**) Borescope inspection was utilized for accessible section of concrete penetration, crevice and pipe casing
Excavation	N/A
Externally Applied Screening Techniques (LRUT/Guided Wave)	(**) LRUT of the selected concrete bulkhead penetrations and concrete support contact points were conducted.


(\*\*) Indicates application of techniques and methodology employed to facilitate the inspection of portions of piping that pass through bulkheads.

General and additional comments: See report section and summary tables for general condition of section of piping inspected

Appendix E Photographs




E.3 Pipe-to-flange attachment (nonstandard weld attachment/unknown fit-up to flange) (TYP)






 $E.9\;$  Topside view of the three-product piping past Tank 7 and 8




[635]





E.16 Saddle type steel support not in contact with pipe at




E.17 Exposed electrical wires at Tank 1 and flanged (unrestrained pipe)




E.18 Efflorescence formation on anchor bulkhead between

and o

line





E.21 Oil staining on Tank 15 skin DBB at valve position indicator (Note length of VPI stem)





E.25 Unrestrained blind flange at Tank 14 (Tank is out-of-service)








E.28 Socket weld on the 32line between





isolation valve, reduction in pipe diameter and HPV at



E.31 Corrosion of fasteners on the

header to lateral tees between Tank 9 and 10



E.32 Rope tied to the


drain valve at Tank 10 (unknown reason) note missing plug





E.33 Coating failure and corrosion on


pipe at

due to conduit strut











[644]








E.45 Flange with insufficient stud engagement



E.46 Coating failure at

UTT and visual inspection)




E.47 Wrap failure with some coating failure and corrosion on



E.48 Saddle 32 on the

line with shims



Note the original pipe with anchor ring within a few inches from the surface of the bulkhead. See E.51 for end anchor ring.


E.49 Borescope inspection of pipe (F-24) in a sleeve at bulkhead between



Space between sleeve and pipe. Red arrow is carrier pipe and green arrow is sleeve.

The original pipe I used as the sleeve with a pipe as the carrier pipe

E.50 Photo of borescope inspection in sleeve (no finding)



Space between sleeve and pipe. Red arrow is carrier pipe and green arrow is sleeve. The original pipe I used as the sleeve with a pipe as the carrier pipe


E.51 Borescope inspection of pipe between sleeve and bulkhead at



Borescope inspection conducted via the small opening on the end ring that is seal welded to the sleeve.

E.52 Borescope inspection of

pipe (JP-5) in a sleeve at bulkhead between



Space between sleeve and pipe. Red arrow is carrier pipe and green arrow is sleeve.

The original pipe I used as the sleeve pipe as with a the carrier pipe

View at 7 to 6 o'clock

E.53 Borescope inspection of (JP-5) pipe in a sleeve at bulkhead between



A wood shim was noted between pipe ad sleeve. (Note the nails). LRUT did not indicate corrosion at this penetration but wood shim is not standard practice for sleeve spacer.

View at 4 o'clock

E.54 Borescope inspection of (JP-5) pipe in a sleeve at bulkhead between



Space between pipe and the concrete bulkhead was used to perform borescope inspection of the pipe via cavity.

E.55 Borescope inspection of pipe between pipe and bulkhead at



Space between pipe and the concrete bulkhead was used to perform borescope inspection of the cavity.


E.56 Borescope inspection of pipe between pipe and bulkhead at



Red arrow is pipe and green arrow is the anchor plate/ring welded around the pipe. The plate/ring is approximately inches from the surface (near the middle of the bulkhead).

E.57 Borescope inspection of pipe between pipe and bulkhead at





E.59 Dent measurement (Typical)



E.60 DFT testing (Typical)



E.61 Coating failure and surface corrosion at threaded LPD (at

on




E.62 Coating failure and corrosion at anchor saddle and pipe (





E.63 Coating failure (no corrosion)

line at



E.64 Coating failure and corrosion at concrete bulkhead penetration



Thickness testing was conducted at all branch welds when it is located near the bottom of the pipe at all locations to inspect for microbial induced corrosion (MIC)

E.65 UTT for MIC at all branch fitting

between

shown)



E.66 Staining on threaded plug on JP-5

line at



The Newspaper was a Saturday, January 3<sup>rd</sup> 1942 Honolulu Star Bulletin.


The stuffed newspaper was removed for crevice/corrosion inspection of saddle contact point and to determine the reason for the stuffed paper.

E.67 Newspaper stuffed between pipe and saddle # 126 (removed for inspection)



Note the piping and coating appears to be original to the facility. Same black coating noted on the newspaper. Reason for the paper is unknown but likely to seal the concrete form boards during construction.

No crevice corrosion noted between the saddle and pipe.



E.69 Plates tack welded to the pipe (use unknown). Location shown is between



E.70 Typical bell-bell welded with coating removed (Welder ID stamps noted at welds)




E.71 Vertical groves noted on bell at PAUT location (PAUT # HT55)

(b) (3) (A)

E.72 UGPH (above grating piping)







E.75 FOR piping outside of 3 (majority of this piping is corroded)



E.76 PAUT daily calibration using standard block (Typical)




E.78 Typical LRUT setup

## Appendix F JP-5 repair Highlights; Tank 20 – Tank 10

## JP-5 repair Highlights; Tank 20 – Tank 10

The section of JP-5 Piping from Tank 20 to was evaluated in July 2021 along with various NDE. This section of piping was not re-evaluated during this trip since it was undergoing active repairs. Several sections of piping spools were replaced or in the process of being repaired.

InterSpec took the opportunity, when available, to visually survey the interior portion of the piping that were cut open. This was achieved at the end of the pipe header flange by tank 19 and 20 (just past and at the rolled offset by The interior portion of the pipe inspected did at spool cut out by not have any significant pitting with an average pit depth of 0.030". The repairs appear to be following industry practice and requirements of API 570 with several hold points scheduled for the required NDE and visual inspection by the repair contractor.





(b) (	Balled Officet by			
(b) (3) (A	Rolled Offset by		Interior view of pipe at the rolled offset by	
	N 11 1 00 4 (T 1 10)		New pipe spool after the eccentric reducer coupling	l
(b) (3) (	New rolled offset (Tank 19)  A)		(Tank 19)	
		48	Lateral restraint pipe at (pipe spool mounted	
93	Tank 19 pipe (Note no ioslation valve)		between flange and tunnel wall)	



## **APPENDIX 'D' - TRIP REPORT**

v								
	Transmittal		TRANSMITTED FOR:		SUBMITTAL NO.	DATE SUBMITTED:		
	Transmittal/Review/Approval		APPROVAL		010	Jun 17, 2022		
CONTRACT NO		CONTRACT TITLE						
CONTINCT NO		CONTINCT TITLE				DATE NEEDED BY:		
N39430-20-D-22	N39430-20-D-2242 DO N3943022F4333 Fuel Transfer Infrastructure Assessment - Red Hill Bulk Storage Facility							
PART I: FOR CO	NTRACTOR USE							
FROM (CONTRACTOR)				TO:				
Austion Brocken	brough & Associates, LLC			NAVFAC EXW	C			
SUBMITTAL PRIORITY	? CHIGH ONOR	MAL PREF	PARED BY QC MGR?	( YES	○ NO			
를 가능하게 되었다면 있는데 보고 있는데 이번에 가는 사람들이 보고 있다면 보다 되었다. 그는데 보고 있다면 보고 있다면 보다 되었다면 보고 있다면 보다 되었다면 보다 되었다면 보다 되었다면 보다 보다 되었다면			ICAL PATH?	( YES	ONO	Add Del		
ITEM NO.	ITEM DESCRIPTION			SPEC SECT	ON & PARAGRAPH DWG NO.	ACT <b>IVI</b> TY <b>I</b> D		
001	Field Investigation Trip Report							
002	Preliminary Piping Inspection Trip Report							
QC MANAGER REMAR	KS: (INCL COMMENTS FOR DETAILED REVIEWERS)		,3					
It is hereby	certified that the mater	rial submitted h	erein confo	orms to cor	tract requirements	and can be		
	the allocated spaces.				S			
stanca ii		(4) (0)	DA	TE:				
QUALITY CONTROL M	ANAGER NAME/SIGNATURE:	(b) (6)	J.	un 17, 2022				
	ENT REVIEW ROUTING YES							
FROM: (FEAD/ROICC)	ENT REVIEW ROUTING YES	O NO	○ N/A					
PROM. (PEAD/ROJCC)		TO: (REVIEWE	KJ					
FEAD/ROICC CONSTR	UCTION MANAGER COMMENTS FOR REVIEWER:							
			DA	TE:				
FEAD/ROICC CM NAM	IE/SIGNATURE:							
PART II: FOR RE	VIEWED LICE CO.							
DETAILED REVIEWER F	O	EW REQUIRED						
DETAILED REVIEWER I	ECOMMENDATION.							
DETAILED REVIEWER	COMMENTS:							
			πı	TLE .		DATE:		
DETAILED REVIEWER	NAME/SIGNATURE							
PART III: FOR AF	PROVER USE							
FROM:			тс	);				
SUBMITTAL IS:						100		
ADDROVEDIS COLLAIFATE.								
APPROVER'S COMMENTS:								
			ПТ	I E		DATE:		
APPROVER NAME/SIG	NATURE				STRUCTION MANAGER			



June 17, 2022

(b) (6)

POL Facilities Engineering Division, Code SH25 - NAVFAC EXWC 1000 23<sup>rd</sup> Avenue
Port Hueneme, CA 93043-4370

Re: Site Investigation Trip Report, Fuel Transfer Infrastructure Assessment, Red Hill Bulk Fuel Storage Facility; A/E Contract No. N39430-20-D-2242, Delivery Order No. N3943022F4333

Dear (b) (6)

Brockenbrough had a facility assessment team on site at the Red Hill Bulk Fuel Storage Facility, JBPHH, Hawaii, on March 21<sup>st</sup> thru May 24<sup>th</sup>, 2022, to perform an assessment of the POL piping, fire protection systems, and other transfer assets. This site visit was performed under A/E Contract No. N39430-20-D-2242, Delivery Order N3943022F4333 as required by the Scope of Work dated 20 January 2022. Assessment team included an API 570 pipe inspection team, a Fire Protection team, and a Life Cycle Sustainment team. Specific investigation tasks are listed in more detail below. Representatives from Brockenbrough and our teaming partners were on site continuously for the entire two-month period listed above.

### **Piping Assessment Field Investigation Notes:**

- Brockenbrough API 570 Inspectors / POL Engineer's performed a walkthrough of all piping systems for the JP-5, F-24, F-76, and FOR piping. The line was investigated and compared to existing drawings and previous piping inspection notes were evaluated.
- Brockenbrough Structural Engineer performed a detailed assessment of all fuel piping supports (Concrete and steel).
- Brockenbrough's Teaming Partner, InterSpec, performed a detailed Visual Inspection of all piping systems for JP-5, F-24, F-76, and FOR piping.
- InterSpec also performed several enhanced inspection activities for the piping systems including Guided Wave Inspection of the piping at locations where it penetrated concrete and Phased Array Inspection of a selection of the fuel piping welds.
- While on site, Lead was identified within the pipe coatings that were being removed to facilitate the Phase Array Inspection of the Welds. A modification was executed to handle and dispose of this lead material.
- In general, all piping systems were found to be in overall "Fair" condition, but with several localized areas of coating failure and significant to severe corrosion and piping wall loss noted. Locations and additional quantitative details of the anomalies will be provided within the Transfer Pipeline Assessment Report.

• The detailed Preliminary Trip Report from has been provided as an appendix to this trip report and details the initial significant findings from the visual piping inspection

#### **Fire Protection Assessment Field Investigation Notes:**

- Brockenbrough's teaming Partner, Jensen-Hughes, has a fire protection assessment team on site and performed a walkthrough of all piping systems for the fire protection systems that protect the piping and tank galleries.
- The fire protection system components were evaluated using the system as-built drawings from FY15 Project P1551 "Upgrade Fire Suppression and Ventilation Systems" to determine if the system was installed per the design.
- Additionally, the overall capacity and operation of the existing system was assessed to determine if adequate protection would be offered in the event of an emergency. This assessment included confirming the findings of the 2010 Audit Report prepared by the Department of the Navy.
- Systems investigated while in the field include the water standpipe system, the fire-foam sprinkling system (lower tunnel), the water sprinkling system (upper tunnel), fire detection, alarm, and mass notification equipment, smoke ventilation system, fire foam retention components, plus pumps, water supply, and all other aspects of the alarm and suppression system.
- Various meetings were held while at the site, including discussions with FLC personnel and NAVFAC Pacific fire protection subject matter expert.
- Equipment cut sheets and product data were investigated to support the fire system assessment, but also to provide information to the life cycle sustainment effort being performed concurrently by Brockenbrough.
- In general, the as-built drawings were not accurate as to the location of various fire system devices (approximately 85% of devices did not match the location shown on the as-built drawings). However, the system was found to be generally in satisfactory condition, with most device locations acceptable per applicable codes and standards. It appears that the issue is mainly with the accuracy of the as-built drawings, not the location of the components.
- The Fire Protection Assessment Report being submitted as a primary deliverable of this task order will offer more details on the findings and recommendations for the fire protection system of this fuel facility.

#### **Life Cycle Sustainment Plan Effort Field Investigation Notes:**

- Brockenbrough Engineers performed a walkthrough of all piping systems, infrastructure
  equipment, and fire protection components as part of the field investigation for the life
  cycle sustainment assessment.
- Available product data was gathered from all applicable equipment and components and all applicable systems were investigated and assessed to determine age, condition, and operability factors.

- Document research was performed in an attempt to determine age, make/model, capacity, and other pertinent information on all applicable components and equipment.
- Various meetings and informal discussions were held while at the site, including discussions with FLC personnel, and NAVFAC Pacific personnel, and several other pertinent representatives.
- Life cycle personnel coordinated closely with the fire protection assessment team for information and evaluation of the fire protection systems and equipment.
- In general, the various system components and equipment that support the red hill fuel
  system were found to be generally in fair condition, with many of the items serviceable
  but approaching their expected service life, and thus requiring significant maintenance or
  repair to remain in operation.
- The Life Cycle Sustainment Report being submitted as a primary deliverable of this task order will offer more details on the findings and recommendations for the overall condition findings and potential required maintenance and routine repairs of this fuel facility.

The above summary represents the initial findings of the Brockenbrough lead field team from our recent site visit. These findings should be considered legitimate, but preliminary. As we continue to process the data and further develop our analysis, significant finding items may be added, subtracted, or adjusted from what is stated above.

Please contact us if you have any questions or need more information. Sincerely,



Project Manager/Mechanical Engineer

Enclosures: InterSpec Preliminary Trip Report



# **Environmental Inspection Services**

464 S Independence Blvd, C-104, Virginia Beach, VA 23452 www.interspecllc.net

June 6, 2022

Office: 757-622-6299

Toll Free: 800-546-7853

Fax: 757-622-9103

Trip Report: Red Hill Bulk Fuel Storage Facility Location: Joint Base Pearl Harbor Hickam; HI

Attention: 6) (6) - Fuels Infrastructure (Austin Brockenbrough & Associates, LLC)

Subject: Draft Summary of Findings and Work Completion Report

This trip report summarizers the work completed and presents a draft finding of inspection conducted between March 22 through May 17, 2022 of the tunnel aboveground piping systems designated for inspection at the Red Hill fuel complex in Hawaii. The inspection was performed by a certified API-570 inspector from InterSpec, LLC. All data was collected in accordance with the guidelines set forth in API Standard 570, the appropriate ASME Codes, 40 CFR 112, and other supporting documents. Note: findings discussed in this trip report are not intended to be comprehensive, and the data collected requires analysis before a complete report is issued.

The project included mobilization of equipment and personnel to support the activities outlined in the SOW. The following inspections and tasks were completed:

- i. Guided wave (GW) or long-range ultrasonic testing (LRUT) of the selected concrete bulkhead penetrations and concrete support contact points. A representative sample of bulkhead penetrations and concrete support contact points were examined at the Tank Gallery, Harbor Tunnel, and Surge Tank. A total of 32 LRUT data acquisition setups were completed (note some locations yielded poor data due to pipe geometry or low amplitude signals).
- ii. Conducted manual and semi-automated Phased Array Ultrasonic Testing (PAUT) examinations of 86 welds. A representative sample of welds were examined at the Tank Gallery, Harbor Tunnel, Surge Tank, and Underground Pump House (UGPH).
- A hands-on API-570 visual inspection of the primary piping, header piping, and associated valves and equipment for the pipelines, the (b) (3) (A) piet propellant grade 5 (JP-5), and the diameter pipelines. Piping associated with Surge Tanks and the FOR lines from the Tank Gallery to Tank 311 were inspected. The UGPH piping, pumps and pressure reliving devices/piping were also closely inspected and findings documented. The section of JP-5 Piping from Tank 20 to MOV 0163 was not evaluated during this trip (An API-570 inspection along with various NDE was completed on this section of piping in July 2021). An appendix will however be provided highlighting the status of this segment of piping and work completed at the time of demobilization.
- iv. Sections of piping inspected were also evaluated with ultrasonic thickness at selected locations to evaluate for internal and external corrosion and to establish Condition Monitoring Locations (CMLs) in accordance with API-570 and per the project scope. Dry Film thickness (DFT) readings were also conducted throughout the facility piping.
- Project also included removal of lead-based paint at 86 locations to support the PAUT weld examinations. All activity related to coating removal, collection, and disposal was managed by trained personnel per industry standard and Facility/OSAH regulations.
- vi. All PAUT weld examination locations required surface preparation (weld spatter filling) to ensure adequate coupling to aid the transmission of ultrasonic energy.
- vii. At the completion of the project, all areas where coating was removed was coated with a Kem Kromik Universal Metal Primer.

#### I. Preliminary Results of LRUT:

The LRUT data collected were field analyzed for accuracy, signal amplitude, and range. The preliminary data did not indicate any significant areas of reportable indications to warrant integrity concern. A full data analysis will be performed using the MsS data analysis and reporting software to validate all collected data. The data, analysis, data summary supporting drawing, and photos will be provided in the draft final of the inspection report. Twenty (20) locations were proposed for LRUT screening.

### **II.** Preliminary Results of PAUT Weld Examinations:

The purpose of this Phased Array Ultrasonic Testing (PAUT) weld examination was to detect any service induced defects such as cracking or erosion/corrosion that may be present in selected welds and heat affected zones. Welds selected are intended to be a representative sample of facility piping and selected based on areas that could see higher than normal stress due to pipe movement, cyclic stresses, or boundary restraints (sections between anchor points). The primary focus of the PAUT weld examination was the circumferential welds, but select abutting longitudinal welds were also examined for completeness when possible. The original welding flaws were considered non-relevant for this inspection since there is satisfactory service history. A combination of manual and semi-automated PAUT was performed and results documented. The preliminary PAUT data indicated there was no service induced defects on all tested welds. The inspection data and results will be provided in the draft final of the inspection report. Eight-six locations were proposed for PAUT weld examination.

# III. Preliminary Results of API-570 Inspection:

A hands-on API 570 visual inspection of the primary piping, header piping, and associated valves and equipment for the F-24, the diameter jet propellant grade 5 (JP-5), and the diameter (F-76) pipelines was completed. Piping associated with Surge Tanks and the FOR lines from the Tank Gallery to Tank 311 was also inspected. The UGPH piping, pumps, and pressure reliving devices/piping were also closely inspected and findings documented. The inspection consisted of close visual examination of the piping to include coating inspection, pit measurements/sizing, corrosion evaluation, dent measurements/sizing, support inspection, soil-to-air/concrete-to-air interface inspections, crevice inspection at saddle and supports, along with other piping system integrity consideration. Inspection also included documenting/reviewing previous repairs. Attached is a summary of inspection findings grouped by location at this facility:


- A. Tank Gallery Piping
- B. Harbor Tunnel Piping
- C. UGPH Piping
- D. Surge Tank Piping
- E. FOR Piping

InterSpec, LLC. API-570 #34301 CWI #10041021 NACE CP 2 (Cert No. 41291)

# SUMMARY OF INSPECTION FINDINGS

	T 1	0 1	1	D.	
A	Tank	(tal	erv	PIT	mo
4	T COLLE	Our	LULY	1 10	1115

A1) Brass/bronze (low melting point) valve attached to the end blind flange of the (F24) line near Tank 15/16.



A2) Minor staining on the upstream throat plug of the DBB skin valve for Tank 16. Monitor as needed; note: plug cannot be removed without draining the tank.



A3) There is an HPV valve on Tank 16 before the skin valve that is missing a plug. Some



A4) Coating failure and corrosion on tank (F-24) pipe at




A5) The \_\_\_\_\_\_ (F-24) line appears to have some type of thick asbestos or bitumen encapsulated asbestos coating from \_\_\_\_\_\_ to about \_\_\_\_\_. Inspection of the pipe in this area is limited. There is one location near \_\_\_\_\_ 38 that appear to be a dent underneath the thick coating around the 7 o'clock position. Size could not be verified.

(b) (3) (A)



A6) Moderate corrosion on the base of plate and vertical member of and on (F-24) line.




A8) Pipe not adequately supported at on (F-24) line. Note: saddle is not engaged, wood shim used, saddle not secured to the I-beam.



A9) Long segment of the unsupported pipe between with only partial support on one side. (F-24) pipe is unsupported. One location has of the unsupported between with only partial support on one side.



A10) Threaded 2-inch carbon steel LPD valve mounted on the underside of the 24) between .





A11) Facility piping at the tank tees has nonstandard (No ASME B16.5) rated flanged fittings and non-standard weld tie-ins. Noted throughout the facility (tees between tanks). Tank 13/14 shown.






A15) There is a threaded fitting with brass (low melting) valve on top of the . Note: these types of valves are not intended to be used on fuel systems. Some staining noted at the packing nut. A16) Coating failure and some corrosion due to material drips from tunnel ceiling on the (JP-5) pipe at (no significant pitting noted). A17) Some coating failure and corrosion between pipe and pipe support on the (JP-5) pipe at . (similar corrosion at A18) There is a threaded gate valve by Tank 7 and 8 that extends down from the (JP-5) down below the pipe. Possibility to get damage by impact. HPV on

A19) There is a threaded bronze/brass (low melting) valve attached on the top of the (F-76) header pipeline between the control of the pipe. Note: these types of valves are not intended to be used on fuel systems. Some staining noted at the packing nut.




A20) Dresser coupling to Tank 14 is missing the deflection ring on the cap noted between the washer and harness lug.












A23) The second pipe support from Tank 9 for the pipe is not in contact with the pipe (floating pipe). It is 39-feet of unsupported pie from tank to the tee.



A24) Several of the fasteners on flange from the between Tank 9 and 10 have moderate corrosion. (F-76) header to lateral tees




A25) The branch piping on (F-76) header has a welded and flanged branch fitting at
about the 2 o'clock position. Two fasteners were not fully engaged.  (b) (3) (A)
A26) Coating failure and some corrosion due to material drips from tunnel ceiling on the (F-76) pipe at PS 66 (no significant pitting or thickness loss noted).
(b) (3) (A)
A27) There is a branch connection on the threaded fitting and valve. Some fuel staining was noted around the flange and pipe, but no active weeping was noted  (b) (3) (A)

A28) Some staining noted on the weeping noted). Note: the staining did not appear to be based on odor and gas meter testing) and had the viscosity of oil. InterSpec suspects this oily substance is caused by one of the two following reasons: oil used to lubricate the bolts or areas rich in polyamide or amine content in the epoxy coating that caused yellowing/blushing and/or an oily exudate. Chemical reactions that form the exudate creates a chain of reactions that can lead to a sticky, oily, or waxy film appearing on the surface of the cured epoxy coating. Amine blush testing or lab testing is suggested to fully determine the fluid type. Review of prior history at this flange and work completed will aid in determining the exact source. Industry standard including gasket manufacturers do not recommend tightening or torqueing a flanged fitting while it is in service

(b) (3) (A)

A29) Wood support extending from the unknown (Near







A30) One joint harness with gap noted on the dresser coupling at the large are no deflection rings and adapters on the harness lugs. Note: lugs are installed



A31) Note: a section of the (JP-5) was undergoing repairs at the time of the inspection. Sections of pipe were isolated, cut, or blanked off.

B1) Moderate coating failure and corrosion on pipe, flange, and fasteners noted on all three lines (segment from to the UGPH bulk head). Corrosion due to drips from tunnel ceiling; there is currently a yellow tarp hanging above the pipes in this area. Notable corrosion was on the (JP-5) line.





B2) HPV are threaded valves, nipples, and ball float trap. Staining and weeping were noted around the threaded fitting on the (F-76) past isolation valve #0151. Similar staining and weeping were noted on the plugged HPV valve just before the bulkhead to UGPH on the line.



B3) Staining noted around the threaded LPD on the to UGPH. This LPD is directly below the plugged HPV valve mentioned above. Note: a total of three threaded LPDs noted on the UGPH bulkhead.






	Some staining and wetting was noted on the threaded LPD assembly on LPD just past note the drip pan)  (F-76)
B5)	All three piping from to the UGPH bulk head have several threaded LPDs.
(h	Corrosion noted on the threaded LPD assembly (including flange, nipples, and fittings).  Notable finding is the (JP-5) line just past (JP-5) line just past (JP-5) line just past (JP-5) (JP-5) line just past (JP-5) (JP-5
\	
B6)	The state of the s
(b)	#0156. Note corrosion on nipple before LPD drain valve.  (3) (A)
50	
B7) (b) (3) (a	The (F-24) line has several threaded LPDs and HPVs


B8) LPD with notable corrosion on the UGPH. Note: corrosion on nipple before LPD drain valve.



B9) Twin Seal DBB flange holes are drilled and tapped, when there is no possibility of fitting a hexagonal nut behind the flange when manufactured. The DBB valve on the F-24 line (Valve # 0159) has four studs on the top and four studs on the bottom with minimal thread engagement to the DBB flange (tank side flange). Threaded engagement of only 0.250 to 0.550 inches was measured. There is also one stud on the other side of the DBB flange (UGPH side) that is not fully engaged with less than 0.500 inches measured. Red arrow shows measured engagement depth of studs (white dots/lines marked with white paint on the flange)

(b) (3) (A)





B17) Several threaded valves and nipples noted on all three piping from beginning of the Tank Gallery section. These are used as LPDs and HPVs. Minor staining was noted on some threaded fittings, but no active weeping or leaks were noted during the inspection (note: system was not in operation or pressurized during the

inspection)
(b) (3) (A)

B18) Isolation DBB valve # 152 on the missing a nut and bolt on the DBB top plate. (F-76) line by ADIT 2 wye past is



B19) The (F-24) line has a nonstandard repair at bulkhead between

The repair includes a full encirclement welded split sleeve (clamshell) on P

side and a partial (patch plate style) repair on side of the bulkhead with square corner (API STD 570 list all repair patches shall have a min of 1"


B21) The concrete saddle (Saddle # 530) is cracked on the edge with large splint noted on (F-76) line at about the 7 o'clock position.






B22) The (F-76) pipe has a threaded NPS 2 HPV welded on top of a full encirclement welded split sleeve repair between lock, and the reducing bushings are not engaged completely in the valve. (Lock valve out)







- (46" from P B25) Pitting Corrosion on (JP-5 line) between 9 o'clock. Corrosion Area is 9" x 9", Pit Depth is 0.050 - 0.140", Metal thickness on unaffected area is 0.239 - 0.244" resulting on a remaining metal thickness of 0.099".
  - Note: this does not meet API 574 structural minimum thickness (SMT). SMT for NPS 18 is 0.110" per Table 7.
  - Note: Also, does not meet ASME B31.3 Equation (3a) from Paragraph 304.1.2









B27) Concrete saddle support (# 337) between the pipe and the concrete saddle. Reason is unknown.





B28) Several active and inactive pitting and general corrosion on section of the (JP-5) pipe, approximately 21-inches from were noted. The pitting/corrosion area is at the 12 o'clock position. The UTT adjacent to the pit was 0.225 -0.242 inches. Remaining metal thickness of 0.130" to 0.147" is estimated here.



B29) Several inactive pitting and general corrosion on section of the between The pitting/corrosion area is at the 10 o'clock position. Pit depth of 0.080" to 0.140" measured.





B30) Pitting Corrosion on (JP-5 line) between (158" from at 6 o'clock. Corrosion Area is 10" x 10", Pit Depth is 0.055" - 0.102", Metal thickness on unaffected area is 0.218" - 0.238" resulting in a remaining metal thickness of 0.116" to 0.136". Note: very close to API 574 (0.110") and ASME 31.3 (0.109" limits).






B31) Corrosion on pipe support at the tunnel wall attachment at





B32) Inactive pitting on JP-5) line between (50" from ) at 10 o'clock. Corrosion Area is 8" x 8", Pit Depth is 0.050" - 0.135", Metal thickness on unaffected area is 0.226" - 0.234" resulting in a remaining metal thickness of 0.091" to 0.099". Note: below the min thickness limits of API 574 (0.110") and ASME 31.3 (0.109").



B33) Inactive pitting on (JP-5) line between (121" from PS 291) at 5 o'clock. Corrosion Area is 6" x 6", Pit Depth is 0.050" - 0.089", Metal thickness on unaffected area is 0.241" - 0.234" resulting in a remaining metal thickness of 0.152" to 0.156".



B34) Inactive pitting on at 6 o'clock. Corrosion Area is 3" x 2", Pit Depth is 0.114", Metal thickness on unaffected area is 0.383" - 0.387" resulting on a remaining metal thickness of 0.269" to 0.273".



B35) Inactive pitting on F-76) line between (22" from ) at 6 o'clock. Corrosion Area is 15" x 24", Pit Depth is 0.050" - 0.114", Metal thickness on unaffected area is 0.386" - 0.393" resulting in a remaining metal thickness of 0.186" to 0.193".





B36) Wood shim installed on (f-76) pipe between Teflon pad and concrete saddle in an attempt to correct lack of support at concert saddle # 193 (Between 0). Pipe is not fully and uniformly supported.





- B37) Pitting Corrosion on (JP-5) pipe between (17" from at 2 o'clock. Corrosion Area is 2" x 2", Pit Depth is 0.113", Metal thickness on unaffected area is 0.233" 0.238" resulting in a remaining metal thickness of 0.101" to 0.105".
  - Note: this does not meet API 574 structural minimum thickness (SMT). SMT for is 0.110" per Table 7.
  - Note: Also, does not meet ASME B31.3 Equation (3a) from Paragraph 304.1.2




B38) Active pitting on (F-76) line near at 11 o'clock. Corrosion Area is 18" x 24", Pit Depth is 0.050" - 0.120", Metal thickness on unaffected area is 0.298" - 0.321" resulting in a remaining metal thickness of 0.178" to 0.201".










B40) The longitudinal weld on the has a five-inch long area of weld porosity. (39" from



B41) There is unsupported and unreinforced branch connection on the July (JP-5) pipe between Line is not used, has skillet, and blind flange.



B42) Lack of thread engagement and one bolt missing a nut on flanged 6-inch branch fitting mounted on the 2 (F-76) line between . Note: the blind flange used also not ASME B16.5 rated/marked flange. It is a one-inch round plate with bolt holes (Plat thickness is 0.981" and appears to meet thickness required). ASME B16.5 NPS 6 class 150 blind flange has a minimum flange thickness of 0.940"



B43) The concrete saddle (Saddle # 36) is cracked on the edge with large splint noted on (F-76) line at about the 7 o'clock position.





B44) Out-of-round/flat spot noted on the weld (12 o'clock to 3 o'clock position).

B45) Air-to-concrete interface corrosion and under-wrap corrosion near weld on

5) pipe between (bulkhead penetration). Corrosion is between 2 to 6 o'clock. Pit Depth is 0.0625" to 0.105", Metal thickness on unaffected area is 0.240" - 0.243" resulting in a remaining metal thickness of 0.135" to 0.138". The interface corrosion appears to be due to drips from ceiling and failed coating system. The interface corrosion does not seem to extend in to the concrete (small section of concrete chipped to check)



B46) Coating at the harbor tunnel consisted of bitumen with asbestos warp; sections with wax tape wrap and coating with lead and another hazardous chemical.





## C. UGPH Piping

C1) Two loose joint harnesses were noted on the discharge side of Pump P-201. Note: before continued operations: All restraining nuts should be snug (not necessarily torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Gaps measured between harness lug and nut were 0.082" and 0.734".

Note: additional design and/or MFG document review is needed to determine how much is too much gap on the joint harnesses, but initial understanding is that gaps should not exceed the pipe-to-pipe gap specified within the coupling. Additionally, joint harness gaps should likely not exceed the height of the deflection ring when provided (note all dresser couplings

in the UGPH are not provided with deflection rings and adapters on the harness lugs).



- C2) Four loose joint harnesses were noted on the suction side of pump Gaps: lower left = 0.200", lower right = 0.173", top right = 0.010", top left = 0.210" (See Notes above)
- C3) Pump shaft guard post not secured to the concrete pad on pump (pump appears to be undergoing repair).



Several open conduits and sensor enclosures noted on pump C4) pump appears to be undergoing repair).



C5) Several loose fasteners noted on the upper half casing of Pump P-201 (pump appears to be

undergoing repair).



C6) Pump P-201 had a skillet installed on the discharge side of the pump nozzle. The assembled joint only had one gasket installed. Consider using two gaskets when installing spectacle blind or skillet to protect the flange face and contact surface from damage; particularly for flanges with serrated finishes (ASME B16.5 and ASME PCC-1-2019). Similar condition noted on P-205.



C7) Some minor coating cracks was noted on the dresser coupling around the middle ring-to-follower joint area of Pump P-201 discharge line (indicating potential movement). This movement is most likely due to loosened joint harnesses and not limitation of the dresser coupling (These couplings have demonstrated satisfactory performance when MFG specification and guidance are followed). PM program that verifies dresser coupling mechanical integrity (verifying joint harness retention rod and follower bolt tightness).




C8) Hairline crack noted on Pump P-201 pump pad. (PHOTO)

Strainer drain ball valve on the inlet side of the control valve is not plugged. Consider C9) installing a plug on the strainer drain valve and remove only during maintenance (Typical

for all control valves on the discharge side of pumps at UGPH).



C10) Weeping at suction side pressure gauge associated with Pump P-201.



C11) Hairline crack noted on Pump P-202 pump pad. (This was noted at several pumps)



C12) Coating failure on pump casing on Pump P-202



C14) Several of the ball valves on the control valve are missing valve handles. Exact reason is unknown but suspected to prevent operation of the valves (Note: operating during emergency such as a tubing break or damage will be difficult with missing valve handles. Consider a carseal for valve line up. (Typical for majority of control valves on the discharge side of pumps



C15) Minor bearing oil staining on pump casing (Typical for some pumps at UGPH). Pump P-



(b)	The control valve tubing on Pump P-202 is in contact with UGPH grating I-beam (potential for abrasion damage that can lead to malfunctioning control valve).  (3) (A)
C17)	Heavy discoloration and staining on control valve body on Pump P-202. Drip pan and absorbent pads were noted beneath the control valve. Similar discoloration and staining but
(b	(3) (A)
(b) (	Conduit plug used on pressure gauge pipe tee. This is not per industry standard and not known if this conduit plug has the correct tapper for use as NPT plug. (This was noted at several locations of the pressure gauge piping and at several pumps at UGPH)  3) (A)
(b) (3) (A)	

- C20) One slightly loose joint harness was noted on the discharge side of Pump P-203. Note: before continued operations: All restraining nuts should be snug (not necessarily torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Gaps measured between harness lug and nut was 0.030". (PHOTO)
- C21) Two loose joint harnesses were noted on the discharge side of pump P-204. Note: before continued operations: All restraining nuts should be snug (not necessarily torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Gaps measured between harness lug and nut were 0.180" and 0.845"



C22) The outlet side flange on the control valve on Pump P-204 is not fully engaged.





C23) Two slightly loose joint harnesses were noted on the discharge side of Pump P-205. Note: before continued operations: All restraining nuts should be snug (not necessarily torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes. Gaps measured between harness lug and nut were approx. 0.030".





C24) The ball valve before the strainer on the inlet side of the control valve was in the closed position at the time of the inspection on P-205. The control valve may not function as intended when the system cannot detect differential pressure. Consider a car-seal for valve



C25) Missing nut observed on the suction side of the joint harnesses of pump P-205. Note: before continued operations: All restraining nuts should be installed and snug (not necessarily torqued down but at least fully in contact with lugs). Should also be equipped with double nut or lock nut to prevent backing-out at areas prone to vibrations. Restraining rods should be engaged to electrically bond the two sections of pipe across the dresser coupling on fuel pipes.

(See next item about loose joint harness on the same dresser coupling)






C26) One loose joint harness on the suction side of the joint harnesses of Pump P-205 (this is the same dresser coupling with the missing nut). Gaps measured between harness lug and nut were: Upper left = 0.250". lower left side = 0.275". (Facing pump)






C27) Moderate weeping/staining on front bearing shaft and casing on Pump P-206. Similar



Some inactive corrosion and bolt diameter reduction (due to the corrosion) noted on the



The hazardous area rated flow switch (MFG by SOR Inc) mounted on the discharge side of Pump P-206 has a housing cover that is not secured. Will not meet hazardous area rating (NFPA class I, division II, Group D). Additionally, all housings must be properly "sealed" at the conduit connection and housing cover to maintain the NEMA classification.



C30) The ½-inch discharge side pressure gauge threaded fittings have several areas of wetting/weeping around the threaded fitting on Pump P-208. Wet absorbent pads noted

beneath the fittings.



C31) One slightly loose joint harness was noted on the discharge side of pump P-209. Gaps measured between harness lug and nut were approx. 0.030" (enough for the rod and bolt to move laterally).

(PHOTO)

C32) Two slightly loose joint harnesses were noted on the discharge side of Pump P-210. Gaps measured between harness lug and nut were approx. 0.030" (enough for the rod and bolt to

move laterally).



C33) Dresser lugs on Pump P-210 suction side are installed backward (this was also noted on the

other dresser couplings at UGPH).



C34) There are several open conduits, exposed wires, and unsealed electrical equipment housing throughout the UGPH including what appears to be abandoned conduits on the floor. Will




C35) The open conduit on the UGPH floor will limit the secondary containment capability of the UGPH (no secondary containment).





C36) Several brass/bronze fittings used on the fuel system (low melting point material). Gate Valve GI58I shown). Same for Valve GI58G, GI58H.




C37)	Several staining, weeping fittings noted in the UGPH piping below the grating (on main header piping to/from the RH and main header to/from the lower yard tunnel). This was noted on tie-ins for temperature sensors, pressure sensors, HPVs, and other small-bore auxiliary fittings
(b) (3	3) (A)
C38)	Several threaded fittings noted in the UGPH piping below the grating (on main header piping to/from the RH and main header to/from the lower yard tunnel). Note: some of the branch tie-in welds are not per industry standard (did not use Weldolet and other branch connecting fittings that provide integral reinforcement and reduce stress at joint). This includes HPVs,
(b) (3)	
C39) (b) (3)	Lack of thread engagement (QTY 12) on the bypass loop across the to/from the RH. This is on the pup piece that replaced the flow meter.


Several transducers are attached to the pipe, and the conduit did not have seal-off fitting. There is no tag or marking on these transducers that provide the hazardous location rating or the enclosure NEMA rating. Additionally, the transducer is connected using ridged conduit

(b) (3) (A)		

C41) Several of the pressure transducers have past due calibration dates. (Due Date of 10/23/18)



There are staining and some drips noted on the Cameron ball valves. shown. The staining /drip is from the stem injection port. Tighten the stem nut to correct or replace the



Localized coating failure and corrosion (due to drips) on section of the line just before ball valve # 232E4. Pit depth = 0.050" to 0.070"





C44) There are several branch tie-ins on the line that are used for pressure relive devices. There is one missing gate wheel nut on Gate Valve # GR68B.



C45) There is DBB valve on the line (Valve # 232E2) with six studs that are not fully engaged. The stud is supposed to be engaged on the upper position of the DBB flange anywhere from 1.75 to 1.88 inches. Threaded engagement of only 0.25 to 0.75 inches where measured. Green arrow shows the available thread depth, the red arrow shows measured engagement depth of studs. (black dots marked with black Sharpie on the flange).




C46) There ¾-inch HPV on the (F-24) line after This ¾-inch line is routed towards the UGPH sump nut and terminates just before the sump. The end of this line is open without a pipe plug. This is located just below the UGPH sump access staircase.








C48) Fuel soaked absorbent pads on the valves, piping, and UGPH floor (typical at several PRD branch connections). Fuel is from the PRD above the grating.



Mechanical dent on F-24) tie-in line (to/from surge tank). Dent depth is 0.505" with perpendicular orientation and length of 5" located 58" from the miter weld before the surge tank-to-UGPH bulkhead penetration. This results in a dent depth of 3.2%. Note: initial assessment indicates this dent is acceptable based on latest edition of API RP 1183; Assessment and Management of Pipeline Dents. Plain dents regardless of shape with depths up to 10 % of the pipe diameter, without coincident features such as metal loss, welds, or cracks have been shown in testing to have the same failure pressure as plain line pipe (Section 1). Dent is also acceptable per API 579 section 12 Level 1 assessment (acceptable if it is  $\leq$  7% of the pipe diameter)







C51) Missing one nut and bolt on the 12-inch valve flange that branches off the line from the lower yard tunnel (Valve 216ES ??) (No close-up photo, but valve/flange before green arrow. Photo facing Surge tank bulk wall)



C52) The JP-5 header manifold attached to the piping to/from the lower yard tunnel is equipped with a ¾-inch gate valve (Valve # GP98J) at the end of header. The ¾-inch valve is allowing product to weep by. NOTE: no pressure relief device (PRD) provided to the header (trapped fuel). The large and large do not have PRDs



C53) All the gate valves on the inlet and outlet side of pump are equipped with valve actuators mounted on stitch-welded adapter plate (four stitch-welds approximately 1" to 1.5" long used). Several of the welds have hairline cracks (potential for adapter plate to shear off during actuator operation). Some had one affected weld, and some had up to three of the four welds showing signa of hairline cracks. (Note: weld inspection is limited due to coating. Coating removal and NDE required to gain full assessment). This was present on



C54) Several of the PRDs were weeping. Weeping noted on the CRL Pressure Relief Control body (manufactured by CLA VAL). Weeping noted on diaphragm between top cover and lower body. Some drips also noted on the strainer fittings, treaded stainless nipples, and tubing. No







C56) The PRV system for each piping in the UGPH has an Emerson Figure 533 flow control valve with Hydramotor actuator (QTY 6). The Hydramotor actuators still have the factory plastic caps on the unused conduit inlet ports. This will not meet hazardous area rating (NFPA class I, division II, Group D). Remove plastic caps and install steel conduit plugs; tighten existing

## D. Surge Tank Piping

D1) Several locations without Teflon or isolation material were noted throughout the surge

tank piping system.





D2) Deteriorated grout noted at the bottom of the pipe support at Surge Tank 1 (just past the isolation DBB valve).






D3) The sample/water drain line that ties to the drain line has a valve that is not secured in the closed position; potential for accidental spill (note: inspection team closed the valve during the inspection. Consider a self-closing valve or a LOTO

program).








D5) Some staining noted on the bottom of the flange for the Tank 2; just before pipe support JP5-4 (no active weeping noted). Note: the staining did not appear to be JP-5 (based on odor and gas meter testing) and had the viscosity of oil. InterSpec suspects this oily substance is caused by one of the two following reasons: oil used to lubricate the bolts or areas rich in polyamide or amine content in the epoxy coating that caused yellowing/blushing and/or an oily exudate. Chemical reactions that form the exudate creates a chain of reactions that can lead to a sticky, oily, or waxy film appearing on the surface of the cured epoxy coating. Amine blush testing or lab testing is suggested to fully determine the fluid type.





D6) Some staining noted on the bottom of the flange for the JP-5 line from Surge Tank 2; just before pipe support JP5-3 (no active weeping noted). *Note: See comment in Item 5 above about non-fuel related oily material.* 




D7)	There is a missing plug on a 1-inch ball valve that is mounted to the 4-inch low suction line at Surge Tank 2 Install a plug: consider a self-closing valve or a LOTO program.
(b) (3	(A)
D8)	Lack of thread engagement noted on the low suction pipe flange from Surge Tank 3 (at the pipe branch tie-in).
(b) (3) (A)	
D9)	There is a missing plug on a 1-inch ball valve that is mounted to the 4-inch low suction line at Surge Tank 3. Install a plug; consider a self-closing valve or a LOTO program.
(b) (	(3) (A)
D10)	Some minor staining noted on the bottom of the 32-inch dresser coupling on Surge
(b)	Tank 4 (no active weeping noted). <i>Note: See comment in Item 5 above about non-fuel</i> (3) (A)
X-12	

D11) The TRV system flange at Surge Tank 4 is equipped with 1/16-inch gaskets instead of 1/8-inch gaskets.



D12) Some minor staining noted on the bottom of the flange for the F-76 line from Surge Tank 4; just before pipe support F76-8 (some staining noted on the floor but no active weeping noted). *Note: See comment in Item 5 above about non-fuel related oily* 




P-76 line from Surge Tank 4; just before pipe support F76-9 (some staining noted on the floor but no active weeping noted). Note: See comment in Item 5 above about non-fuel related oily material.





D14) Some staining noted on the bottom of the low suction DBB skin valve flange from Surge Tank 4. Similar discoloration noted on the 1-inch sample line flange (likely due to drips from the 4-inch flange). Operators or others appeared to have applied Kolor Kut fuel gauging paste to detect weather the staining is fuel. Since Kolor Kut fuel gauging paste reacts to hydrocarbons; this method cannot distinguish between fuel versus other oils. Note: See comment in Item 5 above about non-fuel related oily material.



D15) There is a missing plug on a 1-inch sample ball valve that is mounted to the 4-inch low suction line at Surge Tank 4. Install a plug; consider a self-closing valve or a LOTO



E1) Threaded sampling pipe nipple on tank 20 FOR Line after tank skin valve. The threaded pipe nipple is for the Bottom "BTM" sampling.



E2) Missing Teflon pad (metal-to metal contact) between pipe and support on Tank 20 FOR line in the trench past tank sampling line branch.



E3) Moderate corrosion on blind flange and fasteners on Tank 19 (abandoned branch to the sampling lines).






E4) Coating failure and corrosion on the I-beam type pipe supports within the trench (typical throughout the pipe run but noted to be moderate between Tank 20 and Tank 16).



E5) Displaced pipe support on piping within trench between



E6) Displaced Teflon pad pipe support within trench at (Photo)





E8) Spray foam material used to seal edge of AFFF Sump # 1. Foam material is in contact with pipe (Spray foam intent and function unknown).



E9) The top of flange just before the FOR concrete pit; Sump 7 (near Door C) is covered with concrete to include side of the flange, face of flange, and fasteners.



E10) FOR concrete pit; Sump 7 (near Door C), is not lined. Fuel contact water is dropped in this sump before it is picked up with sump pump to downstream segment of the FOR line. There is moderate sump floor-to-wall deterioration with periodic bubble formation






E11) The pressure gauge on the FOR line (from Sump 7 pump) is out of calibration, and the glass is cracked.




E12) Section of the wall mounted pipe by door C has a stained plastic wrap with C-



E13) Section of the wall mounted pipe by door C has a wood shim between pipe and support. Note: pipe is not secured to the support.



E14) Section for the FOR pipe from Sump 7 is threaded piping until it ties in to the Tank 15/16 FOR line.



E15) Section of threaded FOR piping between and has three segments of unsupported piping measuring 23 ft, 22 ft and 20 ft respectively. Note: industry standard is nine foot span for





E17) The segment of the FOR piping has four brass/bronze (low melting point) valves where the line ties in to Tank 15/16 FOR trench piping. This includes the temporary line that is attached to the header pipe.



E18) There are three pipe supports in the trench that are displaced near the FOR-line tie-in at Tank 15/16 (past the flange from the above photo).





E19) Tank 16 sample lines are not equipped with skin valves positioned as close as practical to the tank shell (and or nozzle).



E20) Threaded sampling pipe nipple on Tank 16 FOR Line after tank skin valve. The threaded pipe nipple is for the Bottom "BTM" sampling (see photo in item 21).

E21) skin valve at Tank 16 has one fastener that is not fully engaged.

(b) (3) (A)


E22) The FOR piping within the trench by Tank 15 has a 2 x 4 wood shim (the support is slanted and not adequately supported.



E23) There are three fasteners on gate valve past the DBB skin valve that are not fully engaged at Tank 15.



E24) Tank 15 sample lines are not equipped with skin valves positioned as close as practical to the tank shell (and or nozzle).







E26) FOR system at Tank 14 was isolated for ongoing repair activity by a contractor.

E27) The tank sampling system at Tank 13 was upgraded with new piping to include installing flanged joints in the past. Three flanged joints have cracked gaskets indicating potential improper torque sequence, over torqueing, or use of lubricants that chemically

```
(b) (3) (A)
```


E28) The FOR piping within the trench at Tank 13 does not have correct pipe supports. Wood








E30) Tank 9 sample lines are not equipped with skin valves positioned as close as practical




E31) Some coating failure and corrosion noted on the tank sampling lines throughout the facility; mostly on the treaded style sampling system that has not yet been upgraded to welded and flanged system. Tank 9 sampling system had the most aggressive corrosion on piping and supports. There are no skin valves close to the tank for Tank 9 sampling system. NOTE: additional evaluation to include coating/corrosion removal is required to fully access the affected sample pipe. A spill kit and pipe repair clamp should be readily available during corrosion removal.

Example of Tank 9 sample lines (heavy corrosion on pipe/support)



Example of tank 7 sample lines (minor to moderate corrosion)



E32) Missing coated U-bolts and isolation Teflon on Tank 5 FOR piping. (QTY 3)





E33) Tank 4 sample lines are not equipped with skin valves positioned as close as practical to the tank shell (and or nozzle). This tank has approximately t of pipe between the tank and the first available isolation valve located at the sample manifold.




E34) Section of FOR piping through the AFFF Sump pit # 4 (Just past plastic (reason unknown but assumed to protect FOR pipe during repair at the sump pit







E36) Tank 3 sample lines are not equipped with skin valves positioned as close as practical to the tank shell (and or nozzle).



E37) Some staining noted on Tank 4 sampling system (just below the "135 foot" sample line valve).



- E38) There is a segment of unsupported FOR piping spanning at Tank 4 (Note: industry standard is fourteen foot span for 1.5-inch pipe). The weight of the sampling line header is also bearing on the FOR line.


  [NO PHOTO]
- E39) Missing Teflon pad (metal-to metal contact) between pipe and support on FOR line between



E40) Missing Teflon pad (metal-to metal contact) between pipe and support on FOR line between [NO PHOTO]

- E41) Missing Teflon pad (metal-to metal contact) between pipe and support on FOR line between (closer to ).

  [NO PHOTO]
- E42) There are three locations on the pipe with repair clamps at the FOR-Sump (S-23) downstream of the isolation valve (shown with green arrow). The presence of these types of clamps indicate there were areas of compromised pipe sections at this location. A 6", 16" and 8" full circumferential, single-section stainless steel repair clamp manufactured by Romac Industries is used with a 54-inch section of the pipe. See next related inspection item



E43) Several low ultrasonic thickness (UT) data was recorded near the locations where repair clamps are used. A section of FOR pipe was closely checked with a UT gauge, and several locations with thickness ranging from 0.106" to 0.190" were identified indicating over 55% of metal loss was present. The nominal thickness of pipe is 0.237" See next related inspection item



E44) The section of piping identified with low UT data and repair clamps is consider a deadleg with stagnant area that normally has little or no significant flow. This section requires a low point drain (LPD) or periodic flushing to prevent microbial-influenced corrosion (MIC).

To sump tank

From pump Tank 311

Sump/pump bypass valve

Area with little or no significant flow (dead-leg)

E45) The sump/pump bypass valve flange is missing a nut.





E46) The DBB on the sump pump discharge line before the strainer is missing a body cavity relief valve handle. The valve is also not plugged when not used.





E47) The valve above the FOR isolation valve has a lose flange with several missing







E48) Missing coated U-bolts and isolation Teflon on FOR isolation valves supports.





isolation valve to the ADIT 3 door is E49) Segment of tunnel piping from the constructed with mechanical coupling (Style 77 Victaulic joint). Some discoloration corrosion cell and staining were noted at some joints (locations will be identified).

starting at Tank 311 and ending at the isolation valves (Fwere labeled to aide in identifying and locating findings reported. The letter " $\overline{F}$ " is tacked to the pipe supports ( numbers to distinguish the FOR from the facility

designated pipe supports.





is damaged likely due to impact with displaced pipe support and U-bolt. E50)





E51) Several locations with lose U-bolts, displaced Teflon pads, missing Teflon pads or loose hangers were noted. Some of the locations are summarized below with a full list to be provided in the report.

F-PS#	Condition
F-	Loose U-bolts
F-	Displaced Teflon pad
F-P	Missing pipe clamp bolt
F-PS	



E52) Areas of total coating failure and heavy corrosion were identified on sections of the FOR line. Some of the locations are summarized in the table (note: some coating repair activity was noted during the inspection on some specific locations):

F-PS#	Condition
	coating failure and heavy corrosion
	total coating failure with some corrosion scale
	total coating failure with some corrosion scale
	total coating failure with some corrosion scale
	total coating failure with some corrosion scale
	total coating failure with some corrosion scale
	total coating failure with some corrosion scale
F-PS	



E53) There is a 2-inch LPD and <sup>3</sup>/<sub>4</sub>-inch HPV near The LPD is missing a camlock cap, and there are two bolts that are not fully engaged on the 2-inch LPD flange.





E54) There is a 2-inch LPD and <sup>3</sup>/<sub>4</sub>-inch HPV near The LPD is missing a camlock cap, and there are two bolts that are not fully engaged on the 2-inch LPD flange.





E55) A LPD with missing plug and a ball valve that is not locked-out was noted on the FOR line near (note: facility personnel corrected this finding).





E56) A LPD with missing plug and a ball valve that is not locked-out was noted on the FOR line beneath ADIT 3 staircase (note: facility personnel corrected this finding).



E57) There is moderate coating failure and some corrosion noted on the FOR penetration sleeve just below the ADIT 3 staircase (water infiltration at penetration)

pipe by the Link-Seal. Some corrosion was not at the





E58) Several external pitting areas were noted on the FOR section of pipe outside ADDIT 3. The thickness data indicates approximately 0.020" to 0.035" internal corrosion on the segment of pipe with several external pitting ranging from 0.010" to 0.190". This section of FOR pipe is Schedule 40 with original thickness of 0.280". Pitting near has depth ranging between 0.100" to 0.140" and local metal thickness of 0.252" Remaining metal thickness: (0.252'' - 0.140'' = 0.112''). This is equivalent of approx. 60% loss from original thickness or 56% localized loss. Segment of the piping near Fhas pit depth of 0.190" with the local metal thickness of 0.248" resulting in remaining metal thickness of (0.248" - 0.190") 0.058". This is equivalent of approx. 79 % loss from original thickness or 77 % localized loss. There are areas that are not accessible without pipe jacking with moderate corrosion and a suspected weeping/wetting noted at This segment of piping from ADIT 3 riser to tank 311 is not fit for continued service and requires replacement. Length of pipe from the FOR riser to tank 311 DBB valve (outside of the secondary containment) is 151-feet.



E59) There are moderate coating failure and corrosion on the FOR riser flange just outside of ADIT 3 door. Note: there is a threaded fittings with a pressure gauge mounted

on the flange.





E60) Excessive vegetation around pipe (section of FOR pipe to Tank 311).





E61) The wooden staircase is partially resting on the pipe at one side of the landing.





E62) The body cavity relief valve of the receipt DBB valve (outside of the secondary containment of Tank 311) is discharging to the isolated side (should discharge towards the tank side).





E63) The DBB valve (outside of the secondary containment of Tank 311) has one loose fastener. Note: Tank 311 has cathodic protection and fasteners with insulating

flange kit (IFK) is required.





DBB valve (outside of the secondary containment of Tank 311) does not have a complete IFK. The gasket used does not appear to be insulating type and has one missing insulating washer. Additional test required to determine if IFK is functioning properly. Note: it may be practical to install ICCP on Tank 311 and remove the IFK to extend CP to the section of buried piping at ADIT 3 (review of the 2021 CP Report indicated the section of buried piping had ineffective magnesium anode).





E65) The TRV bypass lines (QTY 2) at Tank 311 does not have a complete IFK. Only has insulating washer on the lower flange. The gasket used also does not appear to be insulating type.



E66) The body cavity relief valve of the secondary containment of Tank 311) is discharging to the isolated/caped side (should discharge towards the tank side).





# **APPENDIX 'E' - CALCULATIONS**



Project Name: Fuel Transfer System Inspection

Subject:

 Author:
 CSB
 Date:
 8/22/2022

 Reviewer:
 JWK
 Date:
 8/22/2022

#### ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X  $P_O$ .

Pipe Diameter(inches)	18	D		Step 1
Nominal Wall Thickness (inches)	0.233	t		
Depth of Corroded Area (inches)	0.113	d		Step 3
Length of Corroded Area (inches)	2	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>O</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	<b>SMYS</b>	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 0.954$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 1.263$ 

$$Dt$$
  $M = 1.263$   $S_F = S_{FLOW}(\frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M})$   $S_F = 33592.585$  psi

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6

Hoop Stress, So

$$S_O = \frac{P_O D}{2t}$$
  $S_O = 10622.318 \; \mathrm{psi}$   $P_F = \frac{2S_F t}{D}$  869.675 psi Step 7  $SF \; x \; S_O = 15933.476 \; \mathrm{psi}$ 

Flaw is Acceptable



 Project No:
 22-022
 Sheet:
 1
 1

 Project Name:
 Fuel Transfer System Inspection

 Subject:
 (b) (3) (A)

 Author:
 CSB
 Date:
 8/22/2022

 Reviewer:
 JWK
 Date:
 8/22/2022

## ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area. L

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X  $P_O$ .

0				
Pipe Diameter(inches)	18	D		Step 1
Nominal Wall Thickness (inches)	0.226	t		
Depth of Corroded Area (inches)	0.135	d		Stop 2
Length of Corroded Area (inches)	8	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	SMTS	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	SMYS	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 15.733$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 3.168$ 

$$S_F = S_{FLOW} \, (\frac{1 - 0.85 (\frac{d}{t})}{1 - 0.85 (\frac{d}{t})/M}) \qquad \qquad S_F = \qquad \textbf{22568.958} \qquad \text{psi} \qquad \qquad \textbf{Step 5}$$

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6

Hoop Stress, So

$$S_{O} = \frac{P_{O}D}{2t}$$
  $S_{O} = 10951.327 \; \mathrm{psi}$   $P_{F} = \frac{2S_{F}t}{D}$  566.732 psi Step 7  $SF \; x \; S_{O} = 16924.779 \; \mathrm{psi}$ 

Flaw is Acceptable



Project Name: Fuel Transfer System Inspection

Subject:

Date: 8/22/2022 Author: **CSB** Reviewer: JWK Date: 8/22/2022

## ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X Po.

Pipe Diameter(inches)	18	D		Step 1
Nominal Wall Thickness (inches)	0.234	t		
Depth of Corroded Area (inches)	0.089	d		Cton 2
Length of Corroded Area (inches)	6	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	<b>SMYS</b>	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 8.547$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   
 $M = 2.473$ 

$$z = \frac{L^2}{Dt} \qquad z = 8.547 \qquad \qquad M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$$
 
$$M = 2.473 \qquad \qquad M = 2.473$$
 
$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right) \qquad \qquad S_F = 29971.061 \quad \text{psi} \qquad \qquad Step 5$$

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6

Hoop Stress, So

$$S_{O} = \frac{P_{O}D}{2t}$$
  $S_{O} =$  10576.923 psi  $P_{F} = \frac{2S_{F}t}{D}$  779.248 psi Step 7  $SF \times S_{O} =$  16346.154 psi

Flaw is Acceptable



Project Name: Fuel Transfer System Inspection

Subject: (b) (3) (A)

 Author:
 CSB
 Date:
 8/22/2022

 Reviewer:
 JWK
 Date:
 8/22/2022

### ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal

to or greater than SF X Po.

	t		
102			
1102	d		Cton 2
0	L		Step 3
	M	Calculated below	
75	MOP	(also P <sub>o</sub> )	
0000	SMTS	(ASME B31 3 Table A-1)	
5000	SMYS	(ASME B31 3 Table A-1)	Step 4
9500000	E	(ASME B31 3 Table C-6)	
8500	S <sub>FLOW</sub>	(1.1*SMYS)	
()	75 0000 5000 9500000	D L M 75 MOP 0000 SMTS 6000 SMYS	M Calculated below  MOP (also P <sub>O</sub> )  MODO SMTS (ASME B31 3 Table A-1)  MODO SMYS (ASME B31 3 Table A-1)  MODO SMYS (ASME B31 3 Table C-6)

$$z = \frac{L^2}{Dt}$$
  $z = 25.484$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 3.847$ 

$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right) \qquad S_F = 25861.928 \quad \text{psi}$$
 Step 5

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6
$$SF = 1.5$$

Hoop Stress, So

$$S_{O} = \frac{P_{O}D}{2t}$$
  $S_{O} =$  11353.211 psi  $P_{F} = \frac{2S_{F}t}{D}$  626.433 psi Step 7  $SF \times S_{O} =$  17545.872 psi

Flaw is Acceptable



Project Name: Fuel Transfer System Inspection

Subject: (b) (3) (A)

 Author:
 CSB
 Date:
 8/22/2022

 Reviewer:
 JWK
 Date:
 8/22/2022

### ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal

to or greater than SF X P<sub>o</sub>.

Pipe Diameter(inches)	18	D		Step 1
Nominal Wall Thickness (inches)	0.239	t		
Depth of Corroded Area (inches)	0.140	d		Cton 2
Length of Corroded Area (inches)	9	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	SMYS	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 18.828$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 3.409$ 

$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right) \qquad S_F = 22637.289 \quad \text{psi}$$
 Step 5

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6
$$SF = 1.5$$

Hoop Stress, So

$$S_O = \frac{P_O D}{2t}$$
  $S_O = 10355.649 \text{ psi}$   $P_F = \frac{2S_F t}{D}$  601.146 psi Step 7  $SF \times S_O = 16004.184 \text{ psi}$ 

Flaw is Acceptable



Project Name: Fuel Transfer System Inspection

Subject: (b) (3) (A)

 Author:
 CSB
 Date:
 8/22/2022

 Reviewer:
 JWK
 Date:
 8/22/2022

## ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X  $P_O$ .

Pipe Diameter(inches)	18	D		Step 1
Nominal Wall Thickness (inches)	0.240	t		
Depth of Corroded Area (inches)	0.105	d		Cton 2
Length of Corroded Area (inches)	6	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	<b>SMYS</b>	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 8.333$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 2.448$ 

$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right)$$
  $S_F = 28513.543$  psi

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6

Hoop Stress, So

Estimated Failure Pressure 
$$P_F = \frac{2S_F t}{D}$$
 760.361 psi Step 7

 $S_{O} = \frac{P_{O}D}{2t}$   $S_{O} =$  10312.500 psi  $SF \times S_{O} =$  15937.500 psi

Flaw is Acceptable Step 8



Project Name: Fuel Transfer System Inspection

Subject:

Author: **CSB** Date: 8/22/2022 Reviewer: JWK Date: 8/22/2022

### ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X P<sub>o</sub>.

Pipe Diameter(inches)	18	D		Stop 1
	ORDER DE LA COMPANIE	U		Step 1
Nominal Wall Thickness (inches)	0.225	t		
Depth of Corroded Area (inches)	0.095	d		Cton 2
Length of Corroded Area (inches)	3	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	SMYS	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 2.222$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 1.542$ 

$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right) \qquad S_F = 32170.106 \text{ psi}$$
 Step 5

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6

Hoop Stress, So

Hoop Stress, So Estimated Failure Pressure 
$$S_O = \frac{P_OD}{2t} \qquad S_O = \qquad \textbf{11000.000 psi} \qquad P_F = \frac{2S_Ft}{D} \qquad \textbf{804.253 psi} \qquad \textit{Step 7}$$
  $SF \times S_O = \qquad \textbf{17000.000 psi}$ 

Flaw is Acceptable



Project Name: Fuel Transfer System Inspection

Subject: (b) (3) (A)

 Author:
 CSB
 Date:
 8/22/2022

 Reviewer:
 JWK
 Date:
 8/22/2022

## ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L.

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X  $P_O$ .

Pipe Diameter(inches)	32	D		Step 1
Nominal Wall Thickness (inches)	0.430	t		
Depth of Corroded Area (inches)	0.196	d		Cton 2
Length of Corroded Area (inches)	8	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	<b>SMYS</b>	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 4.651$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 1.961$ 

$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right)$$

$$S_F = 29390.154 \text{ psi}$$

$$S_F = 29390.154 \text{ psi}$$

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6

Hoop Stress, So Estimated Failure Pressure

$$S_{O} = \frac{P_{O}D}{2t}$$
  $S_{O} = 10232.558 \text{ psi}$   $P_{F} = \frac{2S_{F}t}{D}$  789.860 psi Step 7  $SF \times S_{O} = 15813.953 \text{ psi}$ 

Flaw is Acceptable Step 8



Project Name: Fuel Transfer System Inspection

Subject:

Date: 8/22/2022 Author: **CSB** Reviewer: JWK Date: 8/22/2022

### ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L.

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X P<sub>O</sub>.

Pipe Diameter(inches)	32	D		Step 1
Nominal Wall Thickness (inches)	0.358	t		
Depth of Corroded Area (inches)	0.14	d		Stop 2
Length of Corroded Area (inches)	24	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	SMYS	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 50.279$   $M = 0.032z + 3.3$   $M = 4.909$ 

$$z = \frac{L^2}{Dt} \qquad z = 50.279 \qquad \qquad M = 0.032z + 3.3 \\ M = 4.909 \qquad \qquad M = 50.032z + 3.3$$
 
$$M = 4.909 \qquad \qquad M = 50.032z + 3.3$$
 
$$M = 4.909 \qquad \qquad M = 50.032z + 3.3$$
 
$$M = 50.032z + 3.0$$

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6
$$SF = 1.5$$

Hoop Stress, So **Estimated Failure Pressure** 

$$S_O = \frac{P_O D}{2t}$$
  $S_O =$  12290.503 psi  $P_F = \frac{2S_F t}{D}$  616.864 psi Step 7  $SF \times S_O =$  18994.413 psi

Flaw is Acceptable Step 8



Project Name: Fuel Transfer System Inspection

Subject:

Date: 8/22/2022 Author: **CSB** Reviewer: JWK Date: 8/22/2022

### ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L.

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X P<sub>o</sub>.

Pipe Diameter(inches)	32	D		Step 1
Nominal Wall Thickness (inches)	0.386	t		
Depth of Corroded Area (inches)	0.114	d		C+ 2
Length of Corroded Area (inches)	24	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>O</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	SMYS	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 46.632$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 4.788$ 

$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right) \qquad S_F = 30430.677 \quad \text{psi}$$
 Step 5

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6
$$SF = 1.5$$

Hoop Stress, So

Hoop Stress, So Estimated Failure Pressure 
$$S_O = \frac{P_OD}{2t} \qquad S_O = \qquad \textbf{11398.964 psi} \qquad P_F = \frac{2S_Ft}{D} \qquad \textbf{734.140 psi} \qquad \textbf{Step 7}$$
  $SF \times S_O = \qquad \textbf{17616.580 psi}$ 

Flaw is Acceptable Step 8



Project Name: Fuel Transfer System Inspection

Subject: (b) (3) (A)

 Author:
 CSB
 Date:
 8/22/2022

 Reviewer:
 JWK
 Date:
 8/22/2022

### ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L.

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal to or greater than SF X  $P_O$ .

Pipe Diameter(inches)	32	D		Step 1
Nominal Wall Thickness (inches)	0.387	t		
Depth of Corroded Area (inches)	0.114	d		Cton 2
Length of Corroded Area (inches)	3	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	<b>SMYS</b>	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 0.727$   $M = \sqrt{(1 + 0.6275z - 0.003375z^2)}$   $M = 1.206$ 

$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right) \qquad S_F = 36422.548 \quad \text{psi}$$
 Step 5

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6

Hoop Stress, So

$$S_{O}=rac{P_{O}D}{2t}$$
  $S_{O}=$  11369.509 psi  $P_{F}=rac{2S_{F}t}{D}$  880.970 psi  $Step$  7  $SF \times S_{O}=$  17571.059 psi

**Estimated Failure Pressure** 

Flaw is Acceptable Step 8



Project Name: Fuel Transfer System Inspection

Subject:

Author: **CSB** Date: 8/22/2022 Reviewer: JWK Date: 8/22/2022

## ASME B31G Level 1 Analysis

Step 1. Determine pipe diameter and nominal wall thickness from appropriate records or direct measurement of the pipe.

Step 2. Clean the corroded pipe surface to bare metal (N/A for the calculation)

Step 3. Measure the max depth of the corroded area, d, and longitudinal extent of the corroded area, L.

Step 4. Determine applicable pipe material properties from appropriate records.

Step 5. Calculate the estimated failure stress, S<sub>F</sub>.

Step 6. Define an acceptable safety factor, SF.

Step 7. Compare S<sub>F</sub> to SF X S<sub>O</sub>.

Step 8. The flaw is acceptable where  $S_F$  is equal to or greater than SF X  $S_O$ , or where  $P_F$  is equal

to or greater than SF X P<sub>o</sub>.

Pipe Diameter(inches)	32	D		Step 1
Nominal Wall Thickness (inches)	0.298	t		2100 2
Depth of Corroded Area (inches)	0.12	d		C/ 0
Length of Corroded Area (inches)	24	L		Step 3
Bulging stress magnification factor		M	Calculated below	
Maximum Operating Pressure (psi)	275	MOP	(also P <sub>o</sub> )	
Specified Minimum Tensile Strength	60000	<b>SMTS</b>	(ASME B31 3 Table A-1)	
Specified Minimum Yield Strength	35000	SMYS	(ASME B31 3 Table A-1)	Step 4
Elastic modulus of steel	29500000	E	(ASME B31 3 Table C-6)	
Flow stress	38500	S <sub>FLOW</sub>	(1.1*SMYS)	

$$z = \frac{L^2}{Dt}$$
  $z = 60.403$ 

$$M = 0.032z + 3.3$$
  
 $M = 5.233$ 

$$z = \frac{L^2}{Dt}$$
  $z = 60.403$  
$$S_F = S_{FLOW} \left( \frac{1 - 0.85(\frac{d}{t})}{1 - 0.85(\frac{d}{t})/M} \right)$$

Safety Factor, 
$$SF = \frac{hydrostatic\ test\ pressure\ (425\ psi)}{MOP}$$
 Step 6

Hoop Stress, So

**Estimated Failure Pressure** 

$$S_{O} = \frac{P_{O}D}{2t}$$
  $S_{O} =$  14765.101 psi   
  $SF \times S_{O} =$  22818.792 psi

$$P_F = \frac{2S_F t}{D}$$
 504.633 psi

Step 5

Flaw is Acceptable



# APPENDIX 'F' - PIPE SUPPORT ASSESSMENT

					Table 15 - FOR Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (			Outside 3	(b)	Good, new, labeled by others.	Other	None.
3) (4			Outside 3	(3) (	Good, new, no teflon pad, pipe not in contact w/ saddle, labeled by others.	Long	Provide teflon pad, adjust support or shim to properly support pipe.
<b>(</b> )			Outside 3	A)	Good, new, photo for example, on exit line, unlabeled.	Other	None.
			Outside 3		Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
			Outside 3		Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
			Outside 3		Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
			Outside 3		Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
			Outside 3		Missing U-bolt, metal to metal contact, labeled by others.	Long	Provide teflon pad and coated U-bolt.
			Outside 3		Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
			Outside 3	· .	Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
	Table E2		Outside 3		Good, metal to metal contact, labeled by others. API 570: Heavy corrosion at saddle-to-pipe crevice (no isolation Teflon pad).	Long	API 570: Reapir support. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal tometal support locations.
2			Outside 3	2	Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
			Outside 3		Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
			3		Actively dripping, medium-high corrosion, metal to metal contact, corroded at pipe support interface, photo taken for how wall support should look, labeled by others.	Urgent	Replace support.
			m		Highly corroded and deformed, no contact w/ pipe, labeled by ABA.	Urgent	Replace support.
			3		Corroded, in contact w/ pipe, labeled by ABA.	Urgent	Replace support.
			e e	3 - 15	Corroded, intact, metal to metal contact, only top anchor to wall present, lower part of bracket not in contact $w/$ wall.	Urgent	Replace support.
			3		Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
			3		Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
					Very minor corrosion, overall good, metal to metal contact.		Provide teflon pad. API 570: Secure pipe clamp. Consider Teflon shims/insulation strips between pipe and saddle or
	Table E2		m		API 570: Missing pipe clamp (no isolation Teflon pad).	Long	half-round Teflon strips between pipe and HBeam structure or other metal to-metal support locations
			8		Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.

	-	٠	
	2	C	
ĺ	•	5	
	•	,	
	3		
į	4	4	
		Ė	
	_	•	
į	2	2	
i	-	ζ	
	5	,	
ì		2	
		ī	
	٠	,	
١		4	
į	2	L	
١	,	ī	
۱	5	ć	
	5	•	
	7	•	
۱	₹	2	
ı	<	5	
	4	4	
ı			
į	,	١	
۱	Š		
	,	ī	
	7	•	
	3	r	
ĺ	í	ī	
ì	ū	•	
	ï	₹	
		2	
•		5	
		۲	
	ŝ	3	
	۰		
	•	۰	
	L	i	
ĺ		ĭ	
	=	7	
۱	٠	J	
	4		

Urgency  Urgency  Long						Table 15 - FOR Pipe Support Findings and Recommendations		
Section	em Fo.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Very minor coronsion, overall good, metal to invest:    3	(Ł			e	(b)	Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
Additional corrosion at AB granchor boilt to concrete at lower boilts. Long Metal to metal contact, corrosion at AB to concrete, minor corrosion at support. Long Metal to metal contact, corrosion at AB to concrete, minor corrosion at support. Long Metal to metal contact, corrosion at AB to concrete, minor corrosion at support. Long Metal to metal contact, corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, no corrosion at AB innor corrosion at support. Long Metal to metal contact, otherwise good  API 57.0. Missing pipe stap at the support for isolation Tellon pad ).  Has reflon pad, but not well supported, C-clamp to hold guide on. Long Has reflon pad, but not well supported, C-clamp to hold guide on. Long Has reflon pad, supporting pipe adequately. Compatible pipe adequately. Has reflon pad, not clanty supporting pipe adequately.  Has reflon pad, not clanty supporting pipe adequately. Or other Has reflon pad, or clanty supporting pipe adequately.	)			e	(3	Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
Metal to metal contact, corrosion at AB to concrete, minor corrosion at support. Long Metal to metal contact, corrosion at AB to concrete, minor corrosion at support. Long Metal to metal contact, corrosion at AB, minor corrosion at support. Long Metal to metal contact, corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact do corrosion at support. Long Metal to metal contact do corrosion at support. Long Metal to metal contact do corrosion at support. Long Metal to me	(3			e	3)	Additional corrosion at AB (anchor bolt) to concrete at lower bolts.	Long	Provide teflon pad.
Metal to metal contact, corrosion at AB to concrete, minor corrosion at support. Long Metal to metal contact, corrosion at AB to concrete, minor corrosion at support. Long Metal to metal contact, corrosion at AB indo corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, no corrosion at AB minor corrosion at support. Long Metal to metal contact, on corrosion at AB minor corrosion at support. Long Metal to metal contact, on corrosion at AB minor corrosion at a support. Long Metal to metal contact, on corrosion	) (		60	3	( <i>A</i>	Additional corrosion at upper and lower bolts to concrete.	Long	Provide teflon pad.
Metal to metal contact, corrosion at AB to concrete, minor corrosion at support. Long Metal to metal contact, corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Long Metal to metal contact, no corrosion at support. Lon	A)			3	<b>\</b> )	Metal to metal contact, corrosion at AB to concrete, minor corrosion at support.	Long	Provide teflon pad, clean corrosion and repaint with high-zinc paint.
Metal to metal contact, corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, on corrosion at AB, minor corrosion at support. Long Metal to metal contact, on every support and contact, no corrosion at support. Long Metal to metal contact, otherwise good.  AP 570: Missing pipe strap at the support (no isolation Teflon pad).  Has teflon pad, but not well supported, C-damp to hold guide on. Long Has teflon pad, but not well supported, C-damp to hold guide on. Long Has teflon pad, put not well supported, C-damp to hold guide on. Long Has teflon pad, put not well supporting pipe.  Has teflon pad, pot deduately.  Has teflon pad, pot deduately.  Has teflon pad, pot supporting pipe adequately.  Has teflon pad, pot supporti				8			Long	Provide teflon pad, clean corrosion and repaint with high- zinc paint.
Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, on corrosion at AB, minor corrosion at support.  Metal to metal contact, on corrosion at AB, minor corrosion at support.  Metal to metal contact, on corrosion at AB, minor corrosion at support.  Metal to metal contact, on corrosion at AB, minor corrosion at support.  Metal to metal contact, on corrosion at AB, minor corrosion at support.  Metal to metal contact, on corrosion at AB, minor corrosion at Support.  Metal to metal contact, on corrosion at Support.  Metal to metal contact, on corrosion at AB, minor corrosion at Support.  Metal to metal contact, on corrosion at Support.  Metal to meta				3		Metal to metal contact, corrosion at AB to concrete, minor corrosion at support.	Long	Provide teflon pad, clean corrosion and repaint with high-zinc paint.
3   Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Has teflon pad, but not well supporteg to wall at top, metal to metal contact.   Long Has teflon pad, supporting pipe.   Long to the properting pipe adequately.   Long Has teflon pad, supporting pipe adequately.   Colamp to hold guide on.   Long Has teflon pad, supporting pipe adequately.   Colamp to hold guide on.   Long Has teflon pad, supporting pipe adequately.   Colamp to hold guide on.   Long Has teflon pad, supporting pipe adequately.   Colamp to hold guide on.   Long Has teflon pad, supporting pipe adequately.   Long Lang Lang Lang Lang Lang Lang Lang La				e		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
3   Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long Metal to metal contact, no corrosion at AB, minor corrosion at support.   Long API 570: Missing pipe strap at the support (no isolation Teflon pad).				e		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at 8B, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  API 570: Support and corrosion at AB, minor corrosion at support.  Has teflon pad, but not well supported, C-clamp to hold guide on.  Has teflon pad, but not well supporting pipe.  Has teflon pad, but not well supporting pipe.  Has teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe adequately.				e		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long Metal to metal contact, no corrosion at AB, minor corrosion at support. Long AB 1570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal contact.  Has teflon pad, but not well supported, C-clamp to hold guide on.  Has teflon pad, supporting pipe adequately.  Other Has teflon pad, not clearly supporting pipe adequately.  Other Has teflon pad, not supporting pipe adequately.  Other Has teflon pad, not supporting pipe adequately.  Other Has teflon pad, not supporting pipe.				8		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, otherwise good.  AP 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal to metal contact.  AP 570: Support anchor disloged from tunnel wall.  Has teflon pad, but not well supported, C-clamp to hold guide on.  Not efflon pad, but not well supporting pipe.  Has teflon pad, supporting pipe adequately.  Other  Has teflon pad, supporting pipe adequately.  Dother				3		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, or no corrosion at AB, minor corrosion at Support.  Metal to metal contact, no corrosion at AB, minor corrosion at Support.  Metal to metal contact, no corrosion at AB, minor corrosion at Support.  Metal to metal contact, no corrosion at AB, minor corrosion at Support.  Metal to metal contact, no corrosion at AB, minor corrosion at Support.  Metal to metal contact, no corrosion at AB, minor corrosion at Support.  Metal to metal contact, no corrosion at AB, minor corrosion at Support and Supporting pipe adequately.  Mot efflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Mot teflon pad, supporting pipe adequately.  Other  Has teflon pad, supporting pipe adequately.  Other  Dong				m		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at 8b, minor corrosion at support.  Metal to metal contact, no corrosion at 8b, minor corrosion at support.  Metal to metal contact, no corrosion at 4b, minor corrosion at support.  Metal to metal contact, no corrosion at 4b, minor corrosion at support.  Metal to metal contact, no corrosion at 4b, minor corrosion at support.  Metal to metal contact, no corrosion at 4b, minor corrosion at support.  Metal to metal contact, on corrosion at 4b, minor corrosion at support.  Metal to metal contact, on corrosion at 4b, minor corrosion at support.  Metal to metal contact, otherwise good.  API 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal contact.  Has teflon pad, but not well supported, C-clamp to hold guide on.  No teflon pad, but not clearly supporting pipe.  Has teflon pad, supporting pipe adequately.  No teflon pad, not supporting pipe adequately.  Long				e e		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, otherwise good.  API 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal contact.  API 570: Support anchor dislodged from tunnel wall.  Has teflon pad, but not well supported, C-clamp to hold guide on.  Has teflon pad, but not well supported, C-clamp to hold guide on.  Has teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe adequately.  No teflon pad, supporting pipe adequately.  No teflon pad, not supporting pipe adequately.  No teflon pad, not supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  No teflon pad, supporting pipe adequately.  No teflon pad, supporting pipe adequately.				m		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, no corrosion at AB, minor corrosion at support.  Metal to metal contact, otherwise good.  API 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal contact.  Has teflon pad, but not well supported, C-damp to hold guide on.  No teflon pad, but not well supporting pipe.  Has teflon pad, but not well supporting pipe.  Has teflon pad, supporting pipe adequately.  Has teflon pad, not clearly supporting pipe adequately.  Has teflon pad, not supporting pipe adequately.  Has teflon pad, not supporting pipe adequately.  Has teflon pad, not supporting pipe adequately.  Hother				m		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at AB, minor corrosion at support. Long  Metal to metal contact, no corrosion at AB, minor corrosion at support. Long  Metal to metal contact, no corrosion at AB, minor corrosion at support. Long  Metal to metal contact, otherwise good.  API 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal contact.  API 570: Support anchor dislodged from tunnel wall.  Has teflon pad, but not well supported, C-clamp to hold guide on. Long  Has teflon pad, but not well supporting pipe.  Not teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe.				m		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at AB, minor corrosion at support. Long  Metal to metal contact, otherwise good.  API 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal to metal contact.  API 570: Support anchor dislodged from tunnel wall.  Has teflon pad, but not well supported, C-clamp to hold guide on. Long  Has teflon pad, but not well supporting pipe.  Has teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe adequately.  Other Has teflon pad, ont supporting pipe.  Other Has teflon pad, supporting pipe adequately.  Other Has teflon pad, ont supporting pipe.			V	8		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, no corrosion at AB, minor corrosion at support. Long  Metal to metal contact, otherwise good. API 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal to metal contact. API 570: Support anchor dislodged from tunnel wall. Has teflon pad, but not well supported, C-clamp to hold guide on. Has teflon pad, but not well supporting pipe.  Not teflon pad, supporting pipe adequately. Has teflon pad, supporting pipe adequately. Other Has teflon pad, supporting pipe adequately. Other Has teflon pad, supporting pipe adequately. Other Has teflon pad, supporting pipe. Has teflon pad, supporting pipe.				8		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, otherwise good.  API 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal contact.  API 570: Support an chor dislodged from tunnel wall. Has teflon pad, but not well supported, C-clamp to hold guide on.  Has teflon pad, but not well supported, C-clamp to hold guide on.  No teflon pad, supporting pipe. Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe.  Other Has teflon pad, supporting pipe.				3		Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
Metal to metal contact, otherwise good.  API 570: Missing pipe strap at the support (no isolation Teflon pad).  Not supporting pipe, no anchorage to wall at top, metal contact.  API 570: Support anchor dislodged from tunnel wall. Has teflon pad, but not well supported, C-clamp to hold guide on. Has teflon pad, but not well supported, C-clamp to hold guide on.  No teflon pad, but not well supported. Has teflon pad, supporting pipe. Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe.								Provide teflon pad. API 570: Secure strap. Consider Teflon
Not supporting pipe, no anchorage to wall at top, metal to metal contact.  API 570: Support anchor dislodged from tunnel wall.  Has teflon pad, but not well supported, C-clamp to hold guide on.  Long Has teflon pad, but not clearly supporting pipe.  Has teflon pad, supporting pipe adequately.  And the teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe.		Table E2		en .		Metal to metal contact, otherwise good.  API 570: Missing pipe strap at the support (no isolation Teflon pad).	Long	shims/insulation strips between pipe and saddle or half- round Teflon strips between pipe and I-Beam structure or
Not supporting pipe, no anchorage to wall at top, metal contact.  API 570: Support anchor dislodged from tunnel wall. Has teflon pad, but not well supported, C-clamp to hold guide on. Long Has teflon pad, but not well supported, C-clamp to hold guide on. Long Has teflon pad, but not dearly supporting pipe. Has teflon pad, supporting pipe adequately. Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Other Has teflon pad, supporting pipe.								other metal to-metal support locations.
Has teflon pad, but not well supported, C-clamp to hold guide on.  Has teflon pad, but not well supported, C-clamp to hold guide on.  Long  No teflon pad, not clearly supporting pipe.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Other  Has teflon pad, supporting pipe adequately.  Other  Other  No teflon pad, supporting pipe adequately.  Other  Long		Table E2		3		Not supporting pipe, no anchorage to wall at top, metal to metal contact.  API 570: Support anchor dislodged from tunnel wall.	Urgent	Replace support.
Has teflon pad, but not well supported, C-clamp to hold guide on.  No teflon pad, not clearly supporting pipe.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Other  Has teflon pad, supporting pipe adequately.  Other  Other  No teflon pad, supporting pipe.				e		Has teflon pad, but not well supported, C-clamp to hold guide on.	Long	Provide teflon pad.
No teflon pad, not clearly supporting pipe.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Other  Has teflon pad, supporting pipe adequately.  Other  Other  No teflon pad, supporting pipe.			8 3	3		Has teflon pad, but not well supported, C-clamp to hold guide on.	Long	Provide teflon pad.
Has teflon pad, supporting pipe adequately.  Other  No teflon pad, not supporting pipe.				e .		No teflon pad, not clearly supporting pipe.	Long	Provide teflon pad, adjust support or shim to properly support pipe.
Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Other  No teflon pad, not supporting pipe.			22	8		Has teflon pad, supporting pipe adequately.	Other	None.
Has teflon pad, supporting pipe adequately.  Has teflon pad, supporting pipe adequately.  Other  No teflon pad, not supporting pipe.				3		Has teflon pad, supporting pipe adequately.	Other	None.
Has teflon pad, supporting pipe adequately.  Other  No teflon pad, not supporting pipe.				e		Has teflon pad, supporting pipe adequately.	Other	None.
No teflon pad, not supporting pipe.				8		Has teflon pad, supporting pipe adequately.	Other	None.
				3		No teflon pad, not supporting pipe.	Long	Provide teflon pad, adjust support or shim to properly support pipe.

Ŀ	•
9	5
Dana	2
÷	٠
ŏ	ž
5	
۶	7
þ	ć
ľ	7
ũ	6
٥	ū
۷	2
MODECTION	5
•	
5	
Ĭ	
	200
CVCTEAA	200
TO CVCTEA	2000
EFD CVCTEA	TEN SISIEN
VOEED CVCTEA	STEN STEIN
ANCEED CVCTER	AND THE STREET
DANCEED CVCTEA	TAIN OF THE
TDANCEED CVCTEA	TAIN OF THE
TDANCEED	TO TO TO
TEL TOANCEED CVCTER	TO TO TO

	5080	API 570: Secure strap. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal tometal support locations.		None.	None.	None.	None.	API 570: Secure strap. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal tometal support locations.	Attach clamp. API 570: Secure strap. Consider Teflon			other metal to-	T	None.	Replace support.	It Replace support.		Attach clamp. API 570: Secure strap. Consider Teflon		round Teflon strips between pipe and I-Beam structure or	other metal to-	metal support locations.	Attach clamp. API 570: Secure strap. Consider Teflon	shims/insulation strips between pipe and saddle or half-	round Teflon strips between pipe and I-Beam structure or		metal support locations.	None.	None.	None.	Modify support to properly support pipe and provide teflon pad.
	Urgency	Long	Other	Other	Other	Other	Other	Long			Long			Other	Urgent	Urgent	Other			Long					Long			Other	Other	Other	Long
Table 15 - FOR Pipe Support Findings and Recommendations	Condition Notes	Clamp not attached, teflon pad w/ contact. API 570: Dislodged pipe clamp bolt (no isolation Teflon pad).	Gamp attached ok, teflon pad.	Clamp attached ok, teflon pad.	Clamp attached ok, teflon pad.	Clamp attached ok, teflon pad.	New, some minor cracking, overall good conditioon.	Overall good. API 570: Dislodged pipe clamp bolt (no isolation Teflon pad).		Clamp not attached	API 570: Dislodged pipe clamp bolt (no isolation Teflon pad).			Overall good.	No guide, support broken so pipe is at end of arm. API 570: Missing pipe clamp bolt (no isolation Teflon pad).	Bottom of bracket deformed from impact.	Overall good.		Clamp not attached	ADI C70: Dielodood ning clamp holt (no icolation Toflon and)	or o's distought pipe daille boir (no isolation renoil pau).			podposte ton ome	ADECO. Distolated aims alones half (no instation Toffee and)	API 5/0: Distodged pipe clamp boit (no isolation Terion pad).		Overall good.	Overall good.	Overall good.	No teffon, no contact.
	Pipe Support No.	(b) (3)	(A	()					\\.				3		2	. 10							2)						() - ()		- <del>V</del>
	Geographic Area	8	e	e	e	m	e	8			m			e	8	3	e	8		m					3			8	3	3	e e
	SGH Report Cross Reference																														
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	Table E2					200	Table E2		8	Table E2				Table E2					Table E2					Table E2						
	Item No.	(b) (3)	(/	١)																											

_
6
-
J
POR
ш
0-
_
_
<
J
_
( )
~
ш
Δ.
_
S
$\sim$
_
_
-
$\sim$
ш
_
75
S
_
1
σ,
~
-
ш
u.
-
S
>
ď
_
4
_
-
_
JEL
$\neg$
_
4

2	No. (9) (8) (4)	No teflon, no contact. API 570: Missing pipe clamp bolt (no isolation Teflon pad). Overall good, Overall good.	Urgency	Recommended Repairs
Table E2	(b) (3) (A)	No teflon, no contact.  API 570: Missing pipe clamp bolt (no isolation Teflon pad).  Overall good.		
	<b>X</b> )	Overall good.  Overall good, photo shows dank area on support is dirty, not corrosion.  Overall good.  Overall good.  Overall good.  Overall good.  Overall good.	Long	Modify support to properly support pipe and provide teflon pad. API 570: Install bolts clamp. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-other metal to-metal support locations.
		Overall good, photo shows dank area on support is dirty, not corrosion.  Overall good.  Overall good.  Overall good.  Overall good.  Overall good.	Other	None.
		Overall good.  Overall good.  Overall good.  Overall good.  Overall good.	Other	None.
		Overall good.  Overall good.  Overall good.  Overall good.	Other	None.
		Overall good.  Overall good.  Overall good.	Other	None.
		Overall good.	Other	None.
		Overall good.	Other	None.
			Other	None.
		Overall good.	Other	None.
		Overall good.	Other	None.
	120	Overall good.	Other	None.
	77-	Overall good.	Other	None.
		Overall good.	Other	None.
		Overall good.	Other	None.
		Overall good.	Other	None.
		Overall good.	Other	None.
		Overall good.	Other	None.
		Teflon pad in place, no sleeve on U-bolt.	Long	Replace with coated U-bolt.
		No contact w/ pipe.	Urgent	Replace support or modify support to properly support pipe.
		Teflon pad in place, no sleeve on U-bolt.	Long	Replace with coated U-bolt.
		No contact w/ pipe.	Urgent	Replace support or modify support to properly support pipe.
		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
m m m m m m m	SJ	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
m m m m m m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
m m m m m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
m   m   m   m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
m m m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
m m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			Long	Replace with coated U-bolt.
m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
m			Long	Replace with coated U-bolt.
en l		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.

ı			
	•	۰	
	3	•	
i	i	7	
١		3	
í	S		
		٠	
١	ě	4	
	3	•	
	7	-	
3	3	,	
١	•	,	
	•	٦	
3		z	
		Ξ	
		7	
9	٠	,	
	ı		
ř	ς	•	
•	٠	,	
Ş	,	7	
1		6	
•	5	•	
	•	•	
ŧ	e		
ì	١	Ę	
į	ì	į	
į			
		1	
		17 10 17	
		200	
		200	
		2000	
		200	
LIL			

No. (9) (9) (9) (9) (9) (9) (9) (9) (9) (9)						Table 15 - FOR Pipe Support Findings and Recommendations		
Coss Reference Cross Area No. Deficiency Reference S.		Appendix C – API	HDS					
(InterSpec, LLC) Reference    A	Item No.	Cross Reference	Report	Geographic Area		Condition Notes	Urgency	Recommended Repairs
	(	(InterSpec, LLC)	Reference					
	b)			3	(b	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (fleabites).	Long	Replace with coated U-bolt.
	(3			m	) (	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
	) (			3	3)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
	Α		62	e	()	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
	)			e	۹)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			8	en a		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites),	Long	Replace with coated U-bolt.
						spattered w/ effluent.		
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e l		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				3	(r = 00)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				3	50	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			8 3	3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				B		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.

L	
⊏	3
ч	
BEDOB	١
≂	•
ч	
ц	4
o	•
_	•
>	
2	
C	)
7	٠
-	•
L	)
INCEPTOT	•
ñ	7
¥	,
2	•
-	
2	5
	-
ū	ì
H	
NAT NA	
D CVCTE	1
٥	1000
٥	1000
٥	1000
٥	200
٥	200
٥	1000
٥	
٥	
٥	
TRANSFER	
TRANSFER	
TRANSFER	
TRANSFER	
٥	

					Table 15 - FOR Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency	SGH Report Cross	Geographic Area	iic Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(t	(InterSpec, LLC)	Neighber	•	(	Total and its place to the second sec	-	distribution of the state of th
))			0 0	b)	Tellon pad in place, no sieeve on 0-pon, very ininor spots of corrosion (nea pices).	COUR	heplace with coaled 0-bolt.
(3			0	(;	Teriori pad in place, no steeve on 0-bott, very minor spots of corrosion (fleablies).	Ruor	Replace with coated U-boit.
)			m	3)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
(A			3	()	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
)	85 20		e	۹)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		Teflon bad in place, no sleeve on U-bolt, very minor spots of corrosion (fleabites).	Long	Replace with coated U-bolt.
			m		Teffon had in place no sleeve on II-bolt very minor spots of corrosion (flea hites)	long	Replace with coated II-holt
			0 0		Teffor and in place no cleave on H-bolt very minor cross of corrocion (flee bites)	000	Poplace with coated II. bolt
Í					Tellori pad in piace, no siesve on o-bort, very minor spots or corrosion (nea bites).	S .	heplace with coated 0-poir.
			m		letion pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-boit.
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
		8 8	e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
					Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites),		
			m		corrosion at half round.	Long	Replace with coated U-bolt.
	*		cr		Teffon pad in place no sleeve on II-holf very minor snots of corrosion (flea hites)	long	Replace with coated II-holf
			0 0		The state of the s	9	
	T.A.		m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-boit.
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
	St. 35		m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		Teflon bad in place, no sleeve on U-bolt, very minor spots of corrosion (fleabites).	Long	Replace with coated U-bolt.
			ď		Teffon had in place no sleeve on II-holf very minor snots of corrosion (flea hites)	long	Replace with coated II-holf
			0 00		Teffor had in place no cleave on 1-bolt very minor spots of corrosion (flee bites).	Pond	Replace with coated U-bolt
	2.1		0 0		Tellon pad in place, no sleeve on o bork, very minor spous of corresponding for bites).	9	Designation with control of both
	30		0		Terion pad in place, no sleeve on 0-boir, very minor spots of corrosion (frea bites).	Suo-	Replace with wated 0-boilt.
			n		Terion pad in place, no sleeve on U-bort, very minor spots of corrosion (flea bites).	Long	Replace with coated U-boit.
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			9		No sleeve on U-bolt, U-bolt corroded to delamination, significant corrosion at	Urgent	Replace support.
					basepiate and anchors.		
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
		4 3	e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
		( 2	m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
	d.		3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites),	Long	Replace with coated U-bolt.
	74		0		Total and in place and closure on 11 half some miner make of courselon (flee bleed)	-	Dan lace suite control II hale
j					Tellori pad III place, Ilo sieeve oli O-boli, vei y IIII ilo spots ol col osioli (ilea bites).		heplace with coaled 0-boil.

H
20R
2
Щ
=
≲
$\succeq$
S
Ä
S
2
5
S
5
Σ,
~
Ш
F
ž
Þ
٤
-
щ
~

					Table 15 - FOR Pipe Support Findings and Recommendations		
Item Co	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3) (A	Table E2		6	(b) (3)	Teflon pad has been displaced, no sleeve on U-bolt, very minor spots of corrosion (flea bites). API 570: Displaced bottom Teflon pad.	Long	Replace teflon pad, replace with coated U-bolt. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal tometal support locations.
()	Table E2		m	(A)	Teflon pad in place, no sleeve on U-bolt. API 570: Loose U-bolt.	Long	Replace with coated U-bolt.
			m		Teflon pad displaced, no sleeve on U-bolt.	Long	Replace teflon pad, Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt, eflourescence spatla but no damage.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
- 63			m		No sleeve on U-bolt, corrosion at U-bolt to FOR pipe, aux pipe to top bar of support.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			e		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
-			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			e		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			8		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt, corrosion on outside of front support where sanitary sewer lines bolt to support.	Long	Replace U-bolt and add sleeve.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
4 /			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			3		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			3		No sleeve on U-bolt, corrosion at U-bolt to pipe interface.	Long	Replace U-bolt and add sleeve, clean and paint pipe.
6 1			æ		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			8		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			n		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
					No sleeve on U-bolt.	Long	Donlace with coated II halt

	ı
_	ı
-	ı
4	ı
	ı
$\sim$	ı
0	ı
Line	ı
~	ı
4	ı
-	ı
<	ı
	ı
$\sim$	ı
	ı
	ı
0	ı
LU1	ı
~	ı
-	ı
S	ı
-	ı
	ı
	ı
_	ı
~	ı
Lin	ı
	ı
-	ı
V)	ı
~	ı
S	ı
	ı
0-	ı
100	ı
-	ı
-	ı
S	ı
-	ı
-	ı
◂	ı
~	ı
-	ı
	ı
	ı
	ı
щ	ı
	ı
_	ı
-	ı
	۰

	Urgency Recommended Repairs	Long Replace with coated U-bolt.	Long Replace with coated U-bolt.		+	1	Long Replace with coated U-bolt.		Long Replace with coated U-bolt.	Long Replace with coated U-bolt.	Long Replace with coated U-bolt.		Long Replace with coated U-bolt.		Long Replace with coated U-bolt.	Long Replace with coated U-bolt.	Long Replace with coated U-bolt.	Urgent Replace support.	Long Replace with coated U-bolt, reattach to wall.	Long Replace with coated U-bolt.	Long Replace with coated U-bolt.	Urgent Replace connect			Other None.		Other									
Table 15 - FOR Pipe Support Findings and Recommendations	Condition Notes	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt, repair area, corrosion at U-bolt to cross brace, repair paint on	renon pao.	No sleeve on U-boit.	No sleeve on U-bolt.	No sleeve on U-bolt, paint at repair.	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt.	Front support flange bent from apparent impact, U-bolt displaced on pipe, not U-shaped. API 570: Loose U-bolt.	No sleeve on U-bolt, not attached to wall.	No sleeve on U-bolt.	No sleeve on U-bolt.	Support completely deformed, removed from baseplate.	API 570: Damaged pipe support (impacted by a moving vehicle).		Overall good.		Overall good.									
	Pipe Support No.	(b	) (	(3)	(A	)																														
	Geographic Area	3	3	9		n	m	m	3	m	3	3	8	8	3	9	8	8	8	n	3	8	8	3	3	3	e	3	3	Between	duns	Between	door and	dwns	door and	sump
	SGH Report Cross Reference																C.				ee .															
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)																									Table E2				E51	Table E2					
	Item No.	(b	)	(3)	(Δ	()																														

REPORT	
NSPECTION	
SYSTEMI	
TRANSFER	
FUEL	

		Ö p			ź
	Recommended Repairs	Glean and repaint, replace grout under baseplates API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal tometal support locations.	Add teflon pad and sleeve to U-bolt.	Add teflon pad.	Replace teflon pads where required, replace severely corroded supports, remove and replace all wood supports.
	Urgency	Long	Long	Long	Long
Table 15 - FOR Pipe Support Findings and Recommendations	Condition Notes	Paint damaged, corroded, grout under baseplate, chipped and missing chunks. API 570: Missing Teflon spacer/pad between pipe and support.	2/3 U-bolts missing sleeve, very minor corrosion, 1/3 teflon pad missing.	All three missing teflon pad, lower line not touching support.	Not positively attached to ground (typical), not well seated on ground (typical), pad not completely under pipe (typical), Total number lightly corroded: 59  Total number moderately corroded: 28  Total number severely corroded: 10  Total number missing teflon pad: 5
	Pipe Support No.	(b) (3) (A	)		
	Geographic Area	Between door and sump	ln sump	Insump	FOR Trench
	SGH Report Cross Reference				_
1000	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	Table E2			E2 E5 E6 E13 E15 E16 E22 E22 E22 E28 E36 E36 E40 E41
	Item No.	(b) (3) (	Α	)	

_
٥-
REPORT
O
~
ш
0-
_
>
٠.
$\sim$
NOL
V
w
$\overline{a}$
-
INSPEC
>
=
_
_
2
,-4
_
SYSTE
ν.
7
v)
~
4
ш
u.
10
2)
2
=
ч
0
_
-
EL
JEL
CEL

tem No. Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area Harbor Tunnel	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
. (4) (2) (4)			Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
		Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel	(b) (3)			
		Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel	) (3)	Saddle overhangs block, condition overall ok.	Other	None.
		Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel	(3)	Plate and saddle overhang block, condition overall ok.	Other	None.
		Harbor Tunnel Harbor Tunnel Harbor Tunnel	) (	Plate and saddle overhang block, condition overall ok, minor chipping at concrete edges.	Other	None.
		Harbor Tunnel Harbor Tunnel Harbor Tunnel	A)	Some plate corrosion, saddle not uniformly in contact w/ plate.	Other	None.
		Harbor Tunnel Harbor Tunnel		Area broken out for steel pipe support base.	Other	None.
		Harbor Tunnel	ad	Overall good.	Other	None.
				Saddle overhangs support on back side wall (by 2in or so), front bottom of concrete chipped out for pipe support (metal) base, see photo PSG-5.	Other	None.
		Harbor Tunnel		Moderately corroded.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Chipping at top of sleeper, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Honeycombing, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Chipping at saddle under pipe, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None
Table E2		Harbor Tunnel		Minor pitting and chipping at base, overall good. API 570: Pipe is not in contact with saddle # 24 (floating pipe).	Long	API 570: Shim and monitor at next inspection.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Chipped at front, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Corroded at baseplate.	Long	Monitor for deterioration.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
- 73		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

ļ			
Ì	i	5	
ĺ	3	Į	
Ì		Ė	
	2		
(		2	
	١		
į		í	
į	;	5	
	2		
ļ	ì	i	
į		5	
Ì			
(	1		
į	i	ä	
į		2	
		ř	
	1		
ļ		į	
ì	7	•	

Item No. Reference Deficiency (InterSpec, LLC) B46 Table E2	Cross Reference	Geographic Area	Pipe Support No.	Vo. Condition Notes	Urgency	Recommended Repairs	_
Reference Deficiency (InterSpec, LLC) B46 Table E2	Reference	Geographic	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs	_
		longit soder					
(A)		Harbor runner	(b)	Pop out at backside w/ exposed and corroded rebar. API 570: Deteriorated saddle with rebar exposed (saddle #36).	Long	Chip out broken concrete, clean rebar and recast concrete. API 570: Repair concrete saddle.	
A)		Harbor Tunnel	(3)	Rebar corrosion.	Other	None.	
		Harbor Tunnel	) (.	Poorly consolidated but solid at back bottom, both sides.	Long	Monitor for deterioration.	
		Harbor Tunnel	A)	Poorly consolidated but solid at back bottom, both sides.	Long	Monitor for deterioration.	
		Harbor Tunnel		Efflorescence at base back but solid, some corrosion to baseplate and saddle.	Long	Monitor for deterioration.	
		Harbor Tunnel		Efflorescence at base back but solid, some corrosion to baseplate and saddle.	Long	Monitor for deterioration.	
		Harbor Tunnel		Efflorescence at base back but solid, some corrosion to baseplate and saddle.	Long	Monitor for deterioration.	
		Harbor Tunnel		Efflorescence at base back but solid, some corrosion to baseplate and saddle, baseplate not seated flush (typical).	Long	Monitor for deterioration.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
		Harbor Tunnel		Concrete has been chipped out on tank side around flange for F-24, JPS lines, F-24 line has broken concrete out (but not fallen) on opposite side.	Urgent	Replace concrete.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at top front, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at top, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	1
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	$\neg$

Ĺ		
	2	
C	Š	
ō	1	
ū	ī	
٥	ē	
5	,	
2	7	
٤	2	
٠	•	
Ļ	,	
ž	4	
i		
	4	
=	:	
e		
S		
Š		
	3151	
	212121	
NA CALLAN	STORY OF THE	
TO COLUMN	EN SISIEIN	
EED COLEAN	TEN SISIEN	
CEED CVCTEA	JULY STORE	
MCEED CVCTEA	MALEN STOLET	
A MICEED CVCTER	AND THE PLANE	
DANCEED CVCTER	משונים כי שונים שו	
TO A NICEED CVCTEA	יייייייייייייייייייייייייייייייייייייי	
TOANCEED	THE PROPERTY OF STREET	
TO A NICEED CVCTER	DEL INAMOTER SI SI EIN	

					Table 16 -	6 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations		
This objective	- N	Appendix C – API 570 Report – Cross	SGH Report	Geographic		Consists on Makes		Document of Document
Harbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Harbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Harbor Tunnel   Minro ptiting and chipping at base, overal good, efforescence at Other Detrom.   Minro ptiting and chipping at base, overal good, efforescence at Other Detrom.   Minro ptiting and chipping at base, overal good, efforescence at Other Detrom.   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at base, overal good.   Other Marbor Tunnel   Minro ptiting and chipping at bas		Deficiency (InterSpec, LLC)	Reference	Area	ribe support no.		Orgency	Necollillelided Nepalls
Harbor Tunnel Minor pitting and chipping at base, overall good, Cherry Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal good, everall good, everall good, everall good, everall good, everall good, everall good to the transportant Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pitting and chipping at base, overall good. Orderal Harbor Tunnel Minor pittin	(b)			Harbor Tunnel	(b	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel Minor ptiting and chipping at base, overall good, efflorescence at Other better that the printing and chipping at base, overall good, efflorescence at Other bottom. Minor ptiting and chipping at base, overall good, efflorescence at Other Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chippin	(;			Harbor Tunnel	) (	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Turnel Ha	3)			Harbor Tunnel	(3)	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at font, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at ba	(A)			Harbor Tunnel	(A)	Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
Minor pitting and chipping at base, overall good, efflorescence at before pitting and chipping at base, overall good, efflorescence at before pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at ba				Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
Minor pitting and chipping at base, overall good, efflorescence at  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Ot				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  A flange visible.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Othe				Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good, except F-24 line has been broken out on tanks side, no flange visible.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
A Overall good, except F-24 line has been broken out on tanks side, no flarage visible.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Oth				Harbor Tunnel	A	Overall good, except F-24 line has been broken out on tanks side, no flange visible.	Urgent	Replace concrete.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at front, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Othe				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Other  Other  Overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Monor pitting and chipping at base, overall good.  Other  Ot				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Overall good.  Other  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other  Overall good. Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.         Other           Minor pitting and chipping at base, overall good.         Other           A         Overall good.         Other           Overall good.         Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good. Other     A   Overall good. Other     Overall good. Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
A         Overall good.         Other           Overall good.         Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Overall good.				Harbor Tunnel	A	Overall good.	Other	None.
				Harbor Tunnel		Overall good.	Other	None.

≂
≂
$\sim$
RE
_
2
0
Ė
Ü
INSPEC
٩
2
2
=
2
ш
Н
S
SYSTE
EB
۳
ŝ
S
3
RA
F
_
UEL
5
u

Annondiv C - ADI						
S70 Reference Deficiency (InterSpec, LLC)	SSS SGH Report Cross Reference	Geographic Area	Pipe Support No.	. Condition Notes	Urgency	Recommended Repairs
(b)		Harbor Tunnel	(b)	Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
(3		Harbor Tunnel	(3	Minor pitting and chipping at base, overall good.	Other	None.
6) (		Harbor Tunnel	) (	Minor pitting and chipping at base, overall good.	Other	None.
Α		Harbor Tunnel	_	d Overall good.	Other	None.
)		Harbor Tunnel	)	Overall good.	Other	None.
		Harbor Tunnel	- 5	Plate not fully seated on concrete.	Other	None.
		Harbor Tunnel		Overall good.	Other	None.
		Harbor Tunnel	21-3	Overall good.	Other	None.
		Harbor Tunnel	a = 0	Pitted concrete at front.	Other	None.
		Harbor Tunnel		Saddle on plate on large concrete block.	Other	None.
		Harbor Tunnel		Overall good.	Other	None.
		Harbor Tunnel	A	d Overall good.	Other	None.
		Harbor Tunnel		Overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel	so=	Minor pitting and chipping at base, overall good.	Other	None.
Table E2		Harbor Tunnel	8	Minor pitting and chipping at base, overall good. API 570: Concrete pipe saddle # 110 is not engaged with pipe (floating	Long	API 570: Shim and monitor at next inspection.
			100	pipe).		
		Harbor Tunnel		Foam filled.	Other	None.
		Harbor Tunnel	:=)	Overall good.	Other	None.
		Harbor Tunnel		Overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel	- 0	Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel	(S X	Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None

١.	_
ĸ	=
DUGGG	5
~	ς.
٠.	,
ñ	
٠	
u	
ñ	=
ч	
_	Ξ
2	•
Ξ	-
	٦.
2	•
С	_
	•
L	
) L	٠.
MODE	4
	ш
	•
y	7
3	
5	
-	
7	
S	i
Š	i
Y	
Y L	
VAP V	
	A CICK
	200
	EN SISIEN
	TEN SISIE
	JIEN SISIEN
CEED CVCTE	ASTEN STORES
CEED CVCTE	March of the
CEED CVCTE	TANGET OF STEEL
CEED CVCTE	AND LAND OF THE
CEED CVCTE	TAIN OF THE PARTY
CEED CVCTE	THE PARTY OF THE
CEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
CEED CVCTE	TO COLON

			- or algel	6 - Concrete Sieepers - F-76 Pipe Support Finaings and Recommendations		
Appendix C – API	Id,					
570 Report – Cross Item No. Reference	01	Geographic	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Deficiency (InterSpec, LLC)	Reference					
<b>)</b>		Harbor Tunnel	(b)	Minor pitting and chipping at base, overall good.	Other	None.
(3		Harbor Tunnel	(3	Efflorescence at bottom.	Other	None.
) (		Harbor Tunnel	3)	Minor pitting and chipping at base, overall good.	Other	None.
A)		Harbor Tunnel	(A	Efflorescence at bottom.	Other	None.
		Harbor Tunnel	()	Minor pitting and chipping at bottom, overall good.	Other	None.
		Harbor Tunnel	2 - 47	Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom, some deterioration at bottom of sleeper but solid.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Deterioration at bottom but solid.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Deterioration at bottom but solid.	Other	None.
		Harbor Tunnel	2 0.	Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Efflorescence at bottom, some deterioration at bottom of sleeper but solid.	Other	None.
		Harbor Tunnel		Efflorescence at bottom w/ deterioration.	Other	None.
		Harbor Tunnel		Efflorescence at bottom w/deterioration.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel	·	Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel	A	Overall good.	Other	None.
		Harbor Tunnel		Deterioration at base, poorly consolidated at back bottom but solid.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel	Y	Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Chipped at saddle under pipe.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Efflorescence at bottom at back but solid.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel	\$1-1	Poorly consolidated at back but solid.	Other	None.
		Harbor Tunnel	·	Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		-		Effloring at had but collid	-	

Appendix 'F' - Pipe Support Assessment

ь	•
Q	
Ċ	١
≂	•
٠	٠
4	4
Q	
≤	
С	)
۶	
	•
	,
ų	4
ч	
v	•
>	
=	=
2	
ū	7
	•
7	5
Š	•
į,	
_	•
Q	
u	ı
	•
3	
ä	ř
2	5
۰	
-	•
	ı
ı	ı
•	5
Ġ	•
-	•

				Table 16 - C	Table 16 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations		
	Appendix C - API						
	570 Report - Cross	SGH Report	Social				
Item No.	Reference	Cross	Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
	(InterSpec, LLC)						
(E			Harbor Tunnel	(Ł	Minor pitting and chipping at base, overall good.	Other	None.
1)			Harbor Tunnel	)	Deterioration at back.	Other	None.
(3				(3	Efflorescence at back, but solid.		
) (A	Table E2		Harbor Tunnel	) (A	API 570: Wood shim at saddle #167 (between steel wear plate and	Other	API 570: Remove wood and install Teflon shim.
			Harbor Tunnel	)	Efforescence at bottom.	Other	None.
			Harbor Tunnel	2-0	Efflorescence at back, but solid.	Other	None.
			Harbor Tunnel	3	Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
	Table E3		loam Trockell		Efflorescence at bottom.  Api 570: Concrete nine caddle # 179 is not engaged with nine (floating	200	ADI 570: Chim and manifor at next increation
	Zapic EZ				pipe).	8	ALOVO: Simil and morning at rext his pectori.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel	8	Efflorescence at bottom.	Other	None.
			Harbor Tunnel		More deteriorated, but still fairly solid, surface crumbling.	Other	None.
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
			Harbor Tunnel		Cannot see anchorage, all others ok.	Other	None.
					Minor pitting and chipping at base, overall good, API 570: Wood shim		API 570: Remove wood. Repair the concrete saddle
	837				installed on Company pipe between Teflon pad and concrete saddle		support or provide a replacement steel support adjacent
	Table E2		Harbor Lunnel		pt to correct	Long	to this pipe support. Alternatively, the existing pipe
					289 — 290). Pipe is not fully and uniformly supported.		pad to uniformly support the pipe.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Saddle corrosion.	Long	Monitor for deterioration.

Appendix 'F' - Pipe Support Assessment

١.	_
ĸ	=
DUGGG	5
~	ς.
٠.	,
ñ	
٠	
u	
ñ	=
ч	
_	Ξ
2	•
Ξ	-
	٦.
2	•
С	_
	•
L	
) L	٠.
MODE	4
	ш
	•
y	7
3	
5	
-	
7	
S	i
Š	i
Y	
Y L	
VAPPA VAPPA	
	A CICK
	200
	EN SISIEN
	TEN SISIE
	JIEN SISIEN
CEED CVCTE	ASTEN STORES
CEED CVCTE	March of the
CEED CVCTE	TANGET OF STEEL
CEED CVCTE	AND LAND OF THE
CEED CVCTE	TAIN OF THE PARTY
CEED CVCTE	THE PARTY OF THE
CEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
CEED CVCTE	TO COLON

Continue   Continue		-	
Harbor Tunnel	No. Condition Notes	Urgency	Recommended Repairs
Harbor Tunnel		Long	Monitor for deterioration.
Harbor Tunnel	Efflorescence at bottom.	Other	None.
Harbor Tunnel	Deteriorated at bottom.		None.
Harbor Tunnel	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel	Minor pitting and chipping at base, overall good.	Other N	None.
Harbor Tunnel	Efflorescence at bottom.	Other	None.
Harbor Tunnel		Other N	None.
Harbor Tunnel		Other	None.
Harbor Tunnel		Other	None.
Harbor Tunnel	Efflorescence at bottom, but solid.	Other	None.
Harbor Tunnel	Efflorescence at bottom, but solid.	Other	None.
Harbor Tunnel	Efflorescence at bottom, but solid.	Other	None.
Harbor Tunnel		Other	None.
Harbor Tunnel	Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
Harbor Tunnel	Minor pitting and chipping at base, overall good.	П	None.
Harbor Tunnel	Corrosion at saddle.	Long	Monitor for deterioration.
Harbor Tunnel		Other	None.
Harbor Tunnel		Other	None.
Harbor Tunnel		Other N	None.
Harbor Tunnel	Corrosion at saddle.	Long	Monitor for deterioration.
Harbor Tunnel	Minor pitting and chipping at base, overall good.	Other N	None.
Harbor Tunnel	Corrosion at saddle.	Long	Monitor for deterioration.
Harbor Tunnel	Minor pitting and chipping at base, overall good.		None.
Harbor Tunnel		Other	None.
Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel Harbor Tunnel Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
Harbor Tunnel	Efflorescence at bottom, minor corrosion at saddle.	Other	None.
	Efflorescence at bottom, minor corrosion at saddle.  API 570: Wood shim at saddle #231 (unknown reason, but no corrosion	Long	API 570: Removed wood and install Teflon shim.
	ninor corrosion at saddle.	7	None.
Harbor Tunnel More corrosion at saddle.	More corrosion at saddle.	Long	Monitor for deterioration.

Appendix 'F' - Pipe Support Assessment

Appendix 'F' - Pipe Support Assessment

2
-
$\mathbf{\circ}$
ο.
REPOR
-
œ
-
_
Š
_
_
( )
~
ш
0
_
S
>
_
_
_
F
E
Ę
FS
SYST
SYST
R SYSTI
ER SYSTI
FER SYSTI
FERS
SFER SYSTI
FERS
EL TRANSFER S
EL TRANSFER S
FERS

			Taple To			
Appendix C – API 570 Report – Cross	SGH Report					
Item No. Reference Deficiency		Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
=						
2)		Harbor Tunnel	(b)	Efflorescence at bottom.	Other	None.
(8		Harbor Tunnel	) (	Efflorescence at bottom.	Other	None.
3)		Harbor Tunnel	3)	Efflorescence at bottom.	Other	None.
(A		Harbor Tunnel	()	Efflorescence at bottom.	Other	None.
.)		Harbor Tunnel	۹)	Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Overall good.	Other	None.
		Harbor Tunnel		Overall good.	Other	None.
		Harbor Tunnel		Excessive efflorescence.	Other	None.
		Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
		Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
		Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
		Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
		Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
		Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
		Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
		Harbor Tunnel		Overall good.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor Tunnel		Continuous cast block at wall begins.	Other	None.
		Harbor Tunnel	4 3	Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel	- 10	Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
	21	Harbor Tunnel	- 30	Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.

_
~
æ
•
POR
ш
0
-
_
_
$\overline{}$
u
_
_
( )
_
照
0
_
S
$\overline{}$
_
_
_
E
Ξ
STE
STE
YSTE
SYSTE
SYSTE
SYSTE!
R SYSTE
ER SYSTE
FER SYSTE
SFER SYSTE
SFER S
SFER S
<b>INSFER SYSTE</b>
SFER S
SFER S
SFER S
SFER S
TRANSFER S
TRANSFER S
SFER S
JEL TRANSFER S
TRANSFER S

Appendix C – API						
570 Report - Cross	SGH Report					
Item No. Reference		Geographic	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(InterSpec, LLC)	Kererence					
(b)		Harbor Tunnel	(1	Efflorescence at back.	Other	None.
(:		Harbor Tunnel	0)	Efflorescence at back.	Other	None.
3)		Harbor Tunnel	(3	Efflorescence at back.	Other	None.
(A		Harbor Tunnel	) (	Efflorescence at back.	Other	None.
<b>(</b> )		Harbor Tunnel	A	Efflorescence at back.	Other	None.
1			)	Efflorescence at back.		
Table E2		Harbor Tunnel		API 570: Wood shim at saddle #231 (unknown reason, but no corrosion noted).	Long	API 570: Shim and monitor at next inspection.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel	vo. 1-	Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Efflorescence at back.	Other	None.
		Harbor Tunnel		Poorly consolidated at back.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel	·	Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
B28 Table E2		Harbor Tunnel		Minor pitting and chipping at base overall good. API 570: Concrete saddle support (# 337) between and 432 has several 1/8" rods between the pipe and the concrete saddle. Reason is unknown.	Long	API 570: Remove the 1/8" rods between the concrete support saddle and pipe. Conduct visual inspection of the interface. Consider a Teflon shim between saddle and pipe.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor Tunnal		Minor pitting and chipping at base, overall good.	Other	None

_	
⊏	3
ч	
BEDOB	١
≂	•
ч	
ц	4
o	•
_	•
>	
2	
C	)
7	٠
-	•
L	)
INCEPTOT	•
ñ	7
¥	,
2	•
-	
2	
	-
ū	ì
H	
NAT NA	
D CVCTE	1
٥	1000
٥	1000
٥	1000
٥	200
٥	200
٥	1000
٥	
٥	
٥	
TRANSFER	
TRANSFER	
TRANSFER	
TRANSFER	
٥	

The control of the					Table 16 - C	5 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations		
Minor pitting and chipping at base, overall good. Other None.		Appendix C – API 570 Report – Cross	SGH Report	1				
Harbor Tunner   Minor pitting and chipping at base, overall good,   Other Harbor Tunner   Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pitting and chipping at base, overall good   Other Harbor Tunner   Minor pi	Item No.	Reference Deficiency	Cross Reference	Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Harbor Tunnel (Minor pitting and chipping at base, overal good, Other Harbor Tunnel (Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, overal good, Other Harbor Tunnel Minor pitting and chipping at base, ove	(b							
Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Mi	))			Harbor Tunnel	(b	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Turnel Minor pitting and chipping at base, overall good, Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good, Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other H				Harbor Tunnel	)	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Turnee Ha				Harbor Tunnel	(3	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Ha				Harbor Tunnel	) (	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chip				Harbor Tunnel	A)	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chip				Harbor Tunnel	)	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting a				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chip				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pi				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Other  Minor pitting and chipping at base, overall good.  Other  O				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Other  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at base, overall good.  Other  Other  Other  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Has teflon pad.  Teflon pad.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Other  Other  Has teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Ot				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Teflon pad.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Top of pier chipped away, including under plate pipe saddle.  Long  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Top of pier chipped away, including under plate pipe saddle.  Inflor pat.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Top of pier chipped away, including under plate pipe saddle.  Long  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  These teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including under plate pipe saddle.  Top of pier chipped away, including at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  The teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Other  Other  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Has teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Has teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other Has teflon pad unseated.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Other Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Has teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Has teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Other  Other  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Has teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle.  Teflon pad.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Has teflon pad unseated.  Top of pier chipped away, including under plate pipe saddle. Long Teflon pad. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Top of pier chipped away, including under plate pipe saddle. Long Teflon pad. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other				Harbor Tunnel		Has teflon pad unseated.	Other	None.
Teflon pad. Other   Minor pitting and chipping at base, overall good. Other   Minor pitting and chipping at base, overall good.				Harbor Tunnel		Top of pier chipped away, including under plate pipe saddle.	Long	Replace concrete.
Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other				Harbor Tunnel		Teflon pad.	Other	None.
Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

Appendix 'F' - Pipe Support Assessment

<b>b</b>	
×	
0	
INSPECTION REPORT	
≂	
_	
2	
ā	
$\simeq$	
-	
C	
ш	
℄	
S	
>	
=	
-	
Σ	
ш	
SYSTE	
S	
>	
S	
~	
w	
SFE	
<b>VSFE</b>	
INSFE	
ANSFE	
RANSFE	
TRANSFER	
FUEL TRANSFE	

Pipe Support No.  Condition Notes  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other None.  Concrete chipped at front.  Con					Table 16 - C	16 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations		
The property of Geographic   Counting and chipping at base, overall good   Other   None.		Appendix C - API						
Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Harbor Tunnel Minor pitting and chipping at base, overall good.   Other Markor Tunnel Minor pitting and chipping at base, overall good.   Other Markor Tun	em No.	570 Report – Cross Reference		Geographic	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Harbor Turnel Hirbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Harbor Turnel Harbor Turnel Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Minor pitting and chipping at base, overall good.  Harbor Turnel Concrete chipped at front.  Harbor Turnel Minor pitting and chipping at base, overall good.  Other Harbor Turnel Concrete chipped at front.  Harbor Turnel Concrete chipped at front.  Harbor Turnel Minor pitting and chipping at base, overall good.  Other Harbor Turnel Concrete	(		Reference	ē.				
Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Other Harbor Turnel Other Other Other Other Harbor Turnel Other Other Other Harbor Turnel Other	D)			Harbor Tunnel	(t	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Minor pitting and chipping at base, overall good Other Harbor Turnel Other Other Harbor Turnel Other Harbor Turnel Other Other Other Harbor Turnel Other Other Other Other Harbor Turnel Other	(3			Harbor Tunnel	o)	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Concrete chipped at front. Other Harbor Tur	) (			Harbor Tunnel	(3	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Other Other Other Other Harbor Tunnel Other Other Other Other Harbor Tunnel Other	A			Harbor Tunnel	) (	Overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Concrete chipped at front.  C				Harbor Tunnel	A)	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Overall good.  Overall good.  Overall good.  Other  Concrete chipped at front.  Other  Concrete chipped at front.  Other  Concrete chipped at front.  Other  Concrete chipped at front.  Concrete chipped at front.  Concrete chipped at front.  Other  Concrete chipped at front.  Other  Concrete chipped at front.  Oth				Harbor Tunnel	)	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Concrete chipped at front.  Concre				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Oncrete chipped at front.  Concrete chipped at front.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Concrete chipped at front.  Concrete chipped at fron				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Concrete chipped at front.  Concrete				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Concrete chipped at front.  Concrete chipp				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Overall good.  Concrete chipped at front.  Concrete chipped				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Overall good.  Concrete chipped at front.  Concrete chi				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Concrete chipped at front.  Concrete chipped				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Outher  Overall good.  Concrete chipped at front.  Conc				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Oncrete chipped at front.  Concrete chipped at front.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Concrete chipped at front.  Concrete chippe				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Concrete chipped at front.  Co				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Concrete chipped at front.  Concrete chi				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  Concrete chipped at front.  Concrete chipped at				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Overall good.  Concrete chipped at front. Concre				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Concrete chipped at front.  Co				Harbor Tunnel		Overall good.	Other	None.
Concrete chipped at front.  Co				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Co				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Co				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Other  Other  Other  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Concrete chipped at front.  Concrete chipped at front.  Concrete chipped at front.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Concrete chipped at front.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Concrete chipped at front.  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Concrete chipped at front.	Other	None.
Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
2000				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

4
$\overline{}$
ο.
1.0
_
Œ
_
_
$\overline{}$
O
_
F
~
9
5
=-
<
_
$\sim$
Σ
ш
_
in
ζ,
SYSI
S
ď
lu i
œ.,
-
Y)
>
$\overline{}$
T.
~
- •
-
~
4

Reference Harbor Tunnel
or Tunnel
Harbor Tunnel

۱			
		•	
	3	•	
i	ī	7	
ė	ī	_	
Ļ	4	١,	
L	1	3	
ì	3	3	
ķ			
i	7	,	
1	2	•	
		٦	
3		z	
ı		_	
9	1	•	
١		۰	
í		6	
	ż		
١	4	L	
t	ı	š	
2	2	2	
i	e	•	
		2	
	ī	7	
۹		•	
	Ş	Ę	
į		i	
ļ		į	
		1	
ļ	١	ς	
ļ	١	ς	
ļ	١	ς	
ļ	١	ς	
ļ	١	ς	
		ς	
		ς	
		ς	
		ς	
		ς	

Appach of C-058					Table 16 - C	6 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations		
STO Report - Coss   Store Reviews   Age		Appendix C – API						
Harbor Tunne		570 Report - Cross	SGH Report	Geographic				
Met base, standing water from PSC 457. Other	n No.	Reference	Cross	Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Harbor Tunnel Wet base, standing water from PSC 457. Other Harbor Tunnel	(t	(InterSpec, LLC)	vereiging					
Harbor Tunnel Wet base, standing water from PSC 457. Other Met base, standing water from PSC 457. Other Harbor Tunnel Poorly consolidated. Other Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Poorly consolidated. Other Harbor Tunnel Harbor Tunnel Poorly consolidated. Other Harbor Tunnel Harbor Tunnel Poorly consolidated. Other Harbor Tunnel Harbor Tunnel Harbor Tunnel Poorly consolidated. Other Harbor Tunnel H	)			Harbor Tunnel	(	Wet base, standing water from PSC 457.	Other	None.
Harbor Tunnel	(3			Harbor Tunnel	b)	Wet base, standing water from PSC 457.	Other	None.
Harbor Turnel Wet base, standing water from PSC 457. Other Harbor Turnel Harbor Turnel Wet base, standing water from PSC 457. Other Harbor Turnel Harbor Turnel Harbor Turnel Harbor Turnel Harbor Turnel Harbor Turnel Poorly consolidated. Other Harbor Turnel Harbor Turnel Poorly consolidated. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipping at base, overall good. Other Harbor Turnel Minor pitting and chipp	) (			Harbor Tunnel	(3	Wet base, standing water from PSC 457.	Other	None.
Harbor Tunnel	A)			Harbor Tunnel	3)	Wet base, standing water from PSC 457.	Other	None.
Harbor Tunnel Wet base, standing water from PSC 457. Other Harbor Tunnel Wet base, standing water from PSC 457. Other Harbor Tunnel Wet base, standing water from PSC 457. Other Harbor Tunnel Harbor Tunnel Poorty consolidated. Plantor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Harbor Tunnel Pitting and chipping at base, overall good. Other Harbor Tunnel Harbor Tunnel Pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Pitting and chipping at base, overall good. Other Pitting and chipping at base, overall				Harbor Tunnel	(A	Wet base, standing water from PSC 457.	Other	None.
Harbor Tunnel Wet base, standing water from PSC 457. Other Wet base, standing water from PSC 457. Other Harbor Tunnel Peoply consolidated. Overlal good. Other Harbor Tunnel Peoply consolidated. Peop				Harbor Tunnel	)	Wet base, standing water from PSC 457.	Other	None.
Harbor Tunnel Harbor Tunnel Poorly consolidated. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Efforescence at base, overall good. Harbor Tunnel Harbor Tunnel Efforescence at base, overall good. Harbor Tunnel Harb				Harbor Tunnel		Wet base, standing water from PSC 457.	Other	None.
Harbor Tunnel Harbor Tunnel Poorly consolidated. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, over				Harbor Tunnel		Wet base, standing water from PSC 457.	Other	None.
Harbor Tunnel Poorly consolidated. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Efforescence at base. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Marbor Tunnel Minor pitting and chipping at base, overall g				Harbor Tunnel		Overall good.	Other	None.
Harbor Tunnel Poorly consolidated. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Minor pitting and chipping at base, overall good. AP 1570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe.) Harbor Tunnel Minor pitting and chipping at base, overall good. AP 1570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe.) Harbor Tunnel Minor pitting and chipping at base, overall good. AP 1570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe.) Harbor Tunnel Minor pitting and chipping at base, overall good. AP 1570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe.) Harbor Tunnel Minor pitting and chipping at base, overall good. AP 1570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe.) Harbor Tunnel Minor pitting and chipping at base, overall good. AP 1570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe.) Harbor Tunnel Minor pitting and chipping at base, overall good. AP 1570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe.) Harbor Tunnel Minor pitting and chipping at base, overall good. AP 1570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe.) Harbor Tunnel Minor pitting and chipping at base, overall good. AP 1				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel Poorly consolidated.  Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Marbor Tunnel Minor pitting and chipping at base, overall good. Other Marbor Tunnel Minor pitting and chipping at base, overall good. Other Marbor Tunnel Minor pi				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel Poorly consolidated.  Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Marbor Tunnel Minor pitting and chipping at base, overall good. Other Marbor Tunnel Minor pitting and chipping at base, overall good. Other Marbor Tunne				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Poorly consolidated. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Efflorescence at base, cracking at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Efflorescence at base, cracking at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overal				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel         Poorly consolidated.         Other           Harbor Tunnel         Poorly consolidated.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Efflorescence at base.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Efflorescence at base.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Mino				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel         Poorly consolidated.         Other           Harbor Tunnel         Poorly consolidated.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Efflorescence at base, cracking at base, overall good.         Other           Harbor Tunnel         Efflorescence at base.         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Efflorescence at base.         Efflorescence at base.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at ba				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Other Marbor Tunnel Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Efflorescence at base, cracking at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Other Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good.  Other Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base,				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         API S70. Concrete pipe saddle # 481 is not engaged with pipe (floating pipe).         Long pipe).           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel <t< td=""><td></td><td></td><td></td><td>Harbor Tunnel</td><td></td><td>Poorly consolidated.</td><td>Other</td><td>None.</td></t<>				Harbor Tunnel		Poorly consolidated.	Other	None.
Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         API 570. Concrete pipe saddle # 481 is not engaged with pipe (floating pipe).         Long pipe).           Harbor Tunnel         Efflorescence at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitti				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Efflorescence at base, cracking at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.	9			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Marbor Tunnel Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         API 570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe).         Long pipe).           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel         Minor pitting and chipping at base, overall good.         Other           Harbor Tunnel <t< td=""><td></td><td></td><td></td><td>Harbor Tunnel</td><td></td><td>Minor pitting and chipping at base, overall good.</td><td>Other</td><td>None.</td></t<>				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel     Minor pitting and chipping at base, overall good.     Other       Harbor Tunnel     API 570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe).     Long pipe).       Harbor Tunnel     Minor pitting and chipping at base, overall good.     Other Dither Dither at base, overall good.       Harbor Tunnel     Minor pitting and chipping at base, overall good.     Other Dither Dither Dither at base.       Harbor Tunnel     Minor pitting and chipping at base, overall good.     Other Dither				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Harbor Tunnel Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.	6			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel       API 570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe).       Long pipe).         Harbor Tunnel       Minor pitting and chipping at base, overall good.       Other Other Ditting and chipping at base, overall good.         Harbor Tunnel       Minor pitting and chipping at base, overall good.       Other Other Ditting and chipping at base, overall good.         Harbor Tunnel       Efflorescence at base.       Other Ditting and chipping at base, overall good.       Other Ditter Ditting and chipping at base, overall good.         Harbor Tunnel       Minor pitting and chipping at base, overall good.       Other Ditter Ditting and chipping at base, overall good.       Other Ditter Ditter Ditting and chipping at base, overall good.         Harbor Tunnel       Minor pitting and chipping at base, overall good.       Other Ditter Ditter Ditting and chipping at base, overall good.       Other Ditter Ditter Ditter Ditting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel API 570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe).  Minor pitting and chipping at base, overall good. Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Harbor Tunnel Efflorescence at base. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Harbor Tunnel Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good. Other Minor pitting and chipping at base, overall good.						Minor pitting and chipping at base, overall good.		
Minor pitting and chipping at base, overall good.  Efflorescence at base, cracking at back, but solid.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other		Table E2		Harbor Tunnel		API 570: Concrete pipe saddle # 481 is not engaged with pipe (floating	Long	API 570: Shim and monitor at next inspection.
Efforescence at base, cracking at back, but solid.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Efflorescence at base, cracking at back, but solid.	Other	None.
Minor pitting and chipping at base, overall good.  Efflorescence at base.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Efflorescence at base.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

_
0
=
O
REPC
u
~
4
>
=
0
-
C
ш
VSP
100
27
<
_
-
2
LL I
SYST
10
ζ,
1
0
S
<
RANSFER
2
_
_
Li i
FUEL
_
щ

				Table 16 - Co	16 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations		
	Appendix C – API						
Item No.	570 Report – Cross Reference	SGH Report Cross	Geographic	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(	Deficiency (InterSpec, LLC)	Reference	Area				
b)			Harbor Tunnel	100	Minor pitting and chipping at base, overall good.	Other	None.
(3			Harbor Tunnel	0)	Minor pitting and chipping at base, overall good.	Other	None.
5) (			Harbor Tunnel	(3	Minor pitting and chipping at base, overall good.	Other	None.
(A			Harbor Tunnel	) (	Minor pitting and chipping at base, overall good.	Other	None.
)			Harbor Tunnel	(A)	Wet on ceiling, efflorescence, concrete rough around all pipe	Other	None.
					penetrations.		
			Harbor Tunnel		Overall good.	Other	None.
			Harbor Tunnel		In standing water, deterioration at base.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
					Minor pitting and chipping at base, overall good.		
	000				API 570: NPS 32 (F-76) pipe has a concrete pipe saddle #501 (Between		API 570: Remove the loose concrete aggregate between
	Table E2		Harbor Tunnel		594 – S95) not engaged with pipe (floating pipe). There is loose	Long	pipe and saddle and shim with Teflon pad. Repair the
	I anie Ez				concrete aggregate between pipe and saddle. Borescope inspection in		saddle as needed. Monitor at next inspection.
					the cavity did not indicate corrosion/erosion at this area.		ž
					Bend welded saddle on plate (typ), corrosion at plate and saddle (typ),		
					saddle supported on wood block and angles.		Replace saddle support. API 570: Remove wood and
	Table E2		Harbor Tunnel		API 570: Wood shim at saddle #502 (between steel wear plate and	Long	install Teflon shim.
					saddle).		
			London T. soda oli		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ),	-	Description of the pass of the
			Harbor Tunnel	Ą	severely corroded saddle and plate on angles, base in standing water.	Long	Replace saddle and saddle support.
			Harbor Tunnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ),	long	Benjace saddle
					corrosion on built up plates.	0	
			Harbor Tunnel	07	Bend welded saddle on plate (typ), corrosion at plate and saddle (typ), corrosion on built up plates (moderate) in standing water.	Long	Replace saddle.
			Harbor Tinnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ),	Duo	Renjare cartrile
				7.0	corrosion on built up plates (moderate) in standing water.	0	
			Harbor Tunnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ).	Long	Replace saddle.
			Harbor Tunnel		Overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel	- 10	Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel	0 Y	Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel	0 Y	Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Poorly consolidated at back but solid.	Other	None.
			Harbor Tunnel		Minor consolidation issues.	Other	None.

۱			
		•	
	3	•	
i	ī	7	
ė	ī	_	
Ļ	4	١,	
L	1	3	
ì	3	3	
ķ			
i	7	,	
1	2	•	
		٦	
3		z	
ı		_	
9	1	•	
١		۰	
í		6	
	ż		
١	4	L	
t	ı	š	
2	2	2	
i	e	•	
		2	
	ī	7	
۹		•	
	Ş	Ę	
į		i	
ļ		į	
		1	
ļ	١	ς	
ļ	١	ς	
ļ	١	ς	
ļ	١	ς	
ļ	١	ς	
		ς	
		ς	
		ς	
		ς	
		ς	

				Table 16 - C	Table 16 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b)			Harbor Tunnel	(b	Minor consolidation issues.	Other	None.
(:			Harbor Tunnel	) (	Minor consolidation issues.	Other	None.
3)			Harbor Tunnel	3)	Minor consolidation issues.	Other	None.
(A			Harbor Tunnel	()	Efflorescence at base.	Other	None.
()			Harbor Tunnel	4)	Efflorescence at base.	Other	None.
	B22				Efflorescence at base. API 570: The concrete saddle (Saddle # 530) is		API 570: Repair the concrete saddle support. Consider
	Table E2		Harbor Tunnel		cracked on the edge with large splint noted on NPS 32 (F-76) line at about the 7 o'clock position.	Long	installing a Teflon pad between the saddle and pipe.
			Harbor Tunnel		Overall good.	Other	None.
			Harbor Tunnel		Efflorescence at base.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
					Efflorescence at base but solid.		
	Table E2		Harbor Tunnel		API 570: Corrosion on steel plate on saddle # 548 (there is steel plate	Long	API 570: Repair as needed/ monitor.
					between	)	
					pipe and concrete saddle).		
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.

_
٥-
REPORT
O
~
ш
0-
_
>
٠.
$\sim$
NOL
V
w
$\overline{a}$
-
INSPEC
>
=
_
_
2
,-4
_
SYSTE
ν.
7
v)
~
4
ш
u.
10
2)
2
=
ч
0
_
-
EL
JEL
CEL

Overal good.  Coveral good.  Sadde on plate on CP type, saddle not welded flush to pipe.  Overal good.  Sadde on plate on CP type, saddle not welded flush to pipe.  Overal good.  Efflorescence at base, watermarks at base of CP trapecold.  Order Efflorescence at base, watermarks at base of CP trapecold.  Order SP					Table 16 - Co	6 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations		
Harbor Tunnel Ha	1000 1000	pendix C – API Report – Cross Reference Deficiency terSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Harbor Turnel Ha	b) (3			Harbor Tunnel	(b) (	Overall good.	Other	None.
Harbor Turnel Ha	3)			Harbor Tunnel	(3)	Saddle on plate on CIP type, saddle not welded flush to pipe.	Other	None.
Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Plates moderately controde, efflorescence at base, waterm	(A			Harbor Tunnel	()	Overall good.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of	.)			Harbor Tunnel	۹)	Efflorescence at base.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base.  Other  Efflorescence at base, watermarks at base.  Othe				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other	w			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Welded saddle on plate type, efflorescence at base.  Other  Built up plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Built up plates moderately corroded, efflor				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Onther  Efflorescence at base, watermarks at base of CIP trapezoid.  Onther  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Built up plates moderately corroded, efflores				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Chher Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Chher Efflorescence at base, watermarks at base of CIP trapezoid.  Chher Efflorescence at base, watermarks at base of CIP trapezoid.  Conosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Other  Welded saddle on plate type, efflorescence at base.  Diates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded efflorescence at base.  Other  Plates moderately corroded efflorescence at base.  Other  Othe	v			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Overall good.  Overall good.  Welded saddle on plate type, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Othe				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Other  Other  Dates  Other  Dates  Other  Dates  Other  Dates  Other  Dates  Other  Dat				Harbor Tunnel	772	Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Other  Other  Othe				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other	8 <u>.</u>			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Welded saddle on plate type, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Connosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Connosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Coher Efflorescence at base, watermarks at base of CIP trapezoid.  Coher Efflorescence at base, watermarks at base of CIP trapezoid.  Coher Efflorescence at base, watermarks at base of CIP trapezoid.  Coher Efflorescence at base, watermarks at base of CIP trapezoid.  Coher Efflorescence at base, watermarks at base of CIP trapezoid.  Coher Efflorescence at base, watermarks at base of CIP trapezoid.  Coher Efflorescence at base, watermarks at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded at Base.  Other Plates moder				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Coher Efflorescence at base, watermarks at base of CIP trapezoid.  Other Efflorescence at base, watermarks at base of CIP trapezoid.  Other Efflorescence at base, watermarks at base of CIP trapezoid.  Other Built up plates moderately corroded, efflorescence at base.  Other Plates moderately corroded at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Other  Built up plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded at Base.  Other	20 - t			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Other  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded at Base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded at base.				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded efflorescence at base.  Other  Plates moderately corroded efflorescence at base.  Other	36			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other	0 0			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Cornosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded at florescence at base.  Other	4 s			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded at base.  Other	:3			Harbor Tunnel		Corrosion at saddle, efflorescence at base.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded at hase.				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded at hase.				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded at hase.	200			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on Off slepner efflorescence at base. Other				Harbor Tunnel		Corrosion at saddle, efflorescence at base.	Other	None.
Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Candilo on Off slepper efflorescence at base.  Other Candilo on Off slepper efflorescence at base.  Other Candilo on Off slepper efflorescence at base.  Other				Harbor Tunnel		Overall good.	Other	None.
Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on Off sleeper efflorescence at base. Other				Harbor Tunnel		Welded saddle on plate type, efflorescence at base.	Other	None.
Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on OP sleeper, efflorescence at base.	a_ t			Harbor Tunnel		Built up plates moderately corroded, efflorescence at base.	Other	None.
Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Saddle on OP sleeper, efflorescence at base.				Harbor Tunnel		Plates moderately corroded, efflorescence at base.	Other	None.
Plates moderately corroded, efflorescence at base. Other	- Jih			Harbor Tunnel		Plates moderately corroded, efflorescence at base.	Other	None.
Saddle on CIP sleeper, efflorescence at base.				Harbor Tunnel		Plates moderately corroded, efflorescence at base.	Other	None.
				Harbor Tunnel		Saddle on CIP sleeper, efflorescence at base.	Other	None.

	Recommended Repairs	None.	None.	None.	
	Urgency	Other	Other	Other	
6 - Concrete Sleepers - F-76 Pipe Support Findings and Recommendations	. Condition Notes	Saddle type ok.	Saddle type ok.	Saddle type ok, beyond PSC 596(c) pipes move horizontally and have individual supports.	(b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c
Table 16 -	Pipe Support No.	b)	(3	8) (A	)
	Geographic Area	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	
	SGH Report Cross Reference				
	Appendix C – API 570 Report – Cross Reference Cross Deficiency Reference				
	Item No.	b) A	) )	3)	

Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations	Geographic Pipe Suppo Area No.	Baseplate corroded, not anchored, minor corrosion at angle to wall connection,  Harbor corrosion at saddle on backside.  Long round Teflon strips between pipe and bipe support (F-24).  Long round Teflon strips between pipe and between pipe and pipe support locations.	Severe baseplate corrosion, severe corrosion at (1) brace to wall. API 570: No wear plate or Teflon pad between pipe and pipe support	Corrosion at baseplate and bottom of column, no grout pad/pier, column baseplate  Harbor bears on slab mild corrosion over entire support, severe corrosion at JP-5 bracket to wall (x1) at Tunnel bolts to wall not uniformly flush tight to wall.	Harbor Corrosion at baseplate and bottom of column, top bolt not seated well at 2 side, Long Clean corrosion and repaint, replace anchorage to wall.  Tunnel	Harbor Harbor Long Gean corrosion and repaint, maintain in good condition.	Severely corroded baseplate and bottom of column, loss of steel in column,  Harbor delamination of baseplate, no grout pad, F-24 connected to wall severely corroded.  API 570: Coating failure and corrosion noted on the steel pipe supports at various locations. Noted on the base plate, on angle iron, and tunnel wall attachment points.	Harbor Harbor Anchor bolts corroded, bottom of column moderately corroded, flange deformed, Long Long Tunnel API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Harbor Harbor and bolts not straight.  Tunnel API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Harbor Bottom of column moderately corroded, anchor bolts and baseplate covered w/ Long Clean corrosion and repaint, maintain in good condition.  Tunnel	Harbor Minor corrosion at column bottom, anchor bolts (nuts) corroded.  Long Gean corrosion and repaint, maintain in good condition.	Harbor Long Gean corrosion and repaint, maintain in good condition.	Harbor Anderately-minor base of column corrosion, baseplate corrosion, anchor bolts Long Gean corrosion and repaint, maintain in good condition.  Tunnel	Harbor Moderately-minor column corrosion, anchors to wall not well seated, severe Long Replace support.	Harbor Mild column corrosion, moderate JP-5 to wall corrosion. moderate JP-5 to wall corrosion.	Harbor Harbor In and renaint maintain in good condition
	100.00	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor	Harbor	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor	Harbor	Harbor	Harbor	Harbor
	Appendix C – API SGH 570 Report – Report Cross Reference Cross Deficiency Reference (InterSpec, LLC)	Table E2	Table E2				B14 Table E2	Table E2	Table E2							
	App 5: Sitem No. Cro	(b) (3)	(A)													

L	
TAUG	7
7	7
۶	,
н	٠
≈	2
2	۰
2	2
c	٥
đ	5
г	7
ŭ	1
CDE	ľ
Ū	5
2	É
-	=
-	2
S	Ę
쓴	4
U	5
E A	i
v	7
0	
ũ	ì
ű	į
¥	2
2	2
◂	ľ
Q	Ē
H	
	á
ü	á
=	٥
L	

				Tabl	Table 17 - Frame Pipe Supports - F-24/1P-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency	SGH Report Cross	Geographic Area	Pipe Support No.		Urgency	Recommended Repairs
(b) (	(interapped, tree)		Harbor	(b)	Mild column corrosion, moderately severe baseplate and anchor botts corrosion, mild corrosion at paint damage, moderate at F-24 anchor bolts to wall at	Long	Gean corrosion and repaint, maintain in good condition.
(3) (			Harbor	(3)	lts co	Long	Gean corrosion and repaint, maintain in good condition.
A)			Harbor	(A)	COLL	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate column corrosion, severe anchor bolts corrosion, moderate at IP-5 anchor bolt to wall, deterioration of top flange, very severe at F-24 anchor bolts to wall, both sides.	Long	Replace support.
			Harbor		Moderate column corrosion, severe anchor bolt corrosion, moderate anchor to wall, both lines 1 side.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild column corrosion, moderate anchor bolt and baseplate corrosion, mild at all bolts on wall.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Mild column corrosion, moderate anchor and baseplate corrosion, mild at baseplate in grout.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild column corrosion, moderate anchor bolt and baseplate corrosion.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild column corrosion, moderate anchor bolt and baseplate corrosion.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate-severe column corrosion moderate anchor bolt and baseplate corrosion, mild all anchor bolts to wall, excep	Long	Replace support.
			Harbor		noderate base	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate column corrosion, moderate anchor bolt and baseplate corrosion, mild anchor bolts to wall.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild column corrosion, moderate anchor bolt corrosion, welded connection to wall at JP-5 at 2 side, no nut F-24 at 1.	Long	Anchor to wall at all locations.
			Harbor Tunnel		Moderate column corrosion, moderate anchor bolt and baseplate corrosion 2 not tight.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate-severe column corrosion, moderate anchor bolt and baseplate corrosion, ok anchor bolts to wall.	Long	Replace support.
			Harbor Tunnel		Moderate column corrosion, moderate anchor bolt and baseplate corrosion, ok anchor bolts to wall.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate column corrosion, moderate-severe anchor bolt and baseplate corrosion.	Long	Replace support.
			Harbor Tunnel		Mild-moderate column corrosion, mild-moderate anchor bolt and baseplate corrosion, moderate	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild column corrosion, moderate anchor bolt and baseplate corrosion, moderate F-24 anchor bolt at 1.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild-moderate column corrosion, moderate anchor bolt and baseplate corrosion.	Long	Clean corrosion and repaint, maintain in good condition.

L	
TAUG	7
7	7
۶	,
н	٠
≈	2
2	۰
2	2
c	٥
đ	5
г	7
ŭ	1
CDE	ľ
Ū	5
2	É
-	=
-	2
S	Ę
쓴	4
U	5
E A	i
v	7
0	
ũ	ì
ű	į
¥	2
2	2
◂	ľ
Q	Ē
H	
	á
ü	á
=	٥
L	

tem No. Cross Reference Report Geographic Pipe S Cross Reference Cross Area N Cross Area N Cross Area N Reference Tunnel	Mild-moderate column corrosion, moderate moderate at 2, anchor bolt not volumn corrosion, moderate anchor both moderate anchor both at 1P-5.  Moderate column corrosion, deformed fla moderate anchor both at 1P-5, moderate an deterioration and corrosion.  New "T" and baseplate installed at severemoderate to baseplate installed at severemoderate to baseplate, mild corrosion to a moderate to baseplate installed at severemoderate to baseplate and minor corrosion paint damage on support. API 570: No wear plate or Teflon pad between pipe and pipe support.  Moderate corrosion at column, moderate	Mild-moderate column corrosion, moderate anchor holt and baseplate corrosion, moderate at 2, anchor bolt not visible a 1 side.  Mild column corrosion, moderate anchor bolt and baseplate corrosion, moderate both 1, mild JP-5.  Moderate column corrosion, deformed flange, severe anchor bolt corrosion, moderate anchor bolt at JP-5, moderate anchor bolt at JP-5, moderate anchor bolt at severe column corrosion, moderate anchor bolt at JP-5 moderate and anchor bolts to wall.	Urgency	Recommended Repairs
Table E2 HT-46 B17 Table E2		Locrrosion, moderate anchor holt and baseplate corrosion,  2, anchor bolt not visible a  1 side.  1 moderate anchor bolt and baseplate corrosion, moderate soion, deformed flange, severe anchor bolt corrosion, at JP-5, moderate anchor bolt at top flange at JP-5 sion.  Installed at severe column corrosion, mild corrosion to T, initial corrosion to achor bolts to wall.  and, baseplate and anchor bolts corroded, grout pad chipped, damage on support.	Long	
Table E2 HT-46  B17  Table E2		woderate anchor bolt and baseplate corrosion, moderate osion, deformed flange, severe anchor bolt corrosion, at IP-5, moderate anchor bolt at top flange at JP-5 osion.  In the severe column corrosion, mild corrosion to T, in the corrosion to achor bolts to wall.  In the severe column corrosion wild corrosion to T, and corrosion to achor bolts to wall.  In the severe column corrosion wild corrosion to T, and corrosion to achor bolts to wall.	Long	Clean corrosion and repaint, maintain in good condition.
Table E2 HT-46  B17  Table E2		osion, deformed flange, severe anchor bolt corrosion, at JP-5, moderate anchor bolt at top flange at JP-5 bsion.  Sign.  Installed at severe column corrosion, mild corrosion to T, mild corrosion to achor bolts to wall.  ands, baseplate and anchor bolts corroded, grout pad chipped, damage on support.	19	Gean corrosion and repaint, maintain in good condition.
НТ-46	New "T" and baseplate moderate to baseplate No saddles or bearing minor corrosion paint. API 570: No wear plate plate or Teflon pad bet between pipe and pipe Moderate corrosion at	installed at severe column corrosion, mild corrosion to T, mild corrosion to achor bolts to wall.  ads, baseplate and anchor bolts corroded, grout pad chipped, damage on support.	Long	Replace support.
HT-46	No saddles or bearing minor corrosion paint: API 570: No wear plate plate or Teflon pad bet between pipe and pipe Moderate corrosion at	bads, baseplate and anchor bolts corroded, grout pad chipped, damage on support.	Long	Gean corrosion and repaint, maintain in good condition.
250	Moderate corrosion at	API 570: No wear plate or Teflon pad between pipe and pipe support No wear plate or Teflon pad between pipe and pipe support (JP-5). No wear plate or Teflon pad between pipe and pipe support	Long	Install bearing pads, clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-tound Teflon strips between pipe and I-Beam structure or other metal to-metal support locations.
	moderate at JP-5 anch API 570: Anchor type v repairs/mods). The exi location (weaker).	Moderate corrosion at column, moderate at basenlate, anchor bolts not visible, moderate at JP-5 anchor bolts (x1), moderate a x1).  API 570: Anchor type welded saddle was cut of the pipe (likely for previous repairs/mods). The existing weld attachment is only tack welded at two location (weaker).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Engineering assessment may be required to determine if this saddle support is sufficiently anchored.
Harbor Tunnel	Moderate-severe at $\infty$ anchor bolts to wall.	Moderate-severe at column, moderate-severe at anchor bolts and baseplate, mild at anchor bolts to wall.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Moderate at column, r wall.	Moderate at column, moderate at anchor bolt and baseplate, mild at anchor bolts to wall.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Moderate at column, r mild at wall.	Moderate at column, moderate at anchor bolt and baseplate, grout pad damaged, mild at wall.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Moderate at column, moderate at anchor b bolt to wall, mild at (3) anchor bolts to wall.	Moderate at column, moderate at anchor bolt and baseplate, moderate at (1) anchor bolt to wall, mild at (3) anchor bolts to wall.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Mild corrosion at anchor bolts to wall, baseplate, severe corrosion at column	Mild corrosion at anchor bolts to wall, moderate at baseplate anchor bolts and baseplate, severe corrosion at column.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Moderate corrosion at	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Moderate corrosion at	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	$\label{eq:condition} \textbf{Gean corrosion and repaint, maintain in good condition.}$
Harbor Tunnel	Moderate corrosion at	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Moderate corrosion at sever corrosion at	Moderate corrosion at any number of locations, may have efflorescence coating it, sever corrosion at column and anchor bolts to wall, grout pad chipped.	Long	Gean corrosion and repaint, maintain in good condition, replace lower column and grout pad.
Harbor Tunnel	Mild corrosion at any r pad damage.	Mild corrosion at any number of locations, may have efflorescence coating it, grout pad damage.	Long	Gean corrosion and repaint, repair grout pad, maintain in good condition.

-	
٥	Ş
Ç	)
8	۱
DEDOD	į
>	,
MOIT	5
č	
C	j
Ä	4
ũ	ì
INCDE	Ė
3	
Ľ	
Ų	1
CVCT	ì
6	
ũ	ì
H	
ž	ż
<	t
TDANCEED	¢
_	1
4	j
E	٥

				Tabl	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3	(mersher, rrc)		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
3) (A			Harbor	(3)	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
)			Harbor	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, anchor bolt not tight.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt at baseplate not tight, anchor bolt a	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, wood shim at baseplate.	Long	Gean corrosion and repaint, maintain in good condition, remove shim and replace grout pad.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, chip at grout pad.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations, no nut.	Long	Replace support.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, wood shim at baseplate.	Long	Gean corrosion and repaint, maintain in good condition, remove shim and replace grout pad.
	-00						

L	_
ь	F
7	₹
TOCOLO	,
В	١,
ų	4
Q	ς
2	
5	÷
C	)
ī	2
r	7
MCDEC	1
×	٠
н	t
×	2
5	ξ
5	3
5	÷
쓴	4
г	3
₹	3
CVCTEAA	7
~	,
۵	c
ц	j
ч	Ę
u	٦
ANCER	2
ê	ř
ã	٤
ď	•
•	
	4
ü	a
2	2

				Tahl	Table 17 - Frame Bine Summent - E 24/18.5 Bine Summert Einglings and Becommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.		Urgency	Recommended Repairs
b) ((			Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
3) (A			Harbor Tunnel	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it, baseplate broken.	Long	Gean corrosion and repaint, maintain in good condition.
()			Harbor	A)	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel	V 3	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent x2.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2	HT-44	Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Long	Replace support.

-
2
PORT
$\approx$
-
REI
-
2
NO
⋍
9
INSPE
S
<
SYSTEM
~
S
Z.
S
~
æ
S
S
=
꿇
5
VEL
ш
2

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (			Harbor	(b)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
3) (A			Harbor Tunnel	(3)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
A)			Harbor	(A)	Severe corrosion w/ loss of material at any number of locations, corrosion on JP-5 braces, corrosion at	Long	Replace support.
	B14 Table E2		Harbor		Extreme corrosion w/ no or very little material at any number of locations.  API 570: Coating failure and corrosion noted on the steel pipe supports at various locations. Noted on the base plate, on angle iron, and tunnel wall attachment points. Moderate corrosion on horizontal support attachment to wall (QTY 4).	Urgent	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Support wear plate to support not engaged (JP-5) (floating pipe).	Long	Clean corrosion and repaint, maintain in good condition. API 570: Shim and monitor at next inspection.
			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Extreme corrosion w/ no or very little material at any number of locations, active dripping.	Urgent	Replace support, support on minimum 6" raised concrete pier.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, anchor bolt bent, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken w/ wood shim.	Long	Gean corrosion and repaint, maintain in good condition, remove shim and replace grout pad.

-
PORT
-
n
~
а.
REF
~
щ
_
~
~
u
_
( )
т.
INSPEC
NSPI
10
27
~
-
_
~
<
ш
_
,
y
SYSTE
in
-,
~
ш
щ
SF
ISF
NSF
ANSF
ANSF
RANSF
<b><i>RANSE</i></b>
TRANSF
TRAN
TRAN
TRAN
TRAN
UEL TRANSF

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b)	6		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
(3) (			Harbor	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
A)			Harbor	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
do inc			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
100			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations, column flange deformed.	Long	Replace support.
			Harbor	7 1	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
t.			Harbor		Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
is in			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
		НТ-36	Harbor		Severe corrosion w/ loss of material at any number of locations, water flowing starts.	Long	Replace support, support on minimum 6" raised concrete pier.
lo c		HT-36	Harbor		Severe corrosion w/loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pler.
		HT-29 HT-36	Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
		НТ-36	Harbor		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support, support on minimum 6" raised concrete pier.
		НТ-36	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
		HT-36	Harbor Tunnel		Severe $\infty$ rrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support, support on minimum 6" raised concrete pier.
		НТ-36	Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support, support on minimum 6" raised concrete pler.

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
b) (3		HT-36	Harbor	(b)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
3) (A		HT-36	Harbor	(3)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
()	Table E2	HT-36 HT-39	Harbor	(A)	Severe corrosion w/ loss of material at any number of locations.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier
	Table E2	НТ-36 НТ-39	Harbor		Severe corrosion w/ loss of material at any number of locations.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-36 HT-39 HT-41	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent and baseplate submerged.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	нт-36 нт-39	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent and baseplate submerged. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-36 HT-39	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, grout pad broken, anchor bolt bent and baseplate submerged. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	НТ-36 НТ-38	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water, Corrosion on base of pipe support (attachment to tunnel floor).	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-36	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, grout pad broken w/ wood shim, water flowing ends. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-36	Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-36	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, no grout pad. API 570: Minor to moderate corrosion on the base plate due to standing water, anchor bolts on the base of plate are not secured down to the floor.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, grout pad broken w/ wood shim, anchor bolt bent. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent. API 570: Minor to moderate corrosion on the base plate due to standing water. No wear plate or Teflon pad between pipe and pipe support (JP-5).	Long	Replace support, support on minimum 6" raised concrete pier. Consider Teffon shims/insulation strips between pipe and saddle or half-round Teffon strips between pipe and LBeam structure or other metal tometal support locations.
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier

				Tabl	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
b) (	Table E2		Harbor	(b)	Moderate corrosion at any number of locations, may have efflourrescense coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
3) (A)	B16 Table E2		Harbor Tunnel	(3) (A)	Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: Majority of the piping support in the harbor tunnel has tack-welded steel wear plates between pipe and pipe support. Few locations with metal-to-metal contact and some corrosion were noted on the NPS 16 (F-24) and NPS 18 (JP-5) lines. Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair coating on the pipe and support. Provide a Teflon shim at location of metal-to-metal contact points.
	Table E2		Harbor	ī	Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pler.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken, anchor bolt bent.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pler.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	B25 Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken, anchor bolt bent w/ wood shim.  API 570: Pipe support with anchor bolts not embedded in the concrete.	Long	Clean corrosion and repaint, maintain in good condition, remove shim and replace grout pad. API 570: Secure the anchor bolts to the base plate of the pipe support.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.

_
٥-
REPORT
O
~
ш
0-
_
>
٠.
$\sim$
NOL
V
w
$\overline{a}$
-
INSPEC
>
=
_
_
2
,-4
_
SYSTE
ν.
7
v)
~
4
ш
u.
10
2)
2
=
ч
0
_
-
EL
JEL
CEL

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3)	Table E2		Harbor Tunnel	(b) (	Severe corrosion w/ loss of material at any number of locations, no grout pad, connection to wall not visible.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
(A)			Harbor Tunnel	3) (A	Severe corrosion w/ loss of material at any number of locations, connection of the wall not visible.	Long	Replace support.
			Harbor Tunnel	4)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, column flange deformed.	Long	Replace support.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel	2	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor	X. a	Severe $\cos rosion  w/loss  of  material  at  any  number  of  locations,  anchor  bolt  bent.$	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
	Table E2	HT-33	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, wall anchors not visible.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.

21
ш
7
Line
La s
ш
Ψ.
Æ
H
SE
SFE
ISFE
VSFE
NSFE
NSFE
ANSFE
ANSFE
ANSFE
RANSFE
RANSFE
RANSFE
TRANSFE
TRANSFE
TRANSFE
TRANSFE
L TRANSFE
L TRANSFE
EL TRANSFE
EL TRANSFE
JEL TRANSFE
<b>UEL TRANSFE</b>
<b>UEL TRANSFE</b>
·UEL TRANSFE
FUEL TRANSFE
FUEL TRANSFE
FUEL TRANSFE

					Table 1	Table 17 - Frame Pipe Supports - F-24/IP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	bort	Condition Notes	Urgency	Recommended Repairs
b) (3			Harbor	(b)	S	Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
3) (A			Harbor Tunnel	(3) (		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
):			Harbor Tunnel	A)	/ ( Table )	Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		3,	Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
	Table E2		Harbor Tunnel		¥ ä ≤	Moderate corrosion at any number of locations, may have efflorescence coating it, anchor bolt bent.  API 570: Anchor bolts on the base of plate are not secured down to the floor	Long	Gean corrosion and repaint, maintain in good condition. API 570: Defer to next inspection (has grouting).
			Harbor		'S	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		3	Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
			Harbor		35	Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
			Harbor		Σ	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Σ	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		S	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		S	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		S.	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		S	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		3	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Š	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
		нт-32	Harbor Tunnel		a & g	Extreme corrosion w/ no or very little material at any number of locations, complete deterioration through bottom front flange of both columns, extreme deterioration of anchor bolts over back flange of both columns.	Urgent	Replace support.
	Table E2	НТ-32	Harbor Tunnel		7 ¢ å ¢ ⊞	Extreme corrosion w/ no or very little material at any number of locations, severe corrosion over entire support complete less of support at bottom of both columns and both flanges, delamination (severe) at baseplate, angles to wall severely deteriorated.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.

L	_
ь	F
7	₹
TOCOLO	,
В	١,
ų	4
Q	ς
2	
5	÷
C	)
ī	2
r	7
MCDEC	1
×	٠
н	t
×	2
5	ξ
5	3
5	÷
ď	4
г	3
₹	3
CVCTEAA	7
~	,
۵	c
ц	j
ч	Ę
u	٦
ANCER	2
ê	ř
ã	٤
ď	•
•	
	4
ü	a
2	2

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
b) (3			Harbor	(b)	Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
(A			Harbor	(3)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
)			Harbor	(A)	Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, grout pad cracked.	Long	Replace support.
95 - 15			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
N. 3			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
c te			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
24			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
	Table E2		Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, wall anchor not visible, flanges at angle column not attached to baseplate, severe delamination at baseplate.  API 570: Support wear plate to support not engaged (JP-5) (floating pipe).	Urgent	Replace support.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it, same style as others, wall shield, wall anchor bolt not visible.	Other	None.
e e			Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme corrosion at baseplate and column flanges, appears unattached and detached when sounded.	Urgent	Replace support.

١.	_
ĸ	=
DUGGG	5
~	ς.
٠.	,
ñ	
٠	
u	
ñ	=
ч	
_	Ξ
2	•
Ξ	-
	٦.
2	•
С	_
	•
L	
) L	٠.
MADE	4
	ш
	•
y	7
3	
5	
-	
7	
S	i
Š	i
Y	
Y L	
VAP V	
	A CICK
	200
	EN SISIEN
	TEN SISIE
	JIEN SISIEN
CEED CVCTE	ASTEN STORES
CEED CVCTE	March of the
CEED CVCTE	TANGET OF STEEL
CEED CVCTE	AND LAND OF THE
CEED CVCTE	TAIN OF THE PARTY
CEED CVCTE	TAIN TO LE LA COLLEGA
CEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
TDANCEED CVCTE	TO COLON
CEED CVCTE	TO COLON

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3)	Table E2		Harbor Tunnel	(b) (3)	Extreme corrosion w/ no or very little material at any number of locations, extreme delamination at baseplate, columns not attached due to extreme deterioration, JP-5 bracket to the wall deteriorated and detached.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
(A)			Harbor Tunnel	(A)	Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.
			Harbor Tunnel		Severe $\cot\cos$ on w/significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe $\cos \cos \omega / \sin i$ ficant loss of material at any number of locations, grout pad chipped.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
_	Table E2		Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations. API 570: No wear plate or Teflon provided after repairs (JP-5) (floating pipe).	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.

	ı
_	ı
-	ı
4	ı
	ı
$\sim$	ı
0	ı
Line	ı
~	ı
4	ı
-	ı
<	ı
	ı
$\sim$	ı
	ı
	ı
0	ı
LU1	ı
~	ı
-	ı
S	ı
-	ı
	ı
	ı
_	ı
~	ı
Lin	ı
	ı
-	ı
V)	ı
~	ı
S	ı
	ı
0-	ı
100	ı
-	ı
-	ı
S	ı
-	ı
-	ı
◂	ı
~	ı
-	ı
	ı
	ı
	ı
щ	ı
	ı
_	ı
-	ı
	۰

				Tab	Table 17 - Frame Pipe Supports - F-24/19-5 Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec. LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (:			Harbor	(b)	Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
3) (A			Harbor	(3)	Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
()			Harbor Tunnel	(A)	Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.

L	
Tacas	ē
ē	₹
ä	•
ŭ	1
ď	7
Ξ	2
<	5
C	٥
201	•
•	٠
ũ	1
MICDE	ď
U	ī
2	ŕ
4	
5	Ę
М	4
ū	₹
ς	4
CVCTEAA	5
	_
9	í
	•
ü	5
2	ŕ
ē	7
TDANCE	2
Ē	2
	1
=	5
×	•

idations	Urgency Recommended Repairs	Long Replace support.	oken. Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	rout pad Long Replace support.	oken. Long Replace support.	oken. Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	Long Replace support.	l anchor Long Replace support.	rout pad Long Replace support.
Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations	Condition Notes	Severe corrosion w/loss of material at any number of locations.	Severe corrosion w/loss of material at any number of locations, grout pad broken.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/loss of material at any number of locations.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/loss of material at any number of locations.	Severe corrosion w/ significant loss of material at any number of locations.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/ significant loss of material at any number of locations.	Severe $\omega$ rrosion w/significant loss of material at any number of locations, grout pad broken.	Severe corrosion w/loss of material at any number of locations, grout pad broken.	Severe corrosion w/loss of material at any number of locations, grout pad broken.	Severe corrosion w/ significant loss of material at any number of locations.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations, all anchor bolts not visible.	Severe corrosion w/significant loss of material at any number of locations, grout pad broken.
Tab	Pipe Support No.	(b)	(3)	(A)						Ĭ											
	Geographic Area	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor
	SGH Report Cross Reference																				
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	55 17 18																			
	Item No.	b) (3	3) (A	)																	

b	
REPORT	ï
ă	•
ū	ī
Q	
2	
C	١
F	:
Ų	)
H	4
v	5
INSPECTION	
_	:
SYSTEM	
Ľ	4
G	5
>	
200	•
ď	ì
ū	:
TRANSF	9
S	ŧ
ã	4
F	
-	į
4	

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (			Harbor	(b)	Severe corrosion w/significant loss of material at any number of locations, grout pad broken.	Long	Replace support.
3) (4			Harbor Tunnel	(3) (	Severe corrosion w/significant loss of material at any number of locations, grout pad broken.	Long	Replace support.
<b>A</b> )			Harbor Tunnel	A)	Severe corrosion w/significant loss of material at any number of locations, grout pad broken, loss of bearing.	Urgent	Replace support.
	Table E2		Harbor		Severe corrosion w/significant loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		APLS/U: No wear plate or Letton provided after repairs (F-24) (floating pipe).  Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor	2	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Extreme corrosion w/ no or very little material at any number of locations, JP-5 at wall.	Urgent	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent, grout pad broken.	Long	Replace support.
			Harbor	X	Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.

ь	•
Lacasa	•
ř	7
١,	,
Q	L
u	J
ñ	7
•	•
>	
MODECTION	7
C	2
c	•
5	•
L	,
ц	3
۵	c
ü	3
ξ	4
9	5
2	
<	
ц	4
Н	=
ù	•
Š	•
	7
	,
MARKED	•
ī	7
ŭ	٠
7	=
×	2
<	5
c	•
ä	3
707	
-	•
_	í
ū	7
=	

Table E2	Reference Reference Harbor Tunnel	No. (p) (3) (A)	Severe corrosion w/ loss of material at any number of locations, anchor bolt bent, grout pad broken.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.	Long Long Long Long Long Long Long Long	Replace Support.
	Tunnel				

_
ъ-
~
REPORT
о.
щ
œ
_
<
NOL
5
-
INSPEC
щ
٥.
S
2
-
-
SYSTEM
ш
$\vdash$
S
>
S
_
4
۳
:=
S
<
A
0
۳
3
LTR
IEL TR

Hem No. Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area Harbor Tunnel	Pipe Support No. (p) (3) (A)	locations. locations. locations. grout pad broken. locations.	Long Long Long Long Long Long Long Long	Replace support.	
		Tunnel Harbor Tunnel Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/ loss of material at any number of locations.  Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support. Replace support. Replace support.	

	ı
_	ı
-	ı
4	ı
	ı
$\sim$	ı
0	ı
Line	ı
~	ı
4	ı
-	ı
<	ı
	ı
$\sim$	ı
	ı
	ı
0	ı
LU1	ı
~	ı
-	ı
S	ı
-	ı
	ı
	ı
_	ı
~	ı
Lin	ı
	ı
-	ı
V)	ı
~	ı
S	ı
	ı
0-	ı
	ı
-	ı
-	ı
S	
-	ı
-	ı
◂	ı
~	ı
-	ı
	ı
	ı
	ı
щ	ı
	ı
_	ı
-	ı
	۰

				Tab	Table 17 - Frame Pine Supports - F-24/IP-5 Pine Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (	55 55 55		Harbor	(b)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
3) (4			Harbor Tunnel	(3)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
4)			Harbor Tunnel	(A)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe $\infty$ rrosion w/significant loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.

Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations	Pipe Support  Urgency Recommended Repairs  No.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/ loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Severe corrosion w/significant loss of material at any number of locations.	Sewere corrosion w/significant loss of material at any number of locations, no nut on Long Replace support.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.	Severe corrosion w/significant loss of material at any number of locations.
		<u> </u>	L =		L (1)	<b>=</b> -	<u> </u>	L 0	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	L -	<u> </u>	L 0	- A
	Geographic Area	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor
	SGH Report Cross Reference								НТ-28		нт-28							HT-30	HT-30	HT-30	HT-30
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)																				
	ltem No.	(b) (	3) (A	<b>(</b> )																	

PEDOPT	
g	Ş
C	٥
Q	Ĺ
ц	ä
Q	Ę
>	
7	₹
5	2
5	,
INCPEC	4
ä	t
š	4
S	Ė
-	
2	2
μ	4
b	:
CVCTEM	•
Ū	5
	_
H	۱
CED	•
Ü	ī
ANC	Ė
d	ř
o	2
F	3
	i
	i
	٥
u	I

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (		HT-30	Harbor Tunnel	(b) (	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
3) (4	Table E2		Harbor Tunnel	(3) (	Mild corrosion at any number of places, may have efflorescence from wall coating it. API 570: No wear plate or Teflon provided after repairs (floating pipe).	Long	API 570: Shim and moniter at next inspection.
<b>(</b> )			Harbor	۹)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
	Table E2	НТ-26 НТ-28	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, column flanges completely deteriorated at slab, baseplate is dust, JP-5 attachments to wall completed corroded - not attached at (1) side.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, corroded baseplate, no grout.	Other	None.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: No wear plate or Teflon provided after repairs (JP-5) (floating pipe).	Long	Gean of corrosion and maintain in good condition. API 570: Shim and monitor at next inspection.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, corroded baseplate, no grout.	Long	Clean of corrosion and maintain in good condition.
			Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme corrosion at bottom of column and significant loss of column flange section at baseplate interface.	Urgent	Replace support.
	B3.2 Table E2	нт-26	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, column moderately corroded, JP-5 anchor to wall complete section loss.  API 570: Corrosion on pipe support at the tunnel wall attachment.	Urgent	Replace Support.
		НТ-26	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, moderate column corrosion, complete loss of section at JP-5 and anchor to wall on 1 side.	Urgent	Replace support.
	Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have offlorescence coating it. API 570: No wear plate or Teflon provided after repair	Long	Gean of corrosion and maintain in good condition. API 570: Shim and monitor at next inspection.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.

۱	
DEDODI	Ċ
c	٥
ā	Ĺ
ų	ä
>	,
NOT	₹
ř	ć
ŗ	٠
ò	1
MICDE	ď
ū	ī
2	É
-	=
5	3
ā	1
F	3
Ų	7
CVCTE	•
٩	ς
H	4
ŭ	5
ź	2
ē	7
ō	2
۴	
	i
	ä
=	٥

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
b) (			Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
3) (#			Harbor	(3) (	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
A)			Harbor	(A)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
	Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: No wear plate or Teflon provided after repairs  No wear plate or Teflon provided after repairs	Long	Gean corrosion and repaint, maintain in good condition. API 570: Shim and monitor at next inspection.
			Harbor		Severe corrosion w/significant loss of material at any number of locations, impacted and deformed column flanges.	Urgent	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it. API 570: No wear plate or Teflon provided after repairs (JP-5).	Long	API 570: Shim and monitor at next inspection.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.

ı			
	•	۰	
	3	•	
i	i	7	
١		3	
í	S		
		٠	
١	ě	4	
	3	•	
	7	-	
3	3	,	
1	•	,	
	•	٦	
3		z	
		Ξ	
		7	
9	٠	,	
	ı		
ř	ς	•	
•	٠	,	
Ş	,	7	
1		6	
•	5	•	
	•	•	
ŧ	e		
ì	١	Ę	
į	ì	į	
į			
		1	
		17 10 17	
		200	
		THE STATE OF THE S	
		2000	
		200	
LIL			
	THE PARTY OF THE P		

L	
TAUG	7
7	7
۶	,
н	٠
≈	2
2	۰
2	2
c	٥
đ	5
г	7
ŭ	1
CDE	ľ
Ū	5
2	É
-	=
-	2
S	Ę
쓴	4
U	5
E A	i
v	7
0	
ũ	ì
ű	į
¥	2
2	2
◂	ľ
Q	Ē
H	
	á
ü	á
=	٥
L	

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
tem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
b) (3	5 7 8		Harbor Tunnel	(b)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
(A			Harbor Tunnel	(3) (	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
)			Harbor	A)	Severe corrosion w/ loss of material at any number of locations.	Long	Clean corrosion and repaint, maintain in good condition.
2 ()			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
k a			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor	m:	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
400			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor	294	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: The original tack welded wear plate between pipe and support is short. The bell-bell weld is resting on directly on pipe support member.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure or other metal-tometal support locations.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor	*	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
A			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
7							

REP	
0	
ISPEC	
<	
S	
S	
S	
Ę	
TEN T	
SEN	
STEA	
STEN	
YSTEN	
YSTEN	
SYSTEA	
SYSTEA	
SYSTEN	
SYSTEN	
R SYSTEN	
R SYSTEN	
R SYSTEN	
<b>ER SYSTEN</b>	
ER SYSTEN	
FER SYSTEN	
FER SYSTEN	
SFER	
SFER	
ISFER SYSTEN	
SFER	
TRANSFER	
SFER	

				Tahl	Table 17 - Frame Dine Sunnorts - E-24/ID-5 Dine Sunnort Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.		Urgency	Recommended Repairs
b) (	9 9		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
3) (A		HT-19	Harbor	(3)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
<b>(</b> )			Harbor Tunnel	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor	. u	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.

-
ORT
$\mathbf{\mathcal{I}}$
0
REI
•
œ
_
>
=
0
9
-
,
ũ
INSP
7
ອ
2
=
~
<
ш
S
,-
y
>
in
-,
0
ш
щ
S
-
<
-
-
9
_
Li i
=
_

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
b) (3			Harbor Tunnel	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
3) (A			Harbor Tunnel	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor	A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/ loss of material at any number of locations, deformed flange column, grout pad broken.	Long	Replace support.
		SGH p242	Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
		SGH p242	Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.

-
ORT
$\mathbf{\mathcal{I}}$
0
REI
•
œ
_
>
=
0
9
-
,
ũ
INSP
7
ອ
2
=
~
<
ш
_
S
y
>
in
-,
0
ш
щ
S
-
<
-
-
9
_
Li i
=
_

				Tahl	Table 17 - Frame Dine Supports - E-24/18.5 Dine Support Findings and Berommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (			Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
3) (4		H-11	Harbor	(3) (	$\label{eq:moderate} \begin{tabular}{ll} Moderate corrosion at any number of locations, may have efflorescence coating it, no saddles, no pads. \end{tabular}$	Long	Clean corrosion and repaint, maintain in good condition.
4)			Harbor	A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
10			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.

_
REPORT
=
O
~
ш
0-
_
>
NOL
$\sim$
V
INSPEC
~
S
S
>
-
_
-
_
щ
_
Š
SYSTE
•
S
_
œ
ш
G.
-
S
>
$\overline{}$
◂
~
,-
_
_
亘
-
_
щ

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
N a	Appendix C – API 570 Report –	SGH Report	Geographic	Pipe Support	Candition Nates	Voneoul	Recommended Renaire
(	Deficiency (InterSpec, LLC)	Cross Reference	Area	No.		(allegio	
b) (3	10 10 10 10 10 10 10 10 10 10 10 10 10 1		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Pong	Gean corrosion and repaint, maintain in good condition.
3) (A			Harbor	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
)			Harbor	A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: Small wood shim between wear plate and Steel support member (JP-5).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Remove wood and install Teflon shim.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad chipped.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.

_
æ
-
C
$\simeq$
ц.
REPORT
0
_
>
NOL
O
_
C
INSPEC
$\overline{}$
-
ຶ
2
-
_
>
,,,,,
_
SYSTE
>
SYS
- "
8
wi
ď
:=
S
2
-
3
×
-
-
_
邑

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
tem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b)	ê		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(3)		HT-8	Harbor	(3)	Severe corrosion w/loss of material at any number of locations, JP-5 brace to wall corroded.	Long	Replace support.
(A)			Harbor	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad chipped.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it brace at wall corroded.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, stacked washers anchor bolt to wall at F-24 line or S side to fit anchor bolt to wall.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad chipped.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad chipped.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, JP-5 supported on frame on attachment to wall, ceiling support threaded rod for frame extension for additional lines (sprinkler lines) abandoned (?) ceiling and pipe support (unnumbered) between and and 144, abandoned frame is level 3, threaded rod is badly deteriorated.  API 570: No wear plate or Teflon at the intermediate lines welded directly to pipe.	Long	Gean corrosion and repaint, replace ceiling supported threaded rods, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure or other metal-tometal support locations.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2	HT-5	Harbor		Severe corrosion w/ loss of material at any number of locations.  API 570: Intermediate between and is welded directly to pipe.	Long	Replace support.

_
PORT
œ
-
u
n
ш
RE
ч.
_
~
õ
O
9
-
•
INSPEC
~
٠.
S
~
<
-
_
~
~
SYSTE
~
_
S
ς,
_
S
0
8
ш
ш
16
2)
-
_
₫
~
_
•
_
107
_
FUEL
~
٠.

				Tabl	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3) (	B16 Table E2		Harbor Tunnel	(b) (3)	Severe corrosion w/loss of material at any number of locations.  API 570: Majority of the piping support in the harbor tunnel has tack-welded steel wear plates between pipe and pipe support. Few locations with metal-to-metal contact and some corrosion were noted on the	Long	Replace support .
A)	Table E2	HT-5	Harbor Tunnel	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: Intermediate betwee	Long	Gean corrosion and repaint, maintain in good condition. API 570: Monitor at next inspection.
	Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it API 570: No wear plate or Teflon at	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure or other metal-tometal support locations.
	Table E2	HT-5	Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: Intermediate between the second of t	Long	Clean corrosion and repaint, maintain in good condition. API 570: Monitor at next inspection.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
		HT-5	Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, JP-5 on stacked plates.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations may have efflorescence coating it.  API 570: Pipe is not in contact with support (floating pipe).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Shim and monitor at next inspection.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.

	3	3	
		:	
١		)	
١	3	Ļ	
١	ŧ	4	
Ę	2		
	>	•	
ì		₹	
3	١	2	
ŀ	٠		
Ç		þ	
ļ	į	4	
	4	Ļ	
١	4	)	
•	S	5	
	1	•	
	S	ī	
i		7	
į		•	
į	i	١	
2	>		
Ļ	•	7	
	s		
ĺ	i	ì	
Ļ		Ĭ	
Ļ	,	)	
i	2	2	
•	q	r	
ľ	ì	2	
ŀ		ij	
į		i	
۰	•	5	
i	ī		

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (	(merches) rec		Harbor	(b)	Mild corrosion at any number of places, may have efflorescence from wall coating it, grout pad broken.	Other	None.
3) (#			Harbor	(3)	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
4)			Harbor	(A)	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
k .			Harbor		Severe corrosion w/ loss of material at any number of locations, JP-5 brace to wall at 3 side corroded, column flange deformed.	Long	Replace support.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it, grout pad broken.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
200			Harbor	81	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Severe corrosion w/ loss of material at any number of locations, JP-5 brace to wall corroded.	Long	Replace support.
	Table E2		Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it. API 570: Anchor bolts on the base of plate are not secured down to the floor.	Long	API 570: Secure anchor bolts.
o 50			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, column flange deformed, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.

				Tal	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations			
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency	SGH Report Cross	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs	
(t	(InterSpec, LLC)	Reference						
o) (3			Harbor Tunnel	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it, extremely long anchor bolt.	Long	Clean corrosion and repaint, maintain in good condition.	
3) (A			Harbor Tunnel	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.	
)			Harbor Tunnel	A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.	
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.	
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, wall to wall WF, high zinc paint, moderate corrosion at paint damage, F-24 line on built up WF, JP-5 on cradle.	Long	Gean corrosion and repaint, maintain in good condition.	
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, wall to wall WF, high zinc paint, moderate corrosion at paint damage, F-24 line on built up WF, JP-5 on cradle.	Long	Gean corrosion and repaint, maintain in good condition.	
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, wall to wall WF, high zinc paint, moderate corrosion at paint damage, F-24 line on built up WF, JP-5 on cradle, both lines on saddles.	Long	Gean corrosion and repaint, maintain in good condition.	
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, WF supported on angles at walls, high zinc paint, bottom flange deformation at several areas.	Long	Gean corrosion and repaint, maintain in good condition.	
			RHTF		efflorescence at pipe penetrations on tunnel side, moderate cracking in gunnite parge coat.	Long	Gean and repair.	
			RHTF		Moderate pitting and paint flaking, moderate deformation of lower flange at (1) location.	Other	None.	
			RHTF		Moderate corrosion at column connection to beam, light corrosion at wall.	Long	Clean corrosion and repaint, maintain in good condition.	
			RHTF		Moderate corrosion at column connection to beam, light corrosion at wall.	Long	Clean corrosion and repaint, maintain in good condition.	
	A15		RHTF		wing con reson in small pockets along beam and column, and corrosion than 96, still mild angle paint is deteriorated.	Long	Gean corrosion and repaint, maintain in good condition, Provide sufficient spacing between pipe and Unistrut.	
			RHTF		Mild corrosion in small pockets along beam and column, minor bottom flange deformation between supports.	Long	Clean corrosion and repaint, maintain in good condition.	
			RHTF		Mild corrosion in small pockets along beam and column, no flange deformation.	Other	None.	
			Tank 1 Lateral		Good condition.	Other	None.	
			Tank 1 Lateral		Good condition.	Other	None.	
			Tank 2 Lateral		Plate deformed at diesel fuel line.	Other	None.	
			Tank 2 Lateral		Good.	Other	None.	

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3) (A)	A11 Table E2		RHTF	(b) (3) ( <i>i</i>	Moderate corrosion along beam and beam brace, grout pad/protection damaged at column. API 570: Pipe is not fully bearing on support (partial support)	Long	Gean corrosion and repaint, maintain in good condition. API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to- metal support locations.
	A11	LAT-52	RHTF	4)	Missing cross brace arm to very mild spot corrosion.  API 570: Long segment of the nipe is unsupported. The pipe is also not adequately supported betwee with only partial support on one side.	Long	Add cross brace arm. API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11		RHTF		Very mild spot corrosion.  API 570: Long segment of the line is unsupported. The pipe is also not adequately supported betwee with only partial support on one side.	Long	API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11		RHTF		Very mild spot corrosion.  API 570: Long segment of the also not adequately supported between with only partial support on one side.	Long	API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11 Table E2		RHTF		Minor corrosion in small areas. API 570: Unistrut in contact with pipe a causing coating failure/corrosion. Pipe is not fully bearing on support (partia	Long	API 570: Repair pipe and shim the pipe or pipe support as needed to support the pipe uniformly.
	A11		RHTF		Minor corrosion in small areas. API 570: Long segment of the adequately supported between with only partial support on one side.	Long	API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11 Table E2		RHTF		Minor corrosion in small areas, deformation at lower angle brace to API 570: Unistrut in contact with pipe at PS86 causing coating failure/corrosion. Long segment of the nine is unsupported. The pipe is also not adequately supported between with only partial support on one side.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair pipe and add shim. Consider Teflon shims/insulation strips between pipe and saddle or half- round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
	A11		RHTF		Moderate corrosion at wall, cracking and chipping of lower grout pad.  API 570: Long segment of the Namer of the Name of the N	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11 Table E2		RHTF		Moderate corrosion at wall, cracking and chipping of lower grout pad. API 570: Pipe is not bearing on support (floating pipe)	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
	A11 Table E2		RHTF		Moderate corrosion at wall, cracking and chipping of lower grout pad. API 570: Pipe is not bearing on support (floating pipe)	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or halfround Teflon strips between pipe and L-Beam structure or other metal-to-metal support locations.

L	_
ь	F
7	₹
TOCOLO	,
В	١,
ų	4
Q	ς
2	
5	÷
C	)
ī	2
r	7
MCDEC	1
×	٠
н	t
×	2
5	ξ
5	3
5	÷
쓴	4
г	3
₹	3
CVCTEAA	7
~	,
۵	c
ц	j
ч	Ę
u	٦
ANCER	2
ê	ř
ã	٤
ď	•
•	
	4
ü	a
2	2

	ncy Recommended Repairs	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.		Repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.	Clean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.	Add cross bracing, clean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Replace steel saddle. Shim the pipe or pipe support as needed to support the pipe uniformly.	er None.	g API 570: Adjust support (raise the plate).	er None.	g Gean corrosion, maintain in good condition.	Replace column, anchorage, and grout pad, clean corrosion and repaint, maintain in good condition.	Clean corrosion and repaint, maintain in good condition, API 570: Replace the corroded steel saddle support. Consider a saddle that is secured (welded to the support structure) and a Teflon pad between pipe and saddle. Apply protective coating.
	Urgency	Long	Long	Long	Long	Long	Other	Long	Other	Long	Long	Long
Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations	Condition Notes	Moderate corrosion at wall, cracking and chipping of lower grout pad. API 570: Pipe is not bearing on support (floating pipe)	API 570: Pipe is not bearing on support (floating pipe)	Cracking and chipping at grout pad. API 570: Pipe is not bearing on support (floating pipe)	Moderate corrosion at wall, cracking and chipping of lower grout pad. API 570: Pipe is not bearing on support (floating pipe)	Moderate corrosion at wall, cracking and chipping of lower grout pad, missing cross brace arm td 79.  API 570: Moderate corrosion on the steel saddle Long segment of the nipe is unsupported. One location has 57' 11" of unsupported pipe between	None.	API 570: Pipe is not bearing on support (floating pipe) NPS 20. Pipe is not bearing on support (floating pipe	None.	Corrosion at pipe support down to cross beam.	Moderate corrosion all over, top flange deformed at wall end, column flange deformed at free end, grout pad damaged, baseplate damaged.	Moderate corrosion, minor grout pad cracking and chipping. API 570: Some coating failure and corrosion between pipe and pipe support on the (JP-S) pipe.
Ta	Pipe Support No.	(b) (3)	(A)									
	100.00											
	Geographic Area	RHTF	RHTF	RHTF	RHTF	RHTF	Tank 3 Lateral	Tank 3 Lateral	Tank 4 Lateral	Tank 4 Lateral	RHTF	RHTF
	SGH Report Cross Reference					LAT-51					LAT-28	
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	A11 Table E2	A11 Table E2	A11 Table E2	A11 Table E2	A11 Table E2		Table E2				A19 Table E2
	ltem No.	(b) (3) (A)										

Ŀ	•
9	5
Dana	2
÷	٠
ŏ	ž
5	
۶	7
þ	ć
ľ	7
ũ	6
٥	ū
۷	2
MODECTION	5
•	
5	
Ĭ	
	200
CVCTEAA	200
TO CVCTEA	2000
EFD CVCTEA	TEN SISIEN
VOEED CVCTEA	STEN STEIN
ANCEED CVCTER	AND THE STREET
DANCEED CVCTEA	TAIN OF THE
TDANCEED CVCTEA	TAIN OF THE
TDANCEED	TO TO TO
TEL TOANCEED CVCTER	TO TO TO

	ncy Recommended Repairs	API 570: Replace the corroded steel saddle support. Consider a saddle that is secured (welded to the support structure) and a Teflon pad between pipe and saddle. Apply protective coating.	API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-tometal support locations.	ng API 570: Shim.	API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-tometal support locations.	ng Clean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition. API 570: Repair coating.	Gean corrosion and repaint, maintain in good condition, repair angle brace at deformed area. API 570: Replace the corroded steel saddle support. Consider a saddle that is secured (welded to the support structure) and a Teflon pad between pipe and saddle. Apply protective coating.	Gean corrosion and repaint, maintain in good condition. API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to- metal support locations.		Gean corrosion and repaint, maintain in good condition.  API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and -Beam structure or other metal tometal support locations.	3-20-20
	Urgency	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long
Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations	Condition Notes	API 570: Some coating failure and corrosion between pipe and pipe support on the (JP-S) pipe.	Grout pad chipped. API 570: Pipe is not bearing on support, missing saddle (floating pipe)	API 570: Wood shim b/w saddle and pipe support member/dislodged	API 570: Pipe is not bearing on support (floating pipe)	Paint chipping, moderate corrosion more severe at wall, pipe support corroded.	Paint chipping, moderate corrosion more severe at wall, pipe support corroded.  API 570: There are moderate coating failure and some corrosion on the horizontal pipe support I-beam.	Corroded at wall, low angle brace between API 570: Some coating failure and corrosion between pipe and pipe support on the (JP-S) pipe. Moderate corrosion on the steel saddle (JP-S).	X bracing removed between for new ventilation door (door 3) installation.  API 570: Pipe is not bearing on support (floating pipe)	Moderate corrosion, splice under pipe, mildly deformed bottom flange at wall.  API 570: Some coating failure and corrosion between pipe and pipe support on the (JP-S) pipe. Moderate corrosion on the steel saddle (JP-S).	Corrosion/efflorescence deformation at support plate at diese API 570: No Teflon between pipe and support (Tank 5).	Corrosion/efflorescence deformation at support plate at diese API 570: Loose nut on adjustable plate/some deflection on plate
Ta	Pipe Support No.	(b) (3)	(A)									
	Geographic F Area	RHTF	RHTF	RHTF	RHTF	RHTF	RHTF	RHTF	RHTF	RHTF	Tank 5 Lateral	Tank 5 Lateral
	SGH Report Cross Reference		LAT-48	LAT-47		LAT-46	LAT-46	LAT-45 LAT-46				
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	A19 Table E2	Table E2	A8 Table E2	Table E2		Table E2	A19 Table E2	Table E2	A19 Table E2	Table E2	Table E2
	ltem No.	(b) (3) ( <i>i</i>	<b>A)</b>									

_
6
~
REPORT
о.
щ
œ
_
<
NOL
5
-
INSPEC
щ
٥.
S
2
-
-
SYSTEM
ш
$\vdash$
S
>
S
_
4
۳
:=
S
<
A
0
۳
3
LTR
IEL TR

Appendix C – API SGH Report Geographic Pipe Support Cross Reference Cross Area No. Deficiency Reference Cross Area No. Deficiency Reference Tank 6 Lateral Tank 6 Lateral Tank 6 Lateral RHTF RHTF RHTF RHTF Table E2 RHTF RHTF Table E2 Lateral Tank 8 Lateral Tank					Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
Table E2   Table E2   Table E3   Corrosion/efflorescence deformation at support plate at diese	ltem No.	Appendix C – API 570 Report – Cross Reference	SGH Report Cross	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Table E2	(	Deficiency (InterSpec, LLC)	Reference					
Table E2 Table E2 Table E2 Table E2 Table E2 Table E3 Table E4 Table E4 Table E5 Table E5 Table E5 Table E5 Table E5 Table E4 Table E5 Tab	b) (3	50 50 50 50 50 50 50 50 50 50 50 50 50 5		Tank 5 Lateral	(b)	Corrosion/efflorescence deformation at support plate at diese	Long	Gean corrosion and repaint, maintain in good condition.
Table E2 RHTF Corrosion/efflorescence deformation at support plate at diese cracked grout tong exposed baseplate.  RHTF RHTF Column flange deformation.  RHTF RHTF Column flange deformation.  RHTF RHTF Column flange deformation, top angle brace to a large and chipped (IP-S).  RHTF RHTF RHTF Column flange deformation, top angle brace to a large and condition.  RHTF RHTF RHTF RHTF RHTF Column flange deformation, top angle brace to a large and condition.  RHTF RHTF RHTF RHTF RHTF RHTF RHTF RHTF	3) (A			Tank 6 Lateral	(3)	Corrosion/efflorescence deformation at support plate at diese	Long	Gean corrosion and repaint, maintain in good condition.
Lateral   RHTF   Flange deformation at wall anchor moderate corrosion at wall.   Long	()			Tank 6	(A)	ence deformation at support plate at diese	long	Gean corrocion and repaint maintain in good condition
RHTF   API 50°C Moderate corrosion at wall anchor moderate corrosion at wall and P150°C Moderate corrosion at wall.   Column flange deformation.   Column flang				Lateral		exposed baseplate.	20102	cream control of the state of t
RHITE Column flange deformation.  RHITE Minor coronson at wall.  RHITE Develail good.  Buikhead anchor in good condition.  RHITE Column flange deformation, top angle brace to leng Column flange deformation, top angle brace to length lengt		Table E2		RHTF		Flange deformation at wall anchor moderate corrosion at wall. API 570: Moderate corrosion on the steel saddle (JP-5).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair pipe and add shim.
HHTF RHIFF Overall good.  RHTF RHIFF Column flange deformation, top angle brace to	-			RHTF		Column flange deformation.	Other	None.
RHTF     Overall good.     Other       RHTF     Bulkhead anchor in good condition.     Other       RHTF     Moderate corrosion at wall.     Long       RHTF     Column flange deformation, top angle brace tod.     Long       RHTF     Overall good.     Long       RHTF     API 570: Contact type abrasion and corrosion at pipe support/pipe (IP-5).     Long       RHTF     Lower angle brace deformed.     Long       API 570: Contact type abrasion and corrosion at pipe support/pipe (IP-5).     Long       Tank 7     API 570: Small deflection on pipe support after dresser coupling (Tank 7).     Long       Tank 8     Overall good.     Other       Tank 8     Overall good.     Other       RHTF     Overall good.     Other       Moderate corrosion at wall, minor deformation to bottom flange bent.     Long       RHTF     Overall good.     Other       LAT-26     RHTF     Column flange deformation, corrosion at bear-wall interface.     Long       LAT-28     RHTF     Column flange deformation, corrosion at bear-wall interface.     Long       LAT-28     RHTF     Column flange deformation, corrosion at bear-wall interface.     Long				RHTF		Minor corrosion at wall.	Other	None.
RHTF   Bulkhead anchor in good condition.   Other				RHTF		Overall good.	Other	None.
RHTF Column flange deformation, top angle brace to long RHTF Column flange deformation, top angle brace to long RHTF Column flange deformation, top angle brace to long RHTF Column flange deformation, top angle brace deformed. API 570: Contact type abrasion and corrosion at pipe support/pipe (IP-5). Tank 7 Plate supporting pipe at T74 bent under weight. Lateral Lateral API 570: Small deflection on pipe support after dresser coupling (Tank 7). Tank 8 Overall good. Coverall good. RHTF Corrosion at baseplate, grout cracked and chipped, beam flange bent. Column flange deformation at several locations on braced column. LAT-26 RHTF Column flange deformation, corrosion at beam-wall interface. LAT-26 RHTF Beam flange deformation, corrosion at beam-wall interface. LONG LAT-26 RHTF Beam flange deformation, corrosion at beam-wall interface. LONG LAT-26 RHTF Beam flange deformation, corrosion at beam-wall interface. LONG LAT-26 RHTF Beam flange deformation, corrosion at beam-wall interface. LONG LAT-26 RHTF Beam flange deformation, corrosion at beam-wall interface. LONG LAT-26 RHTF Beam flange deformation, corrosion at beam-wall interface. LONG LAT-26 RHTF Beam flange deformation, corrosion at beam-wall interface.				RHTF		Bulkhead anchor in good condition.	Other	None.
RHTF Column flange deformation, top angle brace to long and ethors of the long overall good.  RHTF Moderate corrosion under middle line, column flange deformed.  API 570: Contact type abrasion and corrosion at pipe support/pipe (IP-5).  Lateral Lateral API 570: Small deflection on pipe support after dresser coupling (Tank 7).  Lateral API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection on pipe support after dresser coupling (Tank 7).  API 570: Small deflection after after dresser after dresser after dresser after dresser after dresser after dress	~			RHTF		Moderate corrosion at wall.	Long	Clean corrosion and repaint, maintain in good condition.
RHTF         Overall good.         Other           RHTF         Moderate corrosion under middle line, column flange deformed.         Long           RHTF         API 570: Contact type abrasion and corrosion at pipe support/pipe (JP-5).         Long           Tank 7         Plate supporting pipe at T7A bent under weight.         Long           Tank 7         API 570: Small deflection on pipe support after dresser coupling (Tank 7).         Long           Tank 8         Overall good.         Other           Tank 8         Overall good.         Other           RHTF         Corrosion at baseplate, grout cracked and chipped, beam flange bent.         Long           RHTF         Overall good.         Corrosion at wall, minor deformation to bottom flange.         Long           RHTF         Column flange deformation at several locations on braced column.         Long           LAT-28         RHTF         Beam flange deformation, corrosion at beam-wall interface.         Long				RHTF			Long	Clean corrosion and repaint, maintain in good condition, attach angle brace fully.
HHTF API 570: Contact type abrasion and corrosion at pipe support/pipe (IP-5).    RHTF				RHTF		Overall good.	Other	None.
RHTF         Lower angle brace deformed.         Long           Inank 7         Plate supporting pipe at T7A bent under weight.         API 570: Small deflection on pipe support after dresser coupling (Tank 7).         Long           Inank 8         Overall good.         Overall good.         Other           Inank 8         Overall good.         Inng           Inng         Inng         Inng           In		Table E2		RHTF	); (c)	Moderate corrosion under middle line, column flange deformed. API 570: Contact type abrasion and corrosion at pipe support/pipe (JP-5).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair coating. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
Tank 7       Plate supporting pipe at T7A bent under weight.       Long         Tank 7       Overall good.       Overall good.       Other         Tank 8       Overall good.       Other         Tank 8       Overall good.       Other         Tank 8       Overall good.       Other         RHTF       Corrosion at baseplate, grout cracked and chipped, beam flange bent.       Long         RHTF       Moderate corrosion at wall, minor deformation to bottom flange.       Long         LAT-26       RHTF       Column flange deformation at several locations on braced column.       Long         LAT-28       RHTF       Beam flange deformation, corrosion at beam-wall interface.       Long				RHTF			Long	Clean corrosion and repaint, maintain in good condition.
Tank 7     Overall good.     Other       Lateral     Overall good.     Other       Tank 8     Overall good.     Other       Take 8     Overall good.     Other       RHTF     Corrosion at baseplate, grout cracked and chipped, beam flange bent.     Long       RHTF     Overall good.     Long       RHTF     Moderate corrosion at wall, minor deformation to bottom flange.     Long       RHTF     Column flange deformation at several locations on braced column.     Long       RHTF     Beam flange deformation, corrosion at beam-wall interface.     Long		Table E2		Tank 7 Lateral		Plate supporting pipe at T7A bent under weight. API 570: Small deflection on pipe support after dresser coupling (Tank 7).	Long	API 570: Adjust support (raise the plate).
Tank 8  Overall good.  Lateral Tank 8  Overall good.  Lateral RHTF  Overall good.  Corrosion at baseplate, grout cracked and chipped, beam flange bent.  Corrosion at baseplate, grout cracked and chipped, beam flange bent.  Long RHTF  Moderate corrosion at wall, minor deformation to bottom flange.  Column flange deformation at several locations on braced column.  Long RHTF  RHTF  Beam flange deformation, corrosion at beam-wall interface.  Long				Tank 7 Lateral			Other	None.
Tank 8  Corrosion at baseplate, grout cracked and chipped, beam flange bent.  RHTF  Coverall good.  RHTF  Overall good.  Column flange deformation to bottom flange.  Column flange deformation at several locations on braced column.  Long  RHTF  RHTF  RHTF  Column flange deformation, corrosion at beam-wall interface.  Long  Long  Long	oi - 1			Tank 8 Lateral		Overall good.	Other	None.
RHTF       Corrosion at baseplate, grout cracked and chipped, beam flange bent.       Long         RHTF       Overall good.       Other         RHTF       Moderate corrosion at wall, minor deformation to bottom flange.       Long         RHTF       Column flange deformation at several locations on braced column.       Long         RHTF       Beam flange deformation, corrosion at beam-wall interface.       Long				Tank 8 Lateral			Other	None.
RHTF     Overall good.     Other       RHTF     Moderate corrosion at wall, minor deformation to bottom flange.     Long       RHTF     Column flange deformation at several locations on braced column.     Long       RHTF     Beam flange deformation, corrosion at beam-wall interface.     Long				RHTF		Corrosion at baseplate, grout cracked and chipped, beam flange bent.	Long	Clean corrosion and repaint, maintain in good condition, repair grout pad.
RHTF         Moderate corrosion at wall, minor deformation to bottom flange.         Long           RHTF         Column flange deformation at several locations on braced column.         Long           RHTF         Beam flange deformation, corrosion at beam-wall interface.         Long				RHTF		Overall good.	Other	None.
RHTF Column flange deformation at several locations on braced column. Long  RHTF Beam flange deformation, corrosion at beam-wall interface. Long				RHTF		Moderate corrosion at wall, minor deformation to bottom flange.	Long	Clean corrosion and repaint, maintain in good condition.
RHTF Beam flange deformation, corrosion at beam-wall interface.				RHTF		Column flange deformation at several locations on braced column.	Long	Gean corrosion and repaint, maintain in good condition.
			LAT-26 LAT-28	RHTF		Beam flange deformation, corrosion at beam-wall interface.	Long	Clean corrosion and repaint, maintain in good condition.

				Tabl	Table 17 - Frame Pine Supports - F-24/IP-5 Pine Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (interSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3) (A)	Table E2	LAT-26	RHTF	(b) (3) ( <i>i</i>	Corrosion at saddle of wall closest to pipe, corrosion at beam-wall interface. API 570: Coating failure and corrosion at saddle support (JP-5).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair coating. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
		LAT-26 LAT-43	RHTF	۹)	Corrosion at base of center column at repair.	Long	Clean corrosion and repaint, maintain in good condition
		LAT-26	RHTF		Baseplate grout chipped.	Long	Clean corrosion and repaint, maintain in good condition, repair grout pad.
			RHTF		Baseplate corrosion at wall baseplate.	Long	Clean corrosion and repaint, maintain in good condition.
	A25 Table E2		Tank 9 Lateral		API 570: NPS 20 pipe is not in contact with the pipe (floating pipe).	Long	Adjust the elevation of the pipe support plate to provide sufficient load bearing contact between pipe and support plate.
			Tank 9 Lateral		None.	Other	None.
A 40			Tank 10 Lateral		Corrosion on top beam and top of column (efflourescense).	Long	Gean corrosion and repaint, maintain in good condition.
			Tank 10 Lateral		None.	Other	None.
	A7 A10 Table E1 Table E2	LAT-41 LAT-42	RHTF		Severe corrosion and significant loss of support at train-side column (photo), minor corrosion at center column baseplate, grout pad edges destroyed at center column baseplate (photo), severe corrosion and loss of material at beam near wall (photo) API 570: Metal to metal contact. No Teflon shims/insulation strip. Rail-ties wedged between pipe and saddle Corrosion on base of pipe support and I-beam.	Urgent	Replace support  Note: This support is currently programmed for repair as part of the FV21 Emergent Pipeline Repair Project.
	A7 Table E1 Table E2	LAT-38 LAT-40	RHTF		orrosi ntact.	Urgent	Replace support  Note: This support is currently programmed for repair as part of the FV21 Emergent Pipeline Repair Project.
	A9 Table E2		RHTF		eam su segme ipe be	Long	Gean corrosion and repaint, maintain in good condition. API 570: Install saddle supports at meded to support pipe on the saddles. Secure the saddles to the pipe support.
	A9 Table E2	LAT-39	RHTF		Cracking and chipping at grout nad.  API 570: Long segment of the of the office is unsupported. One location has 47' of the office is unsupported pipe between of the office is unsupported by the saddle support missing at	Long	Gean corrosion and repaint, maintain in good condition, replace grout pad. API 570: Install saddle supports at 46 and shim as needed to support pipe on the saddles. Secure the saddles to the pipe support.

- 1
000
0
0
Line
~
4
-
<
0
~
( )
~
W.
0
S
>
~
<
ш
in
2,1
To I
S
0-
-
- 44
4
S
->
⋖.
02
-
-
LL I
5
ш.

Reference   Area   No.	Annendix C - API				Table 3	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
Tank 12	S70 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	100.00	t I	Condition Notes	Urgency	Recommended Repairs
Tank 1.12   None Chipping at baseplate and grout.   Tank 1.12   None Chipping at baseplate and grout.   Tank 1.2   None Corrosion at paint damage, moderate flange corrosion at downspout, top flange defamination at beam, moderate baseplate corrosion at downspout, top flange defamination at beam, moderate baseplate corrosion at downspout, top flange defamination at beam, moderate baseplate corrosion at downspout, top flange deformation at beam, moderate baseplate corrosion at downspout, top flange deformation at beam in moderate baseplate corrosion at downspout.   Minor damage at grout pad damage at wall column.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   Minor grout pad damage at wall column.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   Grout pad damage and flange corrosion at wall column.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   Column flange deformation at train track flange, grout pad damage and minor passable to corrosion at paint chipping.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No Teflon shims/insulation strip.   API 570: Metal to metal contact. No			Tank 11 Lateral	u) (.		lone.	Other	None.
LAT-26 RHTF			Tank 12 Lateral	) ( <i>P</i>	1000	finor chipping at baseplate and grout.	Other	None.
LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF			Tank 12 Lateral	<b>'</b>		lone.	Other	None.
LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF	Table E1	LAT-26	RHTF		≥ # E ₹	finor corrosion at paint damage, moderate flange corrosion at downspout, top ange delamination at beam, moderate baseplate corrosion at train track column w/ ninor grout damage.	Long	Clean corrosion and repaint, maintain in good condition, relocate downspout. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF	Table E1	LAT-26	RHTF		H A		Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pad I-Beam structure at all pipe support locations.
LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF  LAT-26 RHTF	Table E1	LAT-26	RHTF		2 4	finor damage at grout pad. PI 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
LAT-26 RHTF LAT-26 RHTF LAT-26 RHTF	Table E1	LAT-26	RHTF		2 3	finor grout pad damage at wall column. PI 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
LAT-26 RHTF LAT-26 RHTF LAT-26 RHTF	Table E1	LAT-26	RHTF		9 4		Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure at all pipe support locations.
LAT-26 RHTF	Table E1	LAT-26	RHTF		ठर	orrosion at paint chipping. PI 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pad I-Beam structure at all pipe support locations.
LAT-26 RHTF	Table E1	LAT-26	RHTF		A R O	olumn flange deformation at train track flange, grout pad damage and minor aseplate corrosion at wall column. PI 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	 Table E1	LAT-26	RHTF		A K	eam flange corrosion at downspout. PI 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, repair beam at flange delamination, relocate downspout. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and HBeam structure at all pipe support locations.

b	
REPORT	ï
ă	•
ū	ī
Q	
2	
C	١
F	:
Ų	)
H	4
v	5
INSPECTION	
_	:
SYSTEM	
Ľ	4
v	,
>	
200	•
ď	ì
ū	:
TRANSF	9
S	ŧ
ã	4
F	
-	į
4	

				Tah	Table 17 - Frame Dine Sunnorts - F-24/ID-5 Dine Sunnort Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3) (A)	Table E1	LAT-26	RHTF	(b) (3) (A	Grout pad damage and loss of support. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
K			Tank 13 Lateral	<b>A)</b>	Concrete pier/grout pad damage.	Long	Repair grout pad.
			Tank 13 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.
			Tank 13 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.
			Tank 14 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.
			Tank 14 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.
	Table E1	LAT-26	RHTF		Baseplate corrosion at wall column (moderate), moderate-severe column flange corrosion at train track column. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
y.	Table E1 Table E2	LAT-26	RHTF		Moderate flange deformation at train track column, column flange damage at wall column.  API 570: Metal to metal contact. No Teflon shims/insulation strip. Pipe is not bearing on support (floating pipe) (F-76).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to- metal support locations.
	Table E1	LAT-26 LAT-30	RHTF		Flange deformation at wall column, baseplate grout damage and corrosion at wall column.  API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
		LAT-31	RHTF		Overall good.	Other	None.
	Table E1	LAT-26 LAT-30	RHTF		Overall good. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
			RHTF		Overall good.	Other	None.
<i>y</i>	Table E1	LAT-28	RHTF		Column flange deformation at train track column, minor grout chipping at wall column baseplate. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
			RHTF		Overall good.	Other	None.

te e						lable 1/ - Frame Pipe Supports - F-24/1F-5 Pipe Support Findings and Recommendations		
	Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
	(b) (3) (A	Table E1	LAT-26	RHTF	(b) (3) (A)	Beam flange corrosion at downspout, baseplate corrosion at wall column. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition, relocate downspout. API 570: Consider Teflon shims/insulation strips between pipe and saddle or halfround Teflon strips between pipe and I-Beam structure at all pipe support locations.
	)	Table E1	LAT-26 LAT-27	RHTF		Corrosion (moderate) at wall baseplate, grout chips, minor flange deformation at beam, severe delamination and corrosion at wall beam. Severe delamination and corrosion at wall beam. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, replace damaged beam at wall column and wall connection, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
		Table E1 Table E2	LAT-25 LAT-26	RHTF		Corrosion (moderate) at wall baseplate, grout chips, minor flange deformation at beam, severe delamination and corrosion at wall beam. API 570: Metal to metal contact. No Teflon shims/insulation strip. Moderate corrosion on the steel saddle	Long	Gean corrosion and repaint, replace damaged beam at wall column and wall connection, maintain in good condition. API 570: Replace steel saddle. Consider Teflon shins/insulation strips between pipe and saddle or half-round Teflon strips between pipe and Leam structure at all pipe support locations.
		Table E2	LAT-23	RHTF		Beam flange deformation, beam corrosion at JP-5 and lines, baseplate grout cracked and chipped.  API 570: Moderate corrosion on the steel saddle	Long	Replace severely corroded beam area, clean corrosion and repaint, maintain in good condition. API 570: Replace steel saddle.
				Tank 15 Lateral		Corrosion at line.	Long	Clean corrosion, maintain in good condition.
- 3				Tank 15 Lateral		None.	Other	None.
		Table E2		Tank 16 Lateral		Baseplate grout damage. API 570: Small deflection on pipe support after dresser coupling (Tank 16).	Long	API 570: Adjust support (raise the plate).
				Tank 16 Lateral		None.	Other	None.
		Table E1	LAT-19 LAT-20 LAT-23	RHTF		Flange deformation at beam, baseplate corrosion and grout damage at line. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and FBeam structure at all pipe support locations.
		Table E1	LAT-20 LAT-21	RHTF		Grout damage and corrosion at baseplate, minor column flange deformation, cross bracing cut. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
		Table E1	LAT-19 LAT-20	RHTF		Minor flange deformation, significant corrosion at column base and loss of column, flange steel. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Replace Support; alternatively, cut out area of deformation and corrosion and replace in kind

-
2
PORT
$\approx$
-
REI
-
2
NO
⋍
9
INSPE
S
<
SYSTEM
~
S
Z.
S
~
æ
S
S
=
꿇
5
VEL
ш
2

				Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3) ( <i>i</i>	Table E1	LAT-18	RHTF	(b) (3)	Beam flange corrosion (moderate) at pipe support area on top of beam. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
A)	Table E1	LAT-17 LAT-18	RHTF	(A)	Severe corrosion and loss of steel at wall connection. API 570: Not in contact with saddle.	Long	Replace connection to wall, clean corrosion and repaint, maintain in good condition. API 570: Add shims to support to gain contact.
	Table E1		RHTF		Could not access to perform assessment. API 570: There is no saddle support and the pipe is not resting on the I-beam.	Long	API 570: Add shims to support to gain contact.
	Table E1		RHTF		Could not access to perform assessment. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	None. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure at all pipe support locations.
			RHTF		Overall good.	Other	None.
	Table E1		RHTF		No saddle to JP-5 line, cracked and chipped grout at wall column. API 570: There is no saddle support and the pipe is not resting on the I-beam.	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shims to support to gain contact.
	Table E1	LAT-13 LAT-14	RHTF		Minor corrosion at paint damage, has saddle, wall column grout cracked and chipped. API 570: The pipe is partially in contact with the pipe support.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Add shims to support to gain contact.
	Table E1	LAT-11 LAT-12	RHTF		Beam flange deformation, wall baseplate corroded, grout chipped and missing. API 570: Not in contact with saddle.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Add shims to support to gain contact.
			Tank 17 Lateral		Corrosion at column bottoms, loss of steel, corrosion at unknown member, flange cutout at tackwelded member, no visible saddle at JP-5.	Long	Clean corrosion and repaint, maintain in good condition, add saddle.
			Tank 17 Lateral		Corrosion at base of column, no saddle.	Long	Gean corrosion, maintain in good condition, add saddle.
			Tank 17 Lateral		Overall good.	Other	None.
			Tank 18 Lateral		Beam moderately corroded at ends and beam top flange, no saddle for JP-5 line, crack and exposed rebar at unknown gunnite support.	Long	Gean corrosion and repaint, maintain in good condition, repair beam connection each end.
		LAT-10	Tank 18 Lateral		Corrosion at beam to wall, severe corrosion at column baseplate, flange loss and corrosion at JP-5.	Long	Clean corrosion and repaint, maintain in good condition, repair connections beam to wall.
	Table E1		RHTF		Corrosion at beam flanges, loss of flange metal, grout at walkway column chipped away. API 570: The pipe is partially in contact with the pipe support.	Long	Clean corrosion and repaint, maintain in good condition, replace grout pad. API 570: Add shims to support to gain contact.
	Table E1		RHTF		Overall good. API 570: Shimmed with Teflon pads.	Other	None. API 570: None.

Condition Notes  Court at well column broken and displaced, beam at well corroded (beyond column).  Painted flange damage at red pipe, moderate corrosion at wall column, grout cracked and missing.  Painted flange damage at red pipe, moderate corrosion at wall column, grout cracked and missing.  API 570: Missing one nut at concrete footing. Broken grouting.  Saddle damaged only (1) side, grout removed from elevator column baseplate, space between wall column baseplate and grout pad.  API 570: Metal to metal contact. No Teflon shims/insulation strip. Pulled anchor stud at concrete footing. Broken grouting.  No Saddle.  API 570: Metal to metal contact. No Teflon shims/insulation strip and wood.  Overall good.  API 570: Pipe is resting on Lebeam with Teflon shims/insulation strip and wood.  Overall good.  API 570: Pipe is resting on Lebeam with no saddle or Teflon shims/insulation strip.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ copped baseplate.  API 570: Pipe is resting on Lebeam with ninon gaps.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ copped baseplate.  API 570: Pipe is glaced from support beam with 15" Unistrut support placed underneath.  No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown long member-column interface.  No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown long has be made to the fine general at pipe corrosion at beam to wall (beyond column) and long.					Tab	Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations		
Table E1 LAT-5 RHTF Control at wall column broken and displaced, beam at wall corroded (beyond column). Long Table E1 LAT-5 RHTF Control flange damage at red pipe, moderate corrosion at wall column, grout cracked Long API 570. Missing one nut at concrete footing, Broken grouting, API 570. Missing one nut at concrete footing, Broken grouting, API 570. Missing one nut at concrete footing, Broken grouting, Broken grouting, API 570. Missing one nut at concrete footing, Broken grouting, Broken grouting, API 570. Missing one nut at concrete footing, Broken grouting, Broken grouting, API 570. Missing one nut at concrete footing, Broken grouting, API 570. Pipe is resting on i-beam with Teflon shims/insulation strip. Pulled anchor stud at concrete footing, Broken grouting, API 570. Pipe is resting on i-beam with Teflon shims/insulation strip and wood.  Table E1 LAT-5 RHTF Coverall good.  API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam with no saddle or Teflon shims/insulation strip. Long API 570. Pipe is resting on i-beam at order or Teflon shims/insulation strip. Long API	Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Table E1 LAT-5 RHTF API STO: Missing one nut at concrete footing. Broken grouting.  API STO: Missing one nut at concrete footing. Broken grouting.  Saddle damaged only (1) side, grout removed from elevator column baseplate, space between wall column baseplate and grout pad.  LAT-5 Table E1 LAT-5 RHTF API STO: Pipe is resting on beam with Teflon shims/insulation strip. Pulled anchor stud at concrete footing. Broken grouting.  Overall good.  Table E1 LAT-5 RHTF Overall good.  API STO: Pipe is resting on beam with Teflon shims/insulation strip and wood.  Overall good.  API STO: Pipe is resting on beam with Teflon shims/insulation strip and wood.  Overall good.  API STO: Pipe is resting on beam with 1 strip and wood.  API STO: Pipe is resting on beam with 1 strip and wood.  API STO: Rest is displaced from support beam with 1 strip strip strip and wood.  API STO: Rest is displaced from support beam with 1 strip strip and wood.  API STO: Rest is displaced from support placed with minor gaps.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ API STO: Rest is displaced from support beam with 1 strip strip stoport placed underly stoport placed and sepalate.  API STO: Rest is displaced from support beam with 1 strip stoport placed underly strip and wood at unknown long at unknown long and strip strip support placed underly strip support placed underly member-clumn interface.	(b) (3) (a	Table E1	LAT-5	RHTF	(b) (3) (A	Grout at wall column broken and displaced, beam at wall corroded (beyond column). API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition, repair connections beam to wall. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and L'Beam structure at all pipe support locations.
Saddle damaged only (1) side, grout removed fron elevator column baseplate, space between wall column baseplate and grout pad.  LAT-5  LAT-5  RHTF AP1570: Metal to metal contact. No Teflon shims/insulation strip. Pulled anchor stud at concrete footing. Broken grouting.  LAT-5  RHTF AP1570: Pipe is resting on Lebam with Teflon shims/insulation strip and wood.  LAT-5  RHTF Overall good.  AP1570: Pipe is resting on Lebam with no saddle or Teflon shims/insulation strip.  Coverall good.  AP1570: Pipe is resting on Lebam with no saddle or Teflon shims/insulation strip.  Coverall good.  AP1570: Pipe is resting on Lebam with no saddle or Teflon shims/insulation strip.  Coverall good.  AP1570: Pipe is resting on Lebam with no saddle or Teflon shims/insulation strip.  Coverall good.  AP1570: Pipe is resting on Lebam with no saddle or Teflon shims/insulation strip.  Coverall good.  AP1570: Pipe is resting on Lebam with no saddle corroded w/ exposed baseplate.  AP1570: Not in contact with saddle with minor gaps.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ exposed baseplate.  AP1570: Saddle goot damage and corrosion at tunnel-side column, corrosion at unknown constant at unknown long.  Tank 19  No saddle, top flange damage at pipe corrosion at tunnel-side column) and laber-oolumn) and strunded samage at pipe corrosion at tunnel-side column) and laber-oolumn) and strunded samage at pipe corrosion at tunnel-side column) and laber-oolumn at tunnel-side column at unknown laber-oolumn at tunnel-side column at unknown laber-oolumn at tunnel-side column at unknown l	A)	Table E1	LAT-5	RHTF	<b>v)</b>	Painted flange damage at red pipe, moderate corrosion at wall column, grout cracked and missing.  API 570: Missing one nut at concrete footing. Broken grouting.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Replace missing nut and re-grout.
No Saddle.  LAT-5 RHTF Overall good.  LAT-5 RHTF Overall good.  LAT-5 RHTF Overall good.  LAT-5 RHTF Overall good.  API 570: Pipe is resting on Lebam with Teflon shims/insulation strip and wood.  Overall good.  API 570: Pipe is resting on Lebam with no saddle or Teflon shims/insulation strip.  Minor are as of corrosion at paint damage, column at Tank 19 side corroded w/ exposed baseplate.  API 570: Not in contact with saddle with minor gaps.  Minor are as of corrosion at paint damage, column at Tank 19 side corroded w/ exposed baseplate.  API 570: Not in contact with saddle with minor gaps.  Minor are as of corrosion at paint damage, column at Tank 19 side corroded w/ exposed baseplate.  API 570: Not in contact with saddle with minor gaps.  Minor are as of corrosion at paint damage, column at Tank 19 side corroded w/ exposed baseplate.  API 570: Soddle is displaced from support beam with 1 5" Unistrut support placed undermeath.  No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown Lateral  No saddle, grout damage at pipe corrosion at beam to wall (beyond column) and Lateral  No saddle, from the properties of the prope		Table E1	LAT-5 LAT-8 LAT-55	RHTF		Saddle damaged only (1) side, grout removed from elevator column baseplate, space between wall column baseplate and grout pad. API 570: Metal to metal contact. No Teflon shims/insulation strip. Pulled anchor stud at concrete footing. Broken grouting.	Long	Gean corrosion and repaint, maintain in good condition, replace grout pad. API 570: Install support with insulation or half-round Teflon strip. Re-secure anchor stud and re-grout.  Note: The repair to replace deformed anchor bolt at this support is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
LAT-5 RHTF Overall good.  Overall good.  Overall good.  API 570: Pipe is resting on I-beam with no saddle or Teflon shims/insulation strip.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ exposed baseplate.  API 570: Not in contact with saddle with minor gaps.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ exposed baseplate.  API 570: Not in contact with saddle with minor gaps.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ exposed baseplate.  API 570: Saddle is displaced from support beam with 1 5" Unistrut support placed underneath.  No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown member-column interface.  No saddle, grout damage at pipe corrosion at beam to wall (beyond column) and tong strungle side tong saddle, spot flange damage at pipe corrosion at beam to wall (beyond column) and tong strungle side tong saddle, spot flange damage at pipe corrosion at beam to wall (beyond column) and tong saddle, spot flange damage at pipe corrosion at beam to wall (beyond column) and tong saddle, spot flange damage at pipe corrosion at beam to wall (beyond column) and tong saddle, spot flange saddle, spot flange damage at pipe corrosion at beam to wall (beyond column) and saddle, spot flange saddle, spot saddle, spot flange saddle, spot saddle, sp		Table E1	LAT-5 LAT-6 LAT-7	RHTF		No Saddle. API 570: Pipe is resting on L-beam with Teflon shims/insulation strip and wood.	Long	Add saddle. API 570: Remove wood shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure at all pipe support locations.  Note: The repair to replace grout and anchor bolt at this support is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
RHTF API 570: Pipe is resting on L-beam with no saddle or Teflon shims/insulation strip.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ corposed baseplate.  API 570: Not in contact with saddle with minor gaps.  Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/ corposed baseplate.  API 570: Saddle is displaced from support beam with 15" Unistrut support placed underneath.  No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown member-column interface.  Tank 19 No saddle, top flange damage at pipe corrosion at beam to wall (beyond column) and Long at tunnel side top.	en en en en		LAT-5	RHTF		Overall good.	Other	None.
RHTF exposed baseplate.  API 570: Not in contact with saddle with minor gaps.  Minor are as of corrosion at paint damage, column at Tank 19 side corroded w/  Minor are as of corrosion at paint damage, column at Tank 19 side corroded w/  exposed baseplate.  API 570: Saddle is displaced from support beam with 15" Unistrut support placed underneath.  No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown ton saddle, grout damage and corrosion at beam to wall (beyond column) and the saddle, spot flange damage at pipe corrosion at beam to wall (beyond column) and tong tanks at tunnel side ton.		Table E1	LAT-5	RHTF		Overall good. API 570: Pipe is resting on I-beam with no saddle or Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
RHTF exposed baseplate.  API 570: Saddle is displaced from support beam with 15" Unistrut support placed underneath.  Tank 19 Mo saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown Lateral member-column interface.  Tank 19 No saddle, top flange damage at pipe corrosion at beam to wall (beyond column) and Long Long Lateral	,	Table E1		RHTF		Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/exposed baseplate. API 570: Not in contact with saddle with minor gaps.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure at all pipe support locations.
No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown Long member-column interface.  No saddle, top flange damage at pipe corrosion at beam to wall (beyond column) and Long at tunnel cide ton	· · · · · · · · · · · · · · · · · · ·	Table E1		RHTF		Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/exposed baseplate. API 570: Saddle is displaced from support beam with 15" Unistrut support placed underneath.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Remove Unistrut and reposition saddle.
No saddle, top flange damage at pipe corrosion at beam to wall (beyond column) and				Tank 19 Lateral	~ .	No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown member-column interface.	Long	Gean corrosion and repaint, maintain in good condition.
at tulliel side top.				Tank 19 Lateral		No saddle, top flange damage at pipe corrosion at beam to wall (beyond column) and at tunnel side top.	Long	Clean corrosion and repaint, maintain in good condition, replace beam-wall connection.

_
OR
4
-
v
0
ч.
RE
~
4
_
>
-
9
$\overline{}$
_
( )
~
INSPE
$\sim$
-
S
~
<
_
_
2
2
EN
TEN
STEN
STEN
YSTEN
SYSTEN
SYSTEN
SYSTEN
R SYSTEN
ER SYSTEN
ER SYSTEN
FER SYSTEN
SFER SYSTEN
ISFER SYSTEN
<b>NSFER SYSTEN</b>
INSFER SYSTEN
<b>ANSFER SYSTEN</b>
<b><i>PANSFER SYSTEM</i></b>
RANSFER SYSTEN
TRANSFER SYSTEN
TRANSFER
TRANSFER
TRANSFER
JEL TRANSFER SYSTEN

	Recommended Repairs	Add saddle.	None.	Replace column and beam to wall connection, clean corrosion and repaint with high zinc paint, maintain in good condition.
	Urgency	Long	Other	Long
Table 17 - Frame Pipe Supports - F-24/JP-5 Pipe Support Findings and Recommendations	Condition Notes	No saddle.	Severely deteriorated.	Corrosion at wall-beam interface beyond column, severe corrosion and loss of flange at baseplate corrosion on beam.
Tak	Geographic Pipe Support Area No.	(b) (	3) (4	<del>(</del> )
	Geographic Area	Tank 20 Lateral	Tank 20 Lateral	Tank 20 Lateral
	SGH Report Cross Reference			LAT-1 LAT-2
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)			
	tem No.	o) (3	) (A	)

-
n -
ш
=
STE
SIE
YSTE
SYSTE
SYSTE
SYSTE
R SYSTE
R SYSTE
ER SYSTE
FER SYSTE
SFER SYSTE
SFER SYSTE
<b>VSFER SYSTE</b>
NSFER SYSTE
ANSFER SYSTE
ANSFER SYSTE
RANSFER SYSTE
RANSFER SYSTE
TRANSFER SYSTE
TRANSFER SYSTE
LTRAN
LTRAN
LTRAN
LTRAN
UEL TRANSFER SYSTE

	3					
5 E	3					
-	Report	Geographic	Pipe Support	Condition Notes	Urgency	Recommended Repairs
(Interspec, LLC)	Reference	ē Ē	e 1			
		UGPH	b)	Grout pad cracked and exposing baseplate.	Long	Repair grout pad and maintain in good condition.
(3)		NGPH	(3	No grout layer.	Long	Repair grout pad and maintain in good condition.
(		UGPH	3) (	Grout chipped, baseplate displaced (no anchorage except for grout surround).	Long	Repair grout pad and maintain in good condition.
A)		UGPH	(A	Chipped concrete pier.	Other	None.
		UGPH	)	Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Grout chipped.	Long	Repair grout pad and maintain in good condition.
		UGPH		Pier minor chipping, minor corrosion at baseplate.	Long	Clean corrosion and repaint, maintain in good condition.
		UGPH		Overall good.	Other	None.
		UGPH		Grout pad chipped and missing.	Long	Repair grout pad and maintain in good condition.
		UGPH		Overall good.	Other	None.
		UGPH	. 72	Minor corrosion at base of column.	Long	Clean corrosion and repaint, maintain in good condition.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Unpainted, no grout base, corrosion at baseplate and bottom half of X.	Long	Clean corrosion and repaint, maintain in good condition.
		UGPH		Covered in oil.	Other	None.
		UGPH	X	Grout cracked apart, baseplate displaced.	Long	Repair grout pad and maintain in good condition.
		UGPH		Painted, no grout, circular baseplate corroded.	Long	Repair grout pad and maintain in good condition.
		UGPH		Grout broken out at front.	Long	Repair grout pad and maintain in good condition.
		UGPH		Overall good.	Other	None.
		UGPH		Painted top, no grout, circular baseplate corroded.	Long	Repair grout pad and maintain in good condition.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Painted top, no grout, circular baseplate corroded.	Long	Repair grout pad and maintain in good condition.
		UGPH	VI. 15	Minor cracking to grout base.	Long	Repair grout pad and maintain in good condition.
		UGPH		Pier doesn't span trench, covered in oil.	Other	None.
		UGPH		Loss of support under baseplate at sleeper between	Long	Modify support to adequately support pipe without need
				shimmed w/ wood scrap.	0	for shim.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Cut for flange, corrosion at saddle.	Long	Clean corrosion and repaint, maintain in good condition.
		UGPH		Minor pier cracking.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		NGPH		Overall good.	Other	None.
		NGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.

Appendix 'F' - Pipe Support Assessment

L	ı
OR	l
EP	ı
N N	ı
0	ı
5	ı
SPE	ı
2	ı
2	ı
STE	ı
5	ı
ER	ı
ISF	ı
A	ı
F	ı
Æ	l
F	l

				table to condend to produce the support minings and recommendations		
Appendix C – API	HDS					
Cross Poforons	Report	Geographic	Pipe Support	Condition Motor	Indone	Decommended Densire
Deficiency	Cross	Area	No.	COLUMN I NOCES	Olgency	Neconille Inchairs
(InterSpec, LLC)	Kererence					
		NGPH	(b)	Overhangs the trench.	Other	None.
		UGPH	) (	Overall good.	Other	None.
		UGPH	3)	Overall good.	Other	None.
		UGPH	(A	Overall good.	Other	None.
		UGPH	۱)	Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		NGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH	_	Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		NGPH		Overall good.	Other	None.
		UGPH	_	Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH		Overall good.	Other	None.
		NGPH		Minor concrete chips.	Other	None.
		NGPH		Overall good.	Other	None.
		NGPH		Poorly consolidated concrete at base.	Other	None.
		UGPH		Overall good.	Other	None.
		NGPH		Poorly consolidated concrete at base, minor concrete chips.	Other	None.
		UGPH		Overall good.	Other	None.
		UGPH	=	Overall good.	Other	None.
		ПСВН		Wood shim under JP 5.	Long	Modify support to adequately support pipe without need for shim.
		Hdbn		Pier shared w/ grating support column, no baseplate at grating support column, angle	Other	None.

_
ò
_
REPO
0
w
~
_
NOL
=
9
INSPEC
⇄
:-
S
<
_
-
2
ш
Н
S
ς.
S
-"
8
ш
щ
S
>
=
ч
3
_
_
wi
Z
_

ttern No. Cross Reference Cross Area Deficiency (InterSpec, LLC) Reference Cross Area Deficiency (InterSpec, LLC) Reference UGPH UGPH UGPH UGPH UGPH UGPH UGPH UGPH	Pipe Support No. (p) (2) (q)	Overall good.  Missing (1) anchor bolt and nut. Chipping at pier under baseplate. Chipping at pier under baseplate, shared pier w/ grating column. Chipping at pier. Chipping at pier. Chipping at pier. Corrosion at plates. Top channel bottom flange cut for pipe clearance. Top channel bottom flange cut for pipe clearance. Overall good. Shared pier w/ Corrosion at plates. Overall good. In anchor bolt. Corrosion at plates. Overall good. In anchor bolt.	>	Recommended Repairs  None.  Clean corrosion and repaint, maintain in good condition.  Install anchor bolt and nut.  None.  None.
		Minor corrosion at all bearing plates.  Missing (1) anchor bolt and nut. Chipping at pier under baseplate, shared pier w/ grating column. Chipping at pier under baseplate, shared pier w/ grating column. Chipping at pier. Corrosion at plates. Top channel bottom flange cut for pipe clearance. Top channel bottom flange cut for pipe clearance. Overall good. Overall good. Overall good. Overall good. Overall good. In anchor bolt. Overall good. Overall good. In anchor for F24 flange each side.		None.  Clean corrosion and repaint, maintain in good condition.  Install anchor bolt and nut.  None.  Clean corrosion and repaint, maintain in good condition.  None.  Clean corrosion and repaint, maintain in good condition.  None.  None.  None.  None.  None.  None.
		Minor corrosion at all bearing plates.  Missing (1) anchor bolt and nut.  Chipping at pier under baseplate.  Chipping at pier under baseplate, shared pier w/ grating column.  Chipping at pier.  Corrosion at plates.  Top channel bottom flange cut for pipe clearance.  Top channel bottom flange cut for pipe clearance.  Overall good.  Charles od.  Corrosion at plates.  Corrosion at plates.  An on anchor bolt.  Corrosion at plates.  Corrosion at plates.  Overall good.  Interior column flange cut for F24 flange each side.		Clean corrosion and repaint, maintain in good condition. Install anchor bolt and nut. None.
		Missing (1) anchor bolt and nut. Chipping at pier under baseplate. Chipping at pier under baseplate, shared pier w/ grating column. Chipping at pier. Corrosion at plates. Top channel bottom flange cut for pipe clearance. Top channel bottom flange cut for pipe clearance. Overall good. Shared pier w/ Corrosion at plates. Corrosion at plates. In an anchor bolt. Corrosion at plates. Interior column flange cut for F24 flange each side.		Install anchor bolt and nut.  None.  Install anchor bolt and nut.  Clean corrosion and repaint, maintain in good condition.  None.  None.  None.  None.  None.  None.
		Chipping at pier under baseplate. Chipping at pier under baseplate, shared pier w/ grating column. Chipping at pier. Corrosion at plates. Top channel bottom flange cut for pipe clearance. Top channel bottom flange cut for pipe clearance. Overall good. Shared pier w/ Corrosion at plates. Corrosion at plates. Overall good. Interior column flange cut for F24 flange each side.		None.  None.  None.  Clean corrosion and repaint, maintain in good condition.  None.  None.  None.  None.  Clean corrosion and repaint, maintain in good condition.  None.  None.  None.  None.  None.  None.
		Chipping at pier under baseplate, shared pier w/ grating column.  Chipping at pier.  Corrosion at plates.  Top channel bottom flange cut for pipe clearance.  Top channel bottom flange cut for pipe clearance.  Overall good.  Corrosion at plates.  Corrosion at plates.  Overall good.  Interior column flange cut for F24 flange each side.		None.  Clean corrosion and repaint, maintain in good condition.  Clean corrosion and repaint, maintain in good condition.  None.  None.  Install anchor bolt and nut.  Clean corrosion and repaint, maintain in good condition.  None.  None.
Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90		Chipping at pier.  Corrosion at plates.  Top channel bottom flange cut for pipe clearance.  Top channel bottom flange cut for pipe clearance.  Overall good.  Corrosion at plates.  Overall good.  In an onchor bolt.  In an onchor bolt.  In an onchor file file file file file file file file		None.  Clean corrosion and repaint, maintain in good condition.  None.  None.  Install anchor bolt and nut.  Clean corrosion and repaint, maintain in good condition.  None.  None.  Clean corrosion and repaint, maintain in good condition.
Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90		Corrosion at plates.  Top channel bottom flange cut for pipe clearance.  Top channel bottom flange cut for pipe clearance.  Overall good.  Shared pier w/ , no anchor bolt.  Overall good.  Overall good.  Interior column flange cut for F24 flange each side.		Clean corrosion and repaint, maintain in good condition.  None.  None.  Install anchor bolt and nut.  Clean corrosion and repaint, maintain in good condition.  None.  None.  Clean corrosion and repaint, maintain in good condition.
Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90		Top channel bottom flange cut for pipe clearance.  Top channel bottom flange cut for pipe clearance.  Overall good.  Shared pier w/, no anchor bolt.  Overall good.  Overall good.  Interior column flange cut for F24 flange each side.		None.  None.  None.  Install anchor bolt and nut. Clean corrosion and repaint, maintain in good condition.  None.  Clean corrosion and repaint, maintain in good condition.
Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90		Top channel bottom flange cut for pipe clearance.  Overall good.  Shared pier w, no anchor bolt.  Corrosion at plates.  Overall good.  Interior column flange cut for F24 flange each side.		None.  None. Install anchor bolt and nut. Clean corrosion and repaint, maintain in good condition. None. Clean corrosion and repaint, maintain in good condition.
Hd90 Hd90 Hd90 Hd90 Hd90 Hd90 Hd90		Overall good.  Overall good. Shared pier w/, no anchor bolt.  Corrosion at plates.  Overall good. Interior column flange cut for F24 flange each side.		None.  None. Install anchor bolt and nut. Clean corrosion and repaint, maintain in good condition. None. None. None. None.
Hd90 Hd90 Hd90 Hd90 Hd90		Overall good. Shared pier w/, no anchor bolt. Corrosion at plates. Overall good. Interior column flange cut for F24 flange each side.		None.  Install anchor bolt and nut.  Clean corrosion and repaint, maintain in good condition.  None.  None.  None.  None.
Hd50 Hd50 Hd50 Hd50 Hd50		Shared pier w/ , no anchor bolt.  Corrosion at plates.  Overall good.  Interior column flange cut for F24 flange each side.		Install anchor bolt and nut. Clean corrosion and repaint, maintain in good condition. None. None. None. None. None.
Hd50 Hd50 Hd50 Hd50		Corrosion at plates.  Overall good. Interior column flange cut for F24 flange each side.		Clean corrosion and repaint, maintain in good condition.  None.  None.  Clean corrosion and repaint, maintain in good condition.  None.
Hd50 Hd50 Hd50 Hd50		Overall good. Interior column flange cut for F24 flange each side.		None.  None. Clean corrosion and repaint, maintain in good condition. None.
Hd90 Hd90 Hd90		Interior column flange cut for F24 flange each side.		None. Clean corrosion and repaint, maintain in good condition. None.
HdDU HdDU				Clean corrosion and repaint, maintain in good condition. None.
HdDU HqDU		Moderate corrosion at baseplate .	Long	None.
Hdbu		Overall good.	30	
Hdbn		Pier chipping at baseplate.	Other N	None.
		Baseplate corroded.	Long	Clean corrosion and repaint, maintain in good condition.
NGPH		Overall good.	1	None.
пды		Overall good.	Other	None.
ПСРН		Moderate corrosion at plate under saddle.	Long	Clean corrosion and repaint, maintain in good condition.
пды		Overall good.	Other	None.
ПGРН		Overall good.	Other	None.
NGPH		Separate pier under each baseplate, pier straddles trench.	Other	None.
NGPH		Overall good.		None.
NGPH		Overall good.		None.
UGPH		No grout pad.	Long	Repair grout pad and maintain in good condition.
NGPH		Overall good.		None.
NGPH		Overall good.	78 AS	None.
NGPH		Overall good.	Other	None.
NGPH		Overall good.	8.3	None.
UGPH		Overall good.	Sal I	None.
п		Overall good.	Other	None.
UGPH		Overall good.	Other	None.
NGPH	/s - v	Overall good.	8.3	None.
NGPH		Overall good.	5.5	None.
NGPH		Overall good.	. "	None.
NGPH		Overall good.		None.
NGPH		Overall good.	Other	None.

	ı
-	ı
œ	ı
0	ı
Б	ı
ш	ı
Œ	ı
2	ı
0	ı
2	ı
6	ı
ŭ,	ı
٩	ı
S	ı
5	ı
-	ı
2	ı
ш	ı
S	ı
Σ.	ı
S	ı
œ	ı
ш	ı
3	ı
š	ı
9	ı
2	ı
-	ı
-	ı
Æ	ı
2	ı
-	ı

	Recommended Repairs	None.	None.	None.	None.	None.	
	Urgency	Other	Other	Other	Other	Other	
Table 18 - Underground Pumphouse Pipe Support Findings and Recommendations	Condition Notes	Overall good.					
	Pipe Support No.	) (:	3)	(A	<b>(</b> )		
	Geographic Area	UGPH	UGPH	UGPH	UGPH	UGPH	
	SGH Report Cross Reference						
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	500 CO					
	em No.	) (c	(3	) (	A)		

ь	
9	
INSPECTION REPORT	
ο,	
۳	
-	
2	
0	
⊏	
U	
Ų	
9	
š	
S	
-	
Ш	
STE	
YSTE	
SYSTEM	
٥-	
٥-	
٥-	
٥-	
٥-	
٥-	
TRANSFER	
TRANSFER	
٥-	

e plumb. upport						Table 19 - Surge Tank Pipe Support Findings and Recommendations		
Table E2  Surge Tank  Overall good.  Minor loss of grout under baseplate.  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bobts knocked crocked.  Description assessment.  Doverall good.  Description assessment.  Doverall good.  Surge Tank  Overall good.  Doverall good.  Almor loss of grout and support anchors exposed, anchor bobts knocked crocked.  Doverall good.	tem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Surge Tank Overall good. Surge Tank Overall good. Surge Tank Surge Tank Overall good. Surge Tank Overall good. Surge Tank Overall good.	(b) (3) (A	Table E2		Surge Tank	(b) (3) (A	No tefion pads visible, concrete at junction between API 570: No wear plate or Tefion provided after repairs	Long	Provide teflon pad. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
Surge Tank	.)			Surge Tank	.)	Overall good.	Other	None.
Surge Tank Overall good.  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		Could not access for condition assessment.	Other	None.
Surge Tank Overall good.  Corroded baseplates but overall good.  Corroded baseplates but overall good.	0		-0	Surge Tank		part of concrete is broken through and chipped under saddle.	Long	Repair concrete and maintain in good condtion.
Surge Tank Overall good.  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		part of concrete is chipped.	Other	None.
Surge Tank Overall good. Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		Overall good.	Other	None.
Surge Tank Overall good. Overall good.  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		part of concrete is cracked but overall good.	Other	None.
Surge Tank Overall good.  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		part of concrete is cracked but overall good.	Other	None.
Surge Tank Overall good. Surge Tank Surge Tank Surge Tank Surge Tank Overall good. Overall good. Surge Tank Surge Tank Surge Tank Overall good. Overall good. Overall good.  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		Grout loss under baseplates, not all nuts are tightened, not all anchors are plumb.	Long	Replace grout pad and maintain in good condtion.
Surge Tank Overall good. Surge Tank Surge Tank Overall good.  Surge Tank Surge Tank Overall good.  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		Concrete over baseplate cracked, baseplate not displaced.	Long	Repair concrete and maintain in good condtion.
Surge Tank Overall good.  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		Sleeper broken in half at edge of saddle baseplate and displaced, loss of support under baseplate.	Long	Repair concrete, replace grout pad, and maintain in good condtion.
Surge Tank  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.				Surge Tank		Sleeper broken in half at edge of saddle baseplate and displaced, loss of support under baseplate.	Long	Repair concrete, replace grout pad, and maintain in good condition.
Surge Tank  Overall good.				Surge Tank		Overall good.	Other	None.
Surge Tank  Surge Tank  Surge Tank  Surge Tank  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.  Overall good.				Surge Tank		Minor loss of grout under baseplate.	Long	Replace grout pad and maintain in good condtion.
Surge Tank  Surge Tank  Corroded baseplates but overall good.  Loss of grout and support anchors exposed, anchor bolts knocked crocked.  Overall good.				Surge Tank		Overall good.	Other	None.
Surge Tank  Loss of grout and support anchors exposed, anchor bolts knocked crocked.  Surge Tank  Overall good.				Surge Tank		Corroded baseplates but overall good.	Long	Clean corrosion and repaint, maintain in good condition.
Overall good.		D2		Surge Tank		Loss of grout and support anchors exposed, anchor bolts knocked crocked.	Long	Replace grout pad and anchor bolts and maintain in good condtion.
	d)			Surge Tank		Overall good.	Other	None.



## APPENDIX 'G' – SORTED TABLES – FINDINGS AND RECOMMENDATIONS (BY URGENCY)

	Recommended Repairs	Provide threaded caps on tank sample piping downstream of isolation valves.  NOTE: This deficiency has been corrected for the tanks that have been	Pressure y memory, inspection, and repaired.  Replace value with a Clace 150 hall value		Provide threaded plug on ball valve drain.	Replace valve with a Class 150 ball valve.	Long term consideration should be given to replacing the threaded valve and piping with welded pipe and flanged ball valve.	Tighten fasteners per manufacturers or designer of record specifications.	Replace hardware to ensure fasteners are fully engaged (nuts are fully engaged with threaded bolts).	Disassemble threaded connections, retape, and reassemble to prevent future weeps. Replace valves with Class 150 carbon steel ball valves.	Long term consideration should be given to replacing the high point vent piping and valves with welded pipe with flanged connections.	Replace low point drains with Class 150 carbon steel ball valves, replace corroded piping, and recoat affected areas.	Long term consideration should be given to replacing the low point drain piping and valves with welded pipe with flanged connections.
	Urgency	Urgent		Urgent	Urgent		Urgent	Urgent	Urgent		nigent		Urgent
Table 7 (Sorted) - F-24 Findings and Recommendations	Description	Tank sample piping downstream of the isolation valves are open to the atmosphere. If the isolation valves were to be bumped or inadvertently forced open, this could lead to an accidental fuel spill.		Brass/bronze valve flow melting point) attached to the blind flange of the	The DBB valves are equipped with a drain valve in lieu of a plug.  The end of the valves is not secured with a pipe plug.  Tank 2 — On the valves is not secured with a pipe plug.  Tank 3 — On the valves is not secured with a pipe plug.  Tank 4 — On the valves is not secured with a drain valve in the valves is not secured with a plug.		nreaged / carbon steel low point drain valve is located on pipeline. Valve classification is unknown.	Two loose joint harness fasteners were noted on the Dresser coupling on the	3 welded and flanged branch connection on top of the pipeline. Six of the flange fasteners are not fully engaged.	There are two high point vents on the between the UGPH concrete bulkhead and the	vicinity or varye 0.15.1 that are constituted or tiffeaded varyes, nipples, and piping. Staining and weeping were noted around the threaded fittings. Valve classifications are unknown.	There are two low point drains on the pipeline between the UGPH concrete bulkhead and that are	constructed of threaded valves, nipples, and piping. Notable corrosion was observed on the LPD just before the bulkhead to the UGPH. Valve classifications are unknown.
	Location	(D) (C) () .				ı.				2		ì	
	Geographic Area	RHTF		RHTF	RHTF		кнтғ	RHTF	RHTF	Harbor	Tunnel	Harbor	Tunnel
	SGH Report Cross Reference												
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)			A1	A4		A12	A14	A16	10	à	87	B8
	Item No.	(b) (3) (	۹)										

-	
W	1
Ш	ı
W	ı
H	ı
巴	ı
H	ı
STE	I
YSTE	l
YSTE	l
SYSTE	l
SYSTE	l
SYSTE	١
R SYSTE	١
R SYSTE	١
R SYSTE	١
ER SYSTE	١
ER SYSTE	١
ER SYSTE	
ER SYSTE	
FER SYSTE	١
FER SYSTE	
FER SYSTE	
SFER SYSTE	
SFER SYSTE	
ISFER SYSTE	
<b>USFER SYSTE!</b>	
<b>VSFER SYSTE</b>	
NSFER SYSTE	
NSFER SYSTE	
NISFER SYSTE	
ANSFER SYSTE	
ANSFER SYSTE	
ANSFER SYSTE	
SANSFER SYSTE	
RANSFER SYSTE	
RANSFER SYSTE	
RANSFER SYSTE	
TRANSFER SYSTE	
TRANSFER SYSTE	
TRANSFER SYSTE	
TRANSFER SYSTE	
TRANSFER SYSTE	
L TRANSFER SYSTE	
L TRANSFER SYSTE	
L TRANSFER SYSTE	
EL TRANSFER SYSTE	
EL TRANSFER SYSTE	
IEL TRANSFER SYSTE	
JEL TRANSFER SYSTE	
UEL TRANSFER SYSTE	
UEL TRANSFER SYSTE	
UEL TRANSFER SYSTE	
FUEL TRANSFER SYSTE	
FUEL TRANSFER SYSTE	
FUEL TRANSFER SYSTE	
FUEL TRANSFER SYSTE	
FUEL TRANSFER SYSTE	

	Recommended Repairs	Replace fasteners that are not fully engaged per manufacturers recommendations.	Disassemble threaded connections, retape, and reassemble to prevent future weeps at the high point vent between 267 and 268. Replace all associated valves with Class 150 ball valves.  Long term consideration should be given to replacing threaded connections with welded and flanged connections.	Install appropriate threaded pipe plugs on tee fittings.
	Urgency	Urgent	Urgent	Urgent
Table 7 (Sorted) - F-24 Findings and Recommendations	Description	The 16 DBB valve was manufactured with four studs on the top and four studs on the bottom of the valve flanges where dearance to install a hexagonal bolt behind the flange is not possible. The threaded studs are not fully engaged at these locations. Engagement between 0.250 and 0.550 inches was observed with the valve flange.	Several HPVs and LPDs throughout the harbor tunnel. These are composed of threaded valves, piping, and components. Minor staining was noted on some of these fittings. Also, the valve classifications in several locations are unknown. Incations include:  1 threaded plug on top of pipe  1 threaded plug on top of pipe	Conduit plug is being used to plug tee fitting on pressure gauge assemblies.
	Location	(b) (3) (A)		
	Geographic Area	Harbor Tunnel	Harbor Tunnel	прен
	SGH Report Cross Reference			
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	B9	B18	C18
	Item No.	(b) (3) (A)		

Table 7 (Sorted) - F-24 Findings and Recommendations	Description Recommended Repairs	Fuel staining and weeping was noted on the pipe tie-ins associated with the temperature sensors, pressure sensors, high point vents, and low point drains. Weeping is present at threaded connections associated with these fittings. The following locations should addressed:  - PIT-301 and adjacent Temperature Sensor - Valve GI388 - Valve GI388 - Valve GI388 - Valve GI388 - Valve GI488 - Valve GI488 - Valve GI480 - Valve GI480 - Valve GI480 - Valve GI480	It was noted that several of the pressure transducers are past due for calibration of all temperature and pressure devices in the UGPH.	There is a 3/4 high point vent located on the piping piping terminates just before the UGPH sump and is lacking a threaded pipe plug.	There is a 3/4 — threaded valve mounted on the side of the provide plug or cap to prevent accidental discharge of product. Replace valve with Class 150 ball valve.  Urgent  Valve classification is unknown.	There was noticeable fuel drips and weeps coming from pressure relieving devices to prevent future weeps. If valves are relieving devices on the valve above the grating. (Cla Val relief devices)  Service pressure relieving devices to prevent future weeps. If valves are not serviceable, consideration should be given to replacement of these valves. Perform routine pressure testing/calibration of pressure relieving devices.	gate valves is missing a fastener. Urgent Install new fastener on valve flange.	with as of	Remove surface corrosion and recoat affected area. Consider replacing support with a saddle that is welded to the structural support and providine a Teflon pad between pipe and saddle.
Table 7 (Sorted) - F-2	Desc	Fuel staining and weeping was noted on the pipe tie-ins assoc with the temperature sensors, pressure sensors, high point ve and low point drains. Weeping is present at threaded connect associated with these fittings. The following locations should addressed:  - PIT-301 and adjacent Temperature Sensor - Valve G1388 - Valve G1388 - Valve G1388 - Valve G1388 - Valve G1488 - Valve G488 - Valve G488	It was noted that several of the pressure transduce for calibration. (Calibration due date of 10/23/18)	There is a 3/4 ingh point we pipeline downstream of terminates just before the UGPP pipe plug.	There is a 3/4 threaded value of the state is no possible. There is no possible. Note: It is not clear as to Valve classification is unknown.	There was noticeable fuel drips relieving devices on the valve ab devices)	Valve flange for the 12 gate	An area of inactive pitting (approximately 0.050 inches deep) some large area scaling was identified. An additional two are possible corrosion of similar magnitude of pitting are suspect under the pipe wrap at this location.	Coating failure and corrosion on
	Location	(b) (3) (A)		- 21	-	F-2-0	_	8 8 8	9
	Geographic Area	НСРН	ПСРН	Набо	ИВРН	Наби	ПСРН	Harbor Tunnel	RHTF
	SGH Report Cross Reference								
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	37	C41	C46	C47	C48 C54	C51	LRUT Results CML# B17	AS
	Item No.	(b) (3) (A)							

•	
5	
•	ı
	ı
	ı
3	ı
Š	ı
^	ı
~	ı
_	ı
_	ı
_	ı
3	
	ı
×	ı
11	ı
11	
11	
11	
11	
11	
11	
11	
11	
11	
11	
<b>IKANSFER</b>	
11	
11	
LIKANSFE	
LIKANSFE	
11	
LIKANSFE	
LIKANSFE	

				Table 7 (Sorted) - F-24 Findings and Recommendations		
Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	PI SGH Report Cross Cross ()	Geographic Area	Location	Description	Urgency	Recommended Repairs
A6		RHTF	(b) (3) (A	inspection of the pipe exterior. A dent was observed at the 7 o'clock position neal which could not be analyzed due to coating system.	Long	Remove thick coating system, inspect exterior of pipe, and recoat.
A9		RHTF	)	pipeline is not adequately supported, approximately 47 between , with a saddle missing at 46.	Long	Install saddle support a to properly support the pipeline.
A10		RHTF		pipeline has a metal shim between pipe and saddle support.	Long	Remove support and shim, realign support saddle/base to properly support the pipe, and provide Teflon pad between saddle support and pipeline.
A8	LAT-47	RHTF		pipeline is not adequately supported. Saddle is not engaged, wood shim is used, and saddle is not secured to I-beam support.	Long	Replace pipe support at this location with a suitable saddle of sufficient height to properly support the pipe and secure support to the Lbeam structure. Provide Teflon pad between saddle support and pipeline.
A11		RHTF		pipeline is unsupported between supports, approximately 58	Long	Shim the pipe or pipe supports to uniformly support the pipe.
A11		RHTF		pipeline is unsupported between supports. Support is partial engagement on one side of the pipeline.	Long	Shim the pipe or pipe supports to uniformly support the pipe.
A13		RHTF	F	Non-standard flanges and non-standard weld tie-ins at the crosstunnel pipeline tees.	Long	Consider upgrading to ASME B16.5 rated flanges and fittings with buttwelded arrangements at cross-tunnel pipeline connections.
A15		RHTF		Metal-to-metal contact between the pipeline and Unistrut support has caused coating failure and surface corrosion.	Long	Modify Unistrut support to eliminate metal-to-metal contact and spot repair coating system at the affected area.
B48 Table H		Harbor Tunnel		The pipeline is covered by a protective wrap throughout the Harbor Tunnel. Protective wrap is failing in numerous locations and prohibits external inspection of the piping condition.	Long	Remove protective pipe wrap and perform visual inspection of these sections of pipe for external corrosion.
B10 Table H	HT-1 HT-9 HT-16 HT-23 HT-24 HT-24 HT-37	Harbor Tunnel		Several areas of coating failure with minor to moderate corrosion was observed on the pipeline. See Table H in API 570 report for exact locations.	Long	Gean, prep and recoat affected areas.

					Table 7 (Sorted) - F-24 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	-	Urgency	Recommended Repairs
(b) (3) (A	B 81		Harbor Tunnel	(b) (3) (	Moderate coating failure and moderate corrosion on pipe, flanges, fasteners, and components on the pipe pipeline due to mineral deposits and water infiltrating through tunnel ceiling.	Long	Seal the tunnel or provide ceiling trays to prevent further deposits on the pipeline. Clean, prep, and recoat affected area.
4)	B15 Table F	HT-4 HT-18	Harbor Tunnel	A)	Several dents were present on the pipeline within the harbor tunnel. See Table F in API 570 report for exact locations.	Long	The assessment indicates dents are within acceptable limits per API 579 Section 12 Level 1 assessment. Monitor dent locations at next API 570 inspection.
	B50		Harbor Tunnel		There are several plates that are tack welded to the pipeline. These plates do not appear to serve a purpose.	Long	Remove tack welded plates/attachments, grind down, and perform additional NDE at these areas.
			ИВЬН		The gate valves within the piping systems inside the underground pumphouse are weeping and require continuous maintenance	Long	Remove the gate valves and install ball valves. It is recommended to program this valve replacement after defueling of RHTF is complete.
	63		на В		The ball valve on the strainer drains associated with the pump discharge control valves are not plugged.	Long	Provide threaded plugs to prevent accidental discharge of fuel product.
	C14		прен		The small isolation ball valves on the pump discharge control valve tubing are missing operating handles. This will prevent isolation in the event of an emergency such as a tubing break or damage to isolate the fuel leak.	Long	Provide operating handles on ball valves and consider a car-seal to lock valves in desired position.
	CLS		ньчи		Minor bearing oil staining was noted on pump casings.	Long	Perform routine cleaning and removal of bearing oil staining from pump casings.
	972	100	ПСРН		Moderate weeping/staining on front bearing shaft and casing of pump.	Long	Perform routine cleaning and removal of oil staining from pump casings.
	31		ПСРН		One loose joint harness fastener was noted on the Dresser coupling on the discharge side of Pump 209.	Long	Tighten fasteners per manufacturers or designer of record specifications.
	32		перн		Two loose joint harness fasteners were noted on the Dresser coupling on the discharge side of Pump 210.	Long	Tighten fasteners per manufacturers or designer of record specifications.
	<b>G3</b>		набо		Dresser coupling lugs on pump suction side are installed backwards.	Long	Repair dresser coupling lugs to be installed correctly.
	38		ИСРН		Several threaded fittings were noted throughout the UGPH piping below the grating on the main header piping. Some of the branch connections welds are not per industry standard (did not use Weldolet or other approved branch connections).	Long	Replace threaded fitting and pipe with welded connection and replace branch connections with industry approved connections.
	C40		ПСРН		Several transducers are attached to the piping and the conduits do not have seal off fittings. Additionally, the conduits are ridged which could break under pipe movement.	Long	Provide appropriate seal fittings and flexible conduit connections at transducers.

						Table 7 (Sorted) - F-24 Findings and Recommendations			
No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Loca	Location	-	Urgency	Recommended Repairs	
b) (3) (	C42		ОСРН		(b) (3)	There is staining and some minor drips noted on the Cameron ball valves throughout the UGPH. Drips appear to be coming from the stem injection port.	Long	Gean valve body, service stem $\operatorname{nut/upper}$ stem seal to prevent future weeps/drips.	
A)	C49		ИдРН		(A)	Mechanical dent was found on the person in the surge tank. Dent depth is 0.505 inches with perpendicular orientation and length of 5 inches located 58 inches perpendicular orientation and length of 5 inches located 58 inches from the miter weld before the surge tank-to-UGPH bulkhead penetration. This results in a dent depth of 3 2%. Assessment indicates this dent is acceptable based on latest edition of API RP 1183; Assessment and Management of Pipeline Dents. Plain dents regardless of shape with depths up to 10 % of the pipe diameter, without coincident features such as metal loss, welds, or cracks have been shown in testing to have the same failure pressure as plain line pipe (Section 1). Dent is also acceptable per API 579 section 12 Level 1 assessment (acceptable if it is 5 7% of the pipe diameter).	Long	Monitor at next API 570 Inspection.	
	C52		ИЗБИ	ш		It was also noted that there are no pressure relief devices installed on the header piping.	Long	Provide pressure relief devices to prevent an over pressurization of the header piping.	
	C53		ИСРН	6		All the gate valves on the suction and discharge side of the pumps are equipped with motorized valve actuators. It was observed that the motorized valve actuators are mounted on a stich welded adapter plate. Several of the stitch welds have hairline cracks present and could cause the adapter plate to shear off during actuator operation.	Long	Remove coating and perform further weld inspection.	
	CS6		ИЗБИ	ш		The pressure relief system has an Emerson Figure 533 flow control valve with hydramotor actuator. The hydramotor actuator still has the factory plastic caps installed in the unused conduit inlet ports.	Long	Remove plastic caps and provide threaded steel conduit plugs.	
	D1		UGPH			Several locations where the Teflon pad is missing between pipe and pipe support, creating metal-to-metal contact.	Long	Provide Teflon isolation pads to eliminate metal-to-metal contact between support and pipe.	
	D3		ИСРН			The 1 ball valve associated with the sample/water drain line that ties into the 4 low suction line was observed as open and not secured. This could create a potential for a fuel spill. Valve was closed during our inspection.	Long	Consider a self-closing/spring loaded ball valve to prevent the valve from being inadvertently left open which could cause an accidental fuel spill.	

8	
-	
E	

Table 7 (Sorted) - F-24 Findings and Recommendations	Description Urgency Recommended Repairs	Evaluation of Dresser couplings are installed in tank piping laterals.  Evaluation of Dresser couplings are installed in tank piping laterals.  Other Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".	A non-standard repair at the bulkhead between as noted. The repair is full encirclement welded split sleeve (clamshell) on 552 side and a partial patch plate style repair on side of the bulkhead with square corners.		
Table 7 (Sort		Dresser Couplings are in:	A non-standard repair at twas noted. The repair split sleeve (clamshell) on style repair or		
	Location	(b) (3) (A	)		
	Geographic Area	RHTF	Harbor Tunnel		
	SGH Report Cross Reference	PM-19 PM-20 PM-21 PM-22			
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)		B20		
	Item No.	(b) (3) (A)			

REPORT
NSPECTION
SYSTEM I
TRANSFER
FUEL

					Table 8 (Sorted) - F-24/JP-5 Pipe Support Findings and Recommendations	ndations	
ltem No.	Appendix C – API 570 Report – Cross Reference Defidency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3	B14 Table E2		Harbor Tunnel	(b) (3	Severely corroded base plate and bottom of column loss of steel in column, delamination of base plate, no grout pad connected to wall severely corroded.	Urgent	Replace support.
(A)	B14 Table E2		Harbor Tunnel	) (A)	Severe corrosion and loss of support at baseplate and lower column connection.	Urgent	Replace support, support on minimum 6" raised concrete pier.
			Harbor Tunnel		Extreme corrosion with no or very little material at any number of locations, active dripping.	Urgent	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-33	Harbor Tunnel		Corrosion to loss of support, wall anchors not visible.	Urgent	Replace support.
		НТ-32	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, complete deterioration through bottom front flange of both columns, extreme deterioration of anchor bolts over back flange of both columns.	Urgent	Replace support.
	Table E2	НТ-32	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, severe corrosion over entire support complete less of support at bottom of both columns and both flanges, delamination (severe) at baseplate, angles to wall severely deteriorated. API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
	Table E2		Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, wall anchor not visible, flanges at angle column not attached to baseplate, severe delamination at baseplate.  API 570: Support wear plate to support not engaged (JP-5) (floating pipe).	Urgent	Replace support.
		a a	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme corrosion at baseplate and column flanges, appears unattached and detached when sounded.	Urgent	Replace support.
	Table E2		Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme delamination at baseplate, columns not attached due to extreme deterioration, JP-5 bracket to the wall deteriorated and detached.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
			Harbor Tunnel		Severe corrosion w/ significant loss of material at any number of locations, column flange deformed	Urgent	Replace support.

	ı
	ı
_	ı
-	ı
-	ı
	ı
_	ı
О.	ı
Lea	ı
	ı
02	ı
	ı
	ı
	ı
	ı
	ı
-	ı
	ı
0	ı
LU1	ı
~	ı
-	ı
S	ı
	ı
<	ı
_	ı
-	ı
	ı
	ı
LL.	ı
	ı
1	ı
9	ı
_	ı
in	ı
٠,	ı
-	ı
-	ı
ш	ı
L.	ı
16	ı
~	ı
-	ı
	ı
4	ı
~	ı
-	ı
-	ı
257	ı
-	ı
LL1	ı
	ı
-	ı
L	ı
-	ı

	Recommended Repairs	Replace support.	Replace support.	Replace support.	Replace support.	Replace support.	Replace support.	Replace support.	Replace support.	Replace support.	Replace support.	Replace support. This repair is scheduled for completion.
ndations	Urgency	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent
Table 8 (Sorted) - F-24/JP-5 Pipe Support Findings and Recommendations	Description	Severe corrosion w/ significant loss of material at any number of locations, column flange deformed	Severe corrosion w/ significant loss of material at any number of locations, column flange deformed	Severe corrosion w/ significant loss of material at any number of locations, column flange deformed.	Severe corrosion w/ loss of material at any number of locations, grout pad broken, loss of bearing.	Extreme corrosion w/ no or very little material at any number of locations, JP-5 at wall.	Extreme corrosion w/ no or very little material at any number of locations, column flanges completely deteriorated at slab, baseplate is dust, IP-5 attachments to wall completed corroded not attached at (1) side.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Extreme corrosion w/ no or very little material at any number of locations, extreme corrosion at bottom of column and significant loss of column flange section at baseplate interface.	Extreme corrosion w/ no or very little material at any number of locations, column moderately corroded, JP-5 anchor to wall complete section loss.  API 570: Corrosion on pipe support at the tunnel wall attachment.	Extreme corrosion w/ no or very little material at any number of locations, moderate column corrosion, complete loss of section at JP-5 and anchor to wall on 1 side	Severe corrosion w/ loss of material at any number of locations, impacted and deformed column flanges.	Severe corrosion and loss of support at train-side column (photo), minor corrosion at center column baseplate, grout pad edges destroyed at center column baseplate (photo), severe corrosion and loss of material at beam near wall (photo) API 570: Metal to metal contact. No Teflon shims/insulation strip. Rail-ties wedged between pipe and saddle (F-24). Corrosion on base of pipe support and I-beam.
	Location	(b) (	3) (A	<b>(</b> )			V					
	Geographic Area	Harbor	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor	RHTF
3	SGH Report Cross Reference			100		2	HT-26 HT-28		HT-26	HT-26		LAT-41
	Appendix C – API 570 Report – Cross Reference Defidency (InterSpec, LLC)				5		Table E2		B32 Table E2			A7 A10 Table E1 Table E2
	ltem No.	(b) (	3) (A	.)								

		9
	Recommended Repairs	Urgent Replace support. This repair is scheduled for completion.
ndations	Urgency	200
Table 8 (Sorted) - F-24/JP-5 Pipe Support Findings and Recommendations	Description	Severe corrosion and loss of support at bottom of column, minor flange deformation at free end, corrosion at IP-5 saddle corrosion and loss of angle at lower angle support, no saddle at API 570. Metal to metal contact. No Teffon shims/insulation strip. Missing steel saddle (floating pipe)  Corrosion on base of pipe support and L-beam.
	Location	
	Geographic Area	RHTF
	SGH Report Cross Reference	LAT-38 LAT-40
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	A7 Table E1 Table E2
	Item No.	

Table 9 (Sorted) - JP-5 Findings and Recommendations	Description Urgency Recommended Repairs	Tank sample piping downstream of the isolation valve are open to the atmosphere. If the isolation valves were to be bumped or inadvertently forced open, this could lead to an accidental fuel spill.	HPV on Tank 16 jet fuel piping downstream of the isolation valve is missing a threaded plug. Some fuel was noted Urgent Provide threaded plug on high point vent.	The DBB valves are equipped with a drain valve in lieu of a plug.  The end of the valves is not secured with a pipe plug.  Tank 7—  Tank 8—  DBB  Tank 8—  DBB  Tank 9—  DBB  Tank 10—  DBB	Replace high point vent valve with Class 150 ball valve.	High point vent with threaded fittings and a brass (low melting boint) value on top of the 18 18 18 19-5 pipeline. Valve Urgent assembly with welded pipe and valve with flanged connections.	Note: This repair is currently programmed for repair as part of the FY21 Emergent Pipeline Repair Project.	One indication was observed approximately -460 inches from Urgent Remove pipe wrap and inspect the pipeline at these locations.	There are two low point drains on the 18 that are between the UGPH concrete bulkhead and that are constructed of threaded valves, nipples, and piping. There is evidence of tuel staining and weeping noted around the threaded fittings. Moderate cornsion was observed on low point drain piping adjacent to the USP pipe adjacent to isolation valve #0156. Valve classification is unknown.
Table		Tank sample pipi the atmosphere. inadvertently for spill.	HPV on Tank 16 jet fue isolation valve is missi inside the valve body.	ne DBB valves a ne end of the va - Tank 7 – - Tank 8 – - Tank 9 –		igh point vent voint) valve on to	dosinication is a	One indication w setup on the	There are two low between the UGP between the UGP constructed of thr evidence of fuel st fittings. Moderate piping adjacent to LPD pipe adjacent unknown.
32	Location	변 등 등 명 (b) (3) (A)	I	FF		Ξă	3	O as	F & & & & & & & & & & & & & & & & & & &
	Geographic Area	T THILL I	RHTF	RHTF		RHTF		Harbor Tunnel	Harbor Tunnel
6	SGH Report Ge Cross Reference						72	587	3
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)		A3	A4		A17		LRUT Results CML# B26	88 86
	ltem No.	(b) (3) (A)	Ì						

b	
Š	5
ü	ì
9	
ć	5
F	į
CHOS	í
ž	5
S	
2	
7	
D CVCTEN	1000
	1000
NCEED CVCTER	TO COLOR
NOFF	
NOFF	

					Table 9 (Sorted) - JP-5 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3) (A)	(A) (S) (A)		Harbor Tunnel	(b) (3) (A)	Several HPVs and LPDs throughout the harbor tunnel. These are composed of threaded valves, piping, and components. Minor staining was noted on some of these fittings. Also, the valve classifications in several locations are unknown.  - 1 high point vent   2 high poi	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps at the two high point vents between and the threaded plug between associated valves with Class 150 ball valves.  Long term consideration should be given to replacing threaded connections with welded and flanged connections.
	ව		пды	*	The ball valve on the strainer drains associated with the pump discharge control valves are not plugged.	Urgent	Provide threaded plugs to prevent accidental discharge of fuel product.
	C14		прен		The small isolation ball valves on the pump discharge control valve tubing are missing operating handles. This will prevent isolation in the event of an emergency such as a tubing break or damage to isolate the fuel leak.	Urgent	Provide operating handles on ball valves and consider a car-seal to lock valves in desired position.
	C18		UPGH		Conduit plug is being used to plug tee fitting on pressure gauge assemblies.	Urgent	Install appropriate threaded pipe plugs on tee fittings.
	37		ИСРН	Various	Fuel staining and weeping was noted on the pipe tie-ins associated with the temperature sensors, pressure sensors, high point vents, and low point drains. Weeping is present at threaded connections associated with these fittings.	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps.  Long term consideration should be given to replacing threaded connections with welded connections where possible.
	C40		ИСРН	Various	Several transducers are attached to the piping and the conduits do not have seal off fittings. Additionally, the conduits are ridged which could break under pipe movement.	Urgent	Provide appropriate seal fittings and flexible conduit connections at transducers.
	C41		псен	Various	It was noted that several of the pressure transducers are past due for calibration. (Calibration due date of 10/23/18)	Urgent	Perforn calibration of all temperature and pressure devices.

					Table 9 (Sorted) - JP-5 Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3	C42		набо	(b) (3	There is staining and some minor drips noted on the Cameron ball valves throughout the UGPH. Drips appear to be coming from the stem injection port.	Urgent	Clean valve body, service stem nut/upper stem seal to prevent future weeps/drips.
) (A)	C48 C54		ИЗВН	) (A)	There was noticeable fuel drips and weeps coming from pressure relieving devices on the valve above the grating. (Cla Val relief devices)	Urgent	Service pressure relieving devices to prevent future weeps. If valves are not serviceable, consideration should be given to replacement of these valves.
	C55		пред		4 gate valve is weeping at bonnet.	Urgent	Service valve to prevent future weeps. If valve cannot be serviced, consider for replacement.
	D7		ИВРН		The 1 ball valve that is mounted on the 4 low suction line at Surge Tank 2 is missing a plug.	Urgent	Install a plug to prevent accidental fuel release.
					nin		Product staining was noted at threaded connections. Urgent repair should be to disassemble threaded joints, clean, retape, and reassemble to prevent future weeps.
	F13		RHTF		installed with a 3/4 ball valve. Note: There is staining/werting on the lower threaded fitting. Location is between	Urgent	Long term consideration should be given to replacing high point vent assembly with welded pipe and valve with flanged connections.
							Note: This is programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
	Ē	DM.23	THO		The 18 dresser coupling joint harness has four lugs that are	Irgent	Correct positioning of the lugs in accordance with manufacturer's recommendation.
	1	C7.141			welded backwards on the upstream side of the coupling.	o Belli	Note: This is programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
	B52		Harbor Tunnel		A dent was observed at the bell joint. Due to location of anomaly's proximity to a weld this will not pass API 579 Section 12 Level 1 assessment. Measured depth of anomoly was 0.320 inches.	Urgent	Perform follow-on NDE examination of the weld at this location to validate if weld is acceptable for continued service.
	A20		RHTF		The 2 high point vent piping on the 18 P-5 pipeline is threaded and extends down below the pipe. Pipe extends into	Long	Replumb high point vent piping such that it does not extend into personnel movement space and is constructed of welded pipe and flanged components.
				20	personne movement space below and is at risk for possible damage from impact.	P. 1	Note: This repair is currently programmed for repair as part of the FY21 Emergent Pipeline Repair Project.

					Table 9 (Sorted) - JP-5 Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location		Urgency	Recommended Repairs
(b) (3) (A	A2		RHTF	(b) (3) (	Minor staining, indicative of a minor fuel weep, on the upstream body threaded plug associated with DBB tank isolation valve.	Long	Tighten threaded plug and monitor as needed until it is repaired. Remove plug from the valve body and retape and reinstall to prevent future weeps. NOTE: Removal of plug cannot be performed without taking the tank out of service.
4)	A13		RHTF	A)	Non-standard flanges and non-standard weld tie-ins at the crosstunnel pipeline tees.	Long	Consider upgrading to ASME B16.5 rated flanges and fittings with buttwelded arrangements at cross-tunnel pipeline connections.
	A19		RHTF		Coairne failure and corrosion between pipe and pipe support on the	Long	Remove pipe support, clean, and recoat affected area, and reinstall pipe support. Secure saddle support to support beam and provide Teflon pad between support and pipe to eliminate metal-to-metal contact. NOTE: This may require replacement of the affected pipe supports.
	A19		RHTF		Coating failure and corrosion between pipe and pipe support on the	Long	Remove pipe support, clean, and recoat affected area, and reinstall pipe support. Secure saddle support to support beam and provide Teflon pad between support and pipe to eliminate metal-to-metal contact. NOTE: This may require replacement of the affected pipe supports.
	A19		RHTF		Coating failure and corrosion between pipe and pipe support on the	Long	Remove pipe support, clean, and recoat affected area, and reinstall pipe support. Secure saddle support to support beam and provide Teflon pad between support and pipe to eliminate metal-to-metal contact. NOTE: This may require replacement of the affected pipe supports.  Note: This segment of piping (8ft pup) is currently being replaced as part of the FY21 Emergent Pipeline Repair Project.
	A19		RHTF		Coating failure and corrosion between pipe and pipe support on the	Long	Remove pipe support, clean, and recoat affected area, and reinstall pipe support. Secure saddle support to support beam and provide Teflon pad between support and pipe to eliminate metal-to-metal contact. NOTE: This may require replacement of the affected pipe supports.
	A18	LAT-50	RHTF	, s	Coating failure and corrosion due to mineral deposits on the JP-5 pipeline. No significant pitting was observed.	Long	Clean and recoat affected area of the pipeline.
	B44		Harbor Tunnel		The branch connection on the JP-5 pipeline is unsupported and unreinforced. Branch line does not appear to be in use and blinded with a skillet and flange.	Long	Remove unused branch connection.

					Table 9 (Sorted) - JP-5 Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3) (A	B40		Harbor Tunnel	(b) (3) (A)	Pitting corrosion on Sp. 25 pipeline at the 2 o'clock position.  Corrosion areas is 2 by 2 with a pit depth measurement of 0.113 inches. Remaining metal thickness of 0.120 to 0.125 inches. Metal thickness of unaffected area is 0.233 to 0.238 inches. Approximate wall loss of 48.5%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
)	B33		Harbor Tunnel		Inactive pitting on the position. Corrosion area is the position of 0.050 to 0.135 inches. Remaining metal thickness of 0.091 to 0.099 inches. Metal thickness of unaffected area is 0.226 to 0 234 inches. Approximate wall loss of 59.7%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
	B34		Harbor Tunnel		Inactive pitting on the position. Corrosion area is 6 by 6 with pit depth measurements of 0.050 to 0.089 inches. Remaining metal thickness of 0.152 to 0.156 inches. Metal thickness of unaffected areas is 0.234 to 0.241 inches. Approximate wall loss of 38%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
	B31		Harbor Tunnel	·	Pitting corrosion was observed at the 6 o'clack position on the JP-5 pipeline. Corrosion areas is 10 by 10 with pit depth measurements of 0.055 to 0.102 inches. Remaining metal thickness of 0.116 to 0.136 inches. Metal thickness of unaffected areas is 0 218 to 0.238 inches. Approximate wall loss of 46.8%	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
	B26		Harbor Tunnel	· · · · · ·	Heavy nitting was observed on the piping at the 9 o'clock mosition on the Spipeline. Corrosion area is 9 by 9 with pit depth measurements of 0.050 to 0.140 inches. Metal thickness of unaffected area is 0.239 to 0.244 inches. Approximate wall loss of \$8.6%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
	B49		Harbor Tunnel		Heavy pitting was abserved on the piping at the 2-6 o'clock positions on the har-5 pipeline at the interface where the piping penetrates the concrete bulkhead. Pit depth measurements of 0.0625 to 0.105 inches. Metal thickness of the unaffected area is 0.240 to 0.243 inches. Remaining metal thickness of 0.135 to 0.138 inches. Approximate wall loss of 43 8% wall loss.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup. Note, this will require removal of the pipeline within the concrete bulkhead.
	B48 Table H		Harbor Tunnel		The pipeline is covered by a protective wrap throughout the Harbor Tunnel. Protective wrap is failing in numerous locations and prohibits external inspection of the piping condition.	Long	Remove protective pipe wrap and perform visual inspection of these sections of pipe for external corrosion.

ts and Recommendations	Urgency Recommended Repairs	re with minor to moderate corrosion JP-5 pipeline. See Table H in API 570 Long Clean, prep and recoat affected areas.	Prrosion on pipe, flanges,  Long Long pipeline. Clean, prep, and recoat affected area.	branch connection on Long Replace non-standard blind with a 12 blind flange per ASME B16.5.	Clean up gear box and ensure covers are secured to prevent future oil leaks. Verify sufficient lubricant is still present and if needed service actuator gear box.	JP-5 pipeline at the Long Remove temporary attachment on the pipeline and perform NDE.	ns and general corrosion  FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at pit depth a wall thickness of 0.130"  Even the 12 of 20,130 and 12 of 20,130 and 12 of 20,130 and 13 of 30,130 and 13 of 30,130 and 14 of 30 and 15 of 30,130 and 15 o	IP-5 pipeline within the Long Section 12 Level 1 assessment. Monitor dent locations at next API 579 sort for exact locations.	ded to the pipeline.  Long Remove tack welded plates/attachments, grind down, and perform
Table 9 (Sorted) - JP-5 Findings and Recommendations	Description	Several areas of coating failure with minor to moderate corrosion was observed on the JP-5 pipeline. See Table H in API 570 report for exact locations.	Moderate coating failure and moderate corrosion on pipe, flanges, fasteners, and components on the property of pipeline due to mineral deposits and water inflitrating through tunnel ceiling.	Non-standard flange construction a branch connection.  Jp-5 pipeline. Blind flange was constructed with 12-weldneck flange with a flat plate welded to flange for blind.	Moderate oil staining noted on the DBB valw	Tack weld fit up tab is located on the JP-5 pir 12 o'clock position.	Several active and inactive pitting locations and general corrosion was noted on the properties at the 12 o'clock position.  Location is approximately 21-inches from properties of 130° measurement of 0.095 inches. Remaining wall thickness of 0.130° to 0.147″ is estimated at this location. Metal thickness of unaffected areas is 0.225 inches. Approximate wall loss of 42.2%.	Several dents were present on the JP-5 pipeline within the harbor tunnel. See Table F in API 570 report for exact locations.	There are several plates that are tack welded to the pipeline. These plates do not appear to serve a purpose
	Location	(b) (3) (A)							Various
	Geographic Area	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor	Harbor Tunnel	Harbor Tunnel	Harbor	Harbor
	SGH Report Cross Reference	HT-1 HT-16 HT-27 HT-24 HT-41 HT-48 HT-50 HT-51	HT-52			,		HT-18	
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	B10 Table H	B1	B12	B13	B27	829	B15 Table F	B50
	ltem No.	(b) (3) (A)		27					

					Table 9 (Sorted) - JP-5 Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3)			ИСРН	(b) (3)	The gate valves within the piping systems inside the underground pumphouse are weeping and require continuous maintenance.	Long	Remove the gate valves and install ball valves. It is recommended to program this valve replacement after defueling of RHTF is complete.
(A)	972		ИСРН	(A)	Moderate weeping/staining on front bearing shaft and casing of pump.	Long	Perform routine cleaning and removal of oil staining from pump casings.
	28		на В		Inactive corrosion and bolt diameter reduction was noted on the follower bolts associated with the suction side dresser coupling.	Long	Replace dresser coupling follower bolts. Monitor for damage until repair is complete.
	623		ИЗВН		Housing on flow switch mounted on discharge side of pump is not secured and loose. Current configuration does not meet hazardous area rating.	Long	Secure housing and properly seal all conduit connections.
	C30		ИСРН		1/2 piping and pressure gauge assembly was observed to be weeping on the discharge side of 208.	Pong	Disassemble piping and gauge, retape threaded connections, and reassemble to prevent future weeps.
	G33		ИСРН		Dresser coupling lugs on pump suction side are installed backwards.	Long	Repair dresser coupling lugs to be installed correctly.
	38		ИСРН		Several threaded fittings were noted throughout the UGPH piping below the grating on the main header piping. Some of the branch connections welds are not per industry standard (did not use Weldolet or other approved branch connections).  - PIT-284 and adjacent Temperature Sensor  - Valve GI15D  - Valve GI25E  - Valve GI25E  - Valve GI25E	Long	Replace threaded fitting and pipe with welded connection and replace branch connections with industry approved connections.
	C52		ИЗВН		The JP-5 header manifold has a 3/4 gate valve (Valve GP981) at the end of the header. The 3/4 valve is allowing product to weep by and drip into a catchment basin. It was also noted that there are no pressure relief devices installed on the header piping.	Long	Provide pressure relief devices to prevent an over pressurization of the header piping.
	C53		Идри		All the gate valves on the suction and discharge side of the pumps are equipped with motorized valve actuators. It was observed that the motorized valve actuators are mounted on a stich welded adapter plate. Several of the stitch welds have hairline cracks present and could cause the adapter plate to shear off during actuator operation.	Long	Remove coating and perform further weld inspection.

Appendix C – API SGH Cross Reference No. Deficiency (InterSpec, LLC) D5 D6 D6 F6 LAT-12 F7 F10 F12	Table 9 (Sorted) - JP-5 Findings and Recommendations	t Geographic Location Description Urgency Recommended Repairs	The pressure relief system has an Emerson Figure 533 flow control  UGPH  UGPH  Cong  Remove plastic caps and provide threaded steel conduit plugs.  the factory plastic caps installed in the unused conduit inlet ports.	UGPH  Several locations where the Teflon pad is missing between pipe Long  Long  Long  Long  Long  Detween support and pipe.	Some minor staining was noted on the bottom of the flanges for the langes for the	Facility piping at the tank piping laterals tees have nonstandard rated flanged fittings and flanges at these locations.  RHTF  11/12, 13/14, 15/16.	A sertion of 18 JP-5 pipeline is not adequately supported at resulting in an unsupported pipe span of 44 between		A section of is not adequately supported a install saddle supports between the pipe and I-beam are resulting in an unsupported pipe span of 30 between install saddle supports between are supported pipe span of 30 between install saddle supports between are supported pipe span of 30 between install saddle supports between are supported pipe span of 30 between install saddle supports between are supported pipe span of 30 between install saddle supports between the pipe and I-beam are supported pipe span of 30 between install saddle supports between the pipe and I-beam are supported pipe span of 30 between install saddle supports between the pipe and I-beam are supported pipe span of 30 between install saddle supports between the pipe and I-beam are supported pipe span of 30 between the 30	and concrete penetration at Door C. The maximum suggested pipe  Support spacing for 19-5 pipeline is 28 of the FY21 Emergent Pipeline Repair Project.	There is moderate coating failure and associated corrosion on the Company Replace the coating on the DBB valve and associated hardware.	fasteners, flanges, valve body, and relief pipe nipples was noted.	The body cavity relief nipple is in contact with the galvanized conduit. Potential for further corrosion due to contact/interference.	There is heavy corrosion on the flanges promoting Long Replace fasteners.  Long Replace fasteners.	There is heavy corrosion on the conduit and fittings associated Long Replace corroded conduit and associated fittings on with
Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)		ee . t	9n	Sn O	90	- HR	LAT-12 P.1	LAT-14 KH	-	ž	HZ.		R	RH	RH
		Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)		100000	D4 D5 D6	F4		2	C	È	69		F10	F11	F12

Apper S70 S70 No. De	100 CT				Table 9 (Sorted) - JP-5 Findings and Recommendations		
e (Inte	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3) (A)	F15		RHTF	(b) (3) (A)	Facility piping girth (circumferential) welds include several non- typical bell and spigot style fillet welds. Some welds are direct bell- bell buttweld attachments. These welds appear to be part of the original construction. There has been ongoing replacement effort of these welds with several identified and replaced since the 2015 API 570 inspection. There are currently ten (10) welds with a bell and spigot/ bell-bell weld configuration in the segment inspected.	Long	Replace these joints to bring the piping into current standards. Note: and ioints are being replaced between as part of the FY21 Emergent Pipeline Repair Project.
	F16		RHTF		A weld undercut was identified on the (located approximately 100 inches pass at the 4 o'clock position. The measured depth was 1/32 This is acceptable for normal and Category M fluid service.	Long	Recoat affected area where the coating was removed for weld measurement.
	F20		RHTF		There is an dresser coupling joint and associated joint harness at just past the concrete penetration. Visual inspection did not reveal any deficiencies at this location. A slight tilt was noted and documented. Approximately a 0.9-degree tilt over a 36° span was recorded.	Long	Monitor at next API 570 inspection. Note: This is programmed for removal as part of the FV21 Emergent Pipeline Repair Project.
	F22	PM-25	RHTF		There was corrosion identified under insulation at the Tank 10 dresser coupling. Location is at the 8 o'clock to 10 o'clock position.	Long	Clean, prep, and recoat affected areas. Reinstall insulation after coating work is complete. Add inspection to the next API 570 inspection for all dresser couplings.
	F23		RHTF		Internal portions of the piping at Tanks 18 and 20 were visual inspected to get a condition assessment. The piping is in satisfactory condition with minor pitting. Minor pitting was noted at the bottom of the pipe (likely due to standing water). Pitting depth of 0.030" to 0.050" was noted.	Long	Exercise the tank valves periodically to move product and prevent standing water at low points of the piping system.
	F24		RHTF		Minor pipe pitting was identified on Tank 18 laterally below a bubbled coating. Piping is 16 schedule 40. Pitting depth of 0.030" to 0.070" was noted.	Long	Clean, prep, and recoat affected area.
	F26	PM-10	RHTF		There is no hold down u-bolts or slide-guide to prevent lateral pipe movement at the end of the header pipe run (at	Long	Add guided slide support with hold down lugs at Note: This repair is currently programmed as a predictive repair as part of the FY21 Emergent Pipeline Repair Project.
	F27		RHTF		There is coating damage at the pipe repair sleeve located approximately 2.5 from	Long	Clean, prep, and recoat affected areas.

8	
-	
E	

					Table 9 (Sorted) - JP-5 Findings and Recommendations		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3) (A)		PM-19 PM-20 PM-21 PM-22	RHTF	(b) (3) (A	Dresser Couplings are installed in tank piping laterals.	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	B47	10	Harbor Tunnel	)	Out-of-round (flat spot) noted on the JP-5 pipeline at the bell-weld between the 12 o'clock and 3 o'clock position.	Other	No action needed to perform defuel operations. Evaluate at the next API $570\mathrm{inspection}.$
	C15		прдп		Minor bearing oil staining was noted on pump casings.	Other	Perform routine cleaning and removal of bearing oil staining from pump casings.
	F1		RHTF		Dresser coupling joints and associated joint harness at Tanks 18, 19, and 20 are damaged due to the May $6^{\rm th}$ event.	Other	The lateral piping associated with Tanks 18, 19, and 20 are currently under repair as part of the FY21 Emergent Pipeline Repair Project.
	FS		RHTF		Heavy corrosion with pitting was located at the rolled 45-degree elbows. Corrosion is due to active drips from the tunnel ceiling mineral deposits. Nominal thickness was likely 0 375". The general metal thickness at this area is now 0.300" with a pit depth of 0.100" resulting in a remaining thickness of 0.200".	Other	This segment of piping is currently under repair as part of the FY21 Emergent Pipeline Repair Project. No further action is recommended.
	F14 Table F		RHTF		A dent has been identified with a depth of 0.950 and needs to be repaired prior to returning the JP5 pipeline above valve MOV-0163 back to service. An additional 10 dents were located from to Tank 20. Refer to Table F in the API 570 report in Apendix C for exact dent locations of the other 10 dents.	Other	This segment of piping has been repaired by pup replacment as part of the FY21 Emergent Pipeline Repair Project. Recommendation for the other ten dents is to monitor at the next API 570 inspection.

					Table 10 (Sorted) - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location		Urgency	Recommended Repairs
(b) (3)	A22		RHTF	(b) (3	Dresser coupling on the lateral piping to Tank 14 is missing the deflection ring. A small gap was noted between the washer and harness lug.	Urgent	Install appropriate deflection rings and tighten fasteners per manufacturers or designer of record specifications.
(A)			RHTF	3) (A)	Tank sample piping downstream of the isolation valve are open to the atmosphere. If the isolation valves were to be bumped or inadvertently forced open, this could lead to an accidental fuel spill.	Urgent	Provide threaded caps on tank sample piping downstream of isolation valves.  NOTE: This deficiency has been corrected for the tanks that have been previously cleaned, inspected, and repaired.
	A21		RHTF		The high point vent on the pipeline is constructed with a non-standard threaded bronze/brass (low melting point) valve. Valve is located between riser tee to lateral piping and blind flange at the end of the pipe run. Valve classification is unknown.	Urgent	Replace high point vent valve with a Class 150 flanged carbon steel ball valve and welded pipe.
s 35	A33	PM-23 PM-24	RHTF		Dresser coupling on the pipeline was observed with backwards lugs. There are no deflection rings or adapters on the hamess lugs.	Urgent	Correct positioning of the lugs and provide deflection rings and adapters on the harness lugs. Tighten hardware on rods per manufacturer or designer of record specifications.
6	A26		RHTF		Several fasteners on flanges between lateral tee and 32 F-76 pipeline have moderate corrosion.	Urgent	Replace corroded fasteners and remove corrosion from spectacle blind. Recoat affected area.
	A27		RHTF		d on the blind flange associated pipeline.	Urgent	Tighten fasteners or replace fasteners with longer bolts to ensure nuts are fully engaged.
6 8	A32		RHTF		-76 pipeline was observed with to be fully engaged/tightened. dapters on the harness lugs. The sser coupling is located on main	Urgent	Correct positioning of the lugs and provide deflection rings and adapters on the harness lugs. Tighten hardware on rods per manufacturer or designer of record specifications.
Ø 8	B2		Harbor Tunnel		The two high point vents on the pipeline adjacent to valve 0151 and the UGPH bulkhead are constructed of threaded valves, nipples, and piping. There is evidence of fuel staining and weeping noted around the threaded fittings. Valve classification is unknown.	Urgent	Remove, retape, and reassemble threaded connections. Replace high point vent valves with Class 150 carbon steel ball valves.  Long term consideration should be given to replacing the high point vent piping and valves with welded pipe with flanged connections.
8 B	B3 B4 B5		Harbor Tunnel		There are three low point drains on the plane pipeline between the UGPH concrete bulkhead and 690 that are constructed of threaded valves, nipples, and piping. There is evidence of fuel staining and weeping noted around the threaded fittings. Valve classification is unknown.	Urgent	Remove, retape, and reassemble threaded connections. Replace low point drains with Class 150 carbon steel ball valves.  Long term consideration should be given to replacing the low point drain piping and valves with welded pipe with flanged connections.
Ø .	B19		Harbor Tunnel	<i>)</i>	DBB isolation valve on the pipeline is missing a nut and bolt on the top plate.	Urgent	Install new nut and bolt on the top plate of the valve.
				y.			

Table 10 (Sorted) - F-76 Findings and Recommendations		threaded HPV is located on the F-76 pipeline. The ball valve out. Remove the reducing bushing and install a 2-bill valve does not have a lock and the reducing bushing is not fully engaged in the threaded connection. Valve classification is unknown.	Longitudinal weld on the F-76 pipeline has a 5 long Urgent additional NDE to evaluate the extent of the porosity in this weld.	One bolk is missing a nut on the flanged 6 branch fitting Urgent Replace fastener that has a missing nut.	The flanged 6 branch connection on the F-76 pipeline lacks proper thread engagement on a fastener and is missing a nut on another bolt. The blind flange installed does not appear to be ASME B16.5 blind.	Several HPVs and LPDs throughout the harbor tunnel. These are composed of threaded valves, piping, and components. Minor staining was noted on some of these fittings. Also, the valve classifications in several locations are unknown.  1 threaded plug on top class the serial point vent.  2 high point vent.  2 high point vent.  3 weeping a the 2 high point vent.  4 Long term consideration should be given to replacing threaded connections.  5 high point vent.  6 connections with welded and flanged connections.	Two loose joint harness fasteners were noted on the Dresser coupling on the discharge side of pump 201. Four loose joint harness fasteners were noted on the Dresser coupling on the suction side of pump 201. Some minor coating cracks were noted on the discharge dresser coupling around the middle ring-to-follower joint area indicating potential movement.	The ball valve on the strainer drains associated with the pump Urgent Provide threaded plugs to prevent accidental discharge of fuel product.	A small fuel weep was observed on the suction side pressure gauge assembly at the threaded connection, and reassemble to prevent future weeps.	1/2 ball valve (Valve GP26H) is missing a plug. Urgent Provide threaded plug to prevent accidental discharge of fuel product.
	Location	<i>5</i> / (5/ (-1/								
	Geographic Area	Harbor Tunnel	Harbor Tunnel	Harbor	Harbor Tunnel	Harbor Tunnel	ИСРН	на В	прен	ОСРН
	SGH Report Cross Reference									
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	B23	B43	B42	B45	B18	C1 C2 C7	60	C10	C13
	Item No.	(b) (3) (A	N)							

					Table 10 (Sorted) - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3) (	C14		UPGH	(b) (3) ( <i>i</i>	The small isolation ball valves on the pump discharge control valve tubing are missing operating handles. This will prevent isolation in the event of an emergency such as a tubing break or damage to isolate the fuel leak.	Urgent	Provide operating handles on ball valves and consider a car-seal to lock valves in desired position.
(A)	<b>LD</b>		NGPH	Α)	Heavy discoloration and staining observed on the nump discharge control valve. Similar discoloration was noted on 203, 204, 205.	Urgent	Clean, disassemble, and replace valve cover gasketing to prevent future weeps and drips.
	C18		UPGH		Conduit plug is being used to plug tee fitting on pressure gauge assemblies.	Urgent	Install appropriate threaded pipe plugs on tee fittings.
	612		UPGH		A small fuel weep was observed on the suction side pressure gauge assembly at the threaded connection associated with Pump 203.	Urgent	Remove gauge, retape threaded connection and reassemble to prevent future weeps.
3 a	070		пды		One loose joint harness fastener was noted on the Dresser coupling on the discharge side of pump 203.	Urgent	Tighten fasteners per manufacturers or designer of record specifications.
	170		UGPH		Two loose joint harness fasteners were noted on the Dresser coupling on the discharge side of pump 204.	Urgent	Tighten fasteners per manufacturers or designer of record specifications.
	C22		UGPH		The fasteners on the pump discharge control valve are not fully engaged.	Urgent	Tighten fasteners or replace fasteners with longer bolts to ensure nuts are fully engaged.
	623		NGPH		Two loose joint harness fasteners were noted on the Dresser coupling on the discharge side of pump 205.	Urgent	Tighten fasteners per manufacturers or designer of record specifications.
	C24		ИСРН		The isolation ball valve on the pump discharge control valve tubing was in the closed position at the time of inspection. The control valve function may be limited when the piloting is isolated and not subject to system pressures.	Urgent	Verify correct position of isolation valve on the control tubing and consider providing a lock or car-seal to prevent accidental misalignment of the valve position.
	225		ИЗБР		The suction side Dresser coupling is missing a nut on the restraining rod. Also, there was one loose joint harness fastener present.	Urgent	Provide nut and tighten fasteners per manufacturers or design of record specifications.
	C34		ИЗРН		There are several open conduits, junction boxes, and unsealed electrical fittings throughout the UGPH that will not meet hazardous area ratings.	Urgent	Seal all electrical fittings per NFPA requirements to meet hazardous area classifications.
	36		ИСРН		There are several bronze/brass valves installed on the small andillary piping systems within the UGPH. A few examples are Gate Valve GIS8I, GIS8G, and GIS8H. Valve classification is unknown.	Urgent	Replace low melting point valves with Class 150 carbon steel ball valves.

					Table 10 (Sorted) - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3) (A)	37		Набл	(b) (3) (A)	Fuel staining and weeping was noted on the pipe tie-ins associated with the temperature sensors, pressure sensors, high point vents, and low point drains. Weeping is present at threaded connections associated with these fittings.  - PIT-0285 and adjacent Temperature Sensor - Valve Gi36C - Valve Gi36C - Valve Gi36C	Urgent	Disassemble threaded connections, retape, and reassemble to prevent future weeps.  Long term consideration should be given to replacing threaded connections with welded connections where possible.
	623		пдри		Lack of thread engagement was observed on 12 fasteners on the bypass loop flanges associated with the	Urgent	Install proper flange bolts and hardware to insure proper thread engagement at all flanged connections.
	C40		ОСРН		Several transducers are attached to the piping and the conduits do not have seal off fittings. Additionally, the conduits are ridged which could break under pipe movement.	Urgent	Provide appropriate seal fittings and flexible conduit connections at transducers.
	C41		ИЗВН		It was noted that several of the pressure transducers are past due for calibration. (Calibration due date of 10/23/18)	Urgent	Perform calibration of all temperature and pressure devices.
	C42		ИСРН		There is staining and some minor drips noted on the Cameron ball valves throughout the UGPH. Drips appear to be coming from the stem injection port.	Urgent	Gean valve body, service stem $\operatorname{nut/upper}$ stem seal to prevent future weeps/drips.
	C44	6 0	UGPH		Gate valve GR68B is missing wheel nut on valve stem.	Urgent	Install new wheel nut.
	C45		пдри		The 18 DBB valve on the has six fasteners/studs that are not fully engaged.	Urgent	Remove existing hardware and reinstall studs to ensure proper thread engagement with valve body flange.
9	C48 C54		ОСРН		There was noticeable fuel drips and weeps coming from pressure relieving devices on the valve above the grating. (Cla Val relief devices)	Urgent	Service pressure relieving devices to prevent future weeps. If valves are not serviceable, consideration should be given to replacement of these valves.
	53		Набо		All the gate valves on the suction and discharge side of the pumps are equipped with motorized valve actuators. It was observed that the motorized valve actuators are mounted on a stich welded adapter plate. Several of the stitch welds have hairline cracks present and could cause the adapter plate to shear off during actuator operation.	Urgent	Remove coating and perform further weld inspection.
	8Q		ИСРН		Lack of thread engagement on nuts and bolts associated with the lack of thread engagement on nuts and bolts associated with the tien on some connection.	Urgent	Tighten fasteners or install new flange bolting hardware to ensure proper thread engagement is achieved at the flanged joint.
	D9 D15	,	ИЗБИ		The 1 ball valves that are mounted on the 4 low suction line at Surge Tanks 3 and 4 are missing plugs. A brass/bronze valve was noted at Surge Tank 3 location. Valve classification is unknown.	Urgent	Install a plug to prevent accidental fuel release. Replace bronze/brass valve with Class 150 carbon steel ball valve.
	D14		ИВРН		Some minor staining was noted on the bottom of the 4 low suction DBB valve flange at Surge Tank 4.	Urgent	Clean flanges and monitor for future weeps.

					Table 10 (Sorted) - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3	LRUT Results CML# B8		Harbor Tunnel	(b) (3)	LRUT Results - An indication (corrosion spot) was observed approximately 7 inches past the concrete bulkhead, towards the tank gallery, underneath the pipe wrap.	Urgent	Remove pipe wrap and inspect the pipeline at this location.
) (A)	LRUT Results CML# B21		Harbor Tunnel		LRUT Results - One confirmed indication was detected at approximately -402 to -411 inches from setup on the pipeline. There was also an indication identified at the pipeline to concrete saddle support, PSC-195 on the will require additional investigation.	Urgent	Perform further investigation of the indications at both locations. Note: This will require the pipe to be lifted off the concrete support or the pipe support removed and replaced to allow further inspection.
(c)	LRUT Results CML# B26		Harbor Tunnel		Two indications noted approximately -976 inches and -963 inches from setup on the	Urgent	Remove pipe wrap and inspect the pipeline at these locations.
		PM-19 PM-20 PM-21 PM-22	RHTF		Dresser Couplings are installed in tank piping laterals.	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	A13		RHTF		Non-standard flanges and non-standard weld tie-ins at the cross-tunnel pipeline tees.	Long	Consider upgrading to ASME B16.5 rated flanges and fittings with buttwelded arrangements at cross-tunnel pipeline connections.
	A23		RHTF		Area of inactive corrosion observed on between supports, approximately 108 inches from 40. Pit depth = 0.196"-0.200" and UTI of 0.430" on unaffected areas resulting in remaining thickness of 0.219" to 0.250". Approximate wall loss of 46.5%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
	A24		RHTF		pipeline is not fully supported at pipe support.	Long	Modify pipe support to adequately support pipe. Install Teflon pad between saddle support and pipeline to eliminate metal-to-metal contact.
	A24		RHTF		pipeline is not fully supported at pipe support.	Long	Modify pipe support to adequately support pipe. Install Teflon pad between saddle support and pipeline to eliminate metal-to-metal contact.
	A25		RHTF		Second pipe support from Tank 9 is not supporting the lateral tank piping. Approximately 39 of unsupported pipe from the lateral tee to the tank.	Long	Modify pipe support to adequately support pipe.
s	A29		RHTF		Branch connection on 32 F-76 pipeline has a 1 threaded fitting and valve. Fuel staining was evident on pipeline but no active weeping noted.	Long	Clean the staining from the flange joint, branch pipe, and header pipe. Monitor the location for future weeps. Replace threaded fittings and valves with welded pipe and Class 150 flanged ball valve.
94 0	A28		RHTF		Coating failure and corrosion due to mineral deposits or pipeline. No significant pitting or thickness loss noted.	Long	Clean and recoat affected area of the pipeline.
	A30		RHTF		Staining noted on pipeline lateral tie-in between tanks. No active weeping was noted. Oily substance does not appear to be F-76 fuel.	Long	Thoroughly clean tie-in connections and flanges to remove oily substance. Monitor location for potential weeps and drips.

L	
PFDOP	7
4	•
С	•
ñ	7
	•
щ	4
Ω	•
_	•
NOPPORT	•
=	7
L	)
7	٠
-	•
L	)
ū	7
ጽ	•
y	,
2	•
Ξ	2
_	2
S	
	÷
ū	ì
H	į
L	
CVCTEN	
	1000
۵	ţ
۵	ţ
۵	ţ
۵	ţ
۵	ţ
NOFFD	ţ
TRANSFER	
TRANSFER	
TRANSFER	
TRANSFER	
NOFFD	

Item C					lable 10 (sorted) - F-76 Findings and Recommendations		
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	scription	Urgency	Recommended Repairs
(b) (3) (A)	A31		RHTF	(b) (3) (A)	Wood support extending from pipeline to tunnel ceiling. Use and function of the support is unknown and not associated with pipeline support or restraint. The wood beams do not appear to be bearing any load on the pipe based on gaps between wood and top of steel saddle as well as gaps at bolting hardware.	Long	Further investigation of the use and purpose of the wood support. Perform alternative design to remove support from pipeline and for the intended function.
	B48 Table H		Harbor Tunnel		The pipeline is covered by a protective wrap throughout the Harbor Tunnel. Protective wrap is failing in numerous locations and prohibits external inspection of the piping condition.	Long	Remove protective pipe wrap and perform visual inspection of these sections of pipe for external corrosion.
	B10 Table H	H-1 H-16 H-16 H-34 H-35 H-42 H-43 H-45 H-48	Harbor Tunnel		Several areas of coating failure with minor to moderate corrosion was observed on the pipeline. See Table H in API 570 report for exact locations.	Long	Clean, prep, and recoat affected areas.
	B1		Harbor Tunnel		Moderate coating failure and with moderate corrosion on pipe, flanges, fasteners, and components on the due to mineral deposits and water infiltrating through tunnel ceiling.	Long	Seal the tunnel or provide ceiling trays to prevent further deposits on the pipeline. Gean, prep, and recoat affected area.
	811		Harbor Tunnel		ock arc it to e from	Long	Remove coating and conduct close visual inspection along with liquid penetrant testing or magnetic particle testing of the arc strikes and weld lines.
	B51		Harbor		There appears to be a pipe alignment tab weld that was not ground flush.	Long	Grind weld attachment flush and conduct further NDE.
	B30		Harbor Tunnel		ig and general corrosion were observed on the aline was observed between 314 and 315 at a position. Corrosion area is approximately 24 inches with the deepest pit corrosion area covering 9 inches iff pit depths range from 0.080 to 0.140 inches. all thickness of 0.218 to 0.221 inches is estimated at Metal thickness of unaffected area is 0.358 to 0.361 ximate wall loss of 39.1%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.

	ı
1	l
O	l
T	l
R	ı
2	l
2	l
C	ı
SPE	ı
S	ı
=	l
Σ	ı
FE	l
>	ı
3	ı
1	l
S	ı
5	l
2	l
5	I
H	I
H	I

					Table 10 (Sorted) - F-76 Findings and Recommendations		
No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location		Urgency	Recommended Repairs
(b) (	B28		Harbor	b) (3	Concrete saddle support (number 337) has several 1/8 rods between the pipe and concrete saddle.	Long	Remove 1/8 rods between pipe and concrete saddle, inspect interface, and provide Teflon pad between pipe and support.
3) (A)	B21		Harbor Tunnel	3) (A)	"Clock Spring" repair sleeve on the	Long	Review previous documentation to determine reason for repairs.  Consideration should be given into removing the clock spring repairs and replacing the section of piping with new. Note: Replacement of the clock springs was previously mentioned as a long-term repair in EEI's 2016 "Inspection and Repair of Redhill Pipelines Report" but does not appear to be performed as part of the 2019 fuel system repairs.
	B21		Harbor Tunnel		"Clock Spring" repair sleeve on the	Long	Review previous documentation to determine reason for repairs.  Consideration should be given into removing the clock spring repairs and replacing the section of piping with new. Note: Replacement of the clock springs was previously mentioned as a long-term repair in EEI's 2016 "Inspection and Repair of Redhill Pipelines Report" but does not appear to be performed as part of the 2019 fuel system repairs.
	B38		Harbor Tunnel		Concrete pipe support, PSC-501, is not engaged with pipe and the pipe is floating. Loose concrete aggregate was noted between support and pipe.	Long	Remove the loose concrete aggregate between the pipe and the support and shim with Teflon pad.
	B22		Harbor		The concrete saddle type support is cracked.	Long	Repair concrete saddle support.
	B24		Harbor		Coating failure and corrosion on the welded 8 branch on the pipeline	Long	Clean, prep, and recoat affected area.
	B37		Harbor		Wood shim installed between pipeline and concrete saddle support number 193.	Long	Remove wood shim and provide steel plate shim and Teflon pad.
	B35		Harbor Tunnel		pipeline at the 6 o'clock position. Corrosion area is the specification. Corrosion area is the specification of th	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
	B36		Harbor Tunnel		Inactive pitting on the position of the position. Corrosion area is 15 by 24 with pit depth measurements of 0.050 to 0.114 inches. Remaining metal thickness of 0.186 to 0.193 inches. Metal thickness of unaffected areas is 0.386 to 0.393 inches. Approximate wall loss of 29.5%	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.
	B41		Harbor Tunnel		Pitting on the pipeline at the 11 o'clock position.  Corrosion area is 18 by 24 with pit depth measurements of 0.050 to 0.120 inches. Remaining metal thickness of 0.178 to 0.201 inches. Metal thickness of unaffected areas is 0.298 to 0.321 inches. Approximate wall loss of 40.3%.	Long	FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term consideration should be given to replacing pipe segment with a 4 pup.

					Table 10 (Sorted) - F-76 Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3	B15 Table F	HT-4 HT-18 HT-21 HT-24	Harbor Tunnel	(b) (3) (	Several dents were present on the pipeline within the harbor tunnel. See Table F in API 570 report for exact locations.	Long	The assessment indicates dents are within acceptable limits per API 579 Section 12 Level 1 assessment. Monitor dent locations at next API 570 inspection.
) (A)	B50		Harbor Tunnel	(A)	There are several plates that are tack welded to the pipeline. These plates do not appear to serve a purpose.	Long	Remove tack welded plates/attachments, grind down, and perform additional NDE at these areas.
			Hdbn		The gate valves within the piping systems inside the underground pumphouse are weeping and require continuous maintenance.	Long	Remove the gate valves and install ball valves. It is recommended to program this valve replacement after defueling of RHTF is complete.
	C3		UGPH		Pump shaft guard post not secured to concrete pad.	Long	Secure shaft guard post.
	C4		ИСРН		Several open conduits and sensor enclosures were noted on 201 as this pump appears to be undergoing maintenance and/or repair.	Long	Secure all conduits and sensor enclosures prior to returning pump to service.
	CS		NGPH		Several loose fasteners noted on the upper half casing of 201 as this pump appears to be undergoing maintenance and on repair.	Long	Secure all fasteners to the casing prior to returning the pump back to service.
	C12		UGPH		Coating failure on pump casing associated with Pump 202	Long	Clean, prep, and recoat affected areas.
	CIS		прен		Minor bearing oil staining was noted on pump casings.	Long	Perform routine cleaning and removal of bearing oil staining from pump casings.
	910		NGPH		The control valve tubing on the pump discharge control valve is in contact with the grating/l-beam.	Long	Modify control valve tubing or grating to prevent metal-to-metal contact.
	C33		навп		Dresser coupling lugs on pump suction side are installed backwards.	Long	Repair dresser $\mathbf{coupling}$ lugs to be installed $\mathbf{correctly}$ .
	CB5		ИВРН		There are several locations throughout the UGPH where abandoned/open conduit penetrates the UGPH floor, potentially negating the secondary containment.	Long	Cap, seal, or remove all abandoned conduits within the UGPH.
	G38		ОСРН		Several threaded fittings were noted throughout the UGPH piping below the grating on the main header piping. Some of the branch connections welds are not per industry standard (did not use Weldolet or other approved branch connections).	Long	Replace threaded fitting and pipe with welded connection and replace branch connections with industry approved connections.
	C43		ПСРН		Localized coating failure and corrosion observed on pipeline at Valve 232E4. Small pitting was observed with pit depths ranging from 0.05 to 0.07 inches.	Long	Clean, prep, and recoat affected areas.
	CS 0		ОСРН		The flange connection on the bulkhead penetration does not appear to be an ASME rated flange.	Long	Replace flanged connection with ASME B16 5 rated flange.
	C52		ИВЬН		It was also noted that there are no pressure relief devices installed on the header piping.	Long	Provide pressure relief devices to prevent an over pressurization of the header piping.

	Recommended Repairs	Remove plastic caps and provide threaded steel conduit plugs.	Provide Teflon isolation pads to eliminate metal-to-metal contact between support and pipe.	Gean flange and monitor for future weeps.	Disassemble the connection and provide dimensionally correct gaskets.	Clean flanges and monitor for future weeps.	Monitor hairline cracks in pump pad/foundations.	Consider installing another gasket to protect flange faces from contact surface damage.	Monitor hairline cracks in pump pad/foundations.
	Urgency	Long	Long	Long	Long	Long	Other	Other	Other
Table 10 (Sorted) - F-76 Findings and Recommendations	Description	The pressure relief system has an Emerson Figure 533 flow control valve with hydramotor actuator. The hydramotor actuator still has the factory plastic caps installed in the unused conduit inlet ports.	Several locations where the Teflon pad is missing between pipe and pipe support, creating metal-to-metal contact:	Some minor staining was noted on the bottom of the Dresser coupling on Surge Tank 4. No active weeping was observed. Liquid does not appear to be fuel.	The thermal relief flange at Surge Tank 4 appears to be equipped with a 1/16 gaskets instead of 1/8 gaskets.	Some minor staining was noted on the bottom of the flanges for the 32 F-76 pipeline just before support F76-8 and F76-9. No active weeping was observed. Liquid does not appear to be filel.	Hairline crack was noted in pump pad associated with Pump 201. Hairline crack does not appear to be of significant conce <u>rn.</u>	Skillet is installed on the discharge pump nozzle on 201 and 205. The assembled joints have only one gasket installed.	Hairline crack was noted in pump pad associated with Pump 202. Hairline crack does not appear to be of significant concern.
	Location	(b) (3	) (A)		. 17				
	Geographic Area	ИСРН	ПСРН	ИСРН	ПСРН	ИСРН	ПСРН	UGPH	NGPH
	SGH Report Cross Reference								
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	950	D1	D10	D11	D12 D13	80	90	C11
	Item No.	(b) (	3) (A	<b>(</b> )					

	Recommended Repairs	Urgent Remove and replace concrete at anchor bulkhead.	Urgent Remove and replace concrete at anchor bulkhead.	
ations	Urgency	Urgent	Urgent	
Table 11 (Sorted) - F-76 Pipe Support Findings and Recommendations	Description	Concrete has been chipped out and removed on tank side around flange for the JP-5 lines; concrete around line has broken out (but not fallen) on opposite side.	Concrete a has been broken out on tanks side, no flange visible.	
	Location	(b) (3) (A	).	
	Geographic Area	Harbor Tunnel	Harbor Tunnel	
	SGH Report Cross Reference			
	Appendix C - API 570 Report – Cross Reference Defficiency (InterSpec, LLC)			
	Item No.	(b) (3)	(A)	

					Table 12 (Sorted) - FOR Findings and Recommendations		
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
( <b>D</b> ) (	E27		RHTF	(b) (	The tank sampling system at Tank 13 has three 1 flanged joints with cracked gaskets.	Urgent	Remove damaged gaskets and install new gaskets ensure proper torque sequence and specifications are met.
3) (A)	2) (A)		RHTF	(3) (A)	ball valve located on the blind flange on Tank 18's FOR pipeline is not plugged off. This valve is susceptible to being accidentally opened if something were to impact the ball valve handle causing it to open.	Urgent	Provide plug or cap on ball valve to prevent accidental fuel release.
	E11		RHTF		The pressure gauge on the FOR line on the discharge side of the sump <u>pum</u> p is out of calibration and the glass gauge is cracked.	Urgent	Replace damaged pressure gauge.
	E12		RHTF		The 2 FOR pipeline between the tee and gate valve at Door C is covered with a stained plastic wrap and c-clamps. This is indicating a weep at the threaded joint.	Urgent	Remove wrap and repair piping connections to prevent future weeps and drips.
	E21		RHTF		Tank isolation valve on the 6 FOR pipeline has one fastener that is not fully engaged.	Urgent	Replace bolt on flange with a longer bolt to ensure nut has adequate thread engagement.
	E23		RHTF		The FOR-gate valve flange has three fasteners that are not fully engaged.	Urgent	Replace bolts on flange with a longer bolt to ensure nuts have adequate thread engagement.
	E25		RHTF		The 6 DBB tank isolation valve on the pipeline has product staining on the valve body. This is indicative of a prolonged slow weep possibly from valve plugs in the body.	Urgent	Clean valve body and monitor for drips and weeps. Service the DBB valve as required.
			RHTF		The FOR connection from the product lines is constructed out of a combination of hard pipe and hoses.	Urgent	Replace connections and hoses with hard pipe.
	E32		RHTF		The tank sampling piping associated with Tanks is showing signs of minor to moderate corrosion at areas where the piping has not been upgraded. Tank 9 sample piping is severely corroded and requires replacement.	Urgent	Repair by replacement the small-bore tank sample piping up to the sampling stations associated with Tank 9.  Long term - Clean, prep, and recoat other sampling lines associated with
	E38		RHTF		The tank sampling line associated with the 135 ft sample piping has product staining on valve and joints. Does not appear to be an active weep appears to be the result of residual fuel taken during earnly nonesting.	Urgent	the storage tarits.  Gean valve body and monitor for drips and weeps.
	E48		RHTF		Unsequented flange and pipe nozzle at 6 ball valve. The flange is missing several fasteners and the pipe is not capped.	Urgent	Provide fasteners to secure flange connection to 6 ball valve and provide cap to secure pipe end.
	E43		RHTF		A loose fastener was observed on a 4 pipe flange within the pipe trench adjacent to 5-23.	Urgent	Tighten fastener on pipe flange .
	E47		RHTF		The 6 DBB on the sump pump discharge piping within Sump S-23 is missing a body cavity relief handle and does not have a plug.	Urgent	Provide handle and threaded plug on cavity relief valve.
	E54		e		Low Point Drain – No cap on cam_lock fitting. Two fasteners are not fully engaged on the 2 low point drain flange.	Urgent	Provide cam-lock cap on fitting and provide longer bolts to ensure nuts are fully engaged.

					Table 12 (Sorted) - FOR Findings and Recommendations		
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location		Urgency	Recommended Repairs
(b) (3	E55		3	) (3) (	2 Low Point Drain – No cap on cam-lock fitting. Two fasteners are not fully engaged on the 2 low point drain flange.	Urgent	Provide cam-lock cap on fitting and provide longer bolts to ensure nuts are fully engaged.
) (A)			3	А)	Condition of underground segment of the FOR pipeline is unknown. Per the 2021 CP Report, this section of buried pipe had ineffective magnesium anodes.	Urgent	Perform borescope examination of the underground pipeline segment to assess internal condition of the pipeline. This is currently under contract and will be performed in the near future.
	E56		3		1 ½ low point drain valve is missing a plug.	Urgent	Provide plug on valve. NOTE: Facility Personnel corrected this finding during our inspection.
	E57		3		1 1 1 1 1 1 1 1 1 1 2 2 2 2 2 2 2 2 2 2	Urgent	Provide plug on valve. NOTE: Facility Personnel corrected this finding during our inspection.
	E60		TK S-311 – 3 Entrance		Severe corrosion and pitting at several locations between and S-311. Wall Loss observed between 60%-79%. Severe corrosion also observed at pipe support cradle interfaces.	Urgent	Replace approximately 150 linear of 6 pipe on the aboveground portion of the EOR line outside of 3. Limits are from 6 riser pipe outside 3 to the DBB isolation valve outside of the secondary containment area of Tank S-311.
	E63		TK S-311		The body cavity relief valve on the 8 DBB located on the FOR- receipt pipeline is discharging to isolated segment of piping downstream and should be discharging to the atmospheric, tank side of the valve.	Urgent	Replumb the body cavity relief to relieve towards Tank S-311.
	E64		TK S-311		The 8 DBB valve, located outside of the secondary containment, has a loose fastener.	Urgent	Tighten loose fastener on valve flange.
	E67		TK S-311		The body cavity relief valve on the 8 DBB located on the FOR-issue pipeline is discharging to isolated segment of piping downstream and should be discharging to the atmospheric, tank side of the valve.	Urgent	Replumb the body cavity relief to relieve towards Tank S-311.
	13		RHTF		Threaded pipe nipple was noted on the Tank 20 FOR sample pipeline.	Long	Replace threaded connection with a welded connection.
	E2		RHTF		Metal-to-metal contact was observed between the FOR pipeline and pipe support within the pipe trench, just downstream of the tank sampling manifold.	Long	Provide Teflon pad to prevent metal-to-metal contact.
	E3		RHTF		Moderate corrosion was noted on the 2 blind flange and fasteners on the abandoned branch to the sampling lines at Tank 19.	Long	Gean, prep, and recoat branch connection, blind flange, and replace fasteners.
	ES		RHTF		Pipe support on the FOR line within the trench has become displaced and is no longer supporting the piping.	Long	Reposition the pipe support and Teflon pad to properly support the piping.
	E6		RHTF		Pipe support on the FOR line within the trench has become displaced and is no longer supporting the piping.	Long	Reposition the pipe support and Teflon pad to properly support the piping.
	E4		RHTF		General coating failure and corrosion on Lbeam type pipe supports for the FOR pipeline within the trench. Moderate corrosion was observed on supports between Tanks 16 through 20.	Long	Clean, prep, and recoat pipe supports.

					Table 12 (Sorted) - FOR Findings and Recommendations		
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
b)			RHTF	(b)	Spray foam material in contact with	Long	Remove spray foam as required to prevent contact with FOR piping.
(3) (	63		RHTF	(3)	flange is covered with concrete within the sump.	Long	Remove concrete from pipe flange and fasteners. Clean, prep, and recoat affected flange and fasteners.
A)	E10		RHTF	(A)	Moderate sump floor-to-wall deterioration observed in the concrete FOR sump.	Long	Consider installing a SS tank or lining the concrete pit and testing it annually.
	E13		RHTF		The wall mounted pipe support associated with the has a wood shim between the pipe and the support and the pipe is not secured.	Long	Repair/modify pipe support so the pipeline is secured, and the use of a wood shim is eliminated.
	E14		RHTF		is constructed out of threaded pipe and joints from Sump 7 to Tank 15/16.	Long	Replace pipe segment with welded pipe
	E15		RHTF		The section of from Is threaded and not supported adequately. The pipeline spans that are unsupported measure 23 ft, 22 ft, and 20 ft.	Long	Provide additional pipe supports at 9-ft on center per industry standard.
	E16		RHTF		Metal-to-metal contact was observed on the FOR pipeline within the electrical room between the pipe and pipe support.	Long	Provide Teflon pad or polymeric half rounds to eliminate metal-to-metal contact between the pipe and the support.
	E17		RHTF		There are four brass/bronze (low melting point) valves where the piping ties into the FOR-trench piping.	Long	Replace valves with Class 150 carbon steel ball valves.
	E18		RHTF		Three pipe support on the FOR pipeline within the trench has become displaced and is no longer supporting the piping.	Long	Reposition the pipe support and Teflon pad to properly support the piping.
	E19		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
	E20		RHTF		Threaded pipe nipple was noted on the Tank 16 FOR sample pipeline.	Long	Replace threaded connection with a welded connections and Class 150 carbon steel ball valve with flanged ends.
	E22		RHTF		Pipe support on the FOR line within the trench has become displaced and is no longer supporting the piping. Support is also shimmed by a piece of wood.	Long	Provide a new pipe support that fully supports the piping.
	E24		RHTF	90 ×	Tank sample lines do not have tank isolation valves (skin valves) as close <u>as o</u> ractical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
	E28		RHTF		The 4 ToR pipeline within the pipe trench is being supported with a piece of wood.	Long	Provide new metal pipe support with Teflon pads to eliminate metal-to-metal contact.
	E29		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
	E30		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
	E31		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
	E33		RHTF		Metal-to-metal contact is present at three locations between the FOR pipeline and pipe supports.	Long	Provide coated U-bolts and Teflon pads between the pipeline and supports at all three locations.
				30.			

					Table 12 (Sorted) - FOR Findings and Recommendations		
Item No.	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Location	Description	Urgency	Recommended Repairs
(b) (3) (	E34		RHTF	(b) (3)	Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell and/or nozzle. The tank isolation valves are located approximately 30 ft from tank shell/nozzle.	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
A)	E35		RHTF	(A)	The is covered with plastic within the AFF Sump #4.	Long	Remove plastic covering and inspect the pipeline for corrosion or damage.
	E39		RHTF		The 4 FOR pipeline is not supported for a span of ft.	Long	Provide additional pipe supports at no greater than 14-ft on center per industry standard.
	9E3		RHTF		The is not supported for a span of a pproximately 28 ft.	Long	Provide additional pipe support at 14-ft on center per industry standard.
	E37		RHTF		Tank sample lines do not have tank isolation valves (skin valves) as close as practical to the tank shell an <u>d/or nozzle.</u>	Long	Provide tank isolation valves, DBB valves, adjacent to the tank nozzle.
	E40		RHTF		Metal-to-metal contact between the support within the FOR trench.	Long	Provide Teflon pad to eliminate metal-to-metal contact between the pipe and the support.
	E41		RHTF		Metal-to-metal contact between the support within the FOR trench.	Long	Provide Teflon pad to eliminate metal-to-metal contact between the pipe and the support.
	E42		RHTF		Metal-to-metal contact between the and pipe support within the FOR trench.	Long	Provide Teflon pad to eliminate metal-to-metal contact between the pipe and the support.
	E49		RHTF		Metal-to-metal contact between and pipe support.	Long	Provide coated U-bolt and isolation Teflon pad between pipe and support to eliminate metal-to-metal contact.
	E50		en		is constructed with grooved mechanical fittings. Product staining was noted at FOR	Long	The grooved mechanical fittings do not meet current military criteria. Replace the piping system with welded pipe. Urgent maintenance is required at grooved fittings where fuel weeps are evident.
	E51		3		Pipe support supporting the damaged and the frame is bent.	Long	Replace damaged pipe support.
	E52		3		Metal-to-metal contact between and pipe support.	Long	Provide coated U-bolt and isolation Teflon pad between pipe and support to eliminate metal-to-metal contact.
	E52		3		Metal-to-metal contact between and pipe support.	Long	Provide coated U-bolt and isolation Teflon pad between pipe and support to eliminate metal-to-metal contact.
	E53 Table H	HT-2 HT-3	3		Coating failure and heavy corrosion on FOR  Table H in API 570 report for exact locations.	Long	Gean, prep, and recoat pipeline in affected area.
	E58		8		Moderate coating failure and minor corrosion was noted on the 8-FOR penetration sleeve just below the 3 staircase.  Some minor corrosion was noted on at this location as well. Water infiltration at pipe sleeve was observed.	Long	Gean, prep, and recoat affected areas on the pipeline and penetration sleeve. Provide fuel resistant caulking around sleeve penetration to prevent water infiltration through concrete wall.
	E29		3		Moderate coating fail <u>ure and corrosion was observed on the FOR-riser pipe just outside</u> 3 door.	Long	Clean, prep, and recoat affected areas on the flanges.
	E61		3 to TK S-311		Excessive vegetation was observed around the from Tank S-311 to the underground pipeline transition at antrance.	Long	Perform routine trimming/cutting of vegetation away from pipeline.

	Recommended Repairs	Modify wooden stairway to eliminate contact with pipeline.	Provide insulating flange kits on flanges.	This piping repair is being performed as part of the "FLC POL Pipeline Repairs" project (E-Project Work Order No. 1615884). The temporary pipe clamps are being removed and pipeline segment is being replaced with a pipe pup.
	Urgency	Long	Long	Other
Table 12 (Sorted) - FOR Findings and Recommendations	Description	Wooden pipe crossover staircase is in contact with the	DBB valve outside of the secondary containment and thermal relief valve flanges are not equipped with proper insulating flange kits.	Three temporary pipe clamps on 4 FOR nipeline within trench adjacent to S-23. Pipe clamp lengths are 6 16 8 Also, UTT indicates pipe wall loss in this area over 55% metal loss is present.
	Location	(b)	(3) (A	)
	Geographic Area	TK S-311	TK S-311	RHTF
	SGH Report Cross Reference			
	Appendix C - API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	E62	E65 and E66	E44 E45 E46
	Item No.	(b) (	3) (A)	

page 197

	ı	
<	ı	
<b>S</b>	ı	
M	ı	
EN	I	
TEA	I	
TEN	I	
STEA	I	
STEA	l	
STEN	l	
YSTEA	l	
YSTEN		
SYSTEA		
SYSTEA		
SYSTEA		
SYSTEN		
R SYSTEA		
R SYSTEN		
ER SYSTEN		
ER SYSTEN		
FER SYSTEN		
FER SYSTEN		
FER SYSTEN		
SFER SYSTEN		
SFER SYSTEN		
<b>VSFER SYSTEN</b>		
NSFER SYSTEN		
NSFER SYSTEN		
ANSFER SYSTEN		
ANSFER SYSTEN		
ANSFER SYSTEN		
RANSFER SYSTEN		
RANSFER SYSTEN		
RANSFER SYSTEN		
TRANSFER SYSTEN		
TRANSFER SYSTEN		
TRANSFER SYSTEN		
L TRANSFER SYSTEM		
L TRANSFER SYSTEN		
EL TRANSFER SYSTEN		
EL TRANSFER SYSTEN		
IEL TRANSFER SYSTEN		
JEL TRANSFER SYSTEN		
<b>UEL TRANSFER SYSTEN</b>		
UEL TRANSFER SYSTEN		
FUEL TRANSFER SYSTEN		
FUEL TRANSFER SYSTEN		
FUEL TRANSFER SYSTEN		

	Recommended Repairs	Replace support.	Replace support.	Replace support.	Replace support.	Replace support.	Replace Support.	Replace Support or modify to properly support pipe.	Replace Support.	Replace Support.	Replace Support.
ations	Urgency	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent
Table 13 (Sorted) - FOR Pipe Support Findings and Recommendations	Description	Actively dripping, medium-high corrosion, metal to metal contact, corroded at pipe support interface			Corroded, intact, metal to metal contact, only top anchor to wall present, lower part of bracket not in contact w/ wall	Not supporting pipe, no anchorage to wall at top, metal to metal contact	No guide, support broken so pipe is at end of am	No contact w/ pipe	No sleeve on U-bolt, U-bolt corroded to delamination, significant corrosion at base plate and anchors	Front support flange bent from apparent impact, U-bolt displaced on pipe, not U-shaped.	Support completely deformed, removed from base plate
	Location	(b)	(3		(A)						
	Geographic Area	3	e	3	3	3	3	3	3	3	8
	SGH Report Cross Reference					0 1					
	Appendix C - API 570 Report – Cross Reference Defidency (InterSpec, LLC)					Table E2	Table E2			Table E2	E51 Table E2
	Item No.	(b)	(3	) (	A)	S 1				s s	

			Table 14 (S	Sorted) - Validation of Defici	Table 14 (Sorted) - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
(b)	16-TG-19	RHTF	(b)	Threaded Small Bore Valve	Remove 2" threaded bronze gate valve. Provide 2" carbon steel Class 150 ball valve.	Urgent	Same finding was observed. Concur with 2016 recommendation.
(3)	16-TG-2	RHTF	(3) (	Threaded Small Bore Valve	Remove 2" threaded bronze gate valve. Provide 2" carbon steel Class 150 ball valve.	Urgent	Same deficiency observed. Concur with 2016 recommendation.
(A)	16-TG-5	RHTF	A)	Corroding Pipe Support	Remove, provide, and install the bottom 1 ft column of pipe supports 47 and 48. Provide temporary support before repairs.	Urgent	Same deficiency observed. Concur with 2016 recommendation.
	16-TG-20	RHTF		Failing Gasket	Remove the failing gasket on the 3" blind flange. Provide and install new gasket.	Urgent	Did not observe failing gasket during this inspection. However, observed lack of engagement on fasteners at this flange during inspection. This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	16-UGPH-3	Harbor Tunnel		Threaded Small Bore Pipe/Valve	Remove four threaded low point drain (LPD) assemblies and one threaded high point vent (HPV) assembly. Provide welded/flanged LPD and HPV assemblies with schedule 80 carbon steel pipe and Class 150 ball valves. LPDs and HPVs are located near the UGPH wall.	Urgent	Same finding observed. Concur with 2016 recommendation. In addition, refer to F24.020 and F24.021 for more information.
	18-TG-34	RHTF		Threaded Small Bore Pipe/Valve	Remove 1 ft of 3/4" threaded pipe and 3/4" gate valve. Provide 3/4" welded/flanged schedule 80 carbon steel pipe and 3/4" flanged carbon steel Class 150 ball valve.	Urgent	A shorter pipe nipple is now installed with 1/4 ball valve but still contains threaded fittings. Product staining was noted at threaded connections. Urgent repair should be to disassemble threaded joints, clean, retape, and reassemble to prevent future weeps.  Note: This is programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
	18-TG-59	RHTF		Threaded Small Bore Pipe/Valve	Remove 1" threaded pipe and gate valve. Provide 1" welded/flanged schedule 80 carbon steel pipe and 1" flanged carbon steel Class 150 ball valve.	Urgent	Same finding observed. Concur with 2016 recommendations. Note: This is programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
	18-UGPH-10	Harbor Tunnel		Threaded Small Bore Pipe/Valve	Remove four threaded low point drain (LPD) assemblies and one threaded high point vent (HPV) assembly. Provide welded/flanged LPD and HPV assemblies with schedule 80 carbon steel pipe and Class 150 ball valves. LPDs and HPVs are located near the UGPH wall.	Urgent	Same finding observed. Concur with 2016 recommendation. In addition, refer to JP5.026 for more information.

			Table 14 (	Table 14 (Sorted) - Validation of Defici	tion of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-LRUT-1 32- LRUT-2	Harbor Tunnel	(b) (3) (A)	Corrosion at Bulkhead	Remove, provide, and install 10 ft 32" pup piece to eliminate the corroded areas in the bulkhead. This will involve cutting out the concrete surrounding the pipe in the bulkhead. The pipe is currently anchored to the bulkhead using welded on collars that are cast in place in the concrete. The piping will need to be reanchored as part of the repair.	Urgent	Not able to verify without performing LRUT at this location. It is unknown whether this has been repaired. If repair has not been performed, concur with 2016 recommendation.
(b) (	16-TG-3	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same deficiency observed. Concur with 2016 recommendation.
3) (A	16-TG-4	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same deficiency observed. Concur with 2016 recommendation.
<b>4</b> )	16-TG-12	RHTF	e. v	Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	16-TG-13	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	16-TG-16	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. were also observed to be floating during this inspection. Concur with 2016 recommendation.
	16-UGPH-2	Harbor Tunnel		Coating Repair	Recoat 400 ft of failing coating on the 16" piping between the UGPH and 2.	Long	Same finding observed. Concur with 2016 recommendation. Note that the corrosion in this area is approximately 500 linear
	18-TG-1	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding observed. Concur with 2016 recommendation.
	18-TG-5	RHTF		Missing Guide at Pipe Support	Provide guide for pipe support.	Long	Same finding observed. Guide is missing at the 7 oʻclock position. Concur with 2016 recommendation.
	18-TG-12	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	18-TG-16	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	18-TG-18	RHTF		Lifting Lug	Out off lifting lug and perform magnetic particle testing. Recoat after testing.	Long	Same finding was observed. Concur with 2016 recommendation.
	18-TG-21	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding was observed. Concur with 2016 recommendation.
	18-TG-22	RHTF		Corrosion on Sleeve	Install drip shield above pipe.	Long	Moderate coating failure is now present. Concur with 2016 recommendation. In addition, remove corrosion and recoat piping.

Recommendation Reports   Control				Table 14 (	orted) - Validation of Defic	encies from the 2016 and 2019 Inspection and Benair	of Red Hill	Dinelines Report
RHTF Components Replace 1 1/2" plastic ball valve with Class 150 Components threaded pile and fittings.  Socket Weld Remove, provide, and install 6 ft 18" pup piece to Long Intraded pile and fittings.  RHTF Corrosion Replace pile support Recoal bottom of pipe at Long Engineering will be required for the repair design.  RHTF Socket Weld Remove, provide, and install 8 ft 18" pup piece to Long Engineering will be required for the repair design.  RHTF Socket Weld Remove, provide, and install 8 ft 18" pup piece to Long Pipe Support 7 grade pipe support Recoal bottom of pipe at Long Pipe Support 7 grade pipe support. Provide new Long Remove, provide, and install 6 ft 18" pup piece to Long Remove, provide, and install 6 ft 18" pup piece to Long Remove, provide, and install 6 ft 18" pup piece to Long Pipe Support 7 growled, and install 6 ft 18" pup piece to Long Remove, provide, and install 6 ft 18" pup piece to Long Pipe Support Provide subport. Provide such provide and piece to Long Pipe Support Provide similar to close gap between the pipe and Long Pipe Support Provide similar to close gap between the pipe and Long Pipe support.  Harbor Tunnel Remove, provide, and install 6 ft 18" piping Capiting Capiting Repair Recoat 4" bind flange. Provide 4" weld Long Pipe support. Provide similar capiting on the 18" piping Capiting Capiting Repair Recoat 5ft of failing Capiting Capiting Capiting Capiting Repair Recoat 5ft of failing Capiting Capiting Capiting Capiting Repair Recoat 5ft of 18" piping.  Lunnel RHTF RHTF ROSUNG Repair Recoat 5ft of 18" piping.  Long RHTF ROSUNG Repair Recoat 5ft of 18" piping.  Long RHTF RHTF ROSUNG Repair Recoat 5ft of 18" piping.  Long Support Provide and install 4 ft 18" pup piece to Long Femove provide, and install 4 ft 18" pup piece to Long Femove provide 4" weld reck flange.  RHTF RECOATING REPAIR RECOAT 5ft of 18" piping.  LONG Support Provide and Install Provide 4" weld REMOVED STANDARD RECOAT 5ft of 18" piping.  LONG STANDARD REMOVED STANDARD RECOAT 5ft of 18" piping.  LONG STANDARD REMOV	Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
RHTF Corrosion RHTF Socket Weld Remove, provide, and install 8." tee. The repair Welded Saddle Pipe Remove, provide, and install 18." tee. The repair Remove, provide, and install 18." tee. The repair Lifting Lug RHTF RHTF RHTF RHTF RHTF RHTF RHTF RHTF		18-TG-40	RHTF	(b) (3) (A)	Non-Standard Components	Replace 1 1/2" plastic ball valve with Class 150 carbon steel ball valve. Replace 7 ft of small bore threaded pipe and fittings with welded carbon steel pipe and fittings.	1200	Valve has been replaced but threaded piping still exists. Concur with replacing threaded pipe with welded and reroute out of the way of walking path, golf car or rail path.  Note: This repair is currently programmed for repair as part of the FV21 Emergent Pipeline Repair Project.
RHTF Corrosion Replace pile support. Recoat bottom of pipe at Long RHTF Socket Weld RIMINATE Corrosion Replace pile support. Recoat bottom of pipe at Long Riminate the socket welds. RHTF RHTF Socket Weld Riminate the socket welds. RHTF Lifting Lug RHTF RHTF Roating Pipe Support Recoat Adol to failing casting. RHTF Roating Pipe Support Recoat Adol to failing casting on the 18" piping Long RHTF Recoat Adol to failing casting on the 18" piping Long RHTF RHTF Recoating Repair Recoat 400 ft of failing casting on the 18" piping Long Recoat 5ft of 18" piping. Long Recoat 6ft 18" pup piece to Long Provide shims to close gap between the pipe and Long pipe support. Provide shims to close gap between the pipe and Long Recoat 400 ft of failing casting on the 18" piping Long Tunnel Dent Recoat 400 ft of failing casting on the 18" piping Long Recoat 5ft of 18" piping. Long Renove, provide, and install 4ft 18" pup piece to Long Renove, provide, and install 4ft 18" pup piece to Long Renove, provide, and install 4ft 18" pup piece to Long Renove, provide, and install 4ft 18" pup piece to Long Renove, provide, and install 4ft 18" pup piece to Long Renove, provide, and install 4ft 18" pup piece to Long Seating Repair Recoat 5ft of 18" piping. Long Renove non-standard flange. Long Renove non-standard lange. Lon		18-TG-41	RHTF		Socket Weld	Remove, provide, and install 6 ft 18" pup piece to eliminate the socket welds.		Same finding was observed. At the time of our inspection coating was removed at this location presumably for repair. Concur with 2016 recommendation.
RHTF         Corrosion         Replace pipe support Recoat bottom of pipe at Pipe Support 67 during Tank Gallery recoat.         Long           RHTF         Socket Weld         Remove, provide, and install 6 ft 18" pup piece to eliminate the socket welds.         Long           RHTF         Welded Saddle Pipe eliminate the socket welds.         Remove, provide, and install 4 ft 18" pup piece to eliminate the socket welds.         Long           RHTF         Lifting Lug         Remove, provide, and install 4 ft 18" pup piece to eliminate the socket welds.         Long           RHTF         Hoating Pipe Support         Provide shims to close gap between the pipe and pipe support.         Long           Harbor         Threaded Pipe         Provide shims to close gap between the pipe and pipe support.         Long           Harbor         Threaded Pipe         Remove threaded 4" blind flange. Provide 4" weld congression that the pipe and pipe support.         Long           Harbor         Coating Repair         Recoat 400 ft of failing coating on the 18" piping.         Long           Tunnel         Dent         Remove, provide, and install 4 ft 18" pup piece to long eliminate the dent.         Long           Harbor         Coating Repair         Recoat 5 ft of 18" piping.         Long           RHTF         Rocating Repair         Remove non-standard flange. Provide and install         Long		18-TG-44	RHTF		Corrosion	Remove, provide, and install 18" tee. The repair will require piping rework to fit a new tee. Engineering will be required for the repair design.		Same finding observed. Concur with 2016 recommendations. Coating was removed during inspection presumably for repairs.
RHTF Socket Weld Remove, provide, and install 6 ft 18" pup piece to eliminate the socket welds.  Welded Saddle Pipe Remove, provide, and install 6 ft 18" pup piece to Support Bupport Provide new plipe support. Cut off lifting lug and perform magnetic particle Long pipe support.  RHTF Floating Pipe Support pipe support.  Floating Pipe Support provide shims to close gap between the pipe and leng and le		18-TG-45	RHTF		Corrosion	Replace pipe support. Recoat bottom of pipe at Pipe Support 67 during Tank Gallery recoat.		Same finding observed. Concur with 2016 recommendations.
RHTF         Welded Saddle Pipe Support         Remove, provide, and install 4 ft 18" pup piece to support. Provide new ple support.         Long Same finding observer ple support. Drovide shims to close gap between the pipe and perform magnetic particle and perform magnetic particle control of lifting lug and perform magnetic particle control of lifting back and perform magnetic particle control of lifting lug and perform magnetic particle control of lifting observed provide shims to close gap between the pipe and control of pipe support.         Long came finding observed and finding observed and install dender.         Same finding observed and finding observed and install dender.         In pall value with threaded Pipe control of failing cating on the 18" piping.         Long came finding observed and finding observed and install dender.         Long came finding observed and finding observed and install dender.         Same finding observed and finding observed and finding observed and install dender.         Long cating finding observed and finding observed and finding observed and finding observed and finding observed standard Flange.         Remove non-standard flange.         Remove non-standard flange.         Long cate finding observed and finding obse		18-TG-46	RHTF		Socket Weld	Remove, provide, and install 6 ft 18" pup piece to eliminate the socket welds.		Same finding observed. Concur with 2016 recommendations. Coating was removed at the time of our inspection presumably for repair.
RHTF         Lifting Lug         Cut off lifting lug and perform magnetic particle testing. Recoat after testing.         Long         Same finding observer testing.           RHTF         Hoating Pipe Support         Provide shims to close gap between the pipe and perform the pipe and pipe support.         Long         Same finding observer finding coating Repair         Remove threaded 4" blind flange. Provide 4" weld finding observer finding obser		18-TG-49	RHTF			Remove, provide, and install 4 ft 18" pup piece to eliminate the saddle pipe support. Provide new pipe support.		Same finding observed. Concur with 2016 recommendations.
RHTF         Floating Pipe Support         Provide shims to close gap between the pipe and pipe support.         Long         Same finding observed and finding observed and same finding observed and same finding observed and same finding observed.           Harbor         Threaded Pipe         Remove threaded 4" blind flange. Provide 4" weld than the support.         Long         Same finding observed and fittings with the support.           Tunnel         Coating Repair         Remove threaded 4" blind flange. Provide 4" weld than the UGPH and support.         Long         Same finding observed fitting support.           Harbor         Dent         Remove, provide, and install 4 ft 18" pup piece to long.         Long         Same finding observed finding fin		18-TG-56	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.		Same finding observed. Concur with 2016 recommendations.
Harbor Threaded Pipe Remove threaded 4" blind flange. Provide 4" weld Tunnel Threaded Pipe Remove threaded 4" blind flange. Provide 4" weld Tunnel Tunnel Dent Remove, provide, and install 4 ft 18" pup piece to Long Same finding observer eliminate the dent.  Coating Repair Recoat 5 ft of 18" piping.  Long Same finding observer coating Repair Recoat 5 ft of 18" piping.  Long Same finding observer Long Same finding observer leminate the dent.  Long Same finding observer Long Same finding observer leminate the dent.  Long Same finding observer Recoat 5 ft of 18" piping.  Long Same finding observer Long Same finding observer lambor Recoat 5 ft of 18" piping.  Long Same finding observer Recoat 5 ft of 18" piping.  Long Same finding observer lambor Same Same finding observer lambor Same finding observer lambor Same Same finding observer lambor Same Same Same Same Same Same Same Sa		18-TG-58	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.		Same finding observed. Concur with 2016 recommendations.
Harbor Threaded Pipe Remove threaded 4" blind flange. Provide 4" weld Long threaded fittings with neck flange.  Coating Repair Recoat 400 ft of failing coating on the 18" piping Long Same finding observer eliminate the UGPH and 2.  Long Same finding observer eliminate the dent.  Coating Repair Recoat 5ft of 18" piping.  Long Same finding observer Long Same finding observer Recoat 5ft of 18" piping.  Long Same finding observer Long Same finding observer Recoat 5ft of 18" piping.  Long Same finding observer Recoat 5ft of 18" piping.  Long Same finding observer Same finding observer Long Same finding observer Standard Flange Remove non-standard flange. Provide and install Long Same finding observer Standard Hange.		18-TG-60	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.		Same finding observed. Concur with 2016 recommendations.
Harbor Tunnel Coating Repair Recoat 400 ft of failing coating on the 18" piping Long Tunnel Dent Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.  Coating Repair Recoat 5 ft of 18" piping. Long Long Tunnel Coating Repair Recoat 5 ft of 18" piping. Long Remove non-standard flange. Provide and install Long standard Weld neck flange.		18-UGPH-1	Harbor Tunnel		Threaded Pipe	Remove threaded 4" blind flange. Provide 4" weld neck flange.	3,540	Did not observe 4 threaded blind flange. There is a 1-linch threaded fittings with a ball valve between 1 ball valve with welded/flanged fittings and pipe.
RHTF     Dent     Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.     Long       Harbor     Coating Repair     Recoat 5 ft of 18" piping.     Long       Harbor     Coating Repair     Recoat 5 ft of 18" piping.     Long       Tunnel     Non-Standard Flange     Remove non-standard flange. Provide and install standard weld neck flange.     Long		18-UGPH-11	Harbor Tunnel		Coating Repair	Recoat 400 ft of failing coating on the 18" piping between the UGPH and 2.		Same finding observed. Concur with 2016 recommendation.
Harbor Tunnel     Coating Repair     Recoat 5 ft of 18" piping.     Long       Harbor Tunnel     Coating Repair     Recoat 5 ft of 18" piping.     Long       RHTF     Non-Standard Flange     Remove non-standard flange.     Long		18-LRUT-1	RHTF		Dent	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.		Same finding observed. Concur with 2016 recommendation.
Harbor Coating Repair Recoat 5 ft of 18" piping. Long India RHTF Remove non-standard flange Standard Hange Standard weld neck flange.		18-LRUT-2	Harbor Tunnel		Coating Repair	Recoat 5 ft of 18" piping.		Same finding observed. Concur with 2016 recommendation.
RHTF Remove non-standard flange Standard weld neck flange.	7 S.	18-LRUT-4	Harbor Tunnel		Coating Repair	Recoat 5 ft of 18" piping.		Same finding observed. Concur with 2016 recommendation.
		32-TG-1	RHTF		Non-Standard Flange	Remove non-standard flange. Provide and install standard weld neck flange.		Same finding observed. Concur with 2016 recommendation.

			Table 14 (	Sorted) - Validation of Defic	Table 14 (Sorted) - Validation of Deficiencies from the 2015 and 2019 Inspection and Renair of Red Hill Pinelines Renort	of Red Hill	Pinelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-TG-3	RHTF	(b) (3	Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket welds.	Long	Deficiency was not identified. Confirmation on repair is needed. If repair has not been performed, recommend repair per 2016 recommendation.
	32-TG-4	RHTF	3) (A)	Dresser Coupling	Remove deteriorating gasket on the Dresser coupling. Provide and install new gasket? Stress analysis?	Long	Deteriorated gasket was not observed during this inspection. Eight lugs on the upstream side of the dresser coupling are installed backwards and are not per manufacturer's detail. Rotate lugs for correct installation.
	32-TG-6	RHTF		Corrosion	Recoat bottom of pipe at Pipe Support 28 during Tank Gallery recoat. Section of pipe support may need to be removed to recoat.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-7	RHTF		Non-Standard Flanges	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream downstream of the flange set.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-8	RHTF		Patch plate	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream downstream of the 6" diameter patch plate.	Long	Same finding observed. Visual inspection did not indicate area of concern during this inspection. Concur with 2016 recommendation.
	32-TG-9	RHTF		Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-10	RHTF		Patch plate	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream downstream of the 12" diameter patch plate.	Long	Same finding observed. Visual inspection did not indicate are of concern during this inspection. Concur with 2016 recommendation.
	32-TG-11	RHTF		Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-13	RHTF		Coating Removal / Unknown Repair Scope	Remove 5 ft of coating and inspect.	Long	Area has been recoated. Inactive pitting observed between 0.050 and 0.100 inches deep. Continue coating maintenance to deter further corrosion.
\$ <u>_</u> \$	32-TG-14	RHTF		Floating Pipe Support	Provide shims to close gap between the pipe and pipe support.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-15	RHTF		Coating Removal / Unknown Repair Scope	Remove 5 ft of coating and inspect.	Long	Area has been recoated. Inactive pitting observed between 0.050 and 0.100 inches deep. Continue coating maintenance to deter further corrosion.
	32-TG-17	RHTF		Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-20	RHTF		Non-Standard Flange	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream downstream of the flange set.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-21	RHTF		Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendation.

			Table 14 (	Table 14 (Sorted) - Validation of Defici	tion of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-TG-24a 32-TG-24b 32-TG-24c	RHTF	(b) (3) (A	Corrosion Dent/Gouge Corrosion	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded/dent area. *Note: 32-TG-24a, 32- TG-24b, and 32-TG-24c have been combined into one repair recommendation.	Long	Same finding observed. Concur with 2016 recommendation. Coating has been applied to arrest corrosion.
	32-TG-27	RHTF	<b>(</b> )	Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket welds.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-2932- TG-30 32-TG- 3132-TG-32 32-TG-33	RHTF		Corrosion, Non-Standard Repair, Coating Removal	Remove, provide, and install 30 ft 32" pup piece. Pup piece shall extend approximately 4 ft upstream of Pipe Support 70 and approximately 4 ft downstream of Pipe Support 69. *Note: 32-TG-29 through 32-TG-34 have been combined into one repair recommendation.	Long	Same finding observed. Concur with 2016 recommendation. Coating has been applied to arrest corrosion.
	32-TG-36	RHTF		Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-37	RHTF		Tunnel Support	Investigate if supports are load bearing on the piping?	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-38	RHTF		Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-39	RHTF		Socket Weld	Remove, provide, and install 4 ft 32" pup piece to eliminate the socket weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-TG-40	RHTF		Deadleg	Remove, provide, and install 4 ft 32" pup piece to eliminate the deadleg.	Long	Same finding observed. Concur with 2016 recommendation.
	32-16-42	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Long	Area of inactive corrosion was observed. Pit depth of 0.196 – 0.200 inches was found. FFS ASME B31G (2012) Level 1 calculations were performed. Per calculations this flaw is acceptable. Coating system should be repaired at this location to arrest further external corrosion. Long term. Onsideration should be given to replacing pipe segment with a pup.
	32-TG-43	RHTF	¥: r	Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-1	Harbor Tunnel		Threaded Small Bore Pipe/Valve	Remove 2" threaded high point vent (HPV) assembly. Provide welded/flanged HPV assembly with schedule 80 carbon steel pipe and Class 150 ball valve.	Long	Same finding observed. Some product staining was noted but active weeping was not observed. Concur with 2016 recommendation. Recommend high point vent be monitored in until repair can be performed.
	32-A2A3-3	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 5 ft of coating and inspect.	Long	Minor pitting was observed at this location ranging from 0 50-0.080 inches. Repair coating to arrest further corrosion.
	32-A2A3-4	Harbor Tunnel		Coating Repair	Recoat 3 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.

			Table 14 (5	Table 14 (Sorted) - Validation of Defici	tion of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
(b)	32-A2A3-6	Harbor Tunnel	(b) (	Coating Repair	Recoat 3 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
(3) (	32-A2A3-7	Harbor	3) (#	Coating Repair	Recoat 4 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
A)	32-A2A3-8	Harbor	4)	Coating Repair	Recoat 3 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-9	Harbor		Coating Repair	Recoat 1 ft of failing coating at the weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-10	Harbor		Coating Removal / Unknown Repair Scope	Remove 8 ft of coating and inspect.	Long	Pitting was observed at this location approximate pit depth of 0.120 inches. Repair coating at this location to arrest corrosion.
	32-A2A3-12	Harbor Tunnel		Coating Repair	Recoat 16 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-13	Harbor Tunnel		Coating Repair	Remove 24 ft of wrap coating and recoat.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-14	Harbor		Coating Removal / Unknown Repair Scope	Remove 3 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-15	Harbor		Coating Removal / Unknown Repair Scope	Remove 12 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-16	Harbor Tunnel		Coating Repair	Recoat 10 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-17	Harbor Tunnel		Coating Repair	Recoat 4 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-18	Harbor Tunnel		Coating Repair	Recoat 15 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-22	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating at weld.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-24	Harbor Tunnel		Coating Repair	Recoat 10 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-25	Harbor Tunnel		Coating Repair	Recoat 3 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-28	Harbor Tunnel		Coating Repair	Recoat 3 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-29	Harbor Tunnel		Coating Repair	Recoat 6 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-30	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-31	Harbor Tunnel		Coating Repair	Recoat 4ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.

			Table 14 (	Sorted) - Validation of Defici	Table 14 (Sorted) - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
(b)	32-A2A3-33	Harbor Tunnel	(b) (	Gockspring	Remove, provide, and install 32" pup piece to eliminate the Clockspring repair.	Long	Same finding observed. Concur with 2016 recommendation.
(3)	32-A2A3-34	Harbor Tunnel	3) (A	Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
(A)	32-A2A3-35	Harbor	<del>(</del> )	Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-36	Harbor		Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-37	Harbor		Coating Repair	Recoat 12 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-38	Harbor Tunnel		Coating Repair	Recoat 6 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-39	Harbor Tunnel		Coating Repair	Recoat 8 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-40	Harbor Tunnel		Coating Repair	Recoat 2 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-41	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-42	Harbor Tunnel		Coating Repair	Recoat 20 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-43	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Gean, inspect, and recoat approximately 75 ft of piping between Pipe Support 595 and the bulkhead.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-44	Harbor Tunnel		Gockspring	Remove, provide, and install 32" pup piece to eliminate the Clockspring repair.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-45	Harbor Tunnel		Coating Repair	Recoat 10 ft of failing coating.	Long	Same finding observed. Inspection observed minimum corrosion and pitting at this area (pit depths 0.030 – 0.060 inches). Concur with 2016 recommendation.
	32-A2A3-46	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 15 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-47	Harbor Tunnel		Coating Repair	Recoat 6 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-48	Harbor Tunnel		Coating Repair	Recoat 20 ft of failing coating.	Long	Same finding observed. Concur with 2016 recommendation.
	32-A2A3-49	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 30 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	32-UGPH-2	Harbor Tunnel		Dent	Remove, provide, and install 4 ft 32" pup piece to eliminate the dent.	Long	Same finding observed. Concur with 2016 recommendation.

1900	
REPORT	
ECTION	
EM INSP	
ER SYSTI	
TRANSF	
FUEL	

			Table 14 (5	Sorted) - Validation of Defici	Table 14 (Sorted) - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-ИGРН-6	Harbor Tunnel	N/A	Threaded Small Bore Pipe/Valve	Remove three threaded low point drain (LPD) assemblies and one threaded high point vent (HPV) assembly. Provide welded/flanged LPD and HPV assemblies with schedule 80 carbon steel pipe and Class 150 ball valves. LPDs and HPVs are located near the UGPH wall.	Long	Same finding observed. Concur with 2016 recommendation.
	32-UGPH-7	Harbor	N/A	Coating Repair	Recoat 400 ft of failing coating on the piping between the UGPH and 2.	Long	Same finding observed. Concur with 2016 recommendation.
	32-LRUT-3	Harbor Tunnel	(b) (	Coating Removal / Unknown Repair Scope	Remove 8 ft of coating and inspect.	Long	Same finding observed. Concur with 2016 recommendation.
	TK10-TG-2	RHTF	(3)	Non-Standard Flange	TBD	Long	Replace flange with an ASME B16.5 rated flange and fitting.
	TK12-TG-1	RHTF	(/	Non-Standard Flange	TBD	Long	Replace flange with an ASME B16.5 rated flange and fitting.
	TK13-TG-1	RHTF	۱)	Non-Standard Flange	TBD	Long	Replace flange with an ASME B16.5 rated flange and fitting.
	TK16-TG-2	RHTF		Non-Standard Flange	TBD	Long	Replace flange with an ASME B16.5 rated flange and fitting.
	TK19-TG-1	RHTF		Pipe Support	Repair pipe support corroding steel and spalling concrete.	Long	Same conditioned identified in July 2021 inspection. Concur with 2016 recommendation.
	TK20-TG-1	RHTF		Pipe Support	Replace pipe support corroding steel.	Long	Same conditioned identified in July 2021 inspection. Concur with 2016 recommendation.
	16-TG-1	RHTF		Patch Plate	Remove, provide, and install 4 ft 16" pup piece to eliminate the patch plate.	Other	Repair has been completed. No further action required.
	16-TG-6	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Other	Lifting lug has been removed and is presumed NDE was also conducted.  Visual inspection did not indicate area of concern during inspection.  Recommend no further action.
	16-TG-7	RHTF		Pitting at Lifting Lug Weld	Remove coating and perform magnetic particle testing. Recoat after testing.	Other	Lifting lug has been removed and is presumed NDE was also conducted.  Visual inspection did not indicate area of concern during inspection.  Recommend no further action.
	16-TG-9	КНТЕ		Arc Strike	Remove coating and perform magnetic particle testing. Recoat after testing.	Other	Same finding was observed. It is presumed that NDE was conducted.  Visual inspection did not indicate area of concern during inspection.  Recommend no further action.
	16-TG-11	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Other	Same finding was observed. Visual inspection did not indicate area of concern during inspection. Recommend no further action.
	16-TG-15	RHTF		2" Diameter Patch Plate	Remove, provide, and install 16" tee. The repair will require piping rework to fit a new tee. Engineering will be required for the repair design.	Other	Same finding observed. Visual inspection did not indicate area of concern during this inspection. Concur with 2016 recommendation.
	16-TG-17	RHTF		Lifting Lug	Cut off lifting lug and perform magnetic particle testing. Recoat after testing.	Other	Same finding was observed. Visual inspection did not indicate area of concern during inspection. Recommend no further action.
	16-TG-21	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect. Coating has not been removed yet by coating removal contractor.	Other	This repair is currently programmed as part of the FV21 Emergent Pipeline Repair Project.

			Table 14 (	Sorted) - Validation of Defic	Table 14 (Sorted) - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	16-TG-23	RHTF	(b) (3	Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect, Coating was not adequately removed by coating removal contractor.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	16-ИGРН-1	Harbor Tunnel	3) (A)	Non-Standard Repair at Bulkhead	Remove, provide, and install 10 ft 16" pup piece to eliminate the non-standard repair in the bulkhead. This will involve cutting out the concrete surrounding the pipe in the bulkhead. The pipe is currently anchored to the bulkhead using welded on collars that are cast in place in the concrete. The piping will need to be reanchored as part of the repair.	Other	This repair is currently programmed as part of the FY2.1 Emergent Pipeline Repair Project.
	16-LRUT-1	Harbor Tunnel		Coating Removal/Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	Assumed to be completed based on coating at this location appearing relatively new. Current inspection did not identify this as an area of concern. No further action needed.
	16-LRUT-2	Harbor Tunnel		Coating Removal/Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	Assumed to be completed based on coating at this location appearing relatively new. Current inspection did not identify this as an area of concern. No further action required.
	18-TG-2	RHTF		Gouge/Dent	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	This repair has been completed. No further action required.
	18-TG-3	RHTF		Socket Weld	Remove, provide, and install 4 ft 18" pup piece to eliminate the socket weld.	Other	There is a 4 pup installed between and no socket weld. Repair is completed. No further action needed.
	18-TG-6	RHTF		Dent	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	Per 2019 Inspection and Repair of Red Hill Pipelines – Pipe Pedigree Report, no longer recommended for repair.
	18-TG-11	RHTF		Dent/Crease	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	18-TG-14	RHTF		Socket Weld	Remove, provide, and install 4 ft 18" pup piece to eliminate the socket welds.	Other	This repair has been completed. No further action required.
	18-TG-15	RHTF		Lifting Lug	Out off lifting lug and perform magnetic particle testing. Recoat after testing.	Other	Lifting lugs not identified during inspection. Most likely removed during previous repairs. No further action is recommended.
	18-TG-23	RHTF		Weld Overlay Repair	Remove weld overlay, remove coating, and perform magnetic particle testing. Recoat after testing.	Other	This was not identified during this inspection. No further action is recommended.
	18-TG-25	RHTF		Corrosion	Remove the corroded area of piping between the flange sets 20" downstream and 67" upstream of Pipe Support 20. Provide spool piece. Spool piece includes two rolled 45° elbows, elevation difference of 29", lateral difference of 31", and flange face to face distance of 87".	Other	This repair was being performed during our inspection. No further action required.
	18-TG-27	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.

			Table 14 (	Table 14 (Sorted) - Validation of Defic	tion of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	18-TG-28	RHTF	(b) (	Socket Weld	Remove, provide, and install 5 ft 18" pup piece to eliminate the socket welds.	Other	Same finding was observed. Concur with 2016 recommendation. NOTE: This segment of pipe was marked for repair during our inspection.
	18-1G-29	RHTF	3) (A)	Dresser Coupling	ТВD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	18-TG-30	RHTF		Dent	Remove coating and perform magnetic particle testing. Recoat after testing.	Other	Per 2019 Inspection and Repair of Red Hill Pipelines – Pipe Pedigree Report, no longer recommended for repair.
	18-TG-31	RHTF		Corrosion	Remove, provide, and install 4 ft 18" pup piece. Pup piece shall extend 2 ft upstream and 2 ft downstream of Pipe Support 30.	Other	This repair has been completed. No further action required.
	18-TG-32	RHTF		Socket Weld	Remove, provide, and install 4 ft 18" pup piece to eliminate the socket weld.	Other	This was repaired with a 2 pipe pup. No further action required.
	18-TG-33	RHTF		Dent	Remove coating and perform magnetic particle testing. Recoat after testing.	Other	Per 2019 Inspection and Repair of Red Hill Pipelines – Pipe Pedigree Report, no longer recommended for repair.
	18-TG-35	RHTF		Socket Weld	Remove, provide, and install 4 ft 18" pup piece to eliminate the socket welds.	Other	Repair has been completed. No further action is required.
	18-TG-37	RHTF		Socket Weld	Remove, provide, and install 4 ft 18" pup piece to eliminate the socket welds.	Other	Repair has been completed. No further action is required.
	18-TG-42	RHTF		Socket Weld	Remove, provide, and install 4 ft 18" pup piece to eliminate the socket weld.	Other	Repair has been completed. No further action is required.
	18-TG-48	RHTF		Corrosion	Remove, provide, and install 4 ft 18" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action is required.
	18-TG-50	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	This repair is currently programmed as part of the FY21 Emergent. Pipeline Repair Project.
	18-TG-51	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	18-TG-52	RHTF		Corrosion	Remove, provide, and install 4 ft 18" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action is required.
	18-TG-53 and 18-TG-54	RHTF		Corrosion	Remove, provide, and install 6 ft 18" pup piece. Pup piece shall extend 6 ft upstream and 2 ft downstream of Pipe Support 75. *Note: 18-TG-53 and 18-TG-54 have been combined into one repair recommendation.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.

			Table 14 (S	Sorted) - Validation of Defic	Table 14 (Sorted) - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pipelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	18-UGPH-2	Harbor	(b)	Dent/Gouge	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	This repair is currently programmed as part of the FY2.1 Emergent Pipeline Repair Project.
	18-UGPH-5	Harbor Tunnel	(3)	Dent	Term Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	18-UGPH-6	Harbor Tunnel	(A)	Dent	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	18-UGPH-7	Harbor Tunnel		Dent/Gouge	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	This repair is currently programmed as part of the FY2.1 Emergent Pipeline Repair Project.
	18-UGPH-9	Harbor Tunnel		Dent	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	Per 2019 Inspection and Repair of Red Hill Pipelines – Pipe Pedigree Report, no longer recommended for repair.
	18-LRUT-3	Harbor Tunnel		Dent	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent.	Other	This repair is currently programmed as part of the FY2.1 Emergent Pipeline Repair Project.
	18-LRUT-5	Harbor Tunnel		Dent/Gouge	Remove, provide, and install 4 ft 18" pup piece to eliminate the dent/gouge.	Other	This repair is currently programmed as part of the FY2.1 Emergent Pipeline Repair Project.
	18-LRUT-6	Harbor Tunnel		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Other	This repair is currently programmed as part of the FY21 Emergent Pipeline Repair Project.
	32-TG-5	RHTF		Corrosion	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Other	This repair has been completed. No further action required.
	32-TG-16	RHTF		Corrosion	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action required.
	32-TG-19	RHTF		Corrosion	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action required.
	32-TG-25	RHTF		Corrosion	Remove, provide, and install 4 ft 32" pup piece. Pup piece shall extend upstream and downstream of the corroded area.	Other	Repair has been completed. No further action required.
	32-TG-28	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	No issues noted during inspection. Coating system appears to be relatively new in this area. No further action is required.
	32-TG-35	RHTF		Coating Removal / Unknown Repair Scope	Remove 2 ft of coating and inspect.	Other	No issues noted during inspection. Coating system appears to be relatively new in this area. No further action is required.
	32-TG-41	RHTF		Dresser Coupling	TBD	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".

			Table 14 (	sorted) - Validation of Defici	Table 14 (Sorted) - Validation of Deficiencies from the 2016 and 2019 Inspection and Repair of Red Hill Pipelines Report	of Red Hill	Pinelines Report
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	32-TG-44	RHTF	(b) (3)	Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Other	Inspection did not identify areas of concern at this location. Coating was relatively new indicating recent repair. There was a repair sleeve and some inactive pitting (0.05 – 0.180 inches) at this location. No further action is required.
	32-TG-45	RHTF	(A)	Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Other	Inspection did not identify areas of concern at this location. Coating was relatively new indicating recent renair—inactive corrosion/pits identified halfway between with max pit of 0.120 inches. No further action is required.
	32-TG-46	RHTF		Coating Removal / Unknown Repair Scope	Remove 4 ft of coating and inspect.	Other	Inspection did not identify areas of concern at this location. Coating was relatively new indicating recent repair. Inactive corrosion/pits identified nea with max pit of 0.150 inches. No further action is required.
	32-A2A3-2	Harbor Tunnel		Dent/Gouge	Remove, provide, and install 4 ft 32" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-5	Harbor Tunnel		Corrosion	4' Pup Repair. Greater than 50% corrosion on Weld.	Other	Repair has been completed. No further action required.
	32-A2A3-11	Harbor Tunnel		Coating Repair	Recoat 4ft of failing coating.	Other	Repair has been completed. No further action required.
	32-A2A3-19	Harbor		Dent/Gouge	Remove, provide, and install 4 ft 32" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-20	Harbor Tunnel		Dent	Remove, provide, and install 4 ft 32" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-21	Harbor Tunnel		Dent	Remove, provide, and install 4 ft 32" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-23	Harbor		Dent	Remove, provide, and install 4 ft 32" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-26	Harbor		Dent	Remove, provide, and install 4 ft 32" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-27	Harbor		Dent	Remove, provide, and install 4 ft 32" pup piece to eliminate the dent.	Other	Repair has been completed. No further action required.
	32-A2A3-32	Harbor Tunnel		Corrosion	Remove, provide, and install 4 ft 32" pup piece to eliminate the corroded area.	Other	Repair has been completed. No further action required.
	TK2-TG-1	RHTF	N/A	Dresser Coupling	ТВД	Other	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".

			Table 4.4 f	city of a city live in a con-	Table 44 (Cancell Visited attack in the content of Cancell Otto Cancell Otto Cancell Otto Cancell Otto Cancell	I HILL A LILLY	1
Report Cross Reference Item No.	EEI Inspection and Repair of Red Hill Pipelines Report Item No.	Geographic Area	Location	Description	Recommendation Reported (2016)	Urgency	Recommendation (August 2022)
	TK4-TG-1	RHTF	N/A	Dresser Coupling	ТВD	Other B	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK6-TG-1	RHTF	N/A	Dresser Coupling	TBD	Other B	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK6-TG-1	RHTF	N/A	Dresser Coupling	ТВD	Other B	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK8-TG-1	RHTF	N/A	Dresser Coupling	TBD	Other B	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK10-TG-1	RHTF	N/A	Dresser Coupling	ТВО	Other B	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK10-TG-3	RHTF	N/A	Corrosion	Remove jacketing at Dresser Coupling and inspect.	Other 5	Insulation was removed at Tank 10 during July 2021 inspection and the area was inspected and documented. Add CUI inspection to the API 570 inspection program until dresser couplings are replaced or RHBFSF is defuel and decommissioned.
	TK14-TG-1	RHTF	N/A	Dresser Coupling	ТВО	Other B	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".
	TK16-TG-1	RHTF	N/A	Dresser Coupling	TBD	Other B	Evaluation of Dresser couplings was discussed at length in the SGH Red Hill Final Assessment Report dated April of 2022. Per the DoD Red Hill Bulk Fuel Storage Facility Defueling Plan, evaluation of the need for dresser couplings and removal of them if it can be safely done is "under contract".

Table 13   SOR Beard	y Recommended Repairs	Replace support.	t Replace support.		-	Replace support.	Replace support.	t Replace support.	Replace support or modify support to properly support pipe.	Replace support or modify support to properly support pipe.	Replace support.	Replace support.	Replace support.	Provide teflon pad, adjust support or shim to properly support pipe.	Provide teflon pad.	Provide teflon pad.	Provide teflon pad.	Provide teflon pad.	Provide teflon pad and coated U-bolt.	Provide teflon pad.	Provide teflon pad.
Appendix C – API SGH Geographic Cross Reference Cross Area No.  Deficiency (InterSpec, LLC) Reference 3  Table E2 3  Outside 3	Urgency	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Urgent	Long	Long	Long	Long	Long	Long	Long	Long
Appendix C – API SGH Report Geographic Cross Reference Cross Area Deficiency (InterSpec, LLC) Reference 3 3 3 3 3 4 Table E2 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		Actively dripping, medium-high corrosion, metal to metal contact, corroded at pipe support interface, photo taken for how wall support should look, labeled by others.	Highly corroded and deformed, no contact w/ pipe, labeled by ABA.	Corroded, in contact w/ pipe, labeled by ABA.	Corroded, intact, metal to metal contact, only top anchor to wall present, lower part of bracket not in contact w/ wall.	Not supporting pipe, no anchorage to wall at top, metal to metal contact.  API 570: Support anchor dislodged from tunnel wall.	No guide, support broken so pipe is at end of arm. API 570: Missing pipe clamp bolt (no isolation Teflon pad).	Bottom of bracket deformed from impact.	No contact w/ pipe.	No contact w/ pipe.	No sleeve on U-bolt, U-bolt corroded to delamination, significant corrosion at baseplate and anchors.	Front support flange bent from apparent impact, U-bolt displaced on pipe, not U-shaped. API 570: Loose U-bolt.	Support completely deformed, removed from baseplate. API 570: Damaged pipe support (impacted by a moving vehicle).					Good, metal to metal contact, labeled by others.	Missing U-bolt, metal to metal contact, labeled by others.		Good, metal to metal contact, labeled by others.
Appendix C - API SGH S70 Report Cross Reference Cross Peference (InterSpec, LLC) Reference Table E2  Table E2  E51  Table E2	Pipe Support No.	(b)	(3	3)	(A)					Y	,	No. 1								-	er e
Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC) Table E2 Table E2 Table E2 Table E2 Table E2	Geographic Area	8	e	3	8	6	3	3	8	8	8	8	Between door and sump	Outside 3	Outside 3	Outside 3	Outside 3	Outside 3	Outside 3	Outside 3	Outside 3
(b) (3) (A)	SGH Report Cross Reference													60							
(b) (3) (A)	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	9				Table E2	Table E2					Table E2	E51 Table E2								
	Item No.	(b)	(3	) (	(A)								V 2								

Appen S70 No. De (Inter Cross No. De (Inter Cr	Appendix C – API 570 Report –	HDS				L	
	Deficiency (InterSpec, LLC)	Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
	Table E2		(b) (3)	PSF-10	Good, metal to metal contact, labeled by others. API 570: Heavy corrosion at saddle-to-pipe crevice (no isolation Teflon pad).	Long	API 570: Reapir support. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal support locations.
			(A)	PSF-11	Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
				PSF-12	Good, metal to metal contact, labeled by others.	Long	Provide teflon pad.
				PSF-17	Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
-				PSF-18	Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
	Table E2			PSF-19	Very minor corrosion, overall good, metal to metal contact. API 570: Missing pipe clamp (no isolation Teflon pad).	Long	Provide teflon pad. API 570: Secure pipe clamp. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal support locations.
				PSF-20	Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
0 0				PSF-21	Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
				PSF-22	Very minor corrosion, overall good, metal to metal contact.	Long	Provide teflon pad.
				PSF-23	Additional corrosion at AB (anchor bolt) to concrete at lower bolts.	Long	Provide teflon pad.
				PSF-24	Additional corrosion at upper and lower bolts to concrete.	Long	Provide teflon pad.
				PSF-25	Metal to metal contact, corrosion at AB to concrete, minor corrosion at support.	Long	Provide teflon pad, clean corrosion and repaint with high-zinc paint.
				PSF-26	Metal to metal contact, corrosion at AB to concrete, minor corrosion at support.	Long	Provide teflon pad, clean corrosion and repaint with high-zinc paint.
				PSF-27	Metal to metal contact, corrosion at AB to concrete, minor corrosion at support.	Long	Provide teflon pad, clean corrosion and repaint with high-zinc paint.
				PSF-28	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-29	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-30	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-31	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
- 78				PSF-32	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-33	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-34	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-35	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-36	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
		60		PSF-37	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-38	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-39	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.
				PSF-40	Metal to metal contact, no corrosion at AB, minor corrosion at support.	Long	Provide teflon pad.

Appendix C – API 570 Report –	SGH	George	tour S and	Table 15 (Sorted) - Pipe Support Findings and Recommendations		
a)	)	Area		Condition Notes	Urgency	Recommended Repairs
		8	(b)	Metal to metal contact, otherwise good. API 570: Missing pipe strap at the support (no isolation Teflon pad).	Long	Provide teflon pad. API 570: Secure strap. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam
		c	(3)	Dec hollon and his not unil commented Coloma to hold mild on	000	structure or other metal to-metal support locations.
		n	(A	Has teffon pad, but not well supported, C-damp to hold guide on.	Long	Provide teflon pad.
		3	)	No teflon pad, not clearly supporting pipe.	Long	Provide teflon pad, adjust support or shim to properly support pipe.
20		3		No teflon pad, not supporting pipe.	Long	Provide teflon pad, adjust support or shim to properly support pipe.
		3		Gamp not attached, teflon pad w/ contact. API 570: Dislodged pipe clamp bolt (no isolation Teflon pad).	Long	API 570: Secure strap. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal support locations.
		3		Overall good. API 570: Dislodged pipe clamp bolt (no isolation Teflon pad).	Long	API 570: Secure strap. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal support locations.
		3		Gamp not attached. API 570: Dislodged pipe clamp bolt (no isolation Teflon pad).	Long	Attach clamp. API 570: Secure strap. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal tometal support locations.
		3		Gamp not attached. API 570: Dislodged pipe clamp bolt (no isolation Teflon pad).	Long	Attach clamp. API 570: Secure strap. Consider Teflon shims finsulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal tometal support locations.
		3		Gamp not attached. API 570: Dislodged pipe clamp bolt (no isolation Teflon pad).	Long	Attach clamp. API 570: Secure strap. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal tometal support locations.
		3		No teflon, no contact.	Long	Modify support to properly support pipe and provide teflon pad.

t	3	
2	•	
Ş	•	
٠	٠	
•	4	
٠	5	
2	-	
r	5	
ì	4	
ī		
ì		
ŏ	ı	
Ū	5	
2	•	
Ē	=	
4	=	
	7	
Ľ	j	
	315	
	1000	
	3000	
	TH 21 21 F	
	TEN SISIE	
COLUMN TO COLUMN	JULY OF THE	
MCEED CVCT	MASTER STORE	
A MICEED CVCT	AND THE STATE	
DANCEED CVCT	MANAGER STOLE	
TO A MCEED CVCTE	THE PARTY OF STREET	
TOANCEED	TO IC WALLEY OF THE	
EL TOANCEED CVCTE	SEL INGIGEN SISIE	
TOANCEED	OFF INAMOUND TO STORE	

Hem Cross Reference No. Deficiency (InterSpec, LLC)  (InterSpec, LLC)  (InterSpec, LLC)  (InterSpec, LLC)		SGH Report G Cross Reference	Area Area 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	Pipe Support No. (9) (9)		Urgency	Recommended Repairs	
	2		m		No teflon, no contact. API 570: Missing pipe clamp bolt (no isolation Teflon pad). Teflon pad in place, no sleeve on U-bolt. Teflon pad in place, no sleeve on U-bolt.	Long		
A)			m m m m m m m m		Teflon pad in place, no sleeve on U-bolt. Teflon pad in place, no sleeve on U-bolt.		Modify support to properly support pipe and provide teflon pad. API 570: Install bolts clamp. Consider Teflon shims/Insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal to-metal support locations.	2
			m m m m m m m		Teflon pad in place, no sleeve on U-bolt.	Long	Replace with coated U-bolt.	
			m m m m m m		we for the state of the state o	Long	Replace with coated U-bolt.	
			m m m m m		Tetion pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m m m m m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m m m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m m m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			mm		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
					Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
	7 7		m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	-
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
	8		m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
			်က		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites), spattered w/ effluent.	Long	Replace with coated U-bolt.	-
			8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
	- 47		8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
	- 22		3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_
			e		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	
			3		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.	_

l				ŀ				
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area		Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b			m		(t	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
) (	- 14		9		)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
3)			3		(3	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
(/		60	m		) (	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
A)			e		A)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			n			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			e			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
		St. 15	m		88-10	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		6 V2	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m	Ц		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		W	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			8		W	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
- 3			m		-	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
_			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			e l		V - 5	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		2 8	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m		<del></del>	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
_			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
W 8		A	3			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
2 2	20 20	¥ 19	n			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
12		23	e			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			8			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			3		88 8	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
× ×		X (3	3			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			3			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			en M			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites), corrosion at half round.	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
- V/			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			m			Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			•	L		Today and in place on closure and Habit was minor reacts of conscion (flor hiter)	-	Donlard Hoters of Hoter

ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geograp Area	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
b)				e	(b	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
(				m	) (	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
3)				3	3)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
(/			5	m	(,	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
1)				m	A)	Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
			9	m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				8		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites), minor corrosion to half round.	Long	Replace with coated U-bolt.
				m		Teflon pad in place, no sleeve on U-bolt, very minor spots of corrosion (flea bites).	Long	Replace with coated U-bolt.
								Replace teflon pad, replace with coated U-bolt. API 570:
	-					Tetion pad has been displaced, no sleeve on U-boit, very minor spots of corrosion		Consider Terion shims/insulation strips between pipe
	Table E2			n		(Tiea bites).	Long	and saddle or half-round Terion strips between pipe and
						APLS/U: Displaced bottom Terion pad.		-Beam structure or other metal to- metal support locations.
	Table E2			8		Teflon pad in place, no sleeve on U-bolt. API 570: Loose U-bolt.	Long	Replace with coated U-bolt.
				m		Teflon pad displaced, no sleeve on U-bolt.	Long	Replace teflon pad, Replace with coated U-bolt.
		V.		m		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				m		No sleeve on U-bolt, eflourescence spatla but no damage.	Long	Replace with coated U-bolt.
				8		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				3		No sleeve on U-bolt, corrosion at U-bolt to FOR pipe, aux pipe to top bar of support.	Long	Replace with coated U-bolt.
				8		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				3		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
		- 0	ĵ	8		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				3		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				3		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				3		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
			0	3		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				8		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				8		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
				e		No sleeve on U-bolt.	Long	Replace with coated U-bolt.
		L		c		No closure on II-holt	-	Domington width control II half

	Recommended Repairs	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace U-bolt and add sleeve.	Replace with coated U-bolt.	Replace U-bolt and add sleeve, clean and paint pipe.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.	Replace with coated U-bolt.												
Ì	Urgency	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long		Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	
Table 15 (Sorted) - Pipe Support Findings and Recommendations	Condition Notes	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt.	No sleeve on U-bolt, corrosion on outside of front support where sanitary sewer lines bolt to support.	No sleeve on U-bolt.	No sleeve on U-bolt, corrosion at U-bolt to pipe interface.	No sleeve on U-bolt.	No sleeve on U-bolt, repair area, corrosion at U-bolt to cross brace, repair paint on teflon pad.	No sleeve on U-bolt.	No sleeve on U-bolt, paint at repair.	No sleeve on U-bolt.																											
	Pipe Support No.	(b	) (	(3)	(A)																																		
	Geographic P Area	e	m	3	е .	m	m	8	e	m	m	m	3	m	9	3	3	e	3	en M	m	e	e	m	m	m	m	m	m	m	m	m	8	m	m	3	3	m	3
	SGH Report Cross Reference																																						20
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)																																						
-11		71-	1	(2)	(A)											92				97																			

	6000	ng Replace with coated U-bolt.	ng Replace with coated U-bolt, reattach to wall.	ng Replace with coated U-bolt.		Clean and repaint, replace grout under baseplates API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and HBeam structure or other metal tometal support locations.			Replace teflon pads where required, replace severely or corroded supports, remove and replace all wood supports.	ner None.	ner None.	her None.	her None.	her None.				$\neg$	ner None.	
	Urgency	Long	Long	Long	Long	Long	Long	Long	Long	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other
Table 15 (Sorted) - Pipe Support Findings and Recommendations		No sleeve on U-bolt.	No sleeve on U-bolt, not attached to wall.	No sleeve on U-bolt.	No sleeve on U-bolt.	Paint damaged, corroded, grout under baseplate, chipped and missing chunks. API 570: Missing Teflon spacer/pad between pipe and support.	2/3 U-bolts missing sleeve, very minor corrosion, 1/3 teflon pad missing.	All three missing teflon pad, lower line not touching support.	Not positively attached to ground (typical), not well seated on ground (typical), teflon pad not completely under pipe (typical), Total number lightly corroded: 28 Total number severely corroded: 10 Total number severely corroded: 10 Total number missing teflon pad: 5	Good, new, labeled by others.	Good, new, photo for example, on exit line, unlabeled.	Has teflon pad, supporting pipe adequately.	Clamp attached ok, teflon pad.   New come minor cracking overall and condition	Overall good.						
	Pipe Support No.	(b)	) (	3)	(/	4)			N/A	(b)	(3)	(A	)							
	Geographic Area	e	m	9	8	Between door and sump	ln sump	Insump	FOR Trench	Outside 3	Outside 3	e	e	3	3	m	m	m (	m	m
	SGH Report Cross Reference																			
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)					Table E2			E2 E5 E6 E13 E13 E15 E16 E22 E22 E28 E39 E40 E41 E41											
	No.	(	3)	(A	()					(b)	(3) (	A	)						Í	

	ı
0-	ı
	ı
	ı
LUI	
Litt	1
	ı
	1
	1
	1
	1
_	ı
	ı
_	ı
	1
_	1
4	1
	٤

	y Recommended Repairs	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.		None.			None.	
	Urgency	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other		Other			Other	
Table 15 (Sorted) - Pipe Support Findings and Recommendations	Condition Notes	Overall good.	Overall good, photo shows dank area on support is dirty, not corrosion.	Overall good.		Overall good.			Overall good.																		
	Support No.	(b	) (	3)	()	۹)																					
	Pipe																							317	VI.		
	Geographic Area	m	e	3	3	3	3	3	3	3	3	3	9	3	3	3	3	3	3	3	3	Between	door and	duns	Between	door and	sump
	SGH Report Cross Reference		1 32		60	81 3								8 1			A.T.				A.T.						
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)				126																						
	Item No.	(b		3)	()	۹)											5V=3				5V=3						

-	
•	
$\sim$	
3EPO	
4	
_	
<	
$\simeq$	
_	
м	
~	
-	
2	
<	
_	
2	
ш	
_	
5	
Ž.	
S	
4	
4	
SF	
≥	
=	
_	
_	
亘	
≺	
_	
4	

				Table 16 (Sorted)	Table 16 (Sorted) - Concrete Sleepers Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.		Urgency	Recommended Repairs
(b)			Harbor Tunnel	(b)	Concrete has been chipped out on tank side around flange for JPS lines. In on opposite side.	Urgent	Replace concrete.
(3)			Harbor Tunnel	(3) (	Overall good, except line has been broken out on tanks side, no flange visible.	Urgent	Replace concrete.
(A)	Table E2		Harbor Tunnel	A)	Efflorescence at bottom, minor corrosion at saddle. API 570: Wood shim at saddle #231 (unknown reason, but no corrosion noted).	Long	API 570: Removed wood and install Teflon shim.
	B28 Table E2		Harbor Tunnel		Minor pitting and chipping at base overall good. API 570: Concrete saddle support (# 337) between between the pipe and the concrete saddle. Reason is unknown.	Long	API 570: Remove the 1/8" rods between the concrete support saddle and pipe. Conduct visual inspection of the interface. Consider a Teflon shim between saddle and pipe.
	Table E2		Harbor Tunnel		Minor pitting and chipping at base, overall good. API 570: Pipe is not in contact with saddle # 24 (floating pipe).	Long	API 570: Shim and monitor at next inspection.
			Harbor Tunnel		Corroded at baseplate.	Long	Monitor for deterioration.
	B46 Table E2		Harbor Tunnel		Pop out at backside w/ exposed and corroded rebar. API 570: Deteriorated saddle with rebar exposed (saddle #36).	Long	Chip out broken concrete, clean rebar and recast concrete. API 570: Repair concrete saddle.
			Harbor Tunnel		Poorly consolidated but solid at back bottom, both sides.	Long	Monitor for deterioration.
			Harbor Tunnel		Poorly consolidated but solid at back bottom, both sides.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at base back but solid, some corrosion to baseplate and saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at base back but solid, some corrosion to baseplate and saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at base back but solid, some corrosion to baseplate and saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at base back but solid, some corrosion to baseplate and saddle, baseplate not seated flush (typical).	Long	Monitor for deterioration.
	Table E2		Harbor Tunnel		Minor pitting and chipping at base, overall good.  API 570: Concrete pipe saddle # 110 is not engaged with pipe (floating pipe).	Long	API 570: Shim and monitor at next inspection.
	Table E2		Harbor Tunnel		Efflorescence at bottom. API 570: Concrete pipe saddle # 178 is not engaged with pipe (floating pipe).	Long	API 570: Shim and monitor at next inspection.
	B37 Table E2		Harbor Tunnel		Minor pitting and chipping at base, overall good. API 570: Wood shim installed on pipe between Teflon pad and concrete saddle in an attemnt to correct lack of support at concert saddle # 193 (Between ). Pipe is not fully and uniformly supported.	Long	API 570: Remove wood. Repair the concrete saddle support or provide a replacement steel support adjacent to this pipe support. Alternatively, the existing pipe support can be evenly shimmed with steel and Teflon pad to uniformly support the pipe.
			Harbor Tunnel		Saddle corrosion.	Long	Monitor for deterioration.
			Harbor Tunnel		Saddle corrosion.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Corrosion at saddle.	Long	Monitor for deterioration.

	į		
		•	
	Ę		
i			
į		i	
į	į		
i			

				Table 16 (Sorted)	Table 16 (Sorted) - Concrete Sleepers -		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.		Urgency	Recommended Repairs
(b			Harbor Tunnel	(b	Corrosion at saddle.	Long	Monitor for deterioration.
) (			Harbor Tunnel	) (	Corrosion at saddle.	Long	Monitor for deterioration.
(3)			Harbor Tunnel	3)	More corrosion at saddle.	Long	Monitor for deterioration.
) (/			Harbor Tunnel	()	Corrosion at saddle.	Long	Monitor for deterioration.
<b>A</b> )			Harbor Tunnel	۹)	Corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		More corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Corrosion at saddle, debris between saddle and pipe.	Long	Monitor for deterioration.
			Harbor Tunnel		Corrosion at saddle, debris between saddle and pipe.	Long	Monitor for deterioration.
			Harbor Tunnel		Corrosion on saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
	Table E2		Harbor Tunnel		Efflorescence at bottom, corrosion at saddle. API 570: Concrete pipe saddle # 256 is not engaged with pipe (floating pipe).	Long	Monitor for deterioration. API 570: Shim and monitor at next inspection.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Long	Monitor for deterioration.
			Harbor Tunnel		Steel corrosion and concrete breakout at back 1 side, exposed steel.	Long	Chip out broken concrete, clean rebar and recast concrete.
	Table E2		Harbor Tunnel		Efflorescence at back. API 570: Wood shim at saddle #231 (unknown reason, but no corrosion noted).	Long	API 570: Shim and monitor at next inspection.
			Harbor Tunnel		Top of pier chipped away, including under plate pipe saddle.	Long	Replace concrete.
			Harbor Tunnel		Minor breakout at flange of JP-5 line at 1 side.	Long	Replace concrete.
			Harbor Tunnel		Efflorescence and cracking but couldn't knock any concrete off, clearly infiltration, likely rebar corrosion.	Long	Chip out broken concrete, clean rebar and recast concrete.
-2				2			

				Table 16 (Sorted)	Sorted) - Concrete Sleepers - Pipe Support Findings and Recommendations			
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs	
(b) (	Table E2		Harbor Tunnel	(b) (3	Minor pitting and chipping at base, overall good.  API 570: Concrete pipe saddle # 481 is not engaged with pipe (floating pipe).	Long	API 570: Shim and monitor at next inspection.	
3) (A)	B38 Table E2		Harbor Tunnel	8) (A)	Minor pitting and chipping at base, overall good.  API 570: NPS 32 (F-76) pipe has a concrete pipe saddle #501 (Between not engaged with pipe (floating pipe). There is loose concrete aggregate between pipe and saddle. Borescope inspection in the cavity did not indicate corrosion/erosion at this area.	Long	API 570: Remove the loose concrete aggregate between pipe and saddle and shim with Teflon pad. Repair the saddle as needed. Monitor at next inspection.	- 1
	Table E2		Harbor Tunnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ), saddle supported on wood block and angles. API 570: Wood shim at saddle #502 (between steel wear plate and saddle).	Long	Replace saddle support. API 570: Remove wood and install Teflon shim.	
			Harbor Tunnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ), severely corroded saddle and plate on angles, base in standing water.	Long	Replace saddle and saddle support.	
			Harbor Tunnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ), corrosion on built up plates.	Long	Replace saddle.	
			Harbor Tunnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ), corrosion on built up plates (moderate) in standing water.	Long	Replace saddle.	
			Harbor Tunnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ), corrosion on built up plates (moderate) in standing water.	Long	Replace saddle.	
			Harbor Tunnel		Bend welded saddle on plate (typ), corrosion at plate and saddle (typ).	Long	Replace saddle.	
	B22 Table E2		Harbor Tunnel		Efflorescence at base. API 570: The concrete saddle (Saddle # 530) is cracked on the edge with large splint noted or about the 7 o' clock position.	Long	API 570: Repair the concrete saddle support.  Consider installing a Teflon pad between the saddle and pipe.	
wi 9	Table E2		Harbor Tunnel		Efflorescence at base but soil d. API 570: Corrosion on steel plate on saddle # 548 (there is steel plate between pipe and concrete saddle).	Long	API 570: Repair as needed/ monitor.	
			Harbor Tunnel		Saddle overhangs block, condition overall ok.	Other	None.	_
			Harbor Tunnel		Plate and saddle overhang block, condition overall ok.	Other	None.	-
			Harbor Tunnel	**	reate and saddle overnang block, condition overall ok, minor chipping at concrete edges.	Other	None.	
			Harbor Tunnel		Some plate corrosion, saddle not uniformly in contact w/ plate.	Other	None.	_
			Harbor Tunnel		Area broken out for steel pipe support base.	Other	None.	
			Harbor Tunnel		Overall good.	Other	None.	-
			Harbor Tunnel		Saddle overhangs support on back side wall (by Zin or so), front bottom of concrete chipped out for pipe support (metal) base, see photo PSC-5.	Other	None.	
			Harbor Tunnel		Moderately corroded.	Other	None.	
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	1 30
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	10.7
is a			narbor lunner	500	Millor pitting and chipping at base, overall good.	Jamo	None:	-

Heren No. 7076 Report - Cooks   Sofit Report   Appendix C - Adj				lable to (sorted	Sorted) - Concrete Sieepers Pipe Support Findings and Recommendations		
Harbor Tunnel Ha	Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	 Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Harbor Turnel Minor pitting and chipping at base, overall good. Harbor Turnel Minor pitting and chipping at base, ov	(b		Harbor Tunnel	(b	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good, efflorescence at Minor pitting and chipping at base, overall good, efflorescence at Minor pitting and chipping at base, overall good, efflorescence at Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at base, overall good.  Harbor Tunnel Minor pitting and chipping at ba	) (		Harbor Tunnel	) (	Chipping at top of sleeper, overall good.	Other	None.
Harbor Tunnel Ha	3		Harbor Tunnel	3	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good, efficrescence at bottom.  Harbor Tunnel Minor ptiting and chipping at base, overall good, efficrescence at bottom.  Harbor Tunnel Minor ptiting and chipping at base, overall good, efficrescence at bottom.  Harbor Tunnel Minor ptiting and chipping at base, overall good, efficrescence at bottom.  Harbor Tunnel Minor ptiting and chipping at base, overall good, efficrescence at bottom.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor Tunnel Minor ptiting and chipping at base, overall good.  Harbor	) (,		Harbor Tunnel	) (/	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.	A)		Harbor Tunnel	A)	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Honeycombing, overall good.  Minor pitting and chipping at base, overall good.	1 12		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Honeycombing, overall good.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Chipping at saddle under pipe, overall good.  Minor pitting and chipping at base, overall good.	(3. )		Harbor Tunnel		Honeycombing, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Chipping at saddle under pipe, overall good.  Minor pitting and chipping at base, overall good.	w 3		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Chipping at saddle under pipe, overall good.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.	CS 1		Harbor Tunnel		Chipping at saddle under pipe, overall good.	Other	None.
Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None
Minor pitting and chipping at base, overall good.  Chipped at front, overall good.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Chipped at front, overall good.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.	v		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Chipped at front, overall good.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Chipped at front, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Chipped at front, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Rebar corrosion.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Chipped at front, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Rebar corrosion.  Minor pitting and chipping at base, overall good.	. ,		Harbor Tunnel	x -2	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Rebar corrosion.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Rebar corrosion.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.	// ·		Harbor Tunnel	70 o	Rebar corrosion.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel	22 - 22	Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at top front, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at top front, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.	×. 4		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at top front, overall good.  Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at top front, overall good.	Other	None.
Minor pitting and chipping at base, overall good, efflorescence at bottom.  Minor pitting and chipping at base, overall good.			Harbor Tunnel	т.	Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.	(8.1		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.	N W		Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

				Table 16 (Sorted	Sorted) - Concrete Sleepers -		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.		Urgency	Recommended Repairs
(b)			Harbor Tunnel	(b	Minor pitting and chipping at top, overall good.	Other	None.
) (3)			Harbor Tunnel	) (3)	Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
(A)			Harbor Tunnel	(A)	Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at front, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
10			Harbor Tunnel	10	Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chiming at base, overall good.	Other	Notice.
			Harbor Tunnel		Minor pitting and chipping at base, overall good, efflorescence at	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
					minor pricing and emphing at east, over an good.	2	

Recommended Repairs						1724													(J.)				٠٠	20	124	2					2.4			,		
<u> </u>	None	None.	None.	None.	None.	None	None.	None.	None.	None.	None	None.	None.	None.	None.	None.	None	None.	None.	None	None	None.	None.	None.	None.	None.	None.	None	None.	None.	None.	None.	None.	None.	None.	None.
Urgency	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other
(Sorred) - Concrete Steepers - Pipe Support Findings and Recommendations ort No.	Minor nitting and chinning at hace overall good.		Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Overall good.	Overall good.	Minor pitting and chipping at base, overall good, efflorescence at bottom.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Overall good.	Overall good.	Plate not fully seated on concrete.	Overall good.	Overall good.	Pitted concrete at front.	Saddle on plate on large concrete block.	Overall good.	Overall good.	Overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Foam filled.	Overall good.	Overall good.	Minor pitting and chipping at base, overall good.	Efflorescence at bottom.	Efflorescence at bottom.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Efflorescence at bottom.
lable 16 (Soffed																																				
Geographic	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel
SGH Report Cross Reference																																				
Appendix C – API 570 Report – Cross Reference Deficiency	(InterSpec, LLC)																																			
Item No.	(t	) (	(3)	) ()	4)	1																														

_	
=	
9	
ο.	
111	
=	
-	
>	
5	
=	
_	
m	
~	
•	
S	
~	
=	
5	
•	
_	
S	
$\sim$	
5	
-	
4	
T	
Trans	
6	
-	
<	
ď	
~	
-	
-	
T	
=	
E	
4	

				Table 16 (Sorted)	Sorted) - Concrete Sleepers Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b			Harbor Tunnel	(b	Efflorescence at bottom.	Other	None.
) (			Harbor Tunnel	) (	Efflorescence at bottom.	Other	None.
3)			Harbor Tunnel	(3)	Minor pitting and chipping at base, overall good.	Other	None.
(/			Harbor Tunnel	) ( <i>i</i>	Efflorescence at bottom.	Other	None.
<b>A</b> )			Harbor Tunnel	۹)	Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel	)	Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at bottom, overall good.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom, some deterioration at bottom of sleeper but solid.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Deterioration at bottom but solid.	Other	None.
			Harbor Tunnel	). E	Efflorescence at bottom.	Other	None.
- 10			Harbor Tunnel		Deterioration at bottom but solid.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
2)			Harbor Tunnel		Efflorescence at bottom, some deterioration at bottom of sleeper but solid.	Other	None.
			Harbor Tunnel		Efflorescence at bottom w/ deterioration.	Other	None.
			Harbor Tunnel		Efflorescence at bottom w/ deterioration.	Other	None.
			Harbor Tunnel	VI.	Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
- 50			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Overall good.	Other	None.
			Harbor Tunnel		Deterioration at base, poorly consolidated at back bottom but solid.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Chipped at saddle under pipe.	Other	None.
			Harbor Tunnel	0.00	Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Efflorescence at bottom at back but solid.	Other	None.
			Harbor Tunnel		Efflorescence at bottom.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

4
0
$\sim$
REP
-
œ
-
<
Š
=
C
ш
SPE
S
-
<
~
<
ш
_
SYSI
$\sim$
S
9
ш
щ
S
>
=
ч.
9
=
_
FUEL

Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	Cross SGH Report e Cross Cross y Reference		Geographic				Recommended Repairs
(b) (3) (A)	1000		7000				Recommended Repairs
(b) (3) (A)			300				Recommended Repairs
		127	Area	Pipe Support No.	Condition Notes	Urgency	
		Harbor	Harbor Tunnel	(t	Poorly consolidated at back but solid.	Other	None.
		Harbor	Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor	Harbor Tunnel	(3)	Minor pitting and chipping at base, overall good.	Other	None.
		Harbor	Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Table E2		Harbor	Harbor Tunnel	۹)	Efflourenscence at back, but solid.	Other	None.
Table E2		Harbor	Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Table E2		Harbor	Harbor Tunnel		Deterioration at back.	Other	None.
Table E2					Efflorescence at back, but solid.		and the second control of the second control
	TIAN	Harbor	Harbor Tunnel		API 570: Wood shim at saddle #167 (between steel wear plate and saddle).	Other	API 570: Remove wood and install Teflon shim.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at back, but solid.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel	2_0	Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		More deteriorated, but still fairly solid, surface crumbling.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.
		Harbor	Harbor Tunnel		Cannot see anchorage, all others ok.	Other	None.
		Harbor	Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor	Harbor Tunnel		Efflorescence at bottom.	Other	None.
		Harbor	Harbor Tunnel		Deteriorated at bottom.	Other	None.
		Harbor	Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
		Harbor	Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

	Appendix C – API							_
Item No.	570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs	
(Ł			Harbor Tunnel	(b	Efflorescence at bottom.	Other	None.	
)			Harbor Tunnel	) (	Efflorescence at bottom.	Other	None.	
(3			Harbor Tunnel	3)	Efflorescence at bottom.	Other	None.	
) (			Harbor Tunnel	(#	Efflorescence at bottom.	Other	None.	
A)			Harbor Tunnel	۱)	Efflorescence at bottom, but solid.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, but solid.	Other	None.	
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
			Harbor Tunnel		Tefion saddle.	Other	None.	_
			Harbor Tunnel		Teflon saddle.	Other	None.	_
			Harbor Tunnel		Teflon saddle.	Other	None.	
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
9 99			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, corrosion at saddle.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	_
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	_
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	_
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	_
			Harbor Tunnel		Efflorescence at bottom, minor corrosion at saddle.	Other	None.	_
			Harbor Tunnel		Overall good.	Other	None.	17 1
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
. 10			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.	_
			Harbor Tunnel		Large breakout at front.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom.	Other	None.	-
. Tak			Harbor Tunnel		Efflorescence at bottom.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom.	Other	None.	
			Harbor Tunnel		Efflorescence at bottom.	Other	None.	_
			Harbor Tunnel		Efflorescence at bottom.	Other	None.	_
					931	-		

Appendix C – API   SGH Report   Gamma   Gamm	Geographic Area Harbor Tunnel	Pipe Support No. (a) (b) (c) (d)	ipe Support No.  Condition Notes  Efflorescence at bottom.  Efflorescence at bottom.  Efflorescence at bottom.	Urgency	Recommended Repairs
	Harbor Tunnel	(L.) (O.) (A.)	Efflorescence at bottom. Efflorescence at bottom. Efflorescence at bottom.		
	Harbor Tunnel	(0) (4)	Efflorescence at bottom.	Other	None.
	Harbor Tunnel		Efflorescence at bottom.	Other	None.
	Harbor Tunnel	(A)		Other	None.
	Harbor Tunnel	<b>A)</b>	Efflorescence at bottom.	Other	None.
1	Harbor Tunnel		Efflorescence at bottom.	Other	None.
Recommendation   Reco	Harbor Tunnel		Efflorescence at bottom.	Other	None.
1	Harbor Tunnel		Efflorescence at bottom.	Other	None.
	Harbor Tunnel		Efflorescence at bottom.	Other	None.
中	Harbor Tunnel		Overall good.	Other	None.
	Harbor Tunnel		Overall good.	Other	None.
中	Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel		Excessive efflorescence.	Other	None.
中	Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
中	Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
中	Harbor Tunnel Harbor Tunnel Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
中	Harbor Tunnel Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
中	Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
日本   日本   日本   日本   日本   日本   日本   日本	Harbor Tunnel		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
中	Hall DOI Hallici		Excessive efflorescence w/ efflorescence at bottom.	Other	None.
中	Harbor Tunnel		Overall good.	Other	None.
中	Harbor Tunnel		Efflorescence at bottom.	Other	None.
中	Harbor Tunnel		Efflorescence at bottom.	Other	None.
中	Harbor Tunnel		Efflorescence at bottom.	Other	None.
日本   日本   日本   日本   日本   日本   日本   日本	Harbor Tunnel		Continuous cast block at wall begins.	Other	None.
中	Harbor Tunnel		Efflorescence at back.	Other	None.
日本   日本   日本   日本   日本   日本   日本   日本	Harbor Tunnel		Efflorescence at back.	Other	None.
中	Harbor Tunnel		Efflorescence at back.	Other	None.
Ha   Ha   Ha   Ha   Ha   Ha   Ha   Ha	Harbor Tunnel		Efflorescence at back.	Other	None.
型 (型	Harbor Tunnel		Efflorescence at back.	Other	None.
	Harbor Tunnel		Efflorescence at back.	Other	None.
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Harbor Tunnel		Efflorescence at back.	Other	None.
E E E	Harbor Tunnel		Efflorescence at back.	Other	None.
1	Harbor Tunnel		Efflorescence at back.	Other	None.
H Ha	Harbor Tunnel		Efflorescence at back.	Other	None.
Har	Harbor Tunnel		Efflorescence at back.	Other	None.
	Harbor Tunnel		Efflorescence at back.	Other	None.
Hai	Harbor Tunnel		Efflorescence at back.	Other	None.
Hai	Harbor Tunnel		Efflorescence at back.	Other	None.
Hai	Harbor Tunnel		Efflorescence at back.	Other	None.
На	Harbor Tunnel		Efflorescence at back.	Other	None.
На	Harbor Tunnel		Efflorescence at back.	Other	None.

				Table 16 (Sorted)	Sorted) - Concrete Sleepers -		
	Annendix C - API						
	570 Report - Cross	SGH Report					
Item No.	Reference	Cross	Geographic	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
	Deficiency (InterSpec, LLC)	Reference					
(b			Harbor Tunnel	(H	Efflorescence at back.	Other	None.
) )			Harbor Tunnel	o)	Efflorescence at back.	Other	None.
			Harbor Tunnel	(3	Efflorescence at back.	Other	None.
			Harbor Tunnel	) (	Efflorescence at back.	Other	None.
A)			Harbor Tunnel	A)	Efflorescence at back.	Other	None.
			Harbor Tunnel	)	Efflorescence at back.	Other	None.
			Harbor Tunnel		Efflorescence at back.	Other	None.
			Harbor Tunnel		Efflorescence at back.	Other	None.
			Harbor Tunnel	-	Efflorescence at back.	Other	None.
			Harbor Tunnel		Efflorescence at back.	Other	None.
			Harbor Tunnel		Efflorescence at back.	Other	None.
			Harbor Tunnel		Poorly consolidated at back.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

	Recommended Repairs																																								
		None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.																									
	Urgency	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other																									
Table 16 (Sorted) - Concrete Sleepers - Pipe Support Findings and Recommendations	Pipe Support No. Condition Notes	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Has teflon pad unseated.	Teflon pad.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.	Minor pitting and chipping at base, overall good.
	Geographic p Area	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel	Harbor Tunnel																									
	SGH Report Cross Reference																																								
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)																																								
	Item No.	(b	) (	3)	()	۹)																																			

Minor pitting and chippin Concrete chipped at from Minor pitting and chippin					Table 16 (Sorted)	(Sorted) - Concrete Sleepers Pipe Support Findings and Recommendations	5	
(InterSpec, LLC)  Harbor Tunnel	Item No.	Appendix C – API 570 Report – Cross Reference	SGH Report	Geographic	Pipe Support No.		Urgency	Recommended Repairs
Harbor Tunnel		Deficiency (InterSpec, LLC)	Reference					
Harbor Tunnel	(t			Harbor Tunnel	(b	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel	) (			Harbor Tunnel	) (	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel	(3			Harbor Tunnel	3)	Minor pitting and chipping at base, overall good.	Other	None.
Harbor Tunnel	) (			Harbor Tunnel	(#	Minor pitting and chipping at base, overall good.	Other	None.
	A)			Harbor Tunnel	<b>Y</b> )	Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Overall good.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
	(/c			Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Concrete chipped at front.	Other	None.
	2 1			Harbor Tunnel		Concrete chipped at front.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
	100			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Poorly consolidated at back but solid.	Other	None.
				Harbor Tunnel		Poorly consolidated at back but solid.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Poorly consolidated.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		At corner welded saddle on plate, typical.	Other	None.
				Harbor Tunnel		At corner welded saddle on plate, typical.	Other	None.

				Table 16 (Sorted)	Sorted) - Concrete Sleepers Pipe Support Findings and Recommendations	dations		
	Appendix C – API							
Item No.	570 Report – Cross	SGH Report	Geographic	Pipe Support No.	Condition Notes	Ure	Urgency	Recommended Renairs
	Deficiency (InterSpec, LLC)	Reference	Area			<u> </u>		
(b	L		Harbor Tunnel	(b	At corner welded saddle on plate, typical.	ð	Other	None.
			Harbor Tunnel		At corner welded saddle on plate, typical.	ō	Other	None.
3)			Harbor Tunnel	(3)	At corner welded saddle on plate, typical.	ŏ	Other	None.
()			Harbor Tunnel		At corner welded saddle on plate, some overhang of saddle over plate.		Other	None.
۹)			Harbor Tunnel	۹)	Back to sleeper w/ cast in saddle type.	ō	Other	None.
Y			Harbor Tunnel		Overall good.	Ö	Other	None.
			Harbor Tunnel		Efflorescence at base, corrosion at saddle, ok w/ teflon pad.	Ö	Other	None.
			Harbor Tunnel		Poorly consolidated.	ŏ	Other	None.
			Harbor Tunnel		Poorly consolidated.	ō		None.
			Harbor Tunnel		Extremely poor consolidatation at base.	ō	Other	None.
			Harbor Tunnel		Efflorescence at base, poorly consolidated.	Õ	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	ő		None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	O	Other	None.
			Harbor Tunnel		Minor pitting and chipping at base, overall good.	O	Other	None.
			Harbor Tunnel		Very poorly consolidated.	Ö	Other	None.
			Harbor Tunnel		Poorly consolidated at lower lift.	ō	Other	None.
			Harbor Tunnel		Poorly consolidated at lower lift.	ō	Other	None.
			Harbor Tunnel		Poorly consolidated at lower lift.	ō	Other	None.
			Harbor Tunnel		Poorly consolidated at lower lift.	ō	Other	None.
			Harbor Tunnel		Poorly consolidated at lower lift.	ŏ	Other	None.
			Harbor Tunnel		Poorly consolidated at lower lift.	ð	Other	None.
			Harbor Tunnel		Efflorescence at base.	ŏ		None.
			Harbor Tunnel		Efflorescence at base, poorly consolidated, dried puddle at back base.		Other	None.
			Harbor Tunnel		Wet base, standing water from	ŏ	Other	None.
			Harbor Tunnel		Wet base, standing water from	ŏ	Other	None.
			Harbor Tunnel		Wet base, standing water from	Õ		None.
			Harbor Tunnel		Wet base, standing water from	Õ		None.
			Harbor Tunnel		Wet base, standing water from	Õ	Other	None.
			Harbor Tunnel		Wet base, standing water from	Õ		None.
			Harbor Tunnel		Wet base, standing water from	Ö		None.
			Harbor Tunnel		Wet base, standing water from	Õ		None.
			Harbor Tunnel		Wet base, standing water from	Õ		None.
			Harbor Tunnel		Wet base, standing water from	ő	Other	None.
			Harbor Tunnel		Wet base, standing water from	ð	Other	None.
			Harbor Tunnel		Wet base, standing water from	ŏ	Other	None.
			Harbor Tunnel		Overall good.	ð	Other	None.
			Harbor Tunnel		Poorly consolidated.	ő		None.
			Harbor Tunnel		Poorly consolidated.	ð	Other	None.
			Harbor Tunnel		Poorly consolidated.	Õ	Other	None.
			Harbor Tunnel		Poorly consolidated.	ő	Other	None.

Other None.					Table 16 (Sorted)	- Concrete Sleeners Pine Support Findings and Recommendations		
Harbor Tunnel Condy consolidated.  Poorly consolidated.  Minor pitting and chipping at base, overal good.  Harbor Tunnel Minor pitting and chipping at base, overa	Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference		Pipe Support No.		$\overline{}$	Recommended Repairs
Harbor Turnel Floorly concolidated.  Harbor Turnel Floorly concolidated.  Floorly concolidated.  Floorly concolidated.  Floorly concolidated.  Floorly concolidated.  Floorly concolidated.  Harbor Turnel Harbor Tu	(b			Harbor Tunnel	74	Poorly consolidated.	Other	None.
Harbor Turnel Ha	) (			Harbor Tunnel	V	Poorly consolidated.	Other	None.
Harbor Turnel Ha	3)			Harbor Tunnel	(3	Poorly consolidated.	Other	None.
Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Minor ptiting and chipping at base, overall good. Other Harbor Tunnel Mi	()			Harbor Tunnel	) (	Poorly consolidated.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and	۹)			Harbor Tunnel	A)	Poorly consolidated.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Wet on celling efflorescence, concrete rough around all pipe  Doverall good.  In standing water, deterioration at base.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Othe	l			Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Overall good.  Overall good.  In standing water, deterioration at base.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall go				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Other  Minor pitting a				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  In standing water, deterioration at base.  Minor pitting and chipping at base, overall good.  Overall good.  In standing water, deterioration at base.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Oth				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Overall good.  In standing water, deterioration at base.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Wet on ceiling, efforescence, concrete rough around all pipe  Overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  O				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Met on ceiling efflorescence, concrete rough around all pipe  Overall good.  In standing water, deterioration at base.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Oth				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Efflorescence at base, cracking at back, but solid.  Minor pitting and chipping at base, overall good.  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Oth				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  In standing water, deterioration at base.  Overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Minor pitting and chipping at base, overall good.  Other  Other				Harbor Tunnel		Efflorescence at base, cracking at back, but solid.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Wet on ceiling, efforescence, concrete rough around all pipe  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Wet on ceiling, efflorescence, concrete rough around all pipe  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Other  Other  Other  Minor pitting and chipping at base, overall good.  Other  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Wet on ceiling, efflorescence, concrete rough around all pipe  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Efflorescence at base.	Other	None.
Minor pitting and chipping at base, overall good.  Other  Wet on ceiling, efflorescence, concrete rough around all pipe  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Wet on ceiling efflorescence, concrete rough around all pipe  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Wet on ceiling efflorescence, concrete rough around all pipe  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Wet on ceiling, efflorescence, concrete rough around all pipe.  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Wet on ceiling, efflorescence, concrete rough around all pipe  Doverall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Wet on ceiling efforescence, concrete rough around all pipe penetrations.  Overall good.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Wet on ceiling, efforescence, concrete rough around all pipe penetrations.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Wet on ceiling, efflorescence, concrete rough around all pipe penetrations.  Overall good.  Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Wet on ceiling, efforescence, concrete rough around all pipe penetrations.  Overall good. In standing water, deterioration at base.  Overall good. Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Wet on ceiling, efflorescence, concrete rough around all pipe penetrations.  Overall good. In standing water, deterioration at base.  Overall good. Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Wet on ceiling, efflorescence, concrete rough around all pipe penetrations.  Overall good. In standing water, deterioration at base.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel	31 - 6	Minor pitting and chipping at base, overall good.	Other	None.
Determine the standing water, deterioration at base.  In standing water, deterioration at base.  In standing water, deterioration at base.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Wet on ceiling, efflorescence, concrete rough around all pipe	Other	None.
In standing water, deterioration at base.  In standing water, deterioration at base.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tinnel		Overall mod	Othor	dood
Minor pitting and chipping at base, overall good.  Overall good.  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		In standing water deterioration at base	Other	NOON
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor niting and chinning at base overall good	Other	None
Minor pitting and chipping at base, overall good.  Other  Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.  Other Minor pitting and chipping at base, overall good.  Other				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
Minor pitting and chipping at base, overall good.				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.
				Harbor Tunnel		Minor pitting and chipping at base, overall good.	Other	None.

				Table 16 (Sorted)	(Sorted) - Concrete Sleepers - Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency	SGH Report Cross Reference	Geographic Area			Urgency	Recommended Repairs
(b			Harbor Tunnel	(b	Minor pitting and chipping at base, overall good.	Other	None.
) (			Harbor Tunnel	) (	Minor pitting and chipping at base, overall good.	Other	None.
3)			Harbor Tunnel	3)	Minor pitting and chipping at base, overall good.	Other	None.
(/			Harbor Tunnel	(4	Minor pitting and chipping at base, overall good.	Other	None.
<b>4</b> )			Harbor Tunnel	(۲	Minor pitting and chipping at base, overall good.	Other	None.
			Harbor Tunnel		Poorly consolidated at back but solid.	Other	None.
			Harbor Tunnel		Minor consolidation issues.	Other	None.
			Harbor Tunnel		Minor consolidation issues.	Other	None.
			Harbor Tunnel		Minor consolidation issues.	Other	None.
			Harbor Tunnel		Minor consolidation issues.	Other	None.
			Harbor Tunnel		Efflorescence at base.	Other	None.
			Harbor Tunnel		Efflorescence at base.	Other	None.
į.			Harbor Tunnel		Overall good.	Other	None.
			Harbor Tunnel	3 2	Efflorescence at base.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel	5 - 10	Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
			Harbor Tunnel		Efflorescence at base but solid.	Other	None.
	ř.						

Overall good.  Saddle on plate on CIP tyy Overall good.  Efflorescence at base, wa Efflorescence					Table 16 (Sorted)	Sorted) - Concrete Sleepers Pipe Support Findings and Recommendations		
Content   Reference   Cross   Geographia   Paps Support No.   Condition Notes   Condition Notes   Content   Conten		Appendix C – API 570 Report – Cross	SGH Report					
Harbor Tunnel Coveral good.  Sadde on plate on CP type, saddle not welded flush to pipe. Other Harbor Tunnel Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Harbor Tunnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Tunnel Harbor Tunnel Bull to plates to be ad	Item No.	Reference Deficiency (InterSpec, LLC)	Cross	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Harbor Turnel Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Efflorescence at base, watermarks at base of CP trapecold. Other Harbor Turnel Base Attach at the CP trapecold of CP trape	(b)			Harbor Tunnel	(b)	Overall good.	Other	None.
Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Harbor Turnel Efforescence at base, watermarks at base of CP trapezoid. Other Harbor Turnel Harbor Turnel Base Afforescence at base, watermarks	(3			Harbor Tunnel	(3)	Saddle on plate on CIP type, saddle not welded flush to pipe.	Other	None.
Harbor Tunnel Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at base, watermaris at base of CP trapezoid. Other Efflorescence at				Harbor Tunnel	) (	Overall good.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, wat	A)			Harbor Tunnel	A)	Efflorescence at base.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Outer Efflorescence at base, wate				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Corosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  O				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Diates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at	7			Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Conrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Conrosion at saddle, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Dither Plates moderately corroded, efflorescence at base.  Other Plates moderately				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Other  Built up plates moderately corroded, efflorescence at base.  Dither  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Diates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Cornosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded server at base.  Other Plates moderately corroded server at base.  Other Plates moderately corroded server				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at b				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Dither  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Ot				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Dither  Noverall good.  Welded saddle on plate type, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Cornosion at saddle, efflorescence at base.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Oth				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Dates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Dates Plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Other  Overall good.  Other  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Other  Neleda saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Other  Nelded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Saddle on CIP sleeper, efflorescence at base.  Other  Other  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Other  Other  Other  Other  Other  Other  Plates moderately corroded, efflorescence at base.  Other  Ot				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Dither  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Saddle on CIP sleeper, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Other Efflorescence at base, watermarks at base of CIP trapezoid.  Other Efflorescence at base, watermarks at base of CIP trapezoid.  Other Cornosion at saddle, efflorescence at base.  Other Overall good.  Welded saddle on plate type, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Other  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Saddle on QP sleeper, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Saddle on GIP sleeper, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Cornosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Other  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Plates moderately corroded, efflorescence at base.  Other  Saddle on QIP sleeper, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid. Other Cornosion at saddle, efflorescence at base.  Efflorescence at base, watermarks at base of CIP trapezoid. Other Efflorescence at base, watermarks at base of CIP trapezoid. Other Cornosion at saddle, efflorescence at base.  Cornosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base. Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base. Other Plates moderately corroded, efflorescence at base. Other Saddle on CIP sleeper, efflorescence at base. Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on QP sleeper, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Overall good.  Weerall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on GIP sleeper, efflorescence at base.  Other Other				Harbor Tunnel		Corrosion at saddle, efflorescence at base.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on CIP sleeper, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Efflorescence at base, watermarks at base of CIP trapezoid.  Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on GIP sleeper, efflorescence at base.  Other Other Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None.
Corrosion at saddle, efflorescence at base.  Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on GIP sleeper, efflorescence at base.  Other				Harbor Tunnel		Efflorescence at base, watermarks at base of CIP trapezoid.	Other	None,
Overall good.  Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on GIP sleeper, efflorescence at base.  Other				Harbor Tunnel		Corrosion at saddle, efflorescence at base.	Other	None.
Welded saddle on plate type, efflorescence at base.  Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on GIP sleeper, efflorescence at base.  Other				Harbor Tunnel		Overall good.	Other	None.
Built up plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on GP sleeper, efflorescence at base.  Other				Harbor Tunnel		Welded saddle on plate type, efflorescence at base.	Other	None.
Plates moderately corroded, efflorescence at base.  Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on GP sleeper, efflorescence at base.  Other				Harbor Tunnel		Built up plates moderately corroded, efflorescence at base.	Other	None.
Plates moderately corroded, efflorescence at base.  Other Plates moderately corroded, efflorescence at base.  Other Saddle on GP sleeper, efflorescence at base.  Other				Harbor Tunnel		Plates moderately corroded, efflorescence at base.	Other	None.
Plates moderately corroded, efflorescence at base. Other Saddle on GP sleeper, efflorescence at base.	-7.			Harbor Tunnel		Plates moderately corroded, efflorescence at base.	Other	None.
Saddle on CIP sleeper, efflorescence at base.				Harbor Tunnel		Plates moderately corroded, efflorescence at base.	Other	None.
				Harbor Tunnel		Saddle on CIP sleeper, efflorescence at base.	Other	None.

				Table 16 (Sorted)	Table 16 (Sorted) - Concrete Sleepers - Pipe Support Findings and Recommendations	Findings and Recommendations			
Item No.	Appendix C – API 570 Report – Cross Reference Cross Deficiency Reference	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Notes	Urgency	Recommended Repairs	
(b)			Harbor Tunnel	(b ( <i>p</i>	Saddle type ok.		Other	None.	
) (;			Harbor Tunnel	(N)	Saddle type ok.		Other	None.	
3) (A			Harbor Tunnel	(3)	Saddle type ok, beyond PSC $596(c)$ pipes move horizontally and have individual supports.	s move horizontally and have	Other	None.	
(۱	230		8						

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -		
kem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition P	Urgency	Recommended Repairs
(b) (3)	B14 Table E2		Harbor Tunnel	(b) (3)	Severely corroded baseplate and bottom of column, loss of steel in column, delamination of baseplate, no grout pad, a connected to wall severely corroded. API 570: Coating failure and corrosion noted on the steel pipe supports at various locations. Noted on the base plate, on angle iron, and tunnel wall attachment points.	Urgent	Replace support.
(A)	B14 Table E2		Harbor Tunnel	(A)	Extreme corrosion w/ no or very little material at any number of locations.  API 570: Coating failure and corrosion noted on the steel pipe supports at various locations. Noted on the base plate, on angle iron, and tunnel wall attachment points.  Moderate corrosion on horizontal support attachment to wall (QTY 4).	Urgent	Replace support, support on minimum 6" raised concrete pier.
			Harbor Tunnel		Extreme corrosion $\mathbf{w}/$ no or very little material at any number of locations, active dripping.	Urgent	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-33	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, wall anchors not visible.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
		нт-32	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, complete deterioration through bottom front flange of both columns, extreme deterioration of anchor bolts over back flange of both columns.	Urgent	Replace support.
	Table E2	НТ-32	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, severe corrosion over entire support complete less of support at bottom of both columns and both flanges, delamination (severe) at baseplate, angles to wall severely deteriorated.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
	Table E2		Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, wall anchor not visible, flanges at angle column not attached to baseplate, severe delamination at baseplate.  API 570: Support wear plate to support not engaged (JP-5) (floating pipe).	Urgent	Replace support.
			Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme corrosion at baseplate and column flanges, appears unattached and detached when sounded.	Urgent	Replace support.
	Table E2		Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme delamination at baseplate, columns not attached due to extreme deterioration, JP-5 bracket to the wall deteriorated and detached.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
			Harbor	2 22	Severe corrosion w/significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.
			Harbor	- v	Severe corrosion w/significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations, column flange deformed.	Urgent	Replace support.

			Table 17	Table 17 (Sorted) - Frame Pipe Supports -		
Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
		Harbor Tunnel	(b)	Severe corrosion w/ significant loss of material at any number of locations, grout pad broken, loss of bearing.	Urgent	Replace support.
		Harbor Tunnel	(3) (	Extreme corrosion w/ no or very little material at any number of locations, JP-5 at wall.	Urgent	Replace support.
Table E2	НТ-26 НТ-28	Harbor	A)	Extreme corrosion w/ no or very little material at any number of locations, column flanges completely deteriorated at slab, baseplate is dust, JP-5 attachments to wall completed corroded - not attached at (1) side.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Urgent	Replace support.
		Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, extreme corrosion at bottom of column and significant loss of column flange section at baseplate interface.	Urgent	Replace support.
B32 Table E2	нт-26	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, column moderately corroded, JP-5 anchor to wall complete section loss.  API 570: Corrosion on pipe support at the tunnel wall attachment.	Urgent	Replace Support.
	нт-26	Harbor Tunnel		Extreme corrosion w/ no or very little material at any number of locations, moderate column corrosion, complete loss of section at JP-5 and anchor to wall on 1 side.	Urgent	Replace support.
		Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations, impacted and deformed column flanges.	Urgent	Replace support.
A7 A10 Table E1 Table E2	LAT-41 LAT-42	RHTF		Severe corrosion and significant loss of support at train-side column (photo), minor corrosion at center column baseplate, grout pad edges destroyed at center column baseplate (photo), severe corrosion and loss of material at beam near wall (photo) API 570: Metal to metal contact. No Teflon shims/insulation strip. Rail-ties wedged between pipe and saddle Corrosion on base of pipe support and I-beam.	Urgent	Replace support  Note: This support is currently programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
A7 Table E1 Table E2	LAT-38 LAT-40	RHTF		fican corros at F-2 ontacl	Urgent	Replace support  Note: This support is currently programmed for repair as part of the FY21 Emergent Pipeline Repair Project.
Table E2		Harbor Tunnel		Severe delamination at baseplate , anchor bolts and bottom of column, no grout, anchor bolts not straight.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Long	Replace support.
Table E2		Harbor		Baseplate corroded, not anchored, minor corrosion at angle to wall connection, corrosion at saddle on backside. API 570: No wear plate or Teflon pad between pipe and pipe support	Long	Anchor column to slab. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal support locations.
Table E2		Harbor Tunnel		Severe baseplate corrosion, severe corrosion at (1) brace to wall. API 570: No wear plate or Teflon pad between pipe and pipe support	Long	Repair brace to wall, anchor column to slab. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal support locations.

	Appendix C – API 570 Report –	SGH					
(b) (	Deficiency (InterSpec, LLC)	Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(3)			Harbor	(b) (3	Corrosion at baseplate and bottom of column, no grout pad/pier, column baseplate bears on slab mild corrosion over entire support severe corrosion at JP-5 bracket to wall (x1) at a 1 side, moderate corrosion at bracket to wall (x1) at botts to wall not uniformly flush tight to wall.	Long	Clean corrosion and repaint, replace anchorage to wall.
(A)			Harbor Tunnel	) (A	Corrosion at baseplate and bottom of column, top bolt not seated well at 2 side, no grout pad.	Long	Gean corrosion and repaint, replace anchorage to wall.
			Harbor	)	Baseplate corroded but ok, small grout pad surrounding top, braces covered w/ effluent from wall.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor Tunnel		Anchor bolts corroded, bottom of column moderately corroded, flange deformed, anchor bolts to wall moderately corroded.  API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Long	Clean corrosion and repaint, maintain in good condition. API 570: Repair.
			Harbor		Bottom of column moderately corroded, anchor bolts and baseplate covered w/concrete.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Minor corrosion at column bottom, anchor bolts (nuts) corroded.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		JP-5 braces to wall connection hidden, corroded.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderately-minor base of column corrosion, base plate corrosion, anchor bolts corrosion.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderately-minor column corrosion, anchors to wall not well seated, severe baseplate and anchor bolts corrosion.	Long	Replace support.
			Harbor		Mild column corrosion, moderately severe baseplate and anchor bolts corrosion, moderate JP-5 to wall corrosion.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate column corrosion, baseplate corrosion, moderate JP-5 to wall corrosion.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild column corrosion, moderately severe haseplate and anchor bolts corrosion, mild corrosion at paint damage, moderate a anchor bolts to wall at 1 side.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild column corrosion, moderately severe baseplate and anchor bolts corrosion, moderate at an anchor bolts to wall, both sides.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild column corrosion, moderately severe baseplate and anchor bolt corrosion, moderate a anchor bolts to wall, 1 side.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate column corrosion, severe anchor bolts corrosion, moderate at JP-5 anchor bolt to wall, deterioration of top flange, very severe a series anchor bolts to wall, both sides.	Long	Replace support.
v 30			Harbor Tunnel		Moderate column corrosion, severe anchor bolt corrosion, moderate anchor to wall, both lines 1 side.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild column corrosion, moderate anchor bolt and baseplate corrosion, mild at all bolts on wall.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild column corrosion, moderate anchor and baseplate corrosion, mild at baseplate in grout.	Long	Gean corrosion and repaint, maintain in good condition.

b	
TO COT O NOT	7
ă	1
ц	ä
Q	c
2	
S	٥
F	
Ļ	į
ă	•
Ū	5
NOPE	
3	
Ľ	4
Ų	7
CVCTEAN	:
d	:
	ì
ч	
š	2
TRANSE	ř
ď	è
۲	•
i	ŧ
4	5

	Recommended Repairs	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Replace support.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Anchor to wall at all locations.	Gean corrosion and repaint, maintain in good condition.	Replace support.	Gean corrosion and repaint, maintain in good condition.	Replace support.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Replace support.	Clean corrosion and repaint, maintain in good condition.	Install bearing pads, clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal support locations.
	Urgency	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long
Table 17 (Sorted) - Frame Pipe Supports Support Findings and Recommendations	Condition Notes	Mild column corrosion, moderate anchor bolt and baseplate corrosion.	Mild column corrosion, moderate anchor bolt and baseplate corrosion.	Moderate-severe column corrosion, moderate anchor bolt and baseplate corrosion, mild all anchor bolts to wall, except on 1 side (moderate).	Mild-moderate column corrosion, moderate baseplate and anchor bolt corrosion, mild anchor bolts to wall.	Moderate column corrosion, moderate anchor bolt and baseplate corrosion, mild anchor bolts to wall.	Mild column corrosion, moderate anchor bolt corrosion, welded connection to wall at JP-5 at 2 side, no nut at 1.	Moderate column corrosion, moderate anchor bolt and baseplate corrosion at 2 not tight.	Moderate-severe column corrosion, moderate anchor bolt and baseplate corrosion, ok anchor bolts to wall.	Moderate column corrosion, moderate anchor bolt and baseplate corrosion, ok anchor bolts to wall.	Moderate column corrosion, moderate-severe anchor bolt and baseplate corrosion.	Mild-moderate column corrosion, mild-moderate anchor bolt and baseplate corrosion, moderate both sides.	Mild column corrosion, moderate anchor bolt and baseplate corrosion, moderate anchor bolt at	Mild-moderate column corrosion, moderate anchor bolt and baseplate corrosion.	Mild-moderate column corrosion, moderate anchor holt and baseplate corrosion, moderate at 2, anchor bolt not visible at	Mild_column corrosion, moderate anchor bolt and baseplate corrosion, moderate both mild JP-5.	Moderate column corrosion, deformed flange, severe anchor bolt corrosion, moderate anchor bolt at JP-5, moderate anchor bolt at deterioration and corrosion.	New "T" and baseplate installed at severe column corrosion, mild corrosion to T, moderate to baseplate, mild corrosion to achor bolts to wall.	No saddles or bearing pads, baseplate and anchor bolts corroded, grout pad chipped, minor corrosion paint damage on support. API 570: No wear plate or Teflon pad between pipe and pipe support plate or Teflon pad between pipe support (JP-5). No wear plate or Teflon pad between pipe and pipe support (JP-5).
Table 17	Pipe Support No.	(b)	(3)	(A)															
	Geographic Area	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor Tunnel
	SGH Report Cross Reference																		HT-46
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)																		Table E2
	ltem No.	(b)	(3)	(A)															

Ŀ	-	
	c	
c	5	
Ğ	ī	
Ų	ū	
٥	ē	
5	5	
Š	2	
LAICOLA	5	
ū	ď	
Ğ	C	
u	ñ	
2	2	
•	=	
4	ŧ	
7	-	
Ų	ū	
ŀ	9	
	200	
	31315	
CVCTEAA	31315	
n	Ē	
n	Ē	
n	Ē	
n	Ē	
n	Ē	
n	Ē	
n	Ē	
TOAACEED	NAME OF THE	
TOAACEED	NAME OF THE	
n	NAME OF THE	

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3) (A	B17 Table E2		Harbor Tunnel	(b) (3)	Moderate corrosion at column, moderate at basenlate, anchor bolts not visible, moderate at 1P-5 anchor bolts (x1), moderate at API 570: Anchor type welded saddle was cut of the pipe (likely for previous repairs/mods). The existing weld attachment is only tack welded at two location (weaker).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Engineering assessment may be required to determine if this saddle support is sufficiently anchored.
۱)			Harbor	(A)	Moderate-severe at column, moderate-severe at anchor bolts and baseplate, mild at anchor bolts to wall.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate at column, moderate at anchor bolt and baseplate, mild at anchor bolts to wall.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate at column, moderate at anchor bolt and baseplate, grout pad damaged, mild at wall.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate at column, moderate at anchor bolt and baseplate, moderate at (1) anchor bolt to wall, mild at (3) anchor bolts to wall.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at anchor bolts to wall, moderate at baseplate anchor bolts and baseplate, severe corrosion at column.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
,			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, sever corrosion at column and anchor bolts to wall, grout pad chipped.	Long	Gean corrosion and repaint, maintain in good condition, replace lower column and grout pad.
			Harbor	~	Mild corrosion at any number of locations, may have efflorescence coating it, grout pad damage.	Long	Gean corrosion and repaint, repair grout pad, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
,			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, anchor bolt not tight.	Long	Gean corrosion and repaint, maintain in good condition.
0			Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt at baseplate not tight, anchor bolt a no nut.	Long	Replace support.
- 10			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.

Table 17 (Sorted) - Frame Pipe Supports - Support Findings and Recommendations	graphic Pipe Support Condition Notes Urgency Recommended Repairs	Index Moderate corrosion at any number of locations, may have efflorescence coating it, wood shim at baseplate.		Moderate corrosion at any number of locations, may have efflorescence coating it.  Long Clean corrosion and repaint, maintain in good condition.	Moderate corrosion at any number of locations, may have efflorescence coating it.  Long Clean corrosion and repaint, maintain in good condition.	Moderate corrosion at any number of locations, may have efflorescence coating it.  Long Clean corrosion and repaint, maintain in good condition.	Moderate corrosion at any number of locations, may have efflorescence coating it.  Long Clean corrosion and repaint, maintain in good condition.	Moderate corrosion at any number of locations, may have efflorescence coating it, configuration.		severe corrosion w/ loss of material at any number of locations, no nut. Long Replace support.	Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.  Long condition.	Mode	Moderate corrosion at any number of locations, may have efflorescence coating it, condition, remove shim and replace grout pad.	Moderate corrosion at any number of locations, may have efflorescence coating it.  Long Clean corrosion and repaint, maintain in good condition.	Moderate corrosion at any number of locations, may have efflorescence coating it, Long baseplate broken.		Mild corrosion at any number of places, may have efflorescence from wall coating it.  Long  Clean corrosion and repaint, maintain in good condition.	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Mild corrosion at any number of places, may have efflorescence from wall coating it.  Long Clean corrosion and repaint, maintain in good condition.	orbor Moderate corrosion at any number of locations may have efflorescence coating it
Table 17	Pipe Support No.	(b)	(3)	(A)														S0.		
	Geographic Area	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor
	SGH Report Cross Reference																			
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)																			
	77.									_	_							_		_

				Table 17	Table 17 (Sorted) - Frame Pine Supports		
	Appendix C – API	NBS					
Item No.	Cross Reference Deficiency (InterSpec, LLC)	Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b)	59 12 83		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.	Long	Clean corrosion and repaint, maintain in good condition.
(3) (			Harbor	(3)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
A)			Harbor Tunnel	(A)	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bentx2.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2	HT-44	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations. API 570: Corrosion on base of pipe support (attachment to tunnel floor).	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/Loss of material at any number of locations, corrosion on JP-5 braces, corrosion at	Long	Replace support.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Support wear plate to support not engaged (JP-5) (floating pipe).	Long	Clean corrosion and repaint, maintain in good condition. API 570: Shim and monitor at next inspection.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.

				Table 17	Table 17 (Sorted) - Frame Pine Supports -		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition P	Urgency	Recommended Repairs
(b)			Harbor Tunnel	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it	Long	Clean corrosion and repaint, maintain in good condition.
(3)			Harbor Tunnel	(3)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
(A)			Harbor Tunnel	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, anchor bolt bent, grout pad broken.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
* 77			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken $\mathbf{w}/\mathbf{wood}$ shim.	Long	Clean corrosion and repaint, maintain in good condition, remove shim and replace grout pad.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe $\cos nv/\log s$ of material at any number of locations, column flange deformed.	Long	Replace support.
W 38			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.

				Table 17	Table 17 (Sorted) - Frame Pine Supports -	v	
tem No.	Appendix C – API 570 Report – Cross Reference Deficiency	SGH Report Cross	Geographic Area	Pipe Support No.	Condition N	Urgency	Recommended Repairs
(b)	(iliterapped, the)		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(3)			Harbor	(3)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Glean corrosion and repaint, maintain in good condition.
(A)		НТ-36	Harbor	(A)	Severe corrosion w/ loss of material at any number of locations, water flowing starts.	Long	Replace support, support on minimum 6" raised concrete pier.
		НТ-36	Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
		HТ-29 HT-36	Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
* 7		НТ-36	Harbor		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support, support on minimum 6" raised concrete pier.
		НТ-36	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
		НТ-36	Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent.	Long	Replace support, support on minimum 6" raised concrete pier.
		HT-36	Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support, support on minimum 6" raised concrete pier.
		НТ-36	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
		НТ-36	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HТ-36 HТ-39	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier
	Table E2	HT-36 HT-39	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-36 HT-39 HT-41	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent and baseplate submerged. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
2	Table E2	НТ-36 НТ-39	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent and baseplate submerged. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-36 HT-39	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, grout pad broken, anchor bolt bent and baseplate submerged.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	НТ-36 НТ-38	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water, Corrosion on base of pipe support (attachment to tunnel floor).	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2	HT-36	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, grout pad broken w/ wood shim, water flowing ends.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports	S	
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition	Urgency	Recommended Repairs
(b)	Table E2	HT-36	Harbor Tunnel	(b)	Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
(3) (A	Table E2	HT-36	Harbor Tunnel	(3) (A	Severe corrosion w/ loss of material at any number of locations, no grout pad. API 570: Minor to moderate corrosion on the base plate due to standing water, anchor bolts on the base of plate are not secured down to the floor.	Long	Replace support, support on minimum 6" raised concrete pier.
)	Table E2		Harbor Tunnel	)	Severe corrosion w/ loss of material at any number of locations, grout pad broken w/ wood shim, anchor bolt bent. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent. API 570: Minor to moderate corrosion on the base plate due to standing water. No wear plate or Teflon pad between pipe and pipe support (JP-5).	Long	Replace support, support on minimum 6" raised concrete pier. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure or other metal tometal support locations.
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier
	Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflourrescense coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	B16 Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: Majority of the piping support in the harbor tunnel has tack-welded steel wear plates between pipe and pipe support. Few locations with metal-to-metal contact and some corrosion were noted on the Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair coating on the pipe and support. Provide a Teflon shim at location of metal-tometal contact points.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken, anchor bolt bent.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
	Table E2		Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier
	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.

Appen   S70   S7	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	HDS					
(b) (3) (A)		Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(3) (A)	Table E2		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
)	Table E2		Harbor Tunnel	(3) (A	Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
-	Table E2		Harbor	)	Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
	B25 Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken, anchor bolt bent w/ wood shim. API 570: Pipe support with anchor bolts not embedded in the concrete.	Long	Gean corrosion and repaint, maintain in good condition, remove shim and replace grout pad. API 570: Secure the anchor bolts to the base plate of the pipe support.
1	Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Gean corrosion and repaint, maintain in good condition.
1	Table E2		Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
1	Table E2		Harbor		Severe corrosion w/ loss of material at any number of locations. API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
-	Table E2		Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, no grout pad, connection to wall not visible.  API 570: Minor to moderate corrosion on the base plate due to standing water.	Long	Replace support, support on minimum 6" raised concrete pier.
			Harbor		Severe corrosion w/ loss of material at any number of locations, connection of the wall not visible.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, column flange deformed.	Long	Replace support.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -	S	
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency	SGH Report Cross	Geographic Area	Pipe Support No.	Condition	Urgency	Recommended Repairs
(b)	(InterSpec, LLC)		Harbor	(b	Moderate corrosion at any number of locations, may have efflorescence coating it	Long	Clean corrosion and repaint, maintain in good
(3)			Harbor	(3)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(A)			Harbor	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
,			Harbor	J	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
7 V			Harbor		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
	Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, anchor bolt bent.  API 570: Anchor bolts on the base of plate are not secured down to the floor	Long	Gean corrosion and repaint, maintain in good condition. API 570: Defer to next inspection (has grouting).
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
V-1			Harbor		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations, anchor bolt bent.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
,,,			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -	endations		
tem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition N	Urge	Urgency	Recommended Repairs
(b)			Harbor	(b)	Severe corrosion w/ loss of material at any number of locations.	O	Long	Replace support.
(3)			Harbor Tunnel	(3) (	Severe corrosion w/ loss of material at any number of locations.	Го	Long	Replace support.
(A)			Harbor Tunnel	A)	Severe corrosion w/ loss of material at any number of locations.	О	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	o	Long	Replace support.
			Harbor	ay x	Severe corrosion w/ loss of material at any number of locations.	Го	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	oŋ	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Го	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Ol	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Ol	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations, grout pad cracked.		Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	ol	Long	Replace support.
			Harbor Tunnel	24 25	Severe corrosion w/ loss of material at any number of locations.	ol	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Го	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Ol	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	g	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	ol	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	ol	Long	Replace support.
			Harbor Tunnel	2 /2	Severe corrosion w/ loss of material at any number of locations.	ol	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	ol	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	O	Long	Replace support.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -	**	
tem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b)			Harbor Tunnel	(b) (	Severe $\omega$ rrosion w/ significant loss of material at any number of locations.	Long	Replace support.
(3)			Harbor Tunnel	3) (£	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
(A)			Harbor Tunnel	۹)	Severe $\omega$ rrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
28 - 3			Harbor	23	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations, grout pad chipped.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
St. 3	Table E2		Harbor		Severe corrosion w/significant loss of material at any number of locations. API 570: No wear plate or Teflon provided after repairs (JP-5) (floating pipe).	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
i) i			Harbor Tunnel	N 3	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
:			Harbor		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.

				Table 17	Table 17 (Carted) Erran Dine Councets		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition N	Urgency	Recommended Repairs
(b)			Harbor	(b)	Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
(3) (			Harbor Tunnel	(3)	Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
A)			Harbor Tunnel	(A)	Severe corrosion w/ loss of material at any number of locations.	Pong	Replace support.
			Harbor Tunnel		Severe corrosion w/ significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Pong	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Pong	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.

				Table 17			
				Tanet	Table 17 (30) (ed.) - Frame Tipe 30ppoles	2	
tem No.	S70 Report – Cross Reference	SGH Report	Geographic	Pipe Support	Condition Notes	Urgency	Recommended Repairs
	Deficiency (InterSpec, LLC)	Cross	Area	o Z			
(b)	55 17 85		Harbor	(b)	Severe $\omega$ rrosion w/significant loss of material at any number of locations.	Long	Replace support.
(3) (			Harbor	(3) (	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
A)			Harbor	A)	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe $\operatorname{corrosion} w/\operatorname{significant} \operatorname{loss}$ of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe $\cot \cos n$ loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor	2 Y	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel	W 9	Severe $\cos \log w / \log s$ of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations, all anchor bolts not visible.	Long	Replace support.
			Harbor		Severe $\operatorname{corrosion} w/\operatorname{significant} \operatorname{loss}$ of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe $\operatorname{corrosion} w/\operatorname{significant} \operatorname{loss}$ of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe $\operatorname{corrosion} w/\operatorname{significant} \operatorname{loss}$ of material at any number of locations, grout pad broken.	Long	Replace support.
	Table E2		Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations, grout pad broken. API 570: No wear plate or Teflon provided after repairs (F-24) (floating pipe).	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe $\alpha$ rosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
				2			

				Table 17	Table 17 (Sorted) - Frame Pine Supports -		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition	Urgency	Recommended Repairs
(b)	55 17 18 18		Harbor	(b)	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
(3)			Harbor	(3)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
(A)			Harbor	(A)	Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent, grout pad broken.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent, grout pad broken.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
	Table E2		Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations. API 570: No wear plate or Teflon provided after repairs (JP-5).	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -	9	
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition	Urgency	Recommended Repairs
(b)	59 59 59		Harbor Tunnel	(b) (	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
(3) (			Harbor	(3) (	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
A)			Harbor Tunnel	<b>A)</b>	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
*			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations, anchor bolt bent, grout pad broken.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
7. Y			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe $\omega$ rrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe $\omega$ rrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition N	Urgency	Recommended Repairs
(b)			Harbor Tunnel	(b)	Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
(3) (	(2)		Harbor Tunnel	(3) (	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
A)	A )		Harbor Tunnel	A)	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -	9	
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition	Urgency	Recommended Repairs
(b)			Harbor	(b)	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
(3) (			Harbor	(3) (	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
A)			Harbor Tunnel	A)	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe $\cot \sin w/\sin i f$ cant loss of material at any number of locations, grout pad broken.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe $\cos \log w / \log s$ of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe $\cos \log w/\log s$ of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
			Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
		HT-28	Harbor Tunnel		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
		HT-28	Harbor		Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.

tem No. Cross Reference Cross Area No. Deficiency (InterSpec, LLC) Reference Cross Area No. Cross Reference Cross Area No. (InterSpec, LLC) Reference Tunnel Harbor Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Harbor Tunnel	Condition Notes  Condit	Urgency	Recommended Renairs
HT-30 HT-30 HT-30 HT-30 Table E2			
HT-30 HT-30 HT-30 HT-30 HT-30 Table E2	Severe corrosion w/significant loss of material at any number of locations. Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
HT-30 HT-30 HT-30 HT-30 HT-30	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
HT-30 HT-30 HT-30		Long	Replace support.
H7-30 H7-30 H7-30 H7-30	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
H7-30 H7-30 H7-30 H7-30	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
HT-30 HT-30 HT-30 HT-30	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
HT-30 HT-30 HT-30	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
HT-30 HT-30	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
HT-30	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
HT-30	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
	Severe corrosion w/significant loss of material at any number of locations.	Long	Replace support.
Harbor	Mild corrosion at any number of places, may have efflorescence from wall coating it.  API 570: No wear plate or Teflon provided after repairs (floating pipe).	Long	API 570: Shim and moniter at next inspection.
	Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
Table E2 Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: No wear plate or Teflon provided after repairs (JP-5) (floating pipe).	Long	Gean of corrosion and maintain in good condition. API 570: Shim and monitor at next inspection.
Harbor	Moderate corrosion at any number of locations, may have efflorescence coating it, corroded baseplate, no grout.	Long	Gean of corrosion and maintain in good condition.
Table E2 Harbor Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: No wear plate or Teflon provided after repairs	Long	Gean of corrosion and maintain in good condition. API 570: Shim and monitor at next inspection.
Harbor Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.

No. (p) (3) (A)	upport Condition Notes	Urgency	Recommended Repairs
Tunnel Harbor (C) Tunnel Harbor			
Tunnel Harbor	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Clean corrosion and repaint, maintain in good condition.
Tunnel Harbor	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
Harbor Tunnel	Severe corrosion w/ loss of material at any number of locations.	Long Repla	Replace support.
Harbor Tunnel	Severe corrosion w/ loss of material at any number of locations.	Long Repla	Replace support.
Harbor Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Clean corrosion and repaint, maintain in good condition.
Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel Harbor Tunnel	Severe corrosion w/loss of material at any number of locations, grout pad broken.	Long Repla	Replace support.
	Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: No wear plate or Teflon provided after repairs  J. No wear plate or Teflon provided after repairs	Long cond inspe	Gean corrosion and repaint, maintain in good condition. API 570: Shim and monitor at next inspection.
	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
ow ow ow	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Clean corrosion and repaint, maintain in good condition.
	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
Harbor Modera Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Clean corrosion and repaint, maintain in good condition.
Harbor Tunnel Modera	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
Harbor Modera Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
Harbor Modera Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
Harbor Modera Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
Table E2 Harbor Mild coil Tunnel API 570	Mild corrosion at any number of places, may have efflorescence from wall coating it. API 570: No wear plate or Teflon provided after repairs (JP-5).	Long API 5	API 570: Shim and monitor at next inspection.
Harbor Modera Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.
Harbor Modera Tunnel	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long Clear	Gean corrosion and repaint, maintain in good condition.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b)			Harbor Tunnel	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(3) (			Harbor Tunnel	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(A)			Harbor Tunnel	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it, anchor bolt bent.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, anchor bolt to wall corroded.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
		нт-23	Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations, column flange deformation.	Long	Replace support.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.
			Harbor		Severe corrosion w/ loss of material at any number of locations.	Long	Replace support.

Appendix C – APP 570 Report – O. Cross Reference Deficiency (InterSpec, LLC)
--

				Table 17	Table 17 (Sorted) - Frame Pipe Supports	mmendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition N		Urgency	Recommended Repairs
(b)	6 6	HT-19	Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.
(3)			Harbor	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.
(A)			Harbor	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	pating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	pating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.
-			Harbor	777 S	Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.
. 0			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor	7	Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel	e 26	Moderate corrosion at any number of locations, may have efflorescence coating it.	pating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor	2 42	Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor	-	Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	oating it.	Long	Clean corrosion and repaint, maintain in good condition.

Condition Naber of location naber na					Table 17	Table 17 (Sorted) - Frame Pipe Supports -		
Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor (Moderate corrosion at any number of locations, may have efflorescence coating it. Long (Moderate corrosion at any number of locations, may have efflorescence coating it. Long (Moderate corrosion at any number of locations, may	ltem No.	27.	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition N	Urgency	Recommended Repairs
Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Inned Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Bonderate corrosi	(b)			Harbor Tunnel	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Seete corrosion w/ loss of material at any number of locations, deformed flarge Long Column, grout pad broken.  SGH p242 Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Turnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Saddles, no pads.	(3)			Harbor Tunnel	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Severe corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number	(A)			Harbor	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Severe corrosion w/ loss of material at any number of locations, deformed flange column, grout pad broken.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Modera				Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Tunnel         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Severe corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number				Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any numbe				Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion w/ loss of material at any number of locations, deformed flange         Long           Tunnel         Severe corrosion w/ loss of material at any number of locations, deformed flange         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any numbe				Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Severe corrosion w/ loss of material at any number of locations, deformed flange         Long           Tunnel         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number of locations, may have efflorescence coating it.         Long           Harbor         Moderate corrosion at any number				Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor       Severe corrosion w/ loss of material at any number of locations, deformed flange       Long         Harbor       Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long				Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Tunnel       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long				Harbor Tunnel		Severe $\cos row \log n \le 1$ lange of material at any number of locations, deformed flange column, grout pad broken.	Long	Replace support.
Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it. no saddles, no pads.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it, no Long       Long         Tunnel       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long			SGH p242	Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it. no saddles, no pads.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it, no Long       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it, no Long       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long			SGH p242	Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it, no saddles, no pads.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Tunnel       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long				Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it, no raddles, no pads.       Long         Harbor       Moderate corrosion at any number of locations, may have efflorescence coating it, no raddles, no pads.       Long				Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Saddles, no pads. Moderate corrosion at any number of locations, may have efflorescence coating it, no Long Tunnel Moderate corrosion at any number of locations, may have efflorescence coating it, no Long Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long Long Tunnel				Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel Moderate corrosion at any number of locations, may have efflorescence coating it, no saddles, no pads. Harbor Moderate corrosion at any number of locations, may have efflorescence coating it, no Long Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long				Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long Tunnel Moderate corrosion at any number of locations, may have efflorescence coating it, no saddles, no pads. Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long				Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Harbor Moderate corrosion at any number of locations, may have efflorescence coating it, no Long saddles, no pads.  Harbor Moderate corrosion at any number of locations, may have efflorescence coating it. Long		32		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
Moderate corrosion at any number of locations, may have efflorescence coating it.			H-11	Harbor Tunnel		$\label{eq:moderate} \begin{tabular}{ll} Moderate corrosion at any number of locations, may have efflorescence coating it, no saddles, no pads. \end{tabular}$	Long	Clean corrosion and repaint, maintain in good condition.
				Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.

				Table 17	Table 17 (Sorted) - Frame Dine Supports -		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition	Urgency	Recommended Repairs
(b)			Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(3) (			Harbor	(3)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Glean corrosion and repaint, maintain in good condition.
A)			Harbor Tunnel	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor	S	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel	, , ,	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Glean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel	***	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel	2 /2	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.

				Tolde 17	Table 17 (Sorted) - Frame Dire Surveyte		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b)	55 17 18 18		Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(3)			Harbor Tunnel	(3)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(A)			Harbor	(A)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it. API 570: Small wood shim between wear plate and Steel support member (JP-5).	Long	Clean corrosion and repaint, maintain in good condition. API 570: Remove wood and install Teflon shim.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Pong	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad chipped.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Pong	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
		HT-8	Harbor Tunnel		Severe corrosion w/loss of material at any number of locations, JP-5 brace to wall corroded.	Long	Replace support.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad chipped.	Long	Gean corrosion and repaint, maintain in good condition.

	Recommended Repairs	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Clean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, maintain in good condition.	Gean corrosion and repaint, replace ceiling supported threaded rods, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and the support to or other metal-to-metal support locations.	Gean corrosion and repaint, maintain in good condition.	Replace support.	Replace support .	Gean corrosion and repaint, maintain in good condition. API 570: Monitor at next inspection.
	Urgency	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long	Long
Table 17 (Sorted) - Frame Pipe Supports -	Condition	Moderate corrosion at any number of locations, may have efflorescence coating it, F-24 brace at wall corroded.	Moderate corrosion at any number of <u>locations</u> , may have efflorescence coating it, stacked washers anchor bolt to wall a line or S side to fit anchor bolt to wall.	Moderate corrosion at any number of locations, may have efflorescence coating it.	Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad chipped.	Moderate corrosion at any number of locations, may have efflorescence coating it.	Moderate corrosion at any number of locations, may have efflorescence coating it.	Moderate corrosion at any number of locations, may have efflorescence coating it.	Moderate corrosion at any number of locations, may have efflorescence coating it.	Moderate corrosion at any number of locations, may have efflorescence coating it.	Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad chipped.	Moderate corrosion at apv number of locations, may have efflorescence coating it, JP-5 supported on frame or no attachment to wall, ceiling support threaded rod for frame extension for additional lines (sprinkler lines) abandoned (?) ceiling and pipe supported support (unnumbered) between and abandoned frame is level 3, threaded rod is badly deteriorated. Style begins API 570: No waar plate or Lefton at the intermediate between and line is welded directly to pipe.	Moderate corrosion at any number of locations, may have efflorescence coating it.	Severe corrosion w/ loss of material at any number of locations.  API 570: Intermediate between line is welded directly to pipe.	Severe corrosion w/ loss of material at any number of locations.  API 570: Majority of the piping support in the harbor tunnel has tack-welded steel wear plates between pipe and pipe support. Few locations with metal-to-metal contact and some corrosion were noted on the	Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: Intermediate between line is welded directly to pipe.
Table 17	Pipe Support No.	(b)	(3) (A)													
	Geographic Area	Harbor	Harbor Tunnel	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor	Harbor Tunnel	Harbor	Harbor Tunnel	Harbor	Harbor	Harbor Tunnel	Harbor
	SGH Report Cross Reference													HT-5		HT-5
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	55 19 35										Table E2		Table E2	B16 Table E2	Table E2
	ltem No.	(b)	(3) (A	)												

D)

Table 17 (Sorted) - Frame Pipe Supports	Re	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.  Tunnel API 570: No wear plate or Teffon a	HT-5 Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.  API 570: Intermediate betwee line is welded directly to pipe.	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.	HT-5 Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it, JP- Tunnel 5 on stacked plates.	Harbor Moderate corrosion at any number of locations may have efflorescence coating it.  Tunnel API 570: Pipe is not in contact with support (floating pipe).	Moderate corrosion at any number of locations, may have efflorescence coating it,  Tunnel grout pad broken.	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.  Tunnel	Harbor Moderate corrosion at any number of locations, may have efflorescence coating it.	Harbor Severe_parcsion w/ loss of material at any number of locations, JP-5 Tunnel 3 side corroded, column flange deformed.	Severe corr	Harbor
<u> </u>	2000	Table E2	Table E2 HT-5		HT-5				Table E2									

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -	S	
tem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition N	Urgency	Recommended Repairs
(b)			Harbor	(b)	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
(3) (			Harbor Tunnel	(3) (	Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
A)			Harbor Tunnel	A)	Moderate corrosion at any number of locations, may have efflorescence coating it, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, column flange deformed, grout pad broken.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it, extremely long anchor bolt.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, wall to wall WF, high zinc paint, moderate corrosion at paint damage, line on built up WF, JP-5 on cradle.	Long	Gean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, wall to wall WF, high zinc paint, moderate corrosion at paint damage, line on built up WF, JP-5 on cradle.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, wall to wall WF, high zinc paint, moderate corrosion at paint damage, line on built up WF, JP-5 on cradle, both lines on saddles.	Long	Clean corrosion and repaint, maintain in good condition.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, WF supported on angles at walls, high zinc paint, bottom flange deformation at several areas.	Long	Clean corrosion and repaint, maintain in good condition.
t te			RHTF		efflorescence at pipe penetrations on tunnel side, moderate cracking in gunnite parge coat.	Long	Gean and repair.
			RHTF		Moderate corrosion at column connection to beam, light corrosion at wall.	Long	Gean corrosion and repaint, maintain in good condition.
2			RHTF		Moderate corrosion at column connection to beam, light corrosion at wall.	Long	Clean corrosion and repaint, maintain in good condition.
	A15		RHTF		Mild corrosion in small pockets along beam and column.	Long	Provide sufficient spacing between pipe and Unistrut.
	A15		RHTF		Mild corrosion in small pockets along beam and column, more corrosion than 96, still mild angle paint is deteriorated.	Long	Gean corrosion and repaint, maintain in good condition, Provide sufficient spacing between pipe and Unistrut.

				Table 17	Table 17 (Control)   Eramo Dine Sunnerth		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe S	Condition	Urgency	Recommended Repairs
(b)	55 72 83		RHTF	(b)	Mild corrosion in small pockets along beam and column, minor bottom flange deformation between supports.	Long	Gean corrosion and repaint, maintain in good condition.
(3) (A)	A11 Table E2		RHTF	(3) (A)	Moderate corrosion along beam and beam brace, grout pad/protection damaged at column.  API 570: Pipe is not fully bearing on support (partial support	Long	Gean corrosion and repaint, maintain in good condition. API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
	A11	LAT-52	RHTF		Missing cross brace arm to very mild spot corrosion.  API 570: Long segment of the adequately supported betwee with only partial support on one side.	Long	Add cross brace arm. API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11		RHTF		Very mild spot corrosion.  API 570: Long segment of the pipe is also not adequately supported betwee with only partial support on one side.	Long	API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11		RHTF		Very mild spot corrosion.  API 570: Long segment of the pipe is also not adequately supported betwee with only partial support on one side.	Long	API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11 Table E2		RHTF		Minor corrosion in small areas.  API 570: Unistrut in contact with pipe at causing coating failure/corrosion. Pipe is not fully bearing on support (partial support	Long	API 570: Repair pipe and shim the pipe or pipe support as needed to support the pipe uniformly.
	A11		RHTF		Minor corrosion in small areas.  API 570: Long segment of the adequately supported between with only partial support on one side.	Long	API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11 Table E2		RHTF		Minor corrosion in small areas, deformation at lower angle brace to API 570: Unistrut in contact with pipe at a causing coating failure/corrosion. Long segment of the nine is unsupported. The pipe is also not adequately supported between with only partial support on one side.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Repair pipe and add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and l-Beam structure or other metal-to-metal support locations.
	A11		RHTF		Moderate corrosion at wall, cracking and chipping of lower grout pad.  API 570: Long segment of the page is unsupported. One location has 57'  11" of unsupported pipe between	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Shim the pipe or pipe support as needed to support the pipe uniformly.
	A11 Table E2		RHTF		Moderate corrosion at wall, cracking and chipping of lower grout pad. API 570: Pipe is not bearing on support (floating pipe)	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.

-
2
O
~
ш
0-
_
<
0
ш
₫,
S
2
_
~
5
-
S
×.
S
0-
ш
Ę
S
~
₹
2
-
7
ш
)
4

				Tahle 17	Table 17 (Sorted) - Frame Dire Summerts		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition	Urgency	Recommended Repairs
(b) (3) (A)	A11 Table E2		RHTF	(b) (3) (	Moderate corrosion at wall, cracking and chipping of lower grout pad. API 570: Pipe is not bearing on support (floating pipe)	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
	A11 Table E2		RHTF	A)	Moderate corrosion at wall, cracking and chipping of <u>lower grout</u> pad. API 570: Pipe is not bearing on support (floating pipe	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Bean structure or other metal-to-metal support locations.
	A11 Table E2		RHTF		API 570: Pipe is not bearing on support (floating pipe)	Long	API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
	A11 Table E2		RHTF		Cracking and chipping at grout pad. API 570: Pipe is not bearing on support (floating pipe)	Long	Repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
(communication)	A11 Table E2		RHTF		Moderate corrosion at wall, cracking and chipping of <u>lower g</u> rout pad. API 570: Pipe is not bearing on support (floating pipe	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
	A11 Table E2	LAT-51	RHTF		Moderate corrosion at wall, cracking and chipping of lower grout pad, missing cross brace arm to API 570: Moderate corrosion on the steel saddle Long segment of the nipe is unsupported. One location has 57' 11" of unsupported pipe between	Long	Add cross bracing, clean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Replace steel saddle. Shim the pipe or pipe support as needed to support the pipe uniformly.
	Table E2		Tank 3 Lateral		API 570: Pipe is not bearing on support (floating pipe) support (floating pipe)	Long	API 570: Adjust support (raise the plate).
			Tank 4 Lateral		Corrosion at pipe support down to cross beam.	Long	Gean corrosion, maintain in good condition.
		LAT-28	RHTF		Moderate corrosion all over, top flange deformed at wall end, column flange deformed at free end, grout pad damaged, baseplate damaged.	Long	Replace column, anchorage, and grout pad, clean corrosion and repaint, maintain in good condition.

				Table 17	Table 17 (Sorted). Frame Dine Sunnorts.		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3)	A19 Table E2		RHTF	(b) (3) (	Moderate corrosion, minor grout pad cracking and chipping.  API 570: Some coating failure and corrosion between pipe and pipe support on the (JP-5) pipe.	Long	Gean corrosion and repaint, maintain in good condition, API 570: Replace the corroded steel saddle support. Consider a saddle that is secured (welded to the support structure) and a Teflon pad between pipe and saddle. Apply protective coating.
(A)	A19 Table E2		RHTF	A)	API 570: Some coating failure and corrosion between pipe and pipe support on the (JP-5) pipe.	Long	API 570: Replace the corroded steel saddle support. Consider a saddle that is secured (welded to the support structure) and a Teflon pad between pipe and saddle. Apply protective coating.
	Table E2	LAT-48	RHTF		Grout pad chipped. API 570: Pipe is not bearing on support, missing saddle (floating pipe	Long	API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-tometal support locations.
	A8 Table E2	LAT-47	RHTF		API 570: Wood shim b/w saddle and pipe support member/dislodged	Long	API 570: Shim.
	Table E2		RHTF		API 570: Pipe is not bearing on support (floating pipe)	Long	API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-tometal support locations.
		LAT-46	RHTF		Paint chipping, moderate corrosion more severe at wall, pipe support corroded.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2	LAT-46	RHTF		Paint chipping, moderate corrosion more severe at wall, pipe support corroded.  API 570: There are moderate coating failure and some corrosion on the horizontal pipe support I-beam.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair coating.
	A19 Table E2	LAT-45 LAT-46	RHTF		Corroded at wall, low angle brace between deformed API 570: Some coating failure and corrosion between pipe and pipe support on the (JP-5) pipe. Moderate corrosion on the steel saddle (JP-5).	Long	Gean corrosion and repaint, maintain in good condition, repair angle brace at deformed area. API 570: Replace the corroded steel saddle support. Consider a saddle that is secured (welded to the support structure) and a Teflon pad between pipe and saddle. Apply protective coating.
v.	Table E2		RHTF		X bracing removed between for new ventilation door (door 3) installation.  API 570: Pipe is not bearing on support (floating pipe)	Long	Gean corrosion and repaint, maintain in good condition. API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
	A19 Table E2		RHTF		Moderate corrosion, splice under pipe, mildly deformed bottom flange at wall.  API 57D; Some coating failure and corrosion between pipe and pipe support on the  JP-5) pipe. Moderate corrosion on the steel saddle (JP-5).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Replace the corroded steel saddle support. Consider a saddle that is secured (welded to the support structure) and a Teflon pad between pipe and saddle. Apply protective coating.

				Tahle 17	Table 17 (Sorted) - Frame Dine Sunnorts .	9	
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition	Urgency	Recommended Repairs
(b) (3) (A	Table E2		Tank 5 Lateral	(b) (3) ( <i>A</i>	Corrosion/efflorescence deformation at support plate at diese API 570: No Teflon between pipe and support (Tank 5).	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal to-metal to-metal to-metal support locations.
<b>(</b> )	Table E2		Tank 5 Lateral	A)	Corrosion/efflorescence deformation at support plate at diese API 570: Loose nut on adjustable plate/some deflection on plate	Long	Clean corrosion and repaint, maintain in good condition. API 570: Secure the nut on the plate.
			Tank 5 Lateral		Corrosion/efflorescence deformation at support plate at diese	Long	Gean corrosion and repaint, maintain in good condition.
			Tank 6 Lateral		Corrosion/efflorescence deformation at support plate at diese	Long	Gean corrosion and repaint, maintain in good condition.
			Tank 6 Lateral		Corrosion/efflorescence deformation at support plate at diese , cracked grout exposed baseplate.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		RHTF	4	Hange deformation at wall anchor moderate corrosion at wall. API 570: Moderate corrosion on the steel saddle (JP-5).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair pipe and add shim.
			RHTF		Moderate corrosion at wall.	Long	Gean corrosion and repaint, maintain in good condition.
			RHTF		Column flange deformation, top angle brace to not attached fully.	Long	Gean corrosion and repaint, maintain in good condition, attach angle brace fully.
	Table E2		RHTF		$\label{eq:moderate} Moderate\ corrosion\ under\ middle\ line,\ column\ flange\ deformed.$ API 570: Contact type\ abrasion\ and\ corrosion\ at\ pipe\ support/pipe\ (JP-5)\ .	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair coating. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
			RHTF		Lower angle brace deformed.	Long	Gean corrosion and repaint, maintain in good condition.
	Table E2		Tank 7 Lateral		Plate supporting pipe at T7A bent under weight. API 570: Small deflection on pipe support after dresser coupling (Tank 7).	Long	API 570: Adjust support (raise the plate).
			RHTF		Corrosion at baseplate, grout cracked and chipped, beam flange bent.	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad.
			RHTF		Moderate corrosion at wall, minor deformation to bottom flange.	Long	Gean corrosion and repaint, maintain in good condition.
			RHTF		Column flange deformation at several locations on braced column.	Long	Gean corrosion and repaint, maintain in good condition.
		LAT-26 LAT-28	RHTF	, .	Beam flange deformation, corrosion at beam-wall interface.	Long	Gean corrosion and repaint, maintain in good condition.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condit	Urgency	Recommended Repairs
(b) (3)	Table E2	LAT-26	RHTF	(b) (3) (	Corrosion at saddle of wall closest to pipe, corrosion at beam-wall interface. API 570: Coating failure and corrosion at saddle support (JP-5).	Long	Gean corrosion and repaint, maintain in good condition. API 570: Repair coating. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
(A)		LAT-26 LAT-43	RHTF	A)	Corrosion at base of center column at repair.	Long	Gean corrosion and repaint, maintain in good condition
		LAT-26	RHTF		Baseplate grout chipped.	Pong	Gean corrosion and repaint, maintain in good condition, repair grout pad.
			RHTF		Baseplate corrosion at wall baseplate.	Long	Gean corrosion and repaint, maintain in good condition.
	A25 Table E2		Tank 9 Lateral		API 570 pipe is not in contact with the pipe (floating pipe).	Pong	Adjust the elevation of the pipe support plate to provide sufficient load bearing contact between pipe and support plate.
			Tank 10 Lateral		Corrosion on top beam and top of column (efflourescense).	Long	Gean corrosion and repaint, maintain in good condition.
	A9 Table E2		RHTF		Corrosion at beam support at minor areas of corrosion elsewhere.  API 570: Long segment of the pipe is unsupported. One location has 47' of unsupported pipe betwee with the saddle support missing at	Long	Gean corrosion and repaint, maintain in good condition. API 570: Install saddle supports at shim as needed to support pipe on the saddles. Secure the saddles to the pipe support.
	A9 Table E2	LAT-39	RHTF		out nad	Long	Clean corrosion and repaint, maintain in good condition, replace grout pad. API 570: Install saddle supports at and shim as needed to support pipe on the saddles. Secure the saddles to the pipe support.
	A9 A24 Table E1 Table E2	LAT-26	RHTF		Minor corrosion at paint loss areas, no saddle to line. API 570: Metal to metal contact. No Teflon shims/insulation strip. The pipe is not fully supported. The pipe is natfally in contact with the pipe support (JP-5). Missing steel saddle (floating pipe)	Long	Clean corrosion and repaint, maintainingood condition, add saddle. API 570: Shin pipe support so as to provide positive contact between pipe and saddle support. Consider Teflon shim between pipe and saddle. Shim P-5 pipe and monitor at next inspection. Install saddle on install sad
	A24 Table E1 Table E2	LAT-26	RHTF		Minor corrosion at wall column. API 570: Metal to metal contact. No Teflon shims/insulation strip. The pipe is not fully supported. The pipe is partially in contact with the pipe support (JP-5).	Long	Clean corrosion and repaint maintain in good condition. API 570: Shim pipe support so as to provide positive contact between pipe and saddle support. Consider Teflon shim between pipe and saddle. Shim JP-5 pipe and monitor at next inspection.
	Table E1 Table E2	LAT-26	RHTF		No saddle to line. API 570: Meta <u>l to me</u> tal contact. No Teflon shims/insulation strip.Missing steel saddle (floating pipe)	Long	Gean corrosion and repaint, maintain in good condition, add saddle. API 570: Install saddle. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and LBeam structure or other metal tometal support locations.

INC.

No O Selection			Table 17	Table 17 (Sorted) - Frame Pipe Supports - Support Findings and Recommendations	345	
Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
Table E1	LAT-26	RHTF	(b) (3)	Overall good. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
Table E1 Table E2	LAT-26 LAT-36	RHTF	(A)	Cross bracing deformed. API 570: Metal to metal contact. No Teflon shims/insulation strip. Moderate corrosion on the steel saddle	Long	Repair bracing. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations. Replace steel saddle.
Table E1	LAT-26 LAT-36	RHTF		Loss of grout and corrosion at baseplate, cross bracing deformed. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Repair bracing, clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
Table E1	LAT-26 LAT-35	RHTF		Bottom flange corrosion at downspout. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition, relocate downspout. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
Table E1	LAT-28 LAT-35	RHTF		Flange deformation at (2) locations, connection at "wall" not visible. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
Table E1	LAT-26	RHTF		Minor corrosion at paint damage, moderate flange corrosion at downspout, top flange delamination at beam, moderate baseplate corrosion at train track column w/minor grout damage.  API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition, relocate downspout. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and L-Beam structure at all pipe support locations.
Table E1	LAT-26	RHTF		Flange deformation at line. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
Table E1	LAT-26	RHTF		Minor damage at grout pad. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.

tem No.	Appendix C – API	SGH		1000	Company of the control of the contro		
	570 Report – Cross Reference Deficiency (InterSpec, LLC)	Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3)	Table E1	LAT-26	RHTF	(b) (3) (	Minor grout pad damage at wall column. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
(A)	Table E1	LAT-26	RHTF	(A)	Grout pad damage and flange corrosion at wall column. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-26	RHTF		Corrosion at paint chipping. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-26	RHTF		Column flange deformation at train track flange, grout pad damage and minor baseplate corrosion at wall column. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-26	RHTF		Beam flange corrosion at downspout. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, repair beam at flange delamination, relocate downspout. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-26	RHTF		Grout pad damage and loss of support. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
			Tank 13 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.
· · ·			Tank 13 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.
			Tank 13 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.
			Tank 14 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.
			Tank 14 Lateral		Concrete pier/grout pad damage.	Long	Repair grout pad.

				Table 17	Table 17 (Sorted) - Frame Pine Supports -		
ltem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3)	Table E1	LAT-26	RHTF	(b) (3) (	Baseplate corrosion at wall column (moderate), moderate-severe column flange corrosion at train track column. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
(A)	Table E1 Table E2	LAT-26	RHTF	(A)	Moderate flange deformation at train track column, column flange damage at wall column.  API 570: Metal to metal contact No Teflon shims/insulation strip. Pipe is not bearing on support (floating pipe)	Long	Clean corrosion and repaint, maintain in good condition. API 570: Shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure or other metal-to-metal support locations.
	Table E1	LAT-26 LAT-30	RHTF		Hange deformation at wall column, baseplate grout damage and corrosion at wall column. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-26 LAT-30	RHTF		Overall good. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-28	RHTF		Column flange deformation at train track column, minor grout chipping at wall column baseplate. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-26	RHTF		Beam flange corrosion at downspout, baseplate corrosion at wall column. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition, relocate downspout. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-26 LAT-27	RHTF		Corrosion (moderate) at wall baseplate, grout chips, minor flange deformation at beam, severe delamination and corrosion at wall beam. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, replace damaged beam at wall column and wall connection, maintain in good condition. API 570: Consider Teffon shims/insulation strips between pipe and saddle or half-round Teffon strips between pipe and LBeam structure at all pipe support locations.
	Table E1 Table E2	LAT-25 LAT-26	RHTF		Corrosion (moderate) at wall baseplate, grout chips, minor flange deformation at beam, severe delamination and corrosion at wall beam. API 570: Metal to metal contact. No Teflon shims/insulation strip. Moderate corrosion on the steel saddle	Long	Gean corrosion and repaint, replace damaged beam at wall column and wall connection, maintain in good condition. API 570: Replace steel saddle. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.

				Table 17	Table 17 (Costed) Frame Direc Connected		
	Appendix C – API	100		Tagge	Sorted) - Frame ripe Supports 1		
ltem No.	570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (	Table E2	LAT-23	RHTF	(b) (3	Beam flange deformation, beam corrosion at JP-5 and lines, baseplate grout cracked and chipped.  API 570: Moderate corrosion on the steel saddle	Long	Replace severely corroded beam area, clean corrosion and repaint, maintain in good condition.  API 570: Replace steel saddle.
3) (#			Tank 15 Lateral	3) (A	Corrosion at line.	Long	Clean corrosion, maintain in good condition.
<b>A)</b>	Table E2		Tank 16 Lateral	)	Baseplate grout damage. API 570: Small deflection on pipe support after dresser coupling (Tank 16).	Long	API 570: Adjust support (raise the plate).
	Table E1	LAT-19 LAT-20 LAT-23	RHTF		Flange deformation at beam, baseplate corrosion and grout damage at line. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-20 LAT-21	RHTF		Grout damage and corrosion at baseplate, minor column flange deformation, cross bracing cut. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-19 LAT-20	RHTF		Minor flange deformation, significant corrosion at column base and loss of column, flange steel.  API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Replace Support; alternatively, cut out area of deformation and corrosion and replace in kind
	Table E1	LAT-18	RHTF		Beam flange corrosion (moderate) at pipe support area on top of beam. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1	LAT-17 LAT-18	RHTF		Severe corrosion and loss of steel at wall connection. API 570: Not in contact with saddle.	Long	Replace connection to wall, clean corrosion and repaint, maintain in good condition. API 570: Add shims to support to gain contact.
	Table E1		RHTF		Could not access to perform assessment. API 570: There is no saddle support and the pipe is not resting on the I-beam.	Long	API 570: Add shims to support to gain contact.
	Table E1		RHTF		Could not access to perform assessment. API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	None. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1		RHTF		No saddle to JP-5 line, cracked and chipped grout at wall column. API 570: There is no saddle support and the pipe is not resting on the I-beam.	Long	Gean corrosion and repaint, maintain in good condition, repair grout pad. API 570: Add shims to support to gain contact.
	Table E1	LAT-13 LAT-14	RHTF		Minor corrosion at paint damage, has saddle, wall column grout cracked and chipped. API 570: The pipe is partially in contact with the pipe support.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Add shims to support to gain contact.

				Toble 17	Table 17 (Sorted) Frame Dire Surrente		
tem No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support	Condition Notes	Urgency	Recommended Repairs
(b) (	Table E1	LAT-11 LAT-12	RHTF	(b)	Beam flange deformation, wall baseplate corroded, grout chipped and missing. API 570: Not in contact with saddle.	Long	Clean corrosion and repaint, maintain in good condition. API 570: Add shims to support to gain contact.
3) (/			Tank 17 Lateral	(3) (	Corrosion at column bottoms, loss of steel, corrosion at unknown member, flange cutout at tackwelded member, no visible saddle at JP-5.	Long	Clean corrosion and repaint, maintain in good condition, add saddle.
۹)			Tank 17 Lateral	A)	Corrosion at base of column, no saddle.	Long	Clean corrosion, maintain in good condition, add saddle.
			Tank 18 Lateral		Beam moderately corroded at ends and beam top flange, no saddle for JP-5 line, crack and exposed rebar at unknown gunnite support.	Long	Clean corrosion and repaint, maintain in good condition, repair beam connection each end.
25 2		LAT-10	Tank 18 Lateral		Corrosion at beam to wall, severe corrosion at column baseplate, flange loss and corrosion at JP-5.	Long	Clean corrosion and repaint, maintain in good condition, repair connections beam to wall.
	Table E1		RHTF		Corrosion at beam flanges, loss of flange metal, grout at walkway column chipped away.  API 570: The pipe is partially in contact with the pipe support.	Long	Clean corrosion and repaint, maintain in good condition, replace grout pad. API 570: Add shims to support to gain contact.
	Table E1	LAT-5	RHTF		Grout at wall column broken and displaced, beam at wall corroded (beyond column). API 570: Metal to metal contact. No Teflon shims/insulation strip.	Long	Clean corrosion and repaint, maintain in good condition, repair connections beam to wall. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
ge e	Table E1	LAT-5	RHTF		Painted flange damage at red pipe, moderate corrosion at wall column, grout cracked and missing.  API 570: Missing one nut at concrete footing. Broken grouting.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Replace missing nut and re-grout.
	Table E1	LAT-5 LAT-8 LAT-55	RHTF		Saddle damaged only (1) side, grout removed from elevator column baseplate, space between wall column baseplate and grout pad. API 570: Metal to metal contact. No Teflon shims/insulation strip. Pulled anchor stud at concrete footing. Broken grouting.	Long	Gean corrosion and repaint, maintain in good condition, replace grout pad. API 570: Install support with insulation or half-round Teflon strip. Re-secure anchor stud and re-grout.  Note: The repair to replace deformed anchor bolt at this support is currently programmed as part of the PY21 Emergent Pipeline Repair Project.
	Table E1	LAT-5 LAT-6 LAT-7	RHTF		No Saddle. API 570: Pipe is resting on I-beam with Teflon shims/insulation strip and wood.	Long	Add saddle. API 570: Remove wood shim. Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.  Note: The repair to replace grout and anchor bolt at this support is currently programmed as part of the FY21 Emergent Pipeline Repair Project.

				Table 17	Table 17 (Sorted) - Frame Pipe Supports -		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition N	Urgency	Recommended Repairs
(b) (3)	Table E1	LAT-5	RHTF	(b) (3)	Overall good. API 570: Pipe is resting on Lbeam with no saddle or Teflon shims/insulation strip.	Long	API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
(A)	Table E1		RHTF	(A)	Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/exposed baseplate. API 570: Not in contact with saddle with minor gaps.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and I-Beam structure at all pipe support locations.
	Table E1		RHTF		Minor areas of corrosion at paint damage, column at Tank 19 side corroded w/exposed baseplate. API 570: Saddle is displaced from support beam with 1.5" Unistrut support placed underneath.	Long	Gean corrosion and repaint, maintain in good condition. API 570: Remove Unistrut and reposition saddle.
			Tank 19 Lateral		No saddle, grout damage and corrosion at tunnel-side column, corrosion at unknown member-column interface.	Long	Gean corrosion and repaint, maintain in good condition.
*****			Tank 19 Lateral		No saddle, top flange damage at pipe corrosion at beam to wall (beyond column) and at tunnel side top.	Long	Clean corrosion and repaint, maintain in good condition, replace beam-wall connection.
			Tank 20 Lateral		No saddle.	Long	Add saddle.
		LAT-1 LAT-2	Tank 20 Lateral		Corrosion at wall-beam interface beyond column, severe corrosion and loss of flange at baseplate corrosion on beam.	Long	Replace column and beam to wall connection, clean corrosion and repaint with high zinc paint, maintain in good condition.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it, same style as others, wall shield, wall anchor bolt not visible.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Moderate corrosion at any number of locations, may have efflorescence coating it, corroded baseplate, no grout.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		$\label{eq:mapping} Mild corrosion at any number of places, may have efflorescence from wall coating it, no grout.$	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.

				Tolde17	(Sartod) - Frama Dina Sunnarte	9	
				T alge!	Table 17 (2016a) - Flame Fipe Supports		
N most	570 Report	SGH Report	Geographic	Pipe Support	Condition Notes	Ligan	Recommended Renaire
	Deficiency (InterSpec, LLC)	Cross	Area	No.	sana longino	Organica	
(b)	1		Harbor	(b)	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
(3) (			Harbor	(3) (	Mild corrosion at any number of places, may have efflorescence from wall coating it, grout pad broken.	Other	None.
A)			Harbor Tunnel	A)	Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel	A. A.	Mild corrosion at any number of places, may have efflorescence from wall coating it, grout pad broken.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
-			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor Tunnel		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			Harbor		Mild corrosion at any number of places, may have efflorescence from wall coating it.	Other	None.
			RHTF		Moderate pitting and paint flaking, moderate deformation of lower flange at (1) location.	Other	None.
			RHTF		Mild corrosion in small pockets along beam and column, no flange deformation.	Other	None.
			Tank 1 Lateral		Good condition.	Other	None.
			Tank 1 Lateral		Good condition.	Other	None.
			Tank 2 Lateral		Plate deformed at diesel fuel line.	Other	None.
			Tank 2 Lateral		Good.	Other	None.
			Tank 3 Lateral		None.	Other	None.
4			Tank 4 Lateral		None.	Other	None.

0			Table 17	Table 17 (Sorted) - Frame Pipe Supports - Support Findings and Recommendations	ns	
S70 Report –	SGH	Geographic	Pipe Support			
Cross Reference Deficiency (InterSpec, LLC)	Cross Reference	Area	No.	Condition Notes	Urgency	Recommended Repairs
		RHTF	(b	Column flange deformation.	Other	None.
		RHTF	) (	Minor corrosion at wall.	Other	None.
		RHTF	3)	Overall good.	Other	None.
		RHTF	()	Bulkhead anchor in good condition.	Other	None.
		RHTF	۱)	Overall good.	Other	None.
		Tank 7		Overall good.	Other	None.
		Tank 8			1	New
		Lateral		Overall good.	Other	None.
		Tank 8 Lateral		Overall good.	Other	None.
		RHTF		Overall good.	Other	None.
		Tank 9 Lateral		None.	Other	None.
		Tank 10 Lateral		None.	Other	None.
		RHTF	7.11	Overall good.	Other	None.
		Tank 11 Lateral		Minor chipping at baseplate and grout.	Other	None.
		Tank 11 Lateral		None.	Other	None.
		Tank 12 Lateral		Minor chipping at baseplate and grout.	Other	None.
		Tank 12 Lateral		None.	Other	None.
	LAT-31	RHTF		Overall good.	Other	None.
		RHTF		Overall good.	Other	None.
		RHTF		Overall good.	Other	None.
		Tank 15 Lateral		None.	Other	None.
		Tank 16 Lateral		None.	Other	None.
		RHTF		Overall good.	Other	None.
		Tank 17 Lateral		Overall good.	Other	None.
Table E1		RHTF		Overall good. API 570: Shimmed with Teflon pads.	Other	None. API 570: None.
	LAT-5	RHTF		Overall good.	Other	Nope

	y Recommended Repairs	Other None.
	Urgency	Other
7 (Sorted) - Frame Pipe Supports - Support Findings and Recommendations	Condition Notes	Severely deteriorated.
Table 17 (Sorte	Geographic Pipe Support Area No.	(b ) (3
		Tank 20 Lateral
	SGH Report Cross Reference	
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	59 13 55
	Item No.	(b )

				Table	Table 18 (Sorted) - Underground Pumphouse Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
b)			NGPH	(t	Grout pad cracked and exposing baseplate.	Long	Repair grout pad and maintain in good condition.
(3			NGPH	)	No grout layer.	Long	Repair grout pad and maintain in good condition.
3)			NGPH	(3	Grout chipped, baseplate displaced (no anchorage except for grout surround).	Long	Repair grout pad and maintain in good condition.
(A			UGPH	) (	Grout chipped.	Long	Repair grout pad and maintain in good condition.
.)			перн	A)	Pier minor chipping, minor corrosion at baseplate.	Long	Gean corrosion and repaint, maintain in good condition.
			UGPH		Grout pad chipped and missing.	Long	Repair grout pad and maintain in good condition.
			иды		Minor corrosion at base of column.	Long	Gean corrosion and repaint, maintain in good condition.
			перн		Unpainted, no grout base, corrosion at baseplate and bottom half of X.	Long	Clean corrosion and repaint, maintain in good condition.
			UGPH		Grout cracked apart, baseplate displaced.	Long	Repair grout pad and maintain in good condition.
			UGPH		Painted, no grout, circular baseplate corroded.	Long	Repair grout pad and maintain in good condition.
			UGPH		Grout broken out at front.	Long	Repair grout pad and maintain in good condition.
			NGPH		Painted top, no grout, circular baseplate corroded.	Long	Repair grout pad and maintain in good condition.
			UGPH		Painted top, no grout, circular baseplate corroded.	Long	Repair grout pad and maintain in good condition.
			UGPH		Minor cracking to grout base.	Long	Repair grout pad and maintain in good condition.
			перн		Loss of support under baseplate at sleeper between Shimmed w/ wood scrap.	Long	Modify support to adequately support pipe without need for shim.
			пды		Cut for flange, corrosion at saddle.	Long	Clean corrosion and repaint, maintain in good condition.
			пды		Wood shim under JP5.	Long	Modify support to adequately support pipe without need for shim.
			перн		Minor corrosion at all bearing plates.	Long	Clean corrosion and repaint, maintain in good condition.
			UGPH		Missing (1) anchor bolt and nut.	Long	Install anchor bolt and nut.
			перн		Corrosion at plates.	Long	Gean corrosion and repaint, maintain in good condition.
			UGPH	5 50	Shared pier w/ no anchor bolt.	Long	Install anchor bolt and nut.
			UGPH		Corrosion at plates.	Long	Gean corrosion and repaint, maintain in good condition.
			перн	2 - 17	Moderate corrosion at baseplate .	Long	Clean corrosion and repaint, maintain in good condition.
			идьн		Baseplate corroded.	Long	Gean corrosion and repaint, maintain in good condition.
			UGPH		Moderate corrosion at plate under saddle.	Long	Gean corrosion and repaint, maintain in good condition.
	60		UGPH		No grout pad.	Long	Repair grout pad and maintain in good condition.
			NGPH		Chipped concrete pier.	Other	None.
			Hdbn		Overall good.	Other	None.
			ПСРН		Overall good.	Other	None.

Appendix C – APP S70 Report – S70 Report – Cross Reference Deficiency (InterSpec, LLC)	Report Cross	Geographic Area UGPH UGPH UGPH	Pipe Support No.	Inderground Pumphouse Pipe Support Findings and Recommendations  Condition Notes		None. None. None. None. None.
		Hd50 Hd50 Hd50 Hd50 Hd50 Hd50 Hd50 Hd50		Overall good.         0           Minor pier cracking.         0           Overall good.         0	Other N	None.
		Hd50 Hd50 Hd50 Hd50 Hd50 Hd50 Hd50 Hd50		e trench.		None. None. None. None. None. None. None. None.
		Hd50 Hd50 Hd50 Hd50 Hd50 Hd50 Hd50 Hd50		Overall good.         Overall good.         O           Overall good.         O         O	Other N Other	None.

		Recommended Repairs				4	ai ai	a <sup>i</sup>	ai	4		ai .	**	4	4	ai .	**	4	-	at	4		1		ai.		a:				**	1	**			ai .			Y.	, , , , , , , , , , , , , , , , , , ,			Y.	ati
					None.	None	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None	None	NO.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.
		Urgency			Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Othor	Other		Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other
Table 18 (Sorted) - Underground Pumphouse Pipe Support Findings and Recommendations		Condition Notes			Overall good.	Overall good.	Overall good.	Overall good.	Overall good.	Overall good.	Overall good.	Overall good.	Overall good.	Minor concrete chips.	Overall good.	Poorly consolidated concrete at base.	Overall good.	Poorly consolidated concrete at base, minor concrete chips.	Overall good.	Overall good.	Pier shared w/ grating support column, no baseplate at grating support column, angle out at grating column dance support innainted at column	Overall good	Objusting at play in dar basen late	Chipping at pier under baseplate.	Chipping at pier under baseplate, shared pier w/ grating column.	Chipping at pier.	Top channel bottom flange cut for pipe clearance.	Top channel bottom flange cut for pipe clearance.	Overall good.	Overall good.	Overall good.	Interior column flange cut fo flange each side.	Overall good.	Pier chipping at baseplate.	Overall good.	Overall good.	Overall good.	Overall good.	Separate pier under each baseplate, pier straddles trench.	Overall good.	Overall good.	Overall good.	Overall good.	Overall good.
Tabl		Pipe Support	No.		(b	)	(3	) (	A)												a.	15.			230	7,7								40										
		hic	Area		NGPH	UGPH	UGPH	NGPH	UGPH	UGPH	UGPH	UGPH	UGPH	Hdbn	UGPH	Hdbn	UGPH	UGPH	UGPH	UGPH	HdDN	HODII	T T T T T T T T T T T T T T T T T T T	1100	UGPH	NGPH	NGPH	Hdbn	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	NGPH
	SGH	Report	Cross	Kererence																																								
	Appendix C – API	Cross Reference	Deficiency	(InterSpec, LLC)													20 70																											
		Item No.			(b	) (	(3)	) (.	A)					2 30				0 20							70			81 2				SV 7									2 - Y			

	Recommended Repairs	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.	None.
	Urgency	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other	Other
Table 18 (Sorted) - Underground Pumphouse Pipe Support Findings and Recommendations	Condition Notes	Overall good.	Overall good.	Overall good.		Overall good.									
Table	Pipe Support No.	(b	) (	(3)	) ( <i>i</i>	۹)			90 · 1	6 12 N 4	2 22		90 - 1	5	3 70.0
	Geographic Area	UGPH	NGPH	NGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	UGPH	NGPH
	SGH Report Cross Reference														
	Appendix C – API 570 Report – Cross Reference Deficiency (InterSpec, LLC)														
	Item No.	(b	) (	3)	()	(۲	V - 12				1-11			- 4	

b
ñ
2
щ
æ
2
0
F
C
Ж
VSP
Z
Σ
ш
5
ξ.
S
ĸ
S
≤
Z
F
7
3
_

					Table 19 (Sorted) - Surge Tank Pipe Support Findings and Recommendations		
Item No.	Appendix C – API 570 Report – Cross Reference Defidency (InterSpec, LLC)	SGH Report Cross Reference	Geographic Area	Pipe Support No.	Condition Notes	Urgency	Recommended Repairs
(b) (3) (	Table E2	S.	Surge Tank	(b) (3) (	No teflon pads visible, concrete at junction betweer API 570: No wear plate or Teflon provided after repairs	Long	Provide teflon pad. API 570: Consider Teflon shims/insulation strips between pipe and saddle or half-round Teflon strips between pipe and l-Beam structure or other metal-to-metal support locations.
A)			Surge Tank	A)	F-76 part of concrete is broken through and chipped under saddle.	Long	Repair concrete and maintain in good condtion.
			Surge Tank		Grout loss under baseplates, not all nuts are tightened, not all anchors are plumb.	Long	Replace grout pad and maintain in good condtion.
			Surge Tank		Concrete over baseplate cracked, baseplate not displaced.	Long	Repair concrete and maintain in good condtion.
			Surge Tank		Sleeper broken in half at edge of saddle baseplate and displaced, loss of support under baseplate.	Long	Repair concrete, replace grout pad, and maintain in good condtion.
			Surge Tank		Sleeper broken in half at edge of saddle baseplate and displaced, loss of support under baseplate.	Long	Repair concrete, replace grout pad, and maintain in good condtion.
			Surge Tank		Minor loss of grout under baseplate.	Long	Replace grout pad and maintain in good condtion.
			Surge Tank		Corroded baseplates but overall good.	Long	Clean corrosion and repaint, maintain in good condition.
	D2		Surge Tank		Loss of grout and support anchors exposed, anchor bolts knocked crocked.	Long	Replace grout pad and anchor bolts and maintain in good condtion.
			Surge Tank		Overall good.	Other	None.
	8	0 0	Surge Tank		Could not access for condition assessment.	Other	None.
			Surge Tank		part of concrete is chipped.	Other	None.
			Surge Tank		Overall good.	Other	None.
			Surge Tank		part of concrete is cracked but overall good.	Other	None.
			Surge Tank		part of concrete is cracked but overall good.	Other	None.
			Surge Tank		Overall good.	Other	None.
			Surge Tank	_	Overall good.	Other	None.
			Surge Tank		Overall good.	Other	None.

This page is intentionally left blank.